



# Customer Management Report (Baldwin Park) All Detection Types

01-May-2013 to 31-May-2013

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	11-07%	0-00%	11-02%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
Police Rejects										
Driver Unidentifiable Images poor	0-00%	0-00%	3-02%	1-01%	0-00%	3-09%	4-07%	3-02%	0-00%	14-02%
Red-light not visible in	0-00%	0-00%	0-00%	1-01%	0-00%	1-03%	1-02%	0-00%	3-50%	6-01%
Unclear Scene Image	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues										
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
Total	0-00%	0-00%	5-03%	3-03%	0-00%	5-15%	7-13%	30-18%	3-50%	53-09%
Approved Violations	1-100%	22-100%	140-97%	114-97%	24-100%	28-85%	47-87%	138-82%	3-50%	517-91%
Total Notices Printed	1-100%	22-100%	140-97%	114-97%	24-100%	28-85%	47-87%	138-82%	3-50%	517-91%

Generated By: TESPANTO

Generated On: 1/22/2014 9:26:16 AM

© Redflex Traffic Systems, Inc.

# Customer Management Report (Baldwin Park) All Detection Types

01-Jun-2013 to 30-Jun-2013

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	0	30	209	254	43	73	170	384	19	1182

## Less Uncontrollable Factors

Obstruction	0	0	4	6	7	13	37	4	9	80
Driver Obstruction/Duckers	0	0	0	1	0	0	0	0	0	1
Motor Cycle Helmet	0	0	2	6	0	2	2	1	1	14
Plate Obstruction	0	2	2	6	2	2	8	2	0	24
Vehicle Obstruction	0	2	2	6	2	2	8	2	0	24

## Police Rejects

Citation Issued manually	0	0	0	1	0	0	0	0	0	1
Driver Obstruction (P/D)	0	0	0	0	0	0	0	1	0	1
Incorrect/Incomplete DMV	0	8	37	54	9	13	23	80	2	226
Invalid Offense	0	0	0	0	1	0	0	0	0	1
On or Passed the Stop Bar (P/D), Sun Glare	0	0	6	20	0	2	13	47	0	88
Sun Glare	0	0	0	3	0	0	0	0	0	3
Policy/Weath er	0	0	1	1	0	1	3	0	0	6
Extended Vehicle	0	3	44	28	4	5	31	92	0	207
Sun Glare	0	0	0	0	0	1	0	0	0	1

## Registration Issues

Out of Country Plate	0	2	9	14	1	2	4	14	1	47
Paper Plates	0	0	0	0	0	0	0	1	0	1
Wrong or No DMV	0	15	105	140	24	41	121	242	13	701

Sub Total Violations	0	15	104	114	19	32	49	142	6	481
Less In Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	0	15	104	114	19	32	49	142	6	481

## Less Rejects

Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	10-07%	0-00%	0-00%	9-02%	10-02%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	11-02%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Face Not in Frame	0-00%	0-00%	11-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%

Generated By: TESPANTO  
Generated On: 1/22/2014 9:26:43 AM

# Customer Management Report (Baldwin Park) All Detection Types

01-Jun-2013 to 30-Jun-2013 Operator Id: %

	BAL-DAPU-01	BAL-FRRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Misc Camera Issue	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	5-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Police Driver Unidentifiable images poor	0-00%	0-00%	6-06%	1-01%	0-00%	1-03%	4-08%	4-03%	0-00%	16-03%
Rejects Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	0-00%	0-00%	23-22%	1-01%	2-11%	1-03%	5-10%	23-16%	0-00%	55-11%
Approved Violations	0-00%	15-100%	81-78%	113-99%	17-89%	31-97%	44-90%	119-84%	6-100%	426-89%
Total Notices Printed	0-00%	15-100%	81-78%	113-99%	17-89%	31-97%	44-90%	119-84%	6-100%	426-89%

Generated By: TESPANTO  
Generated On: 1/22/2014 9:26:43 AM



# Customer Management Report (Baldwin Park) All Detection Types

01-Jul-2013 to 31-Jul-2013

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Police Rejects	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	3-02%	0-00%	4-01%
Driver Unidentifiable Images poor	0-00%	0-00%	1-01%	2-02%	2-13%	0-00%	0-00%	4-02%	0-00%	9-02%
Approved Violations	14-100%	9-100%	71-99%	122-98%	13-87%	19-100%	52-100%	192-98%	8-100%	500-98%
Total Notices Printed	14-100%	9-100%	71-99%	122-98%	13-87%	19-100%	52-100%	192-98%	8-100%	500-98%

Generated By: TESPANTO

Generated On: 1/22/2014 9:27:14 AM

© Redflex Traffic Systems, Inc.

# Customer Management Report (Baldwin Park) All Detection Types

01-Aug-2013 to 31-Aug-2013

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
<b>Total Processed Incidents</b>	58	33	156	273	66	69	162	507	31	1355
<b>Less Uncontrollable Factors</b>										
Obstruction	3	2	1	6	16	3	23	18	11	83
Driver Obstruction/Duckers	0	0	0	3	0	0	1	6	0	10
Motor Cycle Helmet	2	2	3	4	1	3	1	1	0	17
Plate Obstruction	0	2	0	5	0	2	4	5	0	18
Vehicle Obstruction	0	0	0	0	0	0	0	0	0	0
Driver Obstruction (PD)	0	0	0	0	0	0	0	1	0	1
Police Rejects	0	0	0	0	1	2	0	0	0	3
Emergency Vehicle Responding	0	0	1	0	0	0	0	0	0	1
Funeral Procession/Police	0	0	0	0	0	0	0	0	0	0
Gender Mismatch	0	0	0	1	0	1	1	1	0	4
Incorrect/Incomplete DMV	15	9	33	70	12	13	37	125	4	318
Multiple vehicles in frame	0	0	0	0	1	0	0	1	0	2
On or Passed the Stop Bar (PD)	0	0	1	8	1	1	5	43	0	59
Sun Glare	0	0	0	0	0	1	3	4	0	8
Policy/Weath	2	0	55	39	9	2	30	69	0	206
er	0	0	0	2	0	0	0	0	0	2
Registration	3	0	1	6	2	3	4	20	0	39
Issues	25	15	95	144	43	31	109	294	15	771
Paper Plates	0	0	0	0	0	0	0	0	0	0
Out of Country Plate	0	0	0	0	0	0	0	0	0	0
<b>Sub Total Violations</b>	33	18	61	129	23	38	53	213	16	584
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	33	18	61	129	23	38	53	213	16	584
<b>Less Rejects</b>										
Camera	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-02%	4-02%	0-00%	6-01%
Face Camera Flash	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-02%	4-02%	0-00%	6-01%
Matfunction	0-00%	0-00%	1-02%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	2-00%
Face Camera Focus Blurry	0-00%	0-00%	1-02%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	2-00%
Plate Burn Out	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: TESPANTO

Generated On: 1/22/2014 9:27:38 AM

# Customer Management Report (Baldwin Park) All Detection Types

01-Aug-2013 to 31-Aug-2013

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Plate Not in Frame	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	6-03%	0-00%	8-01%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
No Images	0-00%	0-00%	1-02%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Unclear Scene Image	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	0-00%	1-06%	4-07%	3-02%	0-00%	1-03%	4-08%	10-05%	0-00%	23-04%
Total	33-100%	17-94%	57-93%	126-98%	23-100%	37-97%	49-92%	203-95%	16-100%	561-96%
Approved Violations	33-100%	17-94%	57-93%	126-98%	23-100%	37-97%	49-92%	203-95%	16-100%	561-96%
Total Notices Printed	33-100%	17-94%	57-93%	126-98%	23-100%	37-97%	49-92%	203-95%	16-100%	561-96%

Generated By: TESPANTO

Generated On: 1/22/2014 9:27:38 AM

© Redflex Traffic Systems, Inc.



# Customer Management Report (Baldwin Park) All Detection Types

01-Sep-2013 to 30-Sep-2013

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
<b>Total Processed Incidents</b>	54	39	149	269	41	76	171	284	18	1101
<b>Less Uncontrollable Factors</b>										
Obstruction	7	2	5	5	8	10	29	6	8	80
Driver Obstruction/Duckers	0	0	2	0	0	0	3	0	0	5
Motor Cycle Helmet	2	3	5	3	1	1	4	2	0	21
Plate Obstruction	1	4	0	5	1	1	7	5	1	25
Vehicle Obstruction	0	0	1	1	0	0	0	0	0	2
Police	0	0	1	1	0	0	0	0	0	2
Rejects	0	0	0	1	0	0	0	0	0	1
Driver Obstruction (PD)	0	0	0	1	0	0	0	0	0	1
Gender Mismatch	0	0	0	1	0	0	1	0	0	2
Incorrect/Incomplete DMV	12	9	16	52	9	15	25	56	3	197
Invalid Offense	0	0	0	0	1	0	0	0	0	1
On or Passed the Stop Bar (PD)	0	0	0	11	0	0	4	46	0	61
Sun Glare	0	0	0	1	0	0	1	0	0	2
Policy/Weath	0	0	0	1	0	0	1	0	0	2
er	0	0	55	33	6	6	39	27	0	166
Sun Glare	0	0	0	0	0	0	1	0	0	1
Yellow with Red Light	0	0	0	0	0	0	0	0	0	0
Registration	0	0	0	0	0	0	0	1	0	1
Issues	1	2	5	14	1	3	5	12	1	44
Paper Plates	0	0	0	1	0	0	0	0	0	1
Wrong or No DMV	23	20	89	129	27	36	120	155	13	612
<b>Sub Total Violations</b>	31	19	60	140	14	40	51	129	5	489
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	31	19	60	140	14	40	51	129	5	489
<b>Less Rejects</b>										
Camera	0-00%	0-00%	1-02%	0-00%	0-00%	1-02%	2-04%	1-01%	0-00%	5-01%
Face Camera Flash										

Generated By: TESPANTO  
Generated On: 1/22/2014 9:27:58 AM

# Customer Management Report (Baldwin Park) All Detection Types

01-Sep-2013 to 30-Sep-2013

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Manufacture										
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Police Driver Unidentifiable images poor	0-00%	0-00%	1-02%	1-01%	2-14%	0-00%	1-02%	3-02%	0-00%	8-02%
Police Unclear Scene Image	0-00%	0-00%	3-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Process Issues Too Old	2-06%	0-00%	4-07%	12-09%	2-14%	4-10%	5-10%	19-15%	0-00%	48-10%
Total	2-06%	0-00%	10-17%	13-09%	4-29%	5-12%	8-16%	25-19%	0-00%	67-14%
Approved Violations	29-94%	19-100%	50-83%	127-91%	10-71%	35-88%	43-84%	104-81%	5-100%	422-86%
Total Notices Printed	29-94%	19-100%	50-83%	127-91%	10-71%	35-88%	43-84%	104-81%	5-100%	422-86%

Generated By: TESPANTO

Generated On: 1/22/2014 9:27:58 AM

© Redflex Traffic Systems, Inc.

# Customer Management Report (Baldwin Park) All Detection Types

01-Oct-2013 to 31-Oct-2013

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
<b>Total Processed Incidents</b>	69	34	137	244	40	81	210	344	26	1185
<b>Less Uncontrollable Factors</b>										
Obstruction	6	0	2	10	5	8	25	5	5	66
Driver Obstruction/Duckers	0	0	0	0	0	0	0	1	0	1
Motor Cycle Helmet	2	1	1	2	0	0	6	1	0	13
Plate Obstruction	2	6	0	5	2	0	11	7	2	35
Vehicle Obstruction	0	0	1	0	0	0	0	0	0	1
Citation Issued manually	0	0	0	0	0	0	0	0	0	0
Emergency Vehicle Responding	0	0	0	0	0	0	1	0	0	1
Gender Mismatch	0	0	0	0	0	1	0	0	0	1
Incorrect/Incomplete DMV	5	2	7	14	0	5	8	11	1	53
On or Passed the Stop Bar (PD)	0	0	1	20	2	2	11	37	0	73
Sun Glare	0	0	0	0	0	0	0	1	0	1
Policy/Weath	0	0	0	0	0	2	1	0	0	3
Extended Vehicle	0	2	36	19	4	5	27	18	0	111
Sun Glare	0	1	3	0	0	0	2	1	0	7
Weather/Nature	0	0	1	0	0	0	1	2	0	4
Registration	1	2	6	8	1	5	8	9	1	41
Out of Country Plate	1	1	1	0	0	0	1	2	0	7
Paper Plates	1	1	1	1	1	1	1	1	1	10
Wrong or No DMV	1	1	0	2	0	0	1	0	0	5
Total	17	15	58	80	14	28	102	93	9	416
<b>Sub Total Violations</b>	52	19	79	164	26	53	108	251	17	769
Less in Progress	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>	52	19	79	164	26	53	108	251	17	769
<b>Less Rejects</b>										
Camera	0-00%	0-00%	1-01%	0-00%	1-04%	1-02%	0-00%	7-03%	0-00%	10-01%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-02%	0-00%	5-01%
Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Face Camera No Flash										

Generated By: TESPANTO

Generated On: 1/22/2014 9:28:20 AM

# Customer Management Report (Baldwin Park) All Detection Types

01-Oct-2013 to 31-Oct-2013

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Face Not in Frame	0-00%	0-00%	0-00%	1-01%	2-08%	2-04%	0-00%	1-00%	0-00%	6-01%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	5-02%	0-00%	7-01%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	1-01%	0-00%	1-02%	0-00%	0-00%	0-00%	2-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	1-00%
Process Issues	14-27%	6-32%	20-25%	31-19%	2-08%	11-21%	33-31%	58-23%	2-12%	177-23%
Too Old	14-27%	6-32%	21-27%	33-20%	5-19%	15-28%	35-32%	76-30%	3-18%	208-27%
Approved Violations	38-73%	13-68%	58-73%	131-80%	21-81%	38-72%	73-68%	175-70%	14-82%	561-73%
Total Notices Printed	38-73%	13-68%	58-73%	131-80%	21-81%	38-72%	73-68%	175-70%	14-82%	561-73%

Generated By: TESPANTO

Generated On: 1/22/2014 9:28:20 AM

© Reflex Traffic Systems, Inc.

# Customer Management Report (Baldwin Park) All Detection Types

01-Nov-2013 to 30-Nov-2013

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
<b>Total Processed Incidents</b>	62	34	126	193	47	62	119	335	20	998
<b>Less Uncontrollable Factors</b>										
Obstruction	5	0	1	3	9	4	15	3	8	48
Driver Obstruction/Duckers	0	0	0	1	0	0	1	0	0	2
Motor Cycle Helmet	1	1	3	2	0	1	0	2	0	10
Plate Obstruction	0	0	0	1	0	0	0	0	0	1
Signal Obstruction	0	3	0	7	1	2	8	3	0	24
Vehicle Obstruction	1	2	0	4	0	0	3	6	0	16
Police	3	1	3	12	1	3	7	44	1	75
Rejects	2	1	23	12	6	2	19	7	1	73
Incorrect/Incomplete DMV	0	0	2	0	0	0	0	2	2	6
On or Passed the Stop Bar (PD)	3	1	3	12	1	3	7	44	1	75
Policy/Weath	2	1	23	12	6	2	19	7	1	73
er	0	0	2	0	0	0	0	2	2	6
Weather/Nature	2	1	23	12	6	2	19	7	1	73
Registration	3	0	6	5	1	4	4	13	2	38
Paper Plates	0	1	0	0	0	0	0	0	0	1
Issues	15	9	38	47	18	16	57	80	14	294
Wrong or No DMV	3	0	6	5	1	4	4	13	2	38
Total	47	25	88	146	29	46	62	255	6	704
Sub Total Violations	0	0	0	0	0	0	0	0	0	0
Less In Progress	47	25	88	146	29	46	62	255	6	704
Available For Prosecution	0	0	0	0	0	0	0	0	0	0
<b>Less Rejects</b>										
Camera	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	2-03%	1-00%	0-00%	4-01%
Face Camera Focus Blurry	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	1-03%	1-02%	0-00%	1-00%	0-00%	3-00%
Face Not in Frame	2-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	3-00%
Misc Camera Issue	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Burn Out	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	4-06%	0-00%	0-00%	6-01%

Generated By: TESPANTO

Generated On: 11/22/2014 9:28:42 AM

# Customer Management Report (Baldwin Park) All Detection Types

01-Nov-2013 to 30-Nov-2013

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%
Process Too Old	15-32%	6-24%	16-18%	42-29%	7-24%	15-33%	15-24%	97-38%	3-50%	216-31%
Total	17-36%	6-24%	20-23%	43-29%	9-31%	16-35%	21-34%	101-40%	3-50%	236-34%
Approved Violations	30-64%	19-76%	68-77%	103-71%	20-69%	30-65%	41-66%	154-60%	3-50%	468-66%
Total Notices Printed	30-64%	19-76%	68-77%	103-71%	20-69%	30-65%	41-66%	154-60%	3-50%	468-66%

Generated By: TESPANTO

Generated On: 1/22/2014 9:28:42 AM

© Redflex Traffic Systems, Inc.

# Customer Management Report (Baldwin Park) All Detection Types

01-Dec-2013 to 31-Dec-2013

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	51	60	112	190	40	55	118	320	15	961

Less Uncontrollable Factors	Driver Obstruction/Duckers	Motor Cycle Helmet	Plate Obstruction	Vehicle Obstruction	Police Rejects	Police	Policy/Weath	er	Registration	Issues	Total
Obstruction	4	0	3	1	0	0	0	0	0	0	4
Driver Obstruction/Duckers	5	0	0	6	1	1	0	0	0	0	5
Motor Cycle Helmet	0	0	0	0	0	1	0	0	0	0	0
Plate Obstruction	3	0	1	1	0	5	0	0	0	0	3
Vehicle Obstruction	1	6	7	12	5	3	0	0	0	0	12
Police Rejects	0	1	1	3	0	3	0	3	1	3	12
Police	2	0	1	5	0	3	0	5	5	34	50
Policy/Weath	0	0	0	0	1	0	0	0	0	0	1
er	2	0	22	13	3	2	8	4	0	0	54
Registration	0	0	0	0	0	0	0	0	0	1	1
Issues	1	4	3	7	3	2	5	17	0	0	42
Total	0	0	0	1	0	0	0	0	0	0	1
	13	16	44	55	23	21	57	77	7	7	313

Sub Total Violations	Less in Progress	Available For Prosecution
38	0	38
44	0	44
68	0	68
135	0	135
17	0	17
34	0	34
61	0	61
243	0	243
8	0	8
648	0	648

Less Rejects	Camera Malfunction	Digital Distortion	Face Camera Flash	Face Camera Focus Blurry	Face Camera No Flash	Image Missing	Misc Camera Issue
0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	6-04%	1-03%
0-00%	0-00%	0-00%	3-04%	0-00%	0-00%	0-00%	0-00%
0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
1-03%	0-00%	0-00%	11-08%	0-00%	0-00%	0-00%	0-00%

Generated By: TESPANTO  
Generated On: 1/22/2014 9:29:00 AM

# Customer Management Report (Baldwin Park) All Detection Types

01-Dec-2013 to 31-Dec-2013

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Plate Burn Out	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate Camera Blurry	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	2-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	1-00%
Too Old	8-21%	10-23%	14-21%	31-23%	6-35%	7-21%	16-26%	62-26%	4-50%	158-24%
Issues	9-24%	11-25%	19-28%	51-38%	8-47%	9-26%	29-48%	76-31%	4-50%	216-33%
Total	29-76%	33-75%	49-72%	84-62%	9-53%	25-74%	32-52%	167-69%	4-50%	432-67%
Approved Violations	29-76%	33-75%	49-72%	84-62%	9-53%	25-74%	32-52%	167-69%	4-50%	432-67%
Total Notices Printed	29-76%	33-75%	49-72%	84-62%	9-53%	25-74%	32-52%	167-69%	4-50%	432-67%

Generated By: TESPANTO

Generated On: 1/22/2014 9:29:00 AM

© Redflex Traffic Systems, Inc.