

# Customer Management Report (Encinitas) All Detection Types

01-Jun-2004 to 01-Jul-2004

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
Total Violations		402	369	0	771
Less Uncontrollable Factors					
Obstruction	Driver Obstruction/Duckers	11	14	0	25
	Plate Obstruction	34	19	0	53
Police Rejects	Driver Unidentifiable	4	1	0	5
	Images Or Video Do Not Support	1	0	0	1
	Invalid Offense	1	2	0	3
	Vehicle Does Not Appear In All	1	0	0	1
Policy/Weather	Extended Vehicle	0	5	0	5
	Sun Glare	18	36	0	54
Registration Issues	Out of Country Plate	1	0	0	1
	Paper Plates	17	8	0	25
	Wrong or No DMV	11	9	0	20
Total		99	94	0	193
Sub Total Violations		303	275	0	578
Less in Progress		0	0	0	0
Available For Prosecution		303	275	0	578
Less Rejects					
Camera Malfunction	Digital Distortion	1-00%	0-00%	0-00%	1-00%
	Face Camera Flash	21-07%	52-19%	0-00%	73-13%
	Face Not in Frame	2-01%	24-09%	0-00%	26-04%
	Plate Burn Out	2-01%	0-00%	0-00%	2-00%
	Plate Not in Frame	2-01%	7-03%	0-00%	9-02%
	Rear Plate Camera Blurry	0-00%	2-01%	0-00%	2-00%
	Scene Image No Flash	0-00%	13-05%	0-00%	13-02%
Police Rejects	Unclear Images	1-00%	1-00%	0-00%	2-00%
Total		29-10%	99-36%	0-00%	128-22%
Notices Printed		274-90%	176-64%	0-00%	450-78%

BLI) a  
Encl ECR

# Customer Management Report (Encinitas) All Detection Types

01-Jul-2004 to 01-Aug-2004

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
Total Violations		382	379	0	761
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	17	14	0	31
	Motor Cycle Helmet	0	1	0	1
	Plate Obstruction	42	15	0	57
Police Rejects	Driver Unidentifiable	3	6	0	9
	Invalid Offense	5	1	0	6
Policy/Weather	Extended Vehicle	3	3	0	6
	Sun Glare	3	11	0	14
	Weather/Nature	2	0	0	2
Registration Issues	Paper Plates	8	12	0	20
	Wrong or No DMV	8	7	0	15
Total		91	70	0	161
Sub Total Violations		291	309	0	600
Less in Progress		0	0	0	0
Available For Prosecution		291	309	0	600
<b>Less Rejects</b>					
Camera Malfunction	Digital Distortion	0-00%	2-01%	0-00%	2-00%
	Face Camera Flash	21-07%	85-28%	0-00%	106-18%
	Face Camera Focus Blurry	2-01%	5-02%	0-00%	7-01%
	Face Not in Frame	7-02%	35-11%	0-00%	42-07%
	Plate Burn Out	4-01%	1-00%	0-00%	5-01%
	Plate Not in Frame	2-01%	6-02%	0-00%	8-01%
Process Issues	Too Old	3-01%	2-01%	0-00%	5-01%
Total		39-13%	136-44%	0-00%	175-29%
Notices Printed		252-87%	173-56%	0-00%	425-71%

# Customer Management Report (Encinitas) All Detection Types

01-Aug-2004 to 01-Sep-2004

Operator Id: %

		ENC-ECEN-01	ENC-NEC-01	ENC-OLEC-01	TOTAL
Total Violations		302	359	0	661
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	8	13	0	21
	Plate Obstruction	33	7	0	40
	Vehicle Obstruction	1	0	0	1
Police Rejects	DMV Not On File	0	2	0	2
	Driver Unidentifiable	1	7	0	8
	Invalid Offense	4	3	0	7
	Obstructed View	1	0	0	1
Policy/Weather	Extended Vehicle	2	0	0	2
	Sun Glare	3	4	0	7
Registration Issues	Can Not Identify State	1	1	0	2
	Out of Country Plate	0	1	0	1
	Paper Plates	10	7	0	17
	Wrong or No DMV	4	4	0	8
Total		68	49	0	117
Sub Total Violations		234	310	0	544
Less in Progress		0	0	0	0
Available For Prosecution		234	310	0	544
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Flash	19-08%	86-28%	0-00%	105-19%
	Face Camera Focus Blurry	4-02%	3-01%	0-00%	7-01%
	Face Not in Frame	3-01%	26-08%	0-00%	29-05%
	Plate Burn Out	1-00%	7-02%	0-00%	8-01%
	Plate Not in Frame	0-00%	6-02%	0-00%	6-01%
	Scene Image Flash Inappropriate	0-00%	1-00%	0-00%	1-00%
	Scene Image No Flash	0-00%	10-03%	0-00%	10-02%
Police Rejects	Incorrect Details	1-00%	1-00%	0-00%	2-00%
	Red-light not visible in	0-00%	1-00%	0-00%	1-00%
Process Issues	Too Old	35-15%	27-09%	0-00%	62-11%
Total		63-27%	168-54%	0-00%	231-42%
Notices Printed		171-73%	142-46%	0-00%	313-58%

# Customer Management Report (Encinitas) All Detection Types

01-Sep-2004 to 01-Oct-2004

Operator Id: %

		ENC-ECEM-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
Total Violations		379	324	0	703
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	10	22	0	32
	Plate Obstruction	40	12	0	52
	Vehicle Obstruction	1	0	0	1
Police Rejects	DMV Not On File	3	1	0	4
	Driver Unidentifiable	20	22	0	42
	Invalid Offense	8	2	0	10
	Obstructed View	8	0	0	8
Policy/Weather	Extended Vehicle	2	0	0	2
	Sun Glare	3	0	0	3
	Weather/Nature	1	0	0	1
Registration Issues	Can Not Identify State	0	1	0	1
	Out of Country Plate	1	0	0	1
	Paper Plates	12	6	0	18
	Wrong or No DMV	3	4	0	7
Total		112	70	0	182
Sub Total Violations		267	254	0	521
Less in Progress		0	0	0	0
Available For Prosecution		267	254	0	521
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Flash	26-10%	65-26%	0-00%	91-17%
	Face Camera Focus Blurry	0-00%	2-01%	0-00%	2-00%
	Face Not in Frame	10-04%	20-08%	0-00%	30-06%
	Plate Burn Out	2-01%	9-04%	0-00%	11-02%
	Plate Not in Frame	2-01%	1-00%	0-00%	3-01%
	Rear Plate Camera Blurry	1-00%	0-00%	0-00%	1-00%
	Rear Plate Flash Inappropriate	1-00%	0-00%	0-00%	1-00%
Police Rejects Process Issues	Red-light not visible in	0-00%	2-01%	0-00%	2-00%
	Too Old	3-01%	1-00%	0-00%	4-01%
Total		45-17%	100-39%	0-00%	145-28%
Notices Printed		222-83%	154-61%	0-00%	376-72%

# Customer Management Report (Encinitas) All Detection Types

01-Jan-2005 to 01-Feb-2005

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
Total Violations		211	251	0	462
Less Uncontrollable Factors					
Obstruction	Driver Obstruction/Duckers	2	3	0	5
	Plate Obstruction	2	2	0	4
	Vehicle Obstruction	17	5	0	22
Police Rejects	DMV Not On File	0	1	0	1
	Driver Unidentifiable	16	46	0	62
	Invalid Offense	0	4	0	4
	Obstructed View	2	1	0	3
Policy/Weather	Extended Vehicle	1	2	0	3
	Sun Glare	4	49	0	53
	Weather/Nature	2	1	0	3
Registration Issues	Out of Country Plate	1	0	0	1
	Paper Plates	11	5	0	16
	Wrong or No DMV	2	4	0	6
Total		60	123	0	183
Sub Total Violations		151	128	0	279
Less in Progress		0	0	0	0
Available For Prosecution		151	128	0	279
Less Rejects					
Camera Malfunction	Digital Distortion	3-02%	0-00%	0-00%	3-01%
	Face Camera Flash	1-01%	3-02%	0-00%	4-01%
	Face Not in Frame	4-03%	18-14%	0-00%	22-08%
	Image Missing	1-01%	0-00%	0-00%	1-00%
	Plate Burn Out	0-00%	2-02%	0-00%	2-01%
	Plate Not in Frame	0-00%	2-02%	0-00%	2-01%
	Rear Plate Camera Blurry	3-02%	1-01%	0-00%	4-01%
	Rear Plate Flash Inappropriate	2-01%	1-01%	0-00%	3-01%
Process Issues	Too Old	5-03%	2-02%	0-00%	7-03%
Total		19-13%	29-23%	0-00%	48-17%
Notices Printed		132-87%	99-77%	0-00%	231-83%

BCI) b  
January '05 - '10

# Customer Management Report (Encinitas) All Detection Types

01-Jul-2005 to 01-Aug-2005

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OIEC-01	TOTAL
Total Violations		280	229	0	509
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	7	7	0	14
	Plate Obstruction	18	4	0	22
	Vehicle Obstruction	16	5	0	21
Police Rejects	Driver Unidentifiable	22	23	0	45
	Invalid Offense	1	0	0	1
	Obstructed View	2	1	0	3
	Safe Turn On Red	0	1	0	1
Policy/Weather	Extended Vehicle	3	1	0	4
	Sun Glare	29	74	0	103
Registration Issues	Can Not Identify State	3	1	0	4
	Paper Plates	15	4	0	19
	Wrong or No DMV	4	1	0	5
Total		120	122	0	242
Sub Total Violations		160	107	0	267
Less in Progress		0	0	0	0
Available For Prosecution		160	107	0	267
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Flash	1-01%	7-07%	0-00%	8-03%
	Face Camera Focus Blurry	1-01%	2-02%	0-00%	3-01%
	Face Not in Frame	1-01%	4-04%	0-00%	5-02%
	Plate Burn Out	1-01%	2-02%	0-00%	3-01%
	Plate Not in Frame	0-00%	1-01%	0-00%	1-00%
	Rear Plate Camera Blurry	2-01%	0-00%	0-00%	2-01%
	Rear Plate Flash Inappropriate	0-00%	1-01%	0-00%	1-00%
	Scene Image Flash Inappropriate	0-00%	4-04%	0-00%	4-01%
	Scene Image No Flash	0-00%	12-11%	0-00%	12-04%
Total		6-04%	33-31%	0-00%	39-15%
Notices Printed		154-96%	74-69%	0-00%	228-85%

# Customer Management Report (Encinitas) All Detection Types

01-Nov-2005 to 01-Dec-2005

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
Total Violations		173	202	258	633
Less Uncontrollable Factors					
Obstruction	Driver Obstruction/Duckers	9	16	17	42
	Plate Obstruction	10	7	3	20
	Vehicle Obstruction	11	0	6	17
Police Rejects	DMV Not On File	5	0	3	8
	Driver Unidentifiable	13	34	4	51
Policy/Weather	Extended Vehicle	1	1	0	2
	Sun Glare	12	11	1	24
Registration Issues	Can Not Identify State	0	2	1	3
	Out of Country Plate	1	0	0	1
	Paper Plates	6	2	9	17
	Wrong or No DMV	3	2	5	10
Total		71	75	49	195
Sub Total Violations		102	127	209	438
Less in Progress		0	0	0	0
Available For Prosecution		102	127	209	438
Less Rejects					
Camera Malfunction	Face Camera Flash	4-04%	18-14%	3-01%	25-06%
	Face Camera Focus Blurry	29-28%	26-20%	5-02%	60-14%
	Face Not in Frame	8-08%	8-06%	1-00%	17-04%
	Plate Burn Out	0-00%	2-02%	0-00%	2-00%
	Plate Not in Frame	1-01%	1-01%	0-00%	2-00%
	Rear Plate Camera Blurry	2-02%	4-03%	0-00%	6-01%
	Rear Plate Flash Inappropriate	1-01%	0-00%	1-00%	2-00%
	Rear Plate No Flash	0-00%	0-00%	5-02%	5-01%
Police Rejects	Expired Time	1-01%	0-00%	0-00%	1-00%
	Plate Unclear	2-02%	1-01%	0-00%	3-01%
	Red-light not visible in	3-03%	13-10%	12-06%	28-06%
Process Issues	Too Old	0-00%	0-00%	1-00%	1-00%
Total		51-50%	73-57%	28-13%	152-35%
Notices Printed		51-50%	54-43%	181-87%	286-65%

*BLI a  
ENC/ECR and  
ECR/Recepcion*

# Customer Management Report (Encinitas) All Detection Types

01-Dec-2005 to 01-Jan-2006

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
<b>Total Violations</b>		162	202	178	542
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	6	11	10	27
	Motor Cycle Helmet	0	0	1	1
	Plate Obstruction	9	4	4	17
	Vehicle Obstruction	4	3	5	12
Police Rejects	DMV Not On File	4	2	2	8
	Driver Unidentifiable	12	27	1	40
	Invalid Offense	1	2	0	3
Policy/Weather	Extended Vehicle	0	0	2	2
	Sun Glare	4	8	1	13
	Weather/Nature	0	2	1	3
Registration Issues	Can Not Identify State	0	6	0	6
	Paper Plates	5	2	5	12
	Wrong or No DMV	6	4	0	10
<b>Total</b>		51	71	32	154
<b>Sub Total Violations</b>		111	131	146	388
Less in Progress		0	0	0	0
<b>Available For Prosecution</b>		111	131	146	388
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Flash	2-02%	6-05%	1-01%	9-02%
	Face Camera Focus Blurry	6-05%	16-12%	3-02%	25-06%
	Face Not in Frame	0-00%	8-06%	1-01%	9-02%
	Misc Camera Issue	1-01%	0-00%	0-00%	1-00%
	Plate Not in Frame	2-02%	1-01%	0-00%	3-01%
	Rear Plate Camera Blurry	4-04%	4-03%	0-00%	8-02%
	Rear Plate Flash Inappropriate	1-01%	0-00%	0-00%	1-00%
	Rear Plate No Flash	0-00%	0-00%	2-01%	2-01%
Police Rejects	Plate Unclear	1-01%	1-01%	1-01%	3-01%
	Red-light not visible in	2-02%	2-02%	3-02%	7-02%
Process Issues	Too Old	1-01%	0-00%	0-00%	1-00%
<b>Total</b>		20-18%	38-29%	11-08%	69-18%
<b>Notices Printed</b>		91-82%	93-71%	135-92%	319-82%



# Customer Management Report (Encinitas) All Detection Types

01-Jan-2006 to 01-Feb-2006

Operator Id: %

		ENC-EOEN-01	ENC-ENECC-01	ENC-OIECC-01	TOTAL
<b>Total Violations</b>		145	170	160	475
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	7	9	6	22
	Plate Obstruction	15	2	4	21
	Vehicle Obstruction	5	2	7	14
Police Rejects	DMV Not On File	2	1	1	4
	Driver Unidentifiable	7	13	4	24
	Invalid Offense	5	2	0	7
	Obstructed View	0	0	1	1
Policy/Weather	Extended Vehicle	1	1	0	2
	Sun Glare	8	4	1	13
	Weather/Nature	0	3	1	4
Registration Issues	Paper Plates	4	4	8	16
	Wrong or No DMV	2	4	0	6
<b>Total</b>		56	45	33	134
<b>Sub Total Violations</b>		89	125	127	341
Less in Progress		0	0	0	0
<b>Available For Prosecution</b>		89	125	127	341
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Flash	0-00%	0-00%	1-01%	1-00%
	Face Not in Frame	2-02%	3-02%	0-00%	5-01%
	Misc Camera Issue	0-00%	1-01%	0-00%	1-00%
	Plate Burn Out	0-00%	1-01%	0-00%	1-00%
	Plate Not in Frame	2-02%	1-01%	0-00%	3-01%
	Rear Plate Camera Blurry	1-01%	2-02%	1-01%	4-01%
	Rear Plate No Flash	0-00%	0-00%	1-01%	1-00%
Police Rejects	Incorrect Details	0-00%	1-01%	0-00%	1-00%
	Plate Unclear	0-00%	3-02%	0-00%	3-01%
	Red-light not visible in	7-08%	8-06%	7-06%	22-06%
<b>Total</b>		12-13%	20-16%	10-08%	42-12%
<b>Notices Printed</b>		77-87%	105-84%	117-92%	299-88%

# Customer Management Report (Encinitas) All Detection Types

01-Feb-2006 to 01-Mar-2006

Operator Id: %

	ENC-ECEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL	
<b>Total Violations</b>	133	191	151	475	
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	4	5	9	18
	Motor Cycle Helmet	0	1	0	1
	Plate Obstruction	13	4	2	19
	Vehicle Obstruction	5	6	5	16
Police Rejects	DMV Not On File	1	1	0	2
	Driver Unidentifiable	8	16	5	29
	Invalid Offense	1	3	0	4
Policy/Weather	Sun Glare	3	0	1	4
	Weather/Nature	6	0	1	7
Registration Issues	Can Not Identify State	0	2	0	2
	Out of Country Plate	0	1	1	2
	Paper Plates	7	6	3	16
	Wrong or No DMV	2	5	1	8
<b>Total</b>		50	50	28	128
<b>Sub Total Violations</b>		83	141	123	347
Less in Progress		0	0	0	0
<b>Available For Prosecution</b>		83	141	123	347
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Flash	1-01%	0-00%	0-00%	1-00%
	Face Camera Focus Blurry	3-04%	2-01%	2-02%	7-02%
	Face Not in Frame	1-01%	2-01%	0-00%	3-01%
	Misc Camera Issue	0-00%	0-00%	1-01%	1-00%
	Plate Burn Out	0-00%	2-01%	0-00%	2-01%
	Plate Not in Frame	0-00%	1-01%	0-00%	1-00%
	Rear Plate Camera Blurry	2-02%	2-01%	1-01%	5-01%
Police Rejects	Plate Unclear	1-01%	1-01%	0-00%	2-01%
	Red-light not visible in	0-00%	20-14%	4-03%	24-07%
<b>Total</b>		8-10%	30-21%	8-07%	46-13%
<b>Notices Printed</b>		75-90%	111-79%	115-93%	301-87%

# Customer Management Report (Encinitas) All Detection Types

01-Jul-2006 to 01-Aug-2006

Operator Id: %

	ENC:ECEN-01	ENC:ENEC-01	ENC:OLEC-01	TOTAL
Total Violations	171	197	120	488
<b>Less Uncontrollable Factors</b>				
Obstruction				
Driver Obstruction/Duckers	8	27	21	56
Plate Obstruction	11	8	1	20
Vehicle Obstruction	11	2	3	16
Police Rejects				
Emergency Vehicle Responding	5	1	0	6
Incorrect Plate on Vehicle	0	1	0	1
Incorrect/Incomplete DMV	1	1	1	3
Multiple vehicles in frame	1	0	1	2
Policy/Weather				
Extended Vehicle	1	1	1	3
Sun Glare	21	37	11	69
Registration Issues				
Can Not Identify State	0	1	0	1
Paper Plates	1	5	3	9
Wrong or No DMV	7	4	0	11
Total	67	88	42	197
Sub Total Violations	104	109	78	291
Less in Progress	0	0	0	0
Available For Prosecution	104	109	78	291
<b>Less Rejects</b>				
Camera Malfunction				
Face Camera Flash	1-01%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	0-00%	1-01%	0-00%	1-00%
Face Not in Frame	0-00%	1-01%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	1-01%	0-00%	1-00%
Rear, Plate Flash Inappropriate	0-00%	0-00%	1-01%	1-00%
Scene Image No Flash	0-00%	0-00%	3-04%	3-01%
Police Rejects				
Driver Unidentifiable images poor	1-01%	2-02%	0-00%	3-01%
Total	2-02%	5-05%	4-05%	11-04%
Notices Printed	102-98%	104-95%	74-95%	280-96%

# Customer Management Report (Encinitas) All Detection Types

01-Jan-2007 to 01-Feb-2007

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OIEC-01	TOTAL
Total Violations		97	99	93	289
Less Uncontrollable Factors					
Obstruction	Driver Obstruction/Duckers	5	7	3	15
	Plate Obstruction	7	2	0	9
	Vehicle Obstruction	6	2	1	9
Police Rejects	Emergency Vehicle Responding	1	1	0	2
	Incorrect/Incomplete DMV	0	1	0	1
	Weather Conditions	1	0	0	1
Policy/Weather	Extended Vehicle	1	0	0	1
	Sun Glare	5	7	3	15
Registration Issues	Paper Plates	4	3	5	12
	Wrong or No DMV	5	2	1	8
Total		35	25	13	73
Sub Total Violations		62	74	80	216
Less in Progress		0	0	0	0
Available For Prosecution		62	74	80	216
Less Rejects					
Camera Malfunction	Face Camera Flash	0-00%	0-00%	2-02%	2-01%
	Face Camera No Flash	0-00%	0-00%	1-01%	1-00%
	Face Not in Frame	1-02%	1-01%	0-00%	2-01%
	Misc Camera Issue	2-03%	0-00%	0-00%	2-01%
	Plate Burn Out	0-00%	0-00%	3-04%	3-01%
	Rear Plate Camera Blurry	0-00%	1-01%	0-00%	1-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	1-01%	1-00%
Police Rejects	Driver Unidentifiable images poor	2-03%	1-01%	0-00%	3-01%
	Plate Unclear	0-00%	1-01%	0-00%	1-00%
	Unclear Scene Image	0-00%	1-01%	0-00%	1-00%
Total		5-08%	5-07%	7-09%	17-08%
Notices Printed		57-92%	69-93%	73-91%	199-92%

# Customer Management Report (Encinitas) All Detection Types

01-Jul-2007 to 01-Aug-2007

Operator Id: %

	ENC-ECEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
Total Violations	150	137	175	462
<b>Less Uncontrollable Factors</b>				
Obstruction				
Driver Obstruction/Duckers	15	12	15	42
Motor Cycle Helmet	1	0	0	1
Plate Obstruction	3	5	5	13
Vehicle Obstruction	2	2	4	8
Police Rejects				
Incorrect/Incomplete DMV	0	0	1	1
Police Discretion	0	1	0	1
Policy/Weather				
Sun Glare	21	19	24	64
Weather/Nature	2	1	1	4
Registration Issues				
Can Not Identify State	0	1	0	1
Paper Plates	3	1	4	8
Total	47	42	54	143
Sub Total Violations	103	95	121	319
Less in Progress	0	0	0	0
Available For Prosecution	103	95	121	319
<b>Less Rejects</b>				
Camera Malfunction				
Face Camera Flash	1-01%	1-01%	0-00%	2-01%
Face Camera Focus Blurry	3-03%	4-04%	0-00%	7-02%
Image Missing	11-11%	0-00%	0-00%	11-03%
Misc Camera Issue	18-17%	0-00%	0-00%	18-06%
Scene Image Flash Inappropriate	7-07%	0-00%	0-00%	7-02%
Police Rejects				
Driver Unidentifiable images poor	0-00%	1-01%	2-02%	3-01%
Sun Glare	0-00%	0-00%	1-01%	1-00%
Total	40-39%	6-06%	3-02%	49-15%
Notices Printed	63-61%	89-94%	118-98%	270-85%

# Customer Management Report (Encinitas) All Detection Types

01-Jan-2008 to 01-Feb-2008

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OIEC-01	TOTAL
Total Violations		71	125	93	289
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	1	5	6	12
	Plate Obstruction	2	3	1	6
	Vehicle Obstruction	1	2	2	5
Police Rejects	Emergency Vehicle Responding	1	0	0	1
	Police Discretion	2	2	0	4
	Weather Conditions	0	0	2	2
Policy/Weather	Extended Vehicle	0	2	0	2
	Sun Glare	2	5	3	10
	Weather/Nature	1	2	0	3
Registration Issues	Can Not Identify State	0	1	0	1
	Paper Plates	2	5	1	8
	Wrong or No DMV	0	1	0	1
Total		12	28	15	55
Sub Total Violations		59	97	78	234
Less in Progress		0	0	0	0
Available For Prosecution		59	97	78	234
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Focus Blurry	0-00%	2-02%	0-00%	2-01%
	Face Camera No Flash	0-00%	1-01%	2-03%	3-01%
	Face Not in Frame	0-00%	0-00%	1-01%	1-00%
	Plate Not in Frame	0-00%	1-01%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	4-04%	0-00%	4-02%
	Unclear Scene Image	2-03%	4-04%	0-00%	6-03%
Process Issues	Too Old	0-00%	0-00%	1-01%	1-00%
Total		2-03%	12-12%	4-05%	18-08%
Notices Printed		57-97%	85-88%	74-95%	216-92%

# Customer Management Report (Encinitas) All Detection Types

01-Jul-2008 to 01-Aug-2008

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
Total Violations		132	240	89	461
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	2	15	7	24
	Motor Cycle Helmet	0	0	2	2
	Plate Obstruction	2	16	0	18
	Vehicle Obstruction	3	10	2	15
Police Rejects	Emergency Vehicle Responding	1	1	1	3
	Face Obstruction	0	1	1	2
	Police Discretion	1	3	1	5
	Safe Turn On Red	0	16	0	16
Policy/Weather	Extended Vehicle	1	1	0	2
	Sun Glare	5	61	15	81
	Weather/Nature	3	18	5	26
Registration Issues	Can Not Identify State	0	1	0	1
	Out of Country Plate	1	0	1	2
	Paper Plates	5	4	5	14
	Wrong or No DMV	1	0	0	1
Total		25	147	40	212
Sub Total Violations		107	93	49	249
Less in Progress		0	0	0	0
Available For Prosecution		107	93	49	249
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Flash	0-00%	4-04%	0-00%	4-02%
	Face Not in Frame	1-01%	3-03%	0-00%	4-02%
	Plate Not in Frame	1-01%	1-01%	0-00%	2-01%
	Rear Plate Camera Blurry	0-00%	2-02%	0-00%	2-01%
Police Rejects	Unclear Scene Image	2-02%	0-00%	0-00%	2-01%
Total		4-04%	10-11%	0-00%	14-06%
Notices Printed		103-96%	83-89%	49-100%	235-94%

# Customer Management Report (Encinitas) All Detection Types

01-Jan-2009 to 01-Feb-2009

Operator Id: %

	ENC-ECEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
<b>Total Violations</b>	54	322	81	457
<b>Less Uncontrollable Factors</b>				
Obstruction				
Driver Obstruction/Duckers	0	21	2	23
Plate Obstruction	5	14	1	20
Vehicle Obstruction	0	24	3	27
Police Rejects				
Emergency Vehicle Responding	0	3	0	3
Face Obstruction	0	1	0	1
Police Discretion	2	6	1	9
Safe Turn On Red	0	46	0	46
Policy/Weather				
Sun Glare	1	27	6	34
Weather/Nature	2	4	0	6
Registration Issues				
Out of Country Plate	1	1	0	2
Paper Plates	0	4	0	4
Wrong or No DMV	1	0	0	1
<b>Total</b>	12	151	13	176
<b>Sub Total Violations</b>	42	171	68	281
Less in Progress	0	0	0	0
<b>Available For Prosecution</b>	42	171	68	281
<b>Less Rejects</b>				
Camera Malfunction				
Face Camera Flash	0-00%	3-02%	0-00%	3-01%
Face Camera Focus Blurry	1-02%	1-01%	1-01%	3-01%
Misc Camera Issue	1-02%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	2-01%	0-00%	2-01%
Police Rejects				
Driver Unidentifiable images poor	0-00%	4-02%	1-01%	5-02%
Red-light not visible in	0-00%	1-01%	0-00%	1-00%
<b>Total</b>	2-05%	11-06%	2-03%	15-05%
<b>Notices Printed</b>	40-95%	160-94%	66-97%	266-95%



# Customer Management Report (Encinitas) All Detection Types

01-Jul-2009 to 01-Aug-2009

Operator Id: %

		ENC-EGEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
Total Violations		48	351	64	463
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	1	45	2	48
	Plate Obstruction	4	12	0	16
	Vehicle Obstruction	2	10	1	13
Police Rejects	Emergency Vehicle Responding	2	2	0	4
	Safe Turn On Red	0	39	0	39
Policy/Weather	Extended Vehicle	1	0	1	2
	Sun Glare	4	115	29	148
Registration Issues	Paper Plates	1	3	0	4
	Wrong or No DMV	0	0	1	1
Total		15	226	34	275
Sub Total Violations		33	125	30	188
Less in Progress		0	0	0	0
Available For Prosecution		33	125	30	188
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Flash	0-00%	3-02%	0-00%	3-02%
	Face Camera Focus Blurry	0-00%	5-04%	2-07%	7-04%
	Face Camera No Flash	0-00%	1-01%	0-00%	1-01%
	Plate Not in Frame	1-03%	8-06%	0-00%	9-05%
	Rear Plate Camera Blurry	5-15%	1-01%	0-00%	6-03%
	Rear Plate No Flash	1-03%	0-00%	0-00%	1-01%
Total		7-21%	18-14%	2-07%	27-14%
Notices Printed		26-79%	107-86%	28-93%	161-86%

# Customer Management Report (Encinitas) All Detection Types

01-Jan-2010 to 01-Feb-2010

Operator Id: %

	ENC-ECEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
<b>Total Violations</b>	32	211	60	303
<b>Less Uncontrollable Factors</b>				
Obstruction				
Driver Obstruction/Duckers	0	24	3	27
Plate Obstruction	0	16	0	16
Vehicle Obstruction	1	7	2	10
Police Rejects				
Emergency Vehicle Responding	0	1	0	1
Police Discretion	0	0	1	1
Safe Turn On Red	0	36	0	36
Policy/Weather Registration Issues				
Sun Glare	0	5	0	5
Paper Plates	0	6	1	7
<b>Total</b>	1	95	7	103
<b>Sub Total Violations</b>	31	116	53	200
Less in Progress	0	0	0	0
<b>Available For Prosecution</b>	31	116	53	200
<b>Less Rejects</b>				
Camera Malfunction				
Face Camera Focus Blurry	0-00%	1-01%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	1-01%	0-00%	1-00%
Police Rejects Process Issues				
Driver Unidentifiable images poor	0-00%	3-03%	0-00%	3-02%
Too Old	0-00%	0-00%	1-02%	1-00%
<b>Total</b>	0-00%	5-04%	1-02%	6-03%
<b>Notices Printed</b>	31-100%	111-96%	52-98%	194-97%

# Customer Management Report (Encinitas) All Detection Types

01-Jul-2010 to 01-Aug-2010

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
Total Violations		71	362	55	488
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	3	22	4	29
	Plate Obstruction	4	23	0	27
	Vehicle Obstruction	0	21	2	23
Police Rejects	Emergency Vehicle Responding	4	3	0	7
	Face Obstruction	0	2	0	2
	Safe Turn On Red	0	59	0	59
Policy/Weather	Extended Vehicle	0	1	0	1
	Sun Glare	3	73	3	79
	Weather/Nature	0	1	0	1
Registration Issues	Can Not Identify State	0	1	0	1
	Paper Plates	0	4	1	5
Total		14	210	10	234
Sub Total Violations		57	152	45	254
Less in Progress		0	0	0	0
Available For Prosecution		57	152	45	254
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Flash	0-00%	2-01%	0-00%	2-01%
	Face Camera Focus Blurry	0-00%	1-01%	0-00%	1-00%
	Face Not in Frame	0-00%	3-02%	0-00%	3-01%
	Misc. Camera Issue	0-00%	1-01%	0-00%	1-00%
	Plate Burn Out	2-04%	0-00%	0-00%	2-01%
	Plate Not in Frame	1-02%	1-01%	0-00%	2-01%
	Rear Plate Camera Blurry	1-02%	0-00%	0-00%	1-00%
	Rear Plate Flash Inappropriate	1-02%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	4-03%	0-00%	4-02%
	Red-light not visible in	2-04%	0-00%	0-00%	2-01%
Process Issues	Too Old	0-00%	2-01%	2-04%	4-02%
Total		7-12%	14-09%	2-04%	23-09%
Notices Printed		50-88%	138-91%	43-96%	231-91%

# Customer Management Report (Encinitas) All Detection Types

01-Sep-2010 to 01-Oct-2010

Operator Id: %

	ENC-ECEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
Total Violations	68	188	79	335
<b>Less Uncontrollable Factors</b>				
Obstruction				
Driver Obstruction/Duckers	2	9	2	13
Motor Cycle Helmet	0	1	0	1
Plate Obstruction	3	13	0	16
Vehicle Obstruction	0	10	2	12
Police Rejects				
Emergency Vehicle Responding	1	1	0	2
Face Obstruction	0	1	3	4
Safe Turn On Red	0	14	0	14
Policy/Weather				
Extended Vehicle	0	2	0	2
Sun Glare	0	36	5	41
Weather/Nature	0	1	1	2
Registration Issues				
Paper Plates	2	6	0	8
Total	8	94	13	115
Sub Total Violations	60	94	66	220
Less in Progress	0	0	0	0
Available For Prosecution	60	94	66	220
<b>Less Rejects</b>				
Camera Malfunction				
Face Camera Focus Blurry	0-00%	1-01%	0-00%	1-00%
Plate Burn Out	1-02%	0-00%	0-00%	1-00%
Plate Not in Frame	1-02%	0-00%	0-00%	1-00%
Police Rejects				
Driver Unidentifiable images poor	0-00%	6-06%	1-02%	7-03%
Unclear Scene Image	0-00%	1-01%	0-00%	1-00%
Process Issues				
Too Old	0-00%	1-01%	0-00%	1-00%
Total	2-03%	9-10%	1-02%	12-05%
Notices Printed	58-97%	85-90%	65-98%	208-95%

*BLI)c*