

Customer Management Report (Escondido) All Detection Types

01-May-2013 to 31-May-2013

Operator Id: %

	ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents	155	45	148	23	50	35	133	54	59	47	254	137	60	56	167	1423
Less Uncontrollable Factors																
Obstruction	Driver Obstruction/Duckers	3	2	2	0	0	4	6	1	0	2	3	1	7	3	34
	Motor Cycle Helmet	0	0	0	0	1	3	1	0	4	1	1	0	5	0	16
	Plate Obstruction	3	1	1	0	0	2	4	1	0	2	2	3	1	0	20
	Vehicle Obstruction	0	2	0	0	0	0	0	0	0	3	2	0	1	1	9
Police Rejects	Emergency Vehicle Responding	8	3	4	2	1	1	1	1	1	1	0	2	1	0	26
	Face Obstruction	2	1	2	1	0	2	3	1	0	1	2	1	1	3	20
	Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
	Invalid Offense	0	0	0	0	0	1	0	0	0	1	0	0	0	0	2
	Multiple vehicles in frame	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	On or Passed the Stop Bar (PD).	27	9	54	1	20	4	2	1	28	64	9	18	2	8	276
	Plate Obstruction (PD)	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Police Discretion	2	2	0	0	0	2	1	4	1	5	1	0	0	6	24
	Safe Turn On Red	27	1	50	1	0	19	0	0	3	64	14	1	0	2	182
	Sun Glare	6	2	1	0	0	5	1	4	0	5	6	3	0	4	37
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	1	0	0	1	1	2	0	0	5
	Sun Glare	17	4	6	2	13	13	4	8	2	22	29	7	14	14	157
	Yellow with Red Light	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Registration Issues	Out of Country Plate	0	0	0	0	0	0	0	0	0	2	0	0	0	0	2
	Paper Plates	3	1	3	2	2	7	0	2	2	15	4	0	3	5	50
	Wrong or No DMV	0	0	0	0	0	0	0	0	0	1	1	0	0	0	2
Total		100	28	123	9	36	63	24	23	41	192	75	38	35	46	866
Sub Total Violations		55	17	25	14	14	70	30	36	6	62	62	22	21	121	557
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Generated By: KNAVARRO

Generated On: 6/4/2013 11:03:02 AM

Customer Management Report (Escondido) All Detection Types

01-May-2013 to 31-May-2013

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Available For Prosecution		55	17	25	14	14	2	70	30	36	6	62	62	22	21	121	557
Less Rejects																	
Camera Malfunction	Face Not in Frame	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-05%	0-00%	3-01%
	Misc Camera Issue	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	2-00%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-09%	0-00%	1-01%	5-01%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	3-01%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	1-01%	2-07%	1-03%	0-00%	1-02%	0-00%	1-05%	0-00%	1-01%	8-01%
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	2-03%	4-06%	0-00%	0-00%	1-01%	9-02%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
Total		2-04%	0-00%	0-00%	0-00%	3-21%	0-00%	4-06%	2-07%	1-03%	0-00%	4-06%	8-13%	3-14%	1-05%	3-02%	31-06%
Approved Violations		53-96%	17-100%	25-100%	14-100%	11-79%	2-100%	66-94%	28-93%	35-97%	6-100%	58-94%	54-87%	19-86%	20-95%	118-98%	526-94%
Total Notices Printed		53-96%	17-100%	25-100%	14-100%	11-79%	2-100%	66-94%	28-93%	35-97%	6-100%	58-94%	54-87%	19-86%	20-95%	118-98%	526-94%

Generated By: KNAVARRO

Generated On: 6/4/2013 11:03:02 AM

Customer Management Report (Escondido) All Detection Types

01-Jun-2013 to 30-Jun-2013

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents		147	35	166	30	41	37	146	43	71	52	155	151	34	56	163	1327
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	1	1	1	0	0	0	1	11	3	1	2	4	2	12	2	41
	Motor Cycle Helmet	0	0	0	0	0	0	2	0	0	4	0	1	0	1	0	8
	Plate Obstruction	2	0	0	0	1	0	1	0	2	0	1	6	1	1	1	16
	Vehicle Obstruction	4	1	1	0	0	0	1	0	0	0	0	0	1	2	2	1
Police Rejects	Emergency Vehicle Responding	2	1	5	2	0	0	5	1	2	0	2	0	1	0	2	23
	Face Obstruction	2	0	0	0	0	0	0	1	1	0	1	4	0	1	0	10
	Multiple vehicles in frame	1	0	0	0	0	0	0	0	0	0	0	1	0	0	0	2
	On or Passed the Stop Bar (PD)	13	9	47	1	20	22	6	2	7	26	26	14	2	2	7	204
	Plate Obstruction (PD)	0	0	0	0	0	0	0	0	1	0	0	0	1	0	1	3
	Plate Unidentifiable	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1	2
	Police Discretion	1	0	0	0	1	1	6	4	2	1	4	6	3	2	11	42
	Safe Turn On Red	46	0	80	2	1	2	31	0	0	1	58	16	0	0	3	240
	Sun Glare	3	3	0	1	0	0	2	1	5	0	3	0	0	2	8	28
	Policy/Weather	Extended Vehicle	0	0	0	0	0	0	0	0	1	0	0	0	0	1	0
Sun Glare		14	9	3	3	3	4	10	3	4	1	6	21	2	9	10	102
Registration Issues	Out of Country Plate	1	0	0	0	0	0	1	0	0	0	0	1	0	0	0	3
	Paper Plates	4	1	6	2	2	2	5	0	1	0	10	6	0	1	5	45
	Wrong or No DMV	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Total		95	25	143	11	28	31	71	23	29	34	114	81	14	34	52	785
Sub Total Violations		52	10	23	19	13	6	75	20	42	18	41	70	20	22	111	542
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		52	10	23	19	13	6	75	20	42	18	41	70	20	22	111	542

Less Rejects

Generated By: KNAVARRO

Generated On: 9/4/2013 9:14:40 AM

Customer Management Report (Escondido) All Detection Types

01-Jun-2013 to 30-Jun-2013

Operator Id: %

		ESC-02ES-01	ESC-AUVVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Camera Malfunction	Face Not in Frame	0-00%	1-10%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Misc Camera Issue	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-07%	0-00%	1-05%	0-00%	0-00%	4-01%
Police Rejects	Driver Unidentifiable images poor	4-08%	0-00%	0-00%	2-11%	1-08%	0-00%	2-03%	0-00%	3-07%	0-00%	3-07%	4-06%	1-05%	1-05%	3-03%	24-04%
	Red-light not visible in	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total		5-10%	2-20%	1-04%	2-11%	1-08%	0-00%	2-03%	0-00%	4-10%	0-00%	6-15%	4-06%	2-10%	1-05%	3-03%	33-06%
Approved Violations		47-90%	8-80%	22-96%	17-89%	12-92%	6-100%	73-97%	20-100%	38-90%	18-100%	35-85%	66-94%	18-90%	21-95%	108-97%	509-94%
Total Notices Printed		47-90%	8-80%	22-96%	17-89%	12-92%	6-100%	73-97%	20-100%	38-90%	18-100%	35-85%	66-94%	18-90%	21-95%	108-97%	509-94%

Generated By: KNAVARRO

Generated On: 9/4/2013 9:14:40 AM

Customer Management Report (Escondido) All Detection Types

01-Jul-2013 to 31-Jul-2013

Operator Id: %

	ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL	
Total Processed Incidents	228	44	142	28	45	44	155	43	72	58	209	147	44	91	177	1527	
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	14	2	3	2	0	3	6	2	1	4	7	3	20	5	72	
	Motor Cycle Helmet	0	0	0	0	0	1	1	0	3	0	0	0	4	3	12	
	Plate Obstruction	2	0	0	0	1	3	3	3	0	2	2	2	1	1	20	
	Vehicle Obstruction	6	1	0	0	1	0	0	1	0	1	1	1	4	0	16	
Police Rejects	Citation Issued manually	0	0	0	0	0	0	0	0	0	0	0	0	1	0	1	
	Emergency Vehicle Responding	3	3	4	1	1	2	0	5	5	1	1	2	0	2	33	
	Face Obstruction	0	1	0	1	0	0	1	1	0	1	1	0	0	1	7	
	Multiple vehicles in frame	1	0	0	0	0	1	0	0	0	0	0	0	0	0	2	
	On or Passed the Stop Bar (PD).	6	6	32	0	14	28	4	3	4	24	28	7	10	2	7	175
	Plate Obstruction (PD)	0	0	0	0	0	0	1	0	1	0	0	0	1	0	3	
	Police Discretion	1	3	0	1	3	5	0	2	2	3	1	2	1	7	31	
	Safe Turn On Red	67	0	73	0	2	24	2	0	2	77	22	1	0	7	278	
	Sun Glare	8	2	3	1	4	5	1	0	1	1	3	1	0	10	40	
	Yielding to an Emergency	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1	
Policy/Weather	Extended Vehicle	1	0	0	0	0	0	0	0	1	2	0	1	1	0	6	
	Sun Glare	38	13	3	2	6	14	4	8	3	19	40	2	16	25	199	
Registration Issues	Out of Country Plate	1	0	1	0	0	1	0	0	2	0	0	0	0	0	5	
	Paper Plates	2	1	3	5	4	3	0	2	3	6	6	5	2	5	47	
	Wrong or No DMV	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1	
Total		150	32	122	13	34	66	22	29	48	145	92	30	53	73	949	
Sub Total Violations		78	12	20	15	11	89	21	43	10	64	55	14	38	104	578	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution		78	12	20	15	11	89	21	43	10	64	55	14	38	104	578	

Generated By: KNAVARRO

Generated On: 9/4/2013 9:17:05 AM

Customer Management Report (Escondido) All Detection Types

01-Jul-2013 to 31-Jul-2013

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Less Rejects																	
Camera Malfunction	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-01%	2-00%
	Face Camera No Flash	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	1-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	1-07%	0-00%	0-00%	3-01%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	1-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	2-00%
	Rear Plate Camera Blurry	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	2-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	1-02%	0-00%	1-07%	0-00%	3-01%
Police Rejects	Driver Unidentifiable images poor	3-04%	1-08%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	2-20%	3-05%	3-05%	1-07%	1-03%	0-00%	15-03%
	Plate Unclear	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
	Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Total		6-08%	1-08%	0-00%	0-00%	1-09%	0-00%	5-06%	1-05%	2-05%	2-20%	7-11%	5-09%	4-29%	1-03%	1-01%	36-06%
Approved Violations		72-92%	11-92%	20-100%	15-100%	10-91%	4-100%	84-94%	20-95%	41-95%	8-80%	57-89%	50-91%	10-71%	37-97%	103-99%	542-94%
Total Notices Printed		72-92%	11-92%	20-100%	15-100%	10-91%	4-100%	84-94%	20-95%	41-95%	8-80%	57-89%	50-91%	10-71%	37-97%	103-99%	542-94%

Generated By: KNAVARRO

Generated On: 9/4/2013 9:17:05 AM

Customer Management Report (Escondido) All Detection Types

01-Aug-2013 to 31-Aug-2013

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents		218	37	162	16	37	31	171	41	64	39	219	140	37	98	185	1495
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	5	5	3	0	4	0	5	8	1	1	4	5	0	13	3	57
	Motor Cycle Helmet	0	0	0	1	0	0	2	0	1	2	3	3	0	4	1	17
	Plate Obstruction	7	0	1	0	0	0	4	2	4	2	4	2	2	0	1	29
	Vehicle Obstruction	2	0	2	0	0	0	0	0	1	0	2	1	0	5	0	13
Police Rejects	Emergency Vehicle Responding	0	1	3	1	0	1	1	0	0	0	0	0	0	1	0	8
	Face Obstruction	2	1	0	0	0	0	0	0	1	0	0	2	0	0	4	10
	Multiple vehicles in frame	1	0	0	0	0	0	0	0	1	0	0	1	1	1	0	5
	On or Passed the Stop Bar (PD)	3	3	26	1	2	9	2	1	1	8	26	3	9	1	6	101
	Plate Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	1
	Police Discretion	12	4	13	1	2	3	20	4	5	1	23	14	4	11	20	137
	Safe Turn On Red	66	0	52	0	2	1	17	0	0	4	50	13	1	0	3	209
	Sun Glare	8	2	0	0	1	0	1	2	0	1	1	1	0	0	1	18
	Policy/Weather	Extended Vehicle	0	0	0	0	0	0	0	0	1	0	0	0	0	2	0
	Sun Glare	29	6	3	1	13	2	22	3	2	1	11	25	6	16	18	158
Registration Issues	Out of Country Plate	0	0	0	0	0	0	0	0	0	0	1	0	1	0	0	2
	Paper Plates	7	0	5	0	0	1	1	1	2	2	12	2	3	1	3	40
Total		142	22	108	5	24	17	75	21	20	22	137	72	27	56	60	808
Sub Total Violations		76	15	54	11	13	14	96	20	44	17	82	68	10	42	125	687
Less in Progress		32	5	31	5	5	9	22	10	8	4	31	20	4	15	34	235
Available For Prosecution		44	10	23	6	8	5	74	10	36	13	51	48	6	27	91	452
Less Rejects																	
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	2-00%
	Face Camera Focus Blurry	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: KNAVARRO

Generated On: 9/4/2013 9:18:04 AM

Customer Management Report (Escondido) All Detection Types

01-Aug-2013 to 31-Aug-2013

Operator Id: %

	ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Face Camera No Flash	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Face Not in Frame	2-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-04%	0-00%	4-01%
Misc Camera Issue	0-00%	0-00%	2-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	3-01%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	2-00%
Plate Not in Frame	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	1-02%	0-00%	0-00%	0-00%	1-01%	3-01%
Rear Plate Flash Inappropriate	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-17%	0-00%	0-00%	2-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	9-20%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	9-02%
Police Rejects																
Driver Unidentifiable images poor	4-09%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-01%	7-02%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues																
Too Old	7-16%	0-00%	12-52%	1-17%	2-25%	5-100%	9-12%	1-10%	5-14%	6-46%	10-20%	10-21%	1-17%	3-11%	9-10%	81-18%
Total	25-57%	2-20%	14-61%	1-17%	3-38%	5-100%	12-16%	2-20%	6-17%	6-46%	13-25%	13-27%	2-33%	4-15%	11-12%	119-26%
Approved Violations	19-43%	8-80%	9-39%	5-83%	5-62%	0-00%	62-84%	8-80%	30-83%	7-54%	38-75%	35-73%	4-67%	23-85%	80-88%	333-74%
Total Notices Printed	19-43%	8-80%	9-39%	5-83%	5-62%	0-00%	62-84%	8-80%	30-83%	7-54%	38-75%	35-73%	4-67%	23-85%	80-88%	333-74%

Generated By: KNAVARRO

Generated On: 9/4/2013 9:18:04 AM