

# Customer Management Report (Hawthorne) All Detection Types

01-Jun-2019 to 30-Jun-2019

Operator Id: %

	HA-HAES-01	HA-HAES-03	HA-HAIM-01	HA-HAIM-03	HA-HIRO-01	HA-IMFR-01	HA-ROHI-01	TOTAL
<b>Total Processed Incidents</b>	24	80	229	28	380	213	694	1648
<b>Less Uncontrollable Factors</b>								
Obstruction	Driver Obstruction/Duckers							
	1	4	29	0	5	3	59	101
	Motor Cycle Helmet							
	0	0	0	0	1	0	4	5
	Plate Obstruction							
	1	0	11	2	6	1	4	25
	Signal Obstruction							
	0	0	0	0	0	0	1	1
	Vehicle Obstruction							
	0	2	0	0	7	3	28	40
Police Rejects	Driver Obstructed							
	0	1	14	1	4	2	46	68
	Incorrect Plate on Vehicle							
	0	0	0	0	0	0	1	1
	Incorrect/Incomplete DMV							
	0	3	0	0	7	5	8	23
	Multiple vehicles in frame							
	0	0	2	0	1	0	29	32
	On or Passed the Stop Bar (PD)							
	0	4	6	0	40	14	1	65
	Police Discretion							
	0	0	1	0	0	0	1	2
	Sun Glare							
	0	0	1	0	1	2	0	4
Policy/Weather	Extended Vehicle							
	0	1	0	0	1	0	4	6
	Sun Glare							
	2	20	41	6	10	46	15	140
Registration Issues	Out of Country Plate							
	0	0	0	0	0	0	1	1
	Paper Plates							
	0	3	9	1	9	10	14	46
	Wrong or No DMV							
	0	0	0	0	0	0	1	1
<b>Total</b>	4	38	114	10	92	86	217	561
<b>Sub Total Violations</b>	20	42	115	18	288	127	477	1087
Less in Progress	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>	20	42	115	18	288	127	477	1087
<b>Less Rejects</b>								
Camera Malfunction	Databar Unreadable/Incorrect							
	0-00%	0-00%	0-00%	0-00%	2-01%	2-02%	0-00%	4-00%
	Digital Distortion							
	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera Flash							
	1-05%	0-00%	1-01%	0-00%	1-00%	0-00%	6-01%	9-01%
	Face Camera Focus Blurry							
	0-00%	4-10%	5-04%	0-00%	2-01%	0-00%	1-00%	12-01%
	Face Camera No Flash							
	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	2-00%	3-00%
	Face Not in Frame							
	1-05%	2-05%	4-03%	0-00%	4-01%	1-01%	14-03%	26-02%
	Plate Burn Out							
	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
	Plate Not in Frame							
	0-00%	0-00%	16-14%	0-00%	1-00%	0-00%	5-01%	22-02%
	Rear Plate Camera Blurry							
	1-05%	2-05%	1-01%	1-06%	0-00%	1-01%	0-00%	6-01%
	Rear Plate Flash Inappropriate							
	0-00%	0-00%	3-03%	0-00%	0-00%	0-00%	0-00%	3-00%
	Rear Plate No Flash							
	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Scene Image Flash Inappropriate							
	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By:

Generated On: 11/30/2020 11:43:14 AM

# Customer Management Report (Hawthorne) All Detection Types

01-Jun-2019 to 30-Jun-2019

Operator Id: %

	HA-HAES-01	HA-HAES-03	HA-HAIM-01	HA-HAIM-03	HA-HIRO-01	HA-IMFR-01	HA-ROHI-01	TOTAL
Police Driver Unidentifiable images poor	1-05%	7-17%	23-20%	5-28%	6-02%	5-04%	18-04%	65-06%
Rejects								
Total	4-20%	17-40%	54-47%	6-33%	17-06%	9-07%	47-10%	154-14%
Approved Violations	16-80%	25-60%	61-53%	12-67%	271-94%	118-93%	430-90%	933-86%
Total Notices Printed	16-80%	25-60%	61-53%	12-67%	271-94%	118-93%	430-90%	933-86%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By:

Generated On: 11/30/2020 11:43:14 AM