

Customer Management Report (San Mateo) All Detection Types

01-Sep-2012 to 30-Sep-2012

Operator Id: %

		SAN-MATEO-01	SAN-MATEO-02	SAN-MATEO-03	SAN-MATEO-04	SAN-MATEO-05	TOTAL
Total Processed Incidents:		270	84	111	59	751	1225
Less Uncontrollable Factors							
Obstruction	Driver Obstruction/Duckers	12	4	4	0	14	34
	Motor Cycle Helmet	0	0	0	0	2	2
	Plate Obstruction	12	0	1	2	98	111
	Vehicle Obstruction	4	0	3	2	51	60
Police Rejects	Emergency Vehicle Responding	1	1	0	2	7	11
	On or Passed the Stop Bar (PD)	0	1	14	1	141	157
	Plate Obstruction (PD)	0	0	1	0	0	1
	Plate Unidentifiable	0	0	1	0	1	2
	Slow Roll - right turn	0	0	1	0	10	11
	Sun Glare	1	0	0	0	0	1
Policy/Weather	Extended Vehicle	1	1	0	0	0	2
	Sun Glare	41	6	0	9	4	59
Registration Issues	Paper Plates	7	0	3	2	17	29
	Wrong or No DMV	0	0	0	0	1	1
Total		79	12	28	18	344	481
Sub Total Violations		191	22	83	41	407	744
Loss In Progress		0	0	0	0	0	0
Available For Prosecution		191	22	83	41	407	744
Less Rejects							
Camera Malfunction	Face Camera Flash	0-00%	1-05%	0-00%	0-00%	0-00%	1-00%
	Face Camera No Flash	0-00%	1-05%	0-00%	0-00%	0-00%	1-00%
	Plate Burn Out	2-01%	1-05%	0-00%	0-00%	7-02%	10-01%
	Plate Not In Frame	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%

Generated By: MPANGALOS

Generated On: 6/14/2013 2:45:19 PM

Customer Management Report (San Mateo) All Detection Types
 01-Sep-2012 to 30-Sep-2012 Operator Id: %

	SAN-HIU-01	SAN-HIN-01	SAN-HIN-03	SAN-HIS-01	SAN-SHI-01	TOTAL
Rear Plate Camera Blurry	3-02%	0-00%	0-00%	0-00%	1-00%	4-01%
Rear Plate Flash Inappropriate	0-00%	1-05%	1-01%	0-00%	9-02%	11-01%
Scene Image Flash Inappropriate	0-03%	0-00%	0-00%	0-00%	6-01%	6-01%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	5-01%	5-01%
Police Rejects Driver Unidentifiable Images poor	0-00%	0-00%	0-00%	1-02%	1-00%	2-00%
Total	6-03%	4-18%	1-01%	1-02%	30-07%	41-08%
Approved Violations	100-97%	100-92%	100-90%	100-98%	97-95%	100-94%
Total Notices Printed	100-97%	100-92%	100-90%	100-98%	97-95%	100-94%

Generated By: MPANGALOS
 Generated On: 6/14/2013 2:45:19 PM

Customer Management Report (San Mateo) All Detection Types

01-Oct-2012 to 31-Oct-2012

Operator Id: %

	SAN-MTL-01	SAN-MND-01	SAN-MND-03	SAN-MSC-01	SAN-MSC-01	TOTAL
Total Processed Incidents:	303	32	100	45	718	1198
Less Uncontrollable Factors						
Obstruction						
Driver Obstruction/Duckers	20	1	3	3	11	38
Motor Cycle Helmet	3	0	0	0	1	4
Plate Obstruction	10	3	0	2	75	90
Vehicle Obstruction	3	1	0	0	51	55
Police Rejects						
Emergency Vehicle Responding	2	2	0	1	5	10
Multiple vehicles in frame	0	0	1	0	2	3
On or Passed the Stop Bar (PD)	0	0	7	0	140	147
Plate Unidentifiable	1	0	0	0	1	2
Slow Roll - right turn	0	0	2	0	14	16
Policy/Weather						
Extended Vehicle	2	1	1	0	0	4
Sun Glare	38	4	0	6	1	47
Weather/Nature	0	1	0	1	0	2
Registration Issues						
Paper Plates	4	0	5	0	18	27
Total	61	13	19	19	319	446
Sub Total Violations	222	19	81	32	399	763
Less In Progress	0	0	0	0	0	0
Available For Prosecution	222	19	81	32	399	763
Less Rejects						
Camera Malfunction						
Face Camera Flash	0-00%	0-00%	0-00%	1-03%	0-00%	1-00%
Face Camera Focus Blurry	1-00%	0-00%	0-00%	1-03%	0-00%	2-00%
Face Not In Frame	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Image Missing	0-00%	0-00%	0-00%	2-00%	0-00%	2-00%

Generated By: MPANGALOS
 Generated On: 5/14/2013 2:46:08 PM

Customer Management Report (San Mateo) All Detection Types

01-Oct-2012 to 31-Oct-2012

Operator Id: %

	SAN-HUD-01	SAN-HUN-01	SAN-HUN-03	SAN-HUN-01	SAN-SAN-01	TOTAL
Misc Camera Issue	0-00%	0-00%	0-00%	1-03%	7-02%	8-01%
Plate Burn Out	6-03%	0-00%	0-00%	1-03%	11-03%	18-02%
Plate Not In Frame	0-00%	0-00%	0-00%	0-00%	10-03%	10-01%
Rear Plate Camera Blurry	1-00%	1-08%	0-00%	0-00%	2-01%	4-01%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	7-02%	7-01%
Rear Plate No Flash	1-00%	1-05%	0-00%	0-00%	0-00%	2-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	4-01%	4-01%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	4-01%	4-01%
Police Rejects						
Insufficient Strobe Lighting	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	3-01%	3-00%
Total	9-04%	2-11%	1-01%	6-10%	49-12%	67-09%
Approved Violations	213-90%	17-50%	30-95%	26-81%	630-89%	666-91%
Total Notices Printed	213-90%	17-50%	30-95%	26-81%	630-89%	666-91%

Generated By: MPANGALOS
 Generated On: 5/14/2013 2:46:08 PM

Customer Management Report (San Mateo) All Detection Types

12-Nov-0012 to 30-Nov-2012

Operator Id: %

	SAN-MHU-01	SAN-MNO-01	SAN-MNO-03	SAN-HSA-01	SAN-SAH-01	TOTAL
Total Processed Incidents	18646	6774	10514	6916	61839	102888
Less Uncontrollable Factors						
Obstruction	1608	218	469	224	2063	4474
Driver Obstruction/Duckers	30	0	1	5	62	98
Motor Cycle Helmet	681	191	322	231	6291	7696
Plate Obstruction	0	0	14	0	12	26
Signal Obstruction	174	86	170	106	2707	3221
Vehicle Obstruction	0	0	0	0	1	1
Police Rejects	0	10	8	13	138	167
Citation Issued manually	247	230	65	188	306	1006
Driver Unidentifiable	0	0	0	0	1	1
Emergency Vehicle Responding	9	1	3	3	10	26
Funeral Procession/Police	5	0	2	1	23	31
Incorrect Plate on Vehicle	1	35	38	26	99	198
Incorrect/Incomplete DMV	3	1	16	7	141	168
Invalid Offense	8	5	186	5	3044	3247
Multiple vehicles in frame	1	0	1	0	3	5
On or Passed the Stop Bar (PD)	20	5	10	1	67	103
Plate Obstruction (PD)	0	0	0	1	0	1
Plate Unidentifiable	18	8	694	8	8641	9267
Police Discretion	1	0	50	0	818	869
Safe Turn On Red	21	4	16	3	16	62
Slow Roll - right turn	2	1	2	0	4	9
Sun Glare	1	0	0	0	1	2
Weather Conditions	1	0	0	0	1	2
Yielding to an Emergency						

Generated By: MPANGALOS
 Generated On: 6/14/2013 2:46:52 PM

Customer Management Report (San Mateo) All Detection Types

12-Nov-0012 to 30-Nov-2012

Operator Id: %

	SAN-411-01	SAN-111-01	SAN-111-03	SAN-111-01	SAN-111-01	TOTAL
Policy/Weather						
Extended Vehicle	85	13	23	32	67	190
Sun Glare	1789	829	808	614	1029	4677
Weather/Nature	88	29	52	28	135	332
Yellow with Red Light	2	0	0	0	2	4
Registration Issues						
Can Not Identify State	22	9	34	11	53	129
Gender Match	0	0	0	1	1	2
Out of Country Plate	7	0	2	4	30	43
Paper Plates	454	140	264	187	1599	2804
Wrong or No DMV	31	43	64	59	243	430
Total	5176	1637	2877	1714	27595	39089
Sub Total Violations	13470	4137	7637	4201	34284	65699
Less in Progress	0	0	0	0	0	0
Available For Prosecution	13470	4137	7637	4201	34284	65699
Less Rejects						
Camera Malfunction						
Databar Unreadable/Incorrect	1-00%	3-00%	4-00%	0-00%	4-00%	12-00%
Digital Distortion	0-00%	1-00%	3-00%	3-00%	12-00%	19-00%
Face Camera Flash	46-00%	61-01%	61-01%	44-01%	171-00%	388-01%
Face Camera Focus Blurry	88-01%	82-02%	147-02%	71-02%	219-01%	605-01%
Face Camera No Flash	132-01%	24-01%	84-01%	85-01%	208-01%	481-01%
Face Not in Frame	36-00%	69-02%	36-01%	36-01%	98-00%	217-00%
Image Missing	29-00%	20-00%	29-00%	59-01%	342-01%	476-01%
Misc Camera Issue	26-00%	64-02%	74-01%	116-03%	1647-05%	1827-03%
Plate Burn Out	81-01%	36-01%	10-00%	10-00%	96-00%	236-00%
Plate Not In Frame	37-00%	16-00%	116-02%	1-00%	253-01%	422-01%
Rear Plate Camera Blurry	213-02%	92-02%	126-02%	96-02%	61-00%	617-01%
Rear Plate Flash Inappropriate	34-00%	12-00%	10-00%	11-00%	53-00%	120-00%


Generated By: MPANGALOS
 Generated On: 8/14/2013 2:46:52 PM

SAN MATEO POLICE DEPARTMENT
 CONTROL DOCUMENT
 DO NOT DUPLICATE

Customer Management Report (San Mateo) All Detection Types
 12-Nov-0012 to 30-Nov-2012 Operator Id: %

	SANMHILO1	SANMHILO1	SANMHILO3	SANMHILO1	SANMHILO1	TOTAL
Rear Plate No Flash	13-00%	2-00%	2-00%	0-00%	20-00%	37-00%
Scene Image Blurry	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Scene Image Flash Inappropriate	16-00%	1-00%	20-00%	10-00%	55-00%	102-00%
Scene Image No Flash	16-00%	14-00%	30-00%	10-00%	50-00%	122-00%
Police Rejects						
Driver Unidentifiable Images poor	36-00%	16-00%	58-01%	26-01%	87-00%	224-00%
Incorrect Details	0-00%	1-00%	6-00%	6-00%	34-00%	46-00%
Incorrect Speed	3-00%	1-00%	1-00%	0-00%	20-00%	25-00%
Insufficient Strobe Lighting	0-00%	0-00%	0-00%	0-00%	4-00%	4-00%
No Images	3-00%	0-00%	3-00%	2-00%	3-00%	11-00%
No Video	2-00%	6-00%	0-00%	1-00%	8-00%	16-00%
Plate Unclear	0-00%	0-00%	3-00%	1-00%	13-00%	17-00%
Red-light not visible in	4-00%	1-00%	23-00%	0-00%	4-00%	32-00%
Unclear Scene Image	33-00%	6-00%	29-00%	4-00%	60-00%	132-00%
Vehicle On or Passed Stop Line	2-00%	2-00%	14-00%	4-00%	50-00%	72-00%
Process Issues						
Too Old	72-01%	22-01%	35-00%	22-01%	204-01%	365-01%
Total	923-07%	550-13%	919-12%	570-14%	3647-11%	6000-10%
Approved Violations	12947-93%	3597-87%	6610-86%	3821-80%	30007-59%	59990-10%
Total Notices Printed	12947-93%	3597-87%	6610-86%	3821-80%	30007-59%	59990-10%

Generated By: MPANGALOS
 Generated On: 8/14/2013 2:46:52 PM



SAN MATEO POLICE DEPARTMENT
 CONTROL DOCUMENT
 DO NOT DUPLICATE

Customer Management Report (San Mateo) All Detection Types

01-Dec-2012 to 31-Dec-2012

Operator Id: %

	SAN-4RL-01	SAN-HIN-01	SAN-HIN-03	SAN-HIS-01	SAN-SAR-01	TOTAL
Total Processed Incidents	118	44	107	35	487	791
Less Uncontrollable Factors						
Obstruction						
Driver Obstruction/Duckers	4	1	5	0	10	20
Plate Obstruction	6	3	4	3	43	59
Vehicle Obstruction	0	0	2	0	49	51
Police						
Rejects						
Emergency Vehicle Responding	1	0	0	1	7	9
Multiple vehicles in frame	0	0	1	0	3	4
On or Passed the Stop Bar (PD)	0	0	10	0	63	73
Plate Unidentifiable	0	0	0	0	2	2
Safe Turn On Red	0	0	1	0	1	2
Slow Roll - right turn	0	0	1	0	7	8
Sun Glare	0	0	1	0	0	1
Policy/Weather						
or						
Extended Vehicle	1	0	0	0	0	1
Sun Glare	3	2	1	2	6	14
Weather/Nature	0	0	0	0	3	3
Registration						
Issues						
Paper Plates	5	1	4	0	17	27
Wrong or No DMV	1	0	0	0	0	1
Total	21	7	30	6	211	275
Sub Total Violations	87	37	77	29	276	516
Less In Progress	0	0	0	0	0	0
Available For Prosecution	87	37	77	29	276	516
Less Rejects						
Camera						
Malfunction						
Face Camera Flash	0-00%	0-00%	0-00%	1-03%	0-00%	1-00%
Face Camera No Flash	0-00%	0-00%	0-00%	1-03%	0-00%	1-00%
Image Missing	0-00%	0-00%	0-00%	1-03%	1-00%	2-00%

Generated By: MPANGALOS

Generated On: 8/14/2013 2:48:05 PM

Customer Management Report (San Mateo) All Detection Types
 01-Dec-2012 to 31-Dec-2012 Operator Id: %

	SAN-4HJ-D1	10-ONLE-RV3	SAN-4HJ-D1	SAN-4HJ-D1	SAN-4HJ-D1	TOTAL
Misc Camera Issue	0-00%	0-00%	0-00%	4-14%	0-00%	4-01%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	7-03%	7-01%
Rear Plate Camera Blurry	1-01%	2-05%	0-00%	0-00%	1-00%	4-01%
Rear Plate Flash Inappropriate	1-01%	1-03%	0-00%	0-00%	3-01%	5-01%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	2-01%	2-00%
Driver Unidentifiable Images poor	0-00%	0-00%	0-00%	0-00%	6-02%	6-01%
Too Old	0-00%	0-00%	1-01%	0-00%	2-01%	3-01%
Total	2-02%	3-06%	1-01%	7-24%	22-08%	35-07%
Approved Violations	85-98%	86-00%	76-99%	77-75%	91-92%	78-99%
Total Notices Printed	86-96%	84-92%	76-99%	77-75%	91-92%	78-99%

Generated By: MPANGALOS
 Generated On: 5/14/2013 2:48:05 PM

Customer Management Report (San Mateo) All Detection Types

01-Jan-2013 to 31-Jan-2013

Operator Id: %

	SAN-4HL-01	SAN-4HN-01	SAN-4NE-03	SAN-4SA-01	SAN-4SA-10	TOTAL
Total Processed Incidents	190	37	88	18	679	906
Less Uncontrollable Factors						
Obstruction	8	2	2	0	7	19
Driver Obstruction/Duckers						
Plate Obstruction	10	1	1	0	65	77
Vehicle Obstruction	3	0	1	1	60	65
Police Rejects	0	2	1	1	2	6
Emergency Vehicle Responding						
Multiple vehicles in frame	0	0	1	0	3	4
On or Passed the Stop Bar (PD)	0	0	5	0	96	101
Slow Roll - right turn	0	0	0	0	15	15
Policy/Weather	17	2	0	3	9	31
Sun Glare						
Weather/Nature	0	0	0	0	1	1
Registration Issues	5	1	2	1	13	22
Paper Plates						
Total	43	8	13	6	261	331
Sub-Total Violations	147	29	76	12	312	576
Less In Progress	0	0	0	0	0	0
Available For Prosecution	147	29	76	12	312	576
Less Rejects						
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Databar Unreadable/Incorrect						
Face Camera Focus Blurry	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Not in Frame	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Burn Out	1-01%	0-00%	0-00%	0-00%	8-03%	8-02%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Rear Plate Camera Blurry	2-01%	8-28%	0-00%	0-00%	0-00%	10-02%
Rear Plate Flash Inappropriate	1-01%	0-00%	0-00%	0-00%	4-01%	6-01%

Generated By: MPANGALOB
 Generated On: 6/14/2013 2:48:46 PM

SAN MATEO POLICE DEPARTMENT
 CONTROL DOCUMENT
 DO NOT DUPLICATE

Customer Management Report (San Mateo) All Detection Types

01-Jan-2013 to 31-Jan-2013

Operator Id: %

	SAN-HIL-01	SAN-HIN-01	SAN-HIN-03	SAN-HSA-01	SAN-SAH-01	TOTAL
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Total	6-04%	8-28%	0-00%	0-00%	15-05%	29-05%
Approved Violations	24-96%	2-72%	75-100%	12-100%	29-95%	64-96%
Total Notices Printed	141-96%	21-72%	75-100%	12-100%	29-95%	64-96%

Generated By: MPANGALOS
 Generated On: 5/14/2013 2:48:45 PM

SAN MATEO POLICE DEPARTMENT
 CONTROL DOCUMENT
 DO NOT DUPLICATE

Customer Management Report (San Mateo) All Detection Types

01-Feb-2013 to 28-Feb-2013

Operator Id: %

	SANMATEO	SANMATEO	SANMATEO	SANMATEO	SANMATEO	TOTAL
Total Processed Incidents	170	29	117	16	528	860
Less Uncontrollable Factors						
Obstruction	11	4	5	0	8	28
Driver Obstruction/Duckers						
Motor Cycle Helmet	1	0	0	0	2	3
Plate Obstruction	4	2	3	1	70	80
Vehicle Obstruction	2	0	1	0	42	45
Police Rejects	4	1	0	1	0	6
Emergency Vehicle Responding						
Multiple vehicles in frame	0	0	0	0	3	3
On or Passed the Stop Bar (PD)	0	1	12	0	77	90
Plate Unidentifiable	0	0	1	0	1	2
Safe Turn On Red	0	0	0	0	3	3
Slow Roll - right turn	0	0	1	0	16	17
Sun Glare	0	0	2	0	0	2
Policy/Weather	2	0	1	0	0	3
Extended Vehicle						
Sun Glare	23	2	0	1	12	38
Weather/Nature	1	0	0	0	0	1
Registration Issues	1	2	4	0	18	25
Paper Plates						
Wrong or No DMV	0	0	0	0	1	1
Total	49	12	30	3	263	347
Sub Total Violations	121	17	87	13	275	513
Less In Progress	0	0	0	0	0	0
Available For Prosecution	121	17	87	13	275	513
Less Rejects						
Camera	0-00%	0-00%	0-00%	1-08%	0-00%	1-00%
Face Camera Flash						
Malfunction	0-00%	0-00%	0-00%	1-08%	0-00%	1-00%
Face Camera No Flash						

Generated By: MPANGALOS
 Generated On: 5/14/2013 2:49:20 PM

SAN MATEO POLICE DEPARTMENT
 CONTROL DOCUMENT
 DO NOT DUPLICATE

Customer Management Report (San Mateo) All Detection Types

01-Feb-2013 to 28-Feb-2013

Operator Id: %

	SAN-431L-01	SAN-431N-01	SAN-431N-03	SAN-431SA-01	SAN-431HL-01	TOTAL
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	17-08%	17-08%
Plate Burn Out	4-03%	0-00%	0-00%	0-00%	8-03%	12-02%
Rear Plate Camera Blurry	0-00%	1-06%	0-00%	0-00%	5-02%	6-01%
Rear Plate Flash Inappropriate	2-02%	0-00%	0-00%	0-00%	2-01%	4-01%
Police Rejects Process Issues						
Driver Unidentifiable Images poor	0-00%	1-06%	0-00%	1-08%	8-01%	5-01%
Too Old	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Total	6-05%	2-12%	1-01%	3-23%	35-13%	47-09%
Approved Violations	15-95%	15-08%	86-99%	100-77%	240-87%	3486-91%
Total Notices Printed	15-95%	15-08%	86-99%	100-77%	240-87%	3486-91%

Generated By: MPANGALOS
 Generated On: 6/14/2013 2:49:28 PM

SAN MATEO POLICE DEPARTMENT
 CONTROL DOCUMENT
 DO NOT DUPLICATE

Customer Management Report (San Mateo) All Detection Types

01-Feb-2013 to 28-Feb-2013

Operator Id: %

	SAN-4RL-01	SAN-HIN-01	SAN-FIN-03	SAN-HIS-01	SAN-SAR-01	TOTAL
Total Processed Incidents	170	29	117	16	528	860
Less Uncontrollable Factors						
Obstruction	11	4	5	0	8	28
Driver Obstruction/Duckers						
Motor Cycle Helmet	1	0	0	0	2	3
Plate Obstruction	4	2	3	1	70	80
Vehicle Obstruction	2	0	1	0	42	45
Police Rejects	4	1	0	1	0	6
Emergency Vehicle Responding						
Multiple vehicles in frame	0	0	0	0	3	3
On or Passed the Stop Bar (PD)	0	1	12	0	77	90
Plate Unidentifiable	0	0	1	0	1	2
Safe Turn On Red	0	0	0	0	3	3
Slow Roll - right turn	0	0	1	0	16	17
Sun Glare	0	0	2	0	0	2
Policy/Weather	2	0	1	0	0	3
Extended Vehicle						
Sun Glare	23	2	0	1	12	38
Weather/Nature	1	0	0	0	0	1
Registration Issues	1	2	4	0	18	25
Paper Plates						
Wrong or No DMV	0	0	0	0	1	1
Total	49	12	30	3	253	347
Sub Total Violations	121	17	87	13	276	513
Less In Progress	0	0	0	0	0	0
Available For Prosecution	121	17	87	13	276	513
Less Rejects						
Camera	0-00%	0-00%	0-00%	1-08%	0-00%	1-00%
Face Camera Flash						
Malfunction	0-00%	0-00%	0-00%	1-08%	0-00%	1-00%
Face Camera No Flash						

Generated By: MPANGALOS
 Generated On: 2/14/2013 2:48:28 PM

SAN MATEO POLICE DEPARTMENT
 CONTROL DOCUMENT
 DO NOT DUPLICATE

Customer Management Report (San Mateo) All Detection Types

01-Feb-2013 to 28-Feb-2013

Operator Id: %

	SAN-41U-01	SAN-41N-01	SAN-41N-03	SAN-41S-01	SAN-41H-01	TOTAL
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	17-06%	17-03%
Plate Burn Out	4-03%	0-00%	0-00%	0-00%	6-03%	12-02%
Rear Plate Camera Blurry	0-00%	1-06%	0-00%	0-00%	5-02%	6-01%
Rear Plate Flash Inappropriate	2-02%	0-00%	0-00%	0-00%	2-01%	4-01%
Police Rejects Process Issues						
Driver Unidentifiable Images poor	0-00%	1-06%	0-00%	1-08%	3-01%	5-01%
Too Old	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Total	6-08%	2-12%	1-01%	3-23%	35-13%	47-09%
Approved Violations	15-96%	16-88%	86-99%	10-77%	220-87%	488-91%
Total Notices Printed	15-96%	16-88%	86-99%	10-77%	220-87%	488-91%

Generated By: MPANGALOS
 Generated On: 5/14/2013 2:49:28 PM

SAN MATEO POLICE DEPARTMENT
 CONTROL DOCUMENT
 DO NOT DUPLICATE

Customer Management Report (San Mateo) All Detection Types

01-Mar-2013 to 30-Mar-2013

Operator Id: %

		SAN-FHL-01	SAN-HIN-01	SAN-HIN-03	SAN-HIS-01	SAN-SHH-01	TOTAL
Total Processed Incidents		201	30	105	28	548	919
Less Uncontrollable Factors							
Obstruction	Driver Obstruction/Duckers	11	0	0	1	11	23
	Motor Cycle Helmet	1	0	0	0	1	2
	Plate Obstruction	7	3	1	1	54	66
	Vehicle Obstruction	0	1	1	0	55	57
Police Rejects	Emergency Vehicle Responding	4	0	1	2	9	16
	Multiple vehicles in frame	0	0	0	0	1	1
	On or Passed the Stop Bar (FD)	0	0	6	0	66	71
	Safe Turn On Red	0	0	0	0	1	1
	Slow Roll - right turn	0	0	1	0	11	12
	Sun Glare	1	0	0	0	1	2
Policy/Weather	Extended Vehicle	0	1	0	1	2	4
	Sun Glare	26	3	1	6	5	40
	Weather/Nature	0	0	1	0	2	3
Registration Issues	Out of Country Plate	0	0	0	0	1	1
	Paper Plates	7	1	6	0	25	41
Total		57	12	17	10	244	340
Sub Total Violations		144	27	88	16	304	579
Less In Progress		0	0	0	0	0	0
Available For Prosecution		144	27	88	16	304	579
Less Rejects							
Camera	Misc Camera Issue	0-00%	0-00%	0-00%	1-08%	0-00%	1-00%
Malfunction	Plate Burn Out	1-01%	0-00%	0-00%	0-00%	1-00%	2-00%
	Rear Plate Camera Blurry	3-02%	8-10%	0-00%	0-00%	0-00%	8-01%

Generated By: MPANGALOS
 Generated On: 5/14/2013 2:50:26 PM

SAN MATEO POLICE DEPARTMENT
 CONTROL DOCUMENT
 DO NOT DUPLICATE

Customer Management Report (San Mateo) All Detection Types

01-Mar-2013 to 30-Mar-2013

Operator Id: %

	SAN-HIL-01	SAN-HIN-01	SAN-HIN-03	SAN-HIS-01	SAN-SAN-01	TOTAL
Police Driver Unidentifiable Images poor	0-00%	0-00%	2-02%	2-12%	2-01%	6-01%
Rejects	4-03%	5-19%	2-02%	3-19%	3-01%	17-03%
Total	4-03%	5-19%	2-02%	3-19%	3-01%	17-03%
Approved Vibrations	140-97%	228-91%	86-98%	13-91%	501-99%	755-97%
Total Notices Printed	140-97%	228-91%	86-98%	13-91%	501-99%	755-97%

Generated By: MPANGALOS
 Generated On: 5/14/2013 2:50:26 PM

Customer Management Report (San Mateo) All Detection Types

01-Mar-2013 to 30-Mar-2013

Operator Id: %

	SAN-MHLC05	SAN-HINC01	SAN-HINC03	SAN-HISA01	SAN-SAHL01	TOTAL
Total Processed Incidents	201	39	108	28	548	810
Less Uncontrollable Factors						
Obstruction						
Driver Obstruction/Duckers	11	0	0	1	11	23
Motor Cycle Helmet	1	0	0	0	1	2
Plate Obstruction	7	3	1	1	54	66
Vehicle Obstruction	0	1	1	0	56	57
Police Rejects						
Emergency Vehicle Responding	4	0	1	2	9	18
Multiple vehicles in frame	0	0	0	0	1	1
On or Passed the Stop Bar (PD)	0	0	6	0	65	71
Safe Turn On Red	0	0	0	0	1	1
Slow Roll - right turn	0	0	1	0	11	12
Sun Glare	1	0	0	0	1	2
Policy/Weather						
Extended Vehicle	0	1	0	1	2	4
Sun Glare	28	3	1	5	5	40
Weather/Nature	0	0	1	0	2	3
Registration Issues						
Out of Country Plate	0	0	0	0	1	1
Paper Plates	7	4	5	0	25	41
Total	57	12	17	10	244	340
Sub Total Violations	144	27	88	16	304	579
Less In Progress	0	0	0	0	0	0
Available For Prosecution	144	27	88	16	304	579
Less Rejects						
Camera						
Misc Camera Issue	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%
Malfunction						
Plate Bum Out	1-01%	0-00%	0-00%	0-00%	1-00%	2-00%
Rear Plate Camera Blurry	3-02%	8-19%	0-00%	0-00%	0-00%	8-01%

Generated By: MPANGALOS
 Generated On: 3/14/2013 2:50:26 PM

SAN MATEO POLICE DEPARTMENT
 CONTROL DOCUMENT
 DO NOT DUPLICATE

Customer Management Report (San Mateo) All Detection Types

01-Mar-2013 to 30-Mar-2013

Operator Id: %

	SAN-4HU-01	SAN-FINQ-01	SAN-HINC-03	SAN-FISA-01	SAN-SARI-01	TOTAL
Police Driver Unidentifiable Images poor	0-00%	0-00%	2-02%	2-12%	2-01%	6-01%
Rejects	4-03%	6-19%	2-02%	3-19%	3-01%	17-03%
Total						
Approved Violators	140-97%	22-01%	83-98%	100-01%	201-99%	546-97%
Total Notices Printed						

Generated By: MPANGALOS
 Generated On: 5/14/2013 2:50:26 PM

SAN MATEO POLICE DEPARTMENT
CONTROL DOCUMENT
DO NOT DUPLICATE

Customer Management Report (San Mateo) All Detection Types

01-Apr-2013 to 30-Apr-2013

Operator Id: %

		SAN-4HUC-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SARI-01	TOTAL
Total Processed Incidents:		204	37	91	18	620	970
Less Uncontrollable Factors							
Obstruction	Driver Obstruction/Duckers	0	0	1	0	14	24
	Plate Obstruction	10	1	8	0	65	82
	Vehicle Obstruction	3	0	1	0	59	63
Police Rejects	Emergency Vehicle Responding	4	0	0	0	1	5
	Multiple vehicles in frame	0	0	0	1	5	6
	On or Passed the Stop Bar (PD)	0	0	5	0	100	105
	Plate Unidentifiable	1	0	0	0	1	2
	Safe Turn On Red	0	0	0	0	1	1
	Slow Roll - right turn	0	0	0	0	10	10
Policy/Weather	Sun Glare	20	3	1	3	7	34
	Weather/Nature	1	0	0	0	0	1
Registration Issues	Out of Country Plate	0	0	1	0	1	2
	Paper Plates	8	3	1	1	16	27
Total		54	7	16	5	260	362
Sub Total Violations		150	30	75	13	340	608
Less in Progress		0	0	0	0	0	0
Available For Prosecution		150	30	75	13	340	608
Less Rejects							
Camera Malfunction	Face Not In Frame	2-01%	0-00%	0-00%	0-00%	0-00%	2-00%
	Image Missing	2-01%	0-00%	0-00%	0-00%	0-00%	2-00%
	Plate Burn Out	0-00%	0-00%	0-00%	2-15%	1-00%	3-00%
	Plate Not In Frame	0-00%	0-00%	0-00%	0-00%	2-01%	2-00%
	Rear Plate Camera Blurry	5-03%	2-07%	1-01%	1-08%	0-00%	0-01%

Generated By: MPANGALOS

Generated On: 5/14/2013 2:51:16 PM

Customer Management Report (San Mateo) All Detection Types

01-Apr-2013 to 30-Apr-2013

Operator Id: %

	SAN-FIU-01	SAN-HIN-01	SAN-HIN-03	SAN-HISA-01	SAN-SAH-01	TOTAL
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-08%	0-00%	1-00%
Rear Plate No Flash	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	10-07%	2-07%	1-01%	4-31%	3-01%	20-03%
Approved Violations	140-93%	228-83%	74-93%	3-88%	337-99%	509-97%
Total Notices Printed	140-93%	228-83%	74-93%	3-88%	337-99%	509-97%