

Customer Management Report (San Mateo) Redlight Incidents

01-Apr-2016 to 30-Apr-2016

Operator Id: %

		SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
Total Processed Incidents		130	34	116	34	738	1052
Less Uncontrollable Factors							
Obstruction	Driver Obstruction/Duckers	5	0	3	0	19	27
	Plate Obstruction	2	1	1	0	7	11
	Vehicle Obstruction	1	2	5	0	34	42
Police Rejects	Emergency Vehicle Responding	5	2	0	1	2	10
	Incorrect Plate on Vehicle	0	0	1	0	0	1
	Incorrect/Incomplete DMV	1	0	0	0	0	1
	Invalid Offense	0	1	0	0	0	1
	Multiple vehicles in frame	0	0	0	0	11	11
	On or Passed the Stop Bar (PD).	10	3	30	6	235	284
	Plate Unidentifiable	0	0	0	0	1	1
	Slow Roll - right turn	0	0	2	0	35	37
	Sun Glare	1	0	0	0	0	1
	Policy/Weather	Extended Vehicle	1	0	0	0	0
Sun Glare		21	3	3	5	16	48
Weather/Nature		1	0	0	1	0	2
Registration Issues	Out of Country Plate	0	0	0	0	1	1
	Paper Plates	0	1	1	1	23	26
Total		48	13	46	14	384	505
Sub Total Violations		82	21	70	20	354	547
Less in Progress		0	0	0	0	0	0
Available For Prosecution		82	21	70	20	354	547
Less Rejects							
Camera Malfunction	Face Camera Focus Blurry	0-00%	0-00%	0-00%	1-05%	0-00%	1-00%
	Face Camera No Flash	0-00%	0-00%	0-00%	1-05%	0-00%	1-00%
	Image Missing	0-00%	0-00%	0-00%	0-00%	2-01%	2-00%
	Video Skips	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	6-07%	0-00%	0-00%	1-05%	6-02%	13-02%
	No Video	0-00%	0-00%	0-00%	0-00%	3-01%	3-01%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Process Issues	Too Old	8-10%	1-05%	12-17%	2-10%	134-38%	157-29%
Total		14-17%	1-05%	12-17%	5-25%	147-42%	179-33%
Approved Violations		68-83%	20-95%	58-83%	15-75%	207-58%	368-67%
Total Notices Printed		68-83%	20-95%	58-83%	15-75%	207-58%	368-67%

Generated By: SHAGAN

Generated On: 12/21/2016 1:16:00 PM

Customer Management Report (San Mateo) Redlight Incidents

01-Apr-2016 to 30-Apr-2016

Operator Id: %

TOTAL	SAN-SAHI-01	SAN-HISA-01	SAN-HINO-03	SAN-HINO-01	SAN-4HU-01
-------	-------------	-------------	-------------	-------------	------------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SHAGAN

Generated On: 12/21/2016 1:16:00 PM

Customer Management Report (San Mateo) Redlight Incidents

01-May-2016 to 31-May-2016

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL	
Total Processed Incidents	170	29	115	77	978	1369	
Less Uncontrollable Factors							
Obstruction	Driver Obstruction/Duckers	6	1	5	0	12	24
	Plate Obstruction	2	0	2	1	0	5
	Vehicle Obstruction	4	0	8	0	56	68
Police Rejects	Emergency Vehicle Responding	7	1	0	1	3	12
	Incorrect/Incomplete DMV	0	0	0	0	3	3
	Multiple vehicles in frame	0	0	1	1	11	13
	On or Passed the Stop Bar (PD).	17	7	40	7	488	559
	Plate Obstruction (PD)	0	0	0	0	1	1
	Slow Roll - right turn	0	0	2	0	25	27
	Sun Glare	2	0	0	0	2	4
Policy/Weather	Extended Vehicle	2	0	0	0	1	3
	Sun Glare	28	4	5	15	27	79
	Weather/Nature	3	0	2	2	2	9
Registration Issues	Paper Plates	2	1	5	2	35	45
	Wrong or No DMV	0	0	0	0	1	1
Total		73	14	70	29	667	853
Sub Total Violations		97	15	45	48	311	516
Less in Progress		0	0	0	0	0	0
Available For Prosecution		97	15	45	48	311	516
Less Rejects							
Camera Malfunction	Face Camera Focus Blurry	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Not in Frame	5-05%	0-00%	0-00%	0-00%	0-00%	5-01%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	2-01%	2-00%
Police Rejects	Driver Unidentifiable images poor	14-14%	4-27%	5-11%	13-27%	36-12%	72-14%
	No Video	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Total		20-21%	4-27%	5-11%	13-27%	41-13%	83-16%
Approved Violations		77-79%	11-73%	40-89%	35-73%	270-87%	433-84%
Total Notices Printed		77-79%	11-73%	40-89%	35-73%	270-87%	433-84%

Generated By: SHAGAN

Generated On: 12/21/2016 1:17:13 PM

Customer Management Report (San Mateo) Redlight Incidents

01-May-2016 to 31-May-2016

Operator Id: %

TOTAL	SAN-SAHI-01	SAN-HISA-01	SAN-HINO-03	SAN-HINO-01	SAN-4HU-01
-------	-------------	-------------	-------------	-------------	------------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SHAGAN

Generated On: 12/21/2016 1:17:13 PM

Customer Management Report (San Mateo) Redlight Incidents

01-Jun-2016 to 30-Jun-2016

Operator Id: %

		SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
Total Processed Incidents		130	49	102	56	1029	1366
Less Uncontrollable Factors							
Obstruction	Driver Obstruction/Duckers	0	0	5	1	21	27
	Motor Cycle Helmet	1	0	0	0	0	1
	Plate Obstruction	4	1	1	3	5	14
	Vehicle Obstruction	6	0	5	1	50	62
Police Rejects	Emergency Vehicle Responding	9	4	0	0	13	26
	Incorrect/Incomplete DMV	1	0	0	1	0	2
	Invalid Offense	0	1	0	0	1	2
	Multiple vehicles in frame	0	0	0	0	7	7
	On or Passed the Stop Bar (PD).	10	7	33	1	482	533
	Slow Roll - right turn	0	0	0	0	11	11
Policy/Weather	Extended Vehicle	0	0	0	1	0	1
	Sun Glare	16	3	2	10	39	70
	Weather/Nature	2	0	0	0	3	5
Registration Issues	Paper Plates	8	3	3	4	29	47
	Wrong or No DMV	0	0	0	0	1	1
Total		57	19	49	22	662	809
Sub Total Violations		73	30	53	34	367	557
Less in Progress		0	0	0	0	0	0
Available For Prosecution		73	30	53	34	367	557
Less Rejects							
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Face Camera Focus Blurry	3-04%	0-00%	0-00%	1-03%	0-00%	4-01%
	Face Not in Frame	0-00%	0-00%	0-00%	4-12%	0-00%	4-01%
	Image Missing	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	4-12%	0-00%	4-01%
	Rear Plate Camera Blurry	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
	Test Pattern	21-29%	0-00%	0-00%	0-00%	0-00%	21-04%
Police Rejects	Driver Unidentifiable images poor	9-12%	1-03%	1-02%	7-21%	29-08%	47-08%
	No Video	0-00%	0-00%	0-00%	1-03%	0-00%	1-00%
	Red-light not visible in	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
Process Issues	Too Old	6-08%	3-10%	4-08%	5-15%	48-13%	66-12%
Total		39-53%	6-20%	6-11%	22-65%	78-21%	151-27%
Approved Violations		34-47%	24-80%	47-89%	12-35%	289-79%	406-73%

Generated By: SHAGAN

Generated On: 12/21/2016 1:17:47 PM

Customer Management Report (San Mateo) Redlight Incidents

01-Jun-2016 to 30-Jun-2016

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
Total Notices Printed	34-47%	24-80%	47-89%	12-35%	289-79%	406-73%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SHAGAN

Generated On: 12/21/2016 1:17:47 PM

Customer Management Report (San Mateo) Redlight Incidents

01-Jul-2016 to 31-Jul-2016

Operator Id: %

		SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
Total Processed Incidents		93	46	133	70	1129	1471
Less Uncontrollable Factors							
Obstruction	Driver Obstruction/Duckers	5	1	2	2	24	34
	Motor Cycle Helmet	1	0	0	0	0	1
	Plate Obstruction	3	1	5	1	4	14
	Signal Obstruction	0	0	0	0	1	1
	Vehicle Obstruction	1	0	4	1	68	74
Police Rejects	Emergency Vehicle Responding	5	2	2	0	3	12
	Gender Mismatch	0	0	0	0	4	4
	Incorrect/Incomplete DMV	0	0	0	1	1	2
	Multiple vehicles in frame	0	0	2	1	16	19
	On or Passed the Stop Bar (PD).	2	6	41	3	527	579
	Slow Roll - right turn	0	0	1	0	29	30
	Sun Glare	1	0	0	0	0	1
Policy/Weather	Extended Vehicle	0	0	1	1	0	2
	Sun Glare	8	5	1	14	36	64
	Weather/Nature	0	0	0	0	1	1
Registration Issues	Out of Country Plate	0	0	0	1	0	1
	Paper Plates	5	0	5	2	26	38
	Wrong or No DMV	0	0	0	0	1	1
Total		31	15	64	27	741	878
Sub Total Violations		62	31	69	43	388	593
Less in Progress		0	0	0	0	0	0
Available For Prosecution		62	31	69	43	388	593
Less Rejects							
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	2-01%	2-00%
	Face Camera Focus Blurry	2-03%	0-00%	0-00%	1-02%	2-01%	5-01%
	Face Not in Frame	2-03%	0-00%	0-00%	0-00%	0-00%	2-00%
	Image Missing	0-00%	0-00%	2-03%	0-00%	4-01%	6-01%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Rear Plate Camera Blurry	0-00%	1-03%	0-00%	0-00%	2-01%	3-01%
	Rear Plate Flash Inappropriate	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	10-16%	1-03%	4-06%	11-26%	18-05%	44-07%
	No Video	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Process Issues	Too Old	0-00%	0-00%	0-00%	1-02%	38-10%	39-07%
Total		14-23%	3-10%	6-09%	13-30%	68-18%	104-18%

Generated By: SHAGAN

Generated On: 12/21/2016 1:19:08 PM

Customer Management Report (San Mateo) Redlight Incidents

01-Jul-2016 to 31-Jul-2016

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
Approved Violations	48-77%	28-90%	63-91%	30-70%	320-82%	489-82%
Total Notices Printed	48-77%	28-90%	63-91%	30-70%	320-82%	489-82%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SHAGAN

Generated On: 12/21/2016 1:19:08 PM

Customer Management Report (San Mateo) Redlight Incidents

01-Aug-2016 to 31-Aug-2016

Operator Id: %

		SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
Total Processed Incidents		116	37	117	74	1077	1421
Less Uncontrollable Factors							
Obstruction	Driver Obstruction/Duckers	8	0	5	2	16	31
	Motor Cycle Helmet	1	0	0	0	1	2
	Plate Obstruction	1	0	4	0	7	12
	Signal Obstruction	0	0	0	0	1	1
	Vehicle Obstruction	2	1	3	1	56	63
Police Rejects	Citation Issued manually	0	0	0	0	1	1
	Emergency Vehicle Responding	5	1	1	1	11	19
	Multiple vehicles in frame	0	0	1	0	30	31
	On or Passed the Stop Bar (PD).	11	3	37	2	428	481
	Plate Unidentifiable	0	0	0	0	1	1
	Slow Roll - right turn	0	0	0	0	48	48
Policy/Weather	Extended Vehicle	0	0	0	0	1	1
	Sun Glare	10	1	0	22	18	51
	Weather/Nature	0	1	0	0	2	3
Registration Issues	Paper Plates	3	1	4	3	32	43
	Wrong or No DMV	0	0	0	0	2	2
Total		41	8	55	31	655	790
Sub Total Violations		75	29	62	43	422	631
Less in Progress		0	0	0	0	0	0
Available For Prosecution		75	29	62	43	422	631
Less Rejects							
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	2-05%	1-00%	3-00%
	Face Camera Focus Blurry	3-04%	0-00%	0-00%	6-14%	0-00%	9-01%
	Face Not in Frame	2-03%	0-00%	0-00%	0-00%	0-00%	2-00%
	Image Missing	0-00%	0-00%	0-00%	0-00%	4-01%	4-01%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	2-00%	2-00%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	2-00%	2-00%
	Rear Plate Camera Blurry	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Test Pattern	0-00%	1-03%	0-00%	0-00%	31-07%	32-05%
Police Rejects	Driver Unidentifiable images poor	4-05%	0-00%	1-02%	6-14%	11-03%	22-03%
	No Video	1-01%	0-00%	1-02%	0-00%	8-02%	10-02%
	Unclear Scene Image	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	Too Old	4-05%	0-00%	3-05%	0-00%	18-04%	25-04%

Generated By: SHAGAN

Generated On: 12/21/2016 1:19:59 PM

Customer Management Report (San Mateo) Redlight Incidents

01-Aug-2016 to 31-Aug-2016

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
Total	15-20%	1-03%	6-10%	14-33%	78-18%	114-18%
Approved Violations	60-80%	28-97%	56-90%	29-67%	344-82%	517-82%
Total Notices Printed	60-80%	28-97%	56-90%	29-67%	344-82%	517-82%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SHAGAN

Generated On: 12/21/2016 1:19:59 PM

Customer Management Report (San Mateo) Redlight Incidents

01-Sep-2016 to 30-Sep-2016

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL	
Total Processed Incidents	130	25	111	58	935	1259	
Less Uncontrollable Factors							
Obstruction	Driver Obstruction/Duckers	3	1	8	0	11	23
	Motor Cycle Helmet	0	0	0	0	2	2
	Plate Obstruction	2	1	0	2	10	15
	Vehicle Obstruction	2	0	4	1	54	61
Police Rejects	Emergency Vehicle Responding	6	2	1	0	2	11
	Incorrect/Incomplete DMV	0	0	1	0	0	1
	Multiple vehicles in frame	0	0	1	0	19	20
	On or Passed the Stop Bar (PD).	8	2	16	2	346	374
	Slow Roll - right turn	0	0	0	0	29	29
Policy/Weather	Extended Vehicle	1	0	0	1	0	2
	Sun Glare	10	4	1	8	19	42
	Weather/Nature	0	0	0	1	1	2
Registration Issues	Out of Country Plate	0	0	0	0	1	1
	Paper Plates	7	1	5	3	32	48
Total		39	11	37	18	526	631
Sub Total Violations		91	14	74	40	409	628
Less in Progress		0	0	0	0	0	0
Available For Prosecution		91	14	74	40	409	628
Less Rejects							
Camera Malfunction	Face Camera Focus Blurry	3-03%	0-00%	0-00%	2-05%	0-00%	5-01%
	Face Not in Frame	1-01%	0-00%	0-00%	0-00%	1-00%	2-00%
	Image Missing	1-01%	0-00%	3-04%	0-00%	16-04%	20-03%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Plate Not in Frame	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Test Pattern	0-00%	0-00%	6-08%	0-00%	5-01%	11-02%
Police Rejects	Driver Unidentifiable images poor	6-07%	1-07%	0-00%	8-20%	8-02%	23-04%
	Insufficient Strobe Lighting	0-00%	0-00%	1-01%	0-00%	5-01%	6-01%
Process Issues	Too Old	11-12%	1-07%	13-18%	9-22%	82-20%	116-18%
Total		23-25%	2-14%	23-31%	19-48%	119-29%	186-30%
Approved Violations		68-75%	12-86%	51-69%	21-52%	290-71%	442-70%
Total Notices Printed		68-75%	12-86%	51-69%	21-52%	290-71%	442-70%

Generated By: SHAGAN

Generated On: 12/21/2016 1:20:27 PM

Customer Management Report (San Mateo) Redlight Incidents

01-Sep-2016 to 30-Sep-2016

Operator Id: %

TOTAL	SAN-SAHI-01	SAN-HISA-01	SAN-HINO-03	SAN-HINO-01	SAN-4HU-01
-------	-------------	-------------	-------------	-------------	------------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SHAGAN

Generated On: 12/21/2016 1:20:27 PM

Customer Management Report (San Mateo) Redlight Incidents

01-Oct-2016 to 31-Oct-2016

Operator Id: %

		SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
Total Processed Incidents		109	38	129	81	998	1355
Less Uncontrollable Factors							
Obstruction	Driver Obstruction/Duckers	6	0	4	0	20	30
	Motor Cycle Helmet	1	0	0	0	0	1
	Plate Obstruction	3	0	1	0	6	10
	Vehicle Obstruction	3	1	7	0	37	48
Police Rejects	Emergency Vehicle Responding	4	0	2	2	4	12
	Multiple vehicles in frame	0	0	1	0	36	37
	On or Passed the Stop Bar (PD).	7	2	37	4	311	361
	Plate Obstruction (PD)	0	0	0	1	0	1
	Plate Unidentifiable	0	0	0	0	2	2
	Slow Roll - right turn	0	0	2	0	25	27
	Policy/Weather	Extended Vehicle	1	1	0	0	1
	Sun Glare	5	5	0	8	11	29
	Weather/Nature	1	1	0	2	11	15
Registration Issues	Out of Country Plate	0	0	0	0	1	1
	Paper Plates	1	2	6	4	37	50
Total		32	12	60	21	502	627
Sub Total Violations		77	26	69	60	496	728
Less in Progress		0	0	0	0	0	0
Available For Prosecution		77	26	69	60	496	728
Less Rejects							
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Face Camera Focus Blurry	1-01%	0-00%	0-00%	5-08%	1-00%	7-01%
	Face Not in Frame	5-06%	0-00%	0-00%	0-00%	0-00%	5-01%
	Image Missing	1-01%	0-00%	0-00%	0-00%	9-02%	10-01%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	3-04%	0-00%	0-00%	4-07%	5-01%	12-02%
	Insufficient Strobe Lighting	0-00%	0-00%	1-01%	0-00%	8-02%	9-01%
	No Video	0-00%	1-04%	0-00%	0-00%	12-02%	13-02%
	Unclear Scene Image	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Process Issues	Too Old	10-13%	8-31%	5-07%	10-17%	134-27%	167-23%
Total		20-26%	9-35%	7-10%	19-32%	171-34%	226-31%
Approved Violations		57-74%	17-65%	62-90%	41-68%	325-66%	502-69%
Total Notices Printed		57-74%	17-65%	62-90%	41-68%	325-66%	502-69%

Generated By: SHAGAN

Generated On: 12/21/2016 1:20:52 PM

Customer Management Report (San Mateo) Redlight Incidents

01-Oct-2016 to 31-Oct-2016

Operator Id: %

TOTAL	SAN-SAHI-01	SAN-HISA-01	SAN-HINO-03	SAN-HINO-01	SAN-4HU-01
-------	-------------	-------------	-------------	-------------	------------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SHAGAN

Generated On: 12/21/2016 1:20:52 PM

Customer Management Report (San Mateo) Redlight Incidents

01-Nov-2016 to 30-Nov-2016

Operator Id: %

		SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
Total Processed Incidents		140	55	119	32	1035	1381
Less Uncontrollable Factors							
Obstruction	Driver Obstruction/Duckers	8	2	5	1	32	48
	Plate Obstruction	1	0	0	1	8	10
	Vehicle Obstruction	1	1	6	0	67	75
Police Rejects	Emergency Vehicle Responding	5	1	1	0	5	12
	Incorrect/Incomplete DMV	0	0	0	0	3	3
	Multiple vehicles in frame	0	0	0	0	29	29
	On or Passed the Stop Bar (PD).	7	1	31	2	285	326
	Slow Roll - right turn	0	0	2	0	24	26
	Sun Glare	0	0	1	0	1	2
	Policy/Weather	Extended Vehicle	1	0	0	0	0
	Sun Glare	3	6	0	1	21	31
	Weather/Nature	0	0	0	0	12	12
Registration Issues	Paper Plates	4	2	7	4	43	60
	Wrong or No DMV	0	0	1	0	1	2
Total		30	13	54	9	531	637
Sub Total Violations		110	42	65	23	504	744
Less in Progress		0	0	0	0	0	0
Available For Prosecution		110	42	65	23	504	744
Less Rejects							
Camera Malfunction	Face Not in Frame	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Camera Blurry	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Flash Inappropriate	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
	Video Not In Sync	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	2-05%	1-02%	0-00%	15-03%	18-02%
	Insufficient Strobe Lighting	0-00%	0-00%	0-00%	0-00%	2-00%	2-00%
	No Video	0-00%	0-00%	0-00%	0-00%	7-01%	7-01%
Process Issues	Too Old	17-15%	8-19%	17-26%	4-17%	215-43%	261-35%
Total		18-16%	13-31%	18-28%	4-17%	239-47%	292-39%
Approved Violations		92-84%	29-69%	47-72%	19-83%	265-53%	452-61%
Total Notices Printed		92-84%	29-69%	47-72%	19-83%	265-53%	452-61%

Generated By: SHAGAN

Generated On: 12/21/2016 1:21:18 PM

Customer Management Report (San Mateo) Redlight Incidents

01-Nov-2016 to 30-Nov-2016

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
--	------------	-------------	-------------	-------------	-------------	-------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SHAGAN

Generated On: 12/21/2016 1:21:18 PM