

rec'd 10.26.12 by UPS

# Customer Management Report (Ventura) All Detection Types

01-Jan-2011 to 31-Jan-2011

Operator Id: %

	9	73	9	7	68	26	19	29	247	3	30	33	19	24	26	32	44	52	750
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	9	73	9	7	68	26	19	29	247	3	30	33	19	24	26	32	44	52	750
<b>Less Uncontrollable Factors</b>																			
Obstruction	1	7	1	0	1	2	2	1	2	0	1	2	2	2	2	1	1	1	29
Driver Obstruction/Duckers	0	1	0	0	0	0	0	0	4	0	0	0	0	0	0	0	0	0	5
Motor Cycle Helmet	1	3	0	0	1	2	1	1	5	0	0	6	0	0	1	0	0	0	21
Plate Obstruction	0	0	0	0	5	0	2	0	4	0	1	1	0	0	1	0	2	0	16
Vehicle Obstruction	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Citation Issued manually	0	1	0	0	1	0	0	0	7	0	0	0	0	0	1	0	0	0	11
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Emergency Vehicle Responding	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Multiple vehicles in frame	1	0	1	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	4
On or Passed the Stop Bar (PD)	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Plate Unidentifiable	0	17	0	0	0	0	0	13	85	0	0	0	0	0	0	0	0	5	120
Safe Turn On Red	0	1	0	0	0	1	0	0	0	1	0	3	0	0	1	0	0	1	8
Policy/Weather	1	7	0	0	1	1	0	0	21	0	4	0	0	6	2	4	1	11	59
Extended Vehicle	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Sum Glare	0	4	0	0	0	0	0	0	7	0	0	0	0	0	0	0	0	0	1
Out of County Plate	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Registration Issues	0	4	0	1	3	1	1	1	7	0	1	1	0	1	0	0	1	2	24
Paper Plates	1	2	0	2	3	0	0	1	7	0	0	0	0	0	2	1	1	0	20
Wrong or No DMV	5	45	2	3	14	9	6	17	142	1	7	15	2	10	11	7	6	20	322
<b>Sub Total Violations</b>	4	28	7	4	54	17	13	12	105	2	23	18	17	14	15	25	38	32	428
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	4	28	7	4	54	17	13	12	105	2	23	18	17	14	15	25	38	32	428
<b>Less Rejects</b>																			
Camera Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	2-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-15%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-50%	0-00%	2-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Driver Unidentifiable images poor	0-00%	3-11%	0-00%	0-00%	0-00%	1-06%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	1-03%	0-00%	3-09%	11-03%
Sun Glare	0-00%	4-15%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Total	0-00%	7-25%	0-00%	0-00%	0-00%	1-06%	4-31%	0-00%	0-00%	1-50%	1-04%	2-11%	1-06%	1-07%	1-07%	2-08%	1-03%	4-12%	26-06%
<b>Approved Violations</b>	4-100%	21-75%	7-100%	4-100%	54-100%	16-94%	9-69%	12-100%	105-100%	1-50%	22-96%	16-89%	16-94%	13-93%	14-93%	23-92%	37-97%	28-88%	402-94%
<b>Total Notices Printed</b>	4-100%	21-75%	7-100%	4-100%	54-100%	16-94%	9-69%	12-100%	105-100%	1-50%	22-96%	16-89%	16-94%	13-93%	14-93%	23-92%	37-97%	28-88%	402-94%

# Customer Management Report (Ventura) All Detection Types

01-Feb-2011 to 28-Feb-2011

Operator Id: %

	7	62	10	9	59	16	16	36	234	11	26	37	19	13	23	34	36	35	683
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-UIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	0	9	1	0	1	2	1	0	10	3	0	2	1	1	2	1	0	1	683
<b>Less Uncontrollable Factors</b>																			
Obstruction	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1
Driver Obstruction/Duckers	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Motor Cycle Helmet	1	1	1	1	2	0	0	0	3	1	1	5	0	0	2	1	0	2	20
Plate Obstruction	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	2
Signal Obstruction	1	0	0	0	3	0	1	1	2	0	1	3	1	0	2	0	1	0	16
Vehicle Obstruction	0	0	0	0	0	1	0	0	3	0	0	2	0	0	0	0	0	0	9
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	1
Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
On or Passed the Stop Bar (PD)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1	0	0	0	3
Plate Obstruction (PD)	0	0	0	0	2	0	0	0	0	0	0	0	0	0	1	0	0	0	3
Plate Unidentifiable	0	0	0	0	3	0	0	0	0	0	0	0	0	0	0	0	0	0	3
Safe Turn On Red	0	8	0	0	0	0	0	14	131	0	0	0	0	0	0	0	0	3	156
Policy/Weather	0	0	0	0	1	0	0	0	0	0	0	2	0	0	0	0	0	1	4
Extended Vehicle	0	21	0	0	3	3	1	4	14	0	4	1	0	3	1	3	0	6	64
Sun Glare	0	0	0	0	0	0	2	0	0	1	0	0	0	0	0	0	0	0	3
Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Registration	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1
Can Not Identify State	0	0	0	0	1	0	1	2	2	0	0	4	2	0	0	0	1	1	14
Paper Plates	0	0	0	0	1	0	1	0	3	0	1	0	0	0	0	0	0	1	11
Wrong or No DMV	2	39	2	1	18	6	7	22	167	8	7	19	5	4	8	8	15	346	
<b>Sub Total Violations</b>	5	23	8	8	41	10	9	14	67	3	19	18	14	9	15	26	28	20	337
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>	5	23	8	8	41	10	9	14	67	3	19	18	14	9	15	26	28	20	337
<b>Less Rejects</b>																			
Camera	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Flash	0-00%	2-00%	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police	0-00%	5-22%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-08%	0-00%	0-00%	8-02%
Driver Unidentifiable images poor	0-00%	3-13%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	1-04%	0-00%	0-00%	0-00%	5-01%
Rejects	0-00%	10-43%	1-12%	0-00%	0-00%	0-00%	0-00%	1-07%	1-01%	0-00%	0-00%	1-06%	1-07%	0-00%	3-12%	0-00%	1-05%	20-06%	
Sun Glare	5-100%	13-57%	7-86%	8-100%	41-100%	10-100%	9-100%	13-93%	66-99%	3-100%	19-100%	17-94%	13-93%	9-100%	14-93%	23-88%	28-100%	19-95%	317-94%
<b>Approved Violations</b>	5-100%	13-57%	7-86%	8-100%	41-100%	10-100%	9-100%	13-93%	66-99%	3-100%	19-100%	17-94%	13-93%	9-100%	14-93%	23-88%	28-100%	19-95%	317-94%
<b>Total Notices Printed</b>	5-100%	13-57%	7-86%	8-100%	41-100%	10-100%	9-100%	13-93%	66-99%	3-100%	19-100%	17-94%	13-93%	9-100%	14-93%	23-88%	28-100%	19-95%	317-94%

# Customer Management Report (Ventura) All Detection Types

01-Mar-2011 to 31-Mar-2011  
Operator Id: %

	16	81	10	14	53	18	31	30	252	5	23	49	28	19	34	15	59	42	779
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	1	7	0	1	2	1	1	0	14	0	1	3	4	1	6	2	0	0	44
<b>Less Uncontrollable Factors</b>																			
Obstruction	1	2	0	4	2	0	0	2	1	0	1	6	0	1	2	0	3	0	26
Driver Obstruction/Duckers	0	0	0	0	2	0	1	0	1	0	0	1	0	0	1	0	1	1	8
Plate Obstruction	0	4	0	0	1	0	0	0	7	0	0	0	0	0	1	0	0	0	13
Vehicle Obstruction	0	1	0	0	1	0	0	0	1	0	0	0	0	0	0	0	0	0	3
Police Rejects	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Multiple vehicles in frame	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
On or Passed the Stop Bar (PD)	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1	0	0	2
Plate Obstruction (PD)	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Plate Unidentifiable	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Safe Turn On Red	0	9	0	0	0	0	0	13	99	0	0	0	0	0	0	0	0	3	124
Policy/Weather	0	1	0	1	0	0	0	0	0	0	0	4	0	0	0	0	0	1	7
Extended Vehicle	0	22	0	0	2	2	4	1	28	1	9	2	0	4	1	3	5	15	99
Sun Glare	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	2
Weather/Reture	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Registration Issues	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1
Can Not Identify State	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Out of Country Plate	0	0	1	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	2
Paper Plates	1	1	0	0	2	0	2	2	8	0	2	2	0	0	0	0	0	0	23
Wrong or No DMV	0	1	0	1	0	1	0	0	4	0	0	2	0	1	0	0	3	0	13
Total	4	49	1	7	15	5	9	18	166	1	13	20	5	7	11	7	15	20	373
Sub Total Violations	12	32	9	7	38	13	22	12	86	4	10	29	23	12	23	8	44	22	406
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	12	32	9	7	38	13	22	12	86	4	10	29	23	12	23	8	44	22	406
<b>Less Rejects</b>																			
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-25%	1-02%	4-18%	8-02%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-12%	0-00%	0-00%	2-00%
Police Rejects	0-00%	6-19%	1-11%	0-00%	0-00%	0-00%	2-09%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-09%	1-12%	0-00%	0-00%	14-03%
No Images	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Sun Glare	0-00%	1-03%	0-00%	1-14%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Total	0-00%	7-22%	1-11%	1-14%	1-03%	0-00%	4-18%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-13%	4-50%	4-09%	4-18%	31-08%
Approved Violations	12-100%	25-78%	8-89%	6-86%	37-97%	13-100%	18-82%	12-100%	84-98%	4-100%	10-100%	28-100%	23-100%	12-100%	20-87%	4-50%	40-91%	18-82%	375-92%
Total Notices Printed	12-100%	25-78%	8-89%	6-86%	37-97%	13-100%	18-82%	12-100%	84-98%	4-100%	10-100%	28-100%	23-100%	12-100%	20-87%	4-50%	40-91%	18-82%	375-92%

# Customer Management Report (Ventura) All Detection Types

01-Apr-2011 to 30-Apr-2011

Operator Id: %

	12	95	12	6	67	8	23	40	250	5	25	53	26	21	31	19	38	55	786	
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	12	95	12	6	67	8	23	40	250	5	25	53	26	21	31	19	38	55	786	
<b>Less Uncontrollable Factors</b>																				
Obstruction	1	9	4	0	1	2	3	1	3	0	1	0	4	1	4	1	1	4	40	
Motor Cycle Helmet	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1	2	
Plate Obstruction	3	3	1	1	3	1	0	2	2	1	0	7	1	1	2	0	2	1	31	
Vehicle Obstruction	0	2	0	0	1	0	1	0	1	0	2	2	0	0	1	0	1	1	12	
Police	0	0	0	1	0	0	0	1	3	0	0	0	0	0	0	0	0	1	6	
Rejects	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1	
Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1	
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1	
On or Passed the Stop Bar (PD)	0	1	0	1	0	0	0	0	2	0	0	2	0	0	2	4	0	0	12	
Plate Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	1	1	0	0	0	0	0	0	2	
Safe Turn On Red	0	12	0	0	0	0	0	13	108	0	0	0	0	0	0	0	0	8	141	
Policy/Weather	0	1	0	0	0	0	0	0	0	0	0	6	0	0	0	0	0	3	10	
Extended Vehicle	0	28	1	0	4	0	4	2	32	1	4	1	0	4	1	4	2	15	103	
Sun Glare	0	3	0	0	0	0	0	0	0	1	1	0	0	0	0	0	1	7	7	
Weather/Nature	0	1	0	0	0	0	0	1	0	0	0	1	0	0	0	0	0	0	3	
Registration	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	
Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Out of Country Plate	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2	
Paper Plates	0	2	1	0	2	0	0	0	6	0	1	1	2	1	0	1	2	3	22	
Wrong or No DMV	1	1	0	0	0	0	0	0	6	0	1	0	0	0	0	0	4	0	14	
Total	5	63	7	3	11	3	10	20	164	4	11	22	7	7	11	10	13	38	408	
<b>Sub Total Violations</b>	7	32	5	3	56	5	13	20	86	1	14	31	19	14	20	9	25	17	377	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution	7	32	5	3	56	5	13	20	86	1	14	31	19	14	20	9	25	17	377	
<b>Less Rejects</b>																				
Camera	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	1-00%	
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Police	0-00%	3-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%	
Rejects	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Process	1-14%	0-00%	0-00%	0-00%	0-00%	1-20%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	3-01%	
Issues	1-14%	3-09%	0-00%	0-00%	0-00%	1-20%	0-00%	1-05%	1-01%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	2-22%	0-00%	0-00%	11-03%	
Total	6-86%	29-91%	5-100%	3-100%	56-100%	4-80%	13-100%	19-95%	85-99%	1-100%	14-100%	30-97%	19-100%	14-100%	19-95%	7-78%	25-100%	17-100%	366-97%	
Approved Violations	6-86%	29-91%	5-100%	3-100%	56-100%	4-80%	13-100%	19-95%	85-99%	1-100%	14-100%	30-97%	19-100%	14-100%	19-95%	7-78%	25-100%	17-100%	366-97%	
Total Notices Printed	6-86%	29-91%	5-100%	3-100%	56-100%	4-80%	13-100%	19-95%	85-99%	1-100%	14-100%	30-97%	19-100%	14-100%	19-95%	7-78%	25-100%	17-100%	366-97%	

# Customer Management Report (Ventura) All Detection Types

01-May-2011 to 31-May-2011

Operator Id: %

	15	49	23	6	79	24	29	49	232	7	23	35	27	27	24	31	54	49	783
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	0	8	4	0	3	1	2	0	9	0	0	3	2	3	2	1	3	3	44
<b>Less Uncontrollable Factors</b>	0	0	0	0	0	0	0	0	2	0	1	0	0	0	0	0	0	0	3
Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Driver Obstruction/Duckets	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Plate Obstruction	1	8	0	1	3	2	2	2	1	1	0	3	0	0	1	0	1	0	26
Vehicle Obstruction	0	0	1	0	2	0	0	0	6	0	0	0	1	0	0	0	1	0	11
Police Rejects	0	1	0	0	0	1	0	0	2	0	1	0	0	0	0	1	0	0	6
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
On or Passed the Stop Bar (PD)	2	0	1	0	0	0	1	1	0	0	0	1	1	0	0	3	0	0	10
Plate Obstruction (PD)	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
Safe Turn On Red	0	3	0	0	0	0	0	19	101	0	0	0	0	0	0	0	0	0	127
Policy/Weath	0	0	0	0	1	1	0	0	0	1	0	5	0	0	0	0	0	0	9
Extended Vehicle	3	10	3	0	8	2	7	1	27	0	1	1	0	9	3	5	4	11	85
er	0	2	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2	5
Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Can Not Identify State	0	0	0	0	0	0	0	1	1	0	0	0	0	0	0	1	0	0	3
Paper Plates	1	1	0	0	1	1	1	1	3	0	0	1	0	0	0	1	1	2	14
Wrong or No DMV	0	1	2	3	3	0	0	0	1	0	0	2	0	0	0	0	0	0	13
Total	7	34	11	4	21	8	14	25	163	3	4	16	4	12	6	12	11	24	369
<b>Sub Total Violations</b>	8	15	12	2	58	16	15	24	79	4	19	19	23	15	18	19	43	25	414
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	8	15	12	2	58	16	15	24	79	4	19	19	23	15	18	19	43	25	414
<b>Less Rejects</b>	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	2-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-11%	0-00%	1-04%	5-01%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	2-00%	
Face Camera Focus Blurry	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
Driver Unidentifiable images poor	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	1-04%	3-01%	
Sun Glare	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-07%	0-00%	1-02%	1-04%	4-01%	
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	1-00%	
Issues	1-12%	1-07%	0-00%	0-00%	0-00%	3-19%	1-07%	2-08%	1-01%	0-00%	0-00%	1-05%	1-04%	1-07%	0-00%	2-05%	0-00%	22-05%	
Total	7-88%	14-93%	12-100%	2-100%	58-100%	13-81%	14-93%	22-92%	78-99%	4-100%	19-100%	18-95%	22-96%	14-93%	18-100%	14-74%	41-95%	22-88%	382-95%
<b>Approved Violations</b>																			

Generated By: RWEEKS  
Generated On: 10/30/2012 1:22:52 PM

# Customer Management Report (Ventura) All Detection Types

01-May-2011 to 31-May-2011

Operator Id: %

VE-BRJO-01	7.88%
VE-CATH-01	14.93%
VE-FOVI-01	12.100%
VE-JONB-01	2.100%
VE-MA10-01	56.100%
VE-MALE-01	13.81%
VE-MAMI-01	14.93%
VE-MIDE-01	22.92%
VE-MITG-01	78.98%
VE-TGDA-01	4.100%
VE-THSE-01	19.100%
VE-VIMO-01	16.95%
VE-VIOP-01	22.98%
VE-VIRA-01	14.93%
VE-VITG-01	18.100%
VE-VITP-01	14.74%
VE-VITP-03	41.95%
VE-VIVA-01	22.88%
TOTAL	392.95%

Total Notices Printed

# Customer Management Report (Ventura) All Detection Types

01-Jun-2011 to 30-Jun-2011

Operator Id: %

	12	68	11	13	65	16	34	46	252	7	17	35	30	28	27	46	47	32	786
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	3	5	3	1	5	1	8	5	10	1	2	3	1	4	1	6	1	4	64
<b>Less Uncontrollable Factors</b>	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	1	0	3
Obstruction	0	2	0	0	5	1	3	0	1	1	1	2	1	0	0	0	1	1	19
Driver Obstruction/Ducketers	0	0	0	0	1	0	1	0	1	0	0	0	0	0	1	0	0	0	4
Motor Cycle Helmet	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Plate Obstruction	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0	3
Vehicle Obstruction	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2
Citation Issued manually	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Multiple vehicles in frame	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
On or Passed the Stop Bar (PD)	2	0	0	0	0	0	0	3	0	0	0	2	1	0	0	2	0	0	10
Plate Obstruction (PD)	0	0	0	0	0	1	0	0	0	0	0	1	0	0	0	0	0	0	2
Police Discretion	0	1	0	0	0	0	0	0	7	0	0	0	0	0	0	0	0	0	8
Safe Turn On Red	0	14	0	0	0	0	0	7	100	0	0	0	0	0	0	0	0	0	127
Policy/Weather	0	0	0	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	4
Extended Vehicle	0	10	1	3	2	3	13	12	24	0	2	1	2	11	6	6	9	5	110
Sun Glare	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Weather/Nature	0	1	0	0	1	1	1	1	6	0	0	1	0	1	0	0	2	1	16
Paper Plates	1	4	1	0	0	0	0	0	3	0	0	2	0	0	0	2	0	0	13
Wrong or No DMV	6	39	5	4	14	7	27	29	157	2	5	15	5	16	8	16	15	18	388
<b>Sub Total Violations</b>	6	29	6	9	51	9	7	17	95	5	12	20	25	12	19	30	32	14	388
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>	6	29	6	9	51	9	7	17	95	5	12	20	25	12	19	30	32	14	388
<b>Less Rejects</b>	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Camera	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Flash	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%
Sun Glare	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%
Too Old	0-00%	0-00%	0-00%	0-00%	1-02%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%
Issues	0-00%	3-10%	0-00%	0-00%	1-02%	1-11%	0-00%	1-06%	4-04%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
<b>Total</b>	0-00%	3-10%	0-00%	0-00%	1-02%	1-11%	0-00%	1-06%	4-04%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
<b>Approved Violations</b>	6-100%	26-90%	6-100%	9-100%	50-98%	8-89%	7-100%	16-94%	91-96%	5-100%	11-92%	20-100%	25-100%	12-100%	18-95%	26-93%	29-91%	14-100%	381-96%

Generated By: RWEEDS  
Generated On: 10/3/2012 1:23:16 PM

# Customer Management Report (Ventura) All Detection Types

01-Jun-2011 to 30-Jun-2011

Operator Id: %

VE-BRJO-01	6-100%
VE-CATH-01	26-90%
VE-FOVI-01	6-100%
VE-JONB-01	9-100%
VE-MA10-01	50-99%
VE-MALE-01	8-89%
VE-MAMI-01	7-100%
VE-MIDE-01	16-94%
VE-MITG-01	91-96%
VE-TGDA-01	5-100%
VE-THSE-01	11-92%
VE-VIMO-01	20-100%
VE-VIOP-01	25-100%
VE-VIRA-01	12-100%
VE-VITG-01	18-95%
VE-VITP-01	28-93%
VE-VITP-03	29-91%
VE-VIVA-01	14-100%
TOTAL	381-96%

Total Notices Printed



# Customer Management Report (Ventura) All Detection Types

01-Jul-2011 to 31-Jul-2011

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	12	76	6	11	78	29	17	44	267	7	29	52	10	34	32	21	39	51	815
<b>Less Uncontrollable Factors</b>																			
Obstruction	1	3	1	1	4	2	1	2	6	0	2	3	0	0	5	0	1	2	34
Driver Obstruction/Duckers	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0	2
Motor Cycle Helmet	1	2	0	3	8	1	1	2	2	0	1	4	0	0	2	0	1	0	28
Plate Obstruction	0	0	0	0	4	0	0	1	6	0	0	0	0	1	0	0	0	0	12
Vehicle Obstruction	0	0	0	0	0	0	0	0	2	1	0	0	0	0	1	0	0	0	5
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0	2
Incorrect/Incomplete DMV	0	0	0	0	0	1	0	0	2	0	0	0	0	0	0	0	1	0	4
Multiple vehicles in frame	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
On or Passed the Stop Bar (PD)	1	0	0	0	1	0	0	0	0	0	1	1	0	0	0	1	0	0	5
Plate Obstruction (PD)	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1	0	0	2
Safe Turn On Red	0	13	0	0	0	0	0	7	121	0	0	0	0	0	0	0	0	1	142
Policy/Weath er	0	3	0	0	0	0	0	0	0	0	0	9	0	0	0	0	0	2	14
Extended Vehicle	2	23	1	2	10	7	12	13	35	1	3	3	1	18	6	4	14	20	175
Sun Glare	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1
Weather/Nature	0	4	0	2	2	0	0	2	2	0	1	1	0	0	0	0	0	1	15
Paper Plates	0	2	0	1	1	1	0	0	5	0	0	2	0	1	2	0	0	1	16
Wrong or No DMV	5	51	2	9	31	12	14	27	184	2	8	25	1	20	16	6	17	27	457
<b>Sub Total Violations</b>	7	25	4	2	47	17	3	17	83	5	21	27	9	14	16	15	22	24	358
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>	7	25	4	2	47	17	3	17	83	5	21	27	9	14	16	15	22	24	358
<b>Less Rejects</b>																			
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-50%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Driver Unidentifiable images poor	0-00%	1-04%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	1-07%	0-00%	0-00%	4-01%
No Images	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Sun Glare	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Total	0-00%	1-04%	0-00%	1-50%	2-04%	0-00%	0-00%	1-06%	1-07%	0-00%	0-00%	1-04%	2-22%	0-00%	0-00%	1-07%	0-00%	0-00%	10-03%
<b>Approved Violations</b>	7-100%	24-95%	4-100%	1-50%	45-96%	17-100%	3-100%	16-94%	82-99%	5-100%	21-100%	26-96%	7-78%	14-100%	16-100%	14-93%	22-100%	24-100%	348-97%
<b>Total Notices Printed</b>	7-100%	24-95%	4-100%	1-50%	45-96%	17-100%	3-100%	16-94%	82-99%	5-100%	21-100%	26-96%	7-78%	14-100%	16-100%	14-93%	22-100%	24-100%	348-97%

# Customer Management Report (Ventura) All Detection Types

01-Aug-2011 to 31-Aug-2011  
Operator Id: %

	16	76	10	10	10	92	37	36	46	285	5	61	44	36	40	47	27	40	51	959
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMC-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	16	76	10	10	92	37	36	46	285	5	61	44	36	40	47	27	40	51	959	
<b>Less Uncontrollable Factors</b>																				
Obstruction	3	8	3	0	5	5	4	4	12	0	2	2	2	2	8	2	1	2	85	
Driver Obstruction/Duckers	0	0	0	0	2	0	0	0	6	0	1	0	0	1	1	0	0	1	12	
Motor Cycle Helmet	1	1	0	4	6	4	3	1	2	1	2	11	2	0	3	0	1	1	43	
Plate Obstruction	0	1	0	0	3	0	1	1	2	0	1	0	0	0	0	0	0	0	9	
Vehicle Obstruction	0	1	0	0	1	0	0	0	0	0	0	0	1	0	0	0	0	0	4	
Police Rejects	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
Driver Obstruction (PD)	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
Multiple vehicles in frame	1	0	0	2	0	0	1	1	3	0	0	2	1	0	0	1	0	0	13	
On or Passed the Stop Bar (PD)	0	18	0	0	0	0	0	8	101	0	0	0	0	0	0	0	0	0	130	
Safe Turn On Red	0	2	0	1	3	0	1	0	0	1	0	2	0	0	0	0	0	0	11	
Extended Vehicle	1	14	2	1	8	8	9	14	56	0	13	1	8	17	5	4	7	11	179	
Sun Glare	0	2	0	0	0	2	0	0	2	0	0	0	0	0	0	1	1	1	10	
Weather/Nature	2	2	0	0	1	0	1	0	7	1	2	2	1	2	0	0	0	2	23	
Paper Plates	0	0	0	0	0	0	0	2	9	0	1	2	0	0	1	3	1	0	19	
Registration Issues	8	50	5	8	29	19	20	31	200	3	23	22	15	22	18	11	12	23	519	
Wrong or No DMV	8	26	5	2	63	18	16	15	85	2	38	22	21	18	29	16	28	28	440	
Sub Total Violations	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution	8	26	5	2	63	18	16	15	85	2	38	22	21	18	29	16	28	28	440	
Less Rejects																				
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-66%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-50%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	0-00%	2-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-01%
No Images	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Sun Glare	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-01%
Too Old	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-01%
Process Issues	1-12%	2-08%	0-00%	0-00%	2-03%	2-11%	1-66%	0-00%	0-00%	1-50%	1-03%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	7-88%	24-92%	5-100%	2-100%	61-97%	16-89%	15-94%	15-100%	85-100%	1-50%	37-97%	21-95%	20-95%	18-100%	28-100%	15-94%	27-96%	28-100%	426-97%	
Approved Violations	7-88%	24-92%	5-100%	2-100%	61-97%	16-89%	15-94%	15-100%	85-100%	1-50%	37-97%	21-95%	20-95%	18-100%	28-100%	15-94%	27-96%	28-100%	426-97%	
Total Notices Printed	7-88%	24-92%	5-100%	2-100%	61-97%	16-89%	15-94%	15-100%	85-100%	1-50%	37-97%	21-95%	20-95%	18-100%	28-100%	15-94%	27-96%	28-100%	426-97%	

# Customer Management Report (Ventura) All Detection Types

01-Sep-2011 to 30-Sep-2011  
Operator Id: %

	8	64	9	10	73	20	32	33	242	10	20	57	27	21	40	35	57	56	814
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	8	64	9	10	73	20	32	33	242	10	20	57	27	21	40	35	57	56	814
<b>Less Uncontrollable Factors</b>																			
Obstruction	1	6	2	1	1	0	8	2	6	1	2	2	5	1	4	4	3	8	57
Driver Obstruction/Duckers																			
Plate Obstruction	2	0	1	3	3	0	2	2	4	4	2	13	0	1	1	0	0	5	43
Vehicle Obstruction	0	0	0	0	4	0	1	1	0	0	0	0	0	0	0	0	0	1	7
Police Rejects	0	0	0	0	0	1	1	0	2	0	0	0	0	0	0	0	4	0	9
Driver Obstruction (PD)																			
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1	0	0	2
On or Passed the Stop Bar (PD)	1	0	0	0	0	0	0	0	0	0	0	1	1	0	0	1	0	2	6
Police Discretion	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Safe Turn On Red	0	11	0	0	0	0	0	13	76	0	0	0	0	0	0	0	1	1	101
Yielding to an Emergency	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Extended Vehicle	0	4	0	0	0	2	0	0	0	0	0	2	0	0	0	0	0	1	9
Sun Glare	0	13	0	0	7	2	1	7	23	1	4	0	5	4	5	4	5	11	92
Weather/Nature	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Registration Issues	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Out of Country Plate																			
Paper Plates	0	0	1	0	1	0	1	0	5	0	0	2	1	0	1	1	0	1	14
Wrong or No DMV	0	4	1	0	0	0	0	0	5	0	0	1	0	0	1	3	0	0	17
<b>Total</b>	4	40	5	6	16	5	14	25	122	6	8	22	12	6	12	14	14	30	361
<b>Sub Total Violations</b>	4	24	4	4	57	15	18	8	120	4	12	35	15	15	28	21	43	26	453
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>	4	24	4	4	57	15	18	8	120	4	12	35	15	15	28	21	43	26	453
<b>Less Rejects</b>																			
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-00%
Face Camera Flash																			
Face Camera No Flash	0-00%	2-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-19%	5-01%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	0-00%	7-29%	0-00%	0-00%	0-00%	1-07%	1-06%	0-00%	5-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	15-03%	
Sun Glare	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
<b>Total</b>	0-00%	10-42%	0-00%	0-00%	0-00%	1-07%	2-11%	0-00%	7-06%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-05%	0-00%	7-27%	29-06%
<b>Approved Violations</b>	4-100%	14-58%	4-100%	4-100%	57-100%	14-93%	16-89%	8-100%	113-94%	4-100%	12-100%	34-97%	15-100%	15-100%	28-100%	20-95%	43-100%	19-73%	424-94%
<b>Total Notices Printed</b>	4-100%	14-58%	4-100%	4-100%	57-100%	14-93%	16-89%	8-100%	113-94%	4-100%	12-100%	34-97%	15-100%	15-100%	28-100%	20-95%	43-100%	19-73%	424-94%

# Customer Management Report (Ventura) All Detection Types

01-Oct-2011 to 31-Oct-2011

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	3	24	19	6	72	24	35	47	801	11	18	53	35	20	50	40	42	46	1346
<b>Less Uncontrollable Factors</b>																			
Obstruction	0	6	2	0	7	1	5	6	18	0	2	7	2	1	6	3	2	4	72
Driver Obstruction/Duckers	0	0	0	0	0	0	0	0	5	0	0	0	0	0	1	1	0	0	7
Motor Cycle Helmet	0	0	1	0	5	0	0	1	8	3	0	8	0	0	2	2	0	1	31
Plate Obstruction	0	0	0	0	1	0	2	0	10	0	0	0	1	0	0	0	0	0	14
Vehicle Obstruction	0	0	0	0	1	0	2	0	10	0	0	0	1	0	0	0	0	0	14
Police Rejects	0	0	0	0	1	0	1	0	5	0	0	0	1	0	0	1	0	0	9
Driver Obstruction (PD)	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Emergency Vehicle Responding	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Incorrect/Incomplete DMV	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
On or Passed the Stop Bar (PD)	2	0	1	0	0	0	1	2	5	0	0	2	3	0	0	3	0	0	19
Plate Obstruction (PD)	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Plate Unidentifiable	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Safe Turn On Red	0	3	0	0	0	1	0	9	486	0	0	0	0	0	0	0	0	4	503
Policy/Weath er	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	2	3
Extended Vehicle	0	10	1	0	2	1	2	1	100	1	4	1	3	7	4	6	1	4	148
Sun Glare	0	0	0	0	0	0	0	1	1	0	0	0	0	0	0	0	0	0	3
Weather/Nature	0	0	0	0	0	0	0	1	1	0	0	0	0	0	0	0	0	0	3
Registration Issues	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1
Can Not Identify State	0	0	0	0	1	0	0	1	16	0	1	2	0	2	0	1	1	1	26
Paper Plates	0	0	0	0	1	0	0	1	18	0	1	1	1	0	0	0	1	1	26
Wrong or No DMV	2	18	5	2	17	3	12	24	673	4	8	22	11	10	14	17	5	18	866
<b>Sub Total Violations</b>	1	5	14	4	55	21	23	23	128	7	10	31	24	10	36	23	37	28	480
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>	1	5	14	4	55	21	23	23	128	7	10	31	24	10	36	23	37	28	480
<b>Less Rejects</b>																			
Camera Malfunction	0-00%	1-20%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	0-00%	4-80%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Face Camera No Flash	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	2-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	1-07%	0-00%	3-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	0-00%	0-00%	2-14%	0-00%	1-02%	0-00%	1-04%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	8-02%
No Images	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Sun Glare	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Total	0-00%	5-100%	4-29%	0-00%	5-08%	0-00%	5-22%	0-00%	4-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	30-06%
<b>Approved Violations</b>	1-100%	0-00%	10-71%	4-100%	50-91%	21-100%	18-76%	23-100%	124-97%	7-100%	10-100%	31-100%	24-100%	10-100%	35-97%	20-87%	36-87%	26-93%	450-94%

Generated By: RWEEKS  
Generated On: 10/3/2012 1:26:05 PM

# Customer Management Report (Ventura) All Detection Types

01-Oct-2011 to 31-Oct-2011

Operator Id: %

TOTAL	450-94%
VE-VIVA-01	26-93%
VE-VITP-03	36-97%
VE-VITP-01	20-87%
VE-VITG-01	35-97%
VE-VIRA-01	10-100%
VE-UIOP-01	24-100%
VE-VIMO-01	31-100%
VE-THSE-01	10-100%
VE-TGDA-01	7-100%
VE-MITG-01	124-97%
VE-MIDE-01	23-100%
VE-MAMI-01	18-78%
VE-MALE-01	21-100%
VE-MA10-01	50-91%
VE-JONB-01	4-100%
VE-FOVI-01	10-71%
VE-CATH-01	0-00%
VE-BRJO-01	1-100%
Total Notices Printed	

# Customer Management Report (Ventura) All Detection Types

01-Nov-2011 to 30-Nov-2011

Operator Id: %

	11	112	17	13	62	26	38	77	212	9	20	39	23	43	32	44	54	58	890
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	11	112	17	13	62	26	38	77	212	9	20	39	23	43	32	44	54	58	890
<b>Less Uncontrollable Factors</b>																			
Obstruction	1	6	0	0	3	0	2	1	8	0	1	1	1	2	4	2	2	1	35
Driver Obstruction/Ducklers	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	2	4
Motor Cycle Helmet	1	4	0	3	3	2	5	3	3	3	3	3	0	2	1	0	0	1	37
Plate Obstruction	0	2	0	0	3	1	2	1	1	0	0	3	0	2	0	0	1	0	16
Vehicle Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	6
Police Rejects	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Emergency Vehicle Responding	0	0	0	1	0	1	0	0	2	0	0	0	0	0	1	0	0	0	5
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0	7
On or Passed the Stop Bar (PD)	0	0	0	0	0	0	0	0	2	0	0	1	4	0	0	0	0	0	1
Plate Obstruction (PD)	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Safe Turn On Red	0	34	0	0	0	0	0	40	87	0	0	0	1	0	0	0	0	5	167
Policy/Weather Extended Vehicle	0	3	0	0	0	0	0	0	0	0	0	2	0	0	0	0	0	1	6
er	1	28	3	0	1	1	4	5	23	0	2	0	1	8	1	8	1	12	99
Sun Glare	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	1
Can Not Identify State	0	5	0	0	2	1	0	3	8	3	0	2	0	3	0	1	1	0	29
Paper Plates	0	0	0	1	1	2	0	4	9	0	0	2	0	1	3	0	3	0	26
Wrong or No DMV	3	83	3	5	14	8	13	57	147	6	6	15	7	18	11	11	22	440	26
<b>Total</b>	8	29	14	8	48	18	25	20	65	3	14	24	16	25	21	33	43	36	450
<b>Sub Total Violations</b>	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>	8	29	14	8	48	18	25	20	65	3	14	24	16	25	21	33	43	36	450
<b>Less Rejects</b>																			
Camera Malfunction	0-00%	5-17%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	7-02%
Face Camera Flash	0-00%	4-14%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Face Camera Focus Blurry	0-00%	4-14%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	2-11%	2-08%	0-00%	0-00%	3-100%	2-14%	2-08%	1-05%	2-08%	1-05%	2-06%	0-00%	1-03%	23-05%
Image Missing	0-00%	0-00%	5-36%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Not in Frame	0-00%	1-03%	0-00%	0-00%	1-02%	0-00%	1-04%	1-05%	1-02%	0-00%	0-00%	0-00%	0-00%	1-04%	1-05%	0-00%	0-00%	0-00%	13-03%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Scene Image No Flash	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	4-16%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
Driver Unidentifiable images poor	0-00%	2-07%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-05%	1-03%	0-00%	1-03%	7-02%
Police Rejects	0-00%	17-59%	6-43%	0-00%	4-08%	3-17%	11-44%	3-15%	1-02%	3-100%	2-14%	4-17%	1-06%	4-16%	3-14%	4-12%	4-08%	3-08%	73-16%
<b>Total</b>	8-100%	12-41%	8-57%	8-100%	44-92%	15-53%	14-56%	17-55%	64-98%	0-00%	12-86%	20-53%	15-94%	21-84%	18-66%	29-68%	39-81%	33-52%	377-84%
<b>Approved Violations</b>																			

Generated By: RWEKKS  
Generated On: 10/4/2012 10:25:42 AM

# Customer Management Report (Ventura) All Detection Types

01-Nov-2011 to 30-Nov-2011

Operator Id: %

VE-BRJO-01	8-100%
VE-CATH-01	12-41%
VE-FOVI-01	8-57%
VE-JONB-01	8-100%
VE-MA10-01	44-92%
VE-MALE-01	15-83%
VE-MAMI-01	14-56%
VE-MIDE-01	17-85%
VE-MITG-01	64-98%
VE-TGDA-01	0-00%
VE-THSE-01	12-86%
VE-VIMO-01	20-83%
VE-VIOP-01	15-94%
VE-VIRA-01	21-94%
VE-VITG-01	18-86%
VE-VITP-01	29-88%
VE-VITP-03	39-81%
VE-VIVA-01	33-92%
TOTAL	377-84%

Total Notices Printed

# Customer Management Report (Ventura) All Detection Types

01-Dec-2011 to 31-Dec-2011

Operator Id: %

	12	148	16	12	92	32	29	81	35	8	29	58	35	60	37	40	53	71	848	TOTAL
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01		
<b>Total Processed Incidents</b>	0	16	1	0	5	1	1	8	0	0	0	2	5	5	5	4	2	3	58	
<b>Less Uncontrollable Factors</b>	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1	3	
Obstruction	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Driver Obstruction/Duckers	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Plate Obstruction	2	9	0	1	6	0	0	3	0	0	0	4	0	0	0	0	0	2	27	
Vehicle Obstruction	0	0	0	0	2	1	5	0	0	2	0	1	1	1	0	1	2	1	17	
Police Rejects	0	2	0	0	0	0	0	0	2	0	0	0	0	1	0	1	1	0	7	
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	0	2	0	0	0	0	1	0	3	
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	1	
On or Passed the Stop Bar (PD)	0	0	0	1	0	0	0	0	2	0	0	0	1	0	0	1	1	0	7	
Plate Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	2	
Plate Unidentifiable	0	0	0	0	1	0	1	0	0	0	0	0	0	0	0	0	0	0	2	
Safe Turn On Red	0	55	0	0	0	0	0	30	6	0	0	0	0	0	0	0	0	11	102	
Policy/Weather	0	11	0	0	0	5	0	0	0	0	0	1	0	0	0	0	0	2	19	
Extended Vehicle	1	7	1	1	0	0	5	7	3	0	6	1	2	19	1	7	1	20	82	
Sun Glare	0	0	1	0	1	2	2	3	1	0	1	4	0	2	1	0	1	1	20	
Paper Plates	0	2	0	0	2	0	1	1	0	0	1	0	1	0	0	0	1	1	12	
Registration Issues	3	103	3	3	17	9	15	52	14	2	8	17	10	28	9	14	12	43	362	
Wrong or No DMV	9	45	13	9	75	23	14	29	21	6	21	41	25	32	28	26	41	28	486	
Sub Total Violations	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution	9	45	13	9	75	23	14	29	21	6	21	41	25	32	28	26	41	28	486	
<b>Less Rejects</b>	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-03%	0-00%	0-00%	0-00%	0-00%	1-00%	
Camera Malfunction	0-00%	0-00%	5-38%	2-22%	1-01%	0-00%	4-29%	1-03%	0-00%	2-33%	1-05%	2-05%	2-08%	1-03%	0-00%	0-00%	0-00%	0-00%	21-04%	
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	1-01%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	
Image Missing	0-00%	1-02%	0-00%	0-00%	5-07%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	2-05%	0-00%	0-00%	1-04%	0-00%	0-00%	10-02%		
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%		
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	4-01%		
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%		
Rear Plate Camera Blurry	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%		
Rear Plate Flash Inappropriate	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-17%	0-00%	2-05%	0-00%	0-00%	0-00%	1-02%	0-00%	5-01%		
Rear Plate No Flash	2-22%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%		
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%		
Driver Unidentifiable images poor	0-00%	3-07%	0-00%	0-00%	0-00%	0-00%	1-07%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-04%	7-01%		
Sun Glare	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%		
Too Old	0-00%	2-04%	0-00%	0-00%	2-03%	0-00%	0-00%	2-07%	0-00%	0-00%	0-00%	2-05%	1-04%	0-00%	0-00%	1-02%	0-00%	10-02%		
Process Issues	3-33%	7-16%	5-35%	2-22%	9-12%	4-17%	5-36%	7-24%	0-00%	3-50%	2-10%	10-24%	4-16%	3-08%	1-04%	3-07%	1-04%	69-14%		

Generated By: RWEKES  
Generated On: 10/4/2012 10:26:37 AM



# Customer Management Report (Ventura) All Detection Types

01-Dec-2011 to 31-Dec-2011

Operator Id: %

Category	Approved Violations	Total Notices Printed	Percentage	Percentage
VE-BRJO-01	6-67%	6-67%	27-96%	417-86%
VE-CATH-01	38-84%	38-84%	27-96%	417-86%
VE-FOVI-01	8-62%	8-62%	38-93%	38-93%
VE-JONB-01	7-78%	7-78%	26-100%	26-100%
VE-MA10-01	66-88%	66-88%	27-85%	27-85%
VE-MALE-01	19-83%	19-83%	29-81%	29-81%
VE-MAMI-01	9-64%	9-64%	21-84%	21-84%
VE-MIDE-01	22-76%	22-76%	31-76%	31-76%
VE-MITG-01	21-100%	21-100%	19-90%	19-90%
VE-TGDA-01	3-50%	3-50%	3-50%	3-50%
VE-THSE-01	19-90%	19-90%	31-76%	31-76%
VE-VIMO-01	31-76%	31-76%	21-84%	21-84%
VE-VIOP-01	21-84%	21-84%	29-81%	29-81%
VE-VIRA-01	29-81%	29-81%	27-85%	27-85%
VE-VITG-01	27-85%	27-85%	26-100%	26-100%
VE-VITP-01	26-100%	26-100%	38-93%	38-93%
VE-VITP-03	38-93%	38-93%	27-96%	27-96%
VE-VIVA-01	27-96%	27-96%	417-86%	417-86%
TOTAL				

# Customer Management Report (Ventura) All Detection Types

01-Jan-2012 to 31-Jan-2012 Operator Id: %

	14	139	18	19	73	12	17	97	40	9	25	31	37	37	49	38	41	64	TOTAL
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	
<b>Total Processed Incidents</b>	0	4	4	1	2	1	1	4	0	2	1	5	2	2	9	1	0	2	760
<b>Less Uncontrollable Factors</b>	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2	41
Obstruction - Driver Obstruction/Duckers	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1
Motor Cycle Helmet	5	4	1	4	3	0	0	2	0	2	0	1	0	0	0	0	1	2	25
Plate Obstruction	0	2	1	0	6	0	0	0	0	2	2	1	0	1	1	0	1	0	17
Vehicle Obstruction	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Citation Issued manually	1	3	0	1	0	1	0	1	0	0	1	1	1	0	1	0	1	2	14
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1
Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1
Incorrect/Incomplete DMV	1	0	0	2	0	0	0	2	2	0	0	0	2	0	0	1	0	0	2
On or Passed the Stop Bar (PD)	2	0	0	1	1	0	0	0	0	0	1	1	0	0	0	0	0	1	11
Plate Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	7
Plate Unidentifiable	0	0	0	0	0	0	0	0	0	1	0	1	0	0	0	0	0	0	3
Sale Turn On Red	0	58	0	0	0	0	0	50	6	0	0	0	0	0	0	0	0	9	123
Policy/Weather	0	1	0	0	1	2	0	0	0	0	0	1	0	0	0	0	0	1	6
Extended Vehicle	0	7	1	0	0	0	1	4	1	2	5	0	2	10	0	3	1	20	57
Sun Glare	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Registration	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Out of Country Plate	0	3	0	0	2	0	3	3	0	0	0	0	0	1	1	2	1	2	18
Paper Plates	0	3	0	0	2	0	2	4	1	0	0	1	1	0	2	0	1	0	17
Wrong or No DMV	9	86	7	9	17	4	7	71	10	9	10	12	8	14	14	9	8	41	345
<b>Total</b>	5	53	11	10	56	8	10	26	30	0	15	19	29	23	35	29	33	23	415
<b>Sub Total Violations</b>	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Less in Progress	5	53	11	10	56	8	10	26	30	0	15	19	29	23	35	29	33	23	415
<b>Available For Prosecution</b>	5	53	11	10	56	8	10	26	30	0	15	19	29	23	35	29	33	23	415
<b>Less Rejects</b>	0-00%	0-00%	0-00%	1-10%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-03%	0-00%	0-00%	4-01%
Camera	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Face Not in Frame	0-00%	0-00%	6-55%	3-30%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	2-11%	2-07%	1-04%	1-03%	1-03%	0-00%	0-00%	18-04%
Image Missing	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	7-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	17-04%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	5-01%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Driver Unidentifiable Images poor	0-00%	4-08%	0-00%	0-00%	0-00%	1-12%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	1-04%	9-02%
Sun Glare	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	3-01%
Total	0-00%	5-09%	6-55%	5-50%	12-21%	1-12%	2-20%	1-04%	1-03%	0-00%	2-13%	3-16%	2-07%	3-13%	6-17%	12-41%	2-06%	1-04%	64-15%

# Customer Management Report (Ventura) All Detection Types

01-Jan-2012 to 31-Jan-2012 Operator Id: %

	Approved Violations	Total Notices Printed
VE-BRJO-01	5-100%	5-100%
VE-CATH-01	46-91%	46-91%
VE-FOVI-01	5-45%	5-45%
VE-JONB-01	5-50%	5-50%
VE-MA10-01	44-79%	44-79%
VE-MALE-01	7-88%	7-88%
VE-MAMI-01	8-80%	8-80%
VE-MIDE-01	25-96%	25-96%
VE-MITG-01	29-97%	29-97%
VE-TGDA-01	0-00%	0-00%
VE-THSE-01	13-57%	13-57%
VE-VIMO-01	16-84%	16-84%
VE-VIOP-01	27-93%	27-93%
VE-VIRA-01	20-87%	20-87%
VE-VITG-01	29-83%	29-83%
VE-VITP-01	17-59%	17-59%
VE-VITP-03	31-94%	31-94%
VE-VIVA-01	22-96%	22-96%
TOTAL	351-85%	351-85%

# Customer Management Report (Ventura) All Detection Types

01-Feb-2012 to 29-Feb-2012 Operator Id: %

	11	183	54	19	53	30	35	81	66	9	25	24	32	40	43	36	36	47	824
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	2	11	24	2	2	3	4	4	2	0	5	1	8	2	6	1	0	4	81
<b>Less Uncontrollable Factors</b>	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1
Obstruction Driver Obstruction/Duckers	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0
Motor Cycle Helmet	1	4	5	2	1	1	1	4	1	1	1	1	0	0	1	1	0	0	1
Plate Obstruction	0	4	0	0	1	0	2	0	0	0	0	0	0	0	0	2	0	0	10
Vehicle Obstruction	0	3	0	0	1	0	0	1	1	0	0	1	0	0	1	0	0	0	9
Police Rejects	0	2	0	0	0	1	1	1	0	0	1	0	0	0	0	0	0	0	6
Driver Obstruction (PD)	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	2
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	5	0	0	2	1	0	0	0	0	0	13
Invalid Offense	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
On or Passed the Stop Bar (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	2
Police Discretion	0	67	0	0	0	0	0	31	8	0	0	0	0	0	0	0	0	6	112
Safe Turn On Red	0	0	0	2	0	2	0	0	0	0	0	2	0	0	0	0	0	0	7
Policy/Weath Extended Vehicle er	0	12	3	1	4	1	5	3	12	0	2	0	6	20	7	4	1	17	98
Weather/Nature	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1	0	0	0	2
Registration Paper Plates	0	4	1	1	1	1	3	2	0	0	1	0	0	0	1	1	1	1	18
Issues Wrong or No DMV	5	0	1	2	1	1	0	1	1	0	1	1	0	0	0	1	0	0	14
Total	3	113	33	11	12	12	18	49	31	2	11	8	15	22	17	12	2	29	400
<b>Sub Total Violations</b>	8	70	21	8	41	18	17	32	35	7	14	16	17	18	26	24	34	18	424
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	8	70	21	8	41	18	17	32	35	7	14	16	17	18	26	24	34	18	424
<b>Less Rejects</b>	0-00%	0-00%	4-19%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Camera Malfunction	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	3-01%
Face Camera Focus Blurry	1-12%	1-01%	9-43%	0-00%	1-02%	1-06%	5-29%	0-00%	0-00%	5-71%	0-00%	1-06%	2-12%	0-00%	1-04%	2-08%	0-00%	0-00%	29-07%
Face Not in Frame	0-00%	0-00%	3-14%	0-00%	2-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	6-01%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Plate Undercar	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Sun Glare	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Process Issues	1-12%	4-06%	17-81%	0-00%	6-15%	1-06%	7-41%	1-03%	1-03%	0-00%	0-00%	3-19%	2-12%	1-06%	4-15%	2-08%	1-03%	0-00%	56-13%
<b>Total</b>																			

Generated By: RWEEKS  
Generated On: 10/4/2012 10:29:40 AM

# Customer Management Report (Ventura) All Detection Types

01-Feb-2012 to 29-Feb-2012

Operator Id: %

Category	Approved Violations	Total Notices Printed	Percentage	Percentage
VE-BRJO-01	7-88%	7-88%	7-88%	7-88%
VE-CATH-01	66-94%	66-94%	66-94%	66-94%
VE-FOVI-01	4-19%	4-19%	4-19%	4-19%
VE-JONB-01	8-100%	8-100%	8-100%	8-100%
VE-MA10-01	35-85%	35-85%	35-85%	35-85%
VE-MALE-01	17-94%	17-94%	17-94%	17-94%
VE-MAMI-01	10-59%	10-59%	10-59%	10-59%
VE-MIDE-01	31-97%	31-97%	31-97%	31-97%
VE-MITG-01	34-97%	34-97%	34-97%	34-97%
VE-TGDA-01	2-29%	2-29%	2-29%	2-29%
VE-THSE-01	14-100%	14-100%	14-100%	14-100%
VE-VIMO-01	13-81%	13-81%	13-81%	13-81%
VE-VIOP-01	15-88%	15-88%	15-88%	15-88%
VE-VIRA-01	17-94%	17-94%	17-94%	17-94%
VE-VITG-01	22-92%	22-92%	22-92%	22-92%
VE-VITP-01	22-92%	22-92%	22-92%	22-92%
VE-VITP-03	33-97%	33-97%	33-97%	33-97%
VE-VIVA-01	18-100%	18-100%	18-100%	18-100%
TOTAL	368-87%	368-87%	368-87%	368-87%

# Customer Management Report (Ventura) All Detection Types

01-Mar-2012 to 31-Mar-2012 Operator Id: %

	19	152	32	14	23	21	24	93	75	15	31	33	16	35	55	52	59	62	TOTAL
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	
<b>Total Processed Incidents</b>	1	13	23	0	3	1	5	0	2	1	2	3	3	3	15	5	4	4	811
<b>Less Uncontrollable Factors</b>																			
Obstruction	1	10	2	0	4	2	1	2	0	0	1	3	0	0	0	1	0	1	29
Driver Obstruction/Duckers	0	1	0	0	0	0	2	0	0	4	0	2	1	0	1	0	0	0	11
Plate Obstruction	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1	0	0	0	4
Vehicle Obstruction	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Invalid Offense	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Multiple vehicles in frame	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
On or Passed the Stop Bar (PD)	0	1	1	1	0	1	0	1	2	0	0	1	3	0	0	0	0	0	11
Plate Obstruction (PD)	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Safe Turn On Red	0	62	0	0	0	0	0	41	8	0	0	0	0	0	0	0	0	15	126
Policy/Weather	0	2	0	0	0	1	0	0	0	0	0	1	0	0	0	0	0	1	5
Extended Vehicle	2	19	2	1	2	2	5	13	7	4	6	1	0	11	6	5	7	15	108
Sun Glare	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0	1	0	0	3
Weather/Nature	1	3	0	1	0	0	1	5	3	0	2	1	0	0	1	2	0	4	24
Paper Plates	1	0	0	0	0	0	0	3	2	0	1	2	0	1	1	2	0	0	15
Wrong or No DMV	8	112	28	3	10	7	14	65	25	10	12	15	8	15	25	16	14	40	427
<b>Sub Total Violations</b>	11	40	4	11	13	14	10	28	50	5	19	18	8	20	30	36	45	22	384
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>	11	40	4	11	13	14	10	28	50	5	19	18	8	20	30	36	45	22	384
<b>Less Rejects</b>																			
Camera	2-18%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	1-03%	0-00%	0-00%	0-00%	4-01%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-02%	0-00%	0-00%	0-00%	1-12%	0-00%	0-00%	1-02%	0-00%	0-00%	5-01%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	4-01%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%
Rear Plate No Flash	0-00%	0-00%	0-00%	1-09%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable Images poor	1-05%	0-00%	0-00%	0-00%	0-00%	1-07%	1-10%	0-00%	1-02%	0-00%	1-05%	0-00%	1-12%	1-05%	0-00%	1-03%	0-00%	0-00%	9-02%
Incorrect Speed	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Sun Glare	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-10%	0-00%	1-03%	0-00%	0-00%	3-01%
Total	4-36%	0-00%	0-00%	1-09%	0-00%	2-14%	2-20%	3-11%	3-06%	0-00%	2-11%	0-00%	2-25%	4-20%	1-03%	4-11%	2-04%	1-05%	31-08%
<b>Approved Violations</b>	7-64%	40-100%	4-100%	10-91%	13-100%	12-86%	8-80%	25-89%	47-94%	5-100%	17-93%	18-100%	6-75%	16-80%	29-97%	32-89%	43-96%	21-95%	353-92%
<b>Total Notices Printed</b>	7-64%	40-100%	4-100%	10-91%	13-100%	12-86%	8-80%	25-89%	47-94%	5-100%	17-93%	18-100%	6-75%	16-80%	29-97%	32-89%	43-96%	21-95%	353-92%

# Customer Management Report (Ventura) All Detection Types

01-Apr-2012 to 30-Apr-2012

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	22	173	26	27	0	25	39	91	77	12	32	31	21	45	39	37	38	72	807
<b>Less Uncontrollable Factors</b>																			
Obstruction	1	8	5	2	0	0	2	0	4	1	4	5	4	3	9	1	0	3	52
Motor Cycle Helmet	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1	2
Plate Obstruction	1	2	16	5	0	2	1	3	1	0	2	2	0	0	1	3	0	3	42
Vehicle Obstruction	0	3	0	0	0	0	3	1	0	5	0	3	1	2	1	0	1	0	20
Police Rejects	3	3	0	0	0	0	0	1	3	0	0	1	0	0	0	0	0	1	12
Gender Mismatch	1	4	0	0	0	1	0	0	2	0	0	0	0	0	1	1	1	0	11
Incorrect/Incomplete DMV	0	3	0	1	0	0	0	1	2	0	1	0	0	1	1	1	1	0	12
Multiple vehicles in frame	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
On or Passed the Stop Bar (PD)	0	1	0	1	0	0	5	0	1	0	0	3	2	0	0	0	0	2	15
Plate Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1
Safe Turn On Red	0	82	0	0	0	0	0	46	12	0	0	0	0	0	0	0	0	14	154
Policy/Weather	0	3	1	0	0	1	1	0	0	0	0	3	0	0	0	0	0	1	10
Extended Vehicle	4	10	0	0	0	1	5	9	8	4	1	1	4	16	1	5	6	14	89
Sun Glare	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Out of Country Plate	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	1	3	4	25
Paper Plates	1	5	0	0	0	2	0	4	1	0	1	0	1	2	1	3	0	4	25
Wrong or No DMV	0	7	0	4	0	1	0	2	1	0	0	0	0	2	2	1	1	0	21
<b>Total</b>	11	133	22	13	0	8	17	67	38	10	9	18	12	27	17	16	10	43	469
<b>Sub Total Violations</b>	11	40	4	14	0	17	22	24	41	2	23	13	9	18	22	21	28	29	338
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	11	40	4	14	0	17	22	24	41	2	23	13	9	18	22	21	28	29	338
<b>Less Rejects</b>																			
Camera Flash	1-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera No Flash	2-18%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-01%
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-01%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-01%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-27%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-03%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-01%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	1-08%	5-12%	0-00%	2-14%	0-00%	0-00%	2-09%	0-00%	0-00%	0-00%	1-04%	1-08%	0-00%	2-11%	3-14%	1-05%	1-04%	3-10%	22-07%
Sun Glare	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	0-00%	6-02%

Generated By: RWEEKS

Generated On: 10/4/2012 10:31:06 AM

© Redflex Traffic Systems, Inc.

# Customer Management Report (Ventura) All Detection Types

01-Apr-2012 to 30-Apr-2012

Operator Id: %

	5-45%	5-12%	0-00%	2-14%	0-00%	0-00%	0-00%	14-64%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	TOTAL
VE-BRJO-01	6-55%	35-88%	4-100%	12-86%	0-00%	0-00%	0-00%	8-38%	21-88%	40-98%	2-100%	2-100%	22-96%	11-85%	7-78%	16-89%	15-68%	20-95%	23-82%	22-76%	281-83%
VE-CATH-01	6-55%	35-88%	4-100%	12-86%	0-00%	0-00%	0-00%	8-38%	21-88%	40-98%	2-100%	2-100%	22-96%	11-85%	7-78%	16-89%	15-68%	20-95%	23-82%	22-76%	281-83%
VE-FOVI-01	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
VE-JONB-01	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
VE-MA10-01	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
VE-MALE-01	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
VE-MAMI-01	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
VE-MIDE-01	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
VE-MITG-01	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
VE-TGDA-01	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
VE-THSE-01	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
VE-VIMO-01	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
VE-VIOP-01	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
VE-VIRA-01	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
VE-VITG-01	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
VE-VITP-01	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
VE-VITP-03	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
VE-VIVA-01	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
TOTAL	5-45%	5-12%	0-00%	2-14%	0-00%	0-00%	0-00%	14-64%	3-12%	1-02%	0-00%	0-00%	1-04%	2-15%	2-22%	2-11%	7-32%	1-05%	5-18%	7-24%	57-17%
Approved Violations	6-55%	35-88%	4-100%	12-86%	0-00%	0-00%	0-00%	8-38%	21-88%	40-98%	2-100%	2-100%	22-96%	11-85%	7-78%	16-89%	15-68%	20-95%	23-82%	22-76%	281-83%
Total Notices Printed	6-55%	35-88%	4-100%	12-86%	0-00%	0-00%	0-00%	8-38%	21-88%	40-98%	2-100%	2-100%	22-96%	11-85%	7-78%	16-89%	15-68%	20-95%	23-82%	22-76%	281-83%



# Customer Management Report (Ventura) All Detection Types

01-May-2012 to 31-May-2012  
Operator Id: %

	28	172	51	26	0	31	44	88	62	17	38	40	32	34	45	39	40	66	853
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	28	172	51	26	0	31	44	88	62	17	38	40	32	34	45	39	40	66	853
<b>Less Uncontrollable Factors</b>																			
Obstruction	2	16	41	3	0	3	3	3	3	2	3	4	4	2	14	3	3	2	111
Driver Obstruction/Duckers	0	1	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	2
Motor Cycle Helmet	2	7	0	2	0	5	2	2	1	2	0	2	1	0	0	0	1	3	30
Plate Obstruction	0	3	0	0	0	0	1	0	0	7	0	2	0	1	1	0	0	1	16
Vehicle Obstruction	0	2	0	0	0	0	0	0	1	0	0	2	0	0	0	1	1	1	8
Driver Obstruction (PD)	0	2	0	0	0	0	0	0	0	0	0	2	0	0	0	1	1	1	8
Multiple vehicles in frame	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
On or Passed the Stop Bar (PD)	2	0	0	0	0	1	3	3	3	0	0	1	3	0	0	0	0	0	13
Plate Obstruction (PD)	0	0	0	1	0	0	0	0	0	0	0	0	0	1	0	0	0	0	2
Plate Unidentifiable	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Safe Turn On Red	0	52	0	0	0	0	0	44	8	0	0	0	0	0	0	0	0	15	119
Policy/Weather	0	3	0	1	0	0	0	0	0	0	0	1	0	0	0	0	0	0	7
Extended Vehicle	10	22	3	1	0	3	13	2	6	1	4	0	7	7	5	7	7	10	108
Sun Glare	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Registration	1	4	2	2	0	1	0	2	3	0	0	0	0	1	1	3	1	3	24
Gender Match	1	4	2	2	0	1	0	2	3	0	0	0	0	1	1	3	1	3	24
Paper Plates	1	4	2	2	0	1	0	2	3	0	0	0	0	1	1	3	1	3	24
Wrong or No DMV	1	4	2	2	0	1	0	2	3	0	0	0	0	1	1	3	1	3	24
Total	18	116	46	10	0	12	20	60	29	12	9	16	15	12	21	14	13	38	461
<b>Sub Total Violations</b>	10	56	5	16	0	19	24	28	33	5	29	24	17	22	24	25	27	28	392
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>	10	56	5	16	0	19	24	28	33	5	29	24	17	22	24	25	27	28	392
<b>Less Rejects</b>																			
Camera	2-20%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%
Face Camera Flash	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera No Flash	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	3-01%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-40%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	1-10%	6-11%	0-00%	0-00%	0-00%	0-00%	5-21%	0-00%	1-03%	0-00%	2-07%	0-00%	0-00%	0-00%	0-00%	3-12%	1-04%	1-04%	20-05%
Sun Glare	0-00%	2-04%	0-00%	0-00%	0-00%	2-11%	1-04%	2-07%	2-06%	0-00%	0-00%	0-00%	4-24%	0-00%	1-04%	2-08%	1-04%	1-04%	18-05%
Total	5-50%	8-14%	0-00%	0-00%	0-00%	2-11%	7-28%	3-11%	3-08%	2-40%	2-07%	0-00%	5-23%	0-00%	1-04%	6-24%	3-11%	2-07%	49-12%
<b>Approved Violations</b>	5-50%	48-86%	5-100%	16-100%	0-00%	17-58%	17-71%	25-89%	30-91%	3-60%	27-88%	24-100%	12-71%	22-100%	23-96%	19-76%	24-88%	26-93%	343-88%
<b>Total Notices Printed</b>	5-50%	48-86%	5-100%	16-100%	0-00%	17-58%	17-71%	25-89%	30-91%	3-60%	27-88%	24-100%	12-71%	22-100%	23-96%	19-76%	24-88%	26-93%	343-88%

# Customer Management Report (Ventura) All Detection Types

01-Jun-2012 to 30-Jun-2012

Operator Id: %

	17	203	6	19	0	27	45	99	57	6	61	44	26	43	39	41	51	79	863
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	0	13	0	2	0	1	1	1	2	1	2	3	3	7	6	0	1	7	863
<b>Less Uncontrollable Factors</b>																			
Obstruction	0	0	0	1	0	0	0	0	0	0	0	0	0	1	0	0	0	0	2
Driver Obstruction/Duckers	0	0	0	1	0	0	0	0	0	0	0	0	0	1	0	0	0	0	2
Motor Cycle Helmet	1	7	1	2	0	1	1	1	1	2	1	3	1	0	0	1	0	2	25
Plate Obstruction	0	2	0	0	0	0	6	0	0	1	0	1	0	1	0	1	1	1	14
Vehicle Obstruction	0	6	0	0	0	1	0	0	3	0	3	2	0	0	1	0	1	0	17
Driver Obstruction (PD)	0	0	0	0	0	0	1	1	0	0	0	0	0	0	1	0	1	0	4
Emergency Vehicle Responding	0	1	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	3
Gender Mismatch	0	3	0	0	0	1	0	0	0	0	2	1	0	1	0	0	0	0	8
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Invalid Offense	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Multiple vehicles in frame	1	1	0	2	0	1	1	1	2	0	0	4	1	0	0	0	0	0	14
On or Passed the Stop Bar (PD)	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
Plate Obstruction (PD)	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Plate Unidentifiable	0	88	0	0	0	0	0	42	6	0	0	0	0	0	0	0	0	19	155
Safe Turn On Red	0	2	0	0	0	0	0	0	1	0	2	3	0	0	0	0	0	0	8
Policy/Weather	5	20	0	0	0	7	8	12	6	0	6	1	3	11	1	7	2	20	109
Extended Vehicle	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
Sun Glare	0	0	0	0	0	1	0	1	0	0	1	0	1	2	2	0	0	0	16
Registration	1	7	0	0	0	1	0	1	0	0	1	0	1	2	0	0	0	0	29
Out of Country Plate	0	10	0	2	0	0	0	3	4	0	1	2	2	0	2	2	2	1	460
Issues	9	162	1	9	0	13	19	62	25	4	21	20	11	23	12	11	8	50	460
Paper Plates	8	41	5	10	0	14	26	37	32	2	40	24	15	20	27	30	43	29	403
Wrong or No DMV	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sub Total Violations	8	41	5	10	0	14	26	37	32	2	40	24	15	20	27	30	43	29	403
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	8	41	5	10	0	14	26	37	32	2	40	24	15	20	27	30	43	29	403
<b>Less Rejects</b>																			
Camera	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Flash	0-00%	0-00%	3-60%	0-00%	0-00%	0-00%	9-35%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	1-03%	14-03%
Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	2-05%	1-03%	4-01%
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable Images poor	1-12%	6-15%	1-20%	0-00%	0-00%	0-00%	2-08%	1-03%	2-06%	0-00%	2-05%	2-08%	0-00%	2-10%	3-11%	8-27%	2-05%	3-10%	35-09%
Sun Glare	0-00%	3-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	1-04%	1-03%	5-12%	1-03%	12-03%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: RWEEKS  
Generated On: 10/4/2012 10:32:12 AM



# Customer Management Report (Ventura) All Detection Types

01-Jul-2012 to 31-Jul-2012 Operator Id: %

	10	206	13	16	54	28	44	79	57	24	36	22	24	38	36	33	46	68	834
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	1	8	1	2	0	1	1	3	3	1	0	1	3	2	6	1	2	4	40
<b>Less Uncontrollable Factors</b>	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Obstruction Driver Obstruction/Duckers	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Motor Cycle Helmet	0	7	0	1	1	1	1	1	1	4	0	2	0	0	0	0	0	0	18
Plate Obstruction	0	3	0	0	2	0	0	1	0	3	2	0	1	0	1	0	0	0	14
Vehicle Obstruction	0	7	0	0	1	0	0	0	2	0	0	0	0	0	0	0	0	0	12
Police Rejects	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Gender Mismatch	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Incorrect/Incomplete DMV	2	3	0	0	3	1	0	0	4	0	0	1	4	0	0	0	0	0	18
On or Passed the Stop Bar (PD)	0	1	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	3
Plate Obstruction (PD)	0	74	0	0	0	0	0	38	7	0	0	0	0	0	0	0	0	0	125
Safe Turn On Red	0	5	0	0	0	0	1	0	0	2	0	1	0	0	0	0	0	0	11
Policy/Weather Extended Vehicle	1	17	0	0	4	6	13	8	6	4	4	3	1	12	1	4	4	16	104
Sun Glare	0	5	0	0	0	1	1	2	1	0	1	0	0	0	1	0	0	1	13
Paper Plates	0	7	0	1	0	1	2	0	2	0	0	0	0	0	1	1	2	3	20
Registration Issues	4	138	1	5	13	11	19	53	26	14	7	8	9	14	10	6	9	35	382
Wrong or No DMV	6	68	12	11	41	17	25	26	31	10	29	14	15	24	26	27	37	33	452
<b>Sub Total Violations</b>	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Less in Progress	6	68	12	11	41	17	25	26	31	10	29	14	15	24	26	27	37	33	452
<b>Available For Prosecution</b>	6	68	12	11	41	17	25	26	31	10	29	14	15	24	26	27	37	33	452
<b>Less Rejects</b>	0-00%	0-00%	9-75%	0-00%	2-05%	0-00%	4-16%	1-04%	0-00%	3-30%	2-07%	1-07%	2-13%	0-00%	0-00%	0-00%	0-00%	0-00%	24-05%
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-04%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Image Missing	0-00%	0-00%	0-00%	0-00%	4-10%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	2-05%	0-00%	9-02%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-30%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	5-12%	0-00%	0-00%	0-00%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	8-02%
Plate Not in Frame	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate Camera Inappropriate	1-17%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate No Flash	1-17%	3-04%	1-06%	1-09%	1-02%	6-35%	5-20%	1-04%	0-00%	0-00%	0-00%	0-00%	2-13%	3-12%	4-15%	0-00%	0-00%	6-18%	37-08%
Driver Unidentifiable images poor	0-00%	3-04%	0-00%	0-00%	0-00%	0-00%	2-08%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	2-05%	0-00%	0-00%	8-02%
Sun Glare	2-33%	6-09%	10-03%	2-18%	13-32%	8-47%	13-52%	3-12%	0-00%	7-70%	3-10%	1-07%	5-33%	3-12%	6-22%	4-11%	7-21%	96-21%	96-21%
<b>Approved Violations</b>	4-67%	62-91%	2-17%	9-82%	28-66%	9-53%	12-48%	23-88%	31-100%	3-30%	26-90%	13-93%	10-67%	21-88%	23-88%	21-78%	33-89%	26-79%	356-79%
<b>Total Notices Printed</b>	4-67%	62-91%	2-17%	9-82%	28-66%	9-53%	12-48%	23-88%	31-100%	3-30%	26-90%	13-93%	10-67%	21-88%	23-88%	21-78%	33-89%	26-79%	356-79%

# Customer Management Report (Ventura) All Detection Types

01-Aug-2012 to 31-Aug-2012

Operator Id: %

	16	180	18	17	78	36	35	98	58	12	43	45	21	46	51	38	67	80	939
	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	2	16	3	0	1	1	0	1	1	0	3	3	2	0	6	3	1	2	45
<b>Less Uncontrollable Factors</b>																			
Obstruction	0	0	0	1	0	0	0	0	1	0	0	0	0	0	0	0	0	0	3
Driver Obstruction/Duckets	0	4	0	1	5	2	0	1	0	1	0	3	0	0	0	0	0	0	17
Motor Cycle Helmet	0	2	0	1	1	0	4	0	0	0	0	2	0	0	1	0	0	0	11
Plate Obstruction	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Vehicle Obstruction	0	6	0	0	1	0	0	0	4	0	1	1	0	0	1	0	1	1	16
Citation issued manually	0	0	0	3	3	0	1	1	0	0	0	6	1	0	0	0	0	0	16
Driver Obstruction (PD)	0	0	0	0	1	0	0	0	0	0	0	1	0	0	0	0	0	0	2
On or Passed the Stop Bar (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Plate Obstruction (PD)	0	58	0	0	0	0	55	5	0	0	0	0	0	0	0	0	0	0	131
Plate Unidentifiable	0	1	0	1	1	0	0	0	0	0	1	6	0	0	0	0	0	0	12
Safe Turn On Red	0	26	0	0	9	7	1	7	10	4	8	1	6	12	11	4	10	22	142
Policy/Weath er	0	3	0	0	1	2	0	5	1	1	1	0	2	3	5	0	0	2	26
Extended Vehicle	1	3	0	1	1	0	0	3	0	0	1	0	1	0	1	0	0	0	15
Sun Glare	7	120	3	8	25	12	6	73	22	6	16	23	12	15	25	7	15	43	438
Paper Plates	9	60	15	9	53	24	29	25	36	6	27	22	9	31	26	31	52	37	501
Registration Issues	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Wrong or No DMV	9	60	15	9	53	24	29	25	36	6	27	22	9	31	26	31	52	37	501
<b>Sub Total Violations</b>																			
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>	9	60	15	9	53	24	29	25	36	6	27	22	9	31	26	31	52	37	501
<b>Less Rejects</b>																			
Camera Malfunction	1-11%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Face Camera Flash	1-11%	0-00%	5-33%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
Face Camera No Flash	1-11%	0-00%	0-00%	0-00%	1-04%	1-04%	4-14%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	0-00%	0-00%	0-00%	0-00%	9-02%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Image Missing	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	13-03%
Misc Camera Issue	0-00%	0-00%	5-33%	0-00%	3-06%	0-00%	0-00%	2-08%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	2-08%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-05%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	2-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Rejects	3-33%	4-07%	0-00%	0-00%	1-02%	2-08%	8-28%	2-08%	1-03%	0-00%	0-00%	1-05%	0-00%	2-06%	3-12%	6-19%	1-02%	2-05%	36-07%
Driver Unidentifiable images poor	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Incorrect Speed	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	8-02%
Sun Glare	6-67%	6-10%	11-73%	0-00%	8-19%	5-21%	15-52%	6-24%	3-08%	2-33%	0-00%	3-14%	0-00%	4-13%	5-19%	7-23%	4-08%	4-11%	89-16%
<b>Total</b>	3-33%	54-90%	4-27%	9-100%	45-85%	19-79%	14-48%	19-76%	33-92%	4-57%	27-100%	19-86%	9-100%	27-87%	21-81%	24-77%	48-92%	35-89%	412-82%
<b>Approved Violations</b>	3-33%	54-90%	4-27%	9-100%	45-85%	19-79%	14-48%	19-76%	33-92%	4-57%	27-100%	19-86%	9-100%	27-87%	21-81%	24-77%	48-92%	35-89%	412-82%
<b>Total Notices Printed</b>	3-33%	54-90%	4-27%	9-100%	45-85%	19-79%	14-48%	19-76%	33-92%	4-57%	27-100%	19-86%	9-100%	27-87%	21-81%	24-77%	48-92%	35-89%	412-82%
<b>Generated By:</b>	RWEKES																		
<b>Generated On:</b>	10/4/2012 10:35:09 AM																		

# Customer Management Report (Ventura) All Detection Types

01-Sep-2012 to 30-Sep-2012 Operator Id: %

	18	172	35	20	52	32	45	97	56	21	23	42	26	38	71	40	56	66	TOTAL
<b>Total Processed Incidents</b>	3	9	0	1	0	0	1	2	6	1	0	3	0	3	9	1	0	2	910
<b>Less Uncontrollable Factors</b>																			
Obstruction	0	0	0	1	3	0	1	0	3	0	0	1	0	0	0	0	1	0	41
Driver Obstruction/Duckets	0	2	0	0	0	3	1	0	3	0	0	1	0	0	0	0	1	1	11
Motor Cycle Helmet	0	1	0	0	0	0	2	0	0	1	0	1	1	0	0	1	0	0	12
Plate Obstruction	0	0	0	0	4	0	0	0	0	2	0	1	1	1	2	0	0	0	14
Vehicle Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	7
Police Rejects	0	0	0	0	0	1	0	0	0	0	1	1	1	0	1	0	1	1	7
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Invalid Offense	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Multiple vehicles in frame	0	3	0	0	0	2	1	2	2	0	0	2	4	0	0	0	0	0	16
On or Passed the Stop Bar (PD)	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Plate Unidentifiable	0	75	0	0	0	0	0	44	6	0	0	0	0	0	0	0	0	0	134
Safe Turn On Red	0	0	0	1	2	0	0	0	0	1	0	2	0	0	0	0	0	0	7
Policy/Weath er	0	16	0	2	2	1	1	3	2	5	3	0	1	13	3	4	3	12	71
Extended Vehicle Sun Glare	1	8	0	0	2	3	2	2	2	0	1	1	1	0	1	0	0	3	27
Registration Paper Plates	1	1	0	0	2	4	2	5	1	1	0	2	1	3	1	2	1	2	29
Issues Wrong or No DMV	5	116	0	5	18	14	11	59	22	11	5	14	10	20	17	8	8	31	374
<b>Total</b>	13	56	35	15	34	18	34	38	34	10	18	28	16	18	54	32	48	35	536
<b>Sub Total Violations</b>	0	5	0	0	0	0	2	3	1	0	0	1	3	1	2	0	0	0	18
Less in Progress	13	51	35	15	34	18	32	35	33	10	18	27	13	17	52	32	48	35	518
<b>Available For Prosecution</b>																			
<b>Less Rejects</b>																			
Camera Malfunction	0-00%	0-00%	2-08%	7-47%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	9-02%
Face Camera Flash	0-00%	0-00%	10-29%	5-33%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	15-03%
Face Camera No Flash	1-08%	0-00%	0-00%	0-00%	1-03%	0-00%	5-16%	0-00%	0-00%	4-40%	0-00%	0-00%	1-08%	0-00%	2-04%	0-00%	0-00%	0-00%	14-03%
Face Not in Frame	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	4-01%
Image Missing	0-00%	0-00%	18-51%	0-00%	4-12%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	25-05%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Bum Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	3-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Scene Image No Flash	0-00%	0-00%	2-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Rejects	1-08%	4-08%	0-00%	0-00%	1-06%	0-00%	3-09%	1-03%	2-06%	0-00%	0-00%	1-04%	2-15%	2-12%	7-13%	8-25%	4-08%	2-06%	38-07%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Sun Glare	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	3-09%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	1-06%	0-00%	0-00%	3-06%	1-03%	10-02%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
<b>Total</b>	2-15%	5-10%	33-94%	12-80%	7-21%	5-28%	13-41%	3-09%	2-06%	5-50%	0-00%	2-07%	4-31%	3-18%	10-19%	8-25%	10-21%	7-20%	131-25%

Generated By: RWEKES  
Generated On: 10/4/2012 10:35:55 AM

# Customer Management Report (Ventura) All Detection Types

01-Sep-2012 to 30-Sep-2012

Operator Id: %

Category	Approved Violations	Total Notices Printed	Percentage	Percentage
VE-BRJO-01	11-85%	11-85%		387-75%
VE-CATH-01	46-90%	46-90%		28-80%
VE-FOVI-01	2-06%	2-06%		28-80%
VE-JONB-01	3-20%	3-20%		38-79%
VE-MA10-01	27-79%	27-79%		38-79%
VE-MALE-01	13-72%	13-72%		24-75%
VE-MAMI-01	19-59%	19-59%		24-75%
VE-MIDE-01	32-91%	32-91%		42-81%
VE-MITG-01	31-94%	31-94%		42-81%
VE-TGDA-01	5-50%	5-50%		14-82%
VE-THSE-01	18-100%	18-100%		14-82%
VE-VIMO-01	25-93%	25-93%		9-69%
VE-VIOP-01	9-69%	9-69%		9-69%
VE-VIRA-01	14-82%	14-82%		24-75%
VE-VITG-01	42-81%	42-81%		24-75%
VE-VITP-01	24-75%	24-75%		38-79%
VE-VITP-03	38-79%	38-79%		38-79%
VE-VIVA-01	28-80%	28-80%		387-75%
TOTAL				387-75%