

# Customer Management Report (Ventura) Redlight Incidents

01-Oct-2019 to 31-Oct-2019

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	6	191	17	14	152	47	36	58	0	4	67	69	65	53	282	166	190	66	1483	
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	1	28	1	0	6	4	4	4	0	0	9	8	9	35	5	6	5	125	
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1	2	
	Plate Obstruction	1	2	0	0	15	2	1	8	0	1	5	4	0	1	5	2	0	4	51
	Vehicle Obstruction	1	9	2	0	2	0	3	1	0	0	2	1	1	1	7	1	6	0	37
Police Rejects	Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1	
	On or Passed the Stop Bar (PD).	0	7	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1	9	
	Police Discretion	0	2	0	1	1	1	0	0	0	0	0	3	0	3	5	0	1	17	
	Sun Glare	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1	
	Vehicle Obstruction	0	4	0	0	0	0	0	0	0	0	0	1	0	0	0	1	0	6	
Policy/Weather	Extended Vehicle	0	4	0	0	2	0	0	0	0	0	3	0	0	1	0	3	1	14	
	Sun Glare	0	30	1	0	20	3	10	5	0	14	1	3	20	33	25	29	30	224	
	Weather/Nature	0	0	0	1	0	0	0	0	0	0	0	0	1	0	0	0	0	2	
Registration Issues	Paper Plates	0	0	2	0	2	0	0	0	0	0	0	0	0	0	2	1	1	8	
	Wrong or No DMV	0	3	1	2	2	3	1	1	0	1	1	0	0	4	4	5	2	30	
<b>Total</b>	3	89	7	4	51	13	19	19	0	1	23	20	15	32	89	44	52	46	527	
<b>Sub Total Violations</b>	3	102	10	10	101	34	17	39	0	3	44	49	50	21	193	122	138	20	956	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
<b>Available For Prosecution</b>	3	102	10	10	101	34	17	39	0	3	44	49	50	21	193	122	138	20	956	
<b>Less Rejects</b>																				
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	
	Image Missing	2-67%	0-00%	0-00%	0-00%	3-03%	0-00%	0-00%	3-08%	0-00%	0-00%	0-00%	4-08%	0-00%	0-00%	0-00%	0-00%	0-00%	12-01%	
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	
	Rear Plate Flash Inappropriate	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%	
	Test Pattern	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	1-00%	
	Video Skips	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	1-00%	
Police Rejects	Driver Unidentifiable images poor	0-00%	1-01%	0-00%	0-00%	3-03%	1-03%	1-06%	0-00%	0-00%	0-00%	1-02%	0-00%	2-10%	3-02%	1-01%	6-04%	2-10%	21-02%	
	Plate Unclear	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%	
	Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%	
Process Issues	Too Old	0-00%	6-06%	0-00%	0-00%	4-04%	1-03%	0-00%	1-03%	0-00%	0-00%	0-00%	1-02%	1-05%	5-03%	4-03%	4-03%	1-05%	28-03%	
<b>Total</b>	2-67%	8-08%	0-00%	0-00%	10-10%	2-06%	1-06%	7-18%	0-00%	0-00%	0-00%	6-12%	1-02%	5-24%	10-05%	6-05%	11-08%	3-15%	72-08%	
<b>Approved Violations</b>	1-33%	94-92%	10-100%	10-100%	91-90%	32-94%	16-94%	32-82%	0-00%	3-100%	44-100%	43-88%	49-98%	16-76%	183-95%	116-95%	127-92%	17-85%	884-92%	

Generated By: MESCOBEDO

Generated On: 2/7/2020 1:56:08 PM

# Customer Management Report (Ventura) Redlight Incidents

01-Oct-2019 to 31-Oct-2019

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Notices Printed	1-33%	94-92%	10-100%	10-100%	91-90%	32-94%	16-94%	32-82%	0-00%	3-100%	44-100%	43-88%	49-98%	16-76%	183-95%	116-95%	127-92%	17-85%	884-92%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MESCOBEDO

Generated On: 2/7/2020 1:56:08 PM

# Customer Management Report (Ventura) Redlight Incidents

01-Nov-2019 to 30-Nov-2019

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	46	157	17	37	149	44	30	32	45	18	45	46	100	26	161	199	130	75	1357	
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	8	16	2	6	2	2	1	2	1	0	0	7	8	4	11	4	3	7	84
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
	Plate Obstruction	2	2	2	1	13	2	0	2	1	1	3	5	1	0	2	3	0	1	41
	Vehicle Obstruction	0	9	1	3	5	0	2	0	0	0	1	0	1	2	7	3	2	2	38
Police Rejects	On or Passed the Stop Bar (PD).	0	3	0	0	0	1	0	0	0	0	0	0	0	0	0	2	0	3	9
	Police Discretion	0	3	0	0	2	0	0	0	2	0	0	0	2	0	1	8	0	2	20
	Sun Glare	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
	Vehicle Obstruction	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Policy/Weather	Extended Vehicle	1	3	0	0	1	0	1	0	0	0	4	0	0	0	0	0	0	0	10
	Sun Glare	4	23	2	0	18	1	9	4	14	1	9	0	11	9	19	41	23	29	217
Registration Issues	Out of Country Plate	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	1
	Paper Plates	0	4	0	1	4	0	0	1	0	1	1	0	1	1	0	1	1	1	16
	Wrong or No DMV	2	1	0	2	2	1	0	0	0	0	0	2	0	4	5	5	5	1	25
<b>Total</b>	17	66	7	13	47	7	13	10	18	3	13	17	25	16	46	66	35	46	465	
<b>Sub Total Violations</b>	29	91	10	24	102	37	17	22	27	15	32	29	75	10	115	133	95	29	892	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
<b>Available For Prosecution</b>	29	91	10	24	102	37	17	22	27	15	32	29	75	10	115	133	95	29	892	
<b>Less Rejects</b>																				
Camera Malfunction	Face Not in Frame	2-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	3-00%
	Image Missing	3-10%	0-00%	0-00%	1-04%	1-01%	0-00%	0-00%	1-05%	3-11%	0-00%	0-00%	2-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	11-01%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Video Not In Sync	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	3-03%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	1-07%	0-00%	0-00%	1-01%	1-10%	3-03%	3-02%	4-04%	3-10%	20-02%
	Plate Unclear	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	Too Old	1-03%	5-05%	3-30%	1-04%	4-04%	3-08%	0-00%	2-09%	1-04%	0-00%	0-00%	2-07%	9-12%	3-30%	3-03%	7-05%	3-03%	3-10%	50-06%
<b>Total</b>	7-24%	8-09%	3-30%	2-08%	6-06%	4-11%	1-06%	4-18%	5-19%	2-13%	1-03%	4-14%	12-16%	4-40%	7-06%	11-08%	7-07%	6-21%	94-11%	
<b>Approved Violations</b>	22-76%	83-91%	7-70%	22-92%	96-94%	33-89%	16-94%	18-82%	22-81%	13-87%	31-97%	25-86%	63-84%	6-60%	108-94%	122-92%	88-93%	23-79%	798-89%	
<b>Total Notices Printed</b>	22-76%	83-91%	7-70%	22-92%	96-94%	33-89%	16-94%	18-82%	22-81%	13-87%	31-97%	25-86%	63-84%	6-60%	108-94%	122-92%	88-93%	23-79%	798-89%	

Generated By: MESCOBEDO  
Generated On: 2/7/2020 1:56:51 PM

# Customer Management Report (Ventura) Redlight Incidents

01-Nov-2019 to 30-Nov-2019

Operator Id: %

TOTAL
VE-VIVA-01
VE-VITP-03
VE-VITP-01
VE-VITG-01
VE-VIRA-01
VE-VIOP-01
VE-VIMO-01
VE-THSE-01
VE-TGDA-01
VE-MITG-01
VE-MIDE-01
VE-MAMI-01
VE-MALE-01
VE-MA10-01
VE-JONB-01
VE-FOV1-01
VE-CATH-01
VE-BRJO-01

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) Redlight Incidents

01-Jan-2019 to 31-Dec-2019

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL		
<b>Total Processed Incidents</b>	294	1736	210	200	1527	612	450	632	674	134	580	456	817	552	2543	1869	1820	693	15799		
<b>Less Uncontrollable Factors</b>																					
Obstruction	Driver Obstruction/Duckers	33	206	39	12	77	48	33	29	14	3	24	47	89	80	246	66	55	72	1173	
	Motor Cycle Helmet	0	3	0	0	1	0	1	1	7	0	3	0	1	3	6	0	2	2	30	
	Plate Obstruction	9	38	6	5	68	21	11	20	8	6	18	23	12	8	34	17	9	26	339	
	Signal Obstruction	0	0	2	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	4	
	Vehicle Obstruction	6	80	8	4	42	4	25	7	3	3	18	11	6	23	89	22	37	9	397	
	Police Rejects	Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
		Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
		Incorrect/Incomplete DMV	0	0	0	0	0	1	0	1	0	0	1	0	0	0	1	1	1	1	7
		Invalid Offense	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
		Multiple vehicles in frame	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
		On or Passed the Stop Bar (PD)	0	66	0	1	26	2	0	79	33	2	5	1	0	1	1	29	21	59	326
		Police Discretion	0	20	4	1	6	1	2	0	4	0	2	2	18	0	15	49	56	17	197
		Safe Turn On Red	0	3	0	0	0	0	0	5	2	0	0	0	0	0	0	0	0	2	12
		Sun Glare	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1	0	0	0	2
Vehicle Obstruction		0	19	0	0	0	0	0	0	0	0	0	1	1	0	1	1	1	1	25	
Weather Conditions	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1		
Policy/Weather	Extended Vehicle	4	16	1	1	12	0	3	1	0	2	2	12	3	1	4	8	11	6	87	
	Sun Glare	21	242	9	3	127	35	81	31	110	20	74	5	51	148	207	255	241	154	1814	
	Weather/Nature	2	6	4	1	3	3	4	1	1	1	1	0	1	3	1	9	18	3	62	
Registration Issues	Can Not Identify State	0	1	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	2	
	Out of Country Plate	0	1	0	0	1	1	0	0	0	0	0	0	0	0	1	0	1	0	5	
	Paper Plates	2	32	4	8	33	15	20	23	10	2	15	15	12	16	31	17	39	17	311	
	Wrong or No DMV	6	23	4	12	27	13	7	7	11	1	10	7	20	6	56	51	51	16	328	
<b>Total</b>	83	756	81	48	423	144	187	208	204	40	176	124	214	289	695	525	543	386	5126		
<b>Sub Total Violations</b>	211	980	129	152	1104	468	263	424	470	94	404	332	603	263	1848	1344	1277	307	10673		
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
<b>Available For Prosecution</b>	211	980	129	152	1104	468	263	424	470	94	404	332	603	263	1848	1344	1277	307	10673		
<b>Less Rejects</b>																					
Camera Malfunction	Datar Unreadable/Incorrect	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%		
	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%		
	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	1-00%	6-00%	
	Face Camera Focus Blurry	0-00%	3-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	3-00%	2-00%	2-00%	4-01%	17-00%	
	Face Camera No Flash	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Not in Frame	2-01%	0-00%	5-04%	0-00%	0-00%	0-00%	1-00%	1-00%	0-00%	0-00%	1-00%	3-01%	1-00%	0-00%	3-00%	1-00%	4-00%	0-00%	22-00%	
	Image Missing	5-02%	0-00%	0-00%	2-01%	5-00%	2-00%	0-00%	7-02%	5-01%	0-00%	1-00%	20-06%	0-00%	0-00%	1-00%	0-00%	1-00%	0-00%	49-00%	

Generated By: MESCOBEDO

Generated On: 2/7/2020 2:03:24 PM

# Customer Management Report (Ventura) Redlight Incidents

01-Jan-2019 to 31-Dec-2019

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%	3-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Plate Not in Frame	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	3-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	2-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	5-00%
Rear Plate Flash Inappropriate	0-00%	1-00%	0-00%	0-00%	1-00%	2-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	5-00%
Rear Plate No Flash	0-00%	1-00%	0-00%	0-00%	0-00%	3-01%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-00%
Scene Image Flash Inappropriate	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%	0-00%	3-03%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	12-00%
Scene Image No Flash	1-00%	0-00%	2-02%	0-00%	2-00%	0-00%	0-00%	1-00%	1-00%	2-02%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	10-00%
Test Pattern	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Video Not In Sync	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%
Video Skips	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	2-00%	1-00%	1-00%	3-01%	12-00%
Video does not play	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Police Rejects																			
Driver Unidentifiable images poor	1-00%	43-04%	2-02%	0-00%	12-01%	6-01%	13-05%	9-02%	1-00%	3-03%	1-00%	1-00%	9-01%	7-03%	19-01%	19-01%	30-02%	14-05%	190-02%
Plate Unclear	3-01%	1-00%	0-00%	1-01%	4-00%	2-00%	0-00%	1-00%	1-00%	1-01%	3-01%	0-00%	1-00%	0-00%	7-00%	0-00%	2-00%	0-00%	27-00%
Red-light not visible in	0-00%	0-00%	2-02%	1-01%	4-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%	1-00%	0-00%	3-00%	13-01%	0-00%	28-00%
Unclear Scene Image	0-00%	0-00%	0-00%	1-01%	2-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Process Issues																			
Too Old	4-02%	45-05%	5-04%	5-03%	55-05%	18-04%	8-03%	23-05%	23-05%	4-04%	8-02%	3-01%	23-04%	9-03%	70-04%	49-04%	54-04%	13-04%	419-04%
Total	18-09%	94-10%	18-14%	11-07%	87-08%	37-08%	23-09%	56-13%	32-07%	15-16%	18-04%	29-09%	38-06%	21-08%	108-06%	76-06%	112-09%	36-12%	829-08%
Approved Violations	193-91%	886-90%	111-86%	141-93%	1017-92%	431-92%	240-91%	368-87%	438-93%	79-84%	386-96%	303-91%	565-94%	242-92%	1740-94%	1268-94%	1165-91%	271-88%	9844-92%
Total Notices Printed	193-91%	886-90%	111-86%	141-93%	1017-92%	431-92%	240-91%	368-87%	438-93%	79-84%	386-96%	303-91%	565-94%	242-92%	1740-94%	1268-94%	1165-91%	271-88%	9844-92%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) Redlight Incidents

01-Jan-2019 to 31-Dec-2019

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL		
<b>Total Processed Incidents</b>	294	1736	210	200	1527	612	450	632	674	134	580	456	817	552	2543	1869	1820	693	15799		
<b>Less Uncontrollable Factors</b>																					
Obstruction	Driver Obstruction/Duckers	33	206	39	12	77	48	33	29	14	3	24	47	89	80	246	66	55	72	1173	
	Motor Cycle Helmet	0	3	0	0	1	0	1	1	7	0	3	0	1	3	6	0	2	2	30	
	Plate Obstruction	9	38	6	5	68	21	11	20	8	6	18	23	12	8	34	17	9	26	339	
	Signal Obstruction	0	0	2	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	4	
	Vehicle Obstruction	6	80	8	4	42	4	25	7	3	3	18	11	6	23	89	22	37	9	397	
	Police Rejects	Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
		Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
		Incorrect/Incomplete DMV	0	0	0	0	0	1	0	1	0	0	1	0	0	0	1	1	1	1	7
		Invalid Offense	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
		Multiple vehicles in frame	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
		On or Passed the Stop Bar (PD)	0	66	0	1	26	2	0	79	33	2	5	1	0	1	1	29	21	59	326
		Police Discretion	0	20	4	1	6	1	2	0	4	0	2	2	18	0	15	49	56	17	197
		Safe Turn On Red	0	3	0	0	0	0	0	5	2	0	0	0	0	0	0	0	0	2	12
		Sun Glare	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1	0	0	0	2
Vehicle Obstruction		0	19	0	0	0	0	0	0	0	0	0	1	1	0	1	1	1	1	25	
Weather Conditions	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1		
Policy/Weather	Extended Vehicle	4	16	1	1	12	0	3	1	0	2	2	12	3	1	4	8	11	6	87	
	Sun Glare	21	242	9	3	127	35	81	31	110	20	74	5	51	148	207	255	241	154	1814	
	Weather/Nature	2	6	4	1	3	3	4	1	1	1	1	0	1	3	1	9	18	3	62	
Registration Issues	Can Not Identify State	0	1	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	2	
	Out of Country Plate	0	1	0	0	1	1	0	0	0	0	0	0	0	0	1	0	1	0	5	
	Paper Plates	2	32	4	8	33	15	20	23	10	2	15	15	12	16	31	17	39	17	311	
	Wrong or No DMV	6	23	4	12	27	13	7	7	11	1	10	7	20	6	56	51	51	16	328	
<b>Total</b>	83	756	81	48	423	144	187	208	204	40	176	124	214	289	695	525	543	386	5126		
<b>Sub Total Violations</b>	211	980	129	152	1104	468	263	424	470	94	404	332	603	263	1848	1344	1277	307	10673		
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
<b>Available For Prosecution</b>	211	980	129	152	1104	468	263	424	470	94	404	332	603	263	1848	1344	1277	307	10673		
<b>Less Rejects</b>																					
Camera Malfunction	Databar Unreadable/Incorrect	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%		
	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%		
	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	1-00%	6-00%	
	Face Camera Focus Blurry	0-00%	3-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	3-00%	2-00%	2-00%	4-01%	17-00%	
	Face Camera No Flash	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Not in Frame	2-01%	0-00%	5-04%	0-00%	0-00%	0-00%	1-00%	1-00%	0-00%	0-00%	1-00%	3-01%	1-00%	0-00%	3-00%	1-00%	4-00%	0-00%	22-00%	
	Image Missing	5-02%	0-00%	0-00%	2-01%	5-00%	2-00%	0-00%	7-02%	5-01%	0-00%	1-00%	20-06%	0-00%	0-00%	1-00%	0-00%	1-00%	0-00%	49-00%	

Generated By: MESCOBEDO

Generated On: 2/7/2020 2:03:24 PM

# Customer Management Report (Ventura) Redlight Incidents

01-Jan-2019 to 31-Dec-2019

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%	3-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Plate Not in Frame	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	3-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	2-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	5-00%
Rear Plate Flash Inappropriate	0-00%	1-00%	0-00%	0-00%	1-00%	2-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	5-00%
Rear Plate No Flash	0-00%	1-00%	0-00%	0-00%	0-00%	3-01%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-00%
Scene Image Flash Inappropriate	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%	0-00%	3-03%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	12-00%
Scene Image No Flash	1-00%	0-00%	2-02%	0-00%	2-00%	0-00%	0-00%	1-00%	1-00%	2-02%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	10-00%
Test Pattern	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Video Not In Sync	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%
Video Skips	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	2-00%	1-00%	1-00%	3-01%	12-00%
Video does not play	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Police Rejects																			
Driver Unidentifiable images poor	1-00%	43-04%	2-02%	0-00%	12-01%	6-01%	13-05%	9-02%	1-00%	3-03%	1-00%	1-00%	9-01%	7-03%	19-01%	19-01%	30-02%	14-05%	190-02%
Plate Unclear	3-01%	1-00%	0-00%	1-01%	4-00%	2-00%	0-00%	1-00%	1-00%	1-01%	3-01%	0-00%	1-00%	0-00%	7-00%	0-00%	2-00%	0-00%	27-00%
Red-light not visible in	0-00%	0-00%	2-02%	1-01%	4-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%	1-00%	0-00%	3-00%	13-01%	0-00%	28-00%
Unclear Scene Image	0-00%	0-00%	0-00%	1-01%	2-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Process Issues																			
Too Old	4-02%	45-05%	5-04%	5-03%	55-05%	18-04%	8-03%	23-05%	23-05%	4-04%	8-02%	3-01%	23-04%	9-03%	70-04%	49-04%	54-04%	13-04%	419-04%
Total	18-09%	94-10%	18-14%	11-07%	87-08%	37-08%	23-09%	56-13%	32-07%	15-16%	18-04%	29-09%	38-06%	21-08%	108-06%	76-06%	112-09%	36-12%	829-08%
Approved Violations	193-91%	886-90%	111-86%	141-93%	1017-92%	431-92%	240-91%	368-87%	438-93%	79-84%	386-96%	303-91%	565-94%	242-92%	1740-94%	1268-94%	1165-91%	271-88%	9844-92%
Total Notices Printed	193-91%	886-90%	111-86%	141-93%	1017-92%	431-92%	240-91%	368-87%	438-93%	79-84%	386-96%	303-91%	565-94%	242-92%	1740-94%	1268-94%	1165-91%	271-88%	9844-92%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current



# Customer Management Report (Ventura) Redlight Incidents

01-Jan-2020 to 31-Jan-2020

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	37	119	11	35	121	17	34	49	9	16	47	42	69	27	217	167	152	70	1239	
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	1	12	2	1	2	1	3	0	0	0	1	2	8	6	22	3	4	7	75
	Motor Cycle Helmet	0	1	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	3
	Plate Obstruction	3	3	1	1	5	1	0	2	0	0	0	1	2	0	1	0	0	0	20
	Vehicle Obstruction	2	6	0	0	2	0	0	0	1	2	2	0	2	0	12	3	2	1	35
Police Rejects	Incorrect Plate on Vehicle	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	2
	Incorrect/Incomplete DMV	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
	On or Passed the Stop Bar (PD)	0	5	0	0	0	0	0	0	0	0	0	0	0	0	0	2	1	4	12
	Police Discretion	0	2	1	0	1	0	0	0	0	0	0	0	1	0	1	2	0	1	9
	Vehicle Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Policy/Weather	Extended Vehicle	0	3	0	1	0	0	0	0	1	0	1	1	0	0	0	0	0	2	9
	Sun Glare	3	19	0	1	21	1	9	2	0	0	9	1	3	9	26	38	20	26	188
	Weather/Nature	0	0	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	2
Registration Issues	Paper Plates	0	0	0	0	0	0	1	0	0	0	1	0	0	0	2	0	0	1	5
	Wrong or No DMV	3	1	0	2	3	1	0	1	0	0	1	1	1	0	4	3	7	0	28
<b>Total</b>	12	52	6	6	35	5	15	6	2	2	15	6	17	15	68	51	34	43	390	
<b>Sub Total Violations</b>	25	67	5	29	86	12	19	43	7	14	32	36	52	12	149	116	118	27	849	
Less in Progress	2	3	0	2	2	1	1	2	0	0	2	1	4	0	5	6	11	0	42	
<b>Available For Prosecution</b>	23	64	5	27	84	11	18	41	7	14	30	35	48	12	144	110	107	27	807	
<b>Less Rejects</b>																				
Camera Malfunction	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Image Missing	0-00%	0-00%	0-00%	4-15%	3-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	9-01%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	2-18%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-02%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Video Skips	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	2-03%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-03%	1-01%	6-06%	0-00%	15-02%
	Plate Unclear	0-00%	1-02%	0-00%	1-04%	0-00%	1-09%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
Process Issues	Too Old	1-04%	3-05%	1-20%	0-00%	6-07%	0-00%	0-00%	3-07%	0-00%	0-00%	1-03%	3-09%	3-06%	0-00%	7-05%	7-06%	7-07%	1-04%	43-05%
<b>Total</b>	1-04%	6-09%	1-20%	5-19%	11-13%	3-27%	2-11%	6-15%	0-00%	2-14%	1-03%	6-17%	3-06%	0-00%	12-08%	8-07%	13-12%	1-04%	81-10%	
<b>Approved Violations</b>	22-96%	58-91%	4-80%	22-81%	73-87%	8-73%	16-89%	35-85%	7-100%	12-86%	29-97%	29-83%	45-94%	12-100%	132-92%	102-93%	94-88%	26-96%	726-90%	
<b>Total Notices Printed</b>	22-96%	58-91%	4-80%	22-81%	73-87%	8-73%	16-89%	35-85%	7-100%	12-86%	29-97%	29-83%	45-94%	12-100%	132-92%	102-93%	94-88%	26-96%	726-90%	

Generated By: MESCOBEDO  
Generated On: 2/7/2020 1:59:47 PM

# Customer Management Report (Ventura) Redlight Incidents

01-Jan-2020 to 31-Jan-2020

Operator Id: %

VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	-------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current