

Customer Management Report (Vista) All Detection Types

01-Jun-2013 to 30-Jun-2013

Operator Id: %

		VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Total Processed Incidents		15	159	162	51	94	33	323	125	42	1004
Less Uncontrollable Factors											
Obstruction	Driver Obstruction/Duckers	2	3	21	3	2	2	0	1	0	34
	Motor Cycle Helmet	0	1	0	0	0	0	0	0	0	1
	Plate Obstruction	0	6	4	6	4	0	5	6	2	33
	Vehicle Obstruction	1	2	7	0	0	1	2	3	1	17
Police Rejects	Emergency Vehicle Responding	3	3	3	3	2	2	0	10	3	29
	Face Obstruction	0	0	1	0	0	0	0	1	0	2
	Incorrect/Incomplete DMV	0	2	0	0	0	0	3	0	0	5
	Multiple vehicles in frame	0	1	0	0	0	0	0	0	0	1
	Police Discretion	1	5	4	1	5	0	12	1	0	29
	Safe Turn On Red	0	7	14	0	8	0	25	0	7	61
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	1	0	0	1
	Sun Glare	0	4	31	3	9	4	12	4	7	74
Registration Issues	Out of Country Plate	0	1	0	0	1	0	1	1	0	4
	Paper Plates	0	4	5	1	1	1	7	3	1	23
	Wrong or No DMV	0	0	0	0	1	0	0	0	0	1
Total		7	39	90	17	33	10	68	30	21	315
Sub Total Violations		8	120	72	34	61	23	255	95	21	689
Less in Progress		0	0	0	0	0	0	0	0	0	0
Available For Prosecution		8	120	72	34	61	23	255	95	21	689
Less Rejects											
Camera Malfunction	Face Camera Focus Blurry	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-00%	0-00%	2-10%	4-01%
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	25-10%	0-00%	0-00%	25-04%

Generated By: JBURNETTE

Generated On: 7/29/2013 1:36:28 PM

Customer Management Report (Vista) All Detection Types

01-Jun-2013 to 30-Jun-2013

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Misc Camera Issue	2-25%	2-02%	0-00%	1-03%	0-00%	0-00%	2-01%	2-02%	1-05%	10-01%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-01%	0-00%	2-00%
Plate Not in Frame	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	2-03%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Police Rejects Driver Unidentifiable images poor	0-00%	2-02%	4-06%	1-03%	0-00%	0-00%	0-00%	1-01%	0-00%	8-01%
Total	3-38%	4-03%	6-08%	4-12%	2-03%	0-00%	28-11%	5-05%	3-14%	55-08%
Approved Violations	5-62%	116-97%	66-92%	30-88%	59-97%	23-100%	227-89%	90-95%	18-86%	634-92%
Total Notices Printed	5-62%	116-97%	66-92%	30-88%	59-97%	23-100%	227-89%	90-95%	18-86%	634-92%

Generated By: JBURNETTE

Generated On: 7/29/2013 1:36:28 PM

Customer Management Report (Vista) All Detection Types

01-Jul-2013 to 31-Jul-2013

Operator Id: %

		VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Total Processed Incidents		16	163	90	59	90	9	270	103	31	831
Less Uncontrollable Factors											
Obstruction	Driver Obstruction/Duckers	2	1	13	5	4	0	3	1	1	30
	Plate Obstruction	0	4	1	2	2	0	2	5	0	16
	Vehicle Obstruction	1	2	2	0	1	0	0	1	0	7
Police Rejects	Emergency Vehicle Responding	1	0	2	3	5	1	0	11	1	24
	Face Obstruction	0	0	1	0	1	0	0	0	0	2
	Incorrect/Incomplete DMV	0	0	0	0	0	0	1	0	0	1
	Police Discretion	0	11	9	1	2	0	16	1	1	41
	Safe Turn On Red	0	5	4	1	12	0	14	0	5	41
	Sun Glare	0	0	0	0	0	0	1	0	0	1
	Policy/Weather	Extended Vehicle	0	0	0	2	1	0	2	0	0
	Sun Glare	2	11	13	9	12	2	9	7	4	69
Registration Issues	Out of Country Plate	0	0	0	0	0	0	1	0	0	1
	Paper Plates	1	4	1	1	2	0	5	2	1	17
Total		7	38	46	24	42	3	54	28	13	255
Sub Total Violations		9	125	44	35	48	6	216	75	18	576
Less in Progress		0	0	0	0	0	0	0	0	0	0
Available For Prosecution		9	125	44	35	48	6	216	75	18	576
Less Rejects											
Camera Malfunction	Face Camera Flash	0-00%	0-00%	1-02%	0-00%	2-04%	0-00%	0-00%	0-00%	0-00%	3-01%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	0-00%	0-00%	3-01%
	Misc Camera Issue	0-00%	1-01%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	2-00%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	2-00%

Generated By: JBURNETTE

Generated On: 8/13/2013 4:56:14 PM

Customer Management Report (Vista) All Detection Types

01-Jul-2013 to 31-Jul-2013

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-01%	0-00%	2-00%
Rear Plate Camera Blurry	0-00%	2-02%	1-02%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Rear Plate Flash Inappropriate	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	3-04%	0-00%	4-01%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects Driver Unidentifiable images poor	0-00%	4-03%	2-05%	0-00%	1-02%	0-00%	1-00%	0-00%	0-00%	8-01%
Total	0-00%	8-06%	4-09%	1-03%	7-15%	0-00%	4-02%	6-08%	0-00%	30-05%
Approved Violations	9-100%	117-94%	40-91%	34-97%	41-85%	6-100%	212-98%	69-92%	18-100%	546-95%
Total Notices Printed	9-100%	117-94%	40-91%	34-97%	41-85%	6-100%	212-98%	69-92%	18-100%	546-95%

Generated By: JBURNETTE

Generated On: 8/13/2013 4:56:14 PM

Customer Management Report (Vista) All Detection Types

01-Aug-2013 to 31-Aug-2013

Operator Id: %

		VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Total Processed Incidents		13	120	122	64	97	30	353	88	43	930
Less Uncontrollable Factors											
Obstruction	Driver Obstruction/Duckers	1	3	11	1	5	1	3	1	2	28
	Motor Cycle Helmet	0	0	0	0	1	0	0	0	0	1
	Plate Obstruction	1	2	7	5	4	1	7	3	0	30
	Vehicle Obstruction	0	1	4	1	0	1	4	1	0	12
Police Rejects	Emergency Vehicle Responding	1	0	0	3	3	3	1	22	1	34
	Face Obstruction	0	0	0	0	0	0	0	1	0	1
	Incorrect/Incomplete DMV	0	0	2	0	1	0	2	0	0	5
	Police Discretion	0	9	2	1	3	0	20	0	2	37
	Safe Turn On Red	0	3	10	0	12	0	32	0	9	66
Policy/Weather	Extended Vehicle	0	1	0	1	0	0	8	0	0	10
	Sun Glare	1	3	21	4	13	6	13	3	7	71
Registration Issues	Out of Country Plate	0	0	0	0	0	0	1	0	0	1
	Paper Plates	0	4	1	6	4	1	8	4	2	30
	Wrong or No DMV	0	1	0	0	0	0	0	0	0	1
Total		4	27	58	22	46	13	99	35	23	327
Sub Total Violations		9	93	64	42	51	17	254	53	20	603
Less in Progress		0	0	0	0	0	0	0	0	0	0
Available For Prosecution		9	93	64	42	51	17	254	53	20	603
Less Rejects											
Camera Malfunction	Face Camera Flash	0-00%	1-01%	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	2-10%	5-01%
	Face Camera Focus Blurry	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-15%	3-00%

Generated By: JBURNETTE

Generated On: 1/31/2014 8:07:44 AM

Customer Management Report (Vista) All Detection Types

01-Aug-2013 to 31-Aug-2013

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Misc Camera Issue	0-00%	0-00%	0-00%	1-02%	0-00%	1-06%	0-00%	0-00%	0-00%	2-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	2-04%	0-00%	3-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	2-02%	3-05%	1-02%	0-00%	0-00%	1-00%	0-00%	0-00%	7-01%
Rear Plate Flash Inappropriate	0-00%	1-01%	0-00%	0-00%	1-02%	0-00%	0-00%	2-04%	0-00%	4-01%
Police Rejects Driver Unidentifiable images poor	2-22%	2-02%	0-00%	2-05%	1-02%	0-00%	3-01%	0-00%	1-05%	11-02%
Total	2-22%	6-06%	4-06%	4-10%	5-10%	1-06%	5-02%	4-08%	7-35%	38-06%
Approved Violations	7-78%	87-94%	60-94%	38-90%	46-90%	16-94%	249-98%	49-92%	13-65%	565-94%
Total Notices Printed	7-78%	87-94%	60-94%	38-90%	46-90%	16-94%	249-98%	49-92%	13-65%	565-94%

Generated By: JBURNETTE

Generated On: 1/31/2014 8:07:44 AM

Customer Management Report (Vista) All Detection Types

01-Sep-2013 to 30-Sep-2013

Operator Id: %

		VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Total Processed Incidents		22	27	120	65	104	41	354	79	52	864
Less Uncontrollable Factors											
Obstruction	Driver Obstruction/Duckers	1	0	10	3	2	0	3	1	4	24
	Plate Obstruction	0	0	6	2	1	1	10	5	0	25
	Vehicle Obstruction	2	0	9	0	5	6	5	2	2	31
Police Rejects	Emergency Vehicle Responding	4	0	2	3	4	0	1	11	1	26
	Incorrect/Incomplete DMV	0	0	1	2	0	0	3	0	1	7
	Police Discretion	0	2	6	2	2	0	26	0	5	43
	Safe Turn On Red	0	11	7	1	5	0	24	0	10	58
Policy/Weather	Sun Glare	0	0	0	0	1	0	0	0	1	2
	Extended Vehicle	0	0	0	0	1	0	4	2	0	7
	Sun Glare	0	0	16	6	19	6	7	4	2	60
Registration Issues	Weather/Nature	0	0	0	0	0	0	0	1	0	1
	Out of Country Plate	0	0	0	0	0	0	1	0	0	1
	Paper Plates	0	0	2	1	5	0	8	3	2	21
Total	Wrong or No DMV	0	0	0	1	0	0	0	0	0	1
		7	13	59	21	45	13	92	29	28	307
Sub Total Violations		15	14	61	44	59	28	262	50	24	557
Less in Progress		0	0	0	0	0	0	0	0	0	0
Available For Prosecution		15	14	61	44	59	28	262	50	24	557
Less Rejects											
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-04%	2-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	3-05%	0-00%	0-00%	0-00%	1-04%	4-01%
	Image Missing	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	2-00%
	Misc Camera Issue	0-00%	1-07%	4-07%	0-00%	2-03%	0-00%	2-01%	0-00%	0-00%	9-02%

Generated By: JBURNETTE

Generated On: 1/31/2014 8:11:40 AM

Customer Management Report (Vista) All Detection Types

01-Sep-2013 to 30-Sep-2013

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-04%	2-00%
Plate Not in Frame	2-13%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	2-04%	0-00%	6-01%
Rear Plate Camera Blurry	1-07%	0-00%	0-00%	2-05%	0-00%	0-00%	1-00%	0-00%	0-00%	4-01%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	2-04%	0-00%	3-01%
Police Rejects Process Issues										
Driver Unidentifiable images poor	0-00%	0-00%	4-07%	0-00%	1-02%	0-00%	0-00%	0-00%	2-08%	7-01%
Too Old	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	2-00%
Total	3-20%	1-07%	10-16%	2-05%	9-15%	0-00%	5-02%	6-12%	5-21%	41-07%
Approved Violations	12-80%	13-93%	51-84%	42-95%	50-85%	28-100%	257-98%	44-88%	19-79%	516-93%
Total Notices Printed	12-80%	13-93%	51-84%	42-95%	50-85%	28-100%	257-98%	44-88%	19-79%	516-93%

Generated By: JBURNETTE

Generated On: 1/31/2014 8:11:40 AM

Customer Management Report (Vista) All Detection Types

01-Oct-2013 to 31-Oct-2013

Operator Id: %

		VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Total Processed Incidents		22	179	82	75	81	26	389	93	62	1009
Less Uncontrollable Factors											
Obstruction	Driver Obstruction/Duckers	2	3	13	2	2	1	3	0	1	27
	Plate Obstruction	1	3	4	0	1	0	3	4	1	17
	Vehicle Obstruction	0	0	5	1	4	5	3	2	1	21
Police Rejects	Emergency Vehicle Responding	3	3	0	3	0	1	0	8	4	22
	Face Obstruction	0	0	0	1	0	0	0	0	0	1
	Funeral Procession/Police	0	0	0	0	0	0	0	0	1	1
	Incorrect/Incomplete DMV	0	1	0	1	0	0	0	0	0	2
	Police Discretion	0	9	5	1	1	1	19	0	2	38
	Safe Turn On Red	0	17	6	1	11	0	43	0	13	91
	Yielding to an Emergency	0	0	0	1	0	0	0	0	0	1
Policy/Weather	Extended Vehicle	1	1	0	0	1	0	2	0	1	6
	Sun Glare	1	3	6	9	12	4	3	2	3	43
	Weather/Nature	0	0	0	0	0	0	1	2	0	3
Registration Issues	Out of Country Plate	0	0	0	0	0	0	1	0	1	2
	Paper Plates	0	3	4	5	5	0	15	1	1	34
Total		8	43	43	25	37	12	93	19	29	309
Sub Total Violations		14	136	39	50	44	14	296	74	33	700
Less in Progress		0	0	0	0	0	0	0	0	0	0
Available For Prosecution		14	136	39	50	44	14	296	74	33	700
Less Rejects											
Camera Malfunction	Face Camera Flash	0-00%	0-00%	1-03%	0-00%	1-02%	0-00%	1-00%	0-00%	0-00%	3-00%
	Face Camera Focus Blurry	0-00%	1-01%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: JBURNETTE

Generated On: 1/31/2014 8:12:28 AM

Customer Management Report (Vista) All Detection Types

01-Oct-2013 to 31-Oct-2013

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Misc Camera Issue	0-00%	2-01%	1-03%	0-00%	0-00%	0-00%	1-00%	1-01%	1-03%	6-01%
Plate Not in Frame	1-07%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-01%	0-00%	3-00%
Rear Plate Camera Blurry	0-00%	3-02%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	1-01%	0-00%	2-00%
Police Rejects Process Issues										
Driver Unidentifiable images poor	0-00%	1-01%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Too Old	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	1-07%	8-06%	4-10%	2-04%	2-05%	0-00%	3-01%	3-04%	1-03%	24-03%
Approved Violations	13-93%	128-94%	35-90%	48-96%	42-95%	14-100%	293-99%	71-96%	32-97%	676-97%
Total Notices Printed	13-93%	128-94%	35-90%	48-96%	42-95%	14-100%	293-99%	71-96%	32-97%	676-97%

Generated By: JBURNETTE

Generated On: 1/31/2014 8:12:28 AM

Customer Management Report (Vista) All Detection Types

01-Nov-2013 to 30-Nov-2013

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL	
Total Processed Incidents	14	130	60	65	75	17	304	85	50	800	
Less Uncontrollable Factors											
Obstruction	Driver Obstruction/Duckers	1	3	9	2	5	2	2	1	1	26
	Plate Obstruction	0	4	1	2	1	1	6	0	0	15
	Vehicle Obstruction	2	1	1	0	2	0	2	1	1	10
Police Rejects	Emergency Vehicle Responding	3	1	1	0	3	2	0	7	3	20
	Face Obstruction	0	0	0	1	0	0	0	0	0	1
	Incorrect/Incomplete DMV	0	1	0	1	0	0	2	0	0	4
	Police Discretion	1	5	6	2	2	0	16	1	2	35
	Safe Turn On Red	0	2	8	1	6	0	30	0	10	57
	Sun Glare	0	0	0	0	0	0	0	0	1	1
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	3	0	0	3
	Sun Glare	1	2	5	7	8	1	9	2	1	36
	Yellow with Red Light	0	0	0	0	3	0	0	0	0	3
Registration Issues	Out of Country Plate	0	0	0	0	0	0	1	0	0	1
	Paper Plates	0	1	1	1	0	2	7	2	3	17
	Wrong or No DMV	0	0	0	0	1	0	0	0	0	1
Total		8	20	32	17	31	8	78	14	22	230
Sub Total Violations		6	110	28	48	44	9	226	71	28	570
Less in Progress		0	0	0	0	0	0	0	0	0	0
Available For Prosecution		6	110	28	48	44	9	226	71	28	570
Less Rejects											
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-00%
	Face Camera Focus Blurry	0-00%	1-01%	1-04%	0-00%	0-00%	0-00%	0-00%	1-01%	1-04%	4-01%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	3-07%	0-00%	0-00%	1-01%	1-04%	5-01%
	Image Missing	0-00%	13-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	13-02%
	Misc Camera Issue	0-00%	6-05%	3-11%	0-00%	0-00%	0-00%	1-00%	0-00%	1-04%	11-02%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-04%	2-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	1-02%	1-02%	0-00%	0-00%	1-01%	0-00%	3-01%
	Rear Plate Camera Blurry	0-00%	2-02%	1-04%	1-02%	0-00%	0-00%	2-01%	4-06%	1-04%	11-02%
	Rear Plate Flash Inappropriate	0-00%	1-01%	0-00%	1-02%	0-00%	0-00%	2-01%	1-01%	0-00%	5-01%
Police Rejects Process Issues	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Too Old	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total		0-00%	23-21%	6-21%	4-08%	4-09%	0-00%	6-03%	8-11%	6-21%	57-10%
Approved Violations		6-100%	87-79%	22-79%	44-92%	40-91%	9-100%	220-97%	63-89%	22-79%	513-90%

Generated By: JBURNETTE

Generated On: 12/13/2013 3:26:39 PM

Customer Management Report (Vista) All Detection Types

01-Nov-2013 to 30-Nov-2013

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Total Notices Printed	6-100%	87-79%	22-79%	44-92%	40-91%	9-100%	220-97%	63-89%	22-79%	513-90%

Generated By: JBURNETTE

Generated On: 12/13/2013 3:26:39 PM

Customer Management Report (Vista) All Detection Types

01-Dec-2013 to 31-Dec-2013

Operator Id: %

		VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Total Processed Incidents		16	178	105	35	38	19	290	110	63	854
Less Uncontrollable Factors											
Obstruction	Driver Obstruction/Duckers	1	6	31	3	2	1	12	0	2	58
	Plate Obstruction	0	15	1	0	0	0	6	2	0	24
	Vehicle Obstruction	1	1	3	1	0	1	4	2	2	15
Police Rejects	Emergency Vehicle Responding	1	0	0	2	0	1	1	22	0	27
	Face Obstruction	1	0	0	0	0	0	0	0	0	1
	Incorrect/Incomplete DMV	0	0	0	0	0	0	2	1	0	3
	Police Discretion	0	8	5	1	3	2	16	1	3	39
	Safe Turn On Red	0	10	7	0	3	0	31	0	8	59
	Yielding to an Emergency	0	0	0	0	0	0	0	1	0	1
	Policy/Weather	Extended Vehicle	0	0	0	1	0	0	2	1	0
	Sun Glare	0	2	3	3	0	0	0	1	0	9
Registration Issues	Out of Country Plate	0	0	1	0	0	0	3	1	0	5
	Paper Plates	0	10	2	1	1	0	9	2	6	31
	Wrong or No DMV	0	0	1	0	0	0	0	0	0	1
Total		4	52	54	12	9	5	86	34	21	277
Sub Total Violations		12	126	51	23	29	14	204	76	42	577
Less in Progress		0	0	0	0	0	0	0	0	0	0
Available For Prosecution		12	126	51	23	29	14	204	76	42	577
Less Rejects											
Camera Malfunction	Face Camera Focus Blurry	2-17%	2-02%	4-08%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	9-02%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	4-14%	0-00%	1-00%	0-00%	0-00%	5-01%
	Misc Camera Issue	0-00%	1-01%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	2-00%
	Plate Burn Out	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: JBURNETTE

Generated On: 1/31/2014 8:13:04 AM

Customer Management Report (Vista) All Detection Types

01-Dec-2013 to 31-Dec-2013

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	0-00%	1-02%	4-01%
Rear Plate Camera Blurry	0-00%	4-03%	2-04%	1-04%	0-00%	0-00%	1-00%	0-00%	0-00%	8-01%
Rear Plate Flash Inappropriate	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	3-01%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects Process Issues										
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Total	2-17%	10-08%	6-12%	1-04%	6-21%	0-00%	6-03%	3-04%	1-02%	35-06%
Approved Violations	10-83%	116-92%	45-88%	22-96%	23-79%	14-100%	198-97%	73-96%	41-98%	542-94%
Total Notices Printed	10-83%	116-92%	45-88%	22-96%	23-79%	14-100%	198-97%	73-96%	41-98%	542-94%

Generated By: JBURNETTE

Generated On: 1/31/2014 8:13:04 AM

Customer Management Report (Vista) All Detection Types

01-Jan-2014 to 31-Jan-2014

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL	
Total Processed Incidents	17	160	135	53	52	20	285	106	59	887	
Less Uncontrollable Factors											
Obstruction	Driver Obstruction/Duckers	10	6	37	8	8	2	4	8	9	92
	Motor Cycle Helmet	0	1	0	0	0	0	0	0	0	1
	Plate Obstruction	0	7	8	2	0	1	12	3	0	33
	Signal Obstruction	0	7	0	0	0	0	0	0	0	7
	Vehicle Obstruction	0	2	5	2	1	0	6	1	1	18
Police Rejects	Emergency Vehicle Responding	0	1	1	0	3	1	3	9	6	24
	Face Obstruction	0	0	0	0	0	0	1	0	0	1
	Incorrect/Incomplete DMV	1	0	0	0	0	0	1	1	0	3
	Police Discretion	0	8	7	2	0	1	16	1	5	40
	Safe Turn On Red	0	8	10	1	1	0	14	0	8	42
Policy/Weather	Extended Vehicle	0	1	0	1	0	0	4	1	0	7
	Sun Glare	0	1	4	1	0	0	4	3	2	15
Registration Issues	Paper Plates	0	5	3	2	3	1	6	3	1	24
	Wrong or No DMV	0	0	0	0	0	0	1	0	0	1
Total		11	47	75	19	16	6	72	30	32	308
Sub Total Violations		6	113	60	34	36	14	213	76	27	579
Less in Progress		0	14	3	3	2	0	18	4	0	44
Available For Prosecution		6	99	57	31	34	14	195	72	27	535
Less Rejects											
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-04%	0-00%	0-00%	7-01%
	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-00%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-04%	2-00%
	Misc Camera Issue	1-17%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	4-01%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	2-03%	0-00%	3-01%
	Plate Not in Frame	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	2-00%
	Rear Plate Camera Blurry	0-00%	3-03%	1-02%	0-00%	0-00%	0-00%	1-01%	2-03%	0-00%	7-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	1-02%	1-03%	0-00%	0-00%	5-03%	2-03%	0-00%	9-02%
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
	Red-light not visible in	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total		1-17%	7-07%	2-04%	1-03%	2-06%	0-00%	15-08%	8-11%	3-11%	39-07%
Approved Violations		5-83%	92-93%	55-96%	30-97%	32-94%	14-100%	180-92%	64-89%	24-89%	496-93%
Total Notices Printed		5-83%	91-92%	55-96%	30-97%	32-94%	14-100%	176-90%	64-89%	24-89%	491-92%

Generated By: JBURNETTE

Generated On: 2/3/2014 9:22:04 AM

Customer Management Report (Vista) All Detection Types

01-Jan-2014 to 31-Jan-2014

Operator Id: %

TOTAL	VST-VWEM-01	VST-VISA-01	VST-SYSH-01	VST-SAVI-01	VST-SACC-01	VST-MEHA-01	VST-HAME-01	VST-EMVW-01	VST-CCSA-01

Generated By: JBURNETTE

Generated On: 2/3/2014 9:22:04 AM