

Customer Management Report (Baldwin Park) Redlight Incidents *Rec'd 2-8-12 by USPS/diak*

01-Jul-2006 to 31-Jul-2006 Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	0	71	0	537	51	236	242	1123	31	2291
Less Uncontrollable Factors										
Obstruction	0	7	0	54	3	32	22	36	8	162
Plate Obstruction	0	1	0	14	1	1	4	4	1	26
Vehicle Obstruction	0	2	0	25	1	3	1	5	0	37
Police Rejects	0	10	0	6	2	9	6	6	2	41
Emergency Vehicle Responding	0	6	0	25	3	13	8	49	0	104
Incorrect/Incomplete DMV	0	0	0	1	0	0	0	0	0	1
Invalid Offense	0	0	0	1	0	1	0	11	0	13
Safe Turn On Red	0	0	0	1	0	0	2	2	0	5
Policy/Weather	0	0	0	1	0	0	65	200	1	388
Extended Vehicle	0	0	0	75	4	43	65	200	1	388
Sun Glare	0	0	0	1	0	0	2	0	0	3
Can Not Identify State	0	0	0	3	0	0	0	1	1	5
Out of Country Plate	0	1	0	17	0	9	8	27	3	65
Paper Plates	0	0	0	2	0	1	4	2	0	9
Wrong or No DMV	0	27	0	225	14	112	122	343	16	859
Total	0	44	0	312	37	124	120	780	15	1432
Sub Total Violations	0	0	0	0	0	0	0	0	0	0
Less in Progress	0	44	0	312	37	124	120	780	15	1432
Available For Prosecution	0	0	0	0	0	0	0	0	0	0
Less Rejects	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	100-13%	0-00%	100-07%
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%	0-00%	5-00%
Face Camera Flash	0-00%	0-00%	0-00%	2-01%	0-00%	3-02%	0-00%	6-01%	0-00%	11-01%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	15-02%	0-00%	16-01%
Face Camera No Flash	0-00%	1-02%	0-00%	4-01%	0-00%	0-00%	0-00%	0-00%	1-07%	6-00%
Face Not in Frame										

Generated By: JHENDRICKS
Generated On: 1/25/2012 3:55:41 PM

Customer Management Report (Baldwin Park) Redlight Incidents

01-Jul-2006 to 31-Jul-2006

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	4-01%	1-07%	6-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	2-01%	0-00%	3-02%	0-00%	11-01%	0-00%	16-01%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	3-01%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	2-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	74-09%	0-00%	75-05%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-00%	0-00%	2-00%
No Video	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	2-13%	3-00%
Vehicle On or Passed Stop Line	0-00%	0-00%	0-00%	4-01%	0-00%	4-03%	1-01%	28-04%	0-00%	37-03%
Too Old	0-00%	0-00%	0-00%	4-01%	1-03%	2-02%	1-01%	1-00%	0-00%	9-01%
Process Issues	0-00%	1-02%	0-00%	22-07%	2-05%	13-10%	4-03%	249-32%	4-27%	295-21%
Total	0-00%	43-98%	0-00%	290-93%	35-95%	111-90%	116-97%	531-68%	11-73%	1137-79%
Approved Violations	0-00%	43-98%	0-00%	290-93%	35-95%	111-90%	116-97%	531-68%	11-73%	1137-79%
Total Notices Printed	0-00%	43-98%	0-00%	290-93%	35-95%	111-90%	116-97%	531-68%	11-73%	1137-79%

Generated By: JHENDRICKS
Generated On: 1/25/2012 3:55:41 PM

Customer Management Report (Baldwin Park) Redlight Incidents

01-Nov-2006 to 30-Nov-2006

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	0	51	0	310	45	175	147	962	21	1711
Less Uncontrollable Factors										
Obstruction	0	9	0	17	6	24	18	31	4	109
Plate Obstruction	0	1	0	9	0	5	6	11	6	38
Vehicle Obstruction	0	0	0	6	1	1	5	3	0	16
Police Rejects	0	8	0	6	4	23	2	6	0	49
Emergency Vehicle Responding	0	3	0	14	2	4	6	48	0	77
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	1	1
Police Discretion	0	0	0	0	0	1	1	28	0	30
Safe Turn On Red	0	0	0	0	0	0	0	0	0	0
Policy/Weather	0	0	0	1	0	0	0	0	0	1
Extended Vehicle	0	0	0	54	3	14	23	34	0	128
Sun Glare	0	0	0	2	0	3	0	9	1	15
Weather/Nature	0	0	0	0	0	1	0	0	0	1
Yellow with Red Light	0	0	0	4	1	0	0	1	0	6
Registration Issues	0	0	0	0	0	0	0	3	0	3
Can Not Identify State	0	2	0	14	1	5	5	53	1	81
Out of Country Plate	0	0	0	2	0	0	0	4	0	6
Paper Plates	0	23	0	129	18	81	66	231	13	561
Wrong or No DMV	0	28	0	181	27	94	81	731	8	1150
Sub Total Violations	0	28	0	181	27	94	81	731	8	1150
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	0	28	0	181	27	94	81	731	8	1150
Less Rejects										
Camera Malfunction	0-00%	0-00%	0-00%	3-02%	0-00%	0-00%	1-01%	3-00%	0-00%	7-01%
Face Camera Flash	0-00%	0-00%	0-00%	10-06%	0-00%	2-02%	6-07%	4-01%	0-00%	22-02%
Face Camera Focus Blurry	0-00%	1-04%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	2-00%
Face Not in Frame										

Generated By: JHENDRICKS

Generated On: 1/25/2012 3:57:31 PM

Customer Management Report (Baldwin Park) Redlight Incidents

Operator Id: %

01-Nov-2006 to 30-Nov-2006

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Image Missing	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	6-07%	0-00%	0-00%	7-01%
Misc Camera Issue	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	15-19%	14-02%	0-00%	31-03%
Plate Not in Frame	0-00%	0-00%	0-00%	6-03%	0-00%	0-00%	0-00%	1-00%	0-00%	7-01%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	2-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%
Police Rejects	0-00%	3-11%	0-00%	11-06%	1-04%	4-04%	4-05%	67-09%	0-00%	90-08%
Process Issues	0-00%	4-14%	0-00%	36-20%	2-07%	6-06%	32-40%	92-13%	0-00%	172-15%
Total	0-00%	24-86%	0-00%	145-80%	25-93%	88-94%	49-60%	639-87%	8-100%	978-85%
Approved Violations	0-00%	24-86%	0-00%	145-80%	25-93%	88-94%	49-60%	639-87%	8-100%	978-85%
Total Notices Printed	0-00%	24-86%	0-00%	145-80%	25-93%	88-94%	49-60%	639-87%	8-100%	978-85%

Customer Management Report (Baldwin Park) All Detection Types

01-Jan-2007 to 31-Jan-2007 Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	0	42	0	216	36	167	191	898	25	1575
Less Uncontrollable Factors										
Obstruction	0	4	0	6	18	11	18	4	67	
Driver Obstruction/Duckers	0	0	0	0	0	0	0	1	0	1
Motor Cycle Helmet	0	0	0	9	1	7	6	5	1	29
Plate Obstruction	0	0	0	6	0	1	4	0	0	11
Vehicle Obstruction	0	6	0	1	3	9	7	7	1	34
Emergency Vehicle Responding	0	2	0	21	3	12	10	115	2	165
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	2	0	2
Multiple vehicles in frame	0	0	0	1	0	0	0	1	0	2
Police Discretion	0	0	0	1	0	0	0	1	0	2
Safe Turn On Red	0	0	0	0	0	1	2	35	1	39
Policy/Weather	0	2	0	1	1	1	1	0	0	6
Extended Vehicle	0	0	0	24	1	5	18	14	0	62
Sun Glare	0	1	0	2	0	0	1	5	0	9
Weather/Nature	0	0	0	0	0	1	3	0	0	4
Yellow with Red Light	0	0	0	1	0	0	0	0	0	1
Can Not Identify State	0	0	0	2	0	0	0	8	0	10
Out of Country Plate	0	2	0	11	1	11	10	45	3	83
Paper Plates	0	0	0	1	0	0	1	2	0	4
Wrong or No DMV	0	17	0	86	16	66	74	258	12	529
Sub Total Violations	0	25	0	130	20	101	117	640	13	1046
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	0	25	0	130	20	101	117	640	13	1046
Less Rejects										
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	3-03%	0-00%	0-00%	0-00%	3-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
Face Camera No Flash	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
Image Missing	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	3-00%	1-08%	6-01%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	3-03%	0-00%	0-00%	0-00%	3-00%
Plate Burn Out	0-00%	1-04%	0-00%	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	3-00%
Plate Not in Frame	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%	0-00%	2-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	1-01%	0-00%	1-01%	0-00%	0-00%	0-00%	2-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-08%	2-00%

Customer Management Report (Baldwin Park) All Detection Types

01-Jan-2007 to 31-Jan-2007

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Police Rejects	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	3-00%	0-00%	4-00%
Process Issues	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	3-02%	1-05%	2-02%	4-03%	17-03%	0-00%	28-03%
Plate Unclear	0-00%	1-04%	0-00%	6-05%	2-10%	13-13%	9-08%	24-04%	2-15%	59-06%
Too Old	0-00%	3-12%	0-00%	124-95%	18-90%	88-57%	108-52%	516-96%	11-85%	987-94%
Total	0-00%	22-88%	0-00%	124-95%	18-90%	88-57%	108-52%	516-96%	11-85%	987-94%
Approved Violations	0-00%	22-88%	0-00%	124-95%	18-90%	88-57%	108-52%	516-96%	11-85%	987-94%
Total Notices Printed	0-00%	22-88%	0-00%	124-95%	18-90%	88-57%	108-52%	516-96%	11-85%	987-94%

Customer Management Report (Baldwin Park) All Detection Types

01-Jul-2007 to 30-Jul-2007

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	0	34	0	538	51	35	240	1010	31	1939
Less Uncontrollable Factors										
Obstruction	0	2	0	47	9	6	41	44	5	154
Driver Obstruction/Duckers	0	0	0	3	0	0	0	1	0	4
Motor Cycle Helmet	0	0	0	9	1	0	10	5	1	26
Plate Obstruction	0	0	0	8	1	1	8	5	1	24
Vehicle Obstruction	0	1	0	5	3	3	5	6	4	27
Emergency Vehicle Responding	0	9	0	78	6	5	22	189	2	311
Incorrect/Incomplete DMV	0	0	0	9	0	0	5	20	0	34
Safe Turn On Red	0	0	0	3	0	0	3	0	1	7
Extended Vehicle	0	4	0	95	1	2	92	117	0	311
Sun Glare	0	0	0	2	0	0	1	2	0	5
Weather/Nature	0	0	0	3	1	0	0	0	0	4
Yellow with Red Light	0	0	0	0	0	0	0	0	0	0
Can Not Identify State	0	0	0	0	0	0	0	0	0	0
Out of Country Plate	0	3	0	26	1	2	8	36	0	76
Paper Plates	0	0	0	3	0	0	0	0	0	3
Wrong or No DMV	0	19	0	294	23	19	195	426	14	990
Sub Total Violations	0	15	0	244	28	16	45	584	17	949
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	0	15	0	244	28	16	45	584	17	949
Less Rejects										
Camera Malfunction	0-00%	0-00%	0-00%	1-00%	0-00%	1-06%	0-00%	0-00%	0-00%	2-00%
Face Camera Flash	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	1-00%	0-00%	2-00%
Face Not in Frame	0-00%	0-00%	0-00%	12-05%	0-00%	0-00%	0-00%	1-00%	0-00%	13-01%
Image Missing	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	2-04%	154-26%	1-06%	159-17%
Misc Camera Issue	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-01%	0-00%	7-01%
Police Rejects										
Total	0-00%	0-00%	0-00%	18-07%	0-00%	2-12%	2-04%	163-28%	1-06%	186-20%
Approved Violations	0-00%	15-100%	0-00%	226-93%	28-100%	14-88%	43-96%	421-72%	16-94%	763-80%
Total Notices Printed	0-00%	15-100%	0-00%	226-93%	28-100%	14-88%	43-96%	421-72%	16-94%	763-80%

Customer Management Report (Baldwin Park) All Detection Types

01-Jul-2007 to 30-Jul-2007

Operator Id: %

TOTAL
BAL-RAFR-03
BAL-RAFR-01
BAL-RABA-03
BAL-RABA-01
BAL-PUPA-01
BAL-PUME-01
BAL-PUDA-01
BAL-FRPU-01
BAL-DAPU-01

Customer Management Report (Baldwin Park) All Detection Types

01-Jan-2008 to 31-Jan-2008

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	0	32	0	338	25	94	132	847	10	1478
Less Uncontrollable Factors										
Obstruction	0	0	0	19	2	17	20	12	1	71
Driver Obstruction/Duckers	0	0	0	2	0	0	1	2	0	5
Motor Cycle Helmet	0	0	0	8	1	7	11	7	0	34
Plate Obstruction	0	0	0	13	1	1	3	7	1	26
Vehicle Obstruction	0	6	0	7	5	12	10	6	2	48
Emergency Vehicle Responding	0	1	0	50	2	12	14	153	0	232
Incorrect/Incomplete DMV	0	0	0	6	0	1	7	44	0	58
Safe Turn On Red	0	0	0	3	1	0	2	2	0	8
Policy/Weather	0	0	0	16	0	1	6	11	0	34
Extended Vehicle	0	0	0	0	0	1	0	0	0	1
Sun Glare	0	0	0	1	0	0	0	0	0	1
Weather/Nature	0	0	0	1	0	0	0	0	0	1
Yellow with Red Light	0	1	0	0	0	0	0	0	1	2
Registration	0	1	0	0	0	0	1	1	1	4
Can Not Identify State	0	0	0	2	1	0	1	1	0	5
Issues	0	1	0	16	2	5	4	58	0	86
Out of Country Plate	0	0	0	0	0	0	0	3	0	3
Paper Plates	0	9	0	143	15	57	80	307	6	617
Wrong or No DMV	0	23	0	195	10	37	52	540	4	861
Sub Total Violations	0	0	0	0	0	0	0	0	0	0
Less in Progress	0	23	0	195	10	37	52	540	4	861
Available For Prosecution	0	23	0	195	10	37	52	540	4	861
Less Rejects										
Camera	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	8-01%	0-00%	8-01%
Misc Camera Issue	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	0-00%	3-00%
Rear Plate Camera Blurry										
Rear Plate No Flash										

Generated By: JHENDRICKS
Generated On: 2/1/2012 9:27:31 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Jan-2008 to 31-Jan-2008 Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-00%	0-00%	2-00%
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
Total	0-00%	0-00%	0-00%	1-01%	0-00%	1-03%	1-02%	12-02%	0-00%	15-02%
Approved Violations	0-00%	23-100%	0-00%	194-99%	10-100%	36-97%	51-98%	528-98%	4-100%	846-98%
Total Notices Printed	0-00%	23-100%	0-00%	194-99%	10-100%	36-97%	51-98%	528-98%	4-100%	846-98%

Customer Management Report (Baldwin Park) All Detection Types

01-Jul-2008 to 31-Jul-2008

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	444	32	69	318	29	85	104	911	17	2009
Less Uncontrollable Factors										
Obstruction	16	1	1	25	3	14	18	19	9	106
Driver Obstruction/Duckers										
Motor Cycle Helmet	1	0	0	2	0	0	4	7	1	15
Plate Obstruction	8	0	1	7	0	10	1	3	0	30
Vehicle Obstruction	3	0	1	10	0	0	1	7	0	22
Police Rejects	2	4	8	7	2	11	4	10	2	50
Emergency Vehicle Responding										
Incorrect/Incomplete DMV	26	3	3	12	1	4	3	73	0	125
Safe Turn On Red	23	0	0	11	0	2	7	131	0	174
Policy/Weather	17	0	0	0	0	0	0	0	0	17
Extended Vehicle										
Sun Glare	43	6	7	83	1	8	24	170	0	342
Weather/Nature	1	0	1	4	1	0	0	6	0	13
Registration Issues	3	0	0	0	0	0	0	0	0	3
Can Not Identify State										
Out of Country Plate	0	0	0	3	0	0	0	4	0	7
Paper Plates	29	0	5	14	0	3	2	29	2	84
Wrong or No DMV	1	0	0	1	0	0	0	1	0	3
Total	173	14	27	179	8	52	64	460	14	991
Sub Total Violations	271	18	42	139	21	33	40	451	3	1018
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	271	18	42	139	21	33	40	451	3	1018
Less Rejects										
Camera Malfunction	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Face Camera Focus Blurry										
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	44-16%	9-50%	0-00%	0-00%	0-00%	2-06%	13-32%	10-02%	0-00%	78-08%
Plate Burn Out	5-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-00%

Generated By: JHENDRICKS

Generated On: 2/1/2012 9:28:31 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Jul-2008 to 31-Jul-2008

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Scene Image Flash Inappropriate	6-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
Scene Image No Flash	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Sun Glare	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	3-00%
Police Rejects	57-21%	9-50%	0-00%	2-01%	0-00%	3-09%	13-32%	12-03%	0-00%	96-09%
Approved Violations	214-79%	9-50%	42-100%	137-99%	21-100%	30-91%	27-68%	439-97%	3-100%	922-91%
Total Notices Printed	214-79%	9-50%	42-100%	137-99%	21-100%	30-91%	27-68%	439-97%	3-100%	922-91%

Customer Management Report (Baldwin Park) All Detection Types

01-Jan-2009 to 31-Jan-2009

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	307	28	46	206	21	96	157	696	14	1571
Less Uncontrollable Factors										
Obstruction	11	1	0	16	4	12	20	7	4	75
Driver Obstruction/Duckers										
Motor Cycle Helmet	1	1	0	0	0	0	0	5	0	7
Plate Obstruction	3	0	0	1	0	19	2	5	0	30
Vehicle Obstruction	1	0	0	2	0	1	4	4	0	12
Emergency Vehicle Responding	4	7	7	5	1	10	4	8	2	48
Police Rejects										
Incorrect/Incomplete DMV	21	2	0	15	1	4	16	46	1	106
Safe Turn On Red	18	0	0	7	0	2	20	113	0	160
Policy/Weather										
Extended Vehicle	14	0	0	1	0	0	0	0	0	15
Sun Glare	3	0	8	24	0	4	5	8	0	52
Weather/Nature	4	0	0	3	0	2	2	9	0	20
Yellow with Red Light	0	0	0	0	0	0	0	1	0	1
Registration Issues										
Out of Country Plate	0	0	1	0	0	0	1	0	0	2
Paper Plates	11	1	3	7	1	1	8	22	0	54
Wrong or No DMV	0	1	0	0	0	0	1	2	0	4
Total	91	13	19	81	7	55	83	230	7	586
Sub Total Violations	216	15	27	125	14	41	74	466	7	985
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	216	15	27	125	14	41	74	466	7	985
Less Rejects										
Camera Malfunction	4-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
Databar Unreadable/Incorrect	0-00%	0-00%	0-00%	1-01%	0-00%	4-10%	0-00%	1-00%	0-00%	6-01%
Face Camera Focus Blurry	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera No Flash	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Not in Frame										

Generated By: JHENDRICKS

Generated On: 2/1/2012 9:29:01 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Jan-2009 to 31-Jan-2009

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Misc Camera Issue	11-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	12-01%
Plate Burn Out	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-14%	4-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-01%	1-00%	0-00%	3-00%
Rear Plate Flash Inappropriate	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-14%	2-00%
Rear Plate No Flash	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Too Old	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	0-00%	4-00%
Process Issues	20-09%	1-07%	0-00%	3-02%	0-00%	4-10%	2-03%	7-02%	2-29%	39-04%
Total	196-91%	14-93%	27-100%	122-98%	14-100%	37-90%	72-97%	459-98%	5-71%	946-96%
Approved Violations	196-91%	14-93%	27-100%	122-98%	14-100%	37-90%	72-97%	459-98%	5-71%	946-96%
Total Notices Printed	196-91%	14-93%	27-100%	122-98%	14-100%	37-90%	72-97%	459-98%	5-71%	946-96%

Customer Management Report (Baldwin Park) All Detection Types

01-Jul-2009 to 31-Jul-2009

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	400	27	68	234	28	118	123	888	17	1903
Less Uncontrollable Factors										
Obstruction	32	3	2	11	3	20	16	37	9	133
Driver Obstruction/Duckers	0	0	0	0	0	0	0	8	0	8
Motor Cycle Helmet	10	0	6	3	2	11	3	10	1	46
Plate Obstruction	0	0	0	0	0	0	2	1	0	3
Signal Obstruction	3	0	0	1	0	2	3	2	0	11
Vehicle Obstruction	3	14	9	6	6	17	17	18	1	91
Emergency Vehicle Responding	0	0	0	1	0	0	0	0	0	1
Incorrect Plate on Vehicle	20	0	2	13	1	4	4	40	2	86
Incorrect/Incomplete DMV	31	0	0	13	0	2	11	126	0	183
Safe Turn On Red	0	0	0	1	0	1	0	0	0	2
Yielding to an Emergency	7	0	1	1	0	0	1	0	0	10
Policy/Weather	30	1	8	41	1	12	29	146	0	268
Extended Vehicle	0	0	0	0	0	1	0	0	0	1
Sun Glare	0	0	0	0	0	0	0	0	0	0
Weather/Nature	0	0	0	0	0	0	0	0	0	0
Registration	0	0	0	0	0	1	0	1	0	2
Out of Country Plate	11	3	3	11	1	2	4	29	0	64
Paper Plates	1	0	0	0	0	0	0	1	0	2
Wrong or No DMV	148	21	31	102	14	73	90	419	13	911
Total	252	6	37	132	14	45	33	469	4	992
Sub Total Violations	0	0	0	0	0	0	0	0	0	0
Less in Progress	252	6	37	132	14	45	33	469	4	992
Available For Prosecution										
Less Rejects										
Camera	0-00%	0-00%	1-03%	0-00%	0-00%	1-02%	0-00%	1-00%	0-00%	3-00%
Face Not in Frame	13-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	13-01%
Malfunction										
Misc Camera Issue										

Generated By: JHENDRICKS
Generated On: 2/1/2012 9:29:37 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Jul-2009 to 31-Jul-2009

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Plate Not in Frame	0-00%	0-00%	0-00%	3-02%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Rear Plate Camera Blurry	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	1-00%	0-00%	3-00%
Scene Image Flash Inappropriate	3-01%	0-00%	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	5-01%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	3-01%	0-00%	4-00%
Police Rejects	7-03%	0-00%	0-00%	2-02%	1-07%	0-00%	1-03%	9-02%	0-00%	20-02%
Process Issues	24-10%	0-00%	1-03%	5-04%	3-21%	3-07%	2-06%	15-03%	0-00%	53-05%
Total	228-90%	6-100%	36-97%	127-96%	11-79%	42-93%	31-94%	454-97%	4-100%	939-95%
Approved Violations	228-90%	6-100%	36-97%	127-96%	11-79%	42-93%	31-94%	454-97%	4-100%	939-95%
Total Notices Printed	228-90%	6-100%	36-97%	127-96%	11-79%	42-93%	31-94%	454-97%	4-100%	939-95%

Generated By: JHENDRICKS
Generated On: 2/1/2012 9:29:37 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Jan-2010 to 31-Jan-2010

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	202	23	42	162	25	72	80	440	15	1061
Less Uncontrollable Factors										
Obstruction	5	2	2	10	0	11	6	5	9	50
Driver Obstruction/Duckers	0	0	0	0	0	0	1	0	0	1
Motor Cycle Helmet	7	0	0	2	2	1	2	0	0	14
Plate Obstruction	1	0	2	4	0	0	1	3	0	11
Vehicle Obstruction	8	6	7	7	5	18	11	10	2	74
Emergency Vehicle Responding	1	0	0	0	0	0	0	0	0	1
Funeral Procession/Police	24	0	2	15	3	5	6	49	1	105
Incorrect/Incomplete DMV	0	0	1	0	0	1	0	2	0	4
Invalid Offense	15	0	0	11	0	4	15	77	0	122
Safe Turn On Red	14	0	0	0	0	0	0	0	0	14
Extended Vehicle	1	0	4	10	0	0	4	6	0	25
Sun Glare	1	1	0	0	1	0	1	1	0	5
Weather/Nature	1	0	1	0	0	0	0	0	0	4
Out of Country Plate	1	0	1	0	0	1	0	1	0	4
Paper Plates	7	1	1	8	1	4	1	13	2	38
Total	85	10	20	57	12	45	48	167	14	468
Sub Total Violations	117	13	22	95	13	27	32	273	1	593
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	117	13	22	95	13	27	32	273	1	593
Less Rejects										
Camera	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Malfunction	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	2-00%
Face Not in Frame	0-00%	2-15%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	2-00%

Generated By: JHENDRICKS

Generated On: 2/1/2012 9:31:51 AM

Customer Management Report (Baldwin Park) All Detection Types

Operator Id: %

01-Jan-2010 to 31-Jan-2010

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Rear Plate No Flash	0-00%	3-23%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Police Rejects	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%
Process Issues	2-02%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	3-01%	0-00%	6-01%
Total	2-02%	5-38%	1-05%	2-02%	2-15%	0-00%	0-00%	7-03%	0-00%	19-03%
Approved Violations	115-98%	8-62%	21-95%	93-98%	11-85%	27-100%	32-100%	266-97%	1-100%	574-97%
Total Notices Printed	115-98%	8-62%	21-95%	93-98%	11-85%	27-100%	32-100%	266-97%	1-100%	574-97%

Customer Management Report (Baldwin Park) All Detection Types

01-Apr-2010 to 30-Apr-2010 Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	223	49	48	206	28	81	112	545	18	1310
Less Uncontrollable Factors										
Obstruction	10	6	1	6	3	16	10	12	6	70
Driver Obstruction/Duckers										
Motor Cycle Helmet	0	0	0	1	0	0	3	0	0	4
Plate Obstruction	7	2	1	3	1	2	2	1	1	20
Vehicle Obstruction	2	2	1	2	1	0	1	3	0	12
Police Rejects										
Citation Issued manually	0	0	0	0	0	0	0	1	0	1
Emergency Vehicle Responding	3	4	5	9	5	12	5	3	2	48
Gender Mismatch	1	0	0	0	0	1	0	5	0	7
Incorrect/Incomplete DMV	3	0	0	1	0	3	3	15	0	25
Invalid Offense	0	0	0	0	0	0	1	3	0	4
On or Passed the Stop Bar (PD).	0	4	1	0	0	1	0	0	0	6
Plate Unidentifiable	0	0	0	0	0	0	0	1	0	1
Police Discretion	13	3	0	6	1	2	16	88	0	129
Safe Turn On Red	8	0	0	2	0	1	3	35	0	49
Policy/Weather										
Extended Vehicle	18	0	0	0	0	0	0	0	0	18
Sun Glare	13	10	2	30	2	11	15	49	0	132
Weather/Nature	0	0	0	1	0	0	1	1	0	3
Registration Issues										
Out of Country Plate	0	0	0	0	0	0	1	1	0	2
Paper Plates	9	2	1	9	1	3	0	17	0	42
Wrong or No DMV	0	0	0	0	0	0	0	1	0	1
Total	87	33	12	70	14	52	61	236	9	574
Sub Total Violations	136	16	36	136	14	29	51	309	9	736
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	136	16	36	136	14	29	51	309	9	736

Generated By: JHENDRICKS
Generated On: 2/1/2012 9:38:46 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Apr-2010 to 30-Apr-2010

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Less Rejects										
Camera Malfunction	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Flash	0-00%	2-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Face Camera Focus Blurry	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera No Flash	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	2-01%	0-00%	4-01%
Face Not in Frame	6-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-02%	0-00%	11-01%
Misc Camera Issue	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Burn Out	0-00%	0-00%	0-00%	5-04%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Plate Not in Frame	4-03%	3-19%	1-03%	4-03%	0-00%	0-00%	5-10%	8-03%	1-11%	26-04%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	3-02%	0-00%	0-00%	3-02%	0-00%	0-00%	3-06%	6-02%	0-00%	15-02%
Sun Glare	29-21%	2-12%	11-31%	34-25%	7-50%	6-21%	20-39%	107-35%	1-11%	217-29%
Too Old	43-32%	9-56%	12-33%	48-35%	7-50%	7-24%	28-55%	128-41%	2-22%	284-39%
Approved Violations	93-68%	7-44%	24-67%	88-65%	7-50%	22-76%	23-45%	181-59%	7-78%	452-61%
Total Notices Printed	93-68%	7-44%	24-67%	88-65%	7-50%	22-76%	23-45%	181-59%	7-78%	452-61%

Customer Management Report (Baldwin Park) All Detection Types

01-Jul-2010 to 31-Jul-2010

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	442	43	36	278	32	77	110	383	17	1418
Less Uncontrollable Factors										
Obstruction	19	3	4	8	4	12	23	12	10	95
Driver Obstruction/Duckers										
Motor Cycle Helmet	1	0	1	0	0	0	1	2	0	5
Plate Obstruction	11	0	2	12	0	6	5	0	1	37
Signal Obstruction	0	0	0	0	0	0	0	1	0	1
Vehicle Obstruction	9	2	2	2	2	1	2	1	0	21
Emergency Vehicle Responding	1	0	0	1	0	0	0	0	1	3
Gender Mismatch	1	0	0	1	1	1	0	2	0	6
Incorrect/Incomplete DMV	1	0	0	0	0	0	0	0	0	1
Invalid Offense	8	0	0	2	0	0	2	14	0	26
Multiple vehicles in frame	0	0	0	1	0	0	0	0	0	1
On or Passed the Stop Bar (PD).	0	1	0	0	0	0	0	0	0	1
Police Discretion	1	0	0	3	0	0	0	3	0	7
Safe Turn On Red	24	0	0	5	0	1	9	37	0	76
Policy/Weather	13	0	0	1	0	1	0	0	0	15
Extended Vehicle										
Sun Glare	43	3	1	48	3	7	23	73	0	201
Yellow with Red Light	0	0	0	0	0	0	1	0	0	1
Registration	13	2	1	11	1	3	1	5	0	37
Paper Plates										
Issues	1	0	0	1	0	0	0	0	0	2
Wrong or No DMV										
Total	146	11	11	96	11	32	67	150	12	536
Sub Total Violations	296	32	25	182	21	45	43	233	5	882
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	296	32	25	182	21	45	43	233	5	882
Less Rejects										

Generated By: JHENDRICKS

Generated On: 2/1/2012 9:33:20 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Jul-2010 to 31-Jul-2010 Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Face Not in Frame	0-00%	0-00%	1-04%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-03%	0-00%	7-01%
Misc Camera Issue	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	11-05%	0-00%	12-01%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
Police Rejects	4-01%	0-00%	0-00%	2-01%	1-05%	0-00%	0-00%	6-03%	1-20%	14-02%
Driver Unidentifiable images poor	0-00%	5-16%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Red-light not visible in	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Sun Glare	1-00%	0-00%	0-00%	1-01%	0-00%	0-00%	2-05%	0-00%	0-00%	4-00%
Unclear Scene Image	158-53%	17-53%	13-52%	93-51%	15-71%	30-67%	24-56%	110-47%	3-60%	463-52%
Too Old	166-56%	22-69%	14-56%	100-55%	16-76%	32-71%	26-60%	135-58%	4-80%	515-58%
Approved Violations	130-44%	10-31%	11-44%	82-45%	5-24%	13-29%	17-40%	98-42%	1-20%	367-42%
Total Notices Printed	130-44%	10-31%	11-44%	82-45%	5-24%	13-29%	17-40%	98-42%	1-20%	367-42%

Customer Management Report (Baldwin Park) All Detection Types

01-Oct-2010 to 31-Oct-2010 Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	401	47	47	216	20	71	103	0	5	910
Less Uncontrollable Factors										
Obstruction	17	4	2	10	4	14	19	0	1	71
Driver Obstruction/Duckers	0	0	0	1	0	0	0	0	0	1
Motor Cycle Helmet	9	0	4	6	0	4	4	0	0	27
Plate Obstruction	9	4	0	4	0	1	6	0	0	24
Vehicle Obstruction	0	0	0	1	1	0	3	0	0	5
Police Driver Obstruction (PD)	1	1	1	0	0	1	0	0	0	4
Rejects	22	2	2	8	1	1	5	0	0	41
Emergency Vehicle Responding	0	0	0	0	0	0	1	0	0	1
Gender Mismatch	1	0	0	0	0	0	0	0	0	1
Multiple vehicles in frame	1	0	0	1	0	1	0	0	0	3
On or Passed the Stop Bar (PD)	27	0	0	17	0	1	9	0	0	54
Police Discretion	11	0	0	0	0	0	2	0	0	13
Safe Turn On Red	1	2	3	18	1	4	5	0	0	34
Policy/Weather	1	0	1	1	0	0	0	0	0	3
Extended Vehicle	27	0	0	17	0	1	9	0	0	54
Sun Glare	11	0	0	0	0	0	2	0	0	13
Weather/Nature	1	2	3	18	1	4	5	0	0	34
Out of Country Plate	1	0	1	1	0	0	0	0	0	3
Paper Plates	0	0	0	2	1	0	1	0	0	4
Wrong or No DMV	11	2	4	6	3	7	3	0	0	36
Total	2	0	0	0	0	0	0	0	0	2
Sub Total Violations	113	15	17	75	11	34	58	0	1	324
Less in Progress	288	32	30	141	9	37	45	0	4	586
Available For Prosecution	0	0	0	0	0	0	0	0	0	0
Less Rejects	288	32	30	141	9	37	45	0	4	586
Camera Modification	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: JHENDRICKS
Generated On: 2/11/2012 9:34:46 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Oct-2010 to 31-Oct-2010

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	2-00%
Face Not in Frame	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	5-02%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
Rear Plate No Flash	0-00%	0-00%	1-03%	2-01%	1-11%	0-00%	0-00%	0-00%	0-00%	4-01%
Scene Image No Flash	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Driver Unidentifiable images poor	2-01%	0-00%	0-00%	1-01%	0-00%	0-00%	1-02%	0-00%	0-00%	4-01%
Police Rejects	119-41%	9-28%	10-33%	61-43%	4-44%	19-51%	22-49%	0-00%	2-50%	246-42%
Process Issues	126-44%	9-28%	12-40%	68-48%	5-56%	21-57%	23-51%	0-00%	2-50%	266-45%
Total	162-56%	23-72%	18-60%	73-52%	4-44%	16-43%	22-49%	0-00%	2-50%	320-55%
Approved Violations	162-56%	23-72%	18-60%	73-52%	4-44%	16-43%	22-49%	0-00%	2-50%	320-55%
Total Notices Printed	162-56%	23-72%	18-60%	73-52%	4-44%	16-43%	22-49%	0-00%	2-50%	320-55%

Generated By: JHENDRICKS

Generated On: 2/11/2012 9:34:46 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Jan-2011 to 31-Jan-2011

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	339	43	36	174	31	45	90	9	8	775
Less Uncontrollable Factors										
Obstruction	10	1	2	10	1	8	14	0	3	49
Motor Cycle Helmet	0	0	0	1	0	0	0	0	0	1
Plate Obstruction	16	3	0	3	0	0	4	1	0	27
Vehicle Obstruction	7	3	0	12	0	3	4	1	0	30
Police Rejects										
Emergency Vehicle Responding	0	0	1	0	0	1	0	0	0	2
Incorrect/Incomplete DMV	5	0	0	4	0	0	1	2	0	12
Multiple vehicles in frame	0	0	0	1	0	0	0	0	0	1
Police Discretion	1	0	0	0	0	1	2	0	0	4
Safe Turn On Red	42	0	0	22	0	8	17	0	0	89
Policy/Weather	9	0	0	0	0	0	3	0	0	12
Extended Vehicle	1	0	2	10	0	1	12	0	0	26
Sun Glare										
Can Not Identify State	1	0	0	0	0	0	0	0	0	1
Out of Country Plate	1	0	0	0	0	0	0	1	0	2
Paper Plates	14	2	3	6	2	0	3	0	0	30
Total	107	9	8	69	3	22	60	5	3	286
Sub Total Violations	232	34	28	105	28	23	30	4	5	489
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	232	34	28	105	28	23	30	4	5	489
Less Rejects										
Camera Malfunction	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Misc Camera Issue	10-04%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	11-02%
Rear Plate Flash Inappropriate	0-00%	1-03%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Scene Image Flash Inappropriate	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: JHENDRICKS

Generated On: 2/1/2012 9:35:33 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Jan-2011 to 31-Jan-2011

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Police Rejects	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Sun Glare	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Unclear Scene Image	0-00%	0-00%	0-00%	1-01%	0-00%	1-04%	0-00%	0-00%	0-00%	2-00%
Process Issues	7-03%	0-00%	1-04%	4-04%	5-18%	0-00%	6-20%	0-00%	0-00%	23-05%
Total	17-07%	3-09%	1-04%	8-08%	5-18%	2-09%	6-20%	0-00%	0-00%	42-09%
Approved Violations	215-93%	31-91%	27-96%	97-92%	23-82%	21-91%	24-80%	4-100%	5-100%	447-91%
Total Notices Printed	215-93%	31-91%	27-96%	97-92%	23-82%	21-91%	24-80%	4-100%	5-100%	447-91%

Customer Management Report (Baldwin Park) All Detection Types

01-Apr-2011 to 30-Apr-2011

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	327	44	18	197	26	45	61	121	7	846
Less Uncontrollable Factors										
Obstruction	12	2	3	7	2	8	10	2	2	48
Driver Obstruction/Duckers										
Motor Cycle Helmet	0	0	0	0	0	0	0	1	0	1
Plate Obstruction	1	1	1	4	0	1	3	1	0	12
Vehicle Obstruction	6	2	0	4	1	2	1	2	0	18
Police Rejects										
Incorrect/Incomplete DMV	25	3	2	12	1	2	3	1	1	50
Invalid Offense	1	1	0	0	0	0	1	71	0	74
Multiple vehicles in frame	0	0	0	1	0	0	0	0	0	1
On or Passed the Stop Bar (PD)	16	0	0	12	0	2	3	0	0	33
Police Discretion	2	0	0	2	0	0	0	1	0	5
Safe Turn On Red	10	0	0	4	0	1	5	1	0	21
Policy/Weather										
Extended Vehicle	9	1	0	1	0	0	0	0	0	11
Sun Glare	7	2	2	34	1	2	10	22	0	80
Yellow with Red Light	0	0	0	0	1	0	0	0	0	1
Registration Issues										
Out of Country Plate	2	0	0	0	0	0	0	0	0	2
Paper Plates	16	1	2	5	1	2	2	2	0	31
Wrong or No DMV	2	0	0	0	0	0	0	0	0	2
Total	109	13	10	86	7	20	38	104	3	390
Sub Total Violations	218	31	8	111	19	25	23	17	4	456
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	218	31	8	111	19	25	23	17	4	456
Less Rejects										
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-12%	0-00%	2-00%
Face Not in Frame	0-00%	0-00%	0-00%	3-03%	3-16%	1-04%	0-00%	5-29%	1-25%	13-03%

Generated By: JHENDRICKS

Generated On: 2/1/2012 9:36:14 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Apr-2011 to 30-Apr-2011 Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Plate Burn Out	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-06%	0-00%	3-01%
Rear Plate Camera Blurry	2-01%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Rear Plate Flash Inappropriate	1-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	1-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	1-00%
Police Rejects	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	5-02%	1-03%	0-00%	5-05%	3-16%	1-04%	2-09%	9-53%	1-25%	27-06%
Approved Violations	213-98%	30-97%	8-100%	106-95%	16-84%	24-96%	21-91%	8-47%	3-75%	429-94%
Total Notices Printed	213-98%	30-97%	8-100%	106-95%	16-84%	24-96%	21-91%	8-47%	3-75%	429-94%

Customer Management Report (Baldwin Park) All Detection Types

01-Jun-2011 to 30-Jun-2011 Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	343	22	54	214	34	57	121	24	10	879
Less Uncontrollable Factors										
Obstruction	12	3	0	11	6	11	21	1	4	69
Driver Obstruction/Duckers										
Motor Cycle Helmet	0	0	1	1	0	0	0	1	0	3
Plate Obstruction	5	0	4	2	0	1	4	0	0	16
Signal Obstruction	3	0	0	0	0	0	0	0	1	4
Vehicle Obstruction	4	1	0	8	0	1	2	1	0	17
Police Rejects	3	2	1	2	1	0	1	0	0	10
Incorrect/Incomplete DMV	59	0	5	19	4	4	8	4	1	104
Multiple vehicles in frame	0	0	0	0	0	0	2	0	0	2
On or Passed the Stop Bar (PD)	22	0	0	14	0	4	10	0	0	50
Police Discretion	1	0	0	2	0	0	0	0	0	3
Safe Turn On Red	8	1	0	5	0	0	2	0	0	16
Policy/Weather	12	0	0	0	0	0	0	0	0	12
Extended Vehicle										
Sun Glare	11	5	8	39	7	5	35	14	1	125
Weather/Nature	0	0	0	1	0	0	0	0	0	1
Registration Issues	1	0	0	0	0	0	1	0	0	2
Out of Country Plate										
Paper Plates	6	0	0	6	0	2	2	0	0	16
Wrong or No DMV	1	0	0	0	0	0	0	0	0	1
Total	148	12	19	110	18	28	88	21	7	451
Sub Total Violations	195	10	35	104	16	29	33	3	3	428
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	195	10	35	104	16	29	33	3	3	428
Less Rejects										
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-00%
Face Camera Flash										
Generated By: JHENDRICKS										
Generated On: 2/1/2012 9:39:42 AM										

Customer Management Report (Baldwin Park) All Detection Types

01-Jun-2011 to 30-Jun-2011 Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Face Camera Focus Blurry	2-01%	1-10%	0-00%	3-03%	0-00%	1-03%	4-12%	0-00%	0-00%	11-03%
Face Not in Frame	2-01%	0-00%	1-03%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Plate Burn Out	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	2-02%	0-00%	1-03%	0-00%	0-00%	0-00%	3-01%
Rear Plate No Flash	0-00%	0-00%	0-00%	5-05%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	1-00%
Unclear Scene Image	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects										
Total	4-02%	1-10%	1-03%	16-15%	1-06%	2-07%	6-18%	0-00%	0-00%	31-07%
Approved Violations	191-98%	9-90%	34-97%	88-85%	15-94%	27-93%	27-82%	3-100%	3-100%	397-93%
Total Notices Printed	191-98%	9-90%	34-97%	88-85%	15-94%	27-93%	27-82%	3-100%	3-100%	397-93%

Customer Management Report (Baldwin Park) All Detection Types

Operator Id: %

01-Jul-2011 to 31-Jul-2011

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	369	21	45	208	28	50	83	37	14	855
Less Uncontrollable Factors										
Obstruction	14	0	0	7	4	10	8	2	5	50
Driver Obstruction/Duckers										
Motor Cycle Helmet	0	0	0	1	0	0	1	0	0	2
Plate Obstruction	5	0	2	5	0	6	5	1	0	24
Vehicle Obstruction	7	0	1	7	0	1	2	2	0	20
Police Rejects										
Emergency Vehicle Responding	0	1	0	0	0	0	0	0	0	1
Incorrect/Incomplete DMV	23	0	2	7	1	1	1	0	0	35
Invalid Offense	5	0	0	0	0	0	0	0	0	5
Multiple vehicles in frame	0	0	0	1	0	0	1	0	0	2
On or Passed the Stop Bar (PD)	26	0	0	16	0	1	8	0	0	51
Police Discretion	4	0	0	0	0	0	0	0	0	4
Safe Turn On Red	10	0	0	2	0	0	2	0	0	14
Policy/Weather										
Extended Vehicle	11	0	0	1	0	0	0	0	0	12
Sun Glare	14	4	6	42	2	9	24	25	1	127
Registration Issues										
Out of Country Plate	3	0	1	1	0	0	0	0	0	5
Paper Plates	9	0	0	8	0	1	3	0	1	22
Total	131	5	12	98	7	29	55	30	7	374
Sub Total Violations	238	16	33	110	21	21	28	7	7	481
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	238	16	33	110	21	21	28	7	7	481
Less Rejects										
Camera	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-14%	0-00%	2-00%
Face Camera Flash										
Malfunction	1-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-14%	0-00%	3-01%
Face Camera Focus Blurry										
Face Camera No Flash	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-14%	0-00%	2-00%

Generated By: JHENDRICKS
Generated On: 2/1/2012 9:40:09 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Jul-2011 to 31-Jul-2011 Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Face Not in Frame	0-00%	0-00%	3-09%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Misc Camera Issue	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	0-00%	0-00%	2-00%
Rear Plate Camera Blurry	13-05%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	14-03%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	0-00%	0-00%	2-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Total	15-06%	0-00%	3-09%	7-06%	1-05%	0-00%	4-14%	3-43%	0-00%	33-07%
Approved Violations	223-94%	16-100%	30-91%	103-94%	20-95%	21-100%	24-86%	4-57%	7-100%	448-93%
Total Notices Printed	223-94%	16-100%	30-91%	103-94%	20-95%	21-100%	24-86%	4-57%	7-100%	448-93%

Customer Management Report (Baldwin Park) All Detection Types

Operator Id: %

01-Aug-2011 to 31-Aug-2011

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	355	22	47	267	28	60	149	398	12	1338
Less Uncontrollable Factors										
Obstruction	21	4	0	16	2	12	22	10	1	88
Driver Obstruction/Duckers	1	1	0	0	0	0	1	1	0	4
Motor Cycle Helmet	6	2	1	10	1	6	8	6	0	40
Plate Obstruction	0	0	0	0	0	0	0	1	0	1
Signal Obstruction	3	0	0	4	0	4	4	0	0	15
Vehicle Obstruction	1	0	0	0	0	0	0	0	0	1
Driver Obstruction (PD)	0	0	0	0	0	0	0	1	0	1
Gender Mismatch	26	1	4	12	2	6	3	28	1	83
Incorrect/Incomplete DMV	0	0	0	1	0	0	3	0	0	4
Multiple vehicles in frame	34	0	0	21	0	2	20	36	0	113
On or Passed the Stop Bar (PD)	4	0	0	0	0	0	1	3	0	8
Police Discretion	10	0	0	4	0	0	3	10	0	27
Safe Turn On Red	9	0	1	4	1	0	1	0	0	16
Policy/Weather	15	1	6	39	4	4	35	27	0	131
Extended Vehicle	0	0	0	0	0	0	0	1	0	1
Sun Glare	1	0	0	0	0	0	0	0	0	1
Weather/Nature	1	0	0	1	0	1	0	0	0	3
Out of Country Plate	11	5	2	11	1	2	5	8	2	47
Paper Plates	0	0	0	0	0	0	0	1	0	1
Wrong or No DMV	142	14	14	123	11	37	106	133	4	584
Total	213	8	33	144	17	23	43	265	8	754
Sub Total Violations	0	0	0	0	0	0	0	0	0	0
Less in Progress	213	8	33	144	17	23	43	265	8	754
Available For Prosecution										
Less Rejects										

Generated By: JHENDRICKS

Generated On: 2/1/2012 9:40:35 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Aug-2011 to 31-Aug-2011

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Camera Malfunction	0-00%	0-00%	0-00%	3-02%	0-00%	0-00%	2-05%	4-02%	0-00%	9-01%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-02%	0-00%	7-01%
Face Camera Focus Blurry	1-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	1-00%	0-00%	3-00%
Face Not in Frame	0-00%	3-38%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Misc Camera Issue	1-00%	0-00%	0-00%	7-05%	0-00%	0-00%	0-00%	0-00%	0-00%	8-01%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
Plate Not in Frame	12-06%	0-00%	0-00%	3-02%	0-00%	0-00%	0-00%	0-00%	0-00%	15-02%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	1-00%	0-00%	3-00%
Rear Plate Flash Inappropriate	1-00%	0-00%	0-00%	12-08%	0-00%	0-00%	0-00%	3-01%	0-00%	16-02%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	1-00%	0-00%	2-00%
Police Rejects	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
No Images	0-00%	3-38%	0-00%	29-20%	1-06%	1-04%	1-02%	15-06%	0-00%	70-09%
Sun Glare	198-93%	5-62%	33-100%	115-80%	16-94%	22-96%	37-86%	250-94%	8-100%	684-91%
Approved Violations	198-93%	5-62%	33-100%	115-80%	16-94%	22-96%	37-86%	250-94%	8-100%	684-91%
Total Notices Printed	198-93%	5-62%	33-100%	115-80%	16-94%	22-96%	37-86%	250-94%	8-100%	684-91%

Customer Management Report (Baldwin Park) All Detection Types

01-Sep-2011 to 30-Sep-2011 Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	265	29	43	266	26	69	141	427	16	1282
Less Uncontrollable Factors										
Obstruction	13	1	0	7	1	11	15	6	6	60
Driver Obstruction/Duckers										
Motor Cycle Helmet	1	0	0	0	0	0	0	2	0	3
Plate Obstruction	3	2	1	7	1	3	2	2	0	21
Signal Obstruction	0	0	0	0	0	0	1	0	0	1
Vehicle Obstruction	4	0	0	6	1	0	5	1	0	17
Duplicate nomination	0	0	0	0	0	0	1	0	0	1
Emergency Vehicle Responding	0	0	0	0	0	0	1	0	0	1
Gender Mismatch	0	0	0	0	0	2	0	0	0	2
Incorrect Plate on Vehicle	0	1	0	0	0	0	0	0	0	1
Incorrect/Incomplete DMV	25	2	1	29	1	4	7	31	2	102
Invalid Offense	0	1	2	1	0	0	0	0	0	4
Multiple vehicles in frame	0	0	0	0	0	0	2	0	0	2
On or Passed the Stop Bar (PD).	28	0	0	23	0	3	22	57	0	133
Police Discretion	0	0	2	1	0	0	0	2	0	5
Safe Turn On Red	6	0	0	1	0	0	3	19	0	29
Policy/Weather	5	0	2	2	0	0	1	0	0	10
Extended Vehicle										
Sun Glare	13	2	9	46	2	8	45	12	0	137
Out of Country Plate	1	0	0	0	0	0	1	2	0	4
Paper Plates	6	3	2	6	0	1	5	12	0	35
Wrong or No DMV	0	0	0	1	0	0	0	0	0	1
Total	105	12	19	130	6	32	111	146	8	569
Sub Total Violations	160	17	24	136	20	37	30	281	8	713
Less in Progress	0	0	0	0	0	0	0	0	0	0

Generated By: JHENDRICKS
Generated On: 2/1/2012 9:41:22 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Sep-2011 to 30-Sep-2011 Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Available For Prosecution	160	17	24	136	20	37	30	281	8	713
Less Rejects										
Camera Face Camera Flash	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	2-01%	0-00%	3-00%
Camera Malfunction	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	1-03%	2-01%	0-00%	5-01%
Face Not in Frame	1-01%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	4-01%
Image Missing	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-03%	0-00%	0-00%	2-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	54-19%	0-00%	54-08%
Plate Burn Out	0-00%	0-00%	0-00%	7-05%	0-00%	0-00%	0-00%	0-00%	0-00%	7-01%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	2-01%	0-00%	0-00%	2-01%	0-00%	1-03%	0-00%	0-00%	0-00%	5-01%
Rear Plate Flash Inappropriate	1-01%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	3-01%	0-00%	5-01%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	0-00%	3-00%
Scene Image Blurry	0-00%	0-00%	0-00%	0-00%	2-10%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Rejects	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%
Total	4-02%	0-00%	1-04%	14-10%	2-10%	1-03%	3-10%	67-24%	0-00%	92-13%
Approved Violations	156-98%	17-100%	23-96%	122-90%	18-90%	36-97%	27-90%	214-76%	8-100%	621-87%
Total Notices Printed	156-98%	17-100%	23-96%	122-90%	18-90%	36-97%	27-90%	214-76%	8-100%	621-87%

Customer Management Report (Baldwin Park) All Detection Types

Operator Id: %

01-Oct-2011 to 31-Oct-2011

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	336	34	71	272	19	73	168	565	15	1553
Less Uncontrollable Factors										
Obstruction	10	0	1	8	3	8	25	8	7	70
Driver Obstruction/Duckers										
Motor Cycle Helmet	0	0	1	0	0	0	1	1	0	3
Plate Obstruction	1	0	4	9	0	1	5	2	0	22
Signal Obstruction	0	0	0	0	1	0	0	0	0	1
Vehicle Obstruction	2	4	0	1	0	1	3	1	0	12
Police Rejects										
Driver Obstruction (PD)	2	1	0	0	0	1	0	2	0	6
Emergency Vehicle Responding	0	1	0	0	0	0	1	0	0	2
Gender Mismatch	1	0	0	2	0	0	0	1	0	4
Incorrect/Incomplete DMV	34	1	5	19	1	8	5	57	1	131
Multiple vehicles in frame	0	0	0	2	0	0	1	0	0	3
On or Passed the Stop Bar (PD).	35	0	0	19	0	5	38	133	0	230
Police Discretion	7	5	10	10	1	5	2	8	0	48
Safe Turn On Red	7	0	0	1	0	2	2	34	0	46
Policy/Weather										
Extended Vehicle	7	0	0	2	0	0	1	0	0	10
Sun Glare	3	1	7	33	2	2	27	7	0	82
Weather/Nature	1	0	1	1	0	1	3	0	0	7
Yellow with Red Light	0	0	0	1	0	0	0	0	0	1
Registration Issues										
Can Not Identify State	0	0	0	1	0	0	0	0	0	1
Out of Country Plate	1	0	0	0	0	0	2	3	0	6
Paper Plates	12	1	4	11	1	4	5	14	1	53
Wrong or No DMV	2	0	0	0	0	0	0	0	0	2
Total	125	14	33	120	9	38	121	271	9	740
Sub Total Violations	211	20	38	152	10	35	47	294	6	813

Generated By: JHENDRICKS
Generated On: 2/1/2012 9:41:51 AM

Customer Management Report (Baldwin Park) All Detection Types

Operator id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	211	20	38	152	10	35	47	294	6	813
Less Rejects										
Camera Malfunction	0-00%	0-00%	0-00%	1-01%	0-00%	1-03%	0-00%	0-00%	0-00%	2-00%
Face Camera Flash	0-00%	0-00%	1-03%	3-02%	0-00%	0-00%	4-09%	3-01%	0-00%	11-01%
Face Camera Focus Blurry	0-00%	0-00%	3-08%	1-01%	0-00%	0-00%	2-04%	1-00%	0-00%	7-01%
Face Not in Frame	1-00%	0-00%	0-00%	3-02%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
Image Missing	1-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Misc Camera Issue	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	1-00%	0-00%	1-03%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%	0-00%	2-00%
Police Rejects	4-02%	0-00%	0-00%	11-07%	0-00%	1-03%	2-04%	0-00%	0-00%	18-02%
Driver Unidentifiable images poor	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Sun Glare	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
Unclear Scene Image	0-00%	0-00%	0-00%	1-01%	0-00%	1-03%	0-00%	0-00%	0-00%	2-00%
Total	7-03%	1-05%	6-16%	23-15%	0-00%	4-11%	9-19%	5-02%	0-00%	55-07%
Approved Violations	204-97%	19-95%	32-84%	129-85%	10-100%	31-89%	38-81%	289-98%	6-100%	758-93%
Total Notices Printed	204-97%	19-95%	32-84%	129-85%	10-100%	31-89%	38-81%	289-98%	6-100%	758-93%

Customer Management Report (Baldwin Park) All Detection Types

Operator Id: %

01-Nov-2011 to 30-Nov-2011

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	354	17	40	253	14	51	142	516	21	1408
Less Uncontrollable Factors										
Obstruction	14	1	0	8	0	8	15	2	9	57
Motor Cycle Helmet	0	0	0	1	0	0	0	0	0	1
Plate Obstruction	7	0	4	7	0	2	9	5	0	34
Vehicle Obstruction	5	2	1	5	0	1	6	2	0	22
Police Rejects										
Emergency Vehicle Responding	0	0	0	0	0	0	1	0	0	1
Incorrect/Incomplete DMV	36	3	2	23	1	4	6	53	3	131
Invalid Offense	0	0	1	0	0	0	0	0	0	1
Multiple vehicles in frame	0	0	0	1	0	0	0	0	0	1
On or Passed the Stop Bar (PD)	36	0	0	26	0	3	24	138	0	227
Police Discretion	9	1	3	21	0	1	2	16	1	54
Safe Turn On Red	7	0	0	2	0	1	11	32	0	53
Policy/Weather										
Extended Vehicle	14	0	0	1	0	0	0	0	0	15
Sun Glare	14	1	6	24	4	1	15	4	0	69
Weather/Nature	0	0	0	2	0	0	0	0	0	2
Registration Issues										
Out of Country Plate	3	0	0	2	0	0	0	1	0	6
Paper Plates	14	0	2	9	0	2	6	15	0	48
Total	159	8	19	132	5	23	95	268	13	722
Sub Total Violations	195	9	21	121	9	28	47	248	8	686
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	195	9	21	121	9	28	47	248	8	686
Less Rejects										
Camera Malfunction	0-00%	0-00%	0-00%	1-01%	1-11%	0-00%	3-06%	0-00%	0-00%	5-01%
Face Camera Focus Blurry	1-01%	0-00%	0-00%	7-06%	1-11%	0-00%	4-09%	2-01%	0-00%	15-02%

Generated By: JHENDRICKS
Generated On: 2/1/2012 9:42:29 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Nov-2011 to 30-Nov-2011 Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Face Camera No Flash	0-00%	0-00%	0-00%	1-01%	1-11%	0-00%	0-00%	0-00%	0-00%	2-00%
Face Not in Frame	1-01%	0-00%	1-05%	0-00%	1-11%	0-00%	0-00%	4-02%	0-00%	7-01%
Image Missing	0-00%	1-11%	0-00%	5-04%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
Misc Camera Issue	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	6-13%	0-00%	0-00%	8-01%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	0-00%	3-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	3-02%	0-00%	0-00%	0-00%	1-00%	0-00%	4-01%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
Rear Plate No Flash	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	12-26%	0-00%	0-00%	14-02%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	1-01%	0-00%	2-07%	1-02%	2-01%	0-00%	6-01%
Police Rejects										
Total	4-02%	1-11%	1-05%	20-17%	5-56%	2-07%	27-57%	12-05%	0-00%	72-10%
Approved Violations	191-98%	8-89%	20-95%	101-83%	4-44%	26-93%	20-43%	236-95%	8-100%	614-90%
Total Notices Printed	191-98%	8-89%	20-95%	101-83%	4-44%	26-93%	20-43%	236-95%	8-100%	614-90%

Customer Management Report (Baldwin Park) All Detection Types

Operator Id: %

01-Dec-2011 to 31-Dec-2011

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Total Processed Incidents	369	23	50	222	30	44	166	521	10	1435
Less Uncontrollable Factors										
Obstruction	19	1	1	4	6	3	19	7	3	63
Driver Obstruction/Duckers										
Motor Cycle Helmet	0	0	0	0	0	0	0	2	0	2
Plate Obstruction	7	1	1	8	0	1	5	3	0	26
Vehicle Obstruction	4	3	2	1	0	1	1	2	1	15
Police Rejects										
Driver Obstruction (PD)	0	0	0	0	0	0	0	2	0	2
Emergency Vehicle Responding	0	0	0	0	0	0	1	0	0	1
Incorrect/Incomplete DMV	31	1	3	18	1	3	8	39	0	104
Invalid Offense	1	0	0	0	0	0	0	0	0	1
Multiple vehicles in frame	0	0	0	1	0	0	0	0	0	1
On or Passed the Stop Bar (PD)	31	1	0	16	0	7	31	165	0	251
Plate Obstruction (PD)	0	0	0	0	0	0	1	0	0	1
Plate Unidentifiable	0	0	0	1	0	0	0	0	0	1
Police Discretion	13	6	14	27	4	3	2	21	2	92
Safe Turn On Red	8	0	0	4	0	0	2	25	0	39
Policy/Weather										
Extended Vehicle	5	0	0	0	1	1	1	0	0	8
Sun Glare	25	0	6	21	5	0	18	2	0	77
Registration Issues										
Paper Plates	12	1	2	8	2	2	5	19	0	51
Wrong or No DMV	1	0	0	0	0	1	0	0	0	2
Total	157	14	29	109	19	22	94	287	6	737
Sub Total Violations	212	9	21	113	11	22	72	234	4	698
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	212	9	21	113	11	22	72	234	4	698
Less Rejects										

Generated By: JHENDRICKS

Generated On: 2/1/2012 9:43:00 AM

Customer Management Report (Baldwin Park) All Detection Types

01-Dec-2011 to 31-Dec-2011 Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Camera Malfunction	0-00%	0-00%	0-00%	3-03%	1-09%	0-00%	0-00%	0-00%	0-00%	4-01%
Face Camera Flash	0-00%	0-00%	1-05%	2-02%	0-00%	0-00%	2-03%	1-00%	0-00%	6-01%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	3-27%	0-00%	0-00%	0-00%	0-00%	3-00%
Face Camera No Flash	1-00%	0-00%	0-00%	1-01%	0-00%	2-09%	1-01%	6-03%	0-00%	11-02%
Face Not in Frame	0-00%	0-00%	0-00%	5-04%	0-00%	0-00%	3-04%	0-00%	0-00%	8-01%
Image Missing	1-00%	0-00%	0-00%	1-01%	0-00%	0-00%	33-46%	1-00%	0-00%	36-05%
Misc Camera Issue	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Burn Out	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	3-04%	0-00%	0-00%	4-01%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Police Rejects	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Incorrect Speed	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%
Sun Glare	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Unclear Scene Image	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	2-01%	1-11%	1-05%	15-13%	4-36%	2-09%	43-60%	9-04%	0-00%	77-11%
Approved Violations	210-99%	8-89%	20-95%	98-87%	7-64%	20-91%	29-40%	225-96%	4-100%	621-89%
Total Notices Printed	210-99%	8-89%	20-95%	98-87%	7-64%	20-91%	29-40%	225-96%	4-100%	621-89%