

Customer Management Report (Escondido) All Detection Types

01-Apr-2005 to 30-Apr-2005

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents		108	0	50	34	37	6	0	0	81	0	0	169	135	0	0	620
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	1	0	0	0	0	0	0	0	2	0	0	1	1	0	0	5
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
	Plate Obstruction	3	0	2	0	0	0	0	0	2	0	0	3	5	0	0	15
	Vehicle Obstruction	0	0	1	0	0	1	0	0	2	0	0	1	15	0	0	20
Police Rejects	DMV Not On File	1	0	0	0	0	0	0	0	1	0	0	1	1	0	0	4
	Driver Unidentifiable	0	0	0	0	0	0	0	0	0	0	0	1	2	0	0	3
	Gender Mismatch	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1
	Invalid Offense	4	0	1	0	0	0	0	0	4	0	0	0	2	0	0	11
	Safe Turn On Red	7	0	6	0	0	0	0	0	0	0	0	0	0	0	0	13
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	0	0	1	0	0	3	1	0	0	5
	Sun Glare	8	0	5	0	2	0	0	0	2	0	0	24	10	0	0	51
Registration Issues	Out of Country Plate	0	0	0	1	0	0	0	0	0	0	0	2	0	0	0	3
	Paper Plates	3	0	2	2	0	0	0	0	2	0	0	5	3	0	0	17
	Wrong or No DMV	1	0	0	1	1	0	0	0	5	0	0	3	0	0	0	11
Total		28	0	17	4	3	1	0	0	21	0	0	45	41	0	0	160
Sub Total Violations		80	0	33	30	34	5	0	0	60	0	0	124	94	0	0	460
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		80	0	33	30	34	5	0	0	60	0	0	124	94	0	0	460
Less Rejects																	
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
	Face Camera Focus Blurry	1-01%	0-00%	0-00%	1-03%	0-00%	1-20%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:45:39 AM

Customer Management Report (Escondido) All Detection Types

01-Apr-2005 to 30-Apr-2005

Operator Id: %

	ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Face Not in Frame	2-02%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	4-01%
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	2-00%
Plate Not in Frame	0-00%	0-00%	1-03%	0-00%	0-00%	1-20%	0-00%	0-00%	0-00%	0-00%	0-00%	8-06%	1-01%	0-00%	0-00%	11-02%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	7-12%	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	10-02%
Rear Plate Flash Inappropriate	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues																
Too Old	1-01%	0-00%	0-00%	0-00%	3-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Total	5-06%	0-00%	1-03%	1-03%	5-15%	2-40%	0-00%	0-00%	15-25%	0-00%	0-00%	11-09%	5-05%	0-00%	0-00%	45-10%
Approved Violations	75-94%	0-00%	32-97%	29-97%	29-85%	3-60%	0-00%	0-00%	45-75%	0-00%	0-00%	113-91%	89-95%	0-00%	0-00%	415-90%
Total Notices Printed	75-94%	0-00%	32-97%	29-97%	29-85%	3-60%	0-00%	0-00%	45-75%	0-00%	0-00%	113-91%	89-95%	0-00%	0-00%	415-90%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:45:39 AM

Customer Management Report (Escondido) All Detection Types

01-Oct-2005 to 31-Oct-2005

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents		76	0	54	32	14	8	0	0	77	0	0	135	97	0	0	493
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	3	0	3	3	2	0	0	0	6	0	0	4	8	0	0	29
	Motor Cycle Helmet	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0	2
	Plate Obstruction	4	0	1	0	0	1	0	0	3	0	0	9	9	0	0	27
	Vehicle Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	6	0	0	6
Police Rejects	Authorized Emergency Vehicle	3	0	0	0	0	1	0	0	5	0	0	0	0	0	0	9
	Driver Unidentifiable	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
	Invalid Offense	2	0	0	0	0	0	0	0	0	0	0	0	1	0	0	3
	Safe Turn On Red	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	0	0	1	0	0	1	1	0	0	3
	Sun Glare	1	0	5	1	2	0	0	0	2	0	0	1	3	0	0	15
Registration Issues	Can Not Identify State	1	0	0	0	0	0	0	0	0	0	0	1	0	0	0	2
	Out of Country Plate	0	0	0	0	0	0	0	0	0	0	0	1	1	0	0	2
	Paper Plates	4	0	1	0	1	0	0	0	4	0	0	4	5	0	0	19
	Wrong or No DMV	1	0	3	0	0	0	0	0	0	0	0	4	0	0	0	8
Total		19	0	13	4	5	4	0	0	21	0	0	27	34	0	0	127
Sub Total Violations		57	0	41	28	9	4	0	0	56	0	0	108	63	0	0	366
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		57	0	41	28	9	4	0	0	56	0	0	108	63	0	0	366
Less Rejects																	
Camera Malfunction	Digital Distortion	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera Flash	4-07%	0-00%	2-05%	1-04%	0-00%	0-00%	0-00%	0-00%	3-05%	0-00%	0-00%	4-04%	0-00%	0-00%	0-00%	14-04%
	Face Camera Focus Blurry	2-04%	0-00%	2-05%	3-11%	1-11%	0-00%	0-00%	0-00%	7-12%	0-00%	0-00%	18-17%	11-17%	0-00%	0-00%	44-12%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	9-14%	0-00%	0-00%	10-03%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:46:59 AM

Customer Management Report (Escondido) All Detection Types

01-Oct-2005 to 31-Oct-2005

Operator Id: %

	ESC:02ES-01	ESC:AUVA-01	ESC:CCVP-01	ESC:ES02-01	ESC:ESVA-01	ESC:JU5E-01	ESC:LIFI-01	ESC:LIFI-03	ESC:SEJU-01	ESC:VAAU-01	ESC:VAAU-03	ESC:VAES-01	ESC:VPCC-01	ESC:WVTU-01	ESC:WVTU-03	TOTAL
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	2-01%
Plate Burn Out	1-02%	0-00%	3-07%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-05%	0-00%	0-00%	0-00%	10-03%
Plate Not in Frame	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	2-02%	2-03%	0-00%	0-00%	6-02%
Rear Plate Camera Blurry	6-11%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	20-19%	5-08%	0-00%	0-00%	34-09%
Rear Plate Flash Inappropriate	1-02%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	5-01%
Rear Plate No Flash	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues																
Too Old	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	15-26%	0-00%	13-32%	4-14%	2-22%	0-00%	0-00%	0-00%	16-29%	0-00%	0-00%	51-47%	29-46%	0-00%	0-00%	130-36%
Approved Violations	42-74%	0-00%	28-68%	24-86%	7-78%	4-100%	0-00%	0-00%	40-71%	0-00%	0-00%	57-53%	34-54%	0-00%	0-00%	236-64%
Total Notices Printed	42-74%	0-00%	28-68%	24-86%	7-78%	4-100%	0-00%	0-00%	40-71%	0-00%	0-00%	57-53%	34-54%	0-00%	0-00%	236-64%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:46:59 AM

Customer Management Report (Escondido) All Detection Types

01-Apr-2007 to 30-Apr-2007

Operator Id: %

	ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL	
Total Processed Incidents	38	60	34	16	10	5	135	60	59	28	377	138	62	153	205	1380	
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	2	11	5	0	3	0	17	16	4	2	21	14	5	19	11	130
	Motor Cycle Helmet	0	0	1	0	0	0	0	0	0	0	4	0	0	1	0	6
	Plate Obstruction	2	2	0	0	0	0	3	2	4	0	4	9	2	2	6	36
	Signal Obstruction	0	0	0	0	0	0	2	0	0	1	2	1	0	2	2	10
	Vehicle Obstruction	1	16	0	0	0	0	0	0	1	0	7	0	1	15	4	45
Police Rejects	Citation Issued manually	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
	Emergency Vehicle Responding	3	0	1	1	0	0	0	0	3	0	0	0	1	0	1	10
	Incorrect/Incomplete DMV	0	0	0	0	0	0	1	0	0	0	1	1	1	0	1	5
	Plate Obstruction (PD)	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1	2
	Police Discretion	0	0	0	0	0	0	1	0	0	0	0	2	0	0	1	4
	Safe Turn On Red	0	0	2	0	0	0	4	0	0	0	56	3	0	0	4	69
	Sun Glare	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
	Weather Conditions	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	0	0	0	0	1	0	0	5	1	7
	Sun Glare	14	13	6	3	0	1	14	8	6	2	60	14	8	40	13	202
	Weather/Nature	0	0	1	1	0	0	1	0	0	0	1	3	0	0	0	7
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	2
	Out of Country Plate	0	0	0	0	1	0	0	1	0	0	1	0	0	1	0	4
	Paper Plates	1	1	1	2	0	0	7	1	3	3	26	5	5	1	3	59
	Wrong or No DMV	0	0	0	0	0	0	1	0	0	0	3	1	1	3	3	12
Total		23	43	17	7	4	1	52	28	21	8	188	55	24	89	53	613
Sub Total Violations		15	17	17	9	6	4	83	32	38	20	189	83	38	64	152	767
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Generated By: KNAVARRO

Generated On: 6/4/2013 10:48:03 AM

Customer Management Report (Escondido) All Detection Types

01-Apr-2007 to 30-Apr-2007

Operator Id: %

		ESC-02ES-01	ESC-AUVVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL	
Available For Prosecution		15	17	17	9	6	4	83	32	38	20	189	83	38	64	152	767	
Less Rejects																		
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-08%	0-00%	4-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	11-01%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-01%	3-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	2-01%	3-00%	
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-01%	6-07%	0-00%	0-00%	0-00%	8-01%
Police Rejects	Driver Unidentifiable images poor	0-00%	1-06%	3-18%	0-00%	0-00%	0-00%	4-05%	0-00%	7-18%	0-00%	16-08%	0-00%	0-00%	6-09%	3-02%	40-05%	
	No Video	0-00%	0-00%	0-00%	0-00%	3-50%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%	
Total		0-00%	1-06%	3-18%	0-00%	4-67%	0-00%	12-14%	0-00%	11-29%	0-00%	20-11%	8-10%	1-03%	6-09%	6-04%	72-09%	
Approved Violations		15-100%	16-94%	14-82%	9-100%	2-33%	4-100%	71-86%	32-100%	27-71%	20-100%	169-89%	75-90%	37-97%	58-91%	146-96%	695-91%	
Total Notices Printed		15-100%	16-94%	14-82%	9-100%	2-33%	4-100%	71-86%	32-100%	27-71%	20-100%	169-89%	75-90%	37-97%	58-91%	146-96%	695-91%	

Generated By: KNAVARRO

Generated On: 6/4/2013 10:48:03 AM

Customer Management Report (Escondido) All Detection Types

01-Oct-2007 to 31-Oct-2007

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents		59	48	52	30	13	6	170	38	56	31	249	115	71	120	122	1180
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	4	10	3	1	2	3	6	10	4	1	9	6	4	17	2	82
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	1	0	1	0	0	0	0	2
	Plate Obstruction	5	0	0	1	0	0	10	3	1	0	1	3	5	3	4	36
	Vehicle Obstruction	1	6	1	0	0	0	1	0	1	1	2	1	3	11	1	29
Police Rejects	Emergency Vehicle Responding	5	2	9	0	0	0	7	1	1	0	3	1	5	0	5	39
	Incorrect/Incomplete DMV	1	1	0	0	0	0	0	0	1	0	0	0	1	0	0	4
	Invalid Offense	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1
	Multiple vehicles in frame	0	0	0	0	0	0	0	0	0	1	0	0	0	1	0	2
	Police Discretion	0	0	0	0	1	0	0	0	3	0	0	1	2	1	2	10
	Safe Turn On Red	0	0	6	0	0	0	15	0	0	0	71	7	0	0	5	104
Policy/Weather	Extended Vehicle	1	0	1	0	0	0	0	0	0	0	1	3	0	4	0	10
	Sun Glare	6	3	6	3	2	0	14	0	4	0	1	5	2	11	2	59
	Weather/Nature	0	0	0	0	0	0	0	0	0	0	1	0	0	1	0	2
Registration Issues	Can Not Identify State	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1	2
	Out of Country Plate	0	0	0	0	1	0	2	0	0	0	1	0	0	0	1	5
	Paper Plates	2	0	0	2	0	1	6	2	3	0	10	1	1	1	3	32
Total		25	22	26	7	6	4	62	16	20	3	101	28	23	50	26	419
Sub Total Violations		34	26	26	23	7	2	108	22	36	28	148	87	48	70	96	761
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		34	26	26	23	7	2	108	22	36	28	148	87	48	70	96	761
Less Rejects																	
Camera Malfunction	Face Camera Focus Blurry	1-03%	0-00%	3-12%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	7-01%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-10%	1-01%	0-00%	6-01%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:49:40 AM

Customer Management Report (Escondido) All Detection Types

01-Oct-2007 to 31-Oct-2007

Operator Id: %

	ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Image Missing	0-00%	6-23%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	8-01%
Misc Camera Issue	0-00%	2-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-07%	0-00%	0-00%	0-00%	8-01%
Plate Burn Out	1-03%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	7-08%	0-00%	0-00%	0-00%	10-01%
Plate Not in Frame	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-01%	2-04%	1-01%	2-02%	8-01%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	2-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-05%	1-02%	0-00%	1-01%	8-01%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	1-14%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Rejects																
Driver Unidentifiable images poor	1-03%	1-04%	2-08%	1-04%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	4-03%	0-00%	0-00%	4-06%	1-01%	15-02%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-00%
Total	4-12%	9-35%	5-19%	4-17%	1-14%	0-00%	1-01%	2-09%	1-03%	0-00%	10-07%	18-21%	8-17%	6-09%	5-05%	74-10%
Approved Violations	30-88%	17-65%	21-81%	19-83%	6-86%	2-100%	107-99%	20-91%	35-97%	28-100%	138-93%	69-79%	40-83%	64-91%	91-95%	687-90%
Total Notices Printed	30-88%	17-65%	21-81%	19-83%	6-86%	2-100%	107-99%	20-91%	35-97%	28-100%	138-93%	69-79%	40-83%	64-91%	91-95%	687-90%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:49:40 AM

Customer Management Report (Escondido) All Detection Types

01-Apr-2008 to 30-Apr-2008

Operator Id: %

	ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL	
Total Processed Incidents	48	81	43	22	14	8	105	42	51	30	297	123	75	102	107	1148	
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	0	4	3	1	1	0	7	6	6	0	4	6	2	11	8	59
	Motor Cycle Helmet	0	0	0	0	0	0	1	0	0	0	3	0	0	0	0	4
	Plate Obstruction	1	1	1	0	1	0	4	1	1	0	3	7	2	0	1	23
	Vehicle Obstruction	1	12	0	0	0	0	1	0	1	0	3	0	1	13	1	33
Police Rejects	Citation Issued manually	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
	Emergency Vehicle Responding	0	0	1	0	1	0	0	0	1	0	0	0	0	0	0	3
	Face Obstruction	0	0	0	0	0	0	1	0	0	0	1	0	0	0	0	2
	Incorrect/Incomplete DMV	0	0	0	0	0	0	1	0	0	0	1	0	0	0	0	2
	Multiple vehicles in frame	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	1
	Police Discretion	0	1	2	0	0	0	2	0	0	1	26	5	1	0	0	38
	Safe Turn On Red	2	0	5	0	0	0	4	0	0	0	46	4	0	0	3	64
Policy/Weather	Extended Vehicle	0	1	0	0	0	0	0	0	0	0	1	0	0	2	0	4
	Sun Glare	13	20	3	3	2	1	19	6	6	1	55	20	13	17	9	188
	Two Vehicles in Beam	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Weather/Nature	0	2	2	0	0	0	1	0	0	0	12	1	1	0	2	21
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
	Out of Country Plate	0	0	1	0	0	0	2	0	0	0	0	0	0	0	0	3
	Paper Plates	3	3	0	2	0	0	5	3	0	2	10	5	1	2	1	37
	Wrong or No DMV	0	1	0	0	0	0	1	0	0	0	0	0	0	0	0	2
Total		20	46	18	7	5	1	49	16	14	5	165	49	21	46	25	487
Sub Total Violations		28	35	25	15	9	7	56	26	37	25	132	74	54	56	82	661
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		28	35	25	15	9	7	56	26	37	25	132	74	54	56	82	661

Generated By: KNAVARRO

Generated On: 6/4/2013 10:51:05 AM

Customer Management Report (Escondido) All Detection Types

01-Apr-2008 to 30-Apr-2008

Operator Id: %

		ESC-02ES-01	ESC-AUVVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL	
Less Rejects																		
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%	
	Face Camera Focus Blurry	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	9-07%	0-00%	1-02%	0-00%	0-00%	11-02%	
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-11%	0-00%	0-00%	6-01%	
	Face Not in Frame	3-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	4-01%	
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-02%	5-06%	8-01%	
	Misc Camera Issue	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-09%	8-01%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	2-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-01%	1-02%	0-00%	0-00%	3-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
	Rear Plate No Flash	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	2-00%
Police Rejects Process Issues	Driver Unidentifiable images poor	0-00%	0-00%	2-08%	2-13%	1-11%	0-00%	0-00%	3-12%	0-00%	0-00%	8-06%	0-00%	0-00%	1-02%	0-00%	17-03%	
	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%	
Total		4-14%	0-00%	4-16%	2-13%	1-11%	0-00%	1-02%	3-12%	0-00%	0-00%	18-14%	8-11%	9-17%	2-04%	12-15%	64-10%	
Approved Violations		24-86%	35-100%	21-84%	13-87%	8-89%	7-100%	55-98%	23-88%	37-100%	25-100%	114-86%	66-89%	45-83%	54-96%	70-85%	597-90%	
Total Notices Printed		24-86%	35-100%	21-84%	13-87%	8-89%	7-100%	55-98%	23-88%	37-100%	25-100%	114-86%	66-89%	45-83%	54-96%	70-85%	597-90%	

Generated By: KNAVARRO

Generated On: 6/4/2013 10:51:05 AM

Customer Management Report (Escondido) All Detection Types

01-Oct-2008 to 31-Oct-2008

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL	
Total Processed Incidents		44	42	31	22	8	4	156	38	52	46	246	142	57	89	153	1130	
Less Uncontrollable Factors																		
Obstruction	Driver Obstruction/Duckers	2	5	0	0	1	0	1	2	5	2	0	8	0	8	6	40	
	Motor Cycle Helmet	0	0	0	0	0	0	1	0	0	0	1	1	0	0	2	5	
	Plate Obstruction	1	0	0	0	1	0	5	2	4	0	0	12	3	1	2	31	
	Vehicle Obstruction	0	3	0	0	0	0	0	0	0	2	0	0	4	17	2	28	
Police Rejects	Emergency Vehicle Responding	0	0	2	0	0	0	3	0	0	1	0	2	1	0	2	11	
	Face Obstruction	0	0	0	0	0	0	0	3	0	0	1	0	0	0	1	5	
	Incorrect Plate on Vehicle	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1	
	Incorrect/Incomplete DMV	0	2	0	0	0	0	0	0	0	0	0	1	0	0	0	4	
	Invalid Offense	0	0	0	0	1	0	0	0	1	0	0	0	0	0	0	2	
	Police Discretion	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	1	3
	Safe Turn On Red	1	0	8	0	0	0	12	0	1	0	65	6	0	0	15	108	
Policy/Weather	Extended Vehicle	0	0	1	0	0	0	0	0	0	0	0	1	0	3	0	5	
	Sun Glare	7	3	4	0	0	1	9	0	3	1	9	3	4	6	0	50	
Registration Issues	Out of Country Plate	0	0	0	0	0	0	2	0	1	0	3	0	0	0	1	7	
	Paper Plates	1	1	0	0	0	0	7	2	2	2	8	2	3	3	3	34	
	Wrong or No DMV	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
Total		13	15	15	0	3	1	40	9	17	8	87	37	15	39	36	335	
Sub Total Violations		31	27	16	22	5	3	116	29	35	38	159	105	42	50	117	795	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution		31	27	16	22	5	3	116	29	35	38	159	105	42	50	117	795	
Less Rejects																		
Camera Malfunction	Digital Distortion	0-00%	0-00%	2-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	3-00%	
	Face Not in Frame	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	2-00%	

Generated By: KNAVARRO

Generated On: 6/4/2013 10:51:46 AM

Customer Management Report (Escondido) All Detection Types

01-Oct-2008 to 31-Oct-2008

Operator Id: %

	ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	0-00%	13-08%	1-01%	0-00%	0-00%	0-00%	16-02%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
Police Rejects																
Driver Unidentifiable images poor	0-00%	2-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	3-06%	0-00%	6-01%
No Video	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Unclear Scene Image	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues																
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	1-03%	3-11%	2-12%	0-00%	0-00%	0-00%	0-00%	3-10%	2-06%	0-00%	15-09%	2-02%	2-05%	4-08%	0-00%	34-04%
Approved Violations	30-97%	24-89%	14-88%	22-100%	5-100%	3-100%	116-100%	26-90%	33-94%	38-100%	144-91%	103-98%	40-95%	46-92%	117-100%	761-96%
Total Notices Printed	30-97%	24-89%	14-88%	22-100%	5-100%	3-100%	116-100%	26-90%	33-94%	38-100%	144-91%	103-98%	40-95%	46-92%	117-100%	761-96%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:51:46 AM

Customer Management Report (Escondido) All Detection Types

01-Apr-2009 to 30-Apr-2009

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents		37	19	46	15	19	3	106	33	46	29	202	107	40	92	120	914
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	3	6	1	2	2	1	5	3	6	2	8	7	2	15	2	65
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	3	0	0	0	1	4
	Plate Obstruction	3	0	1	0	0	0	2	1	2	1	4	3	1	0	2	20
	Vehicle Obstruction	0	1	0	0	0	0	0	0	0	1	2	0	1	9	0	14
Police Rejects	Emergency Vehicle Responding	3	0	2	0	1	1	2	0	0	0	0	2	1	2	2	16
	Incorrect/Incomplete DMV	0	0	0	0	0	0	2	0	0	0	1	1	1	1	0	6
	Multiple vehicles in frame	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Police Discretion	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1	2
	Safe Turn On Red	0	0	9	0	0	0	8	0	0	0	56	12	0	0	7	92
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	0	0	0	0	0	2	0	1	0	3
	Sun Glare	10	2	5	0	3	0	11	2	11	2	34	11	6	14	6	117
Registration Issues	Out of Country Plate	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
	Paper Plates	2	1	0	1	0	0	4	0	0	0	10	2	1	1	1	23
	Wrong or No DMV	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Total		21	11	18	3	6	2	35	6	19	6	119	40	13	44	22	365
Sub Total Violations		16	8	28	12	13	1	71	27	27	23	83	67	27	48	98	549
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		16	8	28	12	13	1	71	27	27	23	83	67	27	48	98	549
Less Rejects																	
Camera Malfunction	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	2-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Image Missing	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:52:29 AM

Customer Management Report (Escondido) All Detection Types

01-Apr-2009 to 30-Apr-2009

Operator Id: %

		ESC-02ES-01	ESC-AUVVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total		0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	3-11%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	5-01%
Approved Violations		16-100%	8-100%	27-96%	12-100%	13-100%	1-100%	71-100%	27-100%	24-89%	23-100%	83-100%	67-100%	27-100%	47-98%	98-100%	544-99%
Total Notices Printed		16-100%	8-100%	27-96%	12-100%	13-100%	1-100%	71-100%	27-100%	24-89%	23-100%	83-100%	67-100%	27-100%	47-98%	98-100%	544-99%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:52:29 AM

Customer Management Report (Escondido) All Detection Types

01-Oct-2009 to 31-Oct-2009

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents		39	25	46	11	21	6	125	32	37	41	157	119	44	102	105	910
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	4	2	2	0	2	0	5	6	1	1	4	12	3	12	9	63
	Motor Cycle Helmet	0	0	0	0	0	0	1	0	0	0	2	1	1	0	0	5
	Plate Obstruction	0	0	1	1	0	0	2	5	1	0	1	2	3	1	0	17
	Vehicle Obstruction	1	3	0	0	1	0	1	0	0	1	2	0	2	7	0	18
Police Rejects	Emergency Vehicle Responding	0	2	2	0	0	1	1	0	4	4	0	4	2	0	0	20
	Incorrect/Incomplete DMV	0	0	1	0	1	0	1	1	0	0	0	0	0	1	1	6
	Multiple vehicles in frame	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	1
	Police Discretion	0	0	0	0	2	0	0	0	2	0	2	1	0	1	3	11
	Safe Turn On Red	2	0	13	0	0	0	13	0	0	0	48	13	0	1	9	99
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	0	0	0	0	1	0	1	2	1	5
	Sun Glare	3	2	2	0	1	0	11	0	1	1	10	10	1	7	4	53
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1
	Out of Country Plate	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
	Paper Plates	0	0	4	0	0	0	2	0	0	2	7	2	0	1	4	22
	Wrong or No DMV	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1	2
Total		10	9	25	1	7	1	38	12	10	9	77	45	13	34	33	324
Sub Total Violations		29	16	21	10	14	5	87	20	27	32	80	74	31	68	72	586
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		29	16	21	10	14	5	87	20	27	32	80	74	31	68	72	586
Less Rejects																	
Camera Malfunction	Face Camera Focus Blurry	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:53:40 AM

Customer Management Report (Escondido) All Detection Types

01-Oct-2009 to 31-Oct-2009

Operator Id: %

	ESC-02ES-01	ESC-AUVVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects Driver Unidentifiable images poor	1-03%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Total	2-07%	1-06%	0-00%	1-10%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	6-01%
Approved Violations	27-93%	15-94%	21-100%	9-90%	13-93%	5-100%	87-100%	20-100%	27-100%	32-100%	80-100%	73-99%	31-100%	68-100%	72-100%	580-99%
Total Notices Printed	27-93%	15-94%	21-100%	9-90%	13-93%	5-100%	87-100%	20-100%	27-100%	32-100%	80-100%	73-99%	31-100%	68-100%	72-100%	580-99%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:53:40 AM

Customer Management Report (Escondido) All Detection Types

01-Oct-2010 to 31-Oct-2010

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents		62	14	42	12	11	7	113	30	61	50	88	127	37	30	124	808
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	5	1	0	1	0	0	1	5	7	1	0	5	2	3	5	36
	Plate Obstruction	3	0	1	0	1	1	2	0	3	0	2	4	5	0	0	22
	Vehicle Obstruction	1	2	0	0	0	1	0	0	1	3	0	0	1	4	1	14
Police Rejects	Emergency Vehicle Responding	2	1	2	0	0	1	1	1	2	0	1	1	1	0	1	14
	Face Obstruction	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
	Incorrect/Incomplete DMV	0	0	0	1	0	0	0	0	0	1	0	0	0	0	0	2
	Plate Unidentifiable	1	0	0	0	0	0	0	0	0	0	0	0	0	0	2	3
	Safe Turn On Red	3	0	13	0	0	0	13	0	0	0	25	14	0	0	4	72
Policy/Weather	Extended Vehicle	1	0	0	0	0	0	0	0	1	0	0	0	0	0	0	2
	Sun Glare	4	1	0	0	7	0	6	1	4	3	5	8	2	5	2	48
	Weather/Nature	1	0	0	0	0	0	3	0	1	1	0	2	0	0	1	9
Registration Issues	Out of Country Plate	0	0	0	0	0	0	1	0	0	0	0	0	0	1	0	2
	Paper Plates	2	0	0	0	0	0	0	1	0	0	3	3	0	2	1	12
Total		23	5	16	2	8	3	27	9	19	9	36	37	11	15	17	237
Sub Total Violations		39	9	26	10	3	4	86	21	42	41	52	90	26	15	107	571
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		39	9	26	10	3	4	86	21	42	41	52	90	26	15	107	571
Less Rejects																	
Camera Malfunction	Face Camera Focus Blurry	1-03%	0-00%	0-00%	0-00%	1-33%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-01%	2-00%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
Total		1-03%	0-00%	0-00%	0-00%	1-33%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	2-02%	0-00%	0-00%	1-01%	6-01%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:54:46 AM

Customer Management Report (Escondido) All Detection Types

01-Oct-2010 to 31-Oct-2010

Operator Id: %

	ESC-02ES-01	ESC-AUVVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Approved Violations	38-97%	9-100%	26-100%	10-100%	2-67%	4-100%	86-100%	21-100%	41-98%	41-100%	52-100%	88-98%	26-100%	15-100%	106-99%	565-99%
Total Notices Printed	38-97%	9-100%	26-100%	10-100%	2-67%	4-100%	86-100%	21-100%	41-98%	41-100%	52-100%	88-98%	26-100%	15-100%	106-99%	565-99%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:54:46 AM

Customer Management Report (Escondido) All Detection Types

01-Feb-2011 to 28-Feb-2011

Operator Id: %

		ESC-02ES-01	ESC-AUVVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents		62	9	28	10	9	3	110	34	80	5	79	71	37	16	91	644
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	2	0	3	0	1	1	4	6	3	0	0	6	0	2	1	29
	Plate Obstruction	2	0	0	1	0	0	2	1	7	0	0	3	2	0	0	18
	Vehicle Obstruction	0	0	0	0	0	0	0	0	0	0	1	0	2	4	2	9
Police Rejects	Emergency Vehicle Responding	3	1	0	0	0	0	0	1	2	0	0	0	0	0	1	8
	Face Obstruction	1	0	0	0	0	0	0	1	0	0	0	1	0	0	0	3
	Incorrect Plate on Vehicle	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1
	Incorrect/Incomplete DMV	13	3	5	3	1	1	25	6	21	0	11	14	8	3	20	134
	Police Discretion	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	2
	Safe Turn On Red	2	0	9	0	0	0	17	0	0	0	20	14	0	0	3	65
	Sun Glare	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1
	Total	29	4	18	4	4	2	64	17	41	0	39	43	17	12	32	326
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1
	Sun Glare	6	0	1	0	2	0	10	1	3	0	5	3	1	3	1	36
	Weather/Nature	0	0	0	0	0	0	1	0	0	0	0	0	1	0	0	2
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
	Out of Country Plate	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1	2
	Paper Plates	0	0	0	0	0	0	3	0	3	0	2	1	2	0	2	13
	Wrong or No DMV	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
Sub Total Violations		33	5	10	6	5	1	46	17	39	5	40	28	20	4	59	318
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		33	5	10	6	5	1	46	17	39	5	40	28	20	4	59	318

Less Rejects

Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	1-20%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
--------------------	--------------------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------

Generated By: KNAVARRO

Generated On: 6/4/2013 10:56:08 AM

Customer Management Report (Escondido) All Detection Types

01-Feb-2011 to 28-Feb-2011

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Maintenance	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	7-25%	0-00%	0-00%	0-00%	8-03%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-07%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	4-01%
	Insufficient Strobe Lighting	0-00%	0-00%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-05%	0-00%	0-00%	2-01%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-08%	0-00%	0-00%	0-00%	0-00%	3-01%
Process Issues	Too Old	2-06%	0-00%	2-20%	0-00%	0-00%	0-00%	5-11%	0-00%	2-05%	1-20%	2-05%	0-00%	2-10%	1-25%	3-05%	20-06%
Total		2-06%	0-00%	2-20%	1-17%	1-20%	0-00%	9-20%	0-00%	3-08%	1-20%	6-15%	10-36%	3-15%	1-25%	3-05%	42-13%
Approved Violations		31-94%	5-100%	8-80%	5-83%	4-80%	1-100%	37-80%	17-100%	36-92%	4-80%	34-85%	18-64%	17-85%	3-75%	56-95%	276-87%
Total Notices Printed		31-94%	5-100%	8-80%	5-83%	4-80%	1-100%	37-80%	17-100%	36-92%	4-80%	34-85%	18-64%	17-85%	3-75%	56-95%	276-87%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:56:08 AM

Customer Management Report (Escondido) All Detection Types

01-Mar-2011 to 31-Mar-2011

Operator Id: %

	ESC-02ES-01	ESC-AUVVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL	
Total Processed Incidents	36	10	70	11	12	19	88	38	83	31	110	113	21	39	105	786	
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	2	1	1	0	0	3	2	8	5	1	2	5	1	8	2	41
	Motor Cycle Helmet	0	0	0	0	0	0	0	1	0	1	1	0	0	0	0	3
	Plate Obstruction	3	0	1	1	1	0	3	2	5	0	0	8	3	0	2	29
	Vehicle Obstruction	0	1	1	0	0	0	1	0	0	0	0	0	0	7	0	10
Police Rejects	Emergency Vehicle Responding	1	0	1	0	0	1	1	0	0	1	0	0	1	1	2	9
	Face Obstruction	0	0	0	0	0	0	1	0	0	0	0	0	1	1	0	3
	Incorrect Plate on Vehicle	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1	2
	Incorrect/Incomplete DMV	8	0	3	4	1	0	21	10	14	3	10	17	2	2	21	116
	Invalid Offense	0	1	6	0	0	9	1	0	1	14	3	3	0	0	4	42
	Police Discretion	1	1	1	0	1	1	0	0	0	3	0	0	0	0	0	8
	Safe Turn On Red	1	0	36	0	0	0	16	0	0	0	50	27	0	0	2	132
	Sun Glare	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	2
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1
	Sun Glare	1	1	1	0	3	2	6	1	2	1	3	9	2	5	2	39
	Weather/Nature	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Registration Issues	Can Not Identify State	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
	Paper Plates	1	0	1	0	0	1	2	0	3	2	9	1	0	1	3	24
	Wrong or No DMV	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
Total		18	5	54	5	6	17	55	22	33	26	79	70	10	25	39	464
Sub Total Violations		18	5	16	6	6	2	33	16	50	5	31	43	11	14	66	322
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		18	5	16	6	6	2	33	16	50	5	31	43	11	14	66	322

Less Rejects

Generated By: KNAVARRO

Generated On: 6/4/2013 10:56:58 AM

Customer Management Report (Escondido) All Detection Types

01-Mar-2011 to 31-Mar-2011

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	2-01%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-02%	0-00%	0-00%	0-00%	2-01%
	Rear Plate Camera Blurry	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	3-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	1-20%	0-00%	1-17%	0-00%	1-50%	1-03%	0-00%	2-04%	1-20%	0-00%	2-05%	0-00%	0-00%	0-00%	9-03%
	Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	0-00%	0-00%	1-20%	1-03%	1-02%	0-00%	0-00%	0-00%	5-02%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-00%
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-09%	0-00%	6-12%	0-00%	1-03%	1-02%	0-00%	0-00%	2-03%	13-04%
Total		1-06%	1-20%	0-00%	1-17%	0-00%	1-50%	7-21%	0-00%	10-20%	2-40%	3-10%	9-21%	0-00%	1-07%	3-05%	39-12%
Approved Violations		17-94%	4-80%	16-100%	5-83%	6-100%	1-50%	26-79%	16-100%	40-80%	3-60%	28-90%	34-79%	11-100%	13-93%	63-95%	283-88%
Total Notices Printed		17-94%	4-80%	16-100%	5-83%	6-100%	1-50%	26-79%	16-100%	40-80%	3-60%	28-90%	34-79%	11-100%	13-93%	63-95%	283-88%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:56:58 AM

Customer Management Report (Escondido) All Detection Types

01-May-2011 to 31-May-2011

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents		99	13	143	19	21	33	151	19	63	39	429	112	15	0	0	1156
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	7	1	4	0	2	3	9	6	1	1	14	8	0	0	0	56
	Motor Cycle Helmet	0	2	0	0	0	0	0	0	0	0	2	0	0	0	0	4
	Plate Obstruction	3	0	3	0	1	0	2	1	4	1	3	4	2	0	0	24
	Vehicle Obstruction	0	1	0	0	0	0	0	0	0	0	1	0	1	0	0	3
Police Rejects	Emergency Vehicle Responding	4	1	0	1	1	0	0	0	1	1	0	1	0	0	0	10
	Face Obstruction	1	0	0	0	0	0	1	0	0	0	0	0	0	0	0	2
	Incorrect/Incomplete DMV	10	1	5	1	1	2	28	4	12	0	22	10	2	0	0	98
	On or Passed the Stop Bar (PD)	5	1	21	1	4	22	11	0	1	22	69	7	0	0	0	164
	Safe Turn On Red	11	0	66	0	0	0	19	0	0	0	155	10	0	0	0	261
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
	Sun Glare	26	3	15	1	4	1	19	0	5	6	48	22	3	0	0	153
	Weather/Nature	0	0	0	0	0	0	0	0	0	0	7	1	0	0	0	8
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	1	0	0	1	0	0	0	2
	Out of Country Plate	0	0	0	0	0	0	1	0	0	1	0	0	0	0	0	2
	Paper Plates	1	0	7	1	0	0	2	0	3	1	14	1	0	0	0	30
	Wrong or No DMV	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Total		68	10	121	5	13	28	93	11	28	33	336	65	8	0	0	819
Sub Total Violations		31	3	22	14	8	5	58	8	35	6	93	47	7	0	0	337
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		31	3	22	14	8	5	58	8	35	6	93	47	7	0	0	337
Less Rejects																	
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-03%	1-02%	0-00%	0-00%	0-00%	4-01%
	Face Camera Focus Blurry	1-03%	0-00%	1-05%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:57:43 AM

Customer Management Report (Escondido) All Detection Types

01-May-2011 to 31-May-2011

Operator Id: %

	ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-14%	0-00%	0-00%	1-00%
Police Rejects																
Driver Unidentifiable images poor	6-19%	0-00%	2-09%	0-00%	0-00%	3-60%	3-05%	0-00%	0-00%	1-17%	28-30%	3-06%	2-29%	0-00%	0-00%	48-14%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	2-01%
Process Issues																
Too Old	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-02%	0-00%	0-00%	0-00%	3-01%
Total	7-23%	0-00%	4-18%	0-00%	1-12%	3-60%	4-07%	0-00%	0-00%	1-17%	33-35%	5-11%	3-43%	0-00%	0-00%	61-18%
Approved Violations	24-77%	3-100%	18-82%	14-100%	7-88%	2-40%	54-93%	8-100%	35-100%	5-83%	60-65%	42-89%	4-57%	0-00%	0-00%	276-82%
Total Notices Printed	24-77%	3-100%	18-82%	14-100%	7-88%	2-40%	54-93%	8-100%	35-100%	5-83%	60-65%	42-89%	4-57%	0-00%	0-00%	276-82%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:57:43 AM

Customer Management Report (Escondido) All Detection Types

01-Jun-2011 to 30-Jun-2011

Operator Id: %

	ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL	
Total Processed Incidents	114	22	156	17	39	49	131	26	64	52	361	116	25	26	139	1337	
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	3	1	8	0	1	1	3	2	8	0	11	6	2	19	7	72
	Motor Cycle Helmet	0	0	0	0	1	0	1	0	0	2	1	1	0	0	1	7
	Plate Obstruction	3	0	6	0	6	3	5	1	3	0	3	4	1	0	5	40
	Vehicle Obstruction	0	0	0	0	1	0	0	0	0	0	4	1	1	0	0	7
Police Rejects	Citation Issued manually	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Emergency Vehicle Responding	3	1	1	0	0	2	0	0	1	0	0	0	0	0	1	9
	Face Obstruction	0	0	1	0	0	0	0	1	0	0	0	1	0	0	0	3
	Funeral Procession/Police	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
	Incorrect/Incomplete DMV	11	1	6	4	2	0	33	3	13	2	26	13	1	1	27	143
	Invalid Offense	0	0	0	0	0	0	0	0	0	0	4	0	0	0	0	4
	On or Passed the Stop Bar (PD).	1	5	6	1	11	33	3	1	0	43	3	5	2	0	5	119
	Police Discretion	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2	2
	Safe Turn On Red	19	0	92	0	0	0	33	0	0	0	200	18	0	0	3	365
	Sun Glare	1	0	0	0	1	0	0	0	0	0	1	0	1	0	0	4
	Yielding to an Emergency	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
	Sun Glare	30	7	6	0	8	3	11	3	5	1	27	18	3	2	16	140
	Weather/Nature	0	0	0	0	0	0	0	0	0	0	3	0	0	0	0	3
Registration Issues	Out of Country Plate	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1	2
	Paper Plates	1	0	4	1	0	0	4	1	2	1	12	1	0	0	6	33
Total		73	15	130	6	31	42	94	12	32	49	297	69	11	22	74	957
Sub Total Violations		41	7	26	11	8	7	37	14	32	3	64	47	14	4	65	380
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Generated By: KNAVARRO

Generated On: 6/4/2013 10:58:22 AM

Customer Management Report (Escondido) All Detection Types

01-Jun-2011 to 30-Jun-2011

Operator Id: %

	ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL	
Available For Prosecution	41	7	26	11	8	7	37	14	32	3	64	47	14	4	65	380	
Less Rejects																	
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	2-01%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	8-20%	1-14%	1-04%	2-18%	0-00%	1-14%	0-00%	0-00%	3-09%	0-00%	7-11%	4-09%	4-29%	0-00%	3-05%	34-09%
	Red-light not visible in	0-00%	1-14%	0-00%	0-00%	1-12%	1-14%	0-00%	1-07%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	5-01%
Total		8-20%	2-29%	1-04%	2-18%	2-25%	2-29%	0-00%	1-07%	4-12%	0-00%	8-12%	6-13%	4-29%	0-00%	3-05%	43-11%
Approved Violations		33-80%	5-71%	25-96%	9-82%	6-75%	5-71%	37-100%	13-93%	28-88%	3-100%	56-88%	41-87%	10-71%	4-100%	62-95%	337-89%
Total Notices Printed		33-80%	5-71%	25-96%	9-82%	6-75%	5-71%	37-100%	13-93%	28-88%	3-100%	56-88%	41-87%	10-71%	4-100%	62-95%	337-89%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:58:22 AM

Customer Management Report (Escondido) All Detection Types

01-Jan-2013 to 31-Jan-2013

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents		128	25	148	21	44	55	117	30	44	24	122	125	39	74	102	1098
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	2	2	2	0	4	1	1	5	1	0	4	8	0	16	3	49
	Motor Cycle Helmet	0	0	0	0	1	0	0	0	0	1	0	0	0	2	0	4
	Plate Obstruction	0	1	0	0	1	0	1	1	2	0	2	3	3	0	1	15
	Signal Obstruction	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Vehicle Obstruction	0	0	0	0	0	0	0	0	1	0	1	0	0	2	0	4
Police Rejects	Emergency Vehicle Responding	0	1	3	3	0	2	5	0	2	2	0	0	2	0	2	22
	Face Obstruction	2	0	0	1	1	1	0	7	0	0	2	1	0	1	4	20
	Invalid Offense	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
	On or Passed the Stop Bar (PD).	12	3	19	0	12	36	8	0	3	13	8	11	12	0	3	140
	Police Discretion	4	3	4	0	0	3	6	0	1	0	1	9	0	6	5	42
	Safe Turn On Red	41	0	75	0	2	0	15	0	0	0	53	15	0	0	0	201
	Sun Glare	2	0	2	1	0	0	1	0	0	0	1	3	0	1	1	12
Policy/Weather	Extended Vehicle	1	0	0	0	0	0	0	0	1	0	4	2	0	5	0	13
	Sun Glare	5	0	0	0	8	0	6	1	3	0	0	7	1	5	0	36
Registration Issues	Paper Plates	3	0	6	2	1	2	8	0	1	0	6	2	0	1	3	35
	Wrong or No DMV	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
Total		72	11	112	7	30	45	51	14	15	16	83	61	18	39	22	596
Sub Total Violations		56	14	36	14	14	10	66	16	29	8	39	64	21	35	80	502
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		56	14	36	14	14	10	66	16	29	8	39	64	21	35	80	502
Less Rejects																	
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera Focus Blurry	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	3-01%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:59:26 AM

Customer Management Report (Escondido) All Detection Types

01-Jan-2013 to 31-Jan-2013

Operator Id: %

	ESC-02ES-01	ESC-AUVVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Face Not in Frame	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Image Missing	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	3-01%
Police Rejects Process Issues																
Red-light not visible in	0-00%	2-14%	0-00%	0-00%	0-00%	1-10%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	2-04%	3-21%	0-00%	0-00%	1-07%	2-20%	1-02%	2-12%	0-00%	0-00%	1-03%	4-06%	0-00%	0-00%	0-00%	16-03%
Approved Violations	54-96%	11-79%	36-100%	14-100%	13-93%	8-80%	65-98%	14-88%	29-100%	8-100%	38-97%	60-94%	21-100%	35-100%	80-100%	486-97%
Total Notices Printed	54-96%	11-79%	36-100%	14-100%	13-93%	8-80%	65-98%	14-88%	29-100%	8-100%	38-97%	60-94%	21-100%	35-100%	80-100%	486-97%

Generated By: KNAVARRO

Generated On: 6/4/2013 10:59:26 AM

Customer Management Report (Escondido) All Detection Types

01-Feb-2013 to 28-Feb-2013

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents		136	23	133	17	37	35	94	38	37	30	175	116	24	55	111	1061
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	5	3	1	0	1	1	0	3	3	1	3	7	1	11	1	41
	Motor Cycle Helmet	0	0	0	0	0	0	1	0	0	2	0	0	0	0	0	3
	Plate Obstruction	0	0	3	0	0	1	1	1	0	0	1	4	1	1	3	16
	Vehicle Obstruction	0	1	2	0	0	0	0	1	0	0	2	0	0	0	0	6
Police Rejects	Emergency Vehicle Responding	5	0	2	2	1	3	2	0	3	1	0	2	1	0	1	23
	Face Obstruction	2	1	0	0	1	0	4	2	2	0	3	2	2	2	3	24
	On or Passed the Stop Bar (PD).	8	0	17	2	13	20	1	1	3	18	12	14	9	1	6	125
	Police Discretion	1	4	1	0	1	1	5	1	2	1	14	6	1	1	15	54
	Safe Turn On Red	52	0	87	0	5	1	17	0	0	0	80	25	0	0	3	270
	Sun Glare	3	1	0	0	0	0	0	0	0	0	0	3	0	1	0	8
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	0	0	0	0	0	1	0	1	1	3
	Sun Glare	7	1	0	1	9	2	3	1	0	0	1	4	0	7	1	37
	Weather/Nature	1	0	0	0	0	0	0	0	0	0	0	2	0	0	0	3
Registration Issues	Paper Plates	1	2	2	0	0	0	1	1	0	0	15	3	1	0	0	26
	Wrong or No DMV	0	0	0	0	0	1	0	0	1	0	0	0	0	0	0	2
Total		85	13	115	5	31	30	35	11	14	23	131	73	16	25	34	641
Sub Total Violations		51	10	18	12	6	5	59	27	23	7	44	43	8	30	77	420
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		51	10	18	12	6	5	59	27	23	7	44	43	8	30	77	420
Less Rejects																	
Camera Malfunction	Face Not in Frame	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: KNAVARRO

Generated On: 6/4/2013 11:00:30 AM

Customer Management Report (Escondido) All Detection Types

01-Feb-2013 to 28-Feb-2013

Operator Id: %

	ESC-02ES-01	ESC-AUVVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-05%	0-00%	1-12%	0-00%	0-00%	4-01%
Police Rejects																
Driver Unidentifiable images poor	0-00%	1-10%	0-00%	0-00%	1-17%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	5-01%
Red-light not visible in	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-07%	0-00%	0-00%	0-00%	0-00%	3-01%
Total	1-02%	2-20%	0-00%	1-08%	1-17%	0-00%	0-00%	1-04%	0-00%	0-00%	7-16%	2-05%	1-12%	0-00%	0-00%	16-04%
Approved Violations	50-98%	8-80%	18-100%	11-92%	5-83%	5-100%	59-100%	26-96%	23-100%	7-100%	37-84%	41-95%	7-88%	30-100%	77-100%	404-96%
Total Notices Printed	50-98%	8-80%	18-100%	11-92%	5-83%	5-100%	59-100%	26-96%	23-100%	7-100%	37-84%	41-95%	7-88%	30-100%	77-100%	404-96%

Generated By: KNAVARRO

Generated On: 6/4/2013 11:00:30 AM

Customer Management Report (Escondido) All Detection Types

01-Mar-2013 to 31-Mar-2013

Operator Id: %

	ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL	
Total Processed Incidents	141	24	148	18	46	39	121	42	22	41	159	133	50	80	172	1236	
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	3	3	3	0	1	2	2	5	1	3	1	2	0	14	1	41
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	4	2	0	0	1	2	9	
	Plate Obstruction	1	1	0	0	1	4	0	0	0	2	6	3	0	1	19	
	Vehicle Obstruction	0	2	0	0	0	1	0	1	0	2	0	1	3	1	11	
Police Rejects	Emergency Vehicle Responding	4	1	1	0	2	2	1	0	0	0	0	1	0	3	15	
	Face Obstruction	2	0	0	1	1	0	3	0	0	0	2	0	0	2	11	
	Invalid Offense	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1	
	Multiple vehicles in frame	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1	
	On or Passed the Stop Bar (PD).	10	7	35	1	14	29	6	1	24	13	13	21	4	5	183	
	Plate Unidentifiable	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
	Police Discretion	1	0	0	0	0	5	1	1	0	3	5	0	1	21	38	
	Safe Turn On Red	39	0	86	0	0	25	0	0	0	73	26	1	0	2	252	
	Sun Glare	1	0	0	0	0	1	0	0	0	0	0	1	1	0	4	
	Yielding to an Emergency	2	0	0	0	0	0	0	0	0	0	0	0	0	0	2	
Policy/Weather	Extended Vehicle	2	0	0	0	0	0	0	1	0	2	1	0	1	1	8	
	Sun Glare	11	1	1	0	13	1	13	3	0	1	13	14	4	16	97	
	Weather/Nature	0	1	1	0	0	0	1	0	0	1	1	1	0	0	6	
Registration Issues	Out of Country Plate	0	0	1	0	1	0	0	0	0	0	0	0	0	0	2	
	Paper Plates	4	1	3	0	0	1	1	0	0	5	3	0	3	1	22	
	Wrong or No DMV	0	0	0	0	1	0	1	0	0	0	0	0	0	0	2	
Total		81	17	131	2	34	34	60	14	5	32	117	74	33	44	725	
Sub Total Violations		60	7	17	16	12	5	61	28	17	9	42	59	17	36	511	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	

Generated By: KNAVARRO

Generated On: 6/4/2013 11:01:41 AM

Customer Management Report (Escondido) All Detection Types

01-Mar-2013 to 31-Mar-2013

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Available For Prosecution		60	7	17	16	12	5	61	28	17	9	42	59	17	36	125	511
Less Rejects																	
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-14%	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	0-00%	6-01%
	Face Not in Frame	3-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-14%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-01%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-04%	0-00%	0-00%	3-07%	0-00%	0-00%	0-00%	0-00%	5-01%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-02%	0-00%	0-00%	0-00%	2-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Flash Inappropriate	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	3-01%
Police Rejects	Driver Unidentifiable images poor	2-03%	1-14%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-02%	2-03%	0-00%	1-03%	0-00%	8-02%
	Red-light not visible in	0-00%	1-14%	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Total		7-12%	2-29%	0-00%	0-00%	0-00%	0-00%	2-03%	11-39%	1-06%	0-00%	9-21%	4-07%	0-00%	1-03%	0-00%	37-07%
Approved Violations		53-88%	5-71%	17-100%	16-100%	12-100%	5-100%	59-97%	17-61%	16-94%	9-100%	33-79%	55-93%	17-100%	35-97%	125-100%	474-93%
Total Notices Printed		53-88%	5-71%	17-100%	16-100%	12-100%	5-100%	59-97%	17-61%	16-94%	9-100%	33-79%	55-93%	17-100%	35-97%	125-100%	474-93%

Generated By: KNAVARRO

Generated On: 6/4/2013 11:01:41 AM

Customer Management Report (Escondido) All Detection Types

01-Apr-2013 to 30-Apr-2013

Operator Id: %

	ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents	117	33	159	16	52	31	117	63	40	26	146	127	29	76	137	1169
Less Uncontrollable Factors																
Obstruction																
Driver Obstruction/Duckers	1	4	1	0	4	0	3	5	1	0	1	3	0	11	0	34
Motor Cycle Helmet	0	0	0	0	0	0	3	0	0	0	0	0	0	1	1	5
Plate Obstruction	3	0	1	0	2	0	1	1	1	1	2	4	0	2	2	20
Signal Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1
Vehicle Obstruction	2	2	0	0	0	1	0	0	0	0	1	2	0	1	0	9
Police Rejects																
Emergency Vehicle Responding	1	2	6	0	1	0	0	0	0	1	0	0	0	1	2	14
Face Obstruction	1	0	0	0	0	0	0	6	1	0	0	2	1	0	2	13
Invalid Offense	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1
Multiple vehicles in frame	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
On or Passed the Stop Bar (PD).	19	3	55	2	12	25	9	1	0	16	38	10	11	0	4	205
Plate Unidentifiable	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Police Discretion	4	1	2	1	0	0	6	0	2	0	2	5	0	3	7	33
Safe Turn On Red	24	0	69	0	1	0	20	0	0	0	42	15	0	0	1	172
Sun Glare	3	1	0	0	4	0	2	1	1	0	1	4	0	3	2	22
Policy/Weather																
Extended Vehicle	0	0	0	0	0	0	0	0	0	0	1	1	0	3	0	5
Sun Glare	12	2	0	1	7	0	3	4	1	2	7	17	1	15	6	78
Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
Registration Issues																
Out of Country Plate	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Paper Plates	4	0	4	1	2	1	2	5	3	2	11	4	1	2	2	44
Total	75	15	138	6	33	27	49	23	10	22	107	68	16	42	29	660
Sub Total Violations	42	18	21	10	19	4	68	40	30	4	39	59	13	34	108	509
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	42	18	21	10	19	4	68	40	30	4	39	59	13	34	108	509

Generated By: KNAVARRO

Generated On: 6/4/2013 11:02:18 AM

Customer Management Report (Escondido) All Detection Types

01-Apr-2013 to 30-Apr-2013

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL	
Less Rejects																		
Camera Malfunction	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	4-10%	0-00%	1-25%	1-03%	1-02%	0-00%	0-00%	1-01%	9-02%	
	Face Not in Frame	1-02%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	3-09%	0-00%	6-01%	
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%	
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	2-05%	2-07%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	3-07%	1-06%	0-00%	0-00%	1-05%	0-00%	2-03%	0-00%	1-03%	0-00%	1-03%	1-02%	0-00%	0-00%	1-01%	11-02%	
Total		4-10%	1-06%	1-05%	0-00%	2-11%	0-00%	4-06%	7-18%	3-10%	1-25%	3-08%	3-05%	0-00%	3-09%	2-02%	34-07%	
Approved Violations		38-90%	17-94%	20-95%	10-100%	17-89%	4-100%	64-94%	33-82%	27-90%	3-75%	36-92%	56-95%	13-100%	31-91%	106-98%	475-93%	
Total Notices Printed		38-90%	17-94%	20-95%	10-100%	17-89%	4-100%	64-94%	33-82%	27-90%	3-75%	36-92%	56-95%	13-100%	31-91%	106-98%	475-93%	

Generated By: KNAVARRO

Generated On: 6/4/2013 11:02:18 AM

Customer Management Report (Escondido) All Detection Types

01-May-2013 to 31-May-2013

Operator Id: %

	ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents	155	45	148	23	50	35	133	54	59	47	254	137	60	56	167	1423
Less Uncontrollable Factors																
Obstruction	Driver Obstruction/Duckers	3	2	2	0	0	4	6	1	0	2	3	1	7	3	34
	Motor Cycle Helmet	0	0	0	0	1	3	1	0	4	1	1	0	5	0	16
	Plate Obstruction	3	1	1	0	0	2	4	1	0	2	2	3	1	0	20
	Vehicle Obstruction	0	2	0	0	0	0	0	0	0	3	2	0	1	1	9
Police Rejects	Emergency Vehicle Responding	8	3	4	2	1	1	1	1	1	1	0	2	1	0	26
	Face Obstruction	2	1	2	1	0	2	3	1	0	1	2	1	1	3	20
	Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
	Invalid Offense	0	0	0	0	0	1	0	0	0	1	0	0	0	0	2
	Multiple vehicles in frame	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	On or Passed the Stop Bar (PD).	27	9	54	1	20	4	2	1	28	64	9	18	2	8	276
	Plate Obstruction (PD)	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Police Discretion	2	2	0	0	0	2	1	4	1	5	1	0	0	6	24
	Safe Turn On Red	27	1	50	1	0	19	0	0	3	64	14	1	0	2	182
	Sun Glare	6	2	1	0	0	5	1	4	0	5	6	3	0	4	37
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	1	0	0	1	1	2	0	0	5
	Sun Glare	17	4	6	2	13	13	4	8	2	22	29	7	14	14	157
	Yellow with Red Light	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Registration Issues	Out of Country Plate	0	0	0	0	0	0	0	0	0	2	0	0	0	0	2
	Paper Plates	3	1	3	2	2	7	0	2	2	15	4	0	3	5	50
	Wrong or No DMV	0	0	0	0	0	0	0	0	0	1	1	0	0	0	2
Total		100	28	123	9	36	63	24	23	41	192	75	38	35	46	866
Sub Total Violations		55	17	25	14	14	70	30	36	6	62	62	22	21	121	557
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Generated By: KNAVARRO

Generated On: 6/4/2013 11:03:02 AM

Customer Management Report (Escondido) All Detection Types

01-May-2013 to 31-May-2013

Operator Id: %

		ESC-02ES-01	ESC-AUVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAALU-01	ESC-VAALU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Available For Prosecution		55	17	25	14	14	2	70	30	36	6	62	62	22	21	121	557
Less Rejects																	
Camera Malfunction	Face Not in Frame	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-05%	0-00%	3-01%
	Misc Camera Issue	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	2-00%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-09%	0-00%	1-01%	5-01%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	3-01%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	1-01%	2-07%	1-03%	0-00%	1-02%	0-00%	1-05%	0-00%	1-01%	8-01%
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	2-03%	4-06%	0-00%	0-00%	1-01%	9-02%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
Total		2-04%	0-00%	0-00%	0-00%	3-21%	0-00%	4-06%	2-07%	1-03%	0-00%	4-06%	8-13%	3-14%	1-05%	3-02%	31-06%
Approved Violations		53-96%	17-100%	25-100%	14-100%	11-79%	2-100%	66-94%	28-93%	35-97%	6-100%	58-94%	54-87%	19-86%	20-95%	118-98%	526-94%
Total Notices Printed		53-96%	17-100%	25-100%	14-100%	11-79%	2-100%	66-94%	28-93%	35-97%	6-100%	58-94%	54-87%	19-86%	20-95%	118-98%	526-94%

Generated By: KNAVARRO

Generated On: 6/4/2013 11:03:02 AM

Customer Management Report (Escondido) All Detection Types

01-Jun-2013 to 04-Jun-2013

Operator Id: %

		ESC-02ES-01	ESC-AUVVA-01	ESC-CCVP-01	ESC-ES02-01	ESC-ESVA-01	ESC-JUSE-01	ESC-LIFI-01	ESC-LIFI-03	ESC-SEJU-01	ESC-VAAU-01	ESC-VAAU-03	ESC-VAES-01	ESC-VPCC-01	ESC-WVTU-01	ESC-WVTU-03	TOTAL
Total Processed Incidents		18	5	15	4	10	6	23	4	8	8	17	13	3	6	14	154
Less Uncontrollable Factors																	
Obstruction	Driver Obstruction/Duckers	0	0	0	0	0	0	0	0	1	1	0	0	1	0	1	4
	Plate Obstruction	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
	Vehicle Obstruction	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Police Rejects	On or Passed the Stop Bar (PD).	1	1	2	0	2	1	0	0	0	0	0	0	0	0	1	8
	Police Discretion	0	0	0	0	0	1	0	1	0	0	0	0	0	0	0	2
	Safe Turn On Red	3	0	1	0	0	0	3	0	0	0	2	0	0	0	0	9
	Sun Glare	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Policy/Weather	Sun Glare	1	0	0	0	0	0	2	0	0	0	0	0	0	1	1	5
Registration Issues	Out of Country Plate	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
	Paper Plates	0	0	1	0	0	0	0	0	0	0	1	0	0	0	0	2
Total		6	1	4	1	2	2	6	1	1	1	3	1	1	1	3	34
Sub Total Violations		12	4	11	3	8	4	17	3	7	7	14	12	2	5	11	120
Less in Progress		11	4	11	1	8	3	15	3	5	3	11	10	1	4	8	98
Available For Prosecution		1	0	0	2	0	1	2	0	2	4	3	2	1	1	3	22
Less Rejects																	
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-33%	0-00%	0-00%	0-00%	0-00%	1-05%
Total		0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-33%	0-00%	0-00%	0-00%	0-00%	1-05%
Approved Violations		1-100%	0-00%	0-00%	2-100%	0-00%	1-100%	2-100%	0-00%	2-100%	4-100%	2-67%	2-100%	1-100%	1-100%	3-100%	21-95%
Total Notices Printed		1-100%	0-00%	0-00%	1-50%	0-00%	0-00%	1-50%	0-00%	1-50%	4-100%	1-33%	1-50%	1-100%	0-00%	1-33%	12-55%

Generated By: KNAVARRO

Generated On: 6/4/2013 11:03:45 AM

Customer Management Report (Escondido) All Detection Types

01-Jun-2013 to 04-Jun-2013

Operator Id: %

TOTAL
ESC-WVTU-03
ESC-WVTU-01
ESC-VPCC-01
ESC-VAES-01
ESC-VAAU-03
ESC-VAAU-01
ESC-SEJU-01
ESC-LIFI-03
ESC-LIFI-01
ESC-JUSE-01
ESC-ESVA-01
ESC-ES02-01
ESC-CCVP-01
ESC-AUVA-01
ESC-02ES-01

Generated By: KNAVARRO

Generated On: 6/4/2013 11:03:45 AM