

need 70-23.13 by USPS

# Customer Management Report (Hawthorne) All Detection Types

01-Dec-2004 to 31-Dec-2004

Operator Id: %

		HA-HAES-01(P)	HA-HAES-03(P)	HA-HAIM-01(P)	HA-HAIM-03(P)	HA-HIRO-01(P)	HA-IMFR-01(P)	HA-ROHI-01(P)	TOTAL
Total Processed Incidents		252	182	318	105	639	186	691	2373
Less Uncontrollable Factors									
Obstruction	Driver Obstruction/Duckers	7	1	9	0	17	1	46	81
	Plate Obstruction	0	2	3	1	6	1	11	24
	Vehicle Obstruction	6	4	2	2	11	2	71	98
Police Rejects	Driver Unidentifiable	0	1	0	1	7	3	4	16
	Interest of Justice	6	1	1	0	5	2	1	16
	Invalid Offense	63	16	7	5	6	14	5	116
	Safe Turn On Red	0	0	0	0	1	0	0	1
Policy/Weather	Extended Vehicle	0	0	0	0	1	0	1	2
	Sun Glare	4	12	13	4	7	16	7	63
	Weather/Nature	1	0	1	0	2	2	1	7
Registration Issues	Out of Country Plate	1	0	0	0	0	0	0	1
	Paper Plates	4	4	10	5	33	6	23	85
	Wrong or No DMV	7	7	7	3	17	3	11	55
Total		99	48	53	21	113	50	181	565
Sub Total Violations		153	134	265	84	526	136	510	1808
Less in Progress		0	0	0	0	0	0	0	0
Available For Prosecution		153	134	265	84	526	136	510	1808
Less Rejects									
Camera Malfunction	Digital Distortion	0-00%	22-16%	0-00%	1-01%	0-00%	0-00%	0-00%	23-01%
	Face Camera Flash	0-00%	0-00%	6-02%	0-00%	2-00%	0-00%	0-00%	8-00%
	Face Camera Focus Blurry	2-01%	0-00%	0-00%	6-07%	8-02%	0-00%	0-00%	16-01%
	Face Camera No Flash	0-00%	0-00%	95-36%	0-00%	0-00%	0-00%	0-00%	95-05%
	Face Not in Frame	7-05%	1-01%	5-02%	1-01%	57-11%	5-04%	51-10%	127-07%
	Image Missing	0-00%	3-02%	0-00%	4-05%	0-00%	0-00%	6-01%	13-01%
	Misc Camera Issue	1-01%	19-14%	1-00%	28-33%	0-00%	2-01%	0-00%	51-03%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	3-01%	0-00%	3-01%	6-00%
	Plate Not in Frame	9-06%	2-01%	20-08%	3-04%	2-00%	5-04%	3-01%	44-02%
	Rear Plate Camera Blurry	21-14%	1-01%	12-05%	0-00%	1-00%	2-01%	7-01%	44-02%
	Rear Plate Flash Inappropriate	5-03%	1-01%	0-00%	2-02%	3-01%	2-01%	1-00%	14-01%
	Rear Plate No Flash	0-00%	0-00%	2-01%	4-05%	0-00%	0-00%	2-00%	8-00%
Police Rejects	Expired Time	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Incorrect Details	0-00%	0-00%	0-00%	0-00%	1-00%	2-01%	0-00%	3-00%
Process Issues	Too Old	0-00%	0-00%	1-00%	0-00%	1-00%	0-00%	1-00%	3-00%
Total		46-30%	49-37%	142-54%	49-58%	78-15%	18-13%	74-15%	456-25%

Generated By: SPIMENTEL

Generated On: 9/25/2013 2:45:05 PM

# Customer Management Report (Hawthorne) All Detection Types

01-Dec-2004 to 31-Dec-2004

Operator Id: %

	HA-HAES-01(P)	HA-HAES-03(P)	HA-HAIM-01(P)	HA-HAIM-03(P)	HA-HIRO-01(P)	HA-IMFR-01(P)	HA-ROHI-01(P)	TOTAL
Approved Violations	107-70%	85-63%	123-46%	35-42%	448-85%	118-87%	436-85%	1352-75%
Total Notices Printed	107-70%	85-63%	123-46%	35-42%	448-85%	118-87%	436-85%	1352-75%

Generated By: SPIMENTEL

Generated On: 9/25/2013 2:45:05 PM

# Customer Management Report (Hawthorne) All Detection Types

01-Jun-2005 to 30-Jun-2005

Operator Id: %

	HA-HAES-01(P)	HA-HAES-03(P)	HA-HAIM-01(P)	HA-HAIM-03(P)	HA-HIRO-01(P)	HA-HMER-01(P)	HA-HROI-01(P)	TOTAL
Total Processed Incidents	161	149	251	144	1292	173	147	2317
<b>Less Uncontrollable Factors</b>								
Obstruction								
Driver Obstruction/Duckers	2	1	11	0	26	0	8	48
Motor Cycle Helmet	0	0	0	0	1	0	0	1
Plate Obstruction	2	1	3	2	15	3	2	28
Vehicle Obstruction	2	2	7	2	20	5	4	42
Police Rejects								
Driver Unidentifiable	12	5	8	6	73	8	6	118
Emergency Vehicle Responding	19	6	18	15	4	4	0	66
Gender Mismatch	0	0	0	0	1	0	0	1
Interest of Justice	0	1	0	0	0	0	0	1
Policy/Weather								
Extended Vehicle	0	0	0	1	6	1	0	8
Sun Glare	1	10	3	2	17	3	1	37
Registration Issues								
Can Not Identify State	2	1	1	0	2	0	1	7
Paper Plates	9	8	15	9	76	12	5	134
Wrong or No DMV	2	5	2	0	20	3	0	32
Total	51	40	68	37	261	39	27	523
Sub Total Violations	110	109	183	107	1031	134	120	1794
Less in Progress	0	0	0	0	0	0	0	0
Available For Prosecution	110	109	183	107	1031	134	120	1794
<b>Less Rejects</b>								
Camera Malfunction								
Digital Distortion	0-00%	0-00%	2-01%	0-00%	3-00%	0-00%	0-00%	5-00%
Face Camera Flash	5-05%	13-12%	1-01%	6-06%	68-07%	11-08%	3-02%	107-06%
Face Camera Focus Blurry	4-04%	2-02%	6-03%	2-02%	29-03%	2-01%	0-00%	45-03%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	1-00%	1-01%	0-00%	2-00%
Face Not in Frame	8-07%	13-12%	6-03%	4-04%	134-13%	5-04%	11-09%	181-10%

Generated By: SPIMENTEL

Generated On: 9/25/2013 2:53:35 PM

# Customer Management Report (Hawthorne) All Detection Types

01-Jun-2005 to 30-Jun-2005

Operator Id: %

	HA-HAES-01(P)	HA-HAES-03(P)	HA-HAIM-01(P)	HA-HAIM-03(P)	HA-HIRO-01(P)	HA-HIFR-01(P)	HA-HOHI-01(P)	TOTAL
Image Missing	0-00%	0-00%	0-00%	0-00%	52-05%	0-00%	0-00%	52-03%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%
Plate Burn Out	2-02%	0-00%	11-06%	0-00%	1-00%	0-00%	0-00%	14-01%
Plate Not in Frame	0-00%	0-00%	4-02%	1-01%	1-00%	2-01%	6-05%	14-01%
Rear Plate Camera Blurry	1-01%	9-08%	3-02%	0-00%	4-00%	0-00%	3-02%	20-01%
Rear Plate Flash Inappropriate	2-02%	1-01%	1-01%	0-00%	1-00%	0-00%	1-01%	6-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-01%	2-00%
Scene Image Blurry	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-00%
Police Rejects Process Issues								
Incorrect Details	1-01%	1-01%	5-03%	1-01%	9-01%	4-03%	2-02%	23-01%
Too Old	21-19%	17-16%	30-16%	23-21%	259-25%	31-23%	27-22%	408-23%
Total	44-40%	56-51%	70-38%	38-36%	563-55%	56-42%	55-46%	882-49%
Approved Violations	66-60%	53-49%	113-62%	69-64%	468-45%	78-58%	65-54%	912-51%
Total Notices Printed	66-60%	53-49%	113-62%	69-64%	468-45%	78-58%	65-54%	912-51%

Generated By: SPIMENTEL

Generated On: 9/25/2013 2:53:35 PM

# Customer Management Report (Hawthorne) All Detection Types

01-Aug-2005 to 31-Aug-2005

Operator Id: %

		HA-HAES-01(P)	HA-HAES-03(P)	HA-HAAM-01(P)	HA-HAAM-03(P)	HA-HIRO-01(P)	HA-IMFR-01(P)	HA-ROHI-01(P)	TOTAL
Total Processed Incidents		145	151	210	122	2248	188	174	3238
<b>Less Uncontrollable Factors</b>									
Obstruction	Driver Obstruction/Duckers	25	28	50	12	522	23	46	706
	Motor Cycle Helmet	0	0	0	0	1	0	0	1
	Plate Obstruction	0	2	9	8	32	1	7	59
	Vehicle Obstruction	0	0	1	2	11	1	5	20
Police Rejects	Driver Unidentifiable	3	2	2	0	38	2	5	52
	Emergency Vehicle Responding	46	10	10	15	4	11	0	96
	Interest of Justice	0	0	0	0	1	0	0	1
	Safe Turn On Red	0	0	0	0	53	7	0	60
Policy/Weather	Extended Vehicle	1	2	1	0	3	0	0	7
	Sun Glare	9	24	5	29	104	29	11	211
Registration Issues	Can Not Identify State	0	0	0	0	3	0	0	3
	Out of Country Plate	0	0	0	0	1	0	0	1
	Paper Plates	4	5	11	3	107	11	9	150
	Wrong or No DMV	1	2	1	2	28	1	1	36
<b>Total</b>		<b>89</b>	<b>75</b>	<b>90</b>	<b>71</b>	<b>908</b>	<b>86</b>	<b>84</b>	<b>1403</b>
Sub Total Violations		56	76	120	51	1340	102	90	1835
Less in Progress		0	0	0	0	0	0	0	0
Available For Prosecution		56	76	120	51	1340	102	90	1835
<b>Less Rejects</b>									
Camera Malfunction	Databar Unreadable/Incorrect	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera Flash	10-18%	11-14%	7-06%	6-12%	146-11%	20-20%	5-06%	205-11%
	Face Camera Focus Blurry	15-27%	4-05%	3-02%	1-02%	62-05%	4-04%	2-02%	91-05%
	Face Not in Frame	3-05%	1-01%	0-00%	2-04%	305-23%	6-06%	5-06%	322-18%

Generated By: SPIMENTEL

Generated On: 9/25/2013 2:54:19 PM

# Customer Management Report (Hawthorne) All Detection Types

01-Aug-2005 to 31-Aug-2005

Operator Id: %

	HA-HAES-01(P)	HA-HAES-03(P)	HA-HAIM-01(P)	HA-HAIM-03(P)	HA-HIRO-01(P)	HA-HIMR-01(P)	HA-ROHI-01(P)	TOTAL
Image Missing	0-00%	0-00%	10-08%	0-00%	0-00%	1-01%	3-03%	14-01%
Misc Camera Issue	1-02%	0-00%	65-54%	0-00%	17-01%	0-00%	14-16%	97-05%
Plate Burn Out	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	1-02%	1-01%	1-01%	3-06%	2-00%	1-01%	2-02%	11-01%
Rear Plate Camera Blurry	1-02%	3-04%	0-00%	3-06%	8-01%	2-02%	9-10%	26-01%
Rear Plate Flash Inappropriate	0-00%	2-03%	0-00%	3-06%	1-00%	0-00%	1-01%	7-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	3-06%	0-00%	0-00%	3-03%	6-00%
Scene Image Blurry	0-00%	0-00%	3-02%	0-00%	0-00%	0-00%	1-01%	4-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	2-00%
Scene Image No Flash	0-00%	0-00%	8-07%	0-00%	0-00%	0-00%	2-02%	10-01%
<b>Total</b>	<b>31-55%</b>	<b>22-29%</b>	<b>98-82%</b>	<b>22-43%</b>	<b>541-40%</b>	<b>34-33%</b>	<b>49-54%</b>	<b>797-43%</b>
Approved Violations	25-45%	54-71%	22-18%	29-57%	799-60%	68-67%	41-46%	1038-57%
Total Notices Printed	25-45%	54-71%	22-18%	29-57%	799-60%	68-67%	41-46%	1038-57%

Generated By: SPIMENTEL

Generated On: 9/25/2013 2:54:19 PM

© Redflex Traffic Systems, Inc.

# Customer Management Report (Hawthorne) All Detection Types

01-Sep-2005 to 30-Sep-2005

Operator Id: %

	HA-HAES-01(P)	HA-HAES-03(P)	HA-HAIM-01(P)	HA-HAIM-03(P)	HA-HIRO-01(P)	HA-IMFR-01(P)	HA-ROHI-01(P)	TOTAL
Total Processed Incidents	183	151	172	126	1746	185	105	2668
<b>Less Uncontrollable Factors</b>								
Obstruction								
Driver Obstruction/Duckers	39	33	43	14	438	19	26	612
Motor Cycle Helmet	0	0	0	0	2	1	0	3
Plate Obstruction	4	8	13	3	18	4	2	52
Vehicle Obstruction	1	0	3	1	5	1	2	13
Police Rejects								
Driver Unidentifiable	2	1	1	0	17	3	1	25
Emergency Vehicle Responding	40	11	21	12	4	2	0	90
Policy/Weather								
Extended Vehicle	0	0	0	0	2	1	0	3
Sun Glare	6	18	10	16	101	19	7	177
Registration Issues								
Can Not Identify State	0	0	0	0	1	0	0	1
Out of Country Plate	1	0	0	0	0	0	0	1
Paper Plates	10	4	6	6	94	10	5	135
Wrong or No DMV	1	2	2	0	13	2	0	20
<b>Total</b>	<b>104</b>	<b>77</b>	<b>99</b>	<b>52</b>	<b>695</b>	<b>62</b>	<b>43</b>	<b>1132</b>
Sub Total Violations	79	74	73	74	1051	123	62	1536
Less in Progress	0	0	0	0	0	0	0	0
Available For Prosecution	79	74	73	74	1051	123	62	1536
<b>Less Rejects</b>								
Camera Malfunction								
Face Camera Flash	2-03%	8-11%	2-03%	1-01%	64-06%	2-02%	0-00%	79-05%
Face Camera Focus Blurry	15-19%	4-05%	7-10%	3-04%	61-06%	4-03%	2-03%	96-06%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	5-00%	0-00%	0-00%	5-00%
Face Not in Frame	8-10%	0-00%	2-03%	9-12%	212-20%	2-02%	11-18%	244-16%
Image Missing	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	1-01%	0-00%	0-00%	0-00%	2-00%	0-00%	2-03%	5-00%

Generated By: SPIMENTEL

Generated On: 9/25/2013 2:54:50 PM

# Customer Management Report (Hawthorne) All Detection Types

01-Sep-2005 to 30-Sep-2005

Operator Id: %

	HA-HAES-01(P)	HA-HAES-03(P)	HA-HAIM-01(P)	HA-HAIM-03(P)	HA-HIRO-01(P)	HA-HIR-01(P)	HA-ROHI-01(P)	TOTAL
Plate Burn Out	0-00%	0-00%	1-01%	3-04%	1-00%	1-01%	0-00%	6-00%
Plate Not in Frame	2-03%	0-00%	7-10%	4-05%	1-00%	5-04%	1-02%	20-01%
Rear Plate Camera Blurry	1-01%	0-00%	5-07%	4-05%	1-00%	3-02%	11-18%	25-02%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	3-04%	0-00%	0-00%	3-05%	6-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	12-16%	0-00%	0-00%	5-08%	17-01%
Scene Image Flash Inappropriate	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	2-03%	3-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	2-00%
Police Rejects								
Process Issues								
Plate Unclear	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%
Too Old	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	0-00%	2-00%
<b>Total</b>	<b>29-37%</b>	<b>12-16%</b>	<b>26-36%</b>	<b>39-53%</b>	<b>350-33%</b>	<b>17-14%</b>	<b>39-63%</b>	<b>512-33%</b>
<b>Approved Violations</b>	<b>50-63%</b>	<b>62-84%</b>	<b>47-64%</b>	<b>35-47%</b>	<b>701-67%</b>	<b>106-86%</b>	<b>23-37%</b>	<b>1024-67%</b>
<b>Total Notices Printed</b>	<b>50-63%</b>	<b>62-84%</b>	<b>47-64%</b>	<b>35-47%</b>	<b>701-67%</b>	<b>106-86%</b>	<b>23-37%</b>	<b>1024-67%</b>

Generated By: SPIMENTEL

Generated On: 9/25/2013 2:54:50 PM



# Customer Management Report (Hawthorne) All Detection Types

01-Jul-2013 to 31-Jul-2013

Operator Id: %

	HA-HAES-01(P)	HA-HAES-03(P)	HA-HAM-01(P)	HA-HAM-03(P)	HA-HIRO-01(P)	HA-IMFR-01(P)	HA-ROH-01(P)	TOTAL
Total Processed Incidents	87	90	218	87	281	128	950	1841
<b>Less Uncontrollable Factors</b>								
Obstruction								
Driver Obstruction/Duckers	4	2	8	2	4	3	88	111
Motor Cycle Helmet	0	0	1	0	2	0	1	4
Plate Obstruction	1	0	2	1	0	1	27	32
Vehicle Obstruction	0	1	1	2	4	0	35	43
Police Rejects								
Incorrect Plate on Vehicle	0	0	0	0	0	0	1	1
Incorrect/Incomplete DMV	4	0	1	0	3	1	12	21
Invalid Offense	2	1	0	1	0	0	0	4
Multiple vehicles in frame	0	0	1	0	0	0	1	2
On or Passed the Stop Bar (PD)	6	4	70	2	8	3	0	93
Safe Turn On Red	0	0	1	0	13	1	0	15
Sun Glare	0	1	0	0	1	0	2	4
Policy/Weather								
Extended Vehicle	0	0	0	0	1	0	3	4
Sun Glare	0	19	10	9	53	16	41	148
Weather/Nature	0	0	0	0	0	0	1	1
Registration Issues								
Out of Country Plate	0	0	0	0	0	0	3	3
Paper Plates	3	7	13	4	25	7	33	92
Total	20	35	108	21	114	32	248	578
Sub Total Violations	67	55	110	66	167	96	702	1263
Less in Progress	0	0	0	0	0	0	0	0
Available For Prosecution	67	55	110	66	167	96	702	1263
<b>Less Rejects</b>								
Camera Malfunction								
Face Camera Flash	1-01%	0-00%	0-00%	0-00%	0-00%	1-01%	1-00%	3-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	1-02%	1-01%	1-01%	11-02%	14-01%

Generated By: SPIMENTEL

Generated On: 9/25/2013 2:55:21 PM

# Customer Management Report (Hawthorne) All Detection Types

01-Jul-2013 to 31-Jul-2013

Operator Id: %

	HA-HAES-01(P)	HA-HAES-03(P)	HA-HAM-01(P)	HA-HAM-03(P)	HA-HIRO-01(P)	HA-MFR-01(P)	HA-ROHI-01(P)	TOTAL
Face Camera No Flash	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
Face Not in Frame	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	2-00%	3-00%
Misc Camera Issue	0-00%	1-02%	0-00%	0-00%	0-00%	1-01%	0-00%	2-00%
Plate Burn Out	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	1-02%	0-00%	2-03%	0-00%	2-02%	0-00%	5-00%
Police Rejects								
Driver Unidentifiable images poor	2-03%	1-02%	6-05%	5-08%	14-08%	10-10%	51-07%	89-07%
Unclear Scene Image	0-00%	2-04%	1-01%	0-00%	3-02%	0-00%	3-00%	9-01%
Process Issues								
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Total	3-04%	5-09%	8-07%	10-15%	18-11%	15-16%	69-10%	128-10%
Approved Violations	64-96%	50-91%	102-93%	56-85%	149-89%	81-84%	633-90%	1135-90%
Total Notices Printed	64-96%	50-91%	102-93%	56-85%	149-89%	81-84%	633-90%	1135-90%

Generated By: SPIMENTEL

Generated On: 9/25/2013 2:55:21 PM

# Customer Management Report (Hawthorne) All Detection Types

01-Aug-2013 to 31-Aug-2013

Operator Id: %

		HA-HAES-01(P)	HA-HAES-03(P)	HA-HAIM-01(P)	HA-HAIM-03(P)	HA-HIRO-01(P)	HA-HMFR-01(P)	HA-ROHI-01(P)	TOTAL
Total Processed Incidents		79	81	197	145	263	127	1004	1896
Less Uncontrollable Factors									
Obstruction	Driver Obstruction/Duckers	2	4	17	1	2	4	93	123
	Motor Cycle Helmet	0	0	0	0	2	0	1	3
	Plate Obstruction	1	3	0	0	3	0	42	49
	Signal Obstruction	0	1	0	0	0	0	0	1
	Vehicle Obstruction	0	1	0	3	1	0	36	41
Police Rejects	Incorrect/Incomplete DMV	0	0	3	1	2	1	13	20
	Invalid Offense	0	0	0	1	0	0	0	1
	Multiple vehicles in frame	0	0	1	0	0	0	4	5
	On or Passed the Stop Bar (PD)	5	1	65	4	4	2	0	81
	Safe Turn On Red	0	0	0	0	8	0	0	8
	Sun Glare	0	0	0	4	4	1	6	15
Policy/Weather	Extended Vehicle	0	0	0	1	0	0	3	4
	Sun Glare	2	12	12	28	76	18	36	184
Registration Issues	Out of Country Plate	0	0	0	0	0	0	1	1
	Paper Plates	1	3	11	7	10	6	36	74
	Wrong or No DMV	0	0	0	0	1	0	1	2
Total		11	25	109	50	113	32	272	612
Sub Total Violations		68	56	88	95	150	95	732	1284
Less in Progress		0	0	0	0	0	0	0	0
Available For Prosecution		68	56	88	95	150	95	732	1284
Less Rejects									
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
	Face Camera Focus Blurry	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	5-01%	6-00%

Generated By: SPIMENTEL

Generated On: 9/25/2013 2:56:21 PM

# Customer Management Report (Hawthorne) All Detection Types

01-Aug-2013 to 31-Aug-2013

Operator Id: %

	HA-HAES-01(P)	HA-HAES-03(P)	HA-HAIM-01(P)	HA-HAIM-03(P)	HA-HIRO-01(P)	HA-HIMR-01(P)	HA-ROHI-01(P)	TOTAL
Face Camera No Flash	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	0-00%	2-00%
Image Missing	1-01%	0-00%	0-00%	1-01%	4-03%	0-00%	0-00%	6-00%
Misc Camera Issue	3-04%	1-02%	0-00%	0-00%	1-01%	0-00%	0-00%	5-00%
Plate Not in Frame	2-03%	2-04%	0-00%	0-00%	0-00%	1-01%	1-00%	6-00%
Rear Plate Camera Blurry	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	2-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
Police Rejects								
Driver Unidentifiable images poor	4-06%	4-07%	6-07%	14-15%	19-13%	15-16%	87-12%	149-12%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%	2-00%
Process Issues								
Too Old	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	11-16%	7-12%	9-10%	18-19%	25-17%	16-17%	96-13%	182-14%
Approved Violations	57-84%	49-88%	79-90%	77-81%	125-83%	79-83%	636-87%	1102-86%
Total Notices Printed	57-84%	49-88%	79-90%	77-81%	125-83%	79-83%	636-87%	1102-86%

Generated By: SPIMENTEL

Generated On: 9/25/2013 2:56:21 PM

# Customer Management Report (Hawthorne) All Detection Types

01-Sep-2013 to 30-Sep-2013

Operator Id: %

		HA-HAES-01(P)	HA-HAES-03(P)	HA-HAIM-01(P)	HA-HAIM-03(P)	HA-HIRO-01(P)	HA-HIR-01(P)	HA-ROHI-01(P)	TOTAL
Total Processed Incidents		93	84	146	101	303	85	766	1578
Less Uncontrollable Factors									
Obstruction	Driver Obstruction/Duckers	0	1	14	1	1	1	92	110
	Motor Cycle Helmet	0	0	0	0	1	0	0	1
	Plate Obstruction	5	1	1	1	4	1	43	56
	Vehicle Obstruction	0	0	2	2	9	1	11	25
Police Rejects	Incorrect/Incomplete DMV	0	0	2	2	4	1	14	23
	On or Passed the Stop Bar (PD).	5	3	43	4	4	1	2	62
	Safe Turn On Red	0	0	0	0	27	0	0	27
	Sun Glare	1	0	0	0	6	1	0	8
Policy/Weather	Extended Vehicle	0	0	0	0	1	0	4	5
	Sun Glare	1	13	1	13	72	6	22	128
Registration Issues	Out of Country Plate	0	0	0	1	0	0	0	1
	Paper Plates	4	1	7	5	16	8	19	60
Total		16	19	70	29	145	20	207	506
Sub Total Violations		77	65	76	72	158	65	559	1072
Less in Progress		14	9	34	8	22	11	93	191
Available For Prosecution		63	56	42	64	136	54	466	881
Less Rejects									
Camera Malfunction	Face Camera Flash	0-00%	2-04%	2-05%	0-00%	0-00%	0-00%	1-00%	5-01%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	24-18%	2-04%	12-03%	38-04%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Image Missing	1-02%	2-04%	0-00%	1-02%	0-00%	0-00%	0-00%	4-00%
	Misc Camera Issue	4-06%	1-02%	0-00%	2-03%	0-00%	1-02%	0-00%	8-01%
	Plate Not in Frame	1-02%	2-04%	0-00%	1-02%	0-00%	2-04%	2-00%	8-01%

Generated By: SPIMENTEL

Generated On: 9/25/2013 2:56:48 PM

# Customer Management Report (Hawthorne) All Detection Types

01-Sep-2013 to 30-Sep-2013

Operator Id: %

	HA-HAES-01(P)	HA-HAES-03(P)	HA-HAIM-01(P)	HA-HAIM-03(P)	HA-HIRO-01(P)	HA-IMFR-01(P)	HA-ROHI-01(P)	TOTAL
Rear Plate Camera Blurry	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	2-00%
Scene Image Flash Inappropriate	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Scene Image No Flash	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects								
Driver Unidentifiable images poor	1-02%	2-04%	3-07%	4-06%	18-13%	4-07%	28-06%	60-07%
Unclear Scene Image	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues								
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Total	11-17%	10-18%	5-12%	8-12%	42-31%	9-17%	46-10%	131-15%
Approved Violations	52-83%	46-82%	37-88%	56-88%	94-69%	45-83%	420-90%	750-85%
Total Notices Printed	46-73%	41-73%	31-74%	50-78%	81-60%	41-76%	375-80%	665-75%

Generated By: SPIMENTEL

Generated On: 9/25/2013 2:56:48 PM