

Customer Management Report (Montebello) All Detection Types

01-May-2017 to 31-Oct-2017

Operator Id: %

	MON-BEGA-01	MON-GAVC-01	MON-MOBE-01	MON-MOPA-01	MON-MOPA-03	MON-MOWH-01	MON-VCGA-01	MON-WAGR-01	TOTAL	
Total Processed Incidents	1410	3175	1000	1074	1036	1025	1964	2265	12949	
Less Uncontrollable Factors										
Obstruction	Driver Obstruction/Duckers	10	20	7	12	4	5	27	18	103
	Motor Cycle Helmet	1	0	0	1	1	0	2	0	5
	Plate Obstruction	10	47	12	15	25	23	43	51	226
	Signal Obstruction	0	0	0	0	2	0	0	0	2
	Vehicle Obstruction	29	56	10	9	53	76	158	152	543
Police Rejects	Driver Obstruction (PD)	2	7	4	5	0	2	4	4	28
	Emergency Vehicle Responding	1	2	1	1	0	0	1	1	7
	Funeral Procession/Police	0	4	0	0	0	0	0	0	4
	Gender Mismatch	3	5	0	0	0	1	0	2	11
	Incorrect/Incomplete DMV	58	121	39	36	51	27	46	60	438
	Invalid Offense	0	0	24	252	1	13	14	28	332
	Multiple vehicles in frame	1	3	0	0	0	0	0	0	4
	On or Passed the Stop Bar (PD)	15	46	25	3	22	13	12	11	147
	Plate Unidentifiable	0	0	0	0	0	0	1	0	1
	Police Discretion	18	73	44	9	19	11	27	31	232
	Safe Turn On Red	0	17	7	0	5	2	3	4	38
	Sun Glare	7	45	13	32	10	7	16	43	173
Policy/Weather	Extended Vehicle	7	5	13	9	0	6	11	402	453
	Sun Glare	16	41	14	31	7	13	33	35	190
	Weather/Nature	1	7	2	0	1	2	4	0	17
Registration Issues	Out of Country Plate	0	4	0	2	0	0	3	2	11
	Paper Plates	99	248	95	69	72	86	158	122	949
Total		278	751	310	486	273	287	563	966	3914
Sub Total Violations		1132	2424	690	588	763	738	1401	1299	9035
Less in Progress		61	172	49	40	48	26	160	129	685
Available For Prosecution		1071	2252	641	548	715	712	1241	1170	8350
Less Rejects										
Camera Malfunction	Face Camera Flash	1-00%	0-00%	0-00%	2-00%	0-00%	0-00%	1-00%	0-00%	4-00%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	2-00%	3-00%
	Face Not in Frame	2-00%	0-00%	3-00%	3-01%	4-01%	3-00%	0-00%	0-00%	15-00%
	Image Missing	0-00%	0-00%	1-00%	0-00%	1-00%	1-00%	2-00%	0-00%	5-00%
	Misc Camera Issue	0-00%	0-00%	1-00%	0-00%	2-00%	0-00%	1-00%	1-00%	5-00%
	Plate Burn Out	0-00%	2-00%	0-00%	0-00%	3-00%	0-00%	1-00%	7-01%	13-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%	0-00%	0-00%	4-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	2-00%	3-00%	7-00%

Generated By: JAINILIAN

Generated On: 10/30/2017 12:54:06 PM

Customer Management Report (Montebello) All Detection Types

01-May-2017 to 31-Oct-2017

Operator Id: %

	MON-BEGA-01	MON-GAVC-01	MON-MOBE-01	MON-MOPA-01	MON-MOPA-03	MON-MOWH-01	MON-VCGA-01	MON-WAGR-01	TOTAL
Rear Plate Flash Inappropriate	0-00%	2-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	3-00%
Rear Plate No Flash	1-00%	0-00%	7-01%	0-00%	0-00%	1-00%	0-00%	0-00%	9-00%
Scene Image Flash Inappropriate	1-00%	1-00%	2-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
Scene Image No Flash	2-00%	35-02%	13-02%	0-00%	0-00%	2-00%	0-00%	0-00%	52-01%
Test Pattern	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Video Not In Sync	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	14-01%	1-00%	15-00%
Video Skips	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	0-00%	0-00%	2-00%
Police Rejects									
Driver Unidentifiable images poor	9-01%	36-02%	14-02%	19-03%	11-02%	7-01%	43-03%	16-01%	155-02%
Insufficient Strobe Lighting	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
No Video	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	0-00%	0-00%	0-00%	3-01%	0-00%	0-00%	2-00%	1-00%	6-00%
Unclear Scene Image	1-00%	1-00%	2-00%	2-00%	1-00%	1-00%	4-00%	0-00%	12-00%
Process Issues									
Too Old	53-05%	94-04%	28-04%	21-04%	20-03%	35-05%	85-07%	47-04%	383-05%
Total	70-07%	172-08%	71-11%	51-09%	44-06%	56-08%	157-13%	79-07%	700-08%
Approved Violations	1001-93%	2080-92%	570-89%	497-91%	671-94%	656-92%	1084-87%	1091-93%	7650-92%
Total Notices Printed	1001-93%	2080-92%	570-89%	497-91%	671-94%	656-92%	1084-87%	1091-93%	7650-92%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JAINILIAN

Generated On: 10/30/2017 12:54:06 PM