

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Dec-2016 to 31-Dec-2016

Operator Id: %

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL	
<b>Total Processed Incidents</b>	652	739	170	443	2004	
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	25	129	6	18	178
	Motor Cycle Helmet	1	1	0	0	2
	Plate Obstruction	17	9	4	6	36
	Vehicle Obstruction	8	9	0	15	32
Police Rejects	Emergency Vehicle Responding	2	8	3	7	20
	Incorrect/Incomplete DMV	13	14	5	13	45
	Invalid Offense	0	4	0	1	5
	Multiple vehicles in frame	0	0	0	1	1
	On or Passed the Stop Bar (PD).	98	21	2	101	222
	Police Discretion	9	6	2	13	30
	Safe Turn On Red	1	0	0	0	1
Policy/Weather	Extended Vehicle	0	14	1	3	18
	Sun Glare	21	56	28	10	115
	Weather/Nature	6	14	5	10	35
Registration Issues	Out of Country Plate	1	0	0	0	1
	Paper Plates	23	34	7	26	90
	Wrong or No DMV	0	1	0	0	1
<b>Total</b>		225	320	63	224	832
<b>Sub Total Violations</b>		427	419	107	219	1172
Less in Progress		0	0	0	0	0
<b>Available For Prosecution</b>		427	419	107	219	1172

Generated By: MFONTES

Generated On: 1/10/2017 3:25:12 PM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Dec-2016 to 31-Dec-2016

Operator Id: %

		RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
<b>Less Rejects</b>						
Camera Malfunction	Digital Distortion	1-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera Flash	0-00%	2-00%	0-00%	0-00%	2-00%
	Face Camera Focus Blurry	2-00%	2-00%	0-00%	0-00%	4-00%
	Image Missing	0-00%	8-02%	3-03%	0-00%	11-01%
	Plate Burn Out	0-00%	0-00%	2-02%	0-00%	2-00%
	Rear Plate Camera Blurry	0-00%	0-00%	2-02%	0-00%	2-00%
	Rear Plate Flash Inappropriate	3-01%	2-00%	1-01%	1-00%	7-01%
	Scene Image No Flash	0-00%	0-00%	0-00%	2-01%	2-00%
Police Rejects	Driver Unidentifiable images poor	1-00%	6-01%	1-01%	0-00%	8-01%
	Unclear Scene Image	1-00%	1-00%	0-00%	0-00%	2-00%
Process Issues	Too Old	0-00%	4-01%	0-00%	2-01%	6-01%
Total		8-02%	25-06%	9-08%	5-02%	47-04%
<b>Approved Violations</b>		419-98%	394-94%	98-92%	214-98%	1125-96%
<b>Total Notices Printed</b>		419-98%	394-94%	98-92%	214-98%	1125-96%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MFONTES

Generated On: 1/10/2017 3:25:12 PM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Jan-2017 to 31-Jan-2017

Operator Id: %

		RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
<b>Total Processed Incidents</b>		483	704	129	366	1682
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	15	149	4	18	186
	Motor Cycle Helmet	0	1	0	0	1
	Plate Obstruction	4	11	3	5	23
	Vehicle Obstruction	8	18	2	15	43
Police Rejects	Emergency Vehicle Responding	2	7	18	5	32
	Incorrect/Incomplete DMV	5	6	2	5	18
	Invalid Offense	0	4	0	1	5
	On or Passed the Stop Bar (PD).	86	31	1	60	178
	Police Discretion	25	11	0	13	49
	Safe Stop on Red	0	0	0	1	1
	Safe Turn On Red	0	0	0	1	1
	Yielding to an Emergency	0	1	0	0	1
	Policy/Weather	Extended Vehicle	1	7	3	4
Sun Glare		42	66	20	7	135
Weather/Nature		12	22	1	8	43
Registration Issues	Paper Plates	22	25	4	22	73
<b>Total</b>		222	359	58	165	804
<b>Sub Total Violations</b>		261	345	71	201	878
Less in Progress		0	0	0	0	0
<b>Available For Prosecution</b>		261	345	71	201	878
<b>Less Rejects</b>						
Camera Malfunction	Face Camera Flash	24-09%	5-01%	0-00%	0-00%	29-03%
	Face Camera Focus Blurry	0-00%	1-00%	2-03%	1-00%	4-00%
	Face Camera No Flash	4-02%	0-00%	0-00%	0-00%	4-00%
	Face Not in Frame	1-00%	1-00%	0-00%	1-00%	3-00%
	Image Missing	0-00%	2-01%	8-11%	0-00%	10-01%
	Misc Camera Issue	0-00%	0-00%	0-00%	1-00%	1-00%
	Rear Plate Camera Blurry	3-01%	2-01%	0-00%	0-00%	5-01%
	Rear Plate Flash Inappropriate	0-00%	1-00%	0-00%	0-00%	1-00%
	Rear Plate No Flash	3-01%	0-00%	0-00%	0-00%	3-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	1-00%	1-00%
	Scene Image No Flash	0-00%	1-00%	0-00%	0-00%	1-00%
	Video Not In Sync	0-00%	0-00%	0-00%	3-01%	3-00%

Generated By: MFONTES

Generated On: 2/7/2017 5:51:46 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Jan-2017 to 31-Jan-2017

Operator Id: %

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
Video Skips	0-00%	0-00%	0-00%	1-00%	1-00%
Police Rejects					
Driver Unidentifiable images poor	0-00%	3-01%	0-00%	2-01%	5-01%
Process Issues					
Too Old	1-00%	0-00%	0-00%	0-00%	1-00%
Total	36-14%	16-05%	10-14%	10-05%	72-08%
<b>Approved Violations</b>	<b>225-86%</b>	<b>329-95%</b>	<b>61-86%</b>	<b>191-95%</b>	<b>806-92%</b>
<b>Total Notices Printed</b>	<b>225-86%</b>	<b>329-95%</b>	<b>61-86%</b>	<b>191-95%</b>	<b>806-92%</b>

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MFONTES

Generated On: 2/7/2017 5:51:46 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Feb-2017 to 28-Feb-2017

Operator Id: %

		RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
<b>Total Processed Incidents</b>		498	568	149	428	1643
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	5	87	3	12	107
	Motor Cycle Helmet	0	1	0	0	1
	Plate Obstruction	12	15	8	7	42
	Signal Obstruction	0	1	0	0	1
	Vehicle Obstruction	5	10	1	9	25
Police Rejects	Emergency Vehicle Responding	3	2	7	1	13
	Incorrect/Incomplete DMV	5	14	1	7	27
	Invalid Offense	2	1	0	0	3
	On or Passed the Stop Bar (PD).	133	33	2	104	272
	Police Discretion	4	2	0	8	14
	Yielding to an Emergency	0	1	0	0	1
Policy/Weather	Extended Vehicle	1	8	3	3	15
	Sun Glare	16	71	8	26	121
	Weather/Nature	2	12	6	23	43
Registration Issues	Out of Country Plate	0	1	0	0	1
	Paper Plates	22	20	6	22	70
	Wrong or No DMV	2	0	1	1	4
<b>Total</b>	<b>212</b>	<b>279</b>	<b>46</b>	<b>223</b>	<b>760</b>	
<b>Sub Total Violations</b>		<b>286</b>	<b>289</b>	<b>103</b>	<b>205</b>	<b>883</b>
Less in Progress		0	0	0	0	0
<b>Available For Prosecution</b>		<b>286</b>	<b>289</b>	<b>103</b>	<b>205</b>	<b>883</b>
<b>Less Rejects</b>						
Camera Malfunction	Face Camera Flash	0-00%	2-01%	2-02%	1-00%	5-01%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	9-04%	9-01%
	Face Camera No Flash	1-00%	0-00%	0-00%	1-00%	2-00%
	Face Not in Frame	0-00%	0-00%	2-02%	3-01%	5-01%
	Image Missing	0-00%	7-02%	3-03%	0-00%	10-01%
	Misc Camera Issue	0-00%	0-00%	0-00%	1-00%	1-00%
	Plate Not in Frame	0-00%	0-00%	1-01%	0-00%	1-00%
	Rear Plate Camera Blurry	2-01%	0-00%	1-01%	0-00%	3-00%
	Rear Plate Flash Inappropriate	5-02%	0-00%	0-00%	0-00%	5-01%
	Rear Plate No Flash	4-01%	1-00%	0-00%	0-00%	5-01%
	Video Not In Sync	0-00%	0-00%	0-00%	3-01%	3-00%

Generated By: MFONTES

Generated On: 3/7/2017 11:59:14 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Feb-2017 to 28-Feb-2017

Operator Id: %

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
Police Driver Unidentifiable images poor Rejects	2-01%	6-02%	1-01%	1-00%	10-01%
Total	14-05%	16-06%	10-10%	19-09%	59-07%
Approved Violations	272-95%	273-94%	93-90%	186-91%	824-93%
Total Notices Printed	259-91%	266-92%	91-88%	181-88%	797-90%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MFONTES

Generated On: 3/7/2017 11:59:14 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Mar-2017 to 31-Mar-2017

Operator Id: %

		RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
<b>Total Processed Incidents</b>		815	739	183	547	2284
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	22	113	5	21	161
	Motor Cycle Helmet	1	2	1	1	5
	Plate Obstruction	22	7	8	10	47
	Signal Obstruction	1	0	0	0	1
	Vehicle Obstruction	5	16	3	11	35
Police Rejects	Emergency Vehicle Responding	3	10	11	4	28
	Incorrect/Incomplete DMV	19	11	3	13	46
	Invalid Offense	0	1	0	0	1
	On or Passed the Stop Bar (PD).	214	40	0	89	343
	Police Discretion	42	13	1	16	72
	Yielding to an Emergency	0	0	1	0	1
Policy/Weather	Extended Vehicle	1	13	2	7	23
	Sun Glare	22	80	14	48	164
	Weather/Nature	6	9	1	5	21
Registration Issues	Paper Plates	37	21	10	18	86
<b>Total</b>		395	336	60	243	1034
<b>Sub Total Violations</b>		420	403	123	304	1250
Less in Progress		0	0	0	0	0
<b>Available For Prosecution</b>		420	403	123	304	1250
<b>Less Rejects</b>						
Camera Malfunction	Face Camera Flash	0-00%	8-02%	0-00%	0-00%	8-01%

Generated By: JMMORRIS

Generated On: 4/11/2017 7:32:38 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Mar-2017 to 31-Mar-2017

Operator Id: %

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
Violation					
Face Camera Focus Blurry	1-00%	1-00%	0-00%	4-01%	6-00%
Face Not in Frame	0-00%	1-00%	10-08%	1-00%	12-01%
Image Missing	0-00%	6-01%	8-07%	0-00%	14-01%
Misc Camera Issue	0-00%	1-00%	0-00%	1-00%	2-00%
Plate Not in Frame	0-00%	1-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	2-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate Flash Inappropriate	4-01%	1-00%	0-00%	0-00%	5-00%
Rear Plate No Flash	9-02%	0-00%	0-00%	1-00%	10-01%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	8-03%	8-01%
Scene Image No Flash	0-00%	0-00%	0-00%	1-00%	1-00%
Video Not In Sync	1-00%	3-01%	1-01%	2-01%	7-01%
Police Rejects					
Process Issues					
Driver Unidentifiable images poor	1-00%	4-01%	0-00%	0-00%	5-00%
Too Old	5-01%	0-00%	0-00%	1-00%	6-00%
Total	23-05%	26-06%	19-15%	19-06%	87-07%
Approved Violations	397-95%	377-94%	104-85%	285-94%	1163-93%
Total Notices Printed	397-95%	377-94%	104-85%	285-94%	1163-93%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JMMORRIS

Generated On: 4/11/2017 7:32:38 AM



# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Apr-2017 to 30-Apr-2017

Operator Id: %

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL	
<b>Total Processed Incidents</b>	720	594	518	611	2443	
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	13	85	14	48	160
	Motor Cycle Helmet	0	3	1	0	4
	Plate Obstruction	25	10	11	11	57
	Vehicle Obstruction	11	11	3	46	71
Police Rejects	Emergency Vehicle Responding	3	5	12	4	24
	Gender Mismatch	1	0	0	0	1
	Incorrect/Incomplete DMV	14	3	2	9	28
	Invalid Offense	0	0	2	1	3
	Multiple vehicles in frame	0	0	0	2	2
	On or Passed the Stop Bar (PD).	97	15	4	48	164
	Police Discretion	149	24	56	62	291
	Safe Turn On Red	0	0	2	0	2
Policy/Weather	Extended Vehicle	0	15	6	6	27
	Sun Glare	23	52	47	52	174
	Weather/Nature	20	25	10	26	81
Registration Issues	Can Not Identify State	0	0	0	1	1
	Paper Plates	28	24	17	22	91
<b>Total</b>		384	272	187	338	1181
<b>Sub Total Violations</b>		336	322	331	273	1262
Less in Progress		0	0	0	0	0
<b>Available For Prosecution</b>		336	322	331	273	1262
<b>Less Rejects</b>						
Camera Malfunction	Face Camera Flash	0-00%	2-01%	0-00%	0-00%	2-00%
	Face Camera Focus Blurry	0-00%	1-00%	0-00%	0-00%	1-00%
	Face Camera No Flash	0-00%	1-00%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	14-04%	0-00%	14-01%
	Image Missing	0-00%	3-01%	14-04%	1-00%	18-01%
	Misc Camera Issue	0-00%	1-00%	2-01%	0-00%	3-00%
	Rear Plate Camera Blurry	2-01%	0-00%	1-00%	0-00%	3-00%
	Rear Plate Flash Inappropriate	7-02%	0-00%	0-00%	0-00%	7-01%
	Rear Plate No Flash	4-01%	0-00%	0-00%	0-00%	4-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	5-02%	5-00%
	Video Not In Sync	0-00%	6-02%	0-00%	1-00%	7-01%

Generated By: MFONTES

Generated On: 5/9/2017 3:31:41 PM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Apr-2017 to 30-Apr-2017

Operator Id: %

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
Police Driver Unidentifiable images poor Rejects	1-00%	12-04%	3-01%	5-02%	21-02%
Total	14-04%	26-08%	34-10%	12-04%	86-07%
Approved Violations	322-96%	296-92%	297-90%	261-96%	1176-93%
Total Notices Printed	316-94%	296-92%	296-89%	260-95%	1168-93%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MFONTES

Generated On: 5/9/2017 3:31:41 PM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-May-2017 to 31-May-2017

Operator Id: %

		RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
<b>Total Processed Incidents</b>		826	620	218	702	2366
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	16	95	5	50	166
	Motor Cycle Helmet	0	1	1	0	2
	Plate Obstruction	12	10	6	12	40
	Vehicle Obstruction	8	18	2	63	91
Police Rejects	Emergency Vehicle Responding	5	2	12	3	22
	Incorrect/Incomplete DMV	14	6	5	7	32
	Invalid Offense	1	0	0	2	3
	Multiple vehicles in frame	0	1	0	8	9
	On or Passed the Stop Bar (PD).	226	49	3	101	379
	Police Discretion	35	3	39	16	93
	Safe Turn On Red	0	0	1	0	1
	Yielding to an Emergency	0	1	0	0	1
	Policy/Weather	Extended Vehicle	0	8	1	6
	Sun Glare	32	57	15	92	196
	Weather/Nature	0	4	0	2	6
Registration Issues	Gender Match	0	0	1	0	1
	Out of Country Plate	1	0	0	0	1
	Paper Plates	35	24	11	27	97
	Wrong or No DMV	1	2	1	1	5
<b>Total</b>		386	281	103	390	1160
<b>Sub Total Violations</b>		440	339	115	312	1206
Less in Progress		0	0	0	0	0
<b>Available For Prosecution</b>		440	339	115	312	1206
<b>Less Rejects</b>						
Camera Malfunction	Face Camera Flash	1-00%	3-01%	4-03%	0-00%	8-01%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	17-05%	17-01%
	Image Missing	0-00%	2-01%	4-03%	0-00%	6-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	1-00%	1-00%
	Rear Plate Camera Blurry	0-00%	1-00%	0-00%	0-00%	1-00%
	Rear Plate Flash Inappropriate	1-00%	1-00%	0-00%	0-00%	2-00%
	Rear Plate No Flash	4-01%	2-01%	1-01%	1-00%	8-01%
	Scene Image Flash Inappropriate	0-00%	2-01%	0-00%	0-00%	2-00%
Police Rejects	Driver Unidentifiable images poor	1-00%	2-01%	0-00%	2-01%	5-00%
	Video Malfunction	0-00%	1-00%	0-00%	2-01%	3-00%

Generated By: MFONTES

Generated On: 8/22/2017 8:56:10 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-May-2017 to 31-May-2017

Operator Id: %

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
Total	7-02%	14-04%	9-08%	23-07%	53-04%
Approved Violations	433-98%	325-96%	106-92%	289-93%	1153-96%
Total Notices Printed	433-98%	325-96%	106-92%	289-93%	1153-96%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MFONTES

Generated On: 8/22/2017 8:56:10 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Jun-2017 to 30-Jun-2017

Operator Id: %

		RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
<b>Total Processed Incidents</b>		823	671	201	644	2339
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	40	106	7	58	211
	Motor Cycle Helmet	1	0	0	1	2
	Plate Obstruction	21	25	7	14	67
	Vehicle Obstruction	5	26	12	63	106
Police Rejects	Emergency Vehicle Responding	1	5	6	2	14
	Incorrect/Incomplete DMV	24	10	3	7	44
	Multiple vehicles in frame	0	0	0	2	2
	On or Passed the Stop Bar (PD).	195	38	4	68	305
	Police Discretion	51	13	5	16	85
Policy/Weather	Extended Vehicle	1	1	3	5	10
	Sun Glare	40	76	13	145	274
	Weather/Nature	2	5	0	6	13
Registration Issues	Paper Plates	34	21	7	20	82
	Wrong or No DMV	0	1	0	0	1
<b>Total</b>		415	327	67	407	1216
<b>Sub Total Violations</b>		408	344	134	237	1123
Less in Progress		1	0	0	0	1
<b>Available For Prosecution</b>		407	344	134	237	1122
<b>Less Rejects</b>						
Camera Malfunction	Face Camera Flash	1-00%	9-03%	3-02%	0-00%	13-01%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	9-04%	9-01%
	Face Camera No Flash	0-00%	0-00%	1-01%	0-00%	1-00%
	Image Missing	0-00%	10-03%	7-05%	0-00%	17-02%
	Misc Camera Issue	1-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Camera Blurry	0-00%	1-00%	0-00%	0-00%	1-00%
	Rear Plate Flash Inappropriate	1-00%	1-00%	0-00%	0-00%	2-00%
	Rear Plate No Flash	7-02%	1-00%	0-00%	0-00%	8-01%
	Video Not In Sync	1-00%	3-01%	0-00%	0-00%	4-00%
Police Rejects	Driver Unidentifiable images poor	1-00%	4-01%	1-01%	12-05%	18-02%
	Video Malfunction	0-00%	0-00%	1-01%	0-00%	1-00%
Process Issues	Too Old	0-00%	0-00%	1-01%	0-00%	1-00%
<b>Total</b>		12-03%	29-08%	14-10%	21-09%	76-07%

Generated By: MFONTES

Generated On: 7/13/2017 11:36:01 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Jun-2017 to 30-Jun-2017

Operator Id: %

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
Approved Violations	395-97%	315-92%	120-90%	216-91%	1046-93%
Total Notices Printed	395-97%	315-92%	120-90%	216-91%	1046-93%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MFONTES

Generated On: 7/13/2017 11:36:01 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Jul-2017 to 31-Jul-2017

Operator Id: %

		RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
<b>Total Processed Incidents</b>		871	678	190	399	2138
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	35	102	9	34	180
	Motor Cycle Helmet	4	4	0	3	11
	Plate Obstruction	34	20	6	13	73
	Vehicle Obstruction	6	9	3	13	31
Police Rejects	Emergency Vehicle Responding	6	2	9	1	18
	Incorrect/Incomplete DMV	18	19	3	7	47
	Invalid Offense	2	1	0	1	4
	Multiple vehicles in frame	0	1	0	0	1
	On or Passed the Stop Bar (PD).	211	32	1	47	291
	Police Discretion	27	9	3	13	52
	Yielding to an Emergency	0	1	0	0	1
Policy/Weather	Extended Vehicle	0	5	0	2	7
	Sun Glare	68	101	13	81	263
	Weather/Nature	1	2	1	0	4
Registration Issues	Out of Country Plate	0	0	0	1	1
	Paper Plates	31	25	8	20	84
	Wrong or No DMV	2	1	0	1	4
<b>Total</b>	445	334	56	237	1072	
<b>Sub Total Violations</b>		426	344	134	162	1066
Less in Progress		0	0	0	0	0
<b>Available For Prosecution</b>		426	344	134	162	1066

Generated By: MFONTES

Generated On: 8/8/2017 2:51:55 PM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Jul-2017 to 31-Jul-2017

Operator Id: %

		RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
<b>Less Rejects</b>						
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	1-01%	1-00%
	Face Camera Flash	1-00%	6-02%	5-04%	0-00%	12-01%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	5-03%	5-00%
	Face Not in Frame	0-00%	1-00%	0-00%	0-00%	1-00%
	Image Missing	0-00%	9-03%	8-06%	0-00%	17-02%
	Plate Not in Frame	0-00%	0-00%	0-00%	2-01%	2-00%
	Rear Plate Flash Inappropriate	1-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate No Flash	1-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	2-01%	0-00%	1-01%	3-00%
	Video Malfunction	1-00%	0-00%	0-00%	0-00%	1-00%
Total		4-01%	18-05%	13-10%	9-06%	44-04%
Approved Violations		422-99%	326-95%	121-90%	153-94%	1022-96%
Total Notices Printed		420-99%	319-93%	121-90%	148-91%	1008-95%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MFONTES

Generated On: 8/8/2017 2:51:55 PM