

# Customer Management Report (San Leandro) All Detection Types

01-Apr-2019 to 30-Jun-2019

Operator Id: %

		SLE-14DA-01	SLE-14FA-01	SLE-HAWA-01	SLE-HAWA-03	SLE-MATE-01	TOTAL
<b>Total Processed Incidents</b>		435	1360	1920	3572	2540	9827
<b>Less Uncontrollable Factors</b>							
Obstruction	Driver Obstruction/Duckers	42	62	138	442	103	787
	Motor Cycle Helmet	0	7	0	2	0	9
	Plate Obstruction	24	9	18	38	33	122
	Vehicle Obstruction	25	10	17	52	57	161
Police Rejects	Emergency Vehicle Responding	10	32	7	8	21	78
	Incorrect/Incomplete DMV	1	5	2	8	9	25
	Invalid Offense	0	0	0	6	0	6
	Multiple vehicles in frame	0	0	0	1	1	2
	On or Passed the Stop Bar (PD)	2	172	525	1277	116	2092
	Plate Obstruction (PD)	0	0	0	0	1	1
	Plate Unidentifiable	0	0	0	0	1	1
	Police Discretion	8	26	46	79	48	207
	Safe Turn On Red	0	24	64	144	26	258
	Sun Glare	0	2	2	4	1	9
Policy/Weather	Extended Vehicle	20	2	3	99	65	189
	Sun Glare	142	268	279	331	466	1486
	Weather/Nature	6	8	10	5	9	38
	Yellow with Red Light	0	1	0	0	0	1
Registration Issues	Can Not Identify State	0	0	0	0	1	1
	Out of Country Plate	0	0	2	1	1	4
	Paper Plates	13	62	71	90	99	335
<b>Total</b>	293	690	1184	2587	1058	5812	
<b>Sub Total Violations</b>		142	670	736	985	1482	4015
Less in Progress		0	0	0	1	0	1
<b>Available For Prosecution</b>		142	670	736	984	1482	4014
<b>Less Rejects</b>							
Camera Malfunction	Face Camera Flash	4-03%	2-00%	1-00%	0-00%	4-00%	11-00%
	Face Camera Focus Blurry	1-01%	0-00%	0-00%	1-00%	1-00%	3-00%
	Face Not in Frame	1-01%	0-00%	1-00%	1-00%	5-00%	8-00%
	Image Missing	3-02%	0-00%	0-00%	0-00%	0-00%	3-00%
	Plate Burn Out	1-01%	0-00%	0-00%	1-00%	0-00%	2-00%
	Plate Not in Frame	1-01%	0-00%	0-00%	1-00%	0-00%	2-00%
	Rear Plate Camera Blurry	6-04%	2-00%	0-00%	1-00%	2-00%	11-00%
	Rear Plate Flash Inappropriate	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate No Flash	0-00%	0-00%	16-02%	0-00%	0-00%	16-00%

Generated By: SWONG

Generated On: 7/24/2019 10:54:56 AM

# Customer Management Report (San Leandro) All Detection Types

01-Apr-2019 to 30-Jun-2019

Operator Id: %

	SLE-14DA-01	SLE-14FA-01	SLE-HAWA-01	SLE-HAWA-03	SLE-MATE-01	TOTAL
Scene Image No Flash	0-00%	0-00%	9-01%	0-00%	0-00%	9-00%
Video Not In Sync	0-00%	0-00%	1-00%	1-00%	0-00%	2-00%
Police Rejects						
Driver Unidentifiable images poor	30-21%	83-12%	97-13%	64-07%	148-10%	422-11%
Red-light not visible in	0-00%	1-00%	0-00%	4-00%	0-00%	5-00%
Process Issues						
Too Old	1-01%	1-00%	0-00%	1-00%	2-00%	5-00%
Total	49-35%	89-13%	125-17%	75-08%	162-11%	500-12%
Approved Violations	93-65%	581-87%	611-83%	909-92%	1320-89%	3514-88%
Total Notices Printed	93-65%	581-87%	611-83%	909-92%	1320-89%	3514-88%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SWONG

Generated On: 7/24/2019 10:54:56 AM