

Customer Management Report (Ventura) All Detection Types

01-Apr-2003 to 30-Apr-2003

Operator Id: %

		VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents		25	0	49	50	0	55	0	39	15	30	81	79	23	65	112	122	72	120	937	
Less Uncontrollable Factors																					
Obstruction	Driver Obstruction/Duckers	4	0	14	7	0	3	0	2	0	2	3	4	2	4	15	3	2	3	68	
	Plate Obstruction	2	0	2	4	0	9	0	2	2	0	2	2	1	3	8	5	1	9	52	
	Vehicle Obstruction	3	0	0	0	0	2	0	0	0	0	47	5	0	2	2	3	3	5	72	
Police Rejects	Driver Unidentifiable	0	0	0	0	0	2	0	0	0	1	0	1	0	0	1	2	0	3	10	
	Extended Vehicle	0	0	0	1	0	0	0	0	0	0	0	11	0	1	0	0	0	7	20	
	Sun Glare	1	0	1	6	0	3	0	1	0	10	9	4	2	11	8	19	42	20	137	
Policy/Weather	Yellow with Red Light	0	0	0	0	0	0	0	1	0	0	1	0	0	2	0	0	0	0	4	
	Can Not Identify State	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
	Out of Country Plate	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1	
Registration Issues	Paper Plates	0	0	1	0	0	1	0	3	0	0	1	1	2	1	1	2	1	5	19	
	Wrong or No DMV	0	0	0	2	0	1	0	3	0	0	1	0	1	2	4	3	0	7	24	
	Total	10	0	19	20	0	21	0	12	2	13	64	28	8	27	39	37	49	59	408	
Sub Total Violations		15	0	30	30	0	34	0	27	13	17	17	51	15	38	73	85	23	61	529	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution		15	0	30	30	0	34	0	27	13	17	17	51	15	38	73	85	23	61	529	
Less Rejects																					
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	2-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-10%	0-00%	0-00%	0-00%	0-00%	4-17%	0-00%	11-02%	
	Face Camera Focus Blurry	2-13%	0-00%	0-00%	6-20%	0-00%	5-15%	0-00%	0-00%	0-00%	0-00%	2-12%	5-10%	0-00%	10-26%	1-01%	3-04%	7-30%	7-11%	48-09%	
	Face Not in Frame	0-00%	0-00%	6-20%	2-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	5-29%	4-08%	1-07%	5-13%	5-07%	1-01%	1-04%	4-07%	35-07%
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-08%	0-00%	0-00%	0-00%	0-00%	3-01%
	Plate Burn Out	2-13%	0-00%	1-03%	0-00%	0-00%	2-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	27-37%	0-00%	0-00%	1-02%	34-06%
	Plate Not in Frame	2-13%	0-00%	2-07%	0-00%	0-00%	1-03%	0-00%	1-04%	0-00%	0-00%	0-00%	1-02%	0-00%	2-05%	0-00%	1-01%	1-04%	0-00%	11-02%	

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:19:09 AM

Customer Management Report (Ventura) All Detection Types

01-Apr-2003 to 30-Apr-2003

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Rear Plate Camera Blurry	1-07%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	2-13%	0-00%	2-03%	0-00%	0-00%	6-10%	13-02%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Process Issues Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	1-02%	2-00%
Total	7-47%	0-00%	10-33%	10-33%	0-00%	9-26%	0-00%	1-04%	1-08%	2-12%	8-47%	16-31%	5-33%	20-53%	36-49%	5-06%	13-57%	19-31%	162-31%
Approved Violations	8-53%	0-00%	20-67%	20-67%	0-00%	25-74%	0-00%	26-96%	12-92%	15-88%	9-53%	35-69%	10-67%	18-47%	37-51%	80-94%	10-43%	42-69%	367-69%
Total Notices Printed	8-53%	0-00%	20-67%	20-67%	0-00%	25-74%	0-00%	26-96%	12-92%	15-88%	9-53%	35-69%	10-67%	18-47%	37-51%	80-94%	10-43%	42-69%	367-69%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:19:09 AM

Customer Management Report (Ventura) All Detection Types

01-May-2013 to 31-May-2013

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents		11	179	7	13	65	16	29	79	65	5	21	35	25	45	34	62	38	74	803	
Less Uncontrollable Factors																					
Obstruction	Driver Obstruction/Duckers	0	9	1	1	5	1	1	0	1	0	2	3	2	0	8	2	3	2	41	
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	2	3
	Plate Obstruction	0	6	0	1	5	0	1	0	0	0	1	0	1	1	0	0	0	0	1	17
	Vehicle Obstruction	1	5	0	0	3	0	0	1	0	1	0	0	0	0	0	0	1	1	0	13
Police Rejects	Driver Obstruction (PD)	0	2	0	0	3	0	0	1	0	0	1	1	0	0	0	2	0	2	12	
	Incorrect/Incomplete DMV	0	1	0	0	0	0	1	0	0	0	0	0	0	0	1	0	0	0	3	
	Multiple vehicles in frame	0	4	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	5	
	On or Passed the Stop Bar (PD)	0	0	0	1	2	0	0	0	3	0	0	4	1	1	0	0	0	0	12	
	Plate Obstruction (PD)	1	0	0	2	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1	5
	Plate Unidentifiable	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1	2
	Safe Turn On Red	0	51	0	0	0	0	0	28	3	0	0	0	0	0	0	0	0	0	6	88
	Sun Glare	0	3	0	0	2	0	0	0	0	0	0	0	1	1	0	1	5	4	17	
	Extended Vehicle	0	1	0	0	0	0	1	0	0	1	0	1	0	0	0	0	0	0	0	4
Sun Glare	2	15	0	0	4	3	5	1	9	1	0	1	4	13	3	1	3	12	77		
Registration Issues	Paper Plates	0	8	2	0	1	0	2	3	4	0	1	0	1	1	2	2	2	3	32	
	Wrong or No DMV	0	3	0	2	0	0	0	0	4	0	0	2	0	2	0	3	0	0	16	
Total		4	108	3	7	26	4	11	34	25	4	5	13	10	19	14	12	14	34	347	
Sub Total Violations		7	71	4	6	39	12	18	45	40	1	16	22	15	26	20	50	24	40	456	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution		7	71	4	6	39	12	18	45	40	1	16	22	15	26	20	50	24	40	456	
Less Rejects																					
Camera Malfunction	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:20:35 AM

Customer Management Report (Ventura) All Detection Types

01-May-2013 to 31-May-2013

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Misc Camera Issue	0-00%	0-00%	0-00%	2-33%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Plate Burn Out	1-14%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-11%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Police Rejects Process Issues																			
Driver Unidentifiable images poor	0-00%	6-08%	1-25%	0-00%	1-03%	1-08%	6-33%	1-02%	3-08%	0-00%	0-00%	2-09%	0-00%	3-12%	5-25%	1-02%	3-12%	1-02%	34-07%
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	1-14%	6-08%	1-25%	2-33%	1-03%	2-17%	10-56%	1-02%	4-10%	0-00%	0-00%	3-14%	1-07%	3-12%	5-25%	1-02%	3-12%	1-02%	45-10%
Approved Violations	6-86%	65-92%	3-75%	4-67%	38-97%	10-83%	8-44%	44-98%	36-90%	1-100%	16-100%	19-86%	14-93%	23-88%	15-75%	49-98%	21-88%	39-98%	411-90%
Total Notices Printed	6-86%	65-92%	3-75%	4-67%	38-97%	10-83%	8-44%	44-98%	36-90%	1-100%	16-100%	19-86%	14-93%	23-88%	15-75%	49-98%	21-88%	39-98%	411-90%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:20:35 AM

Customer Management Report (Ventura) All Detection Types

01-Jun-2013 to 30-Jun-2013

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents		15	176	4	28	56	23	26	95	67	9	27	62	40	50	27	37	37	62	841
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	0	10	1	0	4	1	2	0	1	0	0	2	1	0	1	1	1	2	27
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
	Plate Obstruction	0	4	0	0	2	0	0	2	0	0	1	1	0	0	0	0	0	0	10
	Vehicle Obstruction	1	1	0	0	0	0	1	0	0	2	0	1	0	2	0	0	0	0	8
Police Rejects	Driver Obstruction (PD)	0	2	0	0	0	1	0	1	2	0	0	0	0	0	2	2	0	2	12
	Invalid Offense	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	2
	Multiple vehicles in frame	0	5	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	5
	On or Passed the Stop Bar (PD)	0	1	0	2	1	0	0	0	0	0	0	4	1	1	0	0	1	0	11
	Plate Obstruction (PD)	0	0	0	1	0	1	0	0	0	0	0	2	0	0	0	0	0	0	4
	Plate Unidentifiable	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
	Safe Turn On Red	0	47	0	0	0	0	0	33	7	0	0	0	0	0	0	0	0	7	94
	Sun Glare	0	7	0	1	0	1	2	1	2	0	1	0	0	1	0	1	2	1	20
	Policy/Weather	Extended Vehicle	0	0	0	0	0	0	0	0	0	2	2	0	0	0	0	0	0	0
	Sun Glare	3	24	0	5	0	4	6	4	6	2	4	5	7	2	0	9	5	86	
Registration Issues	Paper Plates	0	1	0	1	1	0	0	2	2	0	0	2	2	3	1	2	1	3	21
	Wrong or No DMV	1	4	0	2	2	0	1	5	3	0	0	0	2	0	0	2	2	1	25
Total		6	107	1	12	10	8	12	48	23	4	4	18	11	14	8	8	16	22	332
Sub Total Violations		9	69	3	16	46	15	14	47	44	5	23	44	29	36	19	29	21	40	509
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		9	69	3	16	46	15	14	47	44	5	23	44	29	36	19	29	21	40	509
Less Rejects																				
Camera Malfunction	Face Not in Frame	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-03%	0-00%	0-00%	0-00%	0-00%	3-01%
	Misc Camera Issue	0-00%	0-00%	1-33%	1-06%	3-07%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:21:23 AM

Customer Management Report (Ventura) All Detection Types

01-Jun-2013 to 30-Jun-2013

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Rejects Process Issues																			
Driver Unidentifiable images poor	1-11%	14-20%	0-00%	1-06%	4-09%	4-27%	5-36%	0-00%	3-07%	1-20%	1-04%	2-05%	5-17%	8-22%	5-26%	4-14%	1-05%	3-08%	62-12%
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	1-11%	14-20%	1-33%	3-19%	7-15%	4-27%	7-50%	1-02%	3-07%	1-20%	1-04%	3-07%	6-21%	10-28%	5-26%	4-14%	1-05%	3-08%	75-15%
Approved Violations	8-89%	55-80%	2-67%	13-81%	39-85%	11-73%	7-50%	46-98%	41-93%	4-80%	22-96%	41-93%	23-79%	26-72%	14-74%	25-86%	20-95%	37-92%	434-85%
Total Notices Printed	8-89%	55-80%	2-67%	13-81%	39-85%	11-73%	7-50%	46-98%	41-93%	4-80%	22-96%	41-93%	23-79%	26-72%	14-74%	25-86%	20-95%	37-92%	434-85%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:21:23 AM

Customer Management Report (Ventura) All Detection Types

01-Aug-2013 to 31-Aug-2013

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents	12	200	13	21	127	45	35	100	87	15	51	61	31	43	25	48	70	73	1057	
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	1	18	1	2	7	2	1	6	2	0	0	4	3	3	4	2	1	6	63
	Motor Cycle Helmet	0	1	0	0	1	0	0	0	0	0	0	0	0	0	1	0	0	0	3
	Plate Obstruction	1	7	0	2	2	2	1	0	0	2	0	3	0	0	0	1	2	1	24
	Vehicle Obstruction	0	5	0	0	4	0	2	0	0	4	1	3	0	0	0	0	0	0	19
Police Rejects	Driver Obstruction (PD)	0	3	0	0	2	1	0	0	3	0	1	1	1	0	1	3	1	0	17
	Emergency Vehicle Responding	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1
	Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2	0	0	2
	Multiple vehicles in frame	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
	On or Passed the Stop Bar (PD)	0	0	0	0	0	0	2	0	0	0	0	1	6	0	0	0	0	0	9
	Plate Obstruction (PD)	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Safe Turn On Red	0	30	0	0	0	0	0	33	4	0	0	0	0	0	0	0	0	10	77
	Sun Glare	0	10	0	0	3	0	0	1	4	0	1	1	0	1	1	0	4	4	30
Policy/Weather	Extended Vehicle	0	0	0	0	1	0	1	0	0	0	1	0	0	0	0	0	0	0	3
	Sun Glare	7	40	7	1	12	9	13	3	15	3	7	0	5	14	2	0	8	12	158
	Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1
	Yellow with Red Light	1	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	2
Registration Issues	Out of Country Plate	0	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	2
	Paper Plates	0	7	0	0	2	1	1	2	1	0	1	2	0	2	1	3	1	1	25
	Wrong or No DMV	0	4	1	1	4	2	0	2	7	0	0	1	1	0	1	0	3	4	31
Total		10	127	9	7	38	17	21	47	37	9	14	17	16	21	11	11	20	38	470
Sub Total Violations		2	73	4	14	89	28	14	53	50	6	37	44	15	22	14	37	50	35	587
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		2	73	4	14	89	28	14	53	50	6	37	44	15	22	14	37	50	35	587

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:22:18 AM

Customer Management Report (Ventura) All Detection Types

01-Aug-2013 to 31-Aug-2013

Operator Id: %

		VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Less Rejects																					
Camera Malfunction	Face Camera Flash	0-00%	1-01%	0-00%	0-00%	0-00%	1-04%	2-14%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%	
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Camera No Flash	1-50%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Not in Frame	0-00%	0-00%	1-25%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	1-17%	0-00%	0-00%	2-13%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	4-01%	
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	1-50%	9-12%	0-00%	3-21%	1-01%	4-14%	1-07%	0-00%	2-04%	0-00%	0-00%	2-05%	1-07%	1-05%	1-07%	2-05%	3-06%	1-03%	32-05%	
	Incorrect Speed	0-00%	0-00%	0-00%	0-00%	4-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%	
Total		2-100%	10-14%	1-25%	3-21%	7-08%	7-25%	7-50%	1-02%	2-04%	2-33%	0-00%	5-11%	4-27%	1-05%	2-14%	2-05%	3-06%	1-03%	60-10%	
Approved Violations		0-00%	63-86%	3-75%	11-79%	82-92%	21-75%	7-50%	52-98%	48-96%	4-67%	37-100%	39-89%	11-73%	21-95%	12-86%	35-95%	47-94%	34-97%	527-90%	
Total Notices Printed		0-00%	63-86%	3-75%	11-79%	82-92%	21-75%	7-50%	52-98%	48-96%	4-67%	37-100%	39-89%	11-73%	21-95%	12-86%	35-95%	47-94%	34-97%	527-90%	

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:22:18 AM

Customer Management Report (Ventura) All Detection Types

01-Sep-2013 to 30-Sep-2013

Operator Id: %

		VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents		16	179	6	14	136	59	40	91	71	13	42	73	18	50	102	65	53	61	1089
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	1	16	0	0	4	4	4	1	1	0	0	6	1	2	23	0	1	0	64
	Motor Cycle Helmet	0	1	1	0	1	0	0	0	4	1	0	0	0	0	0	0	1	0	9
	Plate Obstruction	1	4	0	1	3	1	2	0	0	2	1	5	0	0	1	0	0	1	22
	Vehicle Obstruction	2	4	0	0	7	0	3	0	1	2	3	0	0	0	3	0	1	1	27
Police Rejects	Driver Obstruction (PD)	0	1	0	0	0	1	0	1	1	0	1	1	0	0	1	0	1	0	8
	Incorrect/Incomplete DMV	0	1	0	0	0	0	0	1	0	0	0	1	0	0	1	0	0	0	4
	Multiple vehicles in frame	0	5	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	6
	On or Passed the Stop Bar (PD)	1	4	0	0	1	2	0	0	0	0	0	3	1	1	0	0	0	0	13
	Plate Obstruction (PD)	0	0	0	1	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2
	Plate Unidentifiable	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Safe Turn On Red	0	44	0	0	0	0	0	32	5	0	0	0	0	0	0	0	0	13	94
	Sun Glare	0	5	0	1	2	0	2	1	3	0	2	0	0	1	3	0	2	3	25
	Extended Vehicle	1	1	0	0	1	0	0	0	0	0	1	2	0	0	0	0	0	1	7
	Sun Glare	1	30	1	1	14	14	12	1	8	2	2	2	3	21	5	2	7	12	138
Registration Issues	Paper Plates	0	8	0	0	6	4	0	2	2	0	0	1	0	1	2	4	0	0	30
	Wrong or No DMV	1	1	0	2	1	2	0	2	2	0	0	2	0	1	2	1	1	5	23
Total		8	126	2	7	40	28	23	42	27	7	10	23	5	27	41	7	14	36	473
Sub Total Violations		8	53	4	7	96	31	17	49	44	6	32	50	13	23	61	58	39	25	616
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		8	53	4	7	96	31	17	49	44	6	32	50	13	23	61	58	39	25	616
Less Rejects																				
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	5-16%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:22:43 AM

Customer Management Report (Ventura) All Detection Types

01-Sep-2013 to 30-Sep-2013

Operator Id: %

	VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Face Not in Frame	0-00%	0-00%	1-25%	0-00%	0-00%	0-00%	2-12%	0-00%	0-00%	2-33%	0-00%	0-00%	1-08%	0-00%	2-03%	0-00%	0-00%	0-00%	8-01%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	27-28%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	28-05%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Rejects																			
Driver Unidentifiable images poor	2-25%	9-17%	0-00%	0-00%	0-00%	2-06%	4-24%	1-02%	2-05%	0-00%	0-00%	6-12%	0-00%	3-13%	2-03%	0-00%	0-00%	2-08%	33-05%
Incorrect Speed	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues																			
Too Old	0-00%	0-00%	1-25%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	2-00%
Total	2-25%	10-19%	2-50%	0-00%	29-30%	8-26%	10-59%	3-06%	2-05%	2-33%	1-03%	9-18%	2-15%	3-13%	4-07%	0-00%	0-00%	3-12%	90-15%
Approved Violations	6-75%	43-81%	2-50%	7-100%	67-70%	23-74%	7-41%	46-94%	42-95%	4-67%	31-97%	41-82%	11-85%	20-87%	57-93%	58-100%	39-100%	22-88%	526-85%
Total Notices Printed	6-75%	43-81%	2-50%	7-100%	67-70%	23-74%	7-41%	46-94%	42-95%	4-67%	31-97%	41-82%	11-85%	20-87%	57-93%	58-100%	39-100%	22-88%	526-85%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:22:43 AM

Customer Management Report (Ventura) All Detection Types

01-Nov-2013 to 30-Nov-2013

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents		15	141	6	20	130	36	40	74	77	10	28	70	20	43	85	46	58	82	981
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	1	11	1	0	1	2	2	0	4	0	1	4	2	2	12	0	1	6	50
	Motor Cycle Helmet	0	0	1	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	3
	Plate Obstruction	0	3	0	2	2	2	0	0	0	0	0	1	0	0	0	0	0	0	10
	Vehicle Obstruction	1	7	0	0	9	0	3	1	0	2	0	1	0	1	8	1	1	0	35
Police Rejects	Driver Obstruction (PD)	0	0	0	0	0	1	0	0	3	0	0	1	0	0	3	0	5	0	13
	Invalid Offense	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
	Multiple vehicles in frame	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	2
	On or Passed the Stop Bar (PD)	1	0	0	0	0	0	0	0	0	1	0	1	1	1	0	0	0	0	5
	Plate Obstruction (PD)	0	1	0	1	0	1	0	0	0	0	0	0	0	0	1	0	0	0	7
	Plate Unidentifiable	1	1	0	0	0	0	1	0	0	0	1	0	0	0	0	0	0	0	5
	Safe Turn On Red	0	30	0	0	0	0	0	26	5	0	0	0	0	0	0	0	0	10	71
	Sun Glare	0	15	0	0	0	0	3	1	3	0	0	1	1	3	1	2	2	4	36
	Policy/Weather	Extended Vehicle	0	0	0	0	1	1	0	0	0	0	0	5	0	0	0	0	0	2
	Sun Glare	1	23	0	2	1	2	5	1	5	0	2	2	2	13	3	0	0	7	69
Registration Issues	Paper Plates	0	4	1	1	3	0	1	1	4	0	0	2	0	0	4	0	0	2	23
	Wrong or No DMV	0	1	0	0	5	2	1	1	7	0	2	1	0	1	1	1	1	0	24
Total		5	97	3	7	23	11	16	31	31	3	6	19	6	21	34	4	11	35	363
Sub Total Violations		10	44	3	13	107	25	24	43	46	7	22	51	14	22	51	42	47	47	618
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		10	44	3	13	107	25	24	43	46	7	22	51	14	22	51	42	47	47	618
Less Rejects																				
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-14%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
	Face Camera Flash	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	2-08%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:23:24 AM

Customer Management Report (Ventura) All Detection Types

01-Nov-2013 to 30-Nov-2013

Operator Id: %

	VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Not in Frame	1-10%	0-00%	0-00%	1-08%	0-00%	0-00%	4-17%	0-00%	0-00%	5-71%	1-05%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	14-02%
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	4-04%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	4-09%	0-00%	10-02%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	2-05%	0-00%	0-00%	0-00%	3-06%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	7-01%
Police Rejects																			
Driver Unidentifiable images poor	2-20%	10-23%	1-33%	0-00%	2-02%	4-16%	5-21%	1-02%	0-00%	0-00%	0-00%	2-04%	0-00%	3-14%	6-12%	0-00%	0-00%	5-11%	41-07%
Incorrect Speed	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	3-30%	12-27%	1-33%	1-08%	7-07%	4-16%	13-54%	9-21%	3-07%	5-71%	1-05%	8-16%	1-07%	3-14%	8-16%	0-00%	4-09%	6-13%	89-14%
Approved Violations	7-70%	32-73%	2-67%	12-92%	100-93%	21-84%	11-46%	34-79%	43-93%	2-29%	21-95%	43-84%	13-93%	19-86%	43-84%	42-100%	43-91%	41-87%	529-86%
Total Notices Printed	7-70%	32-73%	2-67%	12-92%	100-93%	21-84%	11-46%	34-79%	43-93%	2-29%	21-95%	43-84%	13-93%	19-86%	43-84%	42-100%	43-91%	41-87%	529-86%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:23:24 AM

Customer Management Report (Ventura) All Detection Types

01-Dec-2013 to 31-Dec-2013

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents	11	108	2	15	150	36	46	100	68	8	41	66	0	46	80	48	59	62	946	
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	0	21	1	2	5	11	5	2	7	0	0	5	0	10	20	1	3	3	96
	Motor Cycle Helmet	0	0	0	0	1	0	0	0	1	0	0	0	0	0	0	0	0	1	3
	Plate Obstruction	2	1	1	2	3	1	2	1	2	1	0	3	0	0	1	1	0	0	21
	Signal Obstruction	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Vehicle Obstruction	0	9	0	0	4	0	8	1	0	2	1	2	0	1	5	0	2	1	36
Police Rejects	Driver Obstruction (PD)	0	0	0	0	1	0	0	2	2	0	0	1	0	0	2	0	5	1	14
	Incorrect/Incomplete DMV	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1	0	2
	Invalid Offense	0	1	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	3
	On or Passed the Stop Bar (PD)	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	2
	Plate Obstruction (PD)	0	0	0	0	0	1	1	1	0	0	0	1	0	0	0	0	0	0	4
	Plate Unidentifiable	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
	Safe Turn On Red	0	16	0	0	0	0	0	29	5	0	0	0	0	0	0	0	0	11	61
	Sun Glare	0	9	0	0	0	2	3	0	2	0	3	0	0	2	1	4	0	4	30
Policy/Weather	Extended Vehicle	0	0	0	0	1	0	0	0	1	0	1	1	0	0	0	0	0	0	4
	Sun Glare	0	22	0	1	0	0	5	1	6	1	1	0	0	9	0	1	1	7	55
Registration Issues	Out of Country Plate	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Paper Plates	0	3	0	0	2	2	0	3	2	0	3	1	0	3	3	1	0	2	25
	Wrong or No DMV	2	2	0	1	2	1	0	3	2	0	0	2	0	2	3	0	0	0	20
Total		5	85	2	7	19	19	25	43	30	4	11	16	0	27	36	8	12	30	379
Sub Total Violations		6	23	0	8	131	17	21	57	38	4	30	50	0	19	44	40	47	32	567
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		6	23	0	8	131	17	21	57	38	4	30	50	0	19	44	40	47	32	567

Less Rejects

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:24:24 AM

Customer Management Report (Ventura) All Detection Types

01-Dec-2013 to 31-Dec-2013

Operator Id: %

		VE-BRU0-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Camera Malfunction	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-14%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%	
	Face Not in Frame	1-17%	0-00%	0-00%	0-00%	2-02%	0-00%	3-14%	0-00%	0-00%	3-75%	1-03%	0-00%	0-00%	0-00%	4-09%	0-00%	0-00%	0-00%	14-02%	
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Misc Camera Issue	1-17%	0-00%	0-00%	0-00%	10-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	13-02%	
	Plate Burn Out	0-00%	0-00%	0-00%	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-25%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	2-02%	1-06%	0-00%	2-04%	0-00%	0-00%	3-10%	1-02%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	10-02%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-10%	2-04%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	6-01%	
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
Police Rejects Process Issues	Driver Unidentifiable images poor	3-50%	6-26%	0-00%	0-00%	0-00%	3-18%	5-24%	2-04%	1-03%	0-00%	2-07%	4-08%	0-00%	4-21%	2-05%	0-00%	1-02%	1-03%	34-06%	
	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Total		5-83%	6-26%	0-00%	1-12%	14-11%	4-24%	13-62%	7-12%	2-05%	4-100%	9-30%	10-20%	0-00%	4-21%	7-16%	0-00%	1-02%	3-09%	90-16%	
Approved Violations		1-17%	17-74%	0-00%	7-88%	117-89%	13-76%	8-38%	50-88%	36-95%	0-00%	21-70%	40-80%	0-00%	15-79%	37-84%	40-100%	46-98%	29-91%	477-84%	
Total Notices Printed		1-17%	17-74%	0-00%	7-88%	117-89%	13-76%	8-38%	50-88%	36-95%	0-00%	21-70%	40-80%	0-00%	15-79%	37-84%	40-100%	46-98%	29-91%	477-84%	

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:24:24 AM

Customer Management Report (Ventura) All Detection Types

01-Jan-2013 to 31-Dec-2013

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents		179	1986	78	199	1043	418	436	1068	864	132	429	642	296	562	633	550	621	816	10952	
Less Uncontrollable Factors																					
Obstruction	Driver Obstruction/Duckers	9	140	20	12	33	36	38	32	36	2	12	33	19	34	105	16	21	40	638	
	Motor Cycle Helmet	0	3	3	3	6	0	1	0	12	1	1	1	1	2	5	0	2	6	47	
	Plate Obstruction	11	55	3	15	24	13	15	11	6	19	6	26	2	1	5	5	3	10	230	
	Signal Obstruction	0	0	0	1	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2
	Vehicle Obstruction	5	50	2	1	36	0	23	5	2	24	8	20	4	4	26	2	8	10	230	
Police Rejects	Citation Issued manually	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
	Driver Obstruction (PD)	1	23	0	2	10	4	1	10	27	1	7	12	1	1	13	12	17	6	148	
	Emergency Vehicle Responding	0	0	0	0	0	0	1	2	2	0	1	0	0	0	0	1	1	1	9	
	Incorrect/Incomplete DMV	0	3	0	1	0	2	1	2	3	0	3	1	0	1	2	2	3	0	24	
	Invalid Offense	0	1	0	0	3	0	0	0	0	0	2	0	0	0	2	2	0	1	11	
	Multiple vehicles in frame	1	37	0	1	1	2	2	0	0	1	0	2	0	0	0	0	1	0	48	
	On or Passed the Stop Bar (PD)	6	13	0	8	9	5	6	8	13	2	1	28	25	8	1	0	1	2	136	
	Plate Obstruction (PD)	1	4	0	6	4	4	1	4	0	0	0	5	1	0	2	1	0	4	37	
	Plate Unidentifiable	3	4	1	0	0	0	2	2	1	1	1	0	0	0	1	0	1	2	19	
	Safe Turn On Red	0	469	0	0	0	0	0	370	60	0	0	0	0	0	0	0	0	103	1002	
	Sun Glare	4	64	1	5	12	8	12	8	21	1	10	2	2	14	11	12	27	26	240	
	Policy/Weather	Extended Vehicle	2	7	0	1	7	2	3	1	2	1	5	28	1	0	0	0	1	4	65
		Sun Glare	24	296	10	17	51	60	92	26	98	14	33	14	56	178	51	24	45	159	1248
Weather/Nature		1	0	0	2	0	0	0	0	0	0	0	0	0	1	2	0	1	0	7	
Yellow with Red Light		1	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0	0	1	4	
Registration Issues	Authorized Vehicles	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
	Out of Country Plate	0	2	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	1	6	
	Paper Plates	3	58	4	2	23	10	10	28	23	4	16	15	5	19	20	18	10	25	293	

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:36:47 AM

Customer Management Report (Ventura) All Detection Types

01-Jan-2013 to 31-Dec-2013

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Wrong or No DMV	11	34	2	12	20	12	10	32	36	2	11	18	7	11	19	16	22	22	297
Total	83	1264	46	89	240	158	218	541	343	73	121	205	124	275	265	111	164	423	4743
Sub Total Violations	96	722	32	110	803	260	218	527	521	59	308	437	172	287	368	439	457	393	6209
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	96	722	32	110	803	260	218	527	521	59	308	437	172	287	368	439	457	393	6209
Less Rejects																			
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	6-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-00%
Face Camera Flash	0-00%	3-00%	0-00%	0-00%	0-00%	6-02%	5-02%	0-00%	4-01%	0-00%	1-00%	0-00%	1-01%	2-01%	0-00%	0-00%	1-00%	3-01%	26-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	7-03%	0-00%	0-00%	0-00%	1-00%	1-00%	1-01%	1-00%	1-00%	1-00%	0-00%	0-00%	14-00%
Face Camera No Flash	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Face Not in Frame	4-04%	1-00%	4-12%	2-02%	2-00%	0-00%	27-12%	4-01%	0-00%	13-22%	3-01%	2-00%	7-04%	1-00%	10-03%	0-00%	0-00%	1-00%	81-01%
Image Missing	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	3-01%	0-00%	0-00%	1-00%	0-00%	0-00%	2-01%	9-00%
Misc Camera Issue	1-01%	0-00%	2-06%	3-03%	52-06%	2-01%	7-03%	1-00%	2-00%	0-00%	0-00%	4-01%	2-01%	0-00%	3-01%	0-00%	8-02%	3-01%	90-01%
Plate Burn Out	2-02%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%	0-00%	2-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	7-00%
Plate Not in Frame	1-01%	0-00%	0-00%	2-02%	4-00%	2-01%	1-00%	3-01%	0-00%	6-10%	0-00%	1-00%	1-01%	0-00%	1-00%	0-00%	0-00%	0-00%	22-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	3-00%	1-00%	1-00%	2-00%	0-00%	0-00%	4-01%	2-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%	15-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-01%	0-00%	5-02%	0-00%	0-00%	0-00%	1-02%	3-01%	1-00%	1-01%	0-00%	1-00%	0-00%	0-00%	0-00%	13-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	2-01%	9-02%	0-00%	0-00%	0-00%	7-02%	2-01%	0-00%	0-00%	0-00%	0-00%	2-01%	24-00%
Scene Image No Flash	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	11-05%	7-01%	0-00%	0-00%	0-00%	9-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	29-00%
Police Rejects	23-24%	102-14%	4-12%	7-06%	11-01%	44-17%	46-21%	16-03%	25-05%	1-02%	6-02%	36-08%	11-06%	49-17%	34-09%	31-07%	15-03%	41-10%	502-08%
Incorrect Speed	0-00%	2-00%	0-00%	0-00%	4-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-00%
No Images	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Process Issues	0-00%	2-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	1-00%	0-00%	1-01%	1-00%	1-00%	0-00%	0-00%	1-00%	10-00%
Total	32-33%	110-15%	12-38%	17-15%	82-10%	61-23%	108-50%	50-09%	36-07%	21-36%	20-06%	66-15%	27-16%	54-19%	54-15%	32-07%	24-05%	56-14%	862-14%

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:36:47 AM

Customer Management Report (Ventura) All Detection Types

01-Jan-2013 to 31-Dec-2013

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Approved Violations	64-67%	612-85%	20-62%	93-85%	721-90%	199-77%	110-50%	477-91%	485-93%	38-64%	288-94%	371-85%	145-84%	233-81%	314-85%	407-93%	433-95%	337-86%	5347-86%
Total Notices Printed	64-67%	612-85%	20-62%	93-85%	721-90%	199-77%	110-50%	477-91%	485-93%	38-64%	288-94%	371-85%	145-84%	233-81%	314-85%	407-93%	433-95%	337-86%	5347-86%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:36:47 AM

Customer Management Report (Ventura) All Detection Types

01-Feb-2014 to 28-Feb-2014

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents	13	159	1	16	126	32	31	81	56	4	38	71	16	30	69	56	51	68	918	
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	6	58	1	2	12	5	12	4	10	0	6	6	6	10	14	6	3	18	179
	Motor Cycle Helmet	0	0	0	0	2	1	0	1	1	0	0	0	0	0	0	0	0	0	5
	Plate Obstruction	0	0	0	0	1	0	0	0	0	1	0	3	0	0	1	1	0	3	10
	Vehicle Obstruction	0	13	0	1	5	0	3	0	2	0	0	5	0	0	4	0	0	1	34
Police Rejects	Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2	1	3
	Multiple vehicles in frame	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
	Plate Obstruction (PD)	0	0	0	0	1	0	0	0	0	0	1	0	0	0	0	0	0	0	2
	Plate Unidentifiable	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Police Discretion	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1	0	0	2
	Safe Turn On Red	0	32	0	0	0	0	19	3	0	0	0	0	0	0	0	0	0	12	66
	Sun Glare	1	2	0	1	2	1	0	1	0	1	1	0	3	1	0	1	2	2	17
Policy/Weather	Extended Vehicle	0	1	0	0	2	0	0	1	0	1	6	0	0	0	0	0	0	0	11
	Sun Glare	0	3	0	1	3	0	2	0	1	1	3	1	4	1	0	0	0	0	20
	Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
	Paper Plates	0	1	0	4	2	0	1	1	0	1	2	1	1	0	1	4	5	5	25
	Wrong or No DMV	1	5	0	0	1	1	4	4	0	1	0	0	1	0	1	3	2	2	24
Total		8	117	1	10	31	8	18	29	23	2	12	28	9	19	21	10	13	44	403
Sub Total Violations		5	42	0	6	95	24	13	52	33	2	26	43	7	11	48	46	38	24	515
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		5	42	0	6	95	24	13	52	33	2	26	43	7	11	48	46	38	24	515

Less Rejects

Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-15%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-04%	5-01%
--------------------	-------------------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:29:32 AM

Customer Management Report (Ventura) All Detection Types

01-Feb-2014 to 28-Feb-2014

Operator Id: %

	VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Manufacturing																				
	Face Camera Focus Blurry	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-50%	0-00%	2-05%	1-14%	0-00%	4-08%	0-00%	0-00%	0-00%	9-02%	
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Misc Camera Issue	0-00%	0-00%	0-00%	1-17%	3-03%	0-00%	0-00%	0-00%	0-00%	1-04%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%	
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	2-02%	1-04%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%	
	Rear Plate No Flash	0-00%	0-00%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	2-15%	0-00%	0-00%	0-00%	0-00%	3-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%	
Police Rejects	Driver Unidentifiable images poor	0-00%	6-14%	0-00%	0-00%	0-00%	3-12%	2-15%	1-03%	0-00%	0-00%	3-07%	0-00%	0-00%	0-00%	2-04%	1-03%	1-04%	19-04%	
	Incorrect Speed	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	2-08%	0-00%	2-29%	0-00%	0-00%	2-04%	0-00%	0-00%	7-01%	
Total		0-00%	7-17%	0-00%	2-33%	7-07%	5-21%	6-46%	2-06%	1-50%	5-19%	10-23%	3-43%	0-00%	5-10%	4-09%	1-03%	2-08%	60-12%	
Approved Violations		5-100%	35-83%	0-00%	4-67%	88-93%	19-79%	7-54%	52-100%	31-94%	1-50%	21-81%	33-77%	4-57%	11-100%	43-90%	42-91%	37-97%	22-92%	455-88%
Total Notices Printed		5-100%	35-83%	0-00%	4-67%	88-93%	19-79%	7-54%	52-100%	31-94%	1-50%	21-81%	33-77%	4-57%	11-100%	43-90%	42-91%	37-97%	22-92%	455-88%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:29:32 AM

Customer Management Report (Ventura) All Detection Types

01-Jun-2014 to 30-Jun-2014

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents	23	202	6	28	158	23	31	94	70	4	78	83	18	36	48	50	51	49	1052	
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	1	22	0	1	0	0	1	2	2	0	0	1	4	2	7	1	1	1	46
	Motor Cycle Helmet	1	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2
	Plate Obstruction	0	2	0	1	2	0	0	0	0	3	2	1	0	0	0	0	0	2	13
	Vehicle Obstruction	2	5	0	0	0	0	3	2	1	2	2	4	0	1	3	0	0	0	25
Police Rejects	Citation Issued manually	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Driver Obstruction (PD)	0	6	0	0	1	0	0	1	3	0	1	1	0	0	1	1	1	0	16
	Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	0	1	0	1	0	0	0	0	0	2
	Invalid Offense	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Multiple vehicles in frame	0	2	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	3
	On or Passed the Stop Bar (PD)	1	1	0	2	0	0	0	0	0	0	0	2	0	0	0	0	0	0	6
	Plate Obstruction (PD)	0	0	0	0	1	1	0	0	1	0	0	0	0	0	1	1	0	0	5
	Plate Unidentifiable	0	0	0	0	2	0	0	0	0	0	0	1	0	0	0	0	0	0	3
	Safe Turn On Red	0	55	0	0	0	0	26	1	0	0	0	0	0	0	0	0	1	6	89
	Sun Glare	1	10	2	4	6	1	3	0	3	0	4	2	0	5	2	3	2	5	53
Policy/Weather	Extended Vehicle	0	2	0	0	0	0	2	0	0	0	9	0	0	0	0	0	0	0	13
	Sun Glare	5	17	2	0	11	6	12	2	1	0	4	4	1	10	6	4	7	8	100
	Weather/Nature	1	0	0	0	2	0	0	0	1	0	0	0	0	0	0	0	0	0	4
Registration Issues	Out of Country Plate	0	0	0	1	0	0	0	0	0	1	0	0	0	0	0	0	0	0	2
	Paper Plates	0	4	0	3	2	1	0	1	1	0	2	1	0	0	1	2	2	1	21
	Wrong or No DMV	0	3	0	0	2	0	1	3	0	0	2	2	0	2	2	2	3	2	24
Total		12	129	4	12	31	9	22	37	15	2	19	27	9	21	23	14	17	26	429
Sub Total Violations		11	73	2	16	127	14	9	57	55	2	59	56	9	15	25	36	34	23	623
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:26:49 AM

Customer Management Report (Ventura) All Detection Types

01-Jun-2014 to 30-Jun-2014

Operator Id: %

	VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Available For Prosecution	11	73	2	16	127	14	9	57	55	2	59	56	9	15	25	36	34	23	623	
Less Rejects																				
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	1-06%	0-00%	2-14%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	1-04%	6-01%
	Face Camera Focus Blurry	0-00%	0-00%	1-50%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-22%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	1-02%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Police Rejects	Driver Unidentifiable images poor	4-36%	10-14%	0-00%	1-06%	0-00%	1-07%	3-33%	3-05%	5-09%	0-00%	2-03%	5-09%	2-22%	0-00%	5-20%	2-06%	0-00%	4-17%	47-08%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	Too Old	1-09%	1-01%	1-50%	1-06%	1-01%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-03%	0-00%	0-00%	0-00%	8-01%
Total		5-45%	11-15%	2-100%	3-19%	3-02%	4-29%	6-67%	3-05%	7-13%	0-00%	3-05%	9-16%	4-44%	0-00%	7-28%	3-08%	0-00%	5-22%	75-12%
Approved Violations		6-55%	62-85%	0-00%	13-81%	124-98%	10-71%	3-33%	54-95%	48-87%	2-100%	56-95%	47-84%	5-56%	15-100%	18-72%	33-92%	34-100%	18-78%	548-88%
Total Notices Printed		6-55%	62-85%	0-00%	13-81%	124-98%	10-71%	3-33%	54-95%	48-87%	2-100%	56-95%	47-84%	5-56%	15-100%	18-72%	33-92%	34-100%	18-78%	548-88%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:26:49 AM

Customer Management Report (Ventura) All Detection Types

01-Sep-2014 to 30-Sep-2014

Operator Id: %

		VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents		24	113	8	16	147	54	37	100	89	12	37	94	24	43	100	85	68	84	1135
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	3	6	1	0	3	4	2	3	3	1	1	6	1	2	17	5	3	5	66
	Motor Cycle Helmet	0	1	0	0	0	0	0	0	1	0	0	0	0	0	1	0	0	0	3
	Plate Obstruction	2	0	0	1	3	2	0	3	0	0	1	3	0	0	1	0	0	1	17
	Signal Obstruction	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
	Vehicle Obstruction	1	1	1	0	11	1	0	0	1	0	1	5	0	3	9	0	1	3	38
Police Rejects	Driver Obstruction (PD)	0	0	0	0	2	0	0	0	1	1	0	0	0	1	0	0	1	1	7
	Multiple vehicles in frame	0	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	2
	On or Passed the Stop Bar (PD)	0	0	0	1	1	0	0	0	0	0	0	0	3	0	0	0	0	0	5
	Plate Obstruction (PD)	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0	2
	Plate Unidentifiable	1	0	1	0	1	0	0	0	0	1	0	0	0	0	0	0	0	0	4
	Safe Turn On Red	0	32	0	0	0	0	0	32	7	0	0	0	0	0	0	0	0	14	85
Policy/Weather	Sun Glare	0	3	1	2	3	3	3	1	1	0	2	5	0	5	7	3	7	6	52
	Extended Vehicle	0	0	0	0	3	0	0	0	0	0	1	4	1	0	0	0	0	3	12
Registration Issues	Sun Glare	4	28	3	1	17	13	19	2	17	3	2	2	3	14	10	13	4	18	173
	Paper Plates	2	4	0	1	7	1	3	6	1	0	0	5	0	2	1	1	1	3	38
	Wrong or No DMV	0	0	0	1	5	1	0	2	0	0	2	2	0	1	2	3	3	1	23
Total		13	78	7	8	57	25	27	49	32	6	10	32	8	28	48	26	20	55	529
Sub Total Violations		11	35	1	8	90	29	10	51	57	6	27	62	16	15	52	59	48	29	606
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		11	35	1	8	90	29	10	51	57	6	27	62	16	15	52	59	48	29	606
Less Rejects																				
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:27:20 AM

Customer Management Report (Ventura) All Detection Types

01-Sep-2014 to 30-Sep-2014

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-30%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Face Not in Frame	0-00%	0-00%	1-100%	0-00%	0-00%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	3-06%	0-00%	0-00%	0-00%	7-01%
Image Missing	0-00%	2-06%	0-00%	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Police Rejects																			
Driver Unidentifiable images poor	2-18%	5-14%	0-00%	1-12%	0-00%	2-07%	1-10%	1-02%	1-02%	0-00%	0-00%	6-10%	0-00%	0-00%	9-17%	3-05%	1-02%	0-00%	32-05%
Incorrect Speed	0-00%	2-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
No Images	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues																			
Too Old	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	1-02%	0-00%	1-17%	1-04%	0-00%	0-00%	0-00%	1-02%	2-03%	0-00%	1-03%	9-01%
Total	2-18%	9-26%	1-100%	2-25%	2-02%	2-07%	8-80%	3-06%	1-02%	1-17%	1-04%	10-16%	0-00%	0-00%	14-27%	5-08%	1-02%	2-07%	64-11%
Approved Violations	9-82%	26-74%	0-00%	6-75%	88-98%	27-93%	2-20%	48-94%	56-98%	5-83%	26-96%	52-84%	16-100%	15-100%	38-73%	54-92%	47-98%	27-93%	542-89%
Total Notices Printed	9-82%	26-74%	0-00%	6-75%	88-98%	27-93%	2-20%	48-94%	56-98%	5-83%	26-96%	52-84%	16-100%	15-100%	38-73%	54-92%	47-98%	27-93%	542-89%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:27:20 AM

Customer Management Report (Ventura) All Detection Types

01-Oct-2014 to 31-Oct-2014

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents	16	146	4	19	153	50	52	106	111	6	38	94	25	66	91	37	72	88	1174	
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	3	10	1	1	4	2	2	3	1	1	1	4	3	3	20	1	2	4	66
	Motor Cycle Helmet	0	1	0	0	1	0	0	2	0	1	0	0	1	0	0	0	0	0	6
	Plate Obstruction	0	2	0	0	3	1	0	3	0	0	2	0	1	0	0	0	0	1	13
	Signal Obstruction	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0	0	0	0	3
	Vehicle Obstruction	0	5	0	1	7	2	3	0	2	1	2	8	0	2	5	2	2	0	42
Police Rejects	Driver Obstruction (PD)	0	3	0	0	2	0	0	2	3	0	1	0	1	0	5	0	1	1	19
	Gender Mismatch	0	0	0	0	0	0	0	1	0	0	0	1	0	0	1	0	0	0	3
	Incorrect/Incomplete DMV	1	1	0	1	2	0	0	0	0	0	2	1	0	4	1	0	0	0	13
	Multiple vehicles in frame	0	4	0	0	0	1	1	1	0	0	0	0	0	1	0	0	0	0	8
	On or Passed the Stop Bar (PD)	0	0	0	0	0	1	0	0	0	0	0	2	0	0	0	0	0	0	3
	Plate Obstruction (PD)	0	0	0	0	1	1	0	1	0	0	3	0	0	0	0	0	0	1	7
	Plate Unidentifiable	0	0	0	0	0	1	0	1	0	0	1	0	0	0	0	0	0	1	5
	Safe Turn On Red	0	24	0	0	1	0	0	35	9	0	1	0	0	0	0	0	0	17	87
	Sun Glare	0	17	0	1	13	4	3	3	4	0	3	8	4	5	2	3	5	7	82
Policy/Weather	Extended Vehicle	0	1	0	0	3	0	0	0	0	0	3	0	0	0	0	0	0	2	9
	Sun Glare	2	15	2	4	13	7	22	3	21	0	4	2	3	27	5	2	9	17	158
	Weather/Nature	0	1	0	0	0	1	0	0	0	0	0	0	2	0	0	1	0	0	5
Registration Issues	Out of Country Plate	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1
	Paper Plates	0	4	0	0	3	2	2	1	2	0	1	1	0	1	1	0	2	1	21
	Wrong or No DMV	0	5	0	1	4	0	1	2	2	0	2	1	1	1	1	6	1	28	
Total		6	93	3	9	57	34	56	46	2	15	37	15	43	45	10	28	54	579	
Sub Total Violations		10	53	1	10	96	18	50	65	4	23	57	10	23	46	27	44	34	595	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:27:52 AM

Customer Management Report (Ventura) All Detection Types

01-Oct-2014 to 31-Oct-2014

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Available For Prosecution		10	53	1	10	96	24	18	50	65	4	23	57	10	23	46	27	44	34	595	
Less Rejects																					
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-11%	0-00%	0-00%	2-50%	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	6-01%	
	Image Missing	0-00%	1-02%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	3-03%	6-25%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	10-02%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	4-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%	
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Police Rejects	Driver Unidentifiable images poor	2-20%	4-08%	0-00%	1-10%	1-01%	3-12%	3-17%	3-06%	4-06%	0-00%	0-00%	7-12%	0-00%	3-13%	6-13%	2-07%	1-02%	1-03%	41-07%	
	Incorrect Speed	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	2-00%	
Total		2-20%	6-11%	0-00%	3-30%	4-04%	9-38%	12-67%	5-10%	6-09%	2-50%	0-00%	8-14%	0-00%	3-13%	9-20%	3-11%	2-05%	1-03%	75-13%	
Approved Violations		8-80%	47-89%	1-100%	7-70%	92-96%	15-62%	6-33%	45-90%	59-91%	2-50%	23-100%	49-86%	10-100%	20-87%	37-80%	24-89%	42-95%	33-97%	520-87%	
Total Notices Printed		8-80%	47-89%	1-100%	7-70%	92-96%	15-62%	6-33%	45-90%	59-91%	2-50%	23-100%	49-86%	10-100%	20-87%	37-80%	24-89%	42-95%	33-97%	520-87%	

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:27:52 AM

Customer Management Report (Ventura) All Detection Types

01-Oct-2014 to 31-Oct-2014

Operator Id: %

VE-VIVA-01	VE-VITP-03	VE-VITP-01	VE-VITG-01	VE-VIRA-01	VE-VIOP-01	VE-VIMO-01	VE-THSE-01	VE-TGDA-01	VE-MITG-01	VE-MIDE-01	VE-MAMI-01	VE-MALE-01	VE-MA10-01	VE-JONB-01	VE-FOVI-01	VE-CATH-01	VE-BRJO-01		TOTAL
------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	--	-------

Customer Management Report (Ventura) All Detection Types

01-Nov-2014 to 30-Nov-2014

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents	11	185	6	19	102	44	32	78	77	2	34	72	19	37	78	21	41	69	927	
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	1	16	1	1	0	4	2	1	2	0	1	5	2	0	14	0	2	7	59
	Motor Cycle Helmet	0	0	0	0	0	0	0	1	1	0	0	1	0	1	0	1	1	1	6
	Plate Obstruction	1	2	0	2	1	2	1	0	0	1	2	1	0	3	0	0	0	0	16
	Vehicle Obstruction	0	6	1	0	3	1	3	1	0	0	5	1	0	3	0	0	0	2	26
Police Rejects	Driver Obstruction (PD)	0	2	0	0	0	0	1	2	0	0	0	0	0	4	0	1	0	0	10
	Incorrect/Incomplete DMV	0	0	0	0	0	2	1	0	0	1	0	0	0	0	0	0	0	0	4
	Invalid Offense	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
	Multiple vehicles in frame	0	4	0	0	1	0	0	0	0	0	1	0	0	0	0	0	0	0	6
	On or Passed the Stop Bar (PD).	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
	Plate Obstruction (PD)	0	2	0	0	0	0	0	0	0	0	2	0	0	1	0	0	0	0	5
	Plate Unidentifiable	0	0	0	0	1	0	1	0	0	1	0	0	0	0	0	0	0	0	3
	Safe Turn On Red	0	34	0	0	0	0	19	9	0	0	0	0	0	0	0	0	0	9	71
	Sun Glare	0	7	0	0	0	1	0	1	0	0	2	0	0	0	1	1	1	5	18
Policy/Weather	Extended Vehicle	0	2	0	1	0	0	0	0	0	0	2	0	0	0	0	0	0	0	5
	Sun Glare	2	33	2	1	5	4	6	5	7	0	2	2	14	0	0	0	4	88	
	Weather/Nature	0	0	0	0	0	2	0	4	0	0	0	0	5	0	0	0	0	0	11
Registration Issues	Paper Plates	0	2	0	0	1	0	1	2	1	0	1	0	1	3	0	2	5	20	
	Wrong or No DMV	1	3	0	1	5	0	1	1	2	0	2	0	0	1	0	0	0	0	18
Total		5	115	4	6	17	16	34	30	1	10	22	7	20	30	1	7	33	369	
Sub Total Violations		6	70	2	13	85	16	44	47	1	24	50	12	17	48	20	34	36	558	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		6	70	2	13	85	16	44	47	1	24	50	12	17	48	20	34	36	558	

Less Rejects

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:28:26 AM

Customer Management Report (Ventura) All Detection Types

01-Nov-2014 to 30-Nov-2014

Operator Id: %

		VE-BRU0-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Camera Malfunction	Face Camera Flash	1-17%	0-00%	1-50%	0-00%	0-00%	0-00%	2-12%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	6-01%	
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Not in Frame	0-00%	0-00%	1-50%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	3-01%	
	Image Missing	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Misc Camera Issue	1-17%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	4-01%	
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	3-01%
	Rear Plate Flash Inappropriate	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	2-05%	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Police Rejects Process Issues	Driver Unidentifiable images poor	0-00%	10-14%	0-00%	0-00%	0-00%	3-09%	4-25%	1-02%	1-02%	0-00%	0-00%	5-10%	1-08%	2-12%	2-04%	2-10%	1-03%	2-06%	34-06%	
	Too Old	1-17%	8-11%	0-00%	1-08%	9-11%	3-09%	1-06%	1-02%	4-09%	1-100%	2-08%	8-16%	2-17%	0-00%	9-19%	0-00%	0-00%	6-17%	56-10%	
Total		3-50%	20-29%	2-100%	1-08%	11-13%	6-18%	9-56%	6-14%	5-11%	1-100%	2-08%	16-32%	3-25%	3-18%	13-27%	3-15%	1-03%	9-25%	114-20%	
Approved Violations		3-50%	50-71%	0-00%	12-92%	74-87%	27-82%	7-44%	38-86%	42-89%	0-00%	22-92%	34-68%	9-75%	14-82%	35-73%	17-85%	33-97%	27-75%	444-80%	
Total Notices Printed		3-50%	50-71%	0-00%	12-92%	74-87%	27-82%	7-44%	38-86%	42-89%	0-00%	22-92%	34-68%	9-75%	14-82%	35-73%	17-85%	33-97%	27-75%	444-80%	

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:28:26 AM

Customer Management Report (Ventura) All Detection Types

01-Dec-2014 to 31-Dec-2014

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents	18	200	2	21	109	49	51	99	66	3	33	86	29	51	97	5	34	68	1021	
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	1	26	1	1	1	3	4	2	1	0	0	8	1	6	18	0	1	2	76
	Motor Cycle Helmet	0	1	0	0	1	0	0	1	0	1	0	0	1	0	0	0	0	1	6
	Plate Obstruction	1	4	0	2	2	1	2	0	0	0	1	0	0	0	0	0	0	0	13
	Vehicle Obstruction	0	9	0	0	4	0	6	1	1	1	10	0	2	5	0	1	0	40	
Police Rejects	Citation Issued manually	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
	Driver Obstruction (PD)	1	1	0	0	1	0	0	1	2	0	1	0	0	1	0	0	0	1	9
	Emergency Vehicle Responding	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Incorrect/Incomplete DMV	0	0	0	1	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2
	Invalid Offense	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Multiple vehicles in frame	0	7	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	8
	On or Passed the Stop Bar (PD)	0	2	0	2	0	0	0	0	0	0	0	5	0	0	0	0	0	0	9
	Plate Obstruction (PD)	0	0	0	1	1	1	0	1	0	0	0	0	0	0	0	0	0	0	4
	Plate Unidentifiable	1	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	2
	Safe Turn On Red	0	26	0	0	0	0	26	7	0	0	0	0	0	0	0	0	0	6	65
	Sun Glare	3	1	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	6
Policy/Weather	Extended Vehicle	0	2	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	5
	Sun Glare	0	20	1	2	0	4	10	1	5	0	3	2	3	15	2	0	0	9	77
Registration Issues	Paper Plates	0	7	0	0	2	1	5	2	2	0	2	1	2	3	0	0	0	3	30
	Wrong or No DMV	0	0	0	0	2	2	0	4	1	0	1	0	3	1	0	0	0	3	17
Total		7	107	2	9	15	14	29	37	21	1	7	10	29	31	0	2	25	372	
Sub Total Violations		11	93	0	12	94	35	62	45	2	26	60	19	22	66	5	32	43	649	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		11	93	0	12	94	35	62	45	2	26	60	19	22	66	5	32	43	649	

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:28:50 AM

Customer Management Report (Ventura) All Detection Types

01-Dec-2014 to 31-Dec-2014

Operator Id: %

		VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Less Rejects																					
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-09%	0-00%	0-00%	1-50%	1-04%	1-02%	3-16%	0-00%	2-03%	0-00%	0-00%	0-00%	10-02%	
	Misc Camera Issue	1-09%	46-49%	0-00%	0-00%	1-01%	1-03%	2-09%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	53-08%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	1-02%	0-00%	0-00%	0-00%	0-00%	9-15%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	11-02%
Police Rejects	Driver Unidentifiable images poor	4-36%	7-08%	0-00%	1-08%	1-01%	4-11%	5-23%	0-00%	0-00%	0-00%	0-00%	6-10%	0-00%	2-09%	5-08%	0-00%	0-00%	0-00%	35-05%	
	Incorrect Speed	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	No Images	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Unclear Scene Image	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Process Issues	Too Old	2-18%	4-04%	0-00%	3-25%	12-13%	12-34%	2-09%	14-23%	10-22%	0-00%	8-31%	4-07%	2-11%	4-18%	10-15%	1-20%	6-19%	7-16%	101-16%	
Total		7-64%	58-62%	0-00%	4-33%	15-16%	17-49%	13-59%	15-24%	10-22%	1-50%	10-38%	24-40%	5-26%	6-27%	17-26%	1-20%	7-22%	7-16%	217-33%	
Approved Violations		4-36%	35-38%	0-00%	8-67%	79-84%	18-51%	9-41%	47-76%	35-78%	1-50%	16-62%	36-60%	14-74%	16-73%	49-74%	4-80%	25-78%	36-84%	432-67%	
Total Notices Printed		4-36%	35-38%	0-00%	8-67%	79-84%	18-51%	9-41%	47-76%	35-78%	1-50%	16-62%	36-60%	14-74%	16-73%	49-74%	4-80%	25-78%	36-84%	432-67%	

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:28:50 AM

Customer Management Report (Ventura) All Detection Types

01-Jan-2014 to 31-Dec-2014

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents	229	2177	55	249	1712	469	458	1161	969	82	616	1013	217	543	874	576	651	873	12924	
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	27	286	13	14	63	49	64	27	64	3	22	74	29	63	168	18	23	70	1077
	Motor Cycle Helmet	1	4	0	0	10	1	1	3	9	1	4	4	1	5	2	0	2	7	55
	Plate Obstruction	10	17	0	19	25	8	6	12	3	2	13	27	2	1	7	6	0	19	177
	Signal Obstruction	0	2	0	0	0	3	0	0	0	0	0	0	0	0	0	0	0	0	5
	Vehicle Obstruction	9	101	2	4	62	3	44	12	10	10	18	52	3	14	52	12	10	14	432
Police Rejects	Citation Issued manually	0	0	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	2
	Driver Obstruction (PD)	3	18	0	0	15	2	0	8	18	1	5	5	1	3	15	5	11	5	115
	Emergency Vehicle Responding	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Funeral Procession/Police	0	0	0	0	0	0	0	1	1	0	0	0	0	0	0	0	0	0	2
	Gender Mismatch	0	1	0	0	1	0	0	1	0	0	0	2	0	0	1	0	0	0	6
	Incorrect/Incomplete DMV	2	3	0	2	3	2	1	1	1	0	4	4	1	1	8	2	0	0	35
	Invalid Offense	0	0	0	0	2	0	0	0	0	0	2	0	0	0	0	0	0	1	5
	Multiple vehicles in frame	0	54	0	0	5	1	1	1	0	0	1	3	0	0	3	0	0	1	70
	On or Passed the Stop Bar (PD)	1	8	0	8	2	2	0	0	0	0	3	20	1	1	1	0	0	2	48
	Plate Obstruction (PD)	3	4	0	4	4	4	1	4	2	0	8	0	0	2	3	0	1	1	40
	Plate Unidentifiable	3	2	1	4	6	2	1	3	1	1	2	5	2	0	1	0	1	5	40
	Police Discretion	0	0	0	0	0	0	0	0	0	0	2	0	0	0	0	2	0	0	4
	Safe Turn On Red	0	479	0	0	1	0	0	348	57	0	1	0	0	0	0	1	1	131	1019
	Sun Glare	9	94	4	12	47	24	20	12	22	2	19	26	9	35	27	15	31	39	447
	Weather Conditions	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Policy/Weather	Extended Vehicle	2	12	0	4	14	0	3	0	4	0	3	63	1	0	0	0	0	7	113
	Sun Glare	37	227	19	11	100	77	132	28	110	13	44	30	28	169	56	25	49	123	1278
	Weather/Nature	2	1	0	0	3	1	2	0	6	0	0	0	2	7	0	0	2	0	26

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:37:44 AM

Customer Management Report (Ventura) All Detection Types

01-Jan-2014 to 31-Dec-2014

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1
	Out of Country Plate	0	2	0	2	1	0	0	0	2	0	1	0	0	0	0	0	0	2	10
	Paper Plates	5	58	0	15	35	12	18	28	24	3	13	25	2	10	19	8	16	33	324
	Wrong or No DMV	4	39	0	11	35	9	5	32	20	1	17	23	2	12	13	16	29	16	284
Total		118	1413	39	110	435	201	299	521	354	37	171	355	103	321	376	113	175	476	5617
Sub Total Violations		111	764	16	139	1277	268	159	640	615	45	445	658	114	222	498	463	476	397	7307
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		111	764	16	139	1277	268	159	640	615	45	445	658	114	222	498	463	476	397	7307
Less Rejects																				
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera Flash	1-01%	1-00%	2-12%	1-01%	1-00%	3-01%	9-06%	2-00%	2-00%	0-00%	0-00%	2-00%	0-00%	1-00%	3-01%	0-00%	0-00%	4-01%	32-00%
	Face Camera Focus Blurry	0-00%	1-00%	1-06%	0-00%	0-00%	0-00%	8-05%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	12-00%
	Face Camera No Flash	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	3-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	5-00%
	Face Not in Frame	1-01%	0-00%	3-19%	0-00%	1-00%	0-00%	10-06%	0-00%	0-00%	8-18%	2-00%	5-01%	4-04%	0-00%	19-04%	0-00%	0-00%	1-00%	54-01%
	Image Missing	0-00%	4-01%	0-00%	2-01%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	8-00%
	Misc Camera Issue	3-03%	47-06%	0-00%	3-02%	18-01%	7-03%	3-02%	0-00%	2-00%	1-02%	2-00%	7-01%	0-00%	1-00%	1-00%	0-00%	3-01%	1-00%	99-01%
	Plate Burn Out	0-00%	1-00%	1-06%	0-00%	0-00%	0-00%	0-00%	4-01%	2-00%	0-00%	7-02%	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	0-00%	17-00%
	Plate Not in Frame	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	3-00%	1-00%	1-01%	0-00%	0-00%	1-02%	2-00%	2-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	12-00%
	Rear Plate Flash Inappropriate	0-00%	1-00%	0-00%	1-01%	0-00%	1-00%	1-01%	0-00%	1-00%	1-02%	1-00%	1-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	10-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-01%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	5-01%	0-00%	0-00%	0-00%	13-02%	0-00%	0-00%	2-00%	0-00%	0-00%	0-00%	22-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-04%	13-02%	0-00%	0-00%	0-00%	21-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	42-01%
Police Rejects	Driver Unidentifiable images poor	24-22%	93-12%	2-12%	8-06%	22-02%	36-13%	42-26%	16-02%	33-05%	5-11%	3-01%	66-10%	7-06%	29-13%	50-10%	21-05%	15-03%	17-04%	489-07%
	Incorrect Speed	0-00%	4-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	3-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	8-00%
	Insufficient Strobe Lighting	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:37:44 AM

Customer Management Report (Ventura) All Detection Types

01-Jan-2014 to 31-Dec-2014

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
No Images	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Unclear Scene Image	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Process Issues																			
Too Old	5-05%	18-02%	2-12%	5-04%	27-02%	15-06%	6-04%	20-03%	16-03%	3-07%	14-03%	15-02%	7-06%	5-02%	21-04%	9-02%	8-02%	14-04%	210-03%
Total	34-31%	171-22%	13-81%	22-16%	73-06%	64-24%	95-60%	62-10%	57-09%	20-44%	35-08%	134-20%	21-18%	36-16%	98-20%	32-07%	26-05%	40-10%	1033-14%
Approved Violations	77-69%	593-78%	3-19%	117-84%	1204-94%	204-76%	64-40%	578-90%	558-91%	25-56%	410-92%	524-80%	93-82%	186-84%	400-80%	431-93%	450-95%	357-90%	6274-86%
Total Notices Printed	77-69%	593-78%	3-19%	117-84%	1204-94%	204-76%	64-40%	578-90%	558-91%	25-56%	410-92%	524-80%	93-82%	186-84%	400-80%	431-93%	450-95%	357-90%	6274-86%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:37:44 AM

Customer Management Report (Ventura) All Detection Types

01-Jan-2015 to 31-Jan-2015

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents		13	217	4	24	77	35	34	104	77	6	39	86	12	28	99	35	58	77	1025
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	1	18	0	1	1	1	0	4	2	1	0	1	1	0	18	1	1	2	53
	Motor Cycle Helmet	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Plate Obstruction	1	4	0	1	1	0	0	3	0	0	0	3	0	1	0	0	2	3	19
	Vehicle Obstruction	0	11	0	1	2	2	7	2	0	1	0	3	0	1	12	0	1	0	43
Police Rejects	Driver Obstruction (PD)	0	2	0	1	0	1	1	0	1	0	2	1	0	0	0	1	2	0	12
	Incorrect/Incomplete DMV	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1	2
	Multiple vehicles in frame	0	9	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	10
	On or Passed the Stop Bar (PD)	2	4	0	0	1	0	1	0	1	0	0	0	1	0	1	0	0	0	11
	Plate Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	2
	Plate Unidentifiable	0	0	0	0	0	1	0	1	0	0	0	0	0	0	0	0	0	0	2
	Safe Turn On Red	0	62	0	0	0	0	0	24	3	0	0	0	0	0	2	0	0	15	106
	Sun Glare	1	4	0	0	0	1	1	0	1	0	0	1	0	1	0	1	0	0	11
	Policy/Weather	Extended Vehicle	0	2	0	0	0	0	0	1	0	0	1	5	0	0	0	0	0	1
Sun Glare	0	11	3	0	0	2	7	3	5	1	4	3	5	5	4	0	0	4	57	
Weather/Nature	0	5	0	0	1	0	0	0	2	0	1	0	0	1	1	0	0	0	11	
Registration Issues	Paper Plates	1	8	0	1	4	0	0	3	1	0	0	3	0	2	4	2	1	3	33
	Wrong or No DMV	0	3	0	0	3	2	0	3	2	0	0	3	0	2	2	2	1	1	24
Total		6	143	3	5	15	11	17	44	18	3	8	24	7	13	44	7	8	31	407
Sub Total Violations		7	74	1	19	62	24	17	60	59	3	31	62	5	15	55	28	50	46	618
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		7	74	1	19	62	24	17	60	59	3	31	62	5	15	55	28	50	46	618

Less Rejects

Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
--------------------	-------------------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:30:11 AM

Customer Management Report (Ventura) All Detection Types

01-Jan-2015 to 31-Jan-2015

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Manufacturing																			
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	2-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	1-100%	0-00%	1-02%	3-12%	0-00%	0-00%	0-00%	0-00%	1-03%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-01%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-05%	0-00%	0-00%	0-00%	3-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
Police Rejects																			
Driver Unidentifiable images poor	2-29%	9-12%	0-00%	1-05%	2-03%	2-08%	5-29%	1-02%	5-08%	0-00%	0-00%	10-16%	0-00%	3-20%	5-09%	1-04%	1-02%	4-09%	51-08%
Incorrect Speed	0-00%	2-03%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Total	2-29%	11-15%	1-100%	1-05%	4-06%	5-21%	7-41%	4-07%	7-12%	0-00%	1-03%	15-24%	0-00%	3-20%	7-13%	1-04%	1-02%	4-09%	74-12%
Approved Violations	5-71%	63-85%	0-00%	18-95%	58-94%	19-79%	10-59%	56-93%	52-88%	3-100%	30-97%	47-76%	5-100%	12-80%	48-87%	27-96%	49-98%	42-91%	544-88%
Total Notices Printed	5-71%	63-85%	0-00%	18-95%	58-94%	19-79%	10-59%	56-93%	52-88%	3-100%	30-97%	47-76%	5-100%	12-80%	48-87%	27-96%	49-98%	42-91%	544-88%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:30:11 AM

Customer Management Report (Ventura) All Detection Types

03-Mar-2015 to 31-Mar-2015

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents	16	217	6	12	76	39	25	76	76	14	31	64	17	39	84	30	49	60	931	
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	2	15	0	2	3	3	2	1	0	3	0	3	5	2	16	1	0	4	62
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0	3
	Plate Obstruction	0	5	0	0	0	2	1	1	0	0	0	4	0	0	0	0	0	2	15
	Vehicle Obstruction	0	9	0	0	4	1	1	0	1	0	1	3	0	0	4	0	1	0	25
Police Rejects	Driver Obstruction (PD)	0	1	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2
	Emergency Vehicle Responding	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Incorrect/Incomplete DMV	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Invalid Offense	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Multiple vehicles in frame	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	3
	On or Passed the Stop Bar (PD)	0	0	0	0	0	0	0	2	0	0	0	1	1	0	1	0	0	0	5
	Plate Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	2
	Safe Turn On Red	0	62	0	0	0	0	23	5	0	0	0	0	0	0	0	0	0	13	103
	Sun Glare	0	8	0	0	0	2	1	0	1	0	2	1	2	1	0	1	0	0	19
Policy/Weather	Extended Vehicle	0	1	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	3
	Sun Glare	1	19	3	0	8	2	5	1	16	2	2	1	15	5	1	2	7	7	92
	Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1
Registration Issues	Out of Country Plate	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
	Paper Plates	2	3	0	0	3	2	0	3	7	0	1	1	0	1	2	0	4	3	32
	Wrong or No DMV	0	1	0	0	2	1	1	1	0	0	1	0	0	0	0	0	1	2	10
Total		6	127	3	2	20	13	11	33	33	5	6	20	9	20	29	2	10	32	381
Sub Total Violations		10	90	3	10	56	26	14	43	43	9	25	44	8	19	55	28	39	28	550
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		10	90	3	10	56	26	14	43	43	9	25	44	8	19	55	28	39	28	550

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:30:39 AM

Customer Management Report (Ventura) All Detection Types

03-Mar-2015 to 31-Mar-2015

Operator Id: %

		VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Less Rejects																				
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-07%	0-00%	0-00%	4-16%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	8-01%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	0-00%	2-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	10-11%	1-33%	0-00%	1-02%	4-15%	2-14%	0-00%	3-07%	0-00%	0-00%	8-18%	0-00%	1-05%	10-18%	1-04%	2-05%	1-04%	44-08%
	Plate Unclear	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	Too Old	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total		1-10%	11-12%	1-33%	0-00%	2-04%	4-15%	3-21%	4-09%	3-07%	0-00%	4-16%	9-20%	1-12%	1-05%	10-18%	3-11%	2-05%	1-04%	60-11%
Approved Violations		9-90%	79-88%	2-67%	10-100%	54-96%	22-85%	11-79%	39-91%	40-93%	9-100%	21-84%	35-80%	7-88%	18-95%	45-82%	25-89%	37-95%	27-96%	490-89%
Total Notices Printed		9-90%	79-88%	2-67%	10-100%	54-96%	22-85%	11-79%	39-91%	40-93%	9-100%	21-84%	35-80%	7-88%	18-95%	45-82%	25-89%	37-95%	27-96%	490-89%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:30:39 AM

Customer Management Report (Ventura) All Detection Types

01-Apr-2015 to 30-Apr-2015

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents	10	223	10	14	122	37	28	79	62	14	23	69	13	41	59	32	81	58	975	
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	0	19	1	2	4	1	2	2	0	0	5	1	2	16	1	1	2	59	
	Motor Cycle Helmet	0	2	0	0	2	0	0	1	1	0	0	0	0	0	0	0	0	0	7
	Plate Obstruction	0	3	0	1	1	0	1	2	0	0	1	0	1	0	0	0	0	0	10
	Vehicle Obstruction	0	4	0	0	5	0	1	0	0	0	1	0	1	0	5	0	1	2	20
Police Rejects	Citation Issued manually	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Driver Obstruction (PD)	0	0	0	0	0	0	1	1	1	0	0	0	0	1	0	1	0	0	5
	Gender Mismatch	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Multiple vehicles in frame	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
	On or Passed the Stop Bar (PD)	0	4	0	0	2	0	0	3	1	0	0	0	1	0	0	1	0	5	17
	Plate Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1
	Plate Unidentifiable	0	1	0	0	0	0	0	0	1	0	0	1	0	0	0	0	0	0	3
	Safe Turn On Red	0	36	0	0	1	0	0	18	2	0	0	0	0	0	0	0	0	8	65
	Sun Glare	0	0	0	0	0	1	1	1	3	0	1	1	1	0	0	1	0	1	11
	Policy/Weather	Extended Vehicle	0	3	0	0	0	1	1	0	0	0	4	0	0	0	0	0	0	0
Sun Glare		0	28	7	1	11	9	7	1	9	2	3	2	1	14	1	1	6	11	114
Weather/Nature		0	4	0	0	3	3	0	0	3	0	1	1	0	0	0	2	2	1	20
Registration Issues	Paper Plates	0	3	2	1	5	3	1	2	3	0	0	1	0	0	3	1	2	1	28
	Wrong or No DMV	0	5	0	0	3	1	1	1	2	0	1	2	0	2	5	2	3	0	28
Total	0	115	10	6	37	19	15	32	26	3	8	18	5	19	31	9	16	32	401	
Sub Total Violations	10	108	0	8	85	18	13	47	36	11	15	51	8	22	28	23	65	26	574	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution	10	108	0	8	85	18	13	47	36	11	15	51	8	22	28	23	65	26	574	

Less Rejects

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:31:03 AM

Customer Management Report (Ventura) All Detection Types

01-Apr-2015 to 30-Apr-2015

Operator Id: %

		VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Camera Malfunction	Misc Camera Issue	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Video Not In Sync	0-00%	7-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-01%
Police Rejects	Driver Unidentifiable images poor	0-00%	12-11%	0-00%	0-00%	1-01%	0-00%	5-38%	0-00%	2-06%	1-09%	0-00%	4-08%	0-00%	2-09%	1-04%	0-00%	1-02%	1-04%	30-05%
	Plate Unclear	0-00%	0-00%	0-00%	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Unclear Scene Image	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	Too Old	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total		0-00%	23-21%	0-00%	1-12%	1-01%	0-00%	6-46%	1-02%	2-06%	2-18%	1-07%	4-08%	0-00%	2-09%	1-04%	0-00%	1-02%	1-04%	46-08%
Approved Violations		10-100%	85-79%	0-00%	7-88%	84-99%	18-100%	7-54%	46-98%	34-94%	9-82%	14-93%	47-92%	8-100%	20-91%	27-96%	23-100%	64-98%	25-96%	528-92%
Total Notices Printed		10-100%	85-79%	0-00%	7-88%	84-99%	18-100%	7-54%	46-98%	34-94%	9-82%	14-93%	47-92%	8-100%	20-91%	27-96%	23-100%	64-98%	25-96%	528-92%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 5/13/2015 11:31:03 AM