

Customer Management Report (Hawthorne) All Detection Types

01-Dec-2013 to 31-Dec-2013

Operator Id: %

	HA-HAES-01	HA-HAES-03	HA-HAIM-01	HA-HAIM-03	HA-HIRO-01	HA-IMFR-01	HA-ROHI-01	TOTAL
Total Processed Incidents	125	108	248	3	453	95	1022	2054
Less Uncontrollable Factors								
Obstruction	5	2	12	1	13	2	88	123
Driver Obstruction/Duckers	1	1	4	0	2	0	29	37
Plate Obstruction	3	2	1	0	6	2	43	57
Vehicle Obstruction	2	0	21	0	26	1	87	137
Police Rejects	1	0	0	0	0	0	0	1
Emergency Vehicle Responding	2	1	6	0	7	1	17	34
Incorrect/Incomplete DMV	3	0	1	0	0	0	0	4
Invalid Offense	0	0	0	0	2	0	2	4
Multiple vehicles in frame	5	3	65	0	10	1	0	84
On or Passed the Stop Bar (PD)	0	0	0	0	0	0	1	1
Police Discretion	0	0	0	0	35	0	0	35
Safe Turn On Red	0	0	0	0	1	0	6	7
Sun Glare	0	0	0	0	0	0	6	6
Policy/Weather	3	22	6	0	73	5	24	133
Extended Vehicle	3	1	3	0	0	0	1	8
Sun Glare	0	0	0	0	0	0	1	1
Weather/Nature	7	5	9	0	22	5	22	70
Registration	0	0	0	0	0	0	1	1
Out of Country Plate	0	0	0	0	0	0	1	1
Issues	35	37	128	1	197	17	328	743
Paper Plates	90	71	120	2	256	78	694	1311
Wrong or No DMV	0	0	0	0	0	0	0	0
Sub Total Violations	90	71	120	2	256	78	694	1311
Less in Progress	0	0	0	0	0	0	0	0
Available For Prosecution	90	71	120	2	256	78	694	1311
Less Rejects								

Generated By: SPIMENTEL

Generated On: 4/9/2014 4:55:15 PM

Customer Management Report (Hawthorne) All Detection Types

01-Dec-2013 to 31-Dec-2013

Operator Id: %

	HA-HAES-01	HA-HAES-03	HA-HAIM-01	HA-HAIM-03	HA-HIRO-01	HA-IMFR-01	HA-ROHI-01	TOTAL
Camera Malfunction	0-00%	1-01%	1-01%	0-00%	0-00%	1-01%	0-00%	3-00%
Face Camera Flash	1-01%	2-03%	1-01%	0-00%	0-00%	0-00%	1-00%	5-00%
Face Camera Focus Blurry	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera No Flash	2-02%	0-00%	0-00%	0-00%	1-00%	0-00%	13-02%	16-01%
Face Not in Frame	1-01%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Misc Camera Issue	3-03%	2-03%	0-00%	0-00%	0-00%	4-05%	1-00%	10-01%
Plate Not in Frame	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	2-00%
Rear Plate Camera Blurry	1-01%	0-00%	0-00%	0-00%	6-02%	0-00%	0-00%	7-01%
Scene Image Flash Inappropriate	1-01%	0-00%	0-00%	0-00%	40-16%	0-00%	0-00%	41-03%
Scene Image No Flash	7-08%	11-15%	4-03%	1-50%	33-13%	7-09%	3-00%	66-05%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%	5-00%
Insufficient Strobe Lighting	1-01%	0-00%	1-01%	0-00%	0-00%	0-00%	13-02%	15-01%
Red-light not visible in	1-01%	0-00%	1-01%	0-00%	1-00%	0-00%	1-00%	4-00%
Unclear Scene Image	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Too Old	20-22%	17-24%	9-08%	1-50%	81-32%	12-15%	38-05%	178-14%
Process Issues	70-78%	54-76%	111-92%	1-50%	175-68%	66-85%	656-95%	1133-86%
Total	70-78%	54-76%	111-92%	1-50%	175-68%	66-85%	656-95%	1133-86%
Approved Violations								
Total Notices Printed								

Legend: (P) = Production (I) = Inoperative
 Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SPIMENTEL
 Generated On: 4/9/2014 4:55:15 PM

Customer Management Report (Hawthorne) All Detection Types

01-Jan-2014 to 31-Jan-2014

Operator Id: %

	HA-HAES-01	HA-HAES-03	HA-HAIM-01	HA-HAIM-03	HA-HIRO-01	HA-IMFR-01	HA-ROHI-01	TOTAL
Total Processed Incidents	118	89	214	4	340	105	778	1648
Less Uncontrollable Factors								
Obstruction	2	3	8	0	6	2	51	72
Driver Obstruction/Duckers								
Motor Cycle Helmet	1	0	0	0	1	0	0	2
Plate Obstruction	4	0	2	0	2	0	15	23
Vehicle Obstruction	0	1	3	2	5	0	20	31
Police Rejects								
Driver Obstructed	4	1	4	0	11	1	54	75
Incorrect/Incomplete DMV	0	1	3	0	9	2	14	29
Multiple vehicles in frame	0	0	0	0	0	0	6	6
On or Passed the Stop Bar (PD).	6	0	54	1	8	3	0	72
Safe Turn On Red	0	0	0	0	13	0	0	13
Policy/Weather								
Extended Vehicle	0	0	0	0	1	0	6	7
Sun Glare	9	9	11	1	73	3	12	118
Weather/Nature	1	1	8	0	0	1	1	12
Registration Issues								
Paper Plates	6	8	9	0	21	4	24	72
Wrong or No DMV	0	0	0	0	1	0	0	1
Total	33	24	102	4	151	16	203	533
Sub Total Violations	85	65	112	0	189	89	575	1115
Less in Progress	0	0	0	0	0	0	0	0
Available For Prosecution	85	65	112	0	189	89	575	1115
Less Rejects								
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%	4-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Image Missing	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%

Generated By: SPIMENTEL
Generated On: 4/9/2014 4:56:02 PM

Customer Management Report (Hawthorne) All Detection Types

01-Jan-2014 to 31-Jan-2014

Operator Id: %

	HA-HAES-01	HA-HAES-03	HA-HAIM-01	HA-HAIM-03	HA-HIRO-01	HA-IMFR-01	HA-ROHI-01	TOTAL
Misc Camera Issue	0-00%	2-03%	0-00%	0-00%	3-02%	1-01%	0-00%	6-01%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Plate Not in Frame	1-01%	0-00%	1-01%	0-00%	0-00%	1-01%	0-00%	3-00%
Rear Plate Camera Blurry	1-01%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%	3-00%
Rear Plate Flash Inappropriate	1-01%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate No Flash	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	2-00%
Police Rejects	15-18%	16-25%	18-16%	0-00%	83-44%	12-13%	8-01%	152-14%
Process Issues	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	3-00%
Total	2-02%	2-03%	1-01%	0-00%	2-01%	0-00%	3-01%	10-01%
Approved Violations	20-24%	22-34%	21-19%	0-00%	94-50%	14-16%	19-03%	190-17%
Total Notices Printed	65-76%	43-66%	91-81%	0-00%	95-50%	75-84%	556-97%	925-83%
	65-76%	43-66%	91-81%	0-00%	95-50%	75-84%	556-97%	925-83%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SPIMENTEL
Generated On: 4/9/2014 4:56:02 PM

Customer Management Report (Hawthorne) All Detection Types

01-Feb-2014 to 28-Feb-2014

Operator Id: %

	HA-HAES-01	HA-HAES-03	HA-HAIM-01	HA-HAIM-03	HA-HIRO-01	HA-IMFR-01	HA-ROHI-01	TOTAL
Total Processed Incidents	113	113	194	8	356	87	661	1532
Less Uncontrollable Factors								
Obstruction	2	2	9	0	7	0	69	89
Driver Obstruction/Duckers								
Motor Cycle Helmet	0	0	0	0	1	0	0	1
Plate Obstruction	2	2	3	1	2	0	19	29
Vehicle Obstruction	1	1	2	0	1	0	16	21
Police Rejects								
Driver Obstructed	2	5	10	0	11	2	52	82
Incorrect/Incomplete DMV	1	0	3	0	4	1	3	12
Multiple vehicles in frame	0	0	0	0	1	0	7	8
On or Passed the Stop Bar (PD)	3	1	31	0	14	1	0	50
Safe Turn On Red	0	0	0	0	20	1	0	21
Policy/Weather								
Extended Vehicle	0	0	0	0	1	0	2	3
Sun Glare	8	16	8	1	92	9	12	146
Weather/Nature	1	4	7	2	1	0	3	18
Registration Issues								
Out of Country Plate	0	0	0	0	0	0	1	1
Paper Plates	4	6	7	0	19	2	22	60
Wrong or No DMV	0	0	1	0	0	1	1	3
Total	24	37	81	4	174	17	207	544
Sub Total Violations	89	76	113	4	182	70	454	988
Less in Progress	0	0	0	0	0	0	0	0
Available For Prosecution	89	76	113	4	182	70	454	988
Less Rejects								
Camera Malfunction	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Digital Distortion	0-00%	1-01%	1-01%	0-00%	4-02%	0-00%	4-01%	10-01%
Face Camera Flash	2-02%	0-00%	0-00%	0-00%	3-02%	2-03%	0-00%	7-01%
Face Camera Focus Blurry								

Generated By: SPIMENTEL
Generated On: 4/9/2014 4:56:42 PM

Customer Management Report (Hawthorne) All Detection Types

01-Feb-2014 to 28-Feb-2014

Operator Id: %

	HA-HAES-01	HA-HAES-03	HA-HAIM-01	HA-HAIM-03	HA-HIRO-01	HA-IMFR-01	HA-ROHI-01	TOTAL
Face Not in Frame	0-00%	1-01%	1-01%	0-00%	0-00%	0-00%	7-02%	9-01%
Image Missing	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Misc Camera Issue	1-01%	2-03%	1-01%	0-00%	0-00%	0-00%	0-00%	4-00%
Plate Burn Out	0-00%	1-01%	0-00%	1-25%	0-00%	0-00%	0-00%	2-00%
Plate Not in Frame	1-01%	1-01%	19-17%	0-00%	0-00%	2-03%	0-00%	23-02%
Rear Plate Camera Blurry	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate Flash Inappropriate	0-00%	2-03%	1-01%	0-00%	0-00%	0-00%	0-00%	3-00%
Rear Plate No Flash	1-01%	3-04%	0-00%	0-00%	0-00%	0-00%	1-00%	5-01%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Police	9-10%	8-11%	10-09%	0-00%	63-35%	6-09%	7-02%	103-10%
Rejects	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	3-00%
Process Issues	0-00%	1-01%	0-00%	0-00%	0-00%	1-01%	0-00%	2-00%
Total	17-19%	22-29%	35-31%	1-25%	70-38%	11-16%	22-05%	178-18%
Approved Violations	72-81%	54-71%	78-69%	3-75%	112-62%	59-84%	432-95%	810-82%
Total Notices Printed	72-81%	54-71%	78-69%	3-75%	112-62%	59-84%	432-95%	810-82%

Legend: (P) = Production (I) = Inoperative
 Note: if you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Customer Management Report (Hawthorne) All Detection Types

01-Mar-2014 to 31-Mar-2014

Operator Id: %

	HA-HAES-01	HA-HAES-03	HA-HAIM-01	HA-HAIM-03	HA-HIRO-01	HA-IMFR-01	HA-ROHI-01	TOTAL
Total Processed Incidents	146	124	132	7	401	122	936	1868
Less Uncontrollable Factors								
Obstruction	3	4	8	1	14	3	97	130
Driver Obstruction/Duckers								
Motor Cycle Helmet	0	0	0	0	4	0	1	5
Plate Obstruction	0	0	2	0	0	0	9	11
Vehicle Obstruction	0	3	1	0	5	0	37	46
Police Rejects	7	2	6	0	8	6	78	107
Emergency Vehicle Responding	1	0	1	0	0	0	0	2
Incorrect/Incomplete DMV	4	2	1	0	4	1	14	26
Multiple vehicles in frame	0	0	0	0	0	0	5	5
On or Passed the Stop Bar (PD)	2	1	16	0	9	1	0	29
Safe Turn On Red	0	0	0	0	8	0	0	8
Yielding to an Emergency	0	0	0	0	0	0	1	1
Policy/Weather	1	1	0	0	0	0	4	6
Extended Vehicle								
Sun Glare	23	39	35	4	181	23	74	379
Registration Issues	0	1	1	0	0	0	1	3
Out of Country Plate								
Paper Plates	6	8	7	1	19	14	36	91
Total	47	61	78	6	252	48	357	849
Sub Total Violations	99	63	54	1	149	74	579	1019
Less in Progress	0	0	1	0	0	0	0	1
Available For Prosecution	99	63	53	1	149	74	579	1018
Less Rejects								
Camera Malfunction	1-01%	0-00%	1-02%	0-00%	3-02%	0-00%	1-00%	6-01%
Face Camera Flash	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	1-01%	0-00%	2-04%	0-00%	0-00%	0-00%	5-01%	8-01%
Face Not in Frame								

Generated By: SPIMENTEL
Generated On: 4/9/2014 4:57:16 PM

Customer Management Report (Hawthorne) All Detection Types

01-Mar-2014 to 31-Mar-2014

Operator Id: %

	HA-HAES-01	HA-HAES-03	HA-HAIM-01	HA-HAIM-03	HA-HIRO-01	HA-IMFR-01	HA-ROHI-01	TOTAL
Image Missing	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Misc Camera Issue	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%	7-01%
Plate Burn Out	0-00%	1-02%	0-00%	0-00%	0-00%	1-01%	0-00%	2-00%
Plate Not in Frame	1-01%	0-00%	4-08%	0-00%	0-00%	3-04%	0-00%	8-01%
Rear Plate Camera Blurry	1-01%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%	3-00%
Rear Plate Flash Inappropriate	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%	2-00%
Rear Plate No Flash	0-00%	3-05%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Police Driver Unidentifiable images poor	15-15%	6-10%	3-06%	1-100%	38-26%	8-11%	2-00%	73-07%
Rejects Insufficient Strobe Lighting	0-00%	0-00%	0-00%	0-00%	4-03%	0-00%	0-00%	4-00%
Red-light not visible in	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	3-00%
Unclear Scene Image	4-04%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
Process Issues Too Old	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Total	29-29%	13-21%	11-21%	1-100%	46-31%	13-18%	18-03%	131-13%
Approved Violations	70-71%	50-79%	42-79%	0-00%	103-69%	61-82%	561-97%	887-87%
Total Notices Printed	68-69%	46-73%	38-72%	0-00%	94-63%	58-78%	527-91%	831-82%

Legend: (P) = Production (I) = Inoperative
 Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SPIMENTEL
 Generated On: 4/9/2014 4:57:16 PM