

Customer Management Report (Hayward) Redlight Incidents

01-Dec-2009 to 31-Dec-2009

Operator Id: %

	HAY-B2ND-01	HAY-HEAS-01	HAY-INHU-01	HAY-WIHE-01	HAY-WIHE-03	TOTAL
Total Violations	116	445	541	446	121	1669
Less Uncontrollable Factors						
Obstruction	1	31	24	32	8	96
Motor Cycle Helmet	1	2	0	0	0	3
Plate Obstruction	2	9	21	26	4	62
Vehicle Obstruction	1	4	35	43	18	101
Police Rejects	2	2	0	0	0	4
Emergency Vehicle Responding	0	0	1	0	0	1
Invalid Offense	0	0	0	1	0	1
Plate Unidentifiable	0	0	0	1	0	1
Police Discretion	0	3	0	0	0	3
Safe Turn On Red	2	5	29	1	0	37
Policy/Weather	2	2	236	100	2	342
Extended Vehicle	1	38	21	6	3	69
Sun Glare	0	2	0	0	0	2
Weather/Nature	0	7	0	0	0	7
Yellow with Red Light	4	6	9	5	3	27
Paper Plates	0	2	0	0	0	2
Wrong or No DMV	16	113	376	214	38	757
Sub Total Violations	100	332	165	232	83	912
Less in Progress	0	0	0	1	0	1
Available For Prosecution	100	332	165	231	83	911
Less Rejects						
Camera	0-00%	0-00%	0-00%	0-00%	2-02%	2-00%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	2-02%	2-00%
Face Not in Frame	6-06%	0-00%	1-01%	0-00%	18-22%	25-03%
Misc Camera Issue	0-00%	0-00%	1-01%	1-00%	0-00%	2-00%
Plate Burn Out						

Dec 01

Rear Plate Camera Blurry	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	2-01%	0-00%	2-00%
Scene Image No Flash	0-00%	1-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	1-01%	12-04%	4-02%	4-02%	0-00%	21-02%
Driver Unidentifiable images poor	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Incorrect Speed	0-00%	0-00%	0-00%	2-01%	0-00%	2-00%
Limit line obstructed	6-06%	0-00%	0-00%	0-00%	0-00%	6-01%
No Video	0-00%	4-01%	0-00%	4-02%	0-00%	8-01%
Red-light not visible in	1-01%	4-01%	4-02%	6-03%	1-01%	16-02%
Too Old	14-14%	21-06%	12-07%	19-08%	23-28%	89-10%
Process Issues	86-86%	311-94%	153-93%	212-92%	60-72%	822-90%
Total						

Notices Printed

Customer Management Report (Hayward) Redlight Incidents

01-Jan-2010 to 31-Jan-2010 Operator Id: %

	HAY-A880-01	HAY-A880-03	HAY-B2ND-01	HAY-HEAS-01	HAY-INHU-01	HAY-INWH-01	HAY-MIIN-01	HAY-SCJA-01	HAY-WIHE-01	HAY-WIHE-03	TOTAL
Total Violations	0	0	101	374	439	0	0	0	294	168	1376
Less Uncontrollable Factors											
Obstruction	0	0	1	21	8	0	0	0	17	12	59
Driver Obstruction/Duckers	0	0	1	0	1	0	0	0	0	0	2
Motor Cycle Helmet	0	0	2	3	20	0	0	0	16	25	66
Plate Obstruction	0	0	0	0	0	0	0	0	3	0	3
Signal Obstruction	0	0	0	4	12	0	0	0	25	20	61
Vehicle Obstruction	0	0	1	2	7	0	0	0	2	2	14
Emergency Vehicle Responding	0	0	0	1	0	0	0	0	1	1	3
Invalid Offense	0	0	0	1	0	0	0	0	1	1	3
Plate Unidentifiable	0	0	0	1	0	0	0	0	1	1	3
Police Discretion	0	0	0	0	1	0	0	0	0	0	1
Safe Turn On Red	0	0	2	17	46	0	0	0	1	1	67
Weather Conditions	0	0	0	0	0	0	0	0	1	0	1
Yielding to an Emergency	0	0	0	1	0	0	0	0	0	0	1
Policy/Weather	0	0	0	4	188	0	0	0	60	6	258
Extended Vehicle	0	0	0	27	13	0	0	0	6	11	57
Sun Glare	0	0	1	0	1	0	0	0	0	0	2
Weather/Nature	0	0	0	2	0	0	0	0	0	0	2
Yellow with Red Light	0	0	0	0	0	0	0	0	0	0	0
Registration Issues	0	0	0	0	1	0	0	0	0	0	1
Can Not Identify State	0	0	5	10	8	0	0	0	6	1	30
Paper Plates	0	0	0	0	1	0	0	0	1	0	2
Wrong or No DMV	0	0	13	93	307	0	0	0	140	80	633
Total	0	0	88	281	132	0	0	0	154	88	743
Sub Total Violations	0	0	0	0	0	0	0	0	0	0	0
Less in Progress	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	0	0	88	281	132	0	0	0	154	88	743
Less Rejects											

Customer Management Report (Hayward) Redlight Incidents

01-Feb-2010 to 28-Feb-2010 Operator Id: %

	HAY-A880-01	HAY-A880-03	HAY-B2ND-01	HAY-HEAS-01	HAY-INHU-01	HAY-INWH-01	HAY-MIIN-01	HAY-SCJA-01	HAY-WIHE-01	HAY-WIHE-03	TOTAL
Total Violations	107	51	79	338	378	691	125	10	320	107	2206
Less Uncontrollable Factors											
Obstruction	2	5	0	14	11	71	6	6	12	7	134
Driver Obstruction/Duckers	0	1	0	2	0	0	0	0	0	1	4
Motor Cycle Helmet	14	0	0	6	14	19	2	0	17	19	91
Plate Obstruction	0	0	0	0	17	22	3	0	38	17	97
Vehicle Obstruction	0	0	2	5	7	2	2	0	0	2	20
Emergency Vehicle Responding	0	0	0	0	3	13	5	0	4	0	25
Invalid Offense	1	0	0	1	0	0	0	0	0	1	3
Plate Unidentifiable	0	0	1	1	1	0	0	0	0	0	3
Police Discretion	0	1	4	7	29	1	0	0	2	0	44
Safe Turn On Red	0	0	0	0	0	0	0	0	1	0	1
Weather Conditions	0	0	1	1	177	50	4	0	69	2	304
Policy/Weather	3	18	1	25	9	51	19	0	12	1	139
Extended Vehicle	0	0	1	5	1	7	3	0	4	0	21
Sun Glare	0	0	0	0	0	0	0	0	0	0	0
Weather/Nature	0	0	0	0	2	1	0	0	0	0	1
Can Not Identify State	0	0	0	1	2	1	0	0	0	0	4
Out of Country Plate	5	0	3	12	6	12	8	0	5	1	52
Paper Plates	1	0	0	0	0	3	0	0	1	0	5
Wrong or No DMV	26	25	13	80	277	253	52	6	165	51	948
Total	81	26	66	258	101	438	73	4	155	56	1258
Sub Total Violations	0	0	0	0	0	0	0	0	0	0	0
Less in Progress	81	26	66	258	101	438	73	4	155	56	1258
Available For Prosecution											
Less Rejects											
Camera	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	1-01%	0-00%	2-01%	0-00%	6-00%
Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Face Camera Focus Blurry											

Misc Camera Issue	1-01%	0-00%	0-00%	0-00%	0-00%	7-02%	0-00%	0-00%	0-00%	4-03%	0-00%	12-01%
Plate Burn Out	3-04%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	2-01%	0-00%	6-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	2-01%	0-00%	3-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	1-01%	2-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Driver Unidentifiable images poor	39-48%	15-58%	2-03%	19-07%	2-02%	267-61%	29-40%	0-00%	0-00%	7-05%	0-00%	380-30%
Limit line obstructed	35-43%	3-12%	1-02%	1-00%	0-00%	135-31%	28-38%	0-00%	0-00%	15-10%	2-04%	220-17%
Red-light not visible in	0-00%	1-04%	0-00%	6-02%	1-01%	5-01%	4-05%	0-00%	0-00%	11-07%	0-00%	28-02%
Too Old	0-00%	0-00%	0-00%	1-00%	2-02%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	4-00%
Total	78-96%	19-73%	3-05%	27-10%	6-06%	420-96%	64-88%	0-00%	0-00%	45-29%	2-04%	664-53%
Notices Printed	3-04%	7-27%	63-95%	231-90%	95-94%	18-04%	9-12%	4-100%	4-100%	110-71%	54-96%	594-47%

Feb 10

Customer Management Report (Hayward) Redlight Incidents

01-Mar-2010 to 31-Mar-2010 Operator Id: %

	HAY-A880-01	HAY-A880-03	HAY-B2ND-01	HAY-HEAS-01	HAY-INHU-01	HAY-INWH-01	HAY-MIIN-01	HAY-SCJA-01	HAY-WIHE-01	HAY-WIHE-03	TOTAL
Total Violations	1571	2253	94	336	384	1554	126	479	403	149	7349
Less Uncontrollable Factors											
Obstruction	52	33	2	25	9	427	4	221	25	15	813
Driver Obstruction/Duckers											
Motor Cycle Helmet	1	4	0	1	0	1	1	1	0	0	9
Plate Obstruction	211	50	0	4	10	46	3	23	16	15	378
Vehicle Obstruction	5	7	0	5	18	28	1	44	34	26	168
Emergency Vehicle Responding	13	35	1	6	8	8	3	1	0	0	75
Funeral Procession/Police	0	0	0	0	0	0	1	0	0	0	1
Invalid Offense	1	2	0	3	3	1	0	0	1	0	11
Plate Unidentifiable	4	14	2	1	0	5	1	1	1	1	30
Police Discretion	2	2	1	0	0	0	0	0	0	0	5
Safe Turn On Red	18	61	4	16	42	21	0	0	2	0	164
Weather Conditions	21	24	2	4	1	10	0	0	2	0	64
Policy/Weather	9	8	2	2	165	79	1	7	97	4	374
Extended Vehicle											
Sun Glare	48	41	3	33	17	73	12	14	48	6	295
Weather/Nature	0	2	0	0	1	1	0	0	10	1	15
Registration	39	60	2	8	3	33	7	4	10	3	169
Paper Plates											
Issues	4	1	0	0	1	2	0	0	0	0	8
Wrong or No DMV											
Total	428	344	19	108	278	735	34	316	246	71	2579
Sub Total Violations	1143	1909	75	228	106	819	92	163	157	78	4770
Less in Progress	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	1143	1909	75	228	106	819	92	163	157	78	4770
Less Rejects											
Camera	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-00%
Digital Distortion											
Malfunction	0-00%	0-00%	0-00%	0-00%	1-01%	3-00%	1-01%	0-00%	2-01%	7-09%	14-00%
Face Camera Flash											
Face Camera Focus Blurry	0-00%	1-00%	0-00%	1-00%	0-00%	0-00%	2-02%	0-00%	1-01%	0-00%	5-00%

Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-03%	0-00%	0-00%	0-00%	1-01%	10-00%
Face Not in Frame	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	3-02%	2-01%	3-04%	18-00%	
Image Missing	0-00%	1-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-02%	0-00%	0-00%	6-00%	
Misc Camera Issue	8-01%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	54-34%	0-00%	65-01%	
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	2-00%	
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%	
Rear Plate Camera Blurry	3-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	4-00%	
Rear Plate Flash Inappropriate	13-01%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	16-00%	
Rear Plate No Flash	15-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	15-00%	
Scene Image Flash Inappropriate	2-00%	0-00%	0-00%	0-00%	2-02%	2-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	7-00%	
Police Rejects	185-16%	69-04%	3-04%	31-14%	0-00%	71-09%	12-13%	51-31%	7-04%	2-03%	2-03%	7-04%	2-03%	431-09%	
Incorrect Speed	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Limit line obstructed	241-21%	165-09%	0-00%	6-03%	3-03%	116-14%	19-21%	5-03%	9-06%	4-05%	568-12%				
No Video	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	2-00%				
Red-light not visible in	4-00%	0-00%	0-00%	15-07%	4-04%	1-00%	1-01%	6-04%	2-01%	5-06%	38-01%				
Too Old	0-00%	0-00%	0-00%	1-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-01%	3-00%				
Process Issues	472-41%	239-13%	3-04%	55-24%	11-10%	211-26%	40-43%	69-42%	82-52%	25-32%	1207-25%				
Total	671-59%	1670-87%	72-96%	173-76%	95-90%	608-74%	52-57%	94-58%	75-48%	53-68%	3563-75%				

Notices Printed

Mar 10