

Customer Management Report (Menlo Park) All Detection Types

01-Feb-2011 to 28-Feb-2011

Operator Id: %

	MEN-BAWI-01	MEN-ECRA-01	MEN-ECRA-03	MEN-ECVA-01	TOTAL
Total Processed Incidents	68	163	157	91	479
Less Uncontrollable Factors					
Obstruction	4	17	6	9	36
Driver Obstruction/Duckers	0	3	4	2	9
Plate Obstruction	2	2	4	2	10
Vehicle Obstruction	2	5	0	0	7
Emergency Vehicle Responding	0	0	4	0	4
Plate Unidentifiable	0	5	0	7	12
Safe Turn On Red	0	4	0	1	5
Sun Glare	0	0	1	0	1
Yielding to an Emergency	0	2	1	0	3
Extended Vehicle	0	2	10	5	17
Sun Glare	0	2	0	2	4
Weather/Nature	2	5	0	2	9
Paper Plates	10	47	30	30	117
Sub Total Violations	58	116	127	61	362
Less in Progress	0	0	0	0	0
Available For Prosecution	58	116	127	61	362
Less Rejects					
Camera	0-00%	0-00%	0-00%	2-03%	2-01%
Malfunction	4-07%	1-01%	3-02%	3-05%	11-03%
Face Camera Focus Blurry	2-03%	2-02%	4-03%	1-02%	9-02%
Face Not in Frame	0-00%	0-00%	1-01%	1-02%	2-01%
Image Missing	0-00%	0-00%	0-00%	7-11%	7-02%
Misc Camera Issue	0-00%	1-01%	1-01%	0-00%	2-01%
Plate Not in Frame	0-00%	0-00%	0-00%	6-10%	6-02%
Scene Image Flash Inappropriate	1-02%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable Images poor	0-00%	0-00%	1-01%	0-00%	1-00%
Insufficient Strobe Lighting	0-00%	1-01%	0-00%	0-00%	1-00%
Red-light not visible in	1-02%	2-02%	2-02%	1-02%	6-02%
Unclear Scene Image	4-07%	5-04%	10-08%	6-10%	25-07%
Too Old	12-21%	12-10%	22-17%	27-44%	73-20%
Approved Violations	46-79%	104-90%	105-83%	34-56%	289-80%
Total Notices Printed	46-79%	104-90%	105-83%	34-56%	289-80%

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:38:00 AM

Customer Management Report (Menlo Park) All Detection Types

01-Feb-2011 to 28-Feb-2011

Operator Id: %

MEN-BAWI-01	MEN-ECRA-01	MEN-ECRA-03	MEN-ECVA-01	TOTAL
-------------	-------------	-------------	-------------	-------

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:38:00 AM

Customer Management Report (Menlo Park) All Detection Types

01-Mar-2011 to 31-Mar-2011 Operator Id: %

	MEN-BAWI-01	MEN-ECRA-01	MEN-ECRA-03	MEN-ECVA-01	TOTAL
Total Processed Incidents	68	172	132	127	499
Less Uncontrollable Factors					
Obstruction - Driver Obstruction/Duckers	4	11	6	13	34
Plate Obstruction	2	5	4	2	13
Vehicle Obstruction	2	4	5	1	12
Police Rejects	0	2	0	0	2
Emergency Vehicle Responding	0	1	0	0	1
Invalid Offense	0	1	0	0	1
Plate Obstruction (PD)	0	1	0	0	1
Plate Unidentifiable	0	0	1	2	3
Safe Turn On Red	0	3	0	8	11
Sun Glare	0	0	1	2	3
Policy/Weather	0	2	1	1	4
Extended Vehicle	3	2	15	10	30
Sun Glare	0	1	7	3	11
Weather/Nature					
Paper Plates	4	2	3	2	11
Registration Issues					
Total	15	34	43	44	136
Sub Total Violations	53	138	89	83	363
Less in Progress	0	0	0	0	0
Available For Prosecution	53	138	89	83	363
Less Rejects					
Camera	0-00%	2-01%	0-00%	2-02%	4-01%
Face Camera Flash	7-13%	10-07%	6-07%	2-02%	25-07%
Face Camera Focus Blurry	2-04%	6-04%	1-01%	2-02%	11-03%
Face Not in Frame	1-02%	1-01%	0-00%	0-00%	2-01%
Misc Camera Issue	0-00%	0-00%	1-01%	0-00%	1-00%
Plate Burn Out	0-00%	0-00%	1-01%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	1-01%	0-00%	1-00%
Rear Plate Camera Blurry	1-02%	1-01%	0-00%	1-01%	2-01%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-01%	2-01%
Scene Image No Flash	0-00%	0-00%	0-00%	1-01%	1-00%
Driver Unidentifiable Images poor	1-02%	1-01%	0-00%	0-00%	2-01%
Police Rejects	0-00%	0-00%	1-01%	1-01%	2-01%
Unclear Scene Image	12-23%	21-15%	10-11%	10-12%	53-15%
Total	41-77%	117-85%	79-89%	73-88%	310-85%
Approved Violations	41-77%	117-85%	79-89%	73-88%	310-85%
Total Notices Printed	41-77%	117-85%	79-89%	73-88%	310-85%

Customer Management Report (Menlo Park) All Detection Types

01-Mar-2011 to 31-Mar-2011

Operator Id: %

MEN-BAWI-01	MEN-ECRA-01	MEN-ECRA-03	MEN-ECVA-01	TOTAL
-------------	-------------	-------------	-------------	-------

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:33:42 AM

Customer Management Report (Menlo Park) All Detection Types

01-May-2011 to 31-May-2011

Operator Id: %

		MEN-BAWI-01	MEN-ECRA-01	MEN-ECRA-03	MEN-ECVA-01	TOTAL
Total Processed Incidents		67	109	171	194	541
Less Uncontrollable Factors						
Obstruction	Driver Obstruction/Duckers	12	5	7	17	41
	Plate Obstruction	0	3	5	4	12
	Signal Obstruction	0	0	0	3	3
	Vehicle Obstruction	1	2	2	1	6
Police Rejects	Citation Issued manually	0	1	0	0	1
	Emergency Vehicle Responding	1	0	2	4	7
	On or Passed the Stop Bar (PD)	0	0	1	2	3
	Safe Turn On Red	0	8	0	19	27
	Sun Glare	0	0	0	4	4
Policy/Weather	Extended Vehicle	3	2	0	3	8
	Sun Glare	7	9	31	14	61
Registration Issues	Paper Plates	3	1	2	2	8
Total		27	31	50	73	181
Sub Total Violations		40	78	121	121	360
Less in Progress		0	0	0	0	0
Available For Prosecution		40	78	121	121	360
Less Rejects						
Camera Malfunction	Face Camera Flash	1-02%	1-01%	1-01%	0-00%	3-01%
	Face Camera Focus Blurry	0-00%	0-00%	1-01%	1-01%	2-01%
	Face Not in Frame	5-12%	1-01%	0-00%	0-00%	6-02%
	Misc Camera Issue	0-00%	1-01%	0-00%	3-02%	4-01%
	Plate Not in Frame	0-00%	1-01%	1-01%	0-00%	2-01%
	Rear Plate Camera Blurry	0-00%	1-01%	1-01%	0-00%	2-01%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	4-03%	4-01%
	Scene Image No Flash	0-00%	0-00%	0-00%	1-01%	1-00%
Police Rejects Process Issues	Driver Unidentifiable images poor	2-05%	0-00%	3-02%	4-03%	9-02%
	Too Old	0-00%	1-01%	0-00%	1-01%	2-01%
Total		8-20%	6-08%	7-06%	14-12%	35-10%
Approved Violations		32-80%	72-92%	114-94%	107-88%	325-90%
Total Notices Printed		32-80%	72-92%	114-94%	107-88%	325-90%

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:39:21 AM

Customer Management Report (Menlo Park) All Detection Types

01-May-2011 to 31-May-2011

Operator Id: %

TOTAL	MEN-ECVA-01	MEN-ECRA-03	MEN-ECRA-01	MEN-BAWI-01
-------	-------------	-------------	-------------	-------------

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:39:21 AM

Customer Management Report (Menlo Park) All Detection Types

01-Jun-2011 to 30-Jun-2011

Operator Id: %

		MEN-BAWI-01	MEN-ECRA-01	MEN-ECRA-03	MEN-ECVA-01	TOTAL
Total Processed Incidents		67	95	159	220	541
Less Uncontrollable Factors						
Obstruction	Driver Obstruction/Duckers	4	1	7	23	35
	Plate Obstruction	2	1	10	10	23
	Signal Obstruction	0	0	1	2	3
	Vehicle Obstruction	1	2	10	4	17
Police Rejects	Emergency Vehicle Responding	0	2	0	2	4
	Invalid Offense	0	0	1	0	1
	Multiple vehicles in frame	0	0	2	0	2
	On or Passed the Stop Bar (PD)	0	0	1	0	1
	Safe Turn On Red	0	1	0	14	15
	Sun Glare	0	0	5	2	7
Policy/Weather	Extended Vehicle	0	0	0	3	3
	Sun Glare	4	4	21	20	49
	Weather/Nature	0	1	0	0	1
Registration Issues	Paper Plates	3	1	2	6	12
Total		14	13	60	86	173
Sub Total Violations		53	82	99	134	368
Less in Progress		0	0	0	0	0
Available For Prosecution		53	82	99	134	368
Less Rejects						
Camera Malfunction	Face Camera Flash	0-00%	1-01%	0-00%	0-00%	1-00%
	Face Camera Focus Blurry	3-06%	0-00%	0-00%	1-01%	4-01%
	Face Not in Frame	14-26%	4-05%	3-03%	5-04%	26-07%
	Misc Camera Issue	0-00%	0-00%	0-00%	1-01%	1-00%
	Plate Burn Out	0-00%	0-00%	0-00%	1-01%	1-00%
	Plate Not in Frame	0-00%	0-00%	1-01%	0-00%	1-00%
	Rear Plate Camera Blurry	1-02%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Flash Inappropriate	0-00%	1-01%	0-00%	1-01%	2-01%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	5-04%	5-01%
Scene Image No Flash	0-00%	0-00%	0-00%	1-01%	1-00%	
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	1-01%	1-01%	2-01%
Total		18-34%	6-07%	5-05%	16-12%	45-12%
Approved Violations		35-66%	76-93%	94-95%	118-88%	323-88%
Total Notices Printed		35-66%	76-93%	94-95%	118-88%	323-88%

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:40:20 AM

Customer Management Report (Menlo Park) All Detection Types

01-Jun-2011 to 30-Jun-2011

Operator Id: %

TOTAL	MENEQVA-01	MENEQRA-03	MENEQRA-01	MENBAWI-01
-------	------------	------------	------------	------------

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:40:20 AM

Customer Management Report (Menlo Park) All Detection Types

01-Aug-2011 to 31-Aug-2011

Operator Id: %

		MEN-BAWI-01	MEN-ECRA-01	MEN-ECRA-03	MEN-ECVA-01	TOTAL
Total Processed Incidents		81	152	164	240	637
Less Uncontrollable Factors						
Obstruction	Driver Obstruction/Duckers	11	5	13	37	66
	Motor Cycle Helmet	0	1	0	1	2
	Plate Obstruction	0	4	6	7	17
	Signal Obstruction	0	0	0	1	1
	Vehicle Obstruction	3	1	2	1	7
Police Rejects	Emergency Vehicle Responding	0	0	2	3	5
	Incorrect/Incomplete DMV	0	0	0	1	1
	Invalid Offense	0	0	2	0	2
	Multiple vehicles in frame	0	0	2	1	3
	Safe Turn On Red	0	5	0	19	24
Policy/Weather	Extended Vehicle	0	1	4	0	5
	Sun Glare	9	2	23	22	56
Registration Issues	Can Not Identify State	0	1	0	0	1
	Paper Plates	3	4	4	3	14
Total		26	24	58	96	204
Sub Total Violations		55	128	106	144	433
Less in Progress		0	0	0	0	0
Available For Prosecution		55	128	106	144	433
Less Rejects						
Camera Malfunction	Face Camera Flash	2-04%	0-00%	0-00%	1-01%	3-01%
	Face Camera Focus Blurry	1-02%	0-00%	2-02%	1-01%	4-01%
	Face Not in Frame	2-04%	3-02%	4-04%	5-03%	14-03%
	Misc Camera Issue	0-00%	0-00%	14-13%	1-01%	15-03%
	Plate Burn Out	0-00%	0-00%	0-00%	1-01%	1-00%
	Rear Plate Camera Blurry	0-00%	1-01%	0-00%	0-00%	1-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	1-01%	1-00%
Police Rejects Process Issues	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	4-03%	4-01%
	Too Old	0-00%	0-00%	1-01%	0-00%	1-00%
Total		5-09%	4-03%	21-20%	14-10%	44-10%
Approved Violations		50-91%	124-97%	85-80%	130-90%	389-90%
Total Notices Printed		50-91%	124-97%	85-80%	130-90%	389-90%

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:41:11 AM

Customer Management Report (Menlo Park) All Detection Types

01-Aug-2011 to 31-Aug-2011

Operator Id: %

MEN-BAWI-01	MEN-ECRA-01	MEN-ECRA-03	MEN-ECVA-01	TOTAL
-------------	-------------	-------------	-------------	-------

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:41:11 AM

Customer Management Report (Menlo Park) All Detection Types

01-Sep-2011 to 30-Sep-2011

Operator Id: %

		MEN-BAWI-01	MEN-ECRA-01	MEN-ECRA-03	MEN-ECVA-01	TOTAL
Total Processed Incidents		101	198	163	221	683
Less Uncontrollable Factors						
Obstruction	Driver Obstruction/Duckers	9	7	4	21	41
	Plate Obstruction	4	8	6	16	34
	Signal Obstruction	0	0	1	1	2
	Vehicle Obstruction	4	8	6	0	18
Police Rejects	Emergency Vehicle Responding	0	3	0	0	3
	Invalid Offense	0	2	0	2	4
	Multiple vehicles in frame	0	0	1	0	1
	On or Passed the Stop Bar (PD)	0	0	0	1	1
	Plate Unidentifiable	0	1	1	0	2
	Safe Turn On Red	0	7	0	22	29
	Sun Glare	0	1	0	0	1
Policy/Weather	Extended Vehicle	3	2	3	7	15
	Sun Glare	2	4	14	21	41
Registration Issues	Can Not Identify State	1	1	0	0	2
	Out of Country Plate	0	0	1	1	2
	Paper Plates	2	3	5	5	15
Total		25	47	42	97	211
Sub Total Violations		76	151	121	124	472
Less in Progress		0	0	0	0	0
Available For Prosecution		76	151	121	124	472
Less Rejects						
Camera Malfunction	Face Camera Focus Blurry	2-03%	0-00%	0-00%	0-00%	2-00%
	Face Not in Frame	0-00%	3-02%	5-04%	4-03%	12-03%
	Plate Not in Frame	0-00%	0-00%	0-00%	1-01%	1-00%
	Rear Plate Camera Blurry	0-00%	1-01%	0-00%	3-02%	4-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-01%	1-00%
Police Rejects	Driver Unidentifiable images poor	2-03%	0-00%	3-02%	5-04%	10-02%
	Plate Unclear	0-00%	0-00%	0-00%	1-01%	1-00%
	Red-light not visible in	2-03%	0-00%	0-00%	0-00%	2-00%
	Unclear Scene Image	2-03%	1-01%	1-01%	0-00%	4-01%
Process Issues	Too Old	1-01%	0-00%	0-00%	1-01%	2-00%
Total		9-12%	5-03%	9-07%	16-13%	39-08%
Approved Violations		67-88%	146-97%	112-93%	108-87%	433-92%

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:42:01 AM

Customer Management Report (Menlo Park) All Detection Types

01-Sep-2011 to 30-Sep-2011

Operator Id: %

	MEN-BAWI-01	MEN-ECRA-01	MEN-ECRA-03	MEN-ECVA-01	TOTAL
Total Notices Printed	67-88%	146-97%	112-93%	108-87%	433-92%

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:42:01 AM

Customer Management Report (Menlo Park) All Detection Types

01-Nov-2011 to 30-Nov-2011

Operator Id: %

		MEN-BAWI-01	MEN-ECRA-01	MEN-ECRA-03	MEN-ECVA-01	TOTAL
Total Processed Incidents		70	208	208	180	666
Less Uncontrollable Factors						
Obstruction	Driver Obstruction/Duckers	6	3	3	17	29
	Motor Cycle Helmet	1	0	0	0	1
	Plate Obstruction	3	10	11	4	28
	Signal Obstruction	0	1	0	0	1
	Vehicle Obstruction	0	2	6	0	8
Police Rejects	Emergency Vehicle Responding	0	2	1	2	5
	Invalid Offense	0	0	1	2	3
	Multiple vehicles in frame	0	0	1	0	1
	Plate Unidentifiable	0	0	0	1	1
	Police Discretion	0	1	1	1	3
	Safe Turn On Red	0	13	0	14	27
	Sun Glare	0	4	0	0	4
Policy/Weather	Extended Vehicle	1	2	1	3	7
	Sun Glare	1	7	16	20	44
Registration Issues	Can Not Identify State	0	1	0	0	1
	Paper Plates	2	4	2	3	11
Total		14	50	43	67	174
Sub Total Violations		56	158	165	113	492
Less in Progress		0	0	0	0	0
Available For Prosecution		56	158	165	113	492
Less Rejects						
Camera Malfunction	Face Camera Focus Blurry	3-05%	1-01%	1-01%	7-06%	12-02%
	Face Not in Frame	5-09%	3-02%	3-02%	3-03%	14-03%
	Image Missing	1-02%	0-00%	0-00%	1-01%	2-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	1-01%	1-00%
	Rear Plate Camera Blurry	0-00%	1-01%	0-00%	0-00%	1-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	1-01%	1-00%
Police Rejects	Driver Unidentifiable images poor	2-04%	1-01%	1-01%	5-04%	9-02%
	Unclear Scene Image	0-00%	1-01%	1-01%	0-00%	2-00%
Process Issues	Too Old	0-00%	0-00%	1-01%	0-00%	1-00%
Total		11-20%	7-04%	7-04%	18-16%	43-09%
Approved Violations		45-80%	151-96%	158-96%	95-84%	449-91%
Total Notices Printed		45-80%	151-96%	158-96%	95-84%	449-91%

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:43:25 AM

Customer Management Report (Menlo Park) All Detection Types

01-Nov-2011 to 30-Nov-2011

Operator Id: %

	MEN-BAWI-01	MEN-ECRA-01	MEN-ECRA-03	MEN-ECVA-01	TOTAL
--	-------------	-------------	-------------	-------------	-------

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:43:25 AM

Customer Management Report (Menlo Park) All Detection Types

01-Dec-2011 to 31-Dec-2011

Operator Id: %

		MEN-BAWI-01	MEN-ECRA-01	MEN-ECRA-03	MEN-ECVA-01	TOTAL
Total Processed Incidents		62	192	213	188	655
Less Uncontrollable Factors						
Obstruction	Driver Obstruction/Duckers	6	11	9	10	36
	Plate Obstruction	1	5	8	4	18
	Vehicle Obstruction	3	4	7	2	16
Police Rejects	Emergency Vehicle Responding	0	0	1	2	3
	Incorrect/Incomplete DMV	0	0	0	1	1
	Invalid Offense	0	1	0	1	2
	Multiple vehicles in frame	0	0	1	0	1
	On or Passed the Stop Bar (PD)	0	1	0	2	3
	Plate Obstruction (PD)	0	1	0	1	2
	Police Discretion	0	0	1	0	1
	Safe Turn On Red	0	7	0	14	21
	Policy/Weather	Extended Vehicle Sun Glare	2	1	3	1
Registration Issues	Paper Plates	1	5	4	4	14
	Total	15	38	48	54	155
Sub Total Violations		47	154	165	134	500
Less in Progress		0	0	0	0	0
Available For Prosecution		47	154	165	134	500
Less Rejects						
Camera Malfunction	Face Camera Flash	0-00%	1-01%	0-00%	2-01%	3-01%
	Face Camera Focus Blurry	6-13%	0-00%	0-00%	17-13%	23-05%
	Face Not in Frame	3-06%	4-03%	3-02%	1-01%	11-02%
	Misc Camera Issue	2-04%	0-00%	1-01%	1-01%	4-01%
	Plate Not in Frame	0-00%	0-00%	1-01%	1-01%	2-00%
	Rear Plate Camera Blurry	1-02%	1-01%	0-00%	1-01%	3-01%
Police Rejects	Driver Unidentifiable images poor	1-02%	0-00%	0-00%	3-02%	4-01%
	Unclear Scene Image	0-00%	1-01%	0-00%	0-00%	1-00%
Process Issues	Too Old	0-00%	4-03%	6-04%	3-02%	13-03%
Total		13-28%	11-07%	11-07%	29-22%	64-13%
Approved Violations		34-72%	143-93%	154-93%	105-78%	436-87%
Total Notices Printed		34-72%	143-93%	154-93%	105-78%	436-87%

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:44:15 AM

Customer Management Report (Menlo Park) All Detection Types

01-Dec-2011 to 31-Dec-2011

Operator Id: %

TOTAL	MEN-ECVA-01	MEN-ECRA-03	MEN-ECRA-01	MEN-BAWI-01
-------	-------------	-------------	-------------	-------------

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:44:15 AM

Customer Management Report (Menlo Park) All Detection Types

01-Feb-2013 to 28-Feb-2013

Operator Id: %

		MENBAWI-01	MENECRA-01	MENECRA-03	MENECVA-01	TOTAL
Total Processed Incidents		41	116	112	244	513
Less Uncontrollable Factors						
Obstruction	Driver Obstruction/Duckers	4	2	4	5	15
	Motor Cycle Helmet	0	0	0	1	1
	Plate Obstruction	1	4	8	6	19
	Vehicle Obstruction	7	2	0	5	14
Police Rejects	Emergency Vehicle Responding	0	2	1	3	6
	Incorrect Plate on Vehicle	0	0	1	0	1
	Invalid Offense	0	0	0	1	1
	Multiple vehicles in frame	0	1	0	0	1
	On or Passed the Stop Bar (PD).	0	2	2	3	7
	Safe Turn On Red	0	4	1	20	25
	Sun Glare	0	2	2	1	5
Policy/Weather	Extended Vehicle	0	3	3	7	13
	Sun Glare	2	9	9	10	30
Registration Issues	Paper Plates	0	3	2	8	13
Total		14	34	33	70	151
Sub Total Violations		27	82	79	174	362
Less in Progress		0	0	0	0	0
Available For Prosecution		27	82	79	174	362
Less Rejects						
Camera Malfunction	Face Camera Focus Blurry	1-04%	1-01%	0-00%	2-01%	4-01%
	Face Not in Frame	1-04%	0-00%	0-00%	0-00%	1-00%
	Image Missing	0-00%	0-00%	0-00%	1-01%	1-00%
	Misc Camera Issue	0-00%	3-04%	6-08%	2-01%	11-03%
	Rear Plate Camera Blurry	0-00%	8-10%	9-11%	1-01%	18-05%
Police Rejects	Driver Unidentifiable images poor	0-00%	1-01%	0-00%	11-06%	12-03%
	Red-light not visible in	0-00%	1-01%	11-14%	0-00%	12-03%
Process Issues	Too Old	0-00%	0-00%	0-00%	1-01%	1-00%
Total		2-07%	14-17%	26-33%	18-10%	60-17%
Approved Violations		25-93%	68-83%	53-67%	156-90%	302-83%
Total Notices Printed		25-93%	68-83%	53-67%	156-90%	302-83%

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:45:24 AM

Customer Management Report (Menlo Park) All Detection Types

01-Feb-2013 to 28-Feb-2013

Operator Id: %

TOTAL	MENEQVA-01	MENEQRA-03	MENEQRA-01	MENBAWI-01
-------	------------	------------	------------	------------

Generated By: SKAUFMAN

Generated On: 4/3/2013 7:45:24 AM

Customer Management Report (Menlo Park) All Detection Types

01-Mar-2013 to 31-Mar-2013

Operator Id: %

	MEN-BAWI-01	MEN-ECRA-01	MEN-ECRA-03	MEN-ECVA-01	TOTAL
Total Processed Incidents	132	166	161	306	765
Less Uncontrollable Factors					
Obstruction					
Driver Obstruction/Duckers	9	0	1	6	16
Motor Cycle Helmet	1	0	0	0	1
Plate Obstruction	4	5	3	7	19
Vehicle Obstruction	10	4	5	3	22
Police Rejects					
Emergency Vehicle Responding	0	1	0	3	4
Incorrect/Incomplete DMV	0	0	1	0	1
Invalid Offense	0	0	1	0	1
On or Passed the Stop Bar (PD)	0	3	11	0	14
Safe Turn On Red	0	6	0	15	21
Sun Glare	0	1	0	0	1
Policy/Weather					
Extended Vehicle	1	3	3	4	11
Sun Glare	6	3	11	25	45
Weather/Nature	1	0	0	0	1
Registration Issues					
Out of Country Plate	1	0	0	0	1
Paper Plates	5	6	1	7	19
Total	38	32	37	70	177
Sub Total Violations	94	134	124	236	588
Less in Progress	16	31	26	60	133
Available For Prosecution	78	103	98	176	455
Less Rejects					
Camera Malfunction					
Face Camera Focus Blurry	3-04%	1-01%	0-00%	1-01%	5-01%
Face Not in Frame	1-01%	1-01%	1-01%	0-00%	3-01%
Image Missing	0-00%	0-00%	0-00%	2-01%	2-00%
Misc Camera Issue	0-00%	0-00%	0-00%	1-01%	1-00%
Plate Not in Frame	0-00%	1-01%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	2-01%	2-00%
Police Rejects					
Driver Unidentifiable images poor	6-08%	7-07%	1-01%	12-07%	26-06%
Red-light not visible in	3-04%	0-00%	0-00%	0-00%	3-01%
Process Issues					
Too Old	0-00%	0-00%	0-00%	2-01%	2-00%
Total	13-17%	10-10%	2-02%	20-11%	45-10%
Approved Violations	65-83%	93-90%	96-98%	156-89%	410-90%
Total Notices Printed	62-79%	92-89%	93-95%	152-86%	399-88%

Generated By: SKAUFMAN
Generated On: 4/3/2013 7:46:29 AM

Customer Management Report (Menlo Park) All Detection Types

01-Mar-2013 to 31-Mar-2013

Operator Id: %

TOTAL	MEN-ECVA-01	MEN-ECRA-03	MEN-ECRA-01	MEN-BAWI-01
-------	-------------	-------------	-------------	-------------

Generated By: SKAUFMAN

Generated On: 4/3/2013 7:46:29 AM