

Customer Management Report (Oceanside) All Detection Types

01-Apr-2011 to 30-Apr-2011

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCCO-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Total Processed Incidents	71	163	120	96	56	254	272	285	1317
Less Uncontrollable Factors									
Obstruction	1	7	31	4	2	15	17	21	98
Driver Obstruction/Duckers	0	0	0	0	0	1	2	0	3
Motor Cycle Helmet	1	7	6	2	1	1	7	10	35
Plate Obstruction	0	0	0	0	0	0	0	1	1
Signal Obstruction	0	0	4	1	0	0	2	2	9
Vehicle Obstruction	0	1	1	1	1	0	0	0	4
Emergency Vehicle Responding	1	0	0	2	0	2	2	3	10
Police Rejects	0	0	0	0	0	1	2	2	5
Incorrect/Incomplete DMV	0	1	0	0	1	2	1	3	8
Invalid Offense	9	1	6	7	6	17	9	1	56
Police Discretion	0	0	0	1	1	0	0	0	2
Safe Turn On Red	0	2	2	0	0	0	0	3	7
Sun Glare	0	2	2	0	0	0	0	3	7
Policy/Weather	5	32	15	3	6	49	90	57	257
Extended Vehicle	1	1	0	0	1	6	1	0	10
Sun Glare	0	1	0	0	0	1	1	0	3
Weather/Nature	0	0	0	0	0	0	0	0	0
Yellow with Red Light	0	0	0	2	0	0	1	3	6
Registration Issues	0	0	0	0	1	1	0	0	2
Can Not Identify State	3	4	2	2	0	7	4	5	27
Out of Country Plate	0	2	0	0	0	1	1	0	4
Paper Plates	21	59	67	25	20	104	140	111	547
Wrong or No DMV	50	104	53	71	36	150	132	174	770
Sub Total Violations	0	0	0	0	0	0	0	0	0
Less in Progress	50	104	53	71	36	150	132	174	770
Available For Prosecution									

Generated By: PROMO

Generated On: 5/14/2013 8:22:43 AM

Customer Management Report (Oceanside) All Detection Types

01-Apr-2011 to 30-Apr-2011

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCOC-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Less Rejects									
Camera Malfunction	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Flash	0-00%	0-00%	0-00%	1-01%	0-00%	10-07%	23-17%	1-01%	35-05%
Face Camera Focus Blurry	0-00%	4-04%	1-02%	0-00%	0-00%	2-01%	8-06%	19-11%	34-04%
Face Not in Frame	0-00%	1-01%	2-04%	0-00%	0-00%	0-00%	0-00%	1-01%	4-01%
Misc Camera Issue	1-02%	0-00%	0-00%	0-00%	0-00%	15-10%	2-02%	12-07%	30-04%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-02%	3-02%	6-01%
Rear Plate Camera Blurry	0-00%	3-03%	2-04%	5-07%	1-03%	0-00%	0-00%	2-01%	13-02%
Rear Plate Flash Inappropriate	0-00%	0-00%	1-02%	1-01%	0-00%	0-00%	1-01%	1-01%	4-01%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	3-02%	0-00%	0-00%	3-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Police Rejects	0-00%	0-00%	1-02%	1-01%	0-00%	1-01%	4-03%	10-06%	17-02%
Incorrect Speed	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-02%	3-02%	6-01%
Process Issues	1-02%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Total	3-06%	8-08%	8-15%	8-11%	1-03%	31-21%	46-35%	52-30%	157-20%
Approved Violations	47-94%	96-92%	45-85%	63-89%	35-97%	119-79%	86-65%	122-70%	613-80%
Total Notices Printed	47-94%	96-92%	45-85%	63-89%	35-97%	119-79%	86-65%	122-70%	613-80%

Generated By: PROMO
Generated On: 5/14/2013 8:22:43 AM

Customer Management Report (Oceanside) All Detection Types

01-May-2011 to 31-May-2011

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCCO-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Total Processed Incidents	78	144	144	91	69	265	288	372	1451
Less Uncontrollable Factors									
Obstruction Driver Obstruction/Duckers	3	20	41	7	2	10	13	18	114
Motor Cycle Helmet	0	1	1	0	0	2	0	1	5
Plate Obstruction	0	2	7	4	3	2	12	19	49
Signal Obstruction	0	0	1	0	0	0	12	0	13
Vehicle Obstruction	0	0	9	1	0	1	8	0	19
Police Rejects	1	3	3	0	0	1	1	0	9
Face Obstruction	0	2	1	1	1	3	2	1	11
Incorrect/Incomplete DMV	1	1	0	0	1	4	3	1	11
Invalid Offense	0	0	0	0	0	0	0	68	68
Police Discretion	0	2	4	1	0	3	5	8	23
Safe Turn On Red	9	4	10	7	5	66	12	2	115
Sun Glare	0	1	0	0	3	0	2	2	8
Policy/Weather	1	0	0	0	0	1	1	6	9
Extended Vehicle	2	28	15	9	7	14	56	65	196
Sun Glare	0	0	0	0	0	1	0	0	1
Weather/Nature	0	2	1	0	0	0	0	0	3
Can Not Identify State	0	2	1	0	1	0	0	4	8
Issues	0	0	0	0	0	1	0	1	2
Out of Country Plate	2	3	2	1	6	7	4	7	32
Paper Plates	0	2	0	0	0	0	1	0	3
Wrong or No DMV	19	71	95	31	29	116	132	203	696
Sub Total Violations	59	73	49	60	40	149	156	169	755
Less in Progress	0	0	0	0	0	0	0	0	0
Available For Prosecution	59	73	49	60	40	149	156	169	755

Generated By: PROMO

Generated On: 5/13/2013 2:11:16 PM

Customer Management Report (Oceanside) All Detection Types

01-May-2011 to 31-May-2011

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCOC-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Less Rejects									
Camera Face Camera Flash	0-00%	1-01%	0-00%	0-00%	0-00%	1-01%	4-03%	4-02%	10-01%
Camera Malfunction Face Camera Focus Blurry	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	6-04%	8-01%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-00%
Face Not in Frame	1-02%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	2-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	8-05%	0-00%	9-01%
Plate Burn Out	0-00%	1-01%	0-00%	2-03%	0-00%	0-00%	0-00%	1-01%	4-01%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	2-00%
Rear Plate Camera Blurry	0-00%	4-05%	0-00%	1-02%	0-00%	0-00%	0-00%	1-01%	6-01%
Rear Plate Flash Inappropriate	0-00%	1-01%	0-00%	2-03%	0-00%	0-00%	1-01%	0-00%	4-01%
Police Rejects Driver Unidentifiable images poor	0-00%	0-00%	3-06%	4-07%	2-05%	2-01%	6-04%	20-12%	37-05%
Incorrect Speed	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-04%	0-00%	6-01%
No Video	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	2-01%	3-00%
Total	1-02%	7-10%	3-06%	11-18%	3-08%	4-03%	29-19%	35-21%	93-12%
Approved Violations	58-98%	66-90%	46-94%	49-82%	37-92%	145-97%	127-81%	134-79%	662-88%
Total Notices Printed	58-98%	66-90%	46-94%	49-82%	37-92%	145-97%	127-81%	134-79%	662-88%

Generated By: PROMO
Generated On: 5/13/2013 2:11:16 PM

Customer Management Report (Oceanside) All Detection Types

01-Jun-2011 to 30-Jun-2011

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCOC-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Total Processed Incidents	68	117	127	96	63	235	287	313	1306
Less Uncontrollable Factors									
Obstruction	0	4	34	7	3	15	19	23	105
Driver Obstruction/Duckers	0	0	2	0	0	2	0	0	4
Motor Cycle Helmet	2	2	10	9	2	0	12	6	43
Plate Obstruction	0	0	1	0	0	0	0	1	2
Signal Obstruction	1	0	3	0	1	0	9	0	14
Vehicle Obstruction	1	1	0	1	1	1	3	0	8
Emergency Vehicle Responding	0	1	1	2	0	2	2	3	11
Face Obstruction	0	2	1	1	0	3	2	1	10
Incorrect/Incomplete DMV	0	2	2	1	0	1	8	5	19
Police Discretion	7	6	10	7	6	81	15	3	135
Safe Turn On Red	0	0	0	1	1	1	2	11	16
Sun Glare	0	2	0	0	0	1	5	4	12
Policy/Weather	2	28	12	7	19	16	49	101	234
Extended Vehicle	0	1	0	0	0	0	0	0	1
Sun Glare	0	0	0	0	0	0	3	1	4
Registration	6	1	5	2	0	11	4	7	36
Can Not Identify State	19	50	81	38	33	134	133	166	654
Issues	49	67	46	58	30	101	154	147	652
Out of Country Plate	0	0	0	0	0	0	0	0	0
Paper Plates	49	67	46	58	30	101	154	147	652
Sub Total Violations									
Less in Progress	0	0	0	0	0	0	0	0	0
Available For Prosecution									
Less Rejects									
Camera	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Databar Unreadable/Incorrect	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-01%	2-00%
Malfunction									
Face Camera Flash									

Generated By: PROMO

Generated On: 5/13/2013 2:12:40 PM

Customer Management Report (Oceanside) All Detection Types

01-Jun-2011 to 30-Jun-2011

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCCO-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-02%	0-00%	3-00%
Face Not in Frame	1-02%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	2-00%
Image Missing	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-01%	0-00%	2-00%
Misc Camera Issue	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-01%	0-00%	2-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-01%	2-00%
Rear Plate Camera Blurry	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	2-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Police Rejects	0-00%	3-04%	3-07%	1-02%	1-03%	1-01%	2-01%	26-18%	37-06%
Incorrect Speed	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	11-07%	0-00%	12-02%
Red-light not visible in	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	1-02%	6-09%	4-09%	4-07%	1-03%	6-06%	20-13%	28-19%	70-11%
Approved Violations	48-98%	61-91%	42-91%	54-93%	29-97%	95-94%	134-87%	119-81%	582-89%
Total Notices Printed	48-98%	61-91%	42-91%	54-93%	29-97%	95-94%	134-87%	119-81%	582-89%

Generated By: PROMO
Generated On: 5/13/2013 2:12:40 PM

Customer Management Report (Oceanside) All Detection Types

01-Jul-2011 to 31-Jul-2011

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCOC-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Total Processed Incidents	96	128	173	78	48	265	264	315	1367
Less Uncontrollable Factors									
Obstruction	4	10	46	2	0	10	16	21	109
Driver Obstruction/Duckers	0	0	0	1	0	4	2	1	8
Motor Cycle Helmet	1	8	13	6	2	2	10	5	47
Plate Obstruction	1	0	5	3	0	1	4	0	14
Vehicle Obstruction	0	2	2	0	0	2	1	0	7
Emergency Vehicle Responding	1	1	5	1	0	0	2	5	15
Face Obstruction	0	1	1	1	0	2	0	6	11
Incorrect/Incomplete DMV	0	3	1	0	0	5	3	7	19
Police Discretion	17	5	18	5	5	114	16	5	185
Safe Turn On Red	1	2	2	2	1	6	4	22	40
Sun Glare	0	3	0	0	0	0	3	2	8
Policy/Weather	5	27	22	6	5	19	63	104	251
Extended Vehicle	0	0	0	0	0	0	1	0	1
Weather/Nature	0	0	0	0	0	0	1	0	1
Registration	0	0	0	0	0	0	1	1	2
Can Not Identify State	2	4	1	2	2	6	2	5	24
Paper Plates	0	0	0	2	0	0	0	0	2
Wrong or No DMV	32	66	116	31	15	171	128	184	743
Sub Total Violations	64	62	57	47	33	94	136	131	624
Less in Progress	0	0	0	0	0	0	0	0	0
Available For Prosecution	64	62	57	47	33	94	136	131	624
Less Rejects									
Camera	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Databar Unreadable/Incorrect	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Malfunction	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Flash									

Generated By: PROMO

Generated On: 5/13/2013 2:20:00 PM

Customer Management Report (Oceanside) All Detection Types

01-Jul-2011 to 31-Jul-2011

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCOC-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
Face Not in Frame	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	4-03%	0-00%	5-01%
Image Missing	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	13-39%	0-00%	11-08%	0-00%	24-04%
Plate Burn Out	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-01%	0-00%	2-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	3-05%	1-02%	0-00%	0-00%	0-00%	1-01%	0-00%	5-01%
Rear Plate Flash Inappropriate	0-00%	1-02%	1-02%	1-02%	0-00%	0-00%	0-00%	0-00%	3-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	4-12%	0-00%	0-00%	0-00%	4-01%
Scene Image Flash Inappropriate	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-01%	2-00%
Driver Unidentifiable images poor	1-02%	1-02%	3-05%	3-06%	1-03%	3-03%	1-01%	34-26%	47-08%
Incorrect Speed	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-05%	0-00%	7-01%
Total	1-02%	6-10%	6-11%	7-15%	19-58%	3-03%	28-21%	35-27%	105-17%
Approved Violations	63-98%	56-90%	51-89%	40-85%	14-42%	91-97%	108-79%	96-73%	519-83%
Total Notices Printed	63-98%	56-90%	51-89%	40-85%	14-42%	91-97%	108-79%	96-73%	519-83%

Generated By: PROMO
 Generated On: 5/13/2013 2:20:00 PM

Customer Management Report (Oceanside) All Detection Types

01-Oct-2012 to 31-Oct-2012

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Total Processed Incidents	93	103	189	90	165	185	291	1185
Less Uncontrollable Factors								
Obstruction Driver Obstruction/Duckers	3	9	32	8	4	6	10	75
Motor Cycle Helmet	0	0	0	0	2	1	0	3
Plate Obstruction	0	0	10	7	1	6	6	31
Vehicle Obstruction	4	0	15	5	0	1	2	27
Police Rejects	1	2	0	0	1	1	0	5
Emergency Vehicle Responding	0	3	7	3	0	6	6	28
Face Obstruction	2	0	1	2	1	4	5	17
Gender Mismatch	18	7	21	11	7	16	37	140
Incorrect/Incomplete DMV	0	0	1	1	2	7	14	26
Police Discretion	14	7	11	1	12	13	8	136
Safe Turn On Red	0	0	4	0	0	6	0	10
Sun Glare	0	4	0	0	0	0	0	10
Policy/Weather	0	4	0	0	1	3	4	12
Extended Vehicle	2	18	10	1	7	19	5	66
Sun Glare	1	1	0	0	0	1	0	3
Weather/Nature	0	0	0	0	1	0	0	1
Yellow with Red Light	0	0	0	0	1	0	0	1
Registration Out of Country Plate	0	0	1	0	0	0	1	2
Issues	1	2	3	1	2	6	6	22
Paper Plates	46	53	116	40	116	96	104	604
Sub Total Violations	47	50	73	50	49	89	187	581
Less in Progress	0	0	0	0	0	0	0	0
Available For Prosecution	47	50	73	50	49	89	187	581
Less Rejects								
Camera Face Not in Frame	0-00%	0-00%	0-00%	3-06%	0-00%	1-01%	0-00%	4-01%

Generated By: **PROMO**

Generated On: 5/13/2013 2:15:56 PM

Customer Management Report (Oceanside) All Detection Types

01-Oct-2012 to 31-Oct-2012

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Image Missing	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	2-04%	0-00%	1-01%	0-00%	3-01%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-00%
Police Rejects	3-06%	10-20%	32-44%	7-14%	13-27%	22-25%	29-16%	127-22%
Driver Unidentifiable images poor	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Unclear Scene Image	3-06%	10-20%	34-47%	14-28%	13-27%	24-27%	30-16%	139-24%
Approved Violations	44-94%	40-80%	39-53%	36-72%	36-73%	65-73%	157-84%	442-76%
Total Notices Printed	44-94%	40-80%	39-53%	36-72%	36-73%	65-73%	157-84%	442-76%

Generated By: PROMO
Generated On: 5/13/2013 2:15:56 PM

Customer Management Report (Oceanside) All Detection Types

01-Nov-2012 to 30-Nov-2012

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCOC-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Total Processed Incidents	46	120	150	90	69	168	179	281	1103
Less Uncontrollable Factors									
Obstruction	1	15	25	7	3	1	8	13	73
Driver Obstruction/Duckers									
Motor Cycle Helmet	0	0	2	2	0	1	0	2	7
Plate Obstruction	0	4	10	6	1	2	5	3	31
Vehicle Obstruction	0	1	11	1	0	0	3	1	17
Police Rejects	0	3	4	0	2	0	2	0	11
Emergency Vehicle Responding									
Face Obstruction	0	5	7	4	2	4	2	11	35
Funeral Procession/Police	0	1	0	0	0	0	0	0	1
Gender Mismatch	1	0	0	0	0	1	2	3	7
Incorrect/Incomplete DMV	5	13	21	12	12	19	25	62	169
Police Discretion	0	2	1	0	2	3	7	19	34
Safe Turn On Red	9	10	18	8	12	67	13	4	141
Sun Glare	0	0	0	0	0	0	5	0	5
Policy/Weather									
Extended Vehicle	0	0	0	1	1	1	2	6	11
Sun Glare	1	6	8	5	0	7	5	4	36
Weather/Nature	1	1	1	1	0	2	1	0	7
Registration Issues									
Out of Country Plate	0	0	0	0	0	0	0	1	1
Paper Plates	0	2	2	2	3	6	8	4	27
Wrong or No DMV	0	0	0	2	0	0	0	0	2
Total	18	63	110	51	38	114	88	133	615
Sub Total Violations	28	57	40	39	31	54	91	148	488
Less in Progress	0	0	0	0	0	0	0	0	0
Available For Prosecution	28	57	40	39	31	54	91	148	488
Less Rejects									

Generated By: PROMO

Generated On: 5/13/2013 2:16:43 PM

Customer Management Report (Oceanside) All Detection Types

01-Nov-2012 to 30-Nov-2012

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	2-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Plate Burn Out	0-00%	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	3-01%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	1-01%	3-01%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	2-05%	0-00%	1-01%	0-00%	3-01%
Police Rejects	5-18%	12-21%	13-32%	8-21%	19-35%	11-12%	10-07%	80-16%
Driver Unidentifiable images poor	5-18%	12-21%	13-32%	12-31%	19-35%	14-15%	12-08%	90-18%
Total	23-82%	45-79%	27-68%	27-69%	35-65%	77-85%	136-92%	398-82%
Approved Violations	23-82%	45-79%	27-68%	27-69%	35-65%	77-85%	136-92%	398-82%
Total Notices Printed	23-82%	45-79%	27-68%	27-69%	35-65%	77-85%	136-92%	398-82%

Generated By: PROMO
 Generated On: 5/13/2013 2:16:43 PM

Customer Management Report (Oceanside) All Detection Types

01-Dec-2012 to 31-Dec-2012

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCOC-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Total Processed Incidents	71	106	152	79	62	159	206	324	1159
Less Uncontrollable Factors									
Obstruction	6	8	30	3	2	3	10	10	72
Driver Obstruction/Duckers									
Motor Cycle Helmet	0	0	1	2	1	1	4	1	10
Plate Obstruction	1	2	9	8	0	0	7	11	38
Signal Obstruction	0	0	0	1	0	0	0	0	1
Vehicle Obstruction	0	1	11	4	0	1	5	6	28
Police Rejects									
Emergency Vehicle Responding	0	5	1	0	2	0	2	0	10
Face Obstruction	0	3	8	3	0	2	7	7	30
Gender Mismatch	0	0	0	0	0	1	3	1	5
Incorrect/Incomplete DMV	9	9	19	10	7	11	16	39	120
Police Discretion	1	2	0	0	0	2	8	14	27
Safe Turn On Red	10	9	15	5	9	62	15	6	131
Sun Glare	0	0	1	0	0	0	4	0	5
Yielding to an Emergency	0	1	0	0	0	0	0	0	1
Policy/Weather									
Extended Vehicle	0	1	0	0	0	0	5	4	10
Sun Glare	2	10	8	5	0	4	8	4	41
Weather/Nature	0	0	0	0	0	2	1	1	4
Registration Issues									
Out of Country Plate	0	1	0	0	0	0	0	0	1
Paper Plates	1	2	3	1	2	2	1	6	18
Wrong or No DMV	1	0	0	0	0	0	1	0	2
Total	31	54	106	42	23	91	97	110	554
Sub Total Violations	40	52	46	37	39	68	109	214	605
Less in Progress	0	0	0	0	0	0	0	0	0
Available For Prosecution	40	52	46	37	39	68	109	214	605

Generated By: PROMO

Generated On: 5/13/2013 2:22:18 PM

Customer Management Report (Oceanside) All Detection Types

01-Dec-2012 to 31-Dec-2012

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCOC-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Less Rejects									
Camera Malfunction	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	1-03%	1-01%	0-00%	0-00%	2-00%
Plate Burn Out	0-00%	0-00%	1-02%	1-03%	0-00%	0-00%	0-00%	0-00%	2-00%
Plate Not in Frame	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%	2-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	2-05%	0-00%	0-00%	4-04%	0-00%	6-01%
Rear Plate Flash Inappropriate	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%	2-00%
Rear Plate No Flash	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	11-28%	7-13%	6-13%	1-03%	3-08%	8-12%	11-10%	26-12%	73-12%
Total	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Approved Violations	11-28%	8-15%	9-20%	5-14%	5-13%	10-15%	16-15%	28-13%	92-15%
Total Notices Printed	29-72%	44-85%	37-80%	32-86%	34-87%	58-85%	93-85%	186-87%	513-85%
	29-72%	44-85%	37-80%	32-86%	34-87%	58-85%	93-85%	186-87%	513-85%

Generated By: PROMO
Generated On: 5/13/2013 2:22:18 PM

Customer Management Report (Oceanside) All Detection Types

01-Jan-2013 to 31-Jan-2013

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL	
Total Processed Incidents	60	99	144	113	55	149	196	218	1034
Less Uncontrollable Factors									
Obstruction Driver Obstruction/Ducketers	3	5	31	5	1	8	16	15	84
Motor Cycle Helmet	0	1	0	0	0	0	0	1	2
Plate Obstruction	0	5	16	7	1	3	7	12	51
Signal Obstruction	0	0	1	1	0	0	1	0	3
Vehicle Obstruction	0	1	3	2	0	0	2	0	8
Police Rejects									
Emergency Vehicle Responding	1	5	1	2	0	0	0	0	9
Face Obstruction	2	0	7	4	0	0	3	5	21
Incorrect/Incomplete DMV	5	9	10	6	8	7	12	30	87
Police Discretion	0	4	2	0	2	1	6	12	27
Safe Turn On Red	9	2	16	17	5	58	17	0	124
Sun Glare	0	0	1	0	0	0	9	0	10
Yielding to an Emergency	0	1	0	0	0	0	0	0	1
Policy/Weather Extended Vehicle	0	0	0	0	0	1	3	3	7
Sun Glare	1	3	6	2	0	6	4	3	25
Weather/Nature	0	1	1	0	0	1	0	0	3
Registration Out of Country Plate	0	0	0	0	0	1	0	0	1
Issues Paper Plates	3	2	5	0	2	7	5	0	24
Wrong or No DMV	0	0	1	0	0	0	0	1	2
Total	24	39	101	46	19	93	85	82	489
Sub Total Violations	36	60	43	67	36	56	111	136	545
Less in Progress	0	0	0	0	0	0	0	0	0
Available For Prosecution	36	60	43	67	36	56	111	136	545
Less Rejects									

Generated By: PROMMO

Generated On: 5/13/2013 2:23:56 PM

Customer Management Report (Oceanside) All Detection Types

01-Jan-2013 to 31-Jan-2013

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCOC-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Face Not in Frame	1-03%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Misc Camera Issue	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-01%	4-03%	6-01%
Plate Burn Out	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-01%	1-01%	3-01%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police	8-22%	9-15%	11-26%	8-12%	5-14%	8-14%	7-06%	10-07%	66-12%
Driver Unidentifiable images poor	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rejects	9-25%	10-17%	13-30%	10-15%	5-14%	8-14%	11-10%	15-11%	81-15%
Red-light not visible in	27-75%	50-83%	30-70%	57-85%	31-86%	48-86%	100-90%	121-89%	464-85%
Total	27-75%	50-83%	30-70%	57-85%	31-86%	48-86%	100-90%	121-89%	464-85%
Approved Violations	27-75%	50-83%	30-70%	57-85%	31-86%	48-86%	100-90%	121-89%	464-85%
Total Notices Printed	27-75%	50-83%	30-70%	57-85%	31-86%	48-86%	100-90%	121-89%	464-85%

Generated By: PROMMO
Generated On: 5/13/2013 2:23:56 PM

Customer Management Report (Oceanside) All Detection Types

01-Feb-2013 to 28-Feb-2013

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCCO-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Total Processed Incidents	73	101	145	78	61	151	204	248	1061
Less Uncontrollable Factors									
Obstruction Driver Obstruction/Duckers	1	5	18	4	3	5	11	10	57
Motor Cycle Helmet	0	0	1	0	0	5	0	1	7
Plate Obstruction	1	2	16	2	1	1	12	3	38
Signal Obstruction	0	0	0	0	0	0	1	0	1
Vehicle Obstruction	2	2	10	2	1	0	3	2	22
Police Citation Issued manually	0	0	1	0	0	0	0	0	1
Police Rejects	1	2	1	1	1	1	1	0	8
Emergency Vehicle Responding	0	1	2	3	1	2	0	5	14
Face Obstruction	0	1	0	1	0	0	0	0	2
Gender Mismatch	5	3	8	1	1	4	8	16	46
Incorrect/Incomplete DMV	0	0	3	0	0	0	6	14	23
Police Discretion	15	8	15	12	8	53	13	2	126
Safe Turn On Red	0	1	4	0	0	1	4	0	10
Sun Glare	1	3	0	0	0	0	0	7	11
Policy/Weather Extended Vehicle	1	8	9	2	0	5	14	3	42
Sun Glare	0	0	1	0	0	1	1	0	3
Weather/Nature	1	0	0	0	0	0	0	0	1
Out of Country Plate	4	1	5	3	3	6	7	7	36
Paper Plates	0	1	0	0	0	1	0	1	3
Wrong or No DMV	32	38	94	31	19	85	81	71	451
Sub Total Violations	41	63	51	47	42	66	123	177	610
Less in Progress	0	0	0	0	0	0	0	0	0
Available For Prosecution	41	63	51	47	42	66	123	177	610

Generated By: PROMO

Generated On: 5/13/2013 2:24:31 PM

Customer Management Report (Oceanside) All Detection Types

01-Feb-2013 to 28-Feb-2013

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCOC-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Less Rejects									
Camera Face Not in Frame	2-05%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	3-00%
Camera Malfunction	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Image Missing	0-00%	2-03%	1-02%	1-02%	0-00%	0-00%	0-00%	0-00%	4-01%
Rear Plate Camera Blurry	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate No Flash	6-15%	6-10%	8-16%	4-09%	4-10%	7-11%	9-07%	18-10%	62-10%
Driver Unidentifiable images poor	8-20%	10-16%	9-18%	5-11%	4-10%	8-12%	9-07%	18-10%	71-12%
Police Rejects									
Total	33-80%	53-84%	42-82%	42-89%	38-90%	58-88%	114-93%	159-90%	539-88%
Approved Violations									
Total Notices Printed	33-80%	53-84%	42-82%	42-89%	38-90%	58-88%	114-93%	159-90%	539-88%

Customer Management Report (Oceanside) All Detection Types

01-Mar-2013 to 31-Mar-2013

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCCO-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Total Processed Incidents	59	87	175	103	42	184	283	322	1255
Less Uncontrollable Factors									
Obstruction	1	1	22	7	0	4	6	6	47
Driver Obstruction/Duckers	0	0	3	1	0	2	0	2	8
Motor Cycle Helmet	0	0	19	9	2	0	6	7	43
Plate Obstruction	0	1	9	0	0	0	3	2	15
Vehicle Obstruction	0	8	2	1	0	1	1	2	15
Emergency Vehicle Responding	0	3	6	1	0	1	5	4	20
Face Obstruction	0	1	0	0	0	0	0	0	1
Gender Mismatch	6	1	7	4	1	6	9	26	60
Incorrect/Incomplete DMV	0	2	3	1	2	1	7	9	25
Police Discretion	9	2	11	7	5	82	11	5	132
Safe Turn On Red	0	0	1	0	0	0	5	0	6
Sun Glare	0	3	0	0	0	1	2	5	11
Policy/Weather	0	11	20	3	2	7	47	6	96
Extended Vehicle	1	1	2	1	0	6	4	0	15
Weather/Nature	0	0	0	0	0	0	1	0	1
Yellow with Red Light	1	0	0	1	0	0	1	0	3
Registration	2	2	10	7	1	6	7	8	43
Out of Country Plate	20	36	115	43	13	117	115	82	541
Issues	39	51	60	60	29	67	168	240	714
Paper Plates	0	0	0	0	0	0	0	0	0
Sub Total Violations	39	51	60	60	29	67	168	240	714
Less in Progress	0	0	0	0	0	0	0	0	0
Available For Prosecution	39	51	60	60	29	67	168	240	714
Less Rejects									
Camera	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Not in Frame									
Generated By:	PROMO								
Generated On:	5/13/2013 2:25:06 PM								

Customer Management Report (Oceanside) All Detection Types

01-Mar-2013 to 31-Mar-2013

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCCO-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Image Missing	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Burn Out	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	2-00%
Driver Unidentifiable images poor	3-08%	6-12%	17-28%	13-22%	5-17%	6-09%	8-05%	18-08%	76-11%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	2-00%
Total	4-10%	8-16%	17-28%	15-25%	5-17%	10-15%	11-07%	18-08%	88-12%
Approved Violations	35-90%	43-84%	43-72%	45-75%	24-83%	57-85%	157-93%	222-92%	626-88%
Total Notices Printed	35-90%	43-84%	43-72%	45-75%	24-83%	57-85%	157-93%	222-92%	626-88%

Generated By: PROMO
Generated On: 5/13/2013 2:25:06 PM

Customer Management Report (Oceanside) All Detection Types

01-Apr-2013 to 30-Apr-2013

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCCO-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Total Processed Incidents	66	106	152	91	73	183	270	250	1191
Less Uncontrollable Factors									
Obstruction Driver Obstruction/Duckers	1	1	27	1	2	7	7	7	53
Motor Cycle Helmet	0	0	3	0	2	1	2	1	9
Plate Obstruction	1	2	9	5	3	3	11	4	38
Vehicle Obstruction	2	1	13	2	1	1	2	3	25
Police Rejects	0	3	1	2	1	0	0	0	7
Emergency Vehicle Responding	0	0	6	4	4	2	5	6	27
Face Obstruction	0	1	0	0	0	0	0	1	2
Gender Mismatch	11	5	7	4	4	9	20	21	81
Incorrect/Incomplete DMV	1	7	2	0	0	1	2	13	26
Police Discretion	13	5	12	9	8	97	15	9	168
Safe Turn On Red	0	3	2	0	0	3	11	6	25
Sun Glare	0	0	0	1	0	0	0	0	1
Yielding to an Emergency	0	1	0	0	0	0	3	5	9
Policy/Weather Extended Vehicle	1	12	23	2	3	9	48	12	110
Sun Glare	1	0	0	1	1	0	1	0	4
Registration Out of Country Plate	1	2	5	4	3	3	16	7	41
Paper Plates	1	0	1	0	0	0	0	0	2
Wrong or No DMV	33	43	111	35	32	136	143	95	628
Total	33	63	41	56	41	47	127	155	563
Sub Total Violations	0	0	0	0	0	0	0	0	0
Less in Progress	33	63	41	56	41	47	127	155	563
Available For Prosecution									
Less Rejects	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Camera Face Not in Frame									
Generated By: PROMO									
Generated On: 5/13/2013 2:26:02 PM									

Customer Management Report (Oceanside) All Detection Types

01-Apr-2013 to 30-Apr-2013

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Misc Camera Issue	4-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Plate Burn Out	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-01%	2-00%
Rear Plate Camera Blurry	0-00%	1-02%	0-00%	1-02%	0-00%	2-02%	1-01%	5-01%
Scene Image Flash Inappropriate	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	5-15%	12-19%	11-27%	13-23%	12-26%	12-09%	37-24%	113-20%
Red-light not visible in	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	9-27%	16-25%	11-27%	15-27%	12-26%	14-11%	39-25%	127-23%
Approved Violations	24-73%	47-75%	30-73%	41-73%	35-74%	113-89%	116-75%	436-77%
Total Notices Printed	24-73%	47-75%	30-73%	41-73%	35-74%	113-89%	116-75%	436-77%

Customer Management Report (Oceanside) All Detection Types

01-May-2013 to 31-May-2013

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCOC-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Total Processed Incidents	27	47	92	52	34	115	123	133	623
Less Uncontrollable Factors									
Obstruction Driver Obstruction/Duckers	0	2	7	0	0	0	3	4	16
Motor Cycle Helmet	0	0	0	0	0	1	0	1	2
Plate Obstruction	0	1	5	2	0	0	4	2	14
Vehicle Obstruction	0	0	2	3	0	0	1	0	6
Police Rejects									
Emergency Vehicle Responding	0	0	1	0	0	0	0	0	1
Face Obstruction	1	0	2	1	1	0	2	1	8
Incorrect/Incomplete DMV	1	1	2	3	3	1	6	4	21
Police Discretion	0	1	0	0	0	0	1	5	7
Safe Turn On Red	1	0	2	3	2	24	7	2	41
Sun Glare	0	0	1	0	1	1	1	1	5
Policy/Weather									
Extended Vehicle	0	0	0	0	0	0	1	1	2
Other	1	4	11	1	2	4	21	4	48
Registration Issues									
Paper Plates	1	1	1	4	0	1	3	2	13
Total	5	10	34	17	9	32	50	27	184
Sub Total Violations	22	37	58	35	25	83	73	106	439
Less in Progress	11	24	42	20	11	66	32	41	247
Available For Prosecution	11	13	16	15	14	17	41	65	192
Less Rejects									
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-01%
Face Camera Focus Blurry	1-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-01%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	1-02%	0-00%	2-01%

Generated By: PROMMO

Generated On: 5/13/2013 2:27:40 PM

Customer Management Report (Oceanside) All Detection Types

01-May-2013 to 31-May-2013

Operator Id: %

	OSC-COOC-01	OSC-COOG-01	OSC-MICA-01	OSC-MICA-03	OSC-OCCO-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Police Rejects	1-09%	3-23%	5-31%	5-33%	1-07%	4-24%	2-06%	14-22%	35-18%
Process Issues	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%
Total	2-18%	3-23%	6-38%	6-40%	1-07%	4-24%	3-07%	16-25%	41-21%
Approved Violations	9-82%	10-77%	10-62%	9-60%	13-93%	13-76%	38-93%	49-75%	151-79%
Total Notices Printed	5-45%	5-38%	9-56%	6-40%	5-36%	11-65%	28-68%	30-46%	99-52%