

Recd 11-5-12

Customer Management Report (Oceanside) All Detection Types

01-Feb-2011 to 28-Feb-2011

Operator Id: %

	OSC-COOG-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Total Processed Incidents	0	0	0	0	0
Less Uncontrollable Factors					
Obstruction Driver Obstruction/Duckers	0	0	0	0	0
Motor Cycle Helmet	0	0	0	0	0
Plate Obstruction	0	0	0	0	0
Vehicle Obstruction	0	0	0	0	0
Police Rejects					
Emergency Vehicle Responding	0	0	0	0	0
Face Obstruction	0	0	0	0	0
Incorrect/Incomplete DMV	0	0	0	0	0
Police Discretion	0	0	0	0	0
Safe Turn On Red	0	0	0	0	0
Policy/Weather					
Extended Vehicle	0	0	0	0	0
Sun Glare	0	0	0	0	0
Weather/Nature	0	0	0	0	0
Registration Issues					
Can Not Identify State	0	0	0	0	0
Paper Plates	0	0	0	0	0
Total	0	0	0	0	0
Sub Total Violations	0	0	0	0	0
Less in Progress	0	0	0	0	0
Available For Prosecution	0	0	0	0	0
Less Rejects					
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%

Generated By: PROMO
Generated On: 10/23/2012 8:26:03 AM

Customer Management Report (Oceanside) All Detection Types

01-Feb-2011 to 28-Feb-2011

Operator Id: %

	OSC-COOG-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%
Police Rejects	0-00%	0-00%	0-00%	0-00%	0-00%
Total	0-00%	0-00%	0-00%	0-00%	0-00%
Approved Violations	0-00%	0-00%	0-00%	0-00%	0-00%
Total Notices Printed	0-00%	0-00%	0-00%	0-00%	0-00%

Generated By: PROMO
Generated On: 10/23/2012 8:26:03 AM

© Redflex Traffic Systems, Inc.

Customer Management Report (Oceanside) All Detection Types

01-Mar-2011 to 31-Mar-2011

Operator Id: %

	OSC-COOG-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Total Processed Incidents	0	3	0	0	3
Less Uncontrollable Factors					
Obstruction Driver Obstruction/Duckers	0	0	0	0	0
Motor Cycle Helmet	0	0	0	0	0
Plate Obstruction	0	0	0	0	0
Vehicle Obstruction	0	0	0	0	0
Police Rejects					
Emergency Vehicle Responding	0	1	0	0	1
Face Obstruction	0	0	0	0	0
Incorrect/Incomplete DMV	0	0	0	0	0
Police Discretion	0	0	0	0	0
Safe Turn On Red	0	1	0	0	1
Policy/Weather					
Sun Glare	0	0	0	0	0
Weather/Nature	0	0	0	0	0
Registration Issues					
Can Not Identify State	0	0	0	0	0
Out of Country Plate	0	0	0	0	0
Paper Plates	0	2	0	0	2
Total	0	2	0	0	2
Sub Total Violations	0	1	0	0	1
Less in Progress	0	0	0	0	0
Available For Prosecution	0	1	0	0	1
Less Rejects					
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%

Generated By: PROMMO
Generated On: 10/23/2012 8:28:55 AM

Customer Management Report (Oceanside) All Detection Types

01-Mar-2011 to 31-Mar-2011

Operator Id: %

	OSC-COOG-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%
No Video	0-00%	0-00%	0-00%	0-00%	0-00%
Police Rejects	0-00%	0-00%	0-00%	0-00%	0-00%
Total	0-00%	0-00%	0-00%	0-00%	0-00%
Approved Violations	0-00%	1-100%	0-00%	0-00%	1-100%
Total Notices Printed	0-00%	1-100%	0-00%	0-00%	1-100%

Generated By: PROMO
Generated On: 10/23/2012 8:26:55 AM

Customer Management Report (Oceanside) All Detection Types

01-May-2011 to 31-May-2011

Operator Id: %

	OSC-COOG-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Total Processed Incidents	144	265	288	372	1069
Less Uncontrollable Factors					
Obstruction	20	10	13	18	61
Driver Obstruction/Duckers	1	2	0	1	4
Motor Cycle Helmet	2	2	12	19	35
Plate Obstruction	0	0	12	0	12
Signal Obstruction	0	1	8	0	9
Vehicle Obstruction	3	1	1	0	5
Emergency Vehicle Responding	2	3	2	1	8
Face Obstruction	1	4	3	1	9
Incorrect/Incomplete DMV	0	0	0	68	68
Invalid Offense	2	3	5	8	18
Police Discretion	4	66	12	2	84
Safe Turn On Red	0	1	1	6	8
Extended Vehicle	28	14	56	65	163
Weather	0	1	0	0	1
Weather/Nature	2	0	0	4	6
Can Not Identify State	0	1	0	1	2
Out of Country Plate	3	7	4	7	21
Paper Plates	2	0	1	0	3
Wrong or No DMV	70	116	130	201	517
Sub Total Violations	74	149	158	171	552
Less in Progress	0	0	0	0	0
Available For Prosecution	74	149	158	171	552
Less Rejects					

Generated By: PROMO
Generated On: 10/23/2012 8:28:12 AM

Customer Management Report (Oceanside) All Detection Types

01-May-2011 to 31-May-2011 Operator Id: %

	OSC-COOG-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Camera Malfunction	1-01%	1-01%	4-03%	4-02%	10-02%
Face Camera Flash	0-00%	0-00%	0-00%	6-04%	6-01%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	1-01%	1-00%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%
Face Not in Frame	0-00%	1-01%	8-05%	0-00%	9-02%
Misc Camera Issue	1-01%	0-00%	0-00%	1-01%	2-00%
Plate Burn Out	0-00%	0-00%	2-01%	0-00%	2-00%
Plate Not in Frame	4-05%	0-00%	0-00%	1-01%	5-01%
Rear Plate Camera Blurry	1-01%	0-00%	1-01%	0-00%	2-00%
Rear Plate Flash Inappropriate	0-00%	2-01%	6-04%	20-12%	28-05%
Police Rejects	0-00%	0-00%	6-04%	0-00%	6-01%
Driver Unidentifiable Images poor	0-00%	0-00%	1-01%	0-00%	1-00%
Incorrect Speed	0-00%	0-00%	1-01%	2-01%	3-01%
No Video	1-01%	0-00%	2-01%	2-01%	5-01%
Red-light not visible in	8-11%	4-03%	31-20%	37-22%	80-14%
Sun Glare	66-89%	145-97%	127-80%	134-78%	472-86%
Total	66-89%	145-97%	127-80%	134-78%	472-86%
Approved Violations	66-89%	145-97%	127-80%	134-78%	472-86%
Total Notices Printed	66-89%	145-97%	127-80%	134-78%	472-86%

Customer Management Report (Oceanside) All Detection Types

01-Jun-2011 to 30-Jun-2011 Operator Id: %

	OSC-COOG-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Total Processed Incidents	117	236	287	313	952
Less Uncontrollable Factors					
Obstruction	4	15	19	23	61
Driver Obstruction/Duckers	0	2	0	0	2
Motor Cycle Helmet	2	0	12	6	20
Plate Obstruction	0	0	0	1	1
Signal Obstruction	0	0	9	0	9
Vehicle Obstruction	1	1	3	0	5
Emergency Vehicle Responding	1	2	2	3	8
Face Obstruction	2	3	2	1	8
Incorrect/Incomplete DMV	2	1	8	5	16
Police Discretion	6	81	15	3	105
Safe Turn On Red	2	1	5	4	12
Extended Vehicle	28	16	49	101	194
Sun Glare	1	0	0	0	1
Can Not Identify State	0	0	3	1	4
Out of Country Plate	1	11	4	7	23
Paper Plates	50	133	131	155	469
Sub Total Violations	67	102	156	158	483
Less in Progress	0	0	0	0	0
Available For Prosecution	67	102	156	158	483
Less Rejects					
Camera	0-00%	0-00%	1-01%	0-00%	1-00%
Databar Unreadable/Incorrect	0-00%	1-01%	0-00%	1-01%	2-00%
Malfunction	0-00%	0-00%	3-02%	0-00%	3-01%
Face Camera Flash					
Face Camera Focus Blurry					

Generated By: PROMO
 Generated On: 10/23/2012 8:28:53 AM

Customer Management Report (Oceanside) All Detection Types

01-Jun-2011 to 30-Jun-2011

Operator Id: %

	OSC-COOG-01	OSC-OGCO-01	OSC-VIEC-01	OSC-VIEC-03	TOTAL
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%
Image Missing	0-00%	0-00%	1-01%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	1-01%	0-00%	1-00%
Plate Burn Out	0-00%	1-01%	0-00%	1-01%	2-00%
Rear Plate Camera Blurry	2-03%	0-00%	0-00%	0-00%	2-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%
Scene Image Flash Inappropriate	0-00%	2-02%	0-00%	0-00%	2-00%
Scene Image No Flash	0-00%	0-00%	1-01%	0-00%	1-00%
Police Rejects	3-04%	1-01%	2-01%	26-16%	32-07%
Driver Unidentifiable Images poor	0-00%	1-01%	11-07%	0-00%	12-02%
Incorrect Speed	1-01%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	0-00%	1-01%	2-01%	11-07%	14-03%
Sun Glare	6-09%	7-07%	22-14%	33-25%	74-15%
Total	61-91%	95-93%	134-86%	119-75%	409-85%
Approved Violations	61-91%	95-93%	134-86%	119-75%	409-85%
Total Notices Printed	61-91%	95-93%	134-86%	119-75%	409-85%