

Customer Management Report (San Leandro) All Detection Types

01-Jan-2012 to 31-Dec-2012

Operator Id: %

		SLE-14DA-01	SLE-14FA-01	SLE-HAWA-01	SLE-HAWA-03	SLE-MATE-01	TOTAL
Total Processed Incidents		968	1874	3187	8381	6016	20426
Less Uncontrollable Factors							
Obstruction	Driver Obstruction/Duckers	101	60	239	1002	262	1664
	Motor Cycle Helmet	2	3	0	5	12	22
	Plate Obstruction	27	34	21	26	124	232
	Signal Obstruction	1	0	0	0	0	1
	Vehicle Obstruction	31	12	28	151	147	369
Police Rejects	Emergency Vehicle Responding	62	59	30	22	39	212
	Funeral Procession/Police	1	1	0	0	0	2
	Incorrect Plate on Vehicle	0	1	0	0	0	1
	Incorrect/Incomplete DMV	2	9	21	33	42	107
	Multiple vehicles in frame	0	0	0	0	2	2
	On or Passed the Stop Bar (PD).	1	79	338	1202	89	1709
	Plate Obstruction (PD)	1	0	0	0	0	1
	Police Discretion	139	130	19	39	506	833
	Safe Turn On Red	76	275	753	2188	594	3886
Sun Glare	0	1	16	21	1	39	
Policy/Weather	Extended Vehicle	9	4	1	28	136	178
	Sun Glare	156	242	550	956	489	2393
	Weather/Nature	3	10	23	9	17	62
	Yellow with Red Light	0	0	2	0	0	2
Registration Issues	Can Not Identify State	0	0	0	1	1	2
	Gender Match	0	0	0	1	0	1
	Out of Country Plate	0	1	2	1	7	11
	Paper Plates	24	79	80	215	212	610

Generated By: SWONG

Generated On: 1/15/2013 5:47:24 PM

Customer Management Report (San Leandro) All Detection Types

01-Jan-2012 to 31-Dec-2012

Operator Id: %

		SLE-14DA-01	SLE-14FA-01	SLE-HAWA-01	SLE-HAWA-03	SLE-MATE-01	TOTAL
Total		636	1000	2123	5900	2680	12339
Sub Total Violations		332	874	1064	2481	3336	8087
Less in Progress		0	0	0	0	0	0
Available For Prosecution		332	874	1064	2481	3336	8087
Less Rejects							
Camera Malfunction	Databar Unreadable/Incorrect	0-00%	1-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera Flash	6-02%	2-00%	6-01%	26-01%	5-00%	45-01%
	Face Camera Focus Blurry	1-00%	0-00%	6-01%	8-00%	6-00%	21-00%
	Face Camera No Flash	0-00%	1-00%	1-00%	0-00%	0-00%	2-00%
	Face Not in Frame	8-02%	3-00%	0-00%	91-04%	9-00%	111-01%
	Image Missing	2-01%	0-00%	0-00%	2-00%	4-00%	8-00%
	Misc Camera Issue	0-00%	5-01%	2-00%	13-01%	2-00%	22-00%
	Plate Burn Out	1-00%	0-00%	0-00%	7-00%	4-00%	12-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	1-00%	5-00%	6-00%
	Rear Plate Camera Blurry	0-00%	3-00%	3-00%	7-00%	3-00%	16-00%
	Rear Plate Flash Inappropriate	0-00%	5-01%	1-00%	5-00%	7-00%	18-00%
	Rear Plate No Flash	0-00%	3-00%	1-00%	0-00%	0-00%	4-00%
	Scene Image Flash Inappropriate	0-00%	1-00%	0-00%	4-00%	1-00%	6-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	15-01%	0-00%	15-00%
Police Rejects	Driver Unidentifiable images poor	30-09%	46-05%	98-09%	285-11%	129-04%	588-07%
	Incorrect Speed	0-00%	1-00%	8-01%	5-00%	0-00%	14-00%
	No Video	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%
	Red-light not visible in	0-00%	0-00%	13-01%	14-01%	6-00%	33-00%
	Unclear Scene Image	2-01%	1-00%	1-00%	3-00%	2-00%	9-00%
Process Issues	Too Old	3-01%	0-00%	0-00%	6-00%	2-00%	11-00%

Generated By: SWONG

Generated On: 1/15/2013 5:47:24 PM

Customer Management Report (San Leandro) All Detection Types

01-Jan-2012 to 31-Dec-2012

Operator Id: %

	SLE-14DA-01	SLE-14FA-01	SLE-HAWA-01	SLE-HAWA-03	SLE-MATE-01	TOTAL
Total	53-16%	72-08%	141-13%	492-20%	185-06%	943-12%
Approved Violations	279-84%	802-92%	923-87%	1989-80%	3151-94%	7144-88%
Total Notices Printed	279-84%	802-92%	923-87%	1989-80%	3151-94%	7144-88%

Generated By: SWONG

Generated On: 1/15/2013 5:47:24 PM