

# Customer Management Report (San Leandro) All Detection Types

01-Jan-2014 to 31-Dec-2014

Operator Id: %

	SLE-14DA-01	SLE-14FA-01	SLE-HAWA-01	SLE-HAWA-03	SLE-MATE-01	TOTAL
<b>Total Processed Incidents</b>	1065	3561	3854	10527	4900	23907
<b>Less Uncontrollable Factors</b>						
Obstruction						
Driver Obstruction/Duckers	20	146	143	685	154	1148
Motor Cycle Helmet	6	8	2	3	10	29
Plate Obstruction	13	38	21	136	71	279
Signal Obstruction	2	0	2	6	1	11
Vehicle Obstruction	36	28	56	357	148	625
Police Rejects						
Emergency Vehicle Responding	45	114	25	35	27	246
Incorrect Plate on Vehicle	0	0	0	1	0	1
Incorrect/Incomplete DMV	7	27	18	48	37	137
Invalid Offense	1	0	0	0	0	1
Multiple vehicles in frame	1	0	0	0	1	2
On or Passed the Stop Bar (PD)	0	167	607	1589	74	2437
Police Discretion	129	317	139	344	337	1266
Safe Turn On Red	57	323	753	2167	333	3633
Sun Glare	1	5	12	14	15	47
Yielding to an Emergency	0	0	1	0	0	1
Policy/Weather						
Extended Vehicle	58	2	4	37	75	176
Sun Glare	215	470	433	740	603	2461
Weather/Nature	2	11	10	5	5	33
Yellow with Red Light	0	1	0	1	0	2
Registration Issues						
Out of Country Plate	0	0	0	2	3	5
Paper Plates	41	128	99	281	206	755
<b>Total</b>	<b>634</b>	<b>1785</b>	<b>2325</b>	<b>6451</b>	<b>2100</b>	<b>13295</b>
<b>Sub Total Violations</b>	<b>431</b>	<b>1776</b>	<b>1529</b>	<b>4076</b>	<b>2800</b>	<b>10612</b>
Less in Progress	0	0	0	0	0	0
<b>Available For Prosecution</b>	<b>431</b>	<b>1776</b>	<b>1529</b>	<b>4076</b>	<b>2800</b>	<b>10612</b>
<b>Less Rejects</b>						
Camera Malfunction						
Face Camera Flash	3-01%	9-01%	47-03%	8-00%	12-00%	79-01%
Face Camera Focus Blurry	2-00%	11-01%	15-01%	0-00%	15-01%	43-00%
Face Camera No Flash	0-00%	0-00%	20-01%	16-00%	3-00%	39-00%
Face Not in Frame	1-00%	2-00%	0-00%	4-00%	17-01%	24-00%
Image Missing	10-02%	3-00%	0-00%	2-00%	0-00%	15-00%
Misc Camera Issue	13-03%	22-01%	79-05%	163-04%	17-01%	294-03%
Plate Burn Out	0-00%	1-00%	5-00%	36-01%	1-00%	43-00%
Plate Not in Frame	3-01%	0-00%	0-00%	0-00%	0-00%	3-00%
Rear Plate Camera Blurry	1-00%	4-00%	1-00%	10-00%	5-00%	21-00%

Generated By: SWONG

Generated On: 2/16/2015 11:16:15 AM

# Customer Management Report (San Leandro) All Detection Types

01-Jan-2014 to 31-Dec-2014

Operator Id: %

	SLE-14DA-01	SLE-14FA-01	SLE-HAVNA-01	SLE-HAVNA-03	SLE-MATE-01	TOTAL
Rear Plate Flash Inappropriate	1-00%	0-00%	1-00%	13-00%	0-00%	15-00%
Rear Plate No Flash	0-00%	5-00%	0-00%	0-00%	0-00%	5-00%
Scene Image Flash Inappropriate	0-00%	11-01%	0-00%	4-00%	8-00%	23-00%
Scene Image No Flash	0-00%	12-01%	0-00%	16-00%	0-00%	28-00%
Police Rejects						
Driver Unidentifiable images poor	52-12%	286-16%	262-17%	845-21%	417-15%	1862-18%
Incorrect Speed	0-00%	2-00%	2-00%	0-00%	0-00%	4-00%
Insufficient Strobe Lighting	1-00%	0-00%	6-00%	2-00%	0-00%	9-00%
Red-light not visible in	0-00%	33-02%	2-00%	130-03%	69-02%	234-02%
Unclear Scene Image	0-00%	0-00%	1-00%	0-00%	4-00%	5-00%
Process Issues						
Too Old	9-02%	34-02%	48-03%	147-04%	44-02%	282-03%
Total	96-22%	435-24%	489-32%	1396-34%	612-22%	3028-29%
Approved Violations	335-78%	1341-76%	1040-68%	2680-66%	2188-78%	7584-71%
Total Notices Printed	335-78%	1341-76%	1040-68%	2680-66%	2188-78%	7584-71%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SWONG

Generated On: 2/16/2015 11:16:15 AM