

Mcd 2-6-12

Customer Management Report (South Gate) Redlight Incidents

01-Jul-2009 to 31-Jul-2009 Operator Id: %

	156	153	55	62	108	616	168	202	6	208	86	30	48	67	1965	TOTAL
	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03		
Total Processed Incidents	11	3	1	2	8	38	5	13	0	10	5	2	0	0	0	98
Less Uncontrollable Factors																
Obstruction Driver Obstruction/Ducketers	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Motor Cycle Helmet	10	4	0	1	1	6	3	1	2	2	2	3	1	4	4	40
Plate Obstruction	1	1	0	1	4	33	0	2	0	7	0	2	2	1	1	54
Vehicle Obstruction	12	23	6	8	7	4	8	10	0	5	2	0	5	6	96	
Police Rejects	0	2	1	0	2	1	0	0	0	1	0	0	0	0	7	
Emergency Vehicle Responding	0	0	0	0	0	1	0	0	0	1	0	0	0	0	3	
Incorrect/Incomplete DMV	0	1	0	0	0	2	0	0	0	0	1	0	0	0	4	
Plate Unidentifiable	0	6	1	1	11	153	18	34	0	0	3	0	0	0	227	
Police Discretion	2	0	0	1	5	4	1	3	0	1	0	1	0	1	19	
Safe Turn On Red	43	12	8	7	36	122	57	61	2	97	35	12	15	20	527	
Policy/Weather Extended Vehicle	0	0	0	0	0	2	1	0	0	0	0	0	0	0	3	
Sun Glare	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1	
Weather/Nature	0	0	0	0	0	2	0	0	0	0	0	0	0	0	5	
Registration Can Not Identify State	0	1	0	0	0	2	0	1	0	0	0	0	1	0	67	
Issues Out of Country Plate	6	6	2	3	2	26	4	5	0	7	3	1	2	0	1152	
Paper Plates	86	59	19	24	76	395	97	130	4	131	51	21	27	32	813	
Sub Total Violations	70	94	36	38	32	221	71	72	2	77	35	9	21	35	813	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution	70	94	36	38	32	221	71	72	2	77	35	9	21	35	813	
Less Rejects																
Camera Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Malfunction Face Camera Flash	0-00%	0-00%	4-11%	0-00%	0-00%	0-00%	2-03%	12-17%	0-00%	4-05%	10-29%	1-11%	0-00%	3-09%	36-04%	
Face Camera Focus Blurry	6-09%	0-00%	2-06%	0-00%	4-12%	1-00%	1-01%	1-01%	0-00%	0-00%	2-06%	0-00%	0-00%	0-00%	17-02%	

Generated By: EPEREZ
Generated On: 2/2/2012 7:45:23 PM

Customer Management Report (South Gate) Redlight Incidents

01-Jul-2009 to 31-Jul-2009

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	1-01%	0-00%	0-00%	3-04%	0-00%	0-00%	0-00%	0-00%	6-01%
Face Not in Frame	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	2-00%
Image Missing	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	1-01%	0-00%	2-05%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-14%	1-03%	5-01%
Plate Not in Frame	0-00%	1-01%	0-00%	6-16%	0-00%	3-01%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	11-01%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	1-03%	3-00%
Scene Image Flash Inappropriate	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-10%	0-00%	2-00%
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	6-09%	4-04%	6-17%	9-24%	7-22%	7-03%	4-06%	15-21%	0-00%	9-12%	13-37%	2-22%	5-24%	6-17%	93-11%
Approved Violations	64-91%	90-96%	30-83%	29-76%	25-78%	214-97%	67-94%	57-79%	2-100%	68-88%	22-63%	7-78%	16-76%	29-83%	720-89%
Total Notices Printed	64-91%	90-96%	30-83%	29-76%	25-78%	214-97%	67-94%	57-79%	2-100%	68-88%	22-63%	7-78%	16-76%	29-83%	720-89%

Generated By: EPEREZ

Generated On: 2/2/2012 7:45:23 PM

Customer Management Report (South Gate) Redlight Incidents

01-Jan-2010 to 31-Jan-2010

Operator Id: %

	0	0	37	41	88	513	119	124	7	89	88	24	41	40	1211
	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Total Processed Incidents	0	0	37	41	88	513	119	124	7	89	88	24	41	40	1211
Less Uncontrollable Factors															
Obstruction	0	0	1	1	4	24	1	3	1	4	5	1	2	1	48
Driver Obstruction/Duckers	0	0	0	2	6	5	0	1	0	1	2	2	3	0	22
Plate Obstruction	0	0	2	1	2	42	0	2	0	4	1	2	0	1	57
Vehicle Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Police Rejects	0	0	16	2	12	5	17	13	1	2	4	2	3	5	82
Emergency Vehicle Responding	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
Incorrect Plate on Vehicle	0	0	0	0	0	3	0	1	0	1	0	0	0	0	5
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1
Invalid Offense	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1
Police Discretion	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
Safe Turn On Red	0	0	2	2	12	159	22	20	0	0	4	0	0	0	221
Yielding to an Emergency	0	0	0	0	1	0	0	0	0	0	0	0	1	0	2
Policy/Weather	0	0	0	0	0	0	1	2	0	0	1	0	1	0	5
Extended Vehicle	0	0	0	4	2	5	2	2	0	3	19	0	0	0	37
Sun Glare	0	0	0	1	1	1	1	3	0	1	2	0	0	0	9
Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Registration Issues	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
Can Not Identify State	0	0	0	1	0	1	0	0	0	0	0	0	0	0	3
Out of Country Plate	0	0	0	1	0	1	0	0	0	1	0	0	0	0	3
Paper Plates	0	0	1	4	4	20	5	6	1	5	6	1	2	3	54
Total	0	0	21	14	44	267	50	54	3	22	44	8	12	10	549
Sub Total Violations	0	0	16	27	44	246	69	70	4	67	44	16	29	30	662
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	0	0	16	27	44	246	69	70	4	67	44	16	29	30	662
Less Rejects															
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-04%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	1-02%	1-06%	0-00%	1-03%	5-01%
Face Camera Focus Blurry															

Generated By: EPEREZ

Generated On: 2/2/2012 7:47:40 PM

© Redflex Traffic Systems, Inc.

Customer Management Report (South Gate) Redlight Incidents

01-Jan-2010 to 31-Jan-2010

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-25%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	1-06%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-03%	0-00%	2-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	2-00%
Incorrect Speed	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	1-00%
Police Rejects	0-00%	0-00%	1-06%	0-00%	1-02%	1-00%	6-09%	2-03%	1-25%	0-00%	3-07%	1-06%	2-07%	1-03%	19-03%
Total	0-00%	0-00%	15-94%	27-100%	43-98%	245-100%	63-91%	68-97%	3-75%	67-100%	41-93%	15-94%	27-93%	29-97%	643-97%
Approved Violations	0-00%	0-00%	15-94%	27-100%	43-98%	245-100%	63-91%	68-97%	3-75%	67-100%	41-93%	15-94%	27-93%	29-97%	643-97%
Total Notices Printed	0-00%	0-00%	15-94%	27-100%	43-98%	245-100%	63-91%	68-97%	3-75%	67-100%	41-93%	15-94%	27-93%	29-97%	643-97%

Generated By: EPEREZ

Generated On: 2/2/2012 7:47:40 PM

© Redflex Traffic Systems, Inc.

Customer Management Report (South Gate) Redlight Incidents

01-Jul-2010 to 31-Jul-2010

Operator Id: %

	0	0	0	31	77	131	506	128	127	10	100	114	32	51	29	1336
	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL	
Total Processed Incidents	0	0	0	31	77	131	506	128	127	10	100	114	32	51	29	1336
Less Uncontrollable Factors																
Obstruction	0	0	0	0	2	8	29	4	7	0	2	3	3	3	1	62
Driver Obstruction/Duckers	0	0	0	0	2	8	29	4	7	0	2	3	3	3	1	62
Plate Obstruction	0	0	3	0	2	5	5	0	0	0	0	2	0	2	0	19
Vehicle Obstruction	0	0	0	0	1	3	40	1	0	1	10	3	1	2	0	62
Emergency Vehicle Responding	0	0	5	13	7	4	4	15	8	1	3	2	6	4	2	70
Incorrect/Incomplete DMV	0	0	0	0	1	6	6	1	0	0	1	0	0	0	1	10
Invalid Offense	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Police Discretion	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Safe Turn On Red	0	0	1	2	20	105	8	18	0	3	0	0	0	0	0	157
Yielding to an Emergency	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
Policy/Weather	0	0	0	0	2	1	0	1	0	2	1	0	0	0	0	7
Extended Vehicle	0	0	0	0	2	1	0	1	0	2	1	0	0	0	0	7
Sun Glare	0	0	4	11	26	72	18	27	2	37	23	6	17	10	253	
Registration	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
Out of Country Plate	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Issues	0	0	0	3	4	14	5	4	0	2	7	0	1	2	2	42
Paper Plates	0	0	13	34	77	276	53	65	4	56	46	17	29	16	686	
Total	0	0	18	43	54	230	75	62	6	44	68	15	22	13	650	
Sub Total Violations	0	0	18	43	54	230	75	62	6	44	68	15	22	13	650	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	0	0	18	43	54	230	75	62	6	44	68	15	22	13	650	
Less Rejects																
Camera	0-00%	0-00%	0-00%	1-02%	1-02%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	4-01%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-18%	0-00%	0-00%	4-01%
Misc Camera Issue	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: EPEREZ

Generated On: 2/2/2012 7:49:29 PM

Customer Management Report (South Gate) Redlight Incidents

01-Jul-2010 to 31-Jul-2010

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	1-02%	1-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	3-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-17%	1-02%	0-00%	0-00%	2-09%	0-00%	4-01%
Too Old	0-00%	0-00%	0-00%	1-02%	1-02%	1-00%	0-00%	0-00%	0-00%	0-00%	10-15%	0-00%	1-05%	0-00%	14-02%
Total	0-00%	0-00%	1-06%	2-05%	4-07%	4-02%	0-00%	1-02%	1-17%	2-05%	10-15%	1-07%	7-32%	1-08%	34-05%
Approved Violations	0-00%	0-00%	17-94%	41-95%	50-93%	226-98%	75-100%	61-98%	5-83%	42-95%	58-85%	14-93%	15-68%	12-92%	616-95%
Total Notices Printed	0-00%	0-00%	17-94%	41-95%	50-93%	226-98%	75-100%	61-98%	5-83%	42-95%	58-85%	14-93%	15-68%	12-92%	616-95%

Generated By: EPEREZ
Generated On: 2/2/2012 7:49:29 PM

Customer Management Report (South Gate) Redlight Incidents

01-Jan-2011 to 31-Jan-2011

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Total Processed Incidents	63	160	31	39	143	389	98	122	11	68	63	22	1307
Less Uncontrollable Factors													
Obstruction	7	6	3	0	8	10	4	4	5	2	3	0	57
Plate Obstruction	3	6	1	2	1	7	1	3	8	3	3	2	41
Vehicle Obstruction	2	0	0	0	1	28	0	1	4	2	3	0	49
Police	4	16	4	3	10	5	6	17	0	0	1	2	70
Emergency Vehicle Responding	0	0	0	0	0	1	0	0	0	0	0	0	1
Incorrect/incomplete DMV	0	0	0	0	1	0	0	0	0	0	0	0	1
Invalid Offense	1	21	1	3	32	65	10	15	5	4	6	1	166
Police Discretion	0	14	0	1	25	66	4	6	1	0	0	0	117
Safe Turn On Red	1	1	0	0	1	1	0	0	0	1	0	0	7
Policy/Weather	5	2	0	8	3	3	2	3	3	2	8	2	43
Extended Vehicle	1	1	0	0	0	3	0	0	0	0	1	0	7
Sun Glare	4	4	0	2	13	20	3	3	7	0	3	2	65
Registration	28	71	9	19	95	209	30	52	33	14	28	9	624
Out of Country Plate	35	89	22	20	48	180	68	70	27	24	35	13	683
Issues	0	0	0	0	0	0	0	0	0	0	0	0	0
Paper Plates	35	89	22	20	48	180	68	70	27	24	35	13	683
Total	35	89	22	20	48	180	68	70	27	24	35	13	683
Sub Total Violations	0	0	0	0	0	0	0	0	0	0	0	0	0
Less in Progress	35	89	22	20	48	180	68	70	27	24	35	13	683
Available For Prosecution	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Less Rejects	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Camera	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Face Not in Frame	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-04%	1-03%	0-00%	5-01%
Misc Camera Issue	1-03%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-15%	4-01%
Plate Not in Frame													

Generated By: EPEREZ
Generated On: 2/2/2012 7:50:54 PM

Customer Management Report (South Gate) Redlight Incidents

01-Jan-2011 to 31-Jan-2011

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-02%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	3-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	1-02%	1-01%	0-00%	0-00%	0-00%	0-00%	1-04%	1-04%	0-00%	0-00%	4-01%
Incorrect Speed	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	2-00%
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	3-03%	1-01%	0-00%	1-05%	5-10%	2-01%	0-00%	4-06%	1-11%	1-02%	2-07%	3-12%	4-11%	2-15%	29-04%
Total	32-91%	88-99%	22-100%	19-95%	43-90%	178-99%	68-100%	66-94%	8-89%	42-98%	25-93%	21-88%	31-89%	11-85%	654-96%
Approved Violations	32-91%	88-99%	22-100%	19-95%	43-90%	178-99%	68-100%	66-94%	8-89%	42-98%	25-93%	21-88%	31-89%	11-85%	654-96%
Total Notices Printed	32-91%	88-99%	22-100%	19-95%	43-90%	178-99%	68-100%	66-94%	8-89%	42-98%	25-93%	21-88%	31-89%	11-85%	654-96%

Customer Management Report (South Gate) Redlight Incidents

01-Jul-2011 to 31-Jul-2011

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Total Processed Incidents	116	129	30	82	78	512	141	109	2	288	70	36	63	44	1700
Less Uncontrollable Factors															
Obstruction	5	1	2	3	0	30	5	7	0	9	2	1	3	0	68
Driver Obstruction/Duckers	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
Motor Cycle Helmet	6	5	2	3	0	8	3	1	1	6	6	2	4	2	49
Plate Obstruction	4	0	0	0	0	33	2	1	0	16	2	1	6	0	65
Vehicle Obstruction	8	11	2	9	1	3	4	4	0	1	3	5	3	3	57
Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	1	0	0	0	1	2
Gender Mismatch	0	0	0	0	0	1	0	0	0	0	0	0	0	0	2
Incorrect/Incomplete DMV	0	0	0	0	0	5	0	0	0	0	0	0	0	0	5
Multiple vehicles in frame	0	0	0	0	0	9	2	1	0	0	3	0	0	0	15
On or Passed the Stop Bar (PD)	12	18	4	6	13	97	24	14	0	15	3	1	2	5	214
Police Discretion	0	1	0	1	3	51	4	5	0	0	2	0	0	0	67
Safe Turn On Red	1	0	0	1	1	0	0	0	1	2	0	5	3	0	14
Policy/Weather	17	15	2	24	29	74	34	28	0	142	12	12	13	15	417
Extended Vehicle	0	1	0	0	0	0	0	0	0	0	0	0	0	0	2
Sun Glare	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Out of Country Plate	5	5	1	1	1	25	5	6	0	10	0	1	0	0	61
Paper Plates	58	57	13	48	49	336	84	68	2	203	33	28	35	28	1042
Sub Total Violations	58	72	17	34	29	176	57	41	0	85	37	8	28	16	658
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	58	72	17	34	29	176	57	41	0	85	37	8	28	16	658
Less Rejects															
Camera Malfunction	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-04%	0-00%	3-00%
Face Camera Flash	0-00%	2-03%	1-06%	2-06%	2-07%	7-04%	3-05%	2-05%	0-00%	6-07%	1-03%	0-00%	0-00%	0-00%	26-04%
Face Camera Focus Blurry															
Generated By: EPEREZ															
Generated On: 2/2/2012 7:52:05 PM															

Customer Management Report (South Gate) Redlight Incidents

01-Jul-2011 to 31-Jul-2011

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Not in Frame	3-05%	1-01%	0-00%	3-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	0-00%	9-01%
Image Missing	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	3-00%
Misc Camera Issue	2-03%	0-00%	0-00%	0-00%	1-03%	8-05%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	12-02%
Plate Not in Frame	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	3-00%
Rear Plate Camera Blurry	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	3-00%
Police Rejects	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	2-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-21%	0-00%	7-01%
Sun Glare	0-00%	0-00%	0-00%	1-03%	0-00%	3-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Total	7-12%	5-07%	1-06%	6-18%	5-17%	19-11%	3-05%	2-05%	0-00%	10-12%	2-05%	0-00%	9-32%	2-12%	71-11%
Approved Violations	51-88%	67-93%	16-94%	28-82%	24-83%	157-89%	54-95%	39-95%	0-00%	75-88%	35-85%	8-100%	19-68%	14-88%	587-89%
Total Notices Printed	51-88%	67-93%	16-94%	28-82%	24-83%	157-89%	54-95%	39-95%	0-00%	75-88%	35-85%	8-100%	19-68%	14-88%	587-89%

Customer Management Report (South Gate) Redlight Incidents

01-Aug-2011 to 31-Aug-2011 Operator Id: %

	180	267	38	76	95	385	136	143	13	412	92	130	84	44	2095
	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL	
Total Processed Incidents	8	12	0	2	6	22	0	4	1	29	3	10	7	2	106
Less Uncontrollable Factors	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
Obstruction	11	13	0	4	9	2	6	3	2	8	4	3	10	5	80
Driver Obstruction/Duckers	2	3	1	0	1	18	1	1	0	16	1	3	4	1	52
Motor Cycle Helmet	10	5	6	6	0	2	7	10	2	0	2	5	1	3	59
Plate Obstruction	0	0	0	0	1	0	0	0	0	2	0	0	0	0	3
Vehicle Obstruction	36	63	13	20	20	171	37	50	3	81	20	16	8	5	543
Police	3	1	0	0	1	1	0	0	1	7	2	7	0	0	23
Emergency Vehicle Responding	21	8	0	12	13	30	19	24	2	81	13	19	14	11	267
Multiple vehicles in frame	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
Police Discretion	0	0	0	0	0	1	0	0	0	1	0	0	0	0	2
Policy/Weather	8	9	1	3	7	11	3	2	0	17	4	5	2	1	73
Extended Vehicle	99	114	21	47	58	259	73	94	11	242	50	68	46	28	1210
Sun Glare	81	153	17	29	37	126	63	49	2	170	42	62	38	16	885
Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Issues	0	0	0	0	0	1	0	0	0	1	0	0	0	0	2
Out of Country Plate	8	9	1	3	7	11	3	2	0	17	4	5	2	1	73
Paper Plates	99	114	21	47	58	259	73	94	11	242	50	68	46	28	1210
Total	81	153	17	29	37	126	63	49	2	170	42	62	38	16	885
Sub Total Violations	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Less in Progress	81	153	17	29	37	126	63	49	2	170	42	62	38	16	885
Available For Prosecution															
Less Rejects															
Camera	0-00%	1-01%	0-00%	0-00%	2-05%	2-02%	2-03%	3-06%	0-00%	11-06%	0-00%	3-05%	1-03%	6-38%	31-04%
Face Camera Flash	0-00%	1-01%	1-06%	0-00%	1-03%	2-02%	0-00%	0-00%	0-00%	2-01%	0-00%	2-03%	1-03%	0-00%	10-01%
Face Camera Focus Blurry	1-01%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-02%	1-02%	2-05%	0-00%	7-01%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	4-00%
Image Missing	2-02%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-02%	0-00%	1-02%	0-00%	0-00%	8-01%
Misc Camera Issue	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	1-02%	0-00%	0-00%	5-01%
Plate Burn Out															

Generated By: EPEREZ
Generated On: 2/2/2012 7:53:06 PM

Customer Management Report (South Gate) Redlight Incidents

01-Aug-2011 to 31-Aug-2011

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Plate Not in Frame	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-02%	1-03%	0-00%	4-00%
Driver Unidentifiable images poor	2-02%	3-02%	0-00%	1-03%	1-03%	6-05%	0-00%	1-02%	0-00%	4-02%	0-00%	1-02%	3-08%	1-06%	23-03%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	10-26%	0-00%	10-01%
Sun Glare	0-00%	0-00%	0-00%	0-00%	0-00%	8-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	9-01%
Too Old	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Process Issues	6-07%	9-06%	2-12%	2-07%	4-11%	19-15%	3-05%	4-08%	0-00%	26-15%	1-02%	10-16%	19-50%	8-50%	113-13%
Total	75-93%	144-94%	15-88%	27-93%	33-89%	107-85%	60-95%	45-92%	2-100%	144-85%	41-98%	52-84%	19-50%	8-50%	772-87%
Approved Violations	75-93%	144-94%	15-88%	27-93%	33-89%	107-85%	60-95%	45-92%	2-100%	144-85%	41-98%	52-84%	19-50%	8-50%	772-87%
Total Notices Printed	75-93%	144-94%	15-88%	27-93%	33-89%	107-85%	60-95%	45-92%	2-100%	144-85%	41-98%	52-84%	19-50%	8-50%	772-87%

Customer Management Report (South Gate) Redlight Incidents

01-Sep-2011 to 30-Sep-2011 Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Total Processed Incidents	141	193	28	106	115	322	139	131	5	343	46	82	112	39	1802
Less Uncontrollable Factors															
Obstruction	6	1	0	8	2	15	5	8	0	15	1	7	3	1	72
Driver Obstruction/Duckers	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
Motor Cycle Helmet	14	15	4	3	8	2	3	2	1	12	2	8	8	2	84
Plate Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Signal Obstruction	0	2	0	0	1	16	0	3	0	24	1	9	5	2	63
Vehicle Obstruction	4	14	5	7	3	0	4	7	0	2	2	1	3	3	55
Emergency Vehicle Responding	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1
Incorrect/Incomplete DMV	1	0	0	1	0	0	0	0	0	1	0	0	0	0	5
Multiple vehicles in frame	30	65	7	21	39	173	53	37	1	85	11	9	27	6	564
Police Discretion	2	4	0	1	0	0	4	1	0	4	0	6	0	1	23
Extended Vehicle	13	3	1	18	7	15	5	15	1	31	11	12	14	8	154
Sun Glare	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
Yellow with Red Light	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	0	1	0	2
Out of Country Plate	0	0	0	0	0	0	0	0	0	1	1	0	0	1	3
Paper Plates	4	9	1	3	11	14	9	8	1	14	2	4	3	3	86
Wrong or No DMV	0	0	0	0	0	0	0	0	0	0	0	3	0	0	3
Total	74	114	18	62	71	236	84	82	4	189	31	59	67	27	1118
Sub Total Violations	67	79	10	44	44	86	55	49	1	154	15	23	45	12	684
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	67	79	10	44	44	86	55	49	1	154	15	23	45	12	684
Less Rejects															
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	2-04%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	6-01%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: EPEREZ
Generated On: 2/2/2012 7:53:42 PM

Customer Management Report (South Gate) Redlight Incidents

01-Sep-2011 to 30-Sep-2011

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Face Not in Frame	2-03%	0-00%	0-00%	1-02%	2-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	6-01%
Image Missing	0-00%	1-01%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Misc Camera Issue	1-01%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-03%	0-00%	0-00%	0-00%	0-00%	10-01%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-02%	1-100%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	1-02%	2-02%	0-00%	0-00%	0-00%	1-01%	0-00%	1-04%	0-00%	0-00%	1-00%
Red-light not visible in	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	17-38%	1-08%	5-01%
Sun Glare	0-00%	0-00%	0-00%	0-00%	1-02%	4-05%	0-00%	2-04%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	20-03%
Too Old	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	8-01%
Process Issues	4-06%	2-03%	0-00%	3-07%	7-16%	8-09%	0-00%	5-10%	1-100%	9-06%	0-00%	2-09%	20-44%	3-25%	1-00%
Total	63-94%	77-97%	10-100%	41-93%	37-84%	78-91%	55-100%	44-90%	0-00%	145-94%	15-100%	21-91%	25-56%	9-75%	620-91%
Approved Violations	63-94%	77-97%	10-100%	41-93%	37-84%	78-91%	55-100%	44-90%	0-00%	145-94%	15-100%	21-91%	25-56%	9-75%	620-91%
Total Notices Printed	63-94%	77-97%	10-100%	41-93%	37-84%	78-91%	55-100%	44-90%	0-00%	145-94%	15-100%	21-91%	25-56%	9-75%	620-91%

Customer Management Report (South Gate) Redlight Incidents

01-Oct-2011 to 31-Oct-2011

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Total Processed Incidents	200	280	43	102	114	744	136	146	13	403	113	106	125	59	2584
Less Uncontrollable Factors															
Obstruction	12	11	1	3	7	45	6	7	1	33	6	6	13	6	157
Driver Obstruction/Duckers															
Motor Cycle Helmet	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
Plate Obstruction	11	9	3	4	4	16	5	4	2	12	7	7	6	2	92
Signal Obstruction	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Vehicle Obstruction	2	4	0	0	0	17	2	2	1	12	1	0	2	1	44
Citation Issued Manually	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
Emergency Vehicle Responding	7	9	4	7	3	7	3	2	0	1	1	2	4	6	56
Funeral Procession/Police	0	0	0	0	0	2	0	0	0	2	0	0	0	0	4
Gender Mismatch	4	5	0	1	1	12	2	1	0	9	3	1	1	1	41
Multiple vehicles in frame	1	1	0	0	0	1	1	0	0	2	1	0	1	0	8
On or Passed the Stop Bar (PD)	1	0	0	1	0	2	0	0	0	1	1	0	0	1	7
Police Discretion	34	44	7	16	12	92	23	31	0	60	12	10	21	7	369
Safe Turn On Red	0	2	0	3	14	196	11	16	0	0	7	2	0	0	251
Weather Conditions	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Policy/Weather	5	2	0	1	2	3	1	0	0	5	3	6	0	0	28
Extended Vehicle															
Sun Glare	12	4	0	16	4	30	0	9	3	8	12	8	12	0	118
Weather/Nature	1	3	1	0	0	5	1	4	0	1	0	1	1	3	21
Yellow with Red Light	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Registration	0	0	0	0	0	1	1	0	0	0	0	0	1	0	3
Out of Country Plate															
Issues	7	19	2	6	7	30	5	8	1	19	5	4	6	3	122
Paper Plates															
Wrong or No DMV	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
Total	98	113	18	58	54	461	62	84	8	167	59	47	68	30	1327
Sub Total Violations	102	167	25	44	60	283	74	62	5	236	54	59	57	29	1257

Generated By: EPEREZ
Generated On: 2/2/2012 7:54:48 PM

Customer Management Report (South Gate) Redlight Incidents

01-Oct-2011 to 31-Oct-2011 Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	102	167	25	44	60	283	74	62	5	236	54	59	57	29	1257
Less Rejects															
Camera Malfunction	0-00%	1-01%	0-00%	0-00%	1-02%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	6-00%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	2-03%	1-00%	0-00%	1-02%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	6-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-05%	0-00%	0-00%	3-00%
Face Not in Frame	1-01%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-02%	0-00%	0-00%	0-00%	0-00%	6-00%
Image Missing	4-04%	5-03%	0-00%	0-00%	1-02%	1-00%	0-00%	0-00%	1-20%	5-02%	0-00%	0-00%	0-00%	0-00%	17-01%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	3-10%	5-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	3-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	1-20%	1-00%	1-02%	0-00%	1-02%	0-00%	6-00%
Rear Plate No Flash	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	1-01%	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	1-20%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Driver Unidentifiable Images poor	2-02%	4-02%	2-08%	2-05%	2-03%	14-05%	0-00%	0-00%	1-20%	9-04%	0-00%	4-07%	1-02%	2-07%	43-03%
No Images	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	25-02%
Sun Glare	1-01%	0-00%	0-00%	0-00%	2-03%	1-00%	1-01%	2-03%	0-00%	7-03%	0-00%	0-00%	2-04%	0-00%	16-01%
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	10-10%	13-08%	2-08%	2-05%	9-15%	26-03%	1-01%	3-05%	4-80%	34-14%	2-04%	10-17%	24-42%	6-21%	146-12%
Total	92-90%	154-92%	23-92%	42-95%	51-85%	257-91%	73-99%	59-95%	1-20%	202-86%	52-96%	49-83%	33-58%	23-79%	1111-88%
Approved Violations	92-90%	154-92%	23-92%	42-95%	51-85%	257-91%	73-99%	59-95%	1-20%	202-86%	52-96%	49-83%	33-58%	23-79%	1111-88%
Total Notices Printed	92-90%	154-92%	23-92%	42-95%	51-85%	257-91%	73-99%	59-95%	1-20%	202-86%	52-96%	49-83%	33-58%	23-79%	1111-88%

Customer Management Report (South Gate) Redlight Incidents

01-Oct-2011 to 31-Oct-2011

Operator Id: %

TOTAL
SG-IMGA-03
SG-IMGA-01
SG-GASO-03
SG-GASO-01
SG-FIGA-03
SG-FIGA-01
SG-FICA-03
SG-FICA-01
SG-FIAT-03
SG-FIAT-01
SG-CATW-03
SG-CATW-01
SG-ATTW-03
SG-ATTW-01

Generated By: EPEREZ

Generated On: 2/2/2012 7:54:48 PM

© Redflex Traffic Systems, Inc.

Customer Management Report (South Gate) Redlight Incidents

01-Nov-2011 to 30-Nov-2011 Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Total Processed Incidents	132	128	43	83	106	397	144	113	6	311	85	60	109	43	1760
Less Uncontrollable Factors															
Obstruction	9	2	1	3	2	22	2	5	1	17	6	7	4	1	82
Driver Obstruction/Duckers	0	0	0	0	0	0	2	0	0	0	0	0	0	0	2
Motor Cycle Helmet	4	10	1	1	4	8	3	3	0	15	6	3	12	1	71
Plate Obstruction	2	0	1	1	0	14	1	0	1	7	2	1	3	1	34
Vehicle Obstruction	10	12	8	9	2	0	2	8	1	3	3	0	2	4	64
Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	4	0	0	0	0	4
Funeral Procession/Police	2	1	1	0	1	6	2	3	0	11	1	0	1	1	30
Gender Mismatch	1	2	0	0	0	0	0	0	0	0	0	0	0	0	3
Invalid Offense	1	1	0	0	1	0	1	0	0	0	0	0	2	0	6
Multiple vehicles in frame	8	4	5	6	2	5	2	3	0	11	5	0	2	1	54
On or Passed the Stop Bar (PD).	14	10	6	7	8	14	14	5	1	42	3	1	12	4	141
Police Discretion	0	5	0	2	12	135	22	18	0	0	11	0	0	0	205
Safe Turn On Red	0	0	0	0	0	1	0	0	0	3	0	0	0	0	4
Weather Conditions	0	2	0	0	0	1	0	0	0	3	0	0	0	0	9
Policy/Weather	9	1	1	10	2	10	1	3	0	4	9	8	4	4	66
Extended Vehicle	0	0	0	0	0	4	0	3	0	3	1	0	0	0	11
Sun Glare	0	0	1	0	0	0	0	1	0	1	0	0	0	0	3
Weather/Nature	7	6	1	3	9	15	6	7	0	12	7	9	9	2	93
Out of Country Plate	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Paper Plates	67	56	26	42	43	235	58	59	4	137	54	32	51	19	883
Wrong or No DMV	65	72	17	41	63	162	86	54	2	174	31	28	58	24	877
Sub Total Violations	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Less in Progress	65	72	17	41	63	162	86	54	2	174	31	28	58	24	877
Available For Prosecution															

Generated By: EPEREZ
Generated On: 2/2/2012 7:56:34 PM

Customer Management Report (South Gate) Redlight Incidents

01-Nov-2011 to 30-Nov-2011

Operator Id: %

	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Less Rejects														
Camera Malfunction	1-02%	1-06%	1-02%	1-01%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	0-00%	0-00%	9-01%
Face Camera Flash	0-00%	0-00%	0-00%	2-01%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Face Camera Focus Blurry	3-05%	0-00%	2-05%	1-01%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	10-01%
Face Not in Frame	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	1-04%	0-00%	0-00%	0-00%	6-01%
Image Missing	0-00%	0-00%	1-02%	1-02%	1-02%	0-00%	0-00%	0-00%	3-02%	1-04%	0-00%	2-03%	0-00%	9-01%
Misc Camera Issue	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-02%	1-04%	5-01%
Plate Not in Frame	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-04%	2-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-50%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	2-00%
Scene Image No Flash	0-00%	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Rejects	6-09%	4-24%	7-11%	28-17%	28-17%	2-02%	7-13%	0-00%	13-07%	8-29%	0-00%	0-00%	6-25%	94-11%
Driver Unidentifiable images poor	3-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	15-26%	0-00%	18-02%
Red-light not visible in	0-00%	0-00%	0-00%	1-01%	1-01%	0-00%	1-02%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	3-00%
Sun Glare	1-02%	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	3-00%
Unclear Scene Image	17-26%	5-29%	11-27%	36-22%	36-22%	2-02%	8-15%	1-50%	23-13%	12-43%	0-00%	22-38%	8-33%	166-19%
Approved Violations	48-74%	12-71%	30-73%	126-78%	126-78%	84-98%	46-85%	1-50%	151-87%	28-90%	16-57%	36-62%	16-67%	711-81%
Total Notices Printed	48-74%	12-71%	30-73%	126-78%	126-78%	84-98%	46-85%	1-50%	151-87%	28-90%	16-57%	36-62%	16-67%	711-81%

Customer Management Report (South Gate) Redlight Incidents

01-Dec-2011 to 31-Dec-2011

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Total Processed Incidents	64	131	60	60	92	468	135	71	20	346	76	53	129	44	1749
Less Uncontrollable Factors															
Obstruction	0	1	0	2	5	21	2	4	2	14	3	4	9	0	67
Driver Obstruction/Duckers															
Plate Obstruction	2	10	1	2	5	12	3	1	5	13	4	6	6	3	73
Vehicle Obstruction	2	1	1	1	0	18	0	1	0	17	1	2	5	1	50
Police Rejects															
Emergency Vehicle Responding	8	19	12	7	5	2	1	2	3	2	2	1	6	4	74
Funeral Procession/Police	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Gender Mismatch	3	4	2	1	7	3	0	0	0	14	1	0	2	1	38
Multiple vehicles in frame	0	0	0	0	0	1	2	0	0	0	0	0	3	0	6
On or Passed the Stop Bar (PD)	7	0	6	3	3	14	0	1	2	32	4	1	5	2	80
Police Discretion	5	14	1	3	9	15	15	3	0	32	3	3	13	7	123
Safe Turn On Red	0	6	0	2	10	145	27	11	0	0	8	3	0	0	212
Policy/Weather															
Extended Vehicle	1	1	0	0	0	2	1	1	0	7	1	2	1	0	17
Weather/Nature	4	1	1	9	2	16	2	5	1	9	6	5	6	3	70
Registration Issues															
Out of Country Plate	0	0	0	0	0	1	0	0	0	0	0	0	0	1	2
Paper Plates	1	4	4	4	3	27	7	2	0	16	2	2	3	5	80
Wrong or No DMV	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Total	33	62	29	34	49	280	60	31	13	157	36	30	61	27	902
Sub Total Violations	31	69	31	26	43	188	75	40	7	189	40	23	68	17	847
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	31	69	31	26	43	188	75	40	7	189	40	23	68	17	847
Less Rejects															
Camera Malfunction	0-00%	0-00%	2-06%	0-00%	3-07%	3-02%	0-00%	0-00%	0-00%	0-00%	0-00%	2-09%	0-00%	1-06%	11-01%
Face Camera Flash	0-00%	0-00%	4-13%	0-00%	1-02%	6-03%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	3-04%	0-00%	15-02%
Face Camera Focus Blurry															
Generated By: EPEREZ															
Generated On: 2/2/2012 7:57:46 PM															

Customer Management Report (South Gate) Redlight Incidents

01-Dec-2011 to 31-Dec-2011

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIAT-01	SG-FIAT-03	SG-FICA-01	SG-FICA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Face Not in Frame	0-00%	0-00%	1-03%	3-12%	6-14%	0-00%	0-00%	0-00%	1-14%	0-00%	0-00%	2-09%	1-01%	0-00%	14-02%
Image Missing	0-00%	0-00%	0-00%	0-00%	1-02%	1-01%	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	4-00%
Misc Camera Issue	0-00%	0-00%	0-00%	2-08%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	6-01%
Plate Not in Frame	1-03%	0-00%	1-03%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	2-12%	6-01%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	2-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-43%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	2-06%	5-07%	3-10%	1-04%	6-14%	39-21%	4-05%	7-18%	2-29%	22-12%	6-15%	5-22%	9-13%	0-00%	111-13%
No Images	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	2-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	14-21%	0-00%	16-02%
Sun Glare	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	2-00%
Process Issues	5-16%	5-07%	11-35%	9-35%	18-42%	51-27%	6-08%	7-18%	6-86%	28-15%	6-15%	9-39%	31-46%	3-18%	195-23%
Total	26-84%	64-93%	20-65%	17-65%	25-58%	137-73%	69-92%	33-82%	1-14%	161-85%	34-85%	14-61%	37-54%	14-82%	652-77%
Approved Violations	26-84%	64-93%	20-65%	17-65%	25-58%	137-73%	69-92%	33-82%	1-14%	161-85%	34-85%	14-61%	37-54%	14-82%	652-77%
Total Notices Printed	26-84%	64-93%	20-65%	17-65%	25-58%	137-73%	69-92%	33-82%	1-14%	161-85%	34-85%	14-61%	37-54%	14-82%	652-77%