

BCD (10 pages)

# Customer Management Report (Baldwin Park) All Detection Types

01-Jan-2014 to 31-Jan-2014

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
<b>Total Processed Incidents</b>	47	33	102	174	36	44	111	280	18	845
<b>Less Uncontrollable Factors</b>										
Obstruction Driver Obstruction/Duckers	6	3	17	20	10	6	30	22	4	118
Motor Cycle Helmet	0	0	0	0	2	0	2	1	0	5
Plate Obstruction	1	1	7	0	0	0	3	2	2	16
Signal Obstruction	0	0	0	0	0	0	0	1	0	1
Vehicle Obstruction	1	1	1	6	1	0	7	1	0	18
Citation Issued manually	0	0	0	0	0	0	0	1	0	1
Gender Mismatch	0	0	0	0	0	0	0	1	0	1
Incorrect/Incomplete DMV	8	6	9	20	1	3	7	41	2	97
On or Passed the Stop Bar (PD)	0	0	1	5	0	1	4	24	0	35
Police Discretion	0	0	0	0	1	0	0	0	0	1
Policy/Weather Extended Vehicle	0	0	0	0	0	1	1	1	0	3
Sun Glare	0	0	14	11	1	0	11	4	1	42
Weather/Nature	0	0	3	0	0	0	2	0	0	5
Registration Paper Plates	2	1	9	16	0	1	2	16	0	47
Issues	18	12	61	78	16	12	69	115	9	390
<b>Sub Total Violations</b>	29	21	41	96	20	32	42	165	9	455
Less in Progress	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>	29	21	41	96	20	32	42	165	9	455
<b>Less Rejects</b>										
Camera Face Camera Focus Blurry	0-00%	0-00%	1-02%	1-01%	0-00%	0-00%	3-07%	0-00%	0-00%	5-01%
Malfunction Image Missing	0-00%	0-00%	0-00%	4-04%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Misc Camera Issue	0-00%	0-00%	0-00%	6-06%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%

Generated By: TESPANTO  
Generated On: 8/6/2014 4:24:03 PM

# Customer Management Report (Baldwin Park) All Detection Types

01-Jan-2014 to 31-Jan-2014

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Plate Burn Out	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	2-05%	1-01%	0-00%	4-01%
Scene Image Flash Inappropriate	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Too Old	2-07%	0-00%	3-07%	8-08%	4-20%	3-09%	5-12%	18-11%	1-11%	44-10%
Total	2-07%	2-10%	5-12%	20-21%	4-20%	3-09%	10-24%	19-12%	1-11%	66-15%
Approved Violations	27-93%	19-90%	36-88%	76-79%	16-80%	29-91%	32-76%	146-88%	8-89%	389-85%
Total Notices Printed	27-93%	19-90%	36-88%	76-79%	16-80%	29-91%	32-76%	146-88%	8-89%	389-85%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: TESPANTO  
Generated On: 8/6/2014 4:24:03 PM

© Reflex Traffic Systems, Inc.

# Customer Management Report (Baldwin Park) All Detection Types

01-Feb-2014 to 28-Feb-2014

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
<b>Total Processed Incidents</b>	51	63	125	198	43	57	116	273	29	955
<b>Less Uncontrollable Factors</b>										
Obstruction	4	6	23	17	8	10	30	17	3	118
Motor Cycle Helmet	1	0	0	1	0	0	1	0	0	3
Plate Obstruction	2	1	3	3	0	3	2	0	0	14
Signal Obstruction	0	0	0	0	0	1	0	0	0	1
Vehicle Obstruction	1	4	2	7	4	0	4	7	1	30
Gender Mismatch	0	0	0	1	0	0	0	3	0	4
Incorrect/Incomplete DMV	7	11	5	23	8	10	10	46	2	122
On or Passed the Stop Bar (PD)	1	0	0	6	1	0	0	10	0	18
Policy/Weather	0	1	0	0	0	0	0	1	0	2
Extended Vehicle	0	0	25	10	1	1	19	7	0	63
Sun Glare	0	1	1	0	0	0	0	1	15	18
Weather/Nature	1	1	5	10	1	0	7	20	1	46
Paper Plates	0	0	0	1	0	0	0	1	0	2
Wrong or No DMV	17	25	64	79	23	25	73	113	22	441
<b>Total</b>	34	38	61	119	20	32	43	160	7	514
<b>Sub Total Violations</b>	0	0	0	0	0	0	0	0	0	0
Less in Progress	34	38	61	119	20	32	43	160	7	514
<b>Available For Prosecution</b>										
<b>Less Rejects</b>										
Camera	0-00%	0-00%	1-02%	1-01%	0-00%	0-00%	3-07%	1-01%	0-00%	6-01%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
Malfunction	0-00%	1-03%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Burn Out										
Plate Not in Frame										

Generated By: TESPANTO

Generated On: 8/6/2014 4:24:31 PM

# Customer Management Report (Baldwin Park) All Detection Types

01-Feb-2014 to 28-Feb-2014

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL
Rear Plate Camera Blurry	0-00%	1-03%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Scene Image Blurry	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	1-00%
Unclear Scene Image	0-00%	1-03%	0-00%	1-01%	0-00%	1-03%	0-00%	0-00%	0-00%	3-01%
Too Old	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects Process Issues										
Total	0-00%	3-08%	2-03%	5-04%	1-05%	2-06%	3-07%	2-01%	0-00%	18-04%
Approved Violations	34-100%	35-92%	59-97%	114-96%	19-95%	30-94%	40-93%	158-99%	7-100%	496-96%
Total Notices Printed	34-100%	35-92%	59-97%	114-96%	19-95%	30-94%	40-93%	158-99%	7-100%	496-96%

Legend: (P) = Production (!) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: TESPANTO  
Generated On: 8/6/2014 4:24:31 PM

© Redflex Traffic Systems, Inc.

# Customer Management Report (Baldwin Park) All Detection Types

01-Mar-2014 to 31-Mar-2014 Operator Id: %

	BAL-DAPU-01	BAL-FRRU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RARR-01	BAL-RARR-03	TOTAL
<b>Total Processed Incidents</b>	53	115	138	232	49	78	99	296	21	1081
<b>Less Uncontrollable Factors</b>										
Obstruction	Driver Obstruction/Duckers									
	5	4	8	12	8	14	17	6	10	84
	Motor Cycle Helmet									
	1	0	3	1	1	0	2	0	0	8
	Plate Obstruction									
	1	3	7	3	0	2	0	2	0	18
	Vehicle Obstruction									
	0	7	1	8	3	1	3	3	0	26
Police Rejects	Citation Issued manually									
	1	0	0	0	0	1	0	0	0	2
	Incorrect/Incomplete DMV									
	12	17	22	43	8	11	24	77	4	218
	On or Passed the Stop Bar (PD)									
	0	0	0	1	0	0	0	0	0	1
	Sun Glare									
	0	1	1	0	0	0	0	0	0	2
Policy/Weather	Extended Vehicle									
	0	1	0	0	0	2	0	0	0	3
	Sun Glare									
	2	8	31	37	7	5	18	21	0	129
	Weather/Nature									
	0	0	0	0	0	0	0	1	0	1
Registration Issues	Paper Plates									
	2	7	0	11	3	3	5	8	2	41
<b>Total</b>	24	48	73	116	30	39	69	118	16	533
<b>Sub Total Violations</b>	29	67	65	116	19	39	30	178	5	548
Less in Progress	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>	29	67	65	116	19	39	30	178	5	548
<b>Less Rejects</b>										
Camera Malfunction	Face Camera Flash									
	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	28-16%	0-00%	28-05%
	Face Camera Focus Blurry									
	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
	Face Not in Frame									
	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Camera Blurry									
	0-00%	1-01%	1-02%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
	Scene Image Flash Inappropriate									
	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	2-00%
	Scene Image No Flash									
	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
<b>Total</b>	0-00%	1-01%	1-02%	1-01%	0-00%	2-05%	0-00%	31-17%	0-00%	36-07%
<b>Approved Violations</b>	29-100%	66-99%	64-98%	115-99%	19-100%	37-95%	30-100%	147-83%	5-100%	512-93%
<b>Total Notices Printed</b>	29-100%	66-99%	64-98%	115-99%	19-100%	37-95%	30-100%	147-83%	5-100%	512-93%

Legend: (P) = Production (I) = Inoperative  
 Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Baldwin Park) All Detection Types

01-Apr-2014 to 30-Apr-2014

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL	
<b>Total Processed Incidents</b>	63	89	119	244	37	58	118	319	22	1069	
<b>Less Uncontrollable Factors</b>											
Obstruction	Driver Obstruction/Duckers	6	2	4	3	9	5	10	3	7	49
	Motor Cycle Helmet	1	0	0	2	0	0	0	0	0	3
	Plate Obstruction	1	1	5	4	0	3	2	1	0	17
	Vehicle Obstruction	2	11	1	13	1	1	2	1	1	33
Police Rejects	Gender Mismatch	0	0	1	0	0	0	0	1	0	2
	Incorrect/Incomplete DMV	7	15	20	33	5	6	11	56	1	154
	On or Passed the Stop Bar (PD)	0	0	0	2	0	1	1	2	0	6
	Sun Glare	0	0	0	0	0	0	1	1	0	2
Policy/Weather	Extended Vehicle	0	0	1	0	0	0	0	0	0	1
	Sun Glare	1	2	26	44	3	5	40	30	0	151
Registration Issues	Out of Country Plate	0	0	0	3	0	0	0	0	0	3
	Paper Plates	1	5	6	13	2	4	1	16	2	50
<b>Total</b>		19	36	64	117	20	25	68	111	11	471
<b>Sub Total Violations</b>		44	53	55	127	17	33	50	208	11	598
Less in Progress		0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		44	53	55	127	17	33	50	208	11	598
<b>Less Rejects</b>											
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	1-01%	1-06%	0-00%	1-02%	0-00%	0-00%	3-01%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	3-09%	0-00%	1-00%	0-00%	4-01%
	Image Missing	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	2-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Plate Not in Frame	3-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-02%	0-00%	0-00%	2-00%
	Rear Plate No Flash	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	2-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	1-00%
<b>Total</b>		4-09%	1-02%	0-00%	3-02%	2-12%	3-09%	3-06%	3-01%	0-00%	19-03%
<b>Approved Violations</b>		40-91%	52-98%	55-100%	124-98%	15-88%	30-91%	47-94%	205-99%	11-100%	579-97%
<b>Total Notices Printed</b>		40-91%	52-98%	55-100%	124-98%	15-88%	30-91%	47-94%	205-99%	11-100%	579-97%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: TESPANTO

Generated On: 8/6/2014 4:43:46 PM

# Customer Management Report (Baldwin Park) All Detection Types

01-May-2014 to 31-May-2014

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUPA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL	
<b>Total Processed Incidents</b>	52	89	127	252	61	60	129	353	20	1143	
<b>Less Uncontrollable Factors</b>											
Obstruction	Driver Obstruction/Duckers	1	0	2	7	12	8	15	4	10	59
	Motor Cycle Helmet	0	0	0	2	0	0	2	0	0	4
	Plate Obstruction	2	1	5	4	0	5	1	1	0	19
	Vehicle Obstruction	0	6	0	10	2	4	4	5	0	31
Police Rejects	Citation Issued manually	0	0	0	0	0	0	0	1	0	1
	Gender Mismatch	0	0	0	0	0	0	0	1	0	1
	incorrect/incomplete DMV	12	19	24	57	9	14	20	97	2	254
	Sun Glare	0	0	0	0	0	0	0	1	0	1
Policy/Weather	Extended Vehicle	0	0	0	0	0	2	0	0	0	2
	Sun Glare	0	7	38	35	8	7	35	42	0	172
	Weather/Nature	0	0	0	0	0	0	1	0	0	1
Registration Issues	Out of Country Plate	0	0	0	0	0	0	1	0	0	1
	Paper Plates	1	3	2	14	3	2	3	16	1	45
<b>Total</b>		16	36	71	129	34	42	82	168	13	591
<b>Sub Total Violations</b>		36	53	56	123	27	18	47	185	7	552
Less in Progress		0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		36	53	56	123	27	18	47	185	7	552
<b>Less Rejects</b>											
Camera Malfunction	Face Camera Flash	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	3-01%
	Face Camera Focus Blurry	0-00%	1-02%	1-02%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	3-01%
	Rear Plate Flash Inappropriate	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate No Flash	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Scene Image Flash Inappropriate	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
<b>Total</b>		2-06%	2-04%	3-05%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	9-02%
<b>Approved Violations</b>		34-94%	51-96%	53-95%	123-100%	27-100%	18-100%	45-96%	185-100%	7-100%	543-98%
<b>Total Notices Printed</b>		34-94%	51-96%	53-95%	123-100%	27-100%	18-100%	45-96%	185-100%	7-100%	543-98%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: TESPANTO

Generated On: 8/6/2014 4:44:25 PM

© Redflex Traffic Systems, Inc.

# Customer Management Report (Baldwin Park) All Detection Types

01-Jun-2014 to 30-Jun-2014

Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUUA-01	BAL-PUWE-01	BAL-PUPA-01	BAL-RAEA-01	BAL-RAEA-03	BAL-RAFR-01	BAL-RAFR-03	TOTAL	
<b>Total Processed Incidents</b>	75	103	156	274	39	70	134	313	4	1168	
<b>Less Uncontrollable Factors</b>											
Obstruction	Driver Obstruction/Duckers	6	2	3	4	5	6	21	6	2	55
	Motor Cycle Helmet	0	0	0	1	0	0	0	1	0	2
	Plate Obstruction	1	1	2	2	0	1	1	2	0	10
	Vehicle Obstruction	1	7	0	5	0	2	4	4	0	23
Police Rejects	Citation Issued manually	0	0	2	1	0	0	1	0	0	4
	Driver Obstruction (PD)	0	0	0	0	0	0	0	1	0	1
	Incorrect/Incomplete DMV	20	29	27	58	7	15	19	76	1	252
	On or Passed the Stop Bar (PD)	0	0	0	2	0	0	0	1	0	3
	Sun Glare	0	1	0	1	0	0	0	0	0	2
Policy/Weather	Extended Vehicle	0	0	0	3	0	1	2	1	0	7
	Sun Glare	1	12	37	40	5	16	33	45	0	189
	Weather/Nature	0	0	1	0	0	0	1	0	0	2
	Yellow with Red Light	0	1	0	0	0	0	0	0	0	1
Registration Issues	Out of Country Plate	0	0	1	0	0	0	0	1	0	2
	Paper Plates	6	1	4	11	2	5	7	17	0	53
<b>Total</b>		35	54	77	128	19	46	89	155	3	606
<b>Sub Total Violations</b>		40	49	79	146	20	24	45	158	1	562
Less in Progress		0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		40	49	79	146	20	24	45	158	1	562
<b>Less Rejects</b>											
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-13%	1-01%	0-00%	7-01%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	2-08%	1-02%	1-01%	0-00%	4-01%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	Too Old	1-02%	0-00%	1-01%	10-07%	1-05%	2-08%	3-07%	14-09%	0-00%	32-06%
<b>Total</b>		1-02%	0-00%	1-01%	11-08%	1-05%	4-17%	11-24%	17-11%	0-00%	46-08%
<b>Approved Violations</b>		39-98%	49-100%	78-99%	135-92%	19-95%	20-83%	34-76%	141-89%	1-100%	516-92%
<b>Total Notices Printed</b>		39-98%	49-100%	78-99%	135-92%	19-95%	20-83%	34-76%	141-89%	1-100%	516-92%

Generated By: TESPANTO

Generated On: 8/6/2014 4:44:48 PM



**Customer Management Report (Baldwin Park) All Detection Types**  
 01-Jun-2014 to 30-Jun-2014 Operator Id: %

TOTAL	BAL-RAFR-03	BAL-RAFR-01	BAL-RABA-03	BAL-RABA-01	BAL-PUPA-01	BAL-PUME-01	BAL-PUDA-01	BAL-FRPU-01	BAL-DAPU-01

Legend: (P) = Production (I) = Inoperative  
 Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Baldwin Park) All Detection Types

01-Jul-2014 to 31-Jul-2014 Operator Id: %

	BAL-DAPU-01	BAL-FRPU-01	BAL-PUDA-01	BAL-PUME-01	BAL-PUPA-01	BAL-RABA-01	BAL-RABA-03	BAL-RAFA-01	BAL-RAFA-03	TOTAL	
<b>Total Processed Incidents</b>	58	103	167	287	75	76	156	343	19	1284	
<b>Less Uncontrollable Factors</b>											
Obstruction	Driver Obstruction/Duckers	7	3	3	14	8	9	23	0	5	72
	Motor Cycle Helmet	0	1	1	0	0	0	2	0	0	4
	Plate Obstruction	0	0	3	3	0	2	2	0	0	10
	Signal Obstruction	0	0	0	0	0	0	0	0	1	1
	Vehicle Obstruction	1	12	3	6	1	1	4	2	0	30
Police Rejects	Citation Issued manually	0	1	0	0	0	0	0	0	0	1
	Incorrect/incomplete DMV	13	16	28	65	14	10	13	97	3	259
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	2	0	0	2
	Sun Glare	1	11	65	38	12	15	55	49	1	247
	Weather/Nature	0	1	2	4	0	0	2	1	0	10
Registration Issues	Out of Country Plate	0	0	0	0	0	0	1	0	0	1
	Paper Plates	3	6	5	14	0	2	5	19	1	55
<b>Total</b>		25	51	110	144	35	39	106	171	11	692
<b>Sub Total Violations</b>		33	52	57	143	40	37	50	172	8	592
Less in Progress		0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		33	52	57	143	40	37	50	172	8	592
<b>Less Rejects</b>											
Camera Malfunction	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	2-06%	0-00%	0-00%	0-00%	0-00%	7-19%	9-18%	0-00%	0-00%	18-03%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
	Rear Plate Flash Inappropriate	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Red-light not visible in	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
<b>Total</b>		3-09%	0-00%	0-00%	1-01%	0-00%	8-22%	9-18%	1-01%	0-00%	22-04%
<b>Approved Violations</b>		30-91%	52-100%	57-100%	142-99%	40-100%	29-78%	41-82%	171-99%	8-100%	570-96%
<b>Total Notices Printed</b>		27-82%	48-92%	51-89%	130-91%	32-80%	27-73%	37-74%	156-91%	8-100%	516-87%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: TESPANTO  
Generated On: 8/6/2014 4:45:19 PM