

# Customer Management Report (Encinitas) All Detection Types

01-Jan-2011 to 31-Jan-2011

Operator Id: %

		ENC-EGEN-01	ENC-ENEC-01	ENC-OIEC-01	TOTAL
<b>Total Processed Incidents</b>		53	355	59	467
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	2	16	5	23
	Motor Cycle Helmet	0	1	0	1
	Plate Obstruction	5	18	0	23
	Vehicle Obstruction	0	17	0	17
Police Rejects	Face Obstruction	0	2	0	2
	Police Discretion	0	2	0	2
	Safe Turn On Red	0	56	0	56
Policy/Weather	Sun Glare	0	9	0	9
Registration Issues	Out of Country Plate	0	1	0	1
	Paper Plates	2	3	0	5
<b>Total</b>		9	125	5	139
<b>Sub Total Violations</b>		44	230	54	328
Less in Progress		0	0	0	0
<b>Available For Prosecution</b>		44	230	54	328
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Flash	0-00%	1-00%	0-00%	1-00%
	Face Camera Focus Blurry	0-00%	2-01%	0-00%	2-01%
	Face Camera No Flash	0-00%	0-00%	2-04%	2-01%
	Face Not in Frame	0-00%	2-01%	8-15%	10-03%
	Misc Camera Issue	0-00%	1-00%	5-09%	6-02%
Police Rejects	Driver Unidentifiable images poor	1-02%	8-03%	0-00%	9-03%
	Plate Unclear	0-00%	1-00%	0-00%	1-00%
	Unclear Scene Image	0-00%	2-01%	0-00%	2-01%
<b>Total</b>		1-02%	17-07%	15-28%	33-10%
<b>Approved Violations</b>		43-98%	213-93%	39-72%	295-90%
<b>Total Notices Printed</b>		43-98%	213-93%	39-72%	295-90%

Generated By: RBLOUGH

Generated On: 10/22/2012 3:24:33 PM

# Customer Management Report (Encinitas) All Detection Types

01-Apr-2011 to 30-Apr-2011

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
<b>Total Processed Incidents</b>		54	241	53	348
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	3	19	2	24
	Plate Obstruction	4	18	0	22
	Vehicle Obstruction	0	6	0	6
Police Rejects	Emergency Vehicle Responding	1	1	0	2
	Face Obstruction	0	1	0	1
	Plate Unidentifiable	0	1	0	1
	Police Discretion	0	1	0	1
	Safe Turn On Red	0	41	1	42
Policy/Weather	Extended Vehicle	0	1	0	1
	Sun Glare	1	29	5	35
	Weather/Nature	0	1	0	1
Registration Issues	Out of Country Plate	0	1	0	1
	Paper Plates	0	8	0	8
	Wrong or No DMV	0	1	0	1
<b>Total</b>		9	129	8	146
<b>Sub Total Violations</b>		45	112	45	202
Less in Progress		0	0	0	0
<b>Available For Prosecution</b>		45	112	45	202
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Focus Blurry	0-00%	1-01%	0-00%	1-00%
	Face Not in Frame	0-00%	1-01%	1-02%	2-01%
	Misc Camera Issue	2-04%	1-01%	0-00%	3-01%
	Plate Burn Out	1-02%	0-00%	0-00%	1-00%
	Plate Not in Frame	0-00%	1-01%	0-00%	1-00%
	Rear Plate Flash Inappropriate	1-02%	1-01%	0-00%	2-01%
Police Rejects	Driver Unidentifiable images poor	1-02%	11-10%	1-02%	13-06%
<b>Total</b>		5-11%	16-14%	2-04%	23-11%
<b>Approved Violations</b>		40-89%	96-86%	43-96%	179-89%
<b>Total Notices Printed</b>		40-89%	96-86%	43-96%	179-89%

Generated By: RBLOUGH

Generated On: 10/22/2012 3:27:37 PM

# Customer Management Report (Encinitas) All Detection Types

01-Jul-2011 to 31-Jul-2011

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OIEC-01	TOTAL
<b>Total Processed Incidents</b>		78	316	32	426
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	1	10	4	15
	Motor Cycle Helmet	0	1	0	1
	Plate Obstruction	6	11	1	18
	Vehicle Obstruction	0	6	0	6
Police Rejects	Emergency Vehicle Responding	0	1	0	1
	Face Obstruction	0	1	0	1
	On or Passed the Stop Bar (PD)	1	0	0	1
	Plate Unidentifiable	1	0	0	1
	Police Discretion	1	3	0	4
	Safe Turn On Red	0	32	0	32
Policy/Weather Registration Issues	Sun Glare	4	69	13	86
	Paper Plates	1	4	2	7
	Wrong or No DMV	0	1	0	1
<b>Total</b>		15	139	20	174
<b>Sub Total Violations</b>		63	177	12	252
Less in Progress		0	0	0	0
<b>Available For Prosecution</b>		63	177	12	252
<b>Less Rejects</b>					
Camera Malfunction Police Rejects	Face Camera Focus Blurry	8-13%	1-01%	0-00%	9-04%
	Driver Unidentifiable images poor	1-02%	6-03%	0-00%	7-03%
	Red-light not visible in	0-00%	0-00%	1-08%	1-00%
	Unclear Scene Image	0-00%	2-01%	0-00%	2-01%
<b>Total</b>		9-14%	9-05%	1-08%	19-08%
<b>Approved Violations</b>		54-86%	168-95%	11-92%	233-92%
<b>Total Notices Printed</b>		54-86%	168-95%	11-92%	233-92%

Generated By: RBLOUGH

Generated On: 10/22/2012 3:28:34 PM

# Customer Management Report (Encinitas) All Detection Types

01-Oct-2011 to 31-Oct-2011

Operator Id: %

		ENC-EGEN-01	ENC-ENECC-01	ENC-OIECC-01	TOTAL
<b>Total Processed Incidents</b>		64	256	55	375
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	2	11	4	17
	Plate Obstruction	2	6	2	10
	Vehicle Obstruction	0	11	1	12
Police Rejects	Emergency Vehicle Responding	2	1	0	3
	Invalid Offense	0	3	0	3
	On or Passed the Stop Bar (PD)	0	0	1	1
	Police Discretion	1	1	1	3
	Safe Turn On Red	0	64	0	64
Policy/Weather	Sun Glare	0	8	2	10
	Weather/Nature	1	3	0	4
Registration Issues	Paper Plates	2	3	0	5
<b>Total</b>		10	111	11	132
<b>Sub Total Violations</b>		54	145	44	243
Less in Progress		0	0	0	0
<b>Available For Prosecution</b>		54	145	44	243
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Focus Blurry	0-00%	1-01%	0-00%	1-00%
	Misc Camera Issue	1-02%	1-01%	0-00%	2-01%
	Plate Not in Frame	1-02%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	5-03%	1-02%	6-02%
	Plate Unclear	0-00%	1-01%	0-00%	1-00%
	Red-light not visible in	0-00%	1-01%	0-00%	1-00%
	Sun Glare	0-00%	1-01%	0-00%	1-00%
	Unclear Scene Image	2-04%	2-01%	0-00%	4-02%
<b>Total</b>		4-07%	12-08%	1-02%	17-07%
<b>Approved Violations</b>		50-93%	133-92%	43-98%	226-93%
<b>Total Notices Printed</b>		50-93%	133-92%	43-98%	226-93%

Generated By: RBLOUGH

Generated On: 10/22/2012 3:29:23 PM

# Customer Management Report (Encinitas) All Detection Types

01-Jan-2012 to 31-Jan-2012

Operator Id: %

		ENC-ECEN-01	ENC-ENECC-01	ENC-OIECC-01	TOTAL
<b>Total Processed Incidents</b>		42	262	40	344
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	1	18	6	25
	Plate Obstruction	2	13	0	15
	Vehicle Obstruction	0	9	1	10
Police Rejects	Funeral Procession/Police	0	1	0	1
	Police Discretion	2	0	0	2
	Safe Turn On Red	0	52	0	52
Policy/Weather	Extended Vehicle	0	1	0	1
	Sun Glare	0	15	4	19
Registration Issues	Paper Plates	1	5	2	8
<b>Total</b>		6	114	13	133
<b>Sub Total Violations</b>		36	148	27	211
Less in Progress		0	0	0	0
<b>Available For Prosecution</b>		36	148	27	211
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Flash	0-00%	0-00%	2-07%	2-01%
	Face Camera Focus Blurry	0-00%	3-02%	0-00%	3-01%
	Face Not in Frame	0-00%	0-00%	1-04%	1-00%
	Misc Camera Issue	0-00%	0-00%	7-26%	7-03%
	Rear Plate Camera Blurry	1-03%	0-00%	0-00%	1-00%
	Scene Image No Flash	1-03%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	20-14%	0-00%	20-09%
	Unclear Scene Image	0-00%	1-01%	1-04%	2-01%
<b>Total</b>		2-06%	24-16%	11-41%	37-18%
<b>Approved Violations</b>		34-94%	124-84%	16-59%	174-82%
<b>Total Notices Printed</b>		34-94%	124-84%	16-59%	174-82%

Generated By: RBLOUGH

Generated On: 10/22/2012 3:30:14 PM

# Customer Management Report (Encinitas) All Detection Types

01-Feb-2012 to 29-Feb-2012

Operator Id: %

		ENC-ECEN-01	ENC-ENECC-01	ENC-OLEC-01	TOTAL
Total Processed Incidents		50	204	45	299
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	0	19	3	22
	Plate Obstruction	4	8	2	14
	Vehicle Obstruction	0	7	0	7
Police Rejects	Emergency Vehicle Responding	4	1	0	5
	Police Discretion	1	1	0	2
	Safe Turn On Red	0	32	0	32
Policy/Weather	Sun Glare	1	27	2	30
	Weather/Nature	0	3	0	3
Registration Issues	Out of Country Plate	0	2	1	3
	Paper Plates	2	5	2	9
Total		12	105	10	127
Sub Total Violations		38	99	35	172
Less in Progress		0	0	0	0
Available For Prosecution		38	99	35	172
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Flash	1-03%	0-00%	0-00%	1-01%
	Face Camera Focus Blurry	0-00%	7-07%	0-00%	7-04%
Police Rejects	Driver Unidentifiable images poor	0-00%	11-11%	0-00%	11-06%
	Red-light not visible in	0-00%	1-01%	0-00%	1-01%
	Unclear Scene Image	1-03%	1-01%	0-00%	2-01%
Process Issues	Too Old	1-03%	0-00%	0-00%	1-01%
Total		3-08%	20-20%	0-00%	23-13%
Approved Violations		35-92%	79-80%	35-100%	149-87%
Total Notices Printed		35-92%	79-80%	35-100%	149-87%

Generated By: RBLOUGH

Generated On: 10/22/2012 3:30:51 PM

# Customer Management Report (Encinitas) All Detection Types

01-Mar-2012 to 31-Mar-2012

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OIEC-01	TOTAL
<b>Total Processed Incidents</b>		56	269	36	361
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	0	14	3	17
	Plate Obstruction	2	17	0	19
	Vehicle Obstruction	1	7	1	9
Police Rejects	Emergency Vehicle Responding	3	1	0	4
	Face Obstruction	0	1	0	1
	Incorrect/Incomplete DMV	0	0	1	1
	Police Discretion	0	0	1	1
	Safe Turn On Red	0	54	0	54
Policy/Weather	Sun Glare	0	32	1	33
	Weather/Nature	0	3	0	3
Registration Issues	Paper Plates	1	7	1	9
	Wrong or No DMV	1	0	0	1
<b>Total</b>		8	136	8	152
<b>Sub Total Violations</b>		48	133	28	209
Less in Progress		0	0	0	0
<b>Available For Prosecution</b>		48	133	28	209
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Focus Blurry	0-00%	4-03%	0-00%	4-02%
	Face Not in Frame	0-00%	1-01%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	5-04%	1-04%	6-03%
	Red-light not visible in	0-00%	1-01%	0-00%	1-00%
	Unclear Scene Image	1-02%	0-00%	0-00%	1-00%
Process Issues	Too Old	0-00%	1-01%	0-00%	1-00%
<b>Total</b>		1-02%	12-09%	1-04%	14-07%
<b>Approved Violations</b>		47-98%	121-91%	27-96%	195-93%
<b>Total Notices Printed</b>		47-98%	121-91%	27-96%	195-93%

Generated By: RBLOUGH

Generated On: 10/22/2012 3:31:44 PM

# Customer Management Report (Encinitas) All Detection Types

01-Apr-2012 to 30-Apr-2012

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
<b>Total Processed Incidents</b>		45	300	43	388
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	3	19	1	23
	Plate Obstruction	1	10	1	12
	Vehicle Obstruction	1	9	0	10
Police Rejects	Emergency Vehicle Responding	1	0	0	1
	On or Passed the Stop Bar (PD)	1	0	0	1
	Safe Turn On Red	0	64	0	64
Policy/Weather	Extended Vehicle	0	1	0	1
	Sun Glare	0	36	2	38
Registration Issues	Out of Country Plate	1	0	0	1
	Paper Plates	0	9	1	10
<b>Total</b>		8	148	5	161
<b>Sub Total Violations</b>		37	152	38	227
Less in Progress		0	0	0	0
<b>Available For Prosecution</b>		37	152	38	227
<b>Less Rejects</b>					
Camera Malfunction	Face Not in Frame	0-00%	0-00%	1-03%	1-00%
	Misc Camera Issue	0-00%	1-01%	0-00%	1-00%
	Plate Burn Out	0-00%	1-01%	0-00%	1-00%
	Rear Plate Camera Blurry	1-03%	0-00%	0-00%	1-00%
	Scene Image Flash Inappropriate	1-03%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	13-09%	0-00%	13-06%
	Unclear Scene Image	0-00%	2-01%	0-00%	2-01%
<b>Total</b>		2-05%	17-11%	1-03%	20-09%
<b>Approved Violations</b>		35-95%	135-89%	37-97%	207-91%
<b>Total Notices Printed</b>		35-95%	135-89%	37-97%	207-91%

Generated By: RBLOUGH

Generated On: 10/22/2012 3:32:12 PM

# Customer Management Report (Encinitas) All Detection Types

01-May-2012 to 31-May-2012

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OLEC-01	TOTAL
<b>Total Processed Incidents</b>		56	286	41	383
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	3	20	6	29
	Plate Obstruction	0	8	0	8
	Vehicle Obstruction	0	12	0	12
Police Rejects	Face Obstruction	0	2	0	2
	On or Passed the Stop Bar (PD).	1	0	0	1
	Safe Turn On Red	0	45	0	45
Policy/Weather	Sun Glare	3	43	5	51
	Weather/Nature	0	1	0	1
Registration Issues	Paper Plates	2	5	1	8
	Wrong or No DMV	1	0	0	1
<b>Total</b>		10	136	12	158
<b>Sub Total Violations</b>		46	150	29	225
Less in Progress		0	0	0	0
<b>Available For Prosecution</b>		46	150	29	225
<b>Less Rejects</b>					
Camera Malfunction	Misc Camera Issue	1-02%	1-01%	0-00%	2-01%
Police Rejects	Driver Unidentifiable images poor	1-02%	13-09%	1-03%	15-07%
	Unclear Scene Image	0-00%	0-00%	1-03%	1-00%
Process Issues	Too Old	1-02%	1-01%	0-00%	2-01%
<b>Total</b>		3-07%	15-10%	2-07%	20-09%
<b>Approved Violations</b>		43-93%	135-90%	27-93%	205-91%
<b>Total Notices Printed</b>		43-93%	135-90%	27-93%	205-91%

Generated By: RBLOUGH

Generated On: 10/22/2012 3:32:37 PM

# Customer Management Report (Encinitas) All Detection Types

01-Jun-2012 to 30-Jun-2012

Operator Id: %

	ENC-ECEN-01	ENC-ENEC-01	ENC-OIEC-01	TOTAL
<b>Total Processed Incidents</b>	58	280	49	387
<b>Less Uncontrollable Factors</b>				
Obstruction				
Driver Obstruction/Duckers	1	19	5	25
Plate Obstruction	1	9	1	11
Vehicle Obstruction	1	8	0	9
Police Rejects				
Invalid Offense	0	2	0	2
Safe Turn On Red	0	57	0	57
Policy/Weather				
Extended Vehicle	0	2	0	2
Sun Glare	4	39	7	50
Registration Issues				
Paper Plates	1	6	4	11
<b>Total</b>	<b>8</b>	<b>142</b>	<b>17</b>	<b>167</b>
<b>Sub Total Violations</b>	<b>50</b>	<b>138</b>	<b>32</b>	<b>220</b>
Less in Progress	0	0	0	0
<b>Available For Prosecution</b>	<b>50</b>	<b>138</b>	<b>32</b>	<b>220</b>
<b>Less Rejects</b>				
Camera Malfunction				
Image Missing	1-02%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	1-01%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	1-01%	0-00%	1-00%
Police Rejects				
Driver Unidentifiable images poor	0-00%	8-06%	3-09%	11-05%
Unclear Scene Image	0-00%	1-01%	0-00%	1-00%
Process Issues				
Too Old	0-00%	3-02%	0-00%	3-01%
<b>Total</b>	<b>1-02%</b>	<b>14-10%</b>	<b>3-09%</b>	<b>18-08%</b>
<b>Approved Violations</b>	<b>49-98%</b>	<b>124-90%</b>	<b>29-91%</b>	<b>202-92%</b>
<b>Total Notices Printed</b>	<b>49-98%</b>	<b>124-90%</b>	<b>29-91%</b>	<b>202-92%</b>

Generated By: RBLOUGH

Generated On: 10/22/2012 3:33:04 PM

# Customer Management Report (Encinitas) All Detection Types

01-Jul-2012 to 31-Jul-2012

Operator Id: %

		ENC-ECEN-01	ENC-ENECC-01	ENC-OIEC-01	TOTAL
<b>Total Processed Incidents</b>		68	241	33	342
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	1	11	0	12
	Plate Obstruction	2	8	0	10
	Vehicle Obstruction	1	9	0	10
Police Rejects	Emergency Vehicle Responding	0	2	0	2
	On or Passed the Stop Bar (PD)	1	0	0	1
	Police Discretion	2	1	0	3
	Safe Turn On Red	0	43	0	43
Policy/Weather	Extended Vehicle	0	1	0	1
	Sun Glare	3	42	6	51
	Yellow with Red Light	0	1	0	1
Registration Issues	Out of Country Plate	0	1	0	1
	Paper Plates	0	4	1	5
<b>Total</b>		10	123	7	140
<b>Sub Total Violations</b>		58	118	26	202
Less in Progress		0	0	0	0
<b>Available For Prosecution</b>		58	118	26	202
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Flash	1-02%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	1-04%	1-00%
	Misc Camera Issue	1-02%	0-00%	0-00%	1-00%
	Plate Not in Frame	1-02%	0-00%	0-00%	1-00%
	Rear Plate Camera Blurry	0-00%	1-01%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	14-12%	1-04%	15-07%
	Unclear Scene Image	0-00%	0-00%	1-04%	1-00%
Process Issues	Too Old	0-00%	1-01%	0-00%	1-00%
<b>Total</b>		3-05%	16-14%	3-12%	22-11%
<b>Approved Violations</b>		55-95%	102-86%	23-88%	180-89%
<b>Total Notices Printed</b>		55-95%	102-86%	23-88%	180-89%

Generated By: RBLOUGH

Generated On: 10/22/2012 3:33:43 PM

# Customer Management Report (Encinitas) All Detection Types

01-Aug-2012 to 31-Aug-2012

Operator Id: %

		ENC-ECEN-01	ENC-ENEC-01	ENC-OIEC-01	TOTAL
<b>Total Processed Incidents</b>		64	281	42	387
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	1	16	1	18
	Plate Obstruction	3	6	0	9
	Vehicle Obstruction	0	9	0	9
Police Rejects	Emergency Vehicle Responding	4	1	0	5
	Face Obstruction	0	1	0	1
	Safe Turn On Red	0	27	0	27
Policy/Weather	Sun Glare	2	26	3	31
Registration Issues	Paper Plates	1	10	1	12
<b>Total</b>		11	96	5	112
<b>Sub Total Violations</b>		53	185	37	275
Less in Progress		0	0	0	0
<b>Available For Prosecution</b>		53	185	37	275
<b>Less Rejects</b>					
Camera Malfunction	Digital Distortion	1-02%	0-00%	0-00%	1-00%
	Face Camera Flash	0-00%	4-02%	0-00%	4-01%
	Face Camera No Flash	0-00%	2-01%	0-00%	2-01%
	Face Not in Frame	1-02%	1-01%	1-03%	3-01%
	Plate Burn Out	0-00%	2-01%	0-00%	2-01%
	Rear Plate Flash Inappropriate	1-02%	0-00%	0-00%	1-00%
Police Rejects Process Issues	Driver Unidentifiable images poor	0-00%	40-22%	1-03%	41-15%
	Too Old	1-02%	0-00%	0-00%	1-00%
<b>Total</b>		4-08%	49-26%	2-05%	55-20%
<b>Approved Violations</b>		49-92%	136-74%	35-95%	220-80%
<b>Total Notices Printed</b>		49-92%	136-74%	35-95%	220-80%

Generated By: RBLOUGH

Generated On: 10/22/2012 3:34:16 PM

# Customer Management Report (Encinitas) All Detection Types

01-Sep-2012 to 30-Sep-2012

Operator Id: %

		ENC-EEN-01	ENC-ENEC-01	ENC-OIEC-01	TOTAL
<b>Total Processed Incidents</b>		36	265	56	357
<b>Less Uncontrollable Factors</b>					
Obstruction	Driver Obstruction/Duckers	2	12	7	21
	Plate Obstruction	1	19	1	21
	Vehicle Obstruction	0	4	1	5
Police Rejects	Emergency Vehicle Responding	0	1	0	1
	Face Obstruction	0	1	0	1
	Safe Turn On Red	0	43	0	43
	Yielding to an Emergency	0	1	0	1
Policy/Weather	Extended Vehicle	0	1	1	2
	Sun Glare	1	29	2	32
Registration Issues	Paper Plates	1	5	1	7
<b>Total</b>		5	116	13	134
<b>Sub Total Violations</b>		31	149	43	223
Less in Progress		0	0	0	0
<b>Available For Prosecution</b>		31	149	43	223
<b>Less Rejects</b>					
Camera Malfunction	Face Camera Flash	0-00%	0-00%	1-02%	1-00%
	Face Not in Frame	0-00%	1-01%	1-02%	2-01%
	Image Missing	0-00%	1-01%	0-00%	1-00%
	Rear Plate Flash Inappropriate	1-03%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	26-17%	0-00%	26-12%
<b>Total</b>		1-03%	28-19%	2-05%	31-14%
<b>Approved Violations</b>		30-97%	121-81%	41-95%	192-86%
<b>Total Notices Printed</b>		30-97%	121-81%	41-95%	192-86%

Generated By: RBLOUGH

Generated On: 10/22/2012 3:35:52 PM