

# Customer Management Report (Oceanside) Redlight Incidents

01-Dec-2004 to 31-Dec-2004

Operator Id: %

		OSC-COOC-01	OSC-MICA-01	OSC-MICA-03	OSC-OCOC-01	TOTAL
<b>Total Violations</b>		<b>359</b>	<b>200</b>	<b>203</b>	<b>132</b>	<b>894</b>
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	15	12	2	1	30
	Plate Obstruction	2	10	9	0	21
	Signal Obstruction	0	0	1	0	1
	Vehicle Obstruction	0	0	4	0	4
Police Rejects	Driver Unidentifiable	9	4	7	2	22
	Gender Mismatch	0	0	1	1	2
	Invalid Offense	3	2	2	2	9
	Safe Turn On Red	99	3	16	3	121
Policy/Weather	Sun Glare	8	1	4	2	15
	Weather/Nature	0	0	1	0	1
Registration Issues	Can Not Identify State	0	0	1	0	1
	Out of Country Plate	0	0	2	0	2
	Paper Plates	13	3	4	2	22
	Wrong or No DMV	13	0	5	0	18
<b>Total</b>		<b>162</b>	<b>35</b>	<b>59</b>	<b>13</b>	<b>269</b>
<b>Sub Total Violations</b>		<b>197</b>	<b>165</b>	<b>144</b>	<b>119</b>	<b>625</b>
Less in Progress		0	0	0	0	0
<b>Available For Prosecution</b>		<b>197</b>	<b>165</b>	<b>144</b>	<b>119</b>	<b>625</b>
<b>Less Rejects</b>						
Camera Malfunction	Digital Distortion	4-02%	0-00%	0-00%	40-34%	44-07%
	Face Camera Flash	22-11%	4-02%	4-03%	4-03%	34-05%
	Face Camera Focus Blurry	3-02%	33-20%	4-03%	1-01%	41-07%
	Face Not in Frame	3-02%	4-02%	0-00%	0-00%	7-01%
	Image Missing	1-01%	0-00%	0-00%	1-01%	2-00%

	Misc Camera Issue	0-00%	80-48%	0-00%	14-12%	94-15%
	Plate Burn Out	1-01%	3-02%	0-00%	0-00%	4-01%
	Plate Not in Frame	1-01%	1-01%	4-03%	0-00%	6-01%
	Rear Plate Camera Blurry	1-01%	0-00%	7-05%	0-00%	8-01%
	Scene Image No Flash	45-23%	0-00%	31-22%	32-27%	108-17%
Police Rejects	Plate Unclear	3-02%	0-00%	0-00%	0-00%	3-00%
Total		84-43%	125-76%	50-35%	92-77%	351-56%
<b>Notices Printed</b>		<b>113-57%</b>	<b>40-24%</b>	<b>94-65%</b>	<b>27-23%</b>	<b>274-44%</b>