

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Nov-2017 to 30-Nov-2017

Operator Id: %

		RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
<b>Total Processed Incidents</b>		671	833	162	401	2067
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	20	125	3	13	161
	Motor Cycle Helmet	0	1	0	0	1
	Plate Obstruction	20	18	6	7	51
	Vehicle Obstruction	5	39	7	12	63
Police Rejects	Emergency Vehicle Responding	1	6	5	4	16
	Incorrect/Incomplete DMV	7	8	0	5	20
	Invalid Offense	2	2	1	2	7
	Multiple vehicles in frame	0	1	0	0	1
	On or Passed the Stop Bar (PD).	160	41	4	89	294
	Police Discretion	33	43	3	32	111
	Safe Turn On Red	0	1	0	0	1
	Sun Glare	0	2	0	0	2
	Policy/Weather	Extended Vehicle	0	7	0	2
Sun Glare		22	43	4	9	78
Weather-Blocked Glass		0	2	0	0	2
Weather/Nature		2	12	3	3	20
Registration Issues	Paper Plates	40	29	6	26	101
	Wrong or No DMV	2	2	0	0	4
<b>Total</b>		314	382	42	204	942
<b>Sub Total Violations</b>		357	451	120	197	1125
Less in Progress		0	0	0	0	0
<b>Available For Prosecution</b>		357	451	120	197	1125
<b>Less Rejects</b>						
Camera Malfunction	Face Camera Flash	0-00%	0-00%	1-01%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	1-01%	0-00%	1-00%
	Image Missing	0-00%	4-01%	0-00%	0-00%	4-00%
	Plate Burn Out	13-04%	0-00%	0-00%	0-00%	13-01%
	Plate Not in Frame	0-00%	2-00%	0-00%	0-00%	2-00%
	Rear Plate Camera Blurry	4-01%	0-00%	0-00%	0-00%	4-00%
	Rear Plate Flash Inappropriate	10-03%	1-00%	0-00%	0-00%	11-01%
	Rear Plate No Flash	1-00%	1-00%	0-00%	0-00%	2-00%
	Scene Image Flash Inappropriate	0-00%	1-00%	0-00%	3-02%	4-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	3-02%	3-00%
Video Not In Sync	0-00%	1-00%	0-00%	0-00%	1-00%	

Generated By: MFONTES

Generated On: 12/8/2017 9:54:26 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Nov-2017 to 30-Nov-2017

Operator Id: %

		RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
Police	Driver Unidentifiable images poor	0-00%	4-01%	1-01%	4-02%	9-01%
Rejects	Plate Unclear	1-00%	0-00%	0-00%	0-00%	1-00%
	Red-light not visible in	1-00%	0-00%	0-00%	0-00%	1-00%
	Unclear Scene Image	0-00%	2-00%	0-00%	0-00%	2-00%
Total		30-08%	16-04%	3-02%	10-05%	59-05%
<b>Approved Violations</b>		<b>327-92%</b>	<b>435-96%</b>	<b>117-98%</b>	<b>187-95%</b>	<b>1066-95%</b>
<b>Total Notices Printed</b>		<b>327-92%</b>	<b>435-96%</b>	<b>117-98%</b>	<b>187-95%</b>	<b>1066-95%</b>

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MFONTES

Generated On: 12/8/2017 9:54:26 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Dec-2017 to 31-Dec-2017

Operator Id: %

		RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
<b>Total Processed Incidents</b>		609	734	214	376	1933
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	18	98	10	20	146
	Motor Cycle Helmet	0	1	1	1	3
	Plate Obstruction	25	12	4	4	45
	Vehicle Obstruction	5	18	5	6	34
Police Rejects	Emergency Vehicle Responding	2	2	10	3	17
	Incorrect/Incomplete DMV	10	7	4	4	25
	Invalid Offense	0	1	0	0	1
	Multiple vehicles in frame	0	1	0	1	2
	On or Passed the Stop Bar (PD).	185	69	7	89	350
	Police Discretion	14	8	1	9	32
	Yielding to an Emergency	0	0	1	0	1
Policy/Weather	Extended Vehicle	0	11	5	3	19
	Sun Glare	7	26	3	6	42
	Weather/Nature	2	4	0	0	6
Registration Issues	Can Not Identify State	1	0	0	0	1
	Out of Country Plate	0	0	1	0	1
	Paper Plates	40	31	8	25	104
<b>Total</b>		309	289	60	171	829
<b>Sub Total Violations</b>		300	445	154	205	1104
Less in Progress		0	0	0	0	0
<b>Available For Prosecution</b>		300	445	154	205	1104
<b>Less Rejects</b>						
Camera Malfunction	Face Camera Flash	0-00%	2-00%	1-01%	0-00%	3-00%
	Face Camera No Flash	2-01%	0-00%	0-00%	0-00%	2-00%
	Face Not in Frame	0-00%	0-00%	0-00%	2-01%	2-00%
	Image Missing	0-00%	3-01%	2-01%	0-00%	5-00%
	Plate Burn Out	1-00%	0-00%	0-00%	2-01%	3-00%
	Rear Plate Camera Blurry	0-00%	1-00%	0-00%	0-00%	1-00%
	Rear Plate Flash Inappropriate	3-01%	0-00%	0-00%	0-00%	3-00%
	Scene Image Flash Inappropriate	3-01%	0-00%	0-00%	0-00%	3-00%
Scene Image No Flash	0-00%	1-00%	0-00%	0-00%	1-00%	
Police Rejects	Driver Unidentifiable images poor	0-00%	3-01%	0-00%	0-00%	3-00%
	Unclear Scene Image	1-00%	0-00%	0-00%	0-00%	1-00%
	Video Malfunction	0-00%	0-00%	1-01%	0-00%	1-00%

Generated By: MFONTES

Generated On: 1/5/2018 2:26:09 PM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Dec-2017 to 31-Dec-2017

Operator Id: %

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
Process Too Old Issues	5-02%	7-02%	2-01%	6-03%	20-02%
Total	15-05%	17-04%	6-04%	10-05%	48-04%
Approved Violations	285-95%	428-96%	148-96%	195-95%	1056-96%
Total Notices Printed	266-89%	399-90%	140-91%	174-85%	979-89%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MFONTES

Generated On: 1/5/2018 2:26:09 PM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Jan-2018 to 31-Jan-2018

Operator Id: %

		RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
<b>Total Processed Incidents</b>		547	747	206	399	1899
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	15	112	6	18	151
	Motor Cycle Helmet	0	1	0	1	2
	Plate Obstruction	30	22	10	5	67
	Vehicle Obstruction	7	18	3	5	33
Police Rejects	Citation Issued manually	1	0	0	0	1
	Emergency Vehicle Responding	1	8	16	3	28
	Incorrect Plate on Vehicle	1	0	0	0	1
	Incorrect/Incomplete DMV	2	12	2	7	23
	Multiple vehicles in frame	0	1	0	0	1
	On or Passed the Stop Bar (PD).	162	54	2	110	328
	Police Discretion	18	22	7	20	67
	Safe Turn On Red	1	0	0	0	1
	Policy/Weather	Extended Vehicle	2	6	2	2
	Sun Glare	4	23	5	10	42
	Weather/Nature	2	8	5	10	25
Registration Issues	Paper Plates	30	35	6	21	92
	Wrong or No DMV	0	0	0	1	1
<b>Total</b>		276	322	64	213	875
<b>Sub Total Violations</b>		271	425	142	186	1024
Less in Progress		0	0	0	0	0
<b>Available For Prosecution</b>		271	425	142	186	1024
<b>Less Rejects</b>						
Camera Malfunction	Face Not in Frame	0-00%	0-00%	2-01%	1-01%	3-00%
	Image Missing	0-00%	0-00%	2-01%	0-00%	2-00%
	Rear Plate Camera Blurry	1-00%	1-00%	0-00%	0-00%	2-00%
	Rear Plate Flash Inappropriate	1-00%	1-00%	0-00%	0-00%	2-00%
	Scene Image Flash Inappropriate	1-00%	0-00%	0-00%	0-00%	1-00%
	Scene Image No Flash	1-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	3-01%	1-01%	0-00%	4-00%
	Unclear Scene Image	0-00%	1-00%	1-01%	0-00%	2-00%
	Video Malfunction	0-00%	0-00%	1-01%	0-00%	1-00%
<b>Total</b>		4-01%	6-01%	7-05%	1-01%	18-02%
<b>Approved Violations</b>		267-99%	419-99%	135-95%	185-99%	1006-98%

Generated By: MFONTES

Generated On: 6/26/2018 8:53:18 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Jan-2018 to 31-Jan-2018

Operator Id: %

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
Total Notices Printed	267-99%	419-99%	135-95%	185-99%	1006-98%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MFONTES

Generated On: 6/26/2018 8:53:18 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Feb-2018 to 28-Feb-2018

Operator Id: %

		RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
<b>Total Processed Incidents</b>		625	615	195	318	1753
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	13	89	4	8	114
	Plate Obstruction	17	11	2	3	33
	Vehicle Obstruction	11	16	4	12	43
Police Rejects	Emergency Vehicle Responding	1	6	10	7	24
	Gender Mismatch	0	0	0	1	1
	Incorrect/Incomplete DMV	7	6	2	0	15
	Invalid Offense	0	1	0	1	2
	On or Passed the Stop Bar (PD).	184	45	2	70	301
	Police Discretion	36	19	1	18	74
	Safe Turn On Red	1	0	0	0	1
	Sun Glare	0	0	1	0	1
	Policy/Weather	Extended Vehicle	1	3	6	3
	Sun Glare	8	24	9	3	44
	Weather/Nature	1	4	0	0	5
Registration Issues	Paper Plates	41	32	13	18	104
	Wrong or No DMV	2	1	0	0	3
<b>Total</b>		323	257	54	144	778
<b>Sub Total Violations</b>		302	358	141	174	975
Less in Progress		0	0	0	0	0
<b>Available For Prosecution</b>		302	358	141	174	975
<b>Less Rejects</b>						
Camera Malfunction	Face Camera Flash	0-00%	2-01%	0-00%	0-00%	2-00%
	Face Not in Frame	0-00%	0-00%	2-01%	1-01%	3-00%
	Image Missing	0-00%	0-00%	3-02%	0-00%	3-00%
	Plate Burn Out	1-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-01%	1-00%
	Rear Plate No Flash	1-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	1-00%	1-00%	0-00%	0-00%	2-00%
<b>Total</b>		3-01%	3-01%	5-04%	2-01%	13-01%
<b>Approved Violations</b>		299-99%	355-99%	136-96%	172-99%	962-99%
<b>Total Notices Printed</b>		299-99%	355-99%	136-96%	172-99%	962-99%

Generated By: MFONTES

Generated On: 6/26/2018 8:54:18 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Feb-2018 to 28-Feb-2018

Operator Id: %

---

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
--	-------------	-------------	-------------	-------------	-------

---

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MFONTES

Generated On: 6/26/2018 8:54:18 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Mar-2018 to 31-Mar-2018

Operator Id: %

		RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
<b>Total Processed Incidents</b>		482	788	200	447	1917
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	10	90	5	15	120
	Motor Cycle Helmet	1	0	0	0	1
	Plate Obstruction	17	22	3	11	53
	Vehicle Obstruction	11	33	5	10	59
Police Rejects	Emergency Vehicle Responding	5	11	7	6	29
	Incorrect/Incomplete DMV	5	16	1	9	31
	Invalid Offense	0	1	0	4	5
	On or Passed the Stop Bar (PD).	142	57	5	117	321
	Police Discretion	8	17	1	13	39
	Sun Glare	0	2	0	1	3
	Yielding to an Emergency	0	1	0	0	1
Policy/Weather	Extended Vehicle	1	8	5	3	17
	Sun Glare	14	34	5	10	63
	Weather/Nature	1	9	4	8	22
Registration Issues	Paper Plates	29	38	11	29	107
	Wrong or No DMV	2	0	0	0	2
<b>Total</b>		246	339	52	236	873
<b>Sub Total Violations</b>		236	449	148	211	1044
Less in Progress		0	0	0	0	0
<b>Available For Prosecution</b>		236	449	148	211	1044
<b>Less Rejects</b>						
Camera Malfunction	Face Camera Flash	0-00%	2-00%	0-00%	0-00%	2-00%
	Face Camera No Flash	1-00%	0-00%	0-00%	0-00%	1-00%
	Image Missing	0-00%	3-01%	3-02%	0-00%	6-01%
	Plate Burn Out	2-01%	0-00%	0-00%	0-00%	2-00%
	Rear Plate Flash Inappropriate	1-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate No Flash	0-00%	1-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	4-01%	0-00%	0-00%	4-00%
<b>Total</b>		4-02%	10-02%	3-02%	0-00%	17-02%
<b>Approved Violations</b>		232-98%	439-98%	145-98%	211-100%	1027-98%
<b>Total Notices Printed</b>		232-98%	439-98%	145-98%	211-100%	1027-98%

Generated By: MFONTES

Generated On: 6/26/2018 8:54:54 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Mar-2018 to 31-Mar-2018

Operator Id: %

---

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
--	-------------	-------------	-------------	-------------	-------

---

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MFONTES

Generated On: 6/26/2018 8:54:54 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Apr-2018 to 30-Apr-2018

Operator Id: %

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL	
<b>Total Processed Incidents</b>	540	752	211	423	1926	
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	15	93	5	17	130
	Motor Cycle Helmet	2	3	0	0	5
	Plate Obstruction	14	16	5	7	42
	Vehicle Obstruction	4	27	5	7	43
Police Rejects	Emergency Vehicle Responding	0	4	6	4	14
	Incorrect Plate on Vehicle	1	0	0	0	1
	Incorrect/Incomplete DMV	8	8	0	14	30
	Invalid Offense	1	0	0	0	1
	On or Passed the Stop Bar (PD).	133	66	3	109	311
	Police Discretion	17	19	1	22	59
	Sun Glare	0	2	0	0	2
	Yielding to an Emergency	0	0	0	1	1
Policy/Weather	Extended Vehicle	2	13	0	4	19
	Sun Glare	24	48	9	15	96
	Weather/Nature	8	9	3	1	21
Registration Issues	Out of Country Plate	0	1	0	0	1
	Paper Plates	28	35	6	22	91
	Wrong or No DMV	0	0	1	0	1
<b>Total</b>		257	344	44	223	868
<b>Sub Total Violations</b>		283	408	167	200	1058
Less in Progress		0	0	0	0	0
<b>Available For Prosecution</b>		283	408	167	200	1058
<b>Less Rejects</b>						
Camera Malfunction	Face Camera Focus Blurry	0-00%	0-00%	6-04%	0-00%	6-01%
	Image Missing	0-00%	3-01%	6-04%	0-00%	9-01%
	Misc Camera Issue	0-00%	1-00%	0-00%	1-00%	2-00%
Police Rejects	Driver Unidentifiable images poor	1-00%	1-00%	0-00%	5-02%	7-01%
<b>Total</b>		1-00%	5-01%	12-07%	6-03%	24-02%
<b>Approved Violations</b>		282-100%	403-99%	155-93%	194-97%	1034-98%
<b>Total Notices Printed</b>		282-100%	403-99%	155-93%	194-97%	1034-98%

Generated By: MFONTES

Generated On: 6/26/2018 8:55:23 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-Apr-2018 to 30-Apr-2018

Operator Id: %

---

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
--	-------------	-------------	-------------	-------------	-------

---

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MFONTES

Generated On: 6/26/2018 8:55:23 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-May-2018 to 31-May-2018

Operator Id: %

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL	
<b>Total Processed Incidents</b>	212	785	206	456	1659	
<b>Less Uncontrollable Factors</b>						
Obstruction	Driver Obstruction/Duckers	7	110	8	16	141
	Motor Cycle Helmet	1	1	0	1	3
	Plate Obstruction	5	23	3	8	39
	Vehicle Obstruction	2	28	3	5	38
Police Rejects	Emergency Vehicle Responding	0	1	6	2	9
	Incorrect/Incomplete DMV	1	6	1	1	9
	Invalid Offense	0	1	1	1	3
	Multiple vehicles in frame	0	5	0	0	5
	On or Passed the Stop Bar (PD).	29	54	2	89	174
	Police Discretion	11	17	0	24	52
Policy/Weather	Extended Vehicle	0	12	5	7	24
	Sun Glare	2	43	9	28	82
	Weather/Nature	0	10	0	3	13
Registration Issues	Paper Plates	16	32	9	29	86
	Wrong or No DMV	0	1	0	1	2
<b>Total</b>		74	344	47	215	680
<b>Sub Total Violations</b>		138	441	159	241	979
Less in Progress		0	0	0	0	0
<b>Available For Prosecution</b>		138	441	159	241	979
<b>Less Rejects</b>						
Camera Malfunction	Face Camera Flash	0-00%	3-01%	0-00%	0-00%	3-00%
	Face Not in Frame	0-00%	0-00%	1-01%	0-00%	1-00%
	Image Missing	0-00%	1-00%	7-04%	0-00%	8-01%
	Misc Camera Issue	0-00%	0-00%	0-00%	1-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	1-01%	2-00%	0-00%	1-00%	4-00%
	Unclear Scene Image	0-00%	0-00%	1-01%	0-00%	1-00%
	Video Malfunction	0-00%	0-00%	0-00%	1-00%	1-00%
<b>Total</b>		1-01%	6-01%	9-06%	3-01%	19-02%
<b>Approved Violations</b>		137-99%	435-99%	150-94%	238-99%	960-98%
<b>Total Notices Printed</b>		137-99%	435-99%	150-94%	238-99%	960-98%

Generated By: MFONTES

Generated On: 6/26/2018 8:55:46 AM

# Customer Management Report (Rancho Cordova, CA) All Detection Types

01-May-2018 to 31-May-2018

Operator Id: %

---

	RCO-SUCO-01	RCO-SUFO-01	RCO-ZIOL-01	RCO-ZIWR-01	TOTAL
--	-------------	-------------	-------------	-------------	-------

---

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MFONTES

Generated On: 6/26/2018 8:55:46 AM