

Customer Management Report (San Mateo) All Detection Types

01-Dec-2016 to 31-Dec-2016

Operator Id: %

		SAN-4HU-01(P)	SAN-HINO-01(P)	SAN-HINO-03(P)	SAN-HISA-01(P)	SAN-SAHI-01(P)	TOTAL
Total Processed Incidents		119	65	110	96	1036	1426
Less Uncontrollable Factors							
Obstruction	Driver Obstruction/Duckers	2	4	3	2	41	52
	Plate Obstruction	3	1	7	1	7	19
	Vehicle Obstruction	4	2	4	2	69	81
Police Rejects	Emergency Vehicle Responding	4	0	0	0	5	9
	Incorrect Plate on Vehicle	0	0	0	0	1	1
	Incorrect/Incomplete DMV	0	0	0	0	5	5
	Multiple vehicles in frame	0	0	1	0	12	13
	On or Passed the Stop Bar (PD).	6	7	48	7	486	554
	Plate Unidentifiable	1	0	0	0	1	2
	Slow Roll - right turn	1	0	0	0	14	15
	Sun Glare	1	0	1	0	0	2
	Weather Conditions	0	0	0	0	1	1
	Policy/Weather	Extended Vehicle	0	0	0	0	1
Sun Glare		0	3	0	0	10	13
Weather/Nature		0	0	0	0	4	4
Registration Issues	Out of Country Plate	0	0	1	0	0	1
	Paper Plates	7	3	5	2	33	50
	Wrong or No DMV	0	1	0	0	1	2
Total	29	21	70	14	691	825	
Sub Total Violations		90	44	40	82	345	601
Less in Progress		0	0	0	0	0	0
Available For Prosecution		90	44	40	82	345	601
Less Rejects							
Camera Malfunction Police Rejects	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Driver Unidentifiable images poor	3-03%	6-14%	2-05%	2-02%	12-03%	25-04%
	No Images	0-00%	0-00%	1-02%	0-00%	2-01%	3-00%
	No Video	0-00%	0-00%	0-00%	1-01%	4-01%	5-01%
	Red-light not visible in	0-00%	2-05%	1-02%	0-00%	0-00%	3-00%
Process Issues	Too Old	2-02%	0-00%	1-02%	3-04%	6-02%	12-02%
Total		5-06%	8-18%	5-12%	6-07%	25-07%	49-08%
Approved Violations		85-94%	36-82%	35-88%	76-93%	320-93%	552-92%
Total Notices Printed		85-94%	36-82%	35-88%	76-93%	320-93%	552-92%

Generated By: SHAGAN

Generated On: 2/21/2017 4:08:32 PM

Customer Management Report (San Mateo) All Detection Types

01-Dec-2016 to 31-Dec-2016

Operator Id: %

TOTAL	SAN-SAHI-01(P)	SAN-HISA-01(P)	SAN-HINO-03(P)	SAN-HINO-01(P)	SAN-4HU-01(P)
-------	----------------	----------------	----------------	----------------	---------------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SHAGAN

Generated On: 2/21/2017 4:08:32 PM

Customer Management Report (San Mateo) All Detection Types

01-Jan-2016 to 31-Dec-2016

Operator Id: %

		SAN-4HU-01(P)	SAN-HINO-01(P)	SAN-HINO-03(P)	SAN-HISA-01(P)	SAN-SAHI-01(P)	TOTAL
Total Processed Incidents		1522	487	1384	746	11578	15717
Less Uncontrollable Factors							
Obstruction	Driver Obstruction/Duckers	60	9	60	12	266	407
	Motor Cycle Helmet	7	0	0	0	4	11
	Plate Obstruction	25	11	29	10	72	147
	Signal Obstruction	0	0	0	0	2	2
	Vehicle Obstruction	31	9	62	7	663	772
Police Rejects	Citation Issued manually	0	0	0	0	1	1
	Emergency Vehicle Responding	61	21	10	10	65	167
	Gender Mismatch	0	0	0	0	4	4
	Incorrect Plate on Vehicle	0	0	1	0	1	2
	Incorrect/Incomplete DMV	2	1	2	2	17	24
	Invalid Offense	0	3	0	0	1	4
	Multiple vehicles in frame	0	0	7	2	207	216
	On or Passed the Stop Bar (PD).	103	61	429	48	4588	5229
	Plate Obstruction (PD)	0	0	0	1	1	2
	Plate Unidentifiable	3	0	3	0	11	17
	Slow Roll - right turn	1	0	10	0	360	371
	Sun Glare	5	0	2	0	4	11
	Weather Conditions	0	0	0	0	1	1
	Policy/Weather	Extended Vehicle	11	2	2	5	6
Sun Glare		129	35	15	102	229	510
Weather/Nature		11	3	3	10	59	86
Registration Issues	Out of Country Plate	0	1	1	1	3	6
	Paper Plates	51	17	54	32	384	538
	Wrong or No DMV	0	1	1	0	8	10
Total	500	174	691	242	6957	8564	
Sub Total Violations		1022	313	693	504	4621	7153
Less in Progress		0	0	0	0	0	0
Available For Prosecution		1022	313	693	504	4621	7153
Less Rejects							
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	2-00%	6-00%	8-00%
	Face Camera Focus Blurry	13-01%	0-00%	0-00%	16-03%	3-00%	32-00%
	Face Camera No Flash	0-00%	0-00%	0-00%	1-00%	0-00%	1-00%
	Face Not in Frame	23-02%	0-00%	0-00%	4-01%	1-00%	28-00%
	Image Missing	2-00%	0-00%	6-01%	0-00%	35-01%	43-01%
	Misc Camera Issue	0-00%	0-00%	0-00%	4-01%	8-00%	12-00%

Generated By: SHAGAN

Generated On: 2/21/2017 4:11:38 PM

Customer Management Report (San Mateo) All Detection Types

01-Jan-2016 to 31-Dec-2016

Operator Id: %

	SAN-4HU-01(P)	SAN-HINO-01(P)	SAN-HINO-03(P)	SAN-HISA-01(P)	SAN-SAHI-01(P)	TOTAL
Plate Burn Out	1-00%	0-00%	1-00%	0-00%	2-00%	4-00%
Plate Not in Frame	1-00%	0-00%	0-00%	0-00%	1-00%	2-00%
Rear Plate Camera Blurry	0-00%	5-02%	1-00%	0-00%	4-00%	10-00%
Rear Plate Flash Inappropriate	0-00%	2-01%	0-00%	0-00%	2-00%	4-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	2-00%	2-00%
Scene Image No Flash	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%
Test Pattern	21-02%	1-00%	6-01%	0-00%	55-01%	83-01%
Video Not In Sync	0-00%	1-00%	0-00%	0-00%	0-00%	1-00%
Video Skips	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Police Rejects						
Driver Unidentifiable images poor	57-06%	15-05%	15-02%	54-11%	153-03%	294-04%
Insufficient Strobe Lighting	0-00%	0-00%	2-00%	0-00%	18-00%	20-00%
No Images	0-00%	0-00%	1-00%	0-00%	2-00%	3-00%
No Video	1-00%	1-00%	1-00%	2-00%	36-01%	41-01%
Red-light not visible in	0-00%	3-01%	1-00%	0-00%	0-00%	4-00%
Unclear Scene Image	1-00%	0-00%	1-00%	0-00%	1-00%	3-00%
Process Issues						
Too Old	65-06%	23-07%	59-09%	37-07%	750-16%	934-13%
Total	185-18%	51-16%	95-14%	120-24%	1080-23%	1531-21%
Approved Violations	837-82%	262-84%	598-86%	384-76%	3541-77%	5622-79%
Total Notices Printed	837-82%	262-84%	598-86%	384-76%	3540-77%	5621-79%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SHAGAN

Generated On: 2/21/2017 4:11:38 PM

Customer Management Report (San Mateo) All Detection Types

01-Jan-2017 to 31-Dec-2017

Operator Id: %

		SAN-4HU-01(P)	SAN-HINO-01(P)	SAN-HINO-03(P)	SAN-HISA-01(P)	SAN-SAHI-01(P)	TOTAL
Total Processed Incidents		185	68	163	107	1549	2072
Less Uncontrollable Factors							
Obstruction	Driver Obstruction/Duckers	10	0	10	4	65	89
	Motor Cycle Helmet	1	0	0	0	0	1
	Plate Obstruction	1	2	3	0	9	15
	Signal Obstruction	0	0	1	0	0	1
	Vehicle Obstruction	6	0	6	0	101	113
Police Rejects	Emergency Vehicle Responding	10	4	0	3	10	27
	Incorrect/Incomplete DMV	1	0	0	0	3	4
	Invalid Offense	0	1	0	0	0	1
	Multiple vehicles in frame	0	0	3	0	46	49
	On or Passed the Stop Bar (PD).	9	4	42	11	485	551
	Plate Obstruction (PD)	0	0	0	1	0	1
	Plate Unidentifiable	1	0	0	0	3	4
	Slow Roll - right turn	1	0	1	0	15	17
	Weather Conditions	0	0	0	0	2	2
	Yielding to an Emergency	1	0	0	0	1	2
Policy/Weather	Extended Vehicle	1	0	0	2	1	4
	Sun Glare	5	1	0	2	16	24
	Weather/Nature	1	3	2	1	61	68
Registration Issues	Out of Country Plate	0	0	0	0	1	1
	Paper Plates	9	3	12	7	70	101
Total		57	18	80	31	889	1075
Sub Total Violations		128	50	83	76	660	997
Less in Progress		19	14	3	5	73	114
Available For Prosecution		109	36	80	71	587	883
Less Rejects							
Camera Malfunction	Face Camera Flash	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
	Face Not in Frame	5-05%	0-00%	0-00%	0-00%	0-00%	5-01%
	Image Missing	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	2-00%	2-00%
	Rear Plate No Flash	0-00%	0-00%	7-09%	0-00%	0-00%	7-01%
Police Rejects	Driver Unidentifiable images poor	1-01%	2-06%	0-00%	0-00%	11-02%	14-02%
	Insufficient Strobe Lighting	0-00%	0-00%	0-00%	0-00%	3-01%	3-00%
	No Video	1-01%	0-00%	0-00%	0-00%	2-00%	3-00%
	Red-light not visible in	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: SHAGAN

Generated On: 2/21/2017 4:09:15 PM

Customer Management Report (San Mateo) All Detection Types

01-Jan-2017 to 31-Dec-2017

Operator Id: %

		SAN-4HU-01(P)	SAN-HINO-01(P)	SAN-HINO-03(P)	SAN-HISA-01(P)	SAN-SAHI-01(P)	TOTAL
Process	Too Old	2-02%	0-00%	2-02%	0-00%	18-03%	22-02%
Issues							
Total		10-09%	4-11%	9-11%	0-00%	36-06%	59-07%
Approved Violations		99-91%	32-89%	71-89%	71-100%	551-94%	824-93%
Total Notices Printed		97-89%	32-89%	67-84%	71-100%	542-92%	809-92%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: SHAGAN

Generated On: 2/21/2017 4:09:15 PM