

Customer Management Report (South Gate) All Detection Types

01-May-2013 to 31-May-2013

Operator Id: %

		SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIGA-01	SG-FIGA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Total Processed Incidents		282	176	106	173	200	160	16	377	178	46	66	28	1808
Less Uncontrollable Factors														
Obstruction	Driver Obstruction/Duckers	10	2	4	1	5	2	1	17	4	2	1	1	50
	Motor Cycle Helmet	0	0	0	0	1	0	0	0	0	0	0	0	1
	Plate Obstruction	10	3	0	0	3	4	0	5	2	2	7	4	40
	Vehicle Obstruction	16	1	1	1	1	2	1	20	1	2	7	0	53
Police Rejects	Driver Obstruction (PD)	0	0	0	0	0	0	0	1	0	0	0	0	1
	Emergency Vehicle Responding	15	17	5	7	2	7	2	6	2	2	2	2	69
	Incorrect/Incomplete DMV	3	3	1	0	2	1	0	0	1	0	0	0	11
	Invalid Offense	4	0	0	0	0	0	0	0	2	0	0	0	6
	Multiple vehicles in frame	1	0	0	0	1	0	0	1	0	0	0	0	3
	Police Discretion	6	3	2	4	8	6	0	0	2	0	0	0	31
	Safe Turn On Red	0	4	9	11	12	17	0	0	37	2	0	0	92
	Sun Glare	2	0	0	0	0	0	0	0	0	0	1	0	3
	Yielding to an Emergency	0	0	0	0	0	1	0	0	0	0	0	0	1
	Policy/Weather	Extended Vehicle	2	0	0	0	0	0	1	3	2	1	0	0
Sun Glare		33	5	4	11	26	27	2	35	29	4	12	16	204
Registration Issues	Out of Country Plate	1	0	0	0	0	0	0	1	0	0	0	0	2
	Paper Plates	13	11	8	6	12	6	0	14	11	2	3	0	86
	Wrong or No DMV	0	1	1	0	0	0	0	0	0	0	0	0	2
Total		116	50	35	41	73	73	7	103	93	17	33	23	664
Sub Total Violations		166	126	71	132	127	87	9	274	85	29	33	5	1144
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		166	126	71	132	127	87	9	274	85	29	33	5	1144
Less Rejects														
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Image Missing	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-20%	2-00%
	Misc Camera Issue	3-02%	0-00%	0-00%	8-06%	0-00%	0-00%	0-00%	9-03%	0-00%	0-00%	1-03%	0-00%	21-02%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%	2-02%	0-00%	0-00%	0-00%	4-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	0-00%	0-00%	0-00%	0-00%	3-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-07%	0-00%	0-00%	0-00%	6-01%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	8-09%	0-00%	0-00%	0-00%	8-01%
Police Rejects	Driver Unidentifiable images poor	4-02%	2-02%	0-00%	1-01%	1-01%	0-00%	0-00%	3-01%	0-00%	0-00%	0-00%	0-00%	11-01%
	Red-light not visible in	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	0-00%	3-00%
	Unclear Scene Image	0-00%	0-00%	0-00%	3-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%

Generated By: CDAHLIA

Generated On: 9/27/2013 10:23:34 PM

Customer Management Report (South Gate) All Detection Types

01-May-2013 to 31-May-2013

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIGA-01	SG-FIGA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Total	8-05%	3-02%	0-00%	14-11%	2-02%	1-01%	0-00%	16-06%	17-20%	0-00%	3-09%	1-20%	65-06%
Approved Violations	158-95%	123-98%	71-100%	118-89%	125-98%	86-99%	9-100%	258-94%	68-80%	29-100%	30-91%	4-80%	1079-94%
Total Notices Printed	158-95%	123-98%	71-100%	118-89%	125-98%	86-99%	9-100%	258-94%	68-80%	29-100%	30-91%	4-80%	1079-94%

Generated By: CDAHLIA

Generated On: 9/27/2013 10:23:34 PM

Customer Management Report (South Gate) All Detection Types

01-Jun-2013 to 30-Jun-2013

Operator Id: %

		SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIGA-01	SG-FIGA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Total Processed Incidents		270	171	76	158	203	187	13	440	211	42	81	32	1884
Less Uncontrollable Factors														
Obstruction	Driver Obstruction/Duckers	8	2	5	0	1	10	0	10	4	1	6	0	47
	Motor Cycle Helmet	1	0	0	0	0	0	0	0	1	0	0	0	2
	Plate Obstruction	7	2	1	1	3	0	1	1	4	0	9	2	31
	Vehicle Obstruction	11	2	0	2	2	3	2	23	3	2	7	1	58
Police Rejects	Emergency Vehicle Responding	12	14	8	5	5	7	2	7	7	2	3	2	74
	Gender Mismatch	0	0	0	0	0	0	0	1	0	0	0	0	1
	Incorrect/Incomplete DMV	3	3	0	0	0	3	0	1	0	0	2	0	12
	Invalid Offense	0	0	0	0	0	0	0	1	1	0	0	0	2
	Multiple vehicles in frame	4	0	0	0	0	0	0	1	0	0	0	0	5
	Plate Obstruction (PD)	1	0	0	0	0	0	0	0	0	0	0	0	1
	Police Discretion	1	6	0	1	1	4	0	4	3	1	2	0	23
	Safe Turn On Red	0	3	3	5	9	27	0	0	57	0	0	0	104
	Sun Glare	0	0	0	0	0	0	0	0	0	0	2	0	2
	Policy/Weather	Extended Vehicle	0	0	1	0	0	0	0	8	0	0	0	0
Sun Glare		23	4	6	7	36	27	3	54	36	3	13	18	230
Registration Issues	Out of Country Plate	0	0	0	1	1	0	0	2	0	0	0	0	4
	Paper Plates	13	4	1	5	15	7	1	13	11	4	2	2	78
Total		84	40	25	27	73	88	9	126	127	13	46	25	683
Sub Total Violations		186	131	51	131	130	99	4	314	84	29	35	7	1201
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		186	131	51	131	130	99	4	314	84	29	35	7	1201
Less Rejects														
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	2-29%	3-00%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-03%	0-00%	3-00%
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	1-01%	0-00%	1-02%	2-02%	0-00%	0-00%	0-00%	5-02%	2-02%	0-00%	0-00%	0-00%	11-01%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	3-00%
	Plate Not in Frame	0-00%	1-01%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	4-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Flash Inappropriate	1-01%	0-00%	1-02%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	4-02%	1-01%	0-00%	0-00%	1-01%	0-00%	0-00%	3-01%	0-00%	0-00%	2-06%	1-14%	12-01%
	Red-light not visible in	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total		7-04%	2-02%	2-04%	3-02%	8-06%	0-00%	0-00%	11-04%	4-05%	2-07%	3-09%	3-43%	45-04%

Generated By: CDAHLIA

Generated On: 9/27/2013 10:23:13 PM

Customer Management Report (South Gate) All Detection Types

01-Jun-2013 to 30-Jun-2013

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIGA-01	SG-FIGA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Approved Violations	179-96%	129-98%	49-96%	128-98%	122-94%	99-100%	4-100%	303-96%	80-95%	27-93%	32-91%	4-57%	1156-96%
Total Notices Printed	179-96%	129-98%	49-96%	128-98%	122-94%	99-100%	4-100%	303-96%	80-95%	27-93%	32-91%	4-57%	1156-96%

Generated By: CDAHLIA

Generated On: 9/27/2013 10:23:13 PM

Customer Management Report (South Gate) All Detection Types

01-Jul-2013 to 31-Jul-2013

Operator Id: %

		SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIGA-01	SG-FIGA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL	
Total Processed Incidents		284	176	81	154	207	173	19	362	206	36	87	29	1814	
Less Uncontrollable Factors															
Obstruction	Driver Obstruction/Duckers	8	1	1	1	3	2	2	12	3	4	3	0	40	
	Motor Cycle Helmet	0	0	0	1	1	0	0	0	1	0	1	0	4	
	Plate Obstruction	10	1	2	0	6	2	0	1	7	0	2	0	31	
	Vehicle Obstruction	17	1	1	1	2	1	0	23	3	3	11	1	64	
Police Rejects	Driver Obstruction (PD)	1	0	0	0	0	0	0	0	0	0	0	0	1	
	Emergency Vehicle Responding	7	18	6	9	4	10	1	6	7	2	7	2	79	
	Incorrect/Incomplete DMV	3	2	1	2	0	3	0	3	0	0	2	0	16	
	Invalid Offense	1	0	0	0	0	0	0	1	0	0	0	0	2	
	Multiple vehicles in frame	1	0	0	0	0	0	0	0	0	0	0	0	1	
	Plate Obstruction (PD)	1	0	0	0	0	0	0	0	0	0	0	0	1	
	Plate Unidentifiable	1	0	0	0	0	0	0	0	0	0	0	0	1	
	Police Discretion	0	0	0	0	2	1	1	6	2	0	0	0	0	12
	Safe Turn On Red	0	6	1	1	18	15	0	0	50	0	0	0	1	92
	Sun Glare	0	0	0	0	0	0	0	2	0	0	0	0	0	2
	Policy/Weather	Extended Vehicle	0	0	0	0	1	0	1	5	2	1	1	0	11
Sun Glare		47	2	2	14	31	20	2	33	36	4	17	10	218	
Yellow with Red Light		1	0	0	0	0	0	0	0	0	0	0	0	1	
Registration Issues	Out of Country Plate	0	0	0	1	0	0	0	1	0	0	0	0	2	
	Paper Plates	12	15	7	10	9	17	0	15	16	3	1	1	106	
Total		110	46	21	40	77	71	7	108	127	17	45	15	684	
Sub Total Violations		174	130	60	114	130	102	12	254	79	19	42	14	1130	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution		174	130	60	114	130	102	12	254	79	19	42	14	1130	
Less Rejects															
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	2-00%	
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
	Face Camera No Flash	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Not in Frame	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	1-01%	0-00%	2-05%	0-00%	5-00%	
	Image Missing	1-01%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	3-00%	
	Misc Camera Issue	7-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	11-04%	0-00%	0-00%	1-02%	1-07%	20-02%	
	Plate Burn Out	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	2-00%	
	Plate Not in Frame	2-01%	0-00%	0-00%	2-02%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	6-01%	
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-00%	
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	1-00%	

Generated By: CDAHLIA

Generated On: 9/27/2013 10:22:01 PM

Customer Management Report (South Gate) All Detection Types

01-Jul-2013 to 31-Jul-2013

Operator Id: %

		SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIGA-01	SG-FIGA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Police Rejects	Driver Unidentifiable images poor	1-01%	1-01%	1-02%	1-01%	1-01%	0-00%	0-00%	1-00%	1-01%	0-00%	0-00%	0-00%	7-01%
	Red-light not visible in	4-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	4-10%	0-00%	9-01%
Process Issues	Too Old	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%	1-01%	0-00%	0-00%	0-00%	3-00%
Total		17-10%	2-02%	3-05%	3-03%	4-03%	1-01%	0-00%	17-07%	5-06%	0-00%	8-19%	2-14%	62-05%
Approved Violations		157-90%	128-98%	57-95%	111-97%	126-97%	101-99%	12-100%	237-93%	74-94%	19-100%	34-81%	12-86%	1068-95%
Total Notices Printed		157-90%	128-98%	57-95%	111-97%	126-97%	101-99%	12-100%	237-93%	74-94%	19-100%	34-81%	12-86%	1068-95%

Generated By: CDAHLIA

Generated On: 9/27/2013 10:22:01 PM

Customer Management Report (South Gate) All Detection Types

01-Aug-2013 to 31-Aug-2013

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIGA-01	SG-FIGA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-INGA-01	SG-INGA-03	TOTAL	
Total Processed Incidents	315	193	59	162	126	96	25	431	206	43	83	29	1768	
Less Uncontrollable Factors														
Obstruction	Driver Obstruction/Duckers	26	7	3	0	3	6	2	33	16	8	9	2	115
	Plate Obstruction	6	1	0	2	3	0	1	9	10	2	10	0	44
	Vehicle Obstruction	8	0	0	2	0	0	2	23	1	2	5	0	43
Police Rejects	Driver Obstruction (PD)	1	0	0	0	0	0	0	3	0	0	0	0	4
	Emergency Vehicle Responding	13	13	2	6	0	4	2	6	0	1	4	5	56
	Incorrect/Incomplete DMV	3	3	0	1	0	1	0	2	1	0	4	0	15
	Invalid Offense	7	0	0	0	0	0	0	0	1	0	0	0	8
	Multiple vehicles in frame	1	0	0	0	0	0	0	3	0	0	0	0	4
	Plate Unidentifiable	1	0	0	0	0	0	1	1	0	0	0	0	3
	Police Discretion	4	0	0	1	0	0	0	1	0	0	0	0	6
	Safe Turn On Red	0	4	4	6	11	10	0	0	59	0	0	0	94
	Sun Glare	0	1	0	0	0	0	1	4	0	0	2	0	8
	Yielding to an Emergency	1	0	0	0	0	0	0	1	0	0	0	0	2
Policy/Weather	Extended Vehicle	1	0	0	1	0	0	0	4	3	1	2	1	13
	Sun Glare	45	4	2	17	24	14	5	22	33	3	14	12	195
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	0	1	0	0	1
	Paper Plates	16	13	1	9	9	3	1	20	7	2	0	2	83
Total		133	46	12	45	50	38	15	132	131	20	50	22	694
Sub Total Violations		182	147	47	117	76	58	10	299	75	23	33	7	1074
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		182	147	47	117	76	58	10	299	75	23	33	7	1074
Less Rejects														
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	1-01%	2-03%	1-02%	0-00%	2-01%	1-01%	0-00%	1-03%	2-29%	10-01%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-03%	1-14%	3-00%
	Face Not in Frame	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	1-01%	0-00%	3-09%	0-00%	6-01%
	Image Missing	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Misc Camera Issue	2-01%	1-01%	0-00%	1-01%	0-00%	0-00%	0-00%	6-02%	1-01%	0-00%	0-00%	0-00%	11-01%
	Plate Burn Out	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-14%	2-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	1-02%	0-00%	3-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-14%	5-00%
Police Rejects	Driver Unidentifiable images poor	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	3-09%	0-00%	7-01%
	Insufficient Strobe Lighting	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
	Red-light not visible in	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	3-00%
Total		8-04%	1-01%	1-02%	2-02%	5-07%	1-02%	0-00%	15-05%	5-07%	0-00%	8-24%	5-71%	51-05%
Approved Violations		174-96%	146-99%	46-98%	115-98%	71-93%	57-98%	10-100%	284-95%	70-93%	23-100%	25-76%	2-29%	1023-95%

Generated By: CDAHLIA

Generated On: 9/27/2013 10:21:01 PM

Customer Management Report (South Gate) All Detection Types

01-Aug-2013 to 31-Aug-2013

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIGA-01	SG-FIGA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGA-01	SG-IMGA-03	TOTAL
Total Notices Printed	174-96%	146-99%	46-98%	115-98%	71-93%	57-98%	10-100%	284-95%	70-93%	23-100%	25-76%	2-29%	1023-95%

Generated By: CDAHLIA

Generated On: 9/27/2013 10:21:01 PM

Customer Management Report (South Gate) All Detection Types

01-Sep-2013 to 30-Sep-2013

Operator Id: %

		SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIGA-01	SG-FIGA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGGA-01	SG-IMGGA-03	TOTAL
Total Processed Incidents		262	190	58	101	184	114	13	297	143	49	105	28	1544
Less Uncontrollable Factors														
Obstruction	Driver Obstruction/Duckers	10	2	1	1	2	2	0	6	6	6	6	3	45
	Motor Cycle Helmet	0	0	0	1	0	0	0	0	0	0	0	0	1
	Plate Obstruction	6	3	2	0	2	0	0	2	8	1	3	1	28
	Signal Obstruction	0	0	0	0	2	0	0	0	0	0	1	1	4
	Vehicle Obstruction	15	1	4	1	2	2	0	41	1	1	7	0	75
Police Rejects	Driver Obstruction (PD)	0	0	0	0	0	0	0	6	0	0	0	0	6
	Emergency Vehicle Responding	13	12	2	5	3	5	0	1	3	3	2	1	50
	Incorrect Plate on Vehicle	0	0	1	0	0	0	0	0	0	0	0	0	1
	Incorrect/Incomplete DMV	4	4	1	1	0	0	0	1	1	0	0	0	12
	Invalid Offense	2	0	0	0	0	0	0	1	0	1	0	0	4
	Multiple vehicles in frame	2	0	0	0	0	0	0	0	0	0	0	0	2
	Plate Obstruction (PD)	0	0	0	0	0	1	0	0	0	0	0	0	1
	Police Discretion	2	1	0	1	3	0	0	2	1	0	0	0	10
	Safe Turn On Red	0	3	3	4	9	10	0	1	26	0	0	0	56
	Sun Glare	0	0	0	0	4	4	0	2	1	0	8	0	19
Policy/Weather	Extended Vehicle	1	0	0	0	0	0	0	2	0	1	1	0	5
	Sun Glare	36	2	1	9	7	10	4	7	29	2	20	9	136
Registration Issues	Out of Country Plate	0	0	0	0	0	1	0	1	0	0	0	0	2
	Paper Plates	10	8	3	5	11	5	2	10	10	4	2	2	72
Total		101	36	18	28	45	40	6	83	86	19	50	17	529
Sub Total Violations		161	154	40	73	139	74	7	214	57	30	55	11	1015
Less in Progress		36	41	15	21	41	31	2	61	24	4	21	5	302
Available For Prosecution		125	113	25	52	98	43	5	153	33	26	34	6	713
Less Rejects														
Camera Malfunction	Face Camera Flash	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-08%	1-03%	0-00%	3-00%
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	3-02%	2-02%	0-00%	0-00%	0-00%	0-00%	2-40%	6-04%	0-00%	0-00%	0-00%	0-00%	13-02%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-17%	2-00%
	Plate Not in Frame	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	2-00%
	Rear Plate Camera Blurry	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	2-06%	0-00%	4-01%
	Rear Plate Flash Inappropriate	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	6-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
Police Rejects	Driver Unidentifiable images poor	5-04%	0-00%	0-00%	0-00%	0-00%	0-00%	1-20%	0-00%	2-06%	0-00%	2-06%	1-17%	11-02%
	Insufficient Strobe Lighting	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: CDAHLIA

Generated On: 9/27/2013 10:20:05 PM

Customer Management Report (South Gate) All Detection Types

01-Sep-2013 to 30-Sep-2013

Operator Id: %

	SG-ATTW-01	SG-ATTW-03	SG-CATW-01	SG-CATW-03	SG-FIGA-01	SG-FIGA-03	SG-FIGA-01	SG-FIGA-03	SG-GASO-01	SG-GASO-03	SG-IMGGA-01	SG-IMGGA-03	TOTAL
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-12%	0-00%	4-01%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-01%	1-03%	0-00%	1-03%	1-17%	5-01%
Total	14-11%	2-02%	0-00%	0-00%	7-07%	0-00%	3-60%	9-06%	4-12%	2-08%	11-32%	3-50%	55-08%
Approved Violations	111-89%	111-98%	25-100%	52-100%	91-93%	43-100%	2-40%	144-94%	29-88%	24-92%	23-68%	3-50%	658-92%
Total Notices Printed	111-89%	111-98%	25-100%	52-100%	91-93%	43-100%	2-40%	144-94%	29-88%	24-92%	23-68%	3-50%	658-92%

Generated By: CDAHLIA

Generated On: 9/27/2013 10:20:05 PM