

# Customer Management Report (Ventura) All Detection Types

01-Sep-2001 to 30-Sep-2001

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	0	0	0	0	0	74	62	64	0	0	167	0	189	32	265	204	0	196	1253
<b>Less Uncontrollable Factors</b>																			
Obstruction	Driver Obstruction/Duckers																		
	0	0	0	0	0	4	7	1	0	0	20	0	19	6	41	46	0	9	153
	Motor Cycle Helmet																		
	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
	Plate Obstruction																		
	0	0	0	0	0	5	1	2	0	0	13	0	5	1	6	6	0	17	56
	Vehicle Obstruction																		
	0	0	0	0	0	0	5	0	0	0	12	0	6	0	6	6	0	8	43
Police Rejects	Driver Unidentifiable																		
	0	0	0	0	0	3	2	0	0	0	5	0	2	1	10	4	0	13	40
Policy/Weather	Sun Glare																		
	0	0	0	0	0	1	1	3	0	0	34	0	10	0	13	10	0	10	82
	Yellow with Red Light																		
	0	0	0	0	0	2	1	5	0	0	8	0	2	0	15	2	0	4	39
Registration Issues	Paper Plates																		
	0	0	0	0	0	1	1	1	0	0	1	0	5	0	2	2	0	2	15
	Wrong or No DMV																		
	0	0	0	0	0	5	2	2	0	0	3	0	4	9	9	4	0	8	46
<b>Total</b>	0	0	0	0	0	21	20	14	0	0	97	0	53	17	102	80	0	71	475
<b>Sub Total Violations</b>	0	0	0	0	0	53	42	50	0	0	70	0	136	15	163	124	0	125	778
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>	0	0	0	0	0	53	42	50	0	0	70	0	136	15	163	124	0	125	778
<b>Less Rejects</b>																			
Camera Malfunction	Face Camera Flash																		
	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	6-04%	1-01%	0-00%	1-01%	10-01%
	Face Camera Focus Blurry																		
	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-01%	0-00%	10-07%	0-00%	2-01%	11-09%	0-00%	6-05%	31-04%
	Face Camera No Flash																		
	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-00%
	Face Not in Frame																		
	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-10%	1-02%	0-00%	0-00%	8-11%	0-00%	3-02%	4-27%	26-16%	27-22%	0-00%	6-05%	79-10%
	Image Missing																		
	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	1-01%	0-00%	0-00%	2-00%
	Misc Camera Issue																		
	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-05%	1-02%	0-00%	0-00%	0-00%	0-00%	7-05%	0-00%	0-00%	0-00%	0-00%	0-00%	10-01%
	Plate Burn Out																		
	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-04%	0-00%	0-00%	2-02%	0-00%	2-02%	12-02%
	Plate Not in Frame																		
	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	1-01%	0-00%	2-01%	3-02%	0-00%	3-02%	12-02%
	Rear Plate Camera Blurry																		
	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	2-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	12-02%
	Rear Plate Flash Inappropriate																		
	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate No Flash																		
	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-00%
Process Issues	Too Old																		
	0-00%	0-00%	0-00%	0-00%	0-00%	7-13%	4-10%	9-18%	0-00%	0-00%	10-14%	0-00%	14-10%	2-13%	14-09%	8-06%	0-00%	13-10%	81-10%
<b>Total</b>	0-00%	0-00%	0-00%	0-00%	0-00%	13-25%	13-31%	11-22%	0-00%	0-00%	21-30%	0-00%	43-32%	7-47%	50-31%	54-44%	0-00%	40-32%	252-32%
<b>Approved Violations</b>	0-00%	0-00%	0-00%	0-00%	0-00%	40-75%	29-69%	39-78%	0-00%	0-00%	49-70%	0-00%	93-68%	8-53%	113-69%	70-56%	0-00%	85-68%	526-68%
<b>Total Notices Printed</b>	0-00%	0-00%	0-00%	0-00%	0-00%	40-75%	29-69%	39-78%	0-00%	0-00%	49-70%	0-00%	93-68%	8-53%	113-69%	70-56%	0-00%	85-68%	526-68%

Generated By: JKOHAGEN

Generated On: 4/21/2014 3:49:45 PM

# Customer Management Report (Ventura) All Detection Types

01-Sep-2001 to 30-Sep-2001

Operator Id: %

VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	-------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Nov-2001 to 30-Nov-2001

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	2	0	0	0	0	54	58	93	14	0	96	67	146	129	158	74	0	98	989	
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	0	0	0	0	0	16	7	11	0	0	10	4	13	56	29	21	0	3	170
	Plate Obstruction	0	0	0	0	0	5	1	2	1	0	10	7	4	1	6	3	0	8	48
	Signal Obstruction	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
	Vehicle Obstruction	0	0	0	0	0	0	1	0	1	0	9	1	3	0	1	4	0	1	21
Police Rejects	Driver Unidentifiable	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1	2
Policy/Weather	Sun Glare	0	0	0	0	0	0	1	1	0	7	0	16	0	5	0	0	0	9	39
	Yellow with Red Light	0	0	0	0	0	0	1	0	0	5	0	4	3	6	0	0	0	0	19
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1
	Paper Plates	0	0	0	0	0	0	1	4	1	0	1	0	5	4	4	0	0	3	23
	Wrong or No DMV	0	0	0	0	0	0	2	1	0	4	2	4	0	3	0	0	0	2	18
<b>Total</b>		0	0	0	0	0	22	12	20	4	0	47	14	49	65	54	28	0	27	342
<b>Sub Total Violations</b>		2	0	0	0	0	32	46	73	10	0	49	53	97	64	104	46	0	71	647
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		2	0	0	0	0	32	46	73	10	0	49	53	97	64	104	46	0	71	647
<b>Less Rejects</b>																				
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	3-04%	0-00%	0-00%	12-24%	0-00%	1-01%	0-00%	9-09%	1-02%	0-00%	3-04%	30-05%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	7-22%	8-17%	1-01%	1-10%	0-00%	5-10%	5-09%	7-07%	7-11%	7-07%	21-46%	0-00%	14-20%	83-13%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	9-20%	3-04%	0-00%	0-00%	3-06%	6-11%	3-03%	22-34%	17-16%	7-15%	0-00%	7-10%	79-12%
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	6-08%	0-00%	0-00%	0-00%	3-06%	2-02%	1-02%	4-04%	2-04%	0-00%	2-03%	22-03%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	26-27%	1-02%	2-02%	0-00%	0-00%	4-06%	33-05%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	2-04%	0-00%	2-02%	6-09%	0-00%	1-02%	0-00%	0-00%	13-02%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-08%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	4-06%	9-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-01%	3-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	5-08%	0-00%	0-00%	0-00%	0-00%	0-00%	7-01%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-02%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	2-03%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	2-03%	7-01%
<b>Total</b>		0-00%	0-00%	0-00%	0-00%	0-00%	10-31%	23-50%	18-25%	1-10%	0-00%	23-47%	21-40%	41-42%	44-69%	41-39%	32-70%	0-00%	37-52%	291-45%
<b>Approved Violations</b>		2-100%	0-00%	0-00%	0-00%	0-00%	22-69%	23-50%	55-75%	9-90%	0-00%	26-53%	32-60%	56-58%	20-31%	63-61%	14-30%	0-00%	34-48%	356-55%
<b>Total Notices Printed</b>		2-100%	0-00%	0-00%	0-00%	0-00%	22-69%	23-50%	55-75%	9-90%	0-00%	26-53%	32-60%	56-58%	20-31%	63-61%	14-30%	0-00%	34-48%	356-55%

Generated By: JKOHAGEN

Generated On: 4/21/2014 3:50:47 PM

# Customer Management Report (Ventura) All Detection Types

01-Nov-2001 to 30-Nov-2001

Operator Id: %

VE-VIVA-01	VE-VITP-03	VE-VITP-01	VE-VITG-01	VE-VIRA-01	VE-VIOP-01	VE-VIMO-01	VE-THSE-01	VE-TGDA-01	VE-MITG-01	VE-MIDE-01	VE-MAMI-01	VE-MALE-01	VE-MA10-01	VE-JONB-01	VE-FOV1-01	VE-CATH-01	VE-BRJO-01	TOTAL
------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	-------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Dec-2001 to 31-Dec-2001

Operator Id: %

		VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents		6	0	0	0	0	53	109	82	26	0	54	114	199	110	104	168	0	106	1131	
<b>Less Uncontrollable Factors</b>																					
Obstruction	Driver Obstruction/Duckers	3	0	0	0	0	10	13	8	3	0	6	10	21	31	14	43	0	5	167	
	Plate Obstruction	0	0	0	0	0	6	5	3	0	0	7	13	4	2	5	4	0	14	63	
	Vehicle Obstruction	0	0	0	0	0	1	6	3	0	0	7	3	4	0	3	2	0	4	33	
Police Rejects	Driver Unidentifiable	1	0	0	0	0	1	0	0	0	0	0	2	0	0	1	2	0	1	8	
	Invalid Offense	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1	
Policy/Weather	Sun Glare	0	0	0	0	0	3	4	2	3	0	6	1	18	6	5	11	0	22	81	
	Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1	
	Yellow with Red Light	0	0	0	0	0	0	0	0	0	0	0	0	5	0	0	0	0	0	5	
Registration Issues	Can Not Identify State	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	2	
	Out of Country Plate	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1	
	Paper Plates	0	0	0	0	0	2	4	4	0	0	2	1	2	1	2	3	0	1	22	
	Wrong or No DMV	0	0	0	0	0	1	4	4	0	0	3	4	8	2	1	4	0	3	34	
Total		4	0	0	0	0	24	40	24	6	0	31	34	62	42	32	69	0	50	418	
Sub Total Violations		2	0	0	0	0	29	69	58	20	0	23	80	137	68	72	99	0	56	713	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution		2	0	0	0	0	29	69	58	20	0	23	80	137	68	72	99	0	56	713	
<b>Less Rejects</b>																					
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-01%	1-02%	0-00%	0-00%	1-04%	1-01%	5-04%	0-00%	1-01%	0-00%	0-00%	1-02%	12-02%	
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	2-03%	0-00%	0-00%	0-00%	1-04%	9-11%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	15-02%	
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	17-25%	3-05%	0-00%	0-00%	0-00%	0-00%	2-01%	12-18%	18-25%	6-06%	0-00%	4-07%	64-09%	
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-04%	3-05%	3-15%	0-00%	0-00%	8-10%	6-04%	0-00%	2-03%	4-04%	0-00%	3-05%	32-04%	
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-09%	2-02%	1-01%	0-00%	1-01%	6-06%	0-00%	9-16%	21-03%	
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	1-01%	3-03%	0-00%	1-02%	7-01%	
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	0-00%	1-02%	0-00%	0-00%	0-00%	3-04%	0-00%	0-00%	0-00%	1-01%	0-00%	2-04%	9-01%	
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-01%	3-04%	1-01%	0-00%	0-00%	8-01%	
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	16-24%	10-14%	0-00%	0-00%	0-00%	28-04%	
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%	
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	2-03%	0-00%	0-00%	0-00%	1-02%	5-01%	
Total		0-00%	0-00%	0-00%	0-00%	0-00%	8-28%	24-35%	8-14%	3-15%	0-00%	4-17%	26-32%	15-11%	34-50%	36-50%	24-24%	0-00%	21-38%	203-28%	
Approved Violations		2-100%	0-00%	0-00%	0-00%	0-00%	21-72%	45-65%	50-86%	17-85%	0-00%	19-83%	54-68%	122-89%	34-50%	36-50%	75-76%	0-00%	35-62%	510-72%	
Total Notices Printed		2-100%	0-00%	0-00%	0-00%	0-00%	21-72%	45-65%	50-86%	17-85%	0-00%	19-83%	54-68%	122-89%	34-50%	36-50%	75-76%	0-00%	35-62%	510-72%	

Generated By: JKOHAGEN

Generated On: 4/21/2014 3:51:16 PM

# Customer Management Report (Ventura) All Detection Types

01-Dec-2001 to 31-Dec-2001

Operator Id: %

VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	-------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Apr-2002 to 30-Apr-2002

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	31	0	43	69	0	33	33	57	13	27	94	125	121	108	148	147	0	85	1134	
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	6	0	10	3	0	5	2	4	0	1	6	7	9	21	17	22	0	6	119
	Plate Obstruction	1	0	1	6	0	6	1	2	1	0	8	4	2	4	3	6	0	8	53
	Vehicle Obstruction	2	0	0	2	0	0	0	1	0	1	43	4	0	0	0	3	0	4	60
Police Rejects	Driver Unidentifiable	1	0	0	1	0	1	2	1	0	1	1	2	3	2	1	1	0	3	20
Policy/Weather	Extended Vehicle	0	0	0	0	0	1	1	0	0	0	1	19	1	0	1	2	0	2	28
	Sun Glare	2	0	3	6	0	1	7	1	0	7	12	6	6	5	11	17	0	8	92
	Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
	Yellow with Red Light	0	0	0	0	0	0	0	1	0	0	2	1	2	2	2	0	0	0	10
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	2	0	2	0	0	0	1	5
	Paper Plates	0	0	1	2	0	1	1	2	0	1	5	3	3	6	4	3	0	3	35
	Wrong or No DMV	2	0	1	2	0	1	2	4	1	1	3	9	4	4	8	0	5	48	
<b>Total</b>		14	0	16	22	0	16	16	16	2	12	79	49	37	44	46	62	0	40	471
<b>Sub Total Violations</b>		17	0	27	47	0	17	17	41	11	15	15	76	84	64	102	85	0	45	663
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		17	0	27	47	0	17	17	41	11	15	15	76	84	64	102	85	0	45	663
<b>Less Rejects</b>																				
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Face Camera Flash	0-00%	0-00%	2-07%	4-09%	0-00%	0-00%	1-06%	1-02%	0-00%	0-00%	0-00%	3-04%	1-01%	0-00%	4-04%	2-02%	0-00%	1-02%	19-03%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	1-02%	0-00%	2-12%	0-00%	0-00%	0-00%	0-00%	0-00%	20-26%	0-00%	0-00%	1-01%	1-01%	0-00%	2-04%	27-04%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-07%	0-00%	0-00%	3-03%	1-01%	0-00%	0-00%	9-01%
	Face Not in Frame	2-12%	0-00%	13-48%	0-00%	0-00%	0-00%	6-35%	1-02%	0-00%	0-00%	0-00%	1-01%	2-02%	7-11%	8-08%	8-09%	0-00%	1-02%	49-07%
	Image Missing	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	2-02%	0-00%	0-00%	0-00%	4-01%
	Misc Camera Issue	0-00%	0-00%	0-00%	3-06%	0-00%	0-00%	0-00%	2-05%	0-00%	0-00%	2-13%	16-21%	1-01%	3-05%	4-04%	9-11%	0-00%	10-22%	50-08%
	Plate Burn Out	3-18%	0-00%	0-00%	4-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-03%	1-01%	0-00%	6-13%	17-03%
	Plate Not in Frame	2-12%	0-00%	1-04%	5-11%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	1-07%	2-03%	0-00%	1-02%	31-30%	3-04%	0-00%	1-02%	48-07%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	4-01%
	Rear Plate No Flash	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Scene Image No Flash	0-00%	0-00%	4-15%	0-00%	0-00%	4-24%	1-06%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	10-02%
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
<b>Total</b>		8-47%	0-00%	21-78%	17-36%	0-00%	7-41%	9-53%	5-12%	0-00%	1-07%	4-27%	50-66%	6-07%	11-17%	56-55%	25-29%	0-00%	22-49%	242-37%
<b>Approved Violations</b>		9-53%	0-00%	6-22%	30-64%	0-00%	10-59%	8-47%	36-88%	11-100%	14-93%	11-73%	26-34%	78-93%	53-83%	46-45%	60-71%	0-00%	23-51%	421-63%
<b>Total Notices Printed</b>		9-53%	0-00%	6-22%	30-64%	0-00%	10-59%	8-47%	36-88%	11-100%	14-93%	11-73%	26-34%	78-93%	53-83%	46-45%	60-71%	0-00%	23-51%	421-63%

Generated By: JKOHAGEN

Generated On: 4/21/2014 3:51:49 PM

# Customer Management Report (Ventura) All Detection Types

01-Apr-2002 to 30-Apr-2002

Operator Id: %

VE-VIVA-01	VE-VITP-03	VE-VITP-01	VE-VITG-01	VE-VIRA-01	VE-VIOP-01	VE-VIMO-01	VE-THSE-01	VE-TGDA-01	VE-MITG-01	VE-MIDE-01	VE-MAMI-01	VE-MALE-01	VE-MA10-01	VE-JONB-01	VE-FOV1-01	VE-CATH-01	VE-BRJO-01	TOTAL
------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	-------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current



# Customer Management Report (Ventura) All Detection Types

01-Oct-2002 to 31-Oct-2002

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL		
<b>Total Processed Incidents</b>	34	0	44	50	0	63	60	41	12	26	91	91	174	92	147	164	100	111	1300		
<b>Less Uncontrollable Factors</b>																					
Obstruction	Driver Obstruction/Duckers	7	0	12	1	0	4	2	0	0	1	6	9	11	5	11	3	3	0	75	
	Plate Obstruction	5	0	2	8	0	13	5	0	1	1	10	7	3	3	6	7	3	6	80	
	Vehicle Obstruction	0	0	0	0	0	0	5	0	0	0	38	5	3	0	3	2	2	5	63	
Police Rejects	Driver Unidentifiable	0	0	2	2	0	3	0	0	0	0	1	1	1	1	1	3	4	2	20	
	Gender Mismatch	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	
	Safe Turn On Red	0	0	0	1	0	1	0	0	0	1	0	1	0	1	2	0	6	1	14	
Policy/Weather	Extended Vehicle	1	0	0	1	0	1	1	1	0	0	12	1	0	2	3	0	5	28		
	Sun Glare	0	0	0	4	0	0	5	1	1	2	4	0	2	1	5	1	6	8	40	
	Yellow with Red Light	0	0	0	0	0	0	0	0	0	0	0	7	2	0	0	0	0	9		
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	
	Paper Plates	1	0	1	2	0	1	1	1	0	0	2	1	6	3	2	5	6	1	33	
	Wrong or No DMV	1	0	3	4	0	5	2	5	2	0	5	5	9	7	10	11	6	6	81	
<b>Total</b>	15	0	20	23	0	28	21	8	4	5	65	41	43	23	42	37	36	34	445		
<b>Sub Total Violations</b>	19	0	24	27	0	35	39	33	8	21	26	50	131	69	105	127	64	77	855		
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
<b>Available For Prosecution</b>	19	0	24	27	0	35	39	33	8	21	26	50	131	69	105	127	64	77	855		
<b>Less Rejects</b>																					
Camera Malfunction	Face Camera Flash	0-00%	0-00%	2-08%	3-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	2-04%	1-01%	0-00%	6-06%	0-00%	0-00%	0-00%	15-02%	
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-08%	0-00%	0-00%	0-00%	2-08%	0-00%	3-02%	7-10%	0-00%	1-01%	0-00%	2-03%	18-02%	
	Face Not in Frame	2-11%	0-00%	2-08%	0-00%	0-00%	2-06%	9-23%	0-00%	0-00%	0-00%	1-04%	1-02%	3-02%	3-04%	13-12%	6-05%	1-02%	1-01%	44-05%	
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-00%	
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	11-16%	2-02%	0-00%	2-03%	0-00%	15-02%	
	Plate Burn Out	1-05%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-07%	0-00%	6-09%	15-19%	30-04%
	Plate Not in Frame	1-05%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-08%	3-06%	0-00%	3-04%	1-01%	8-06%	2-03%	3-04%	24-03%	
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-01%	0-00%	0-00%	1-01%	2-03%	2-03%	7-01%	
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	3-38%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%	
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Scene Image No Flash	0-00%	0-00%	5-21%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%	
Police Rejects Process Issues	Incorrect Details	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%	
	Too Old	1-05%	0-00%	2-08%	0-00%	0-00%	0-00%	1-03%	3-09%	0-00%	0-00%	1-04%	2-04%	3-02%	2-03%	0-00%	4-03%	0-00%	0-00%	19-02%	
<b>Total</b>	5-26%	0-00%	12-50%	4-15%	0-00%	3-09%	14-36%	3-09%	3-38%	1-05%	7-27%	9-18%	11-08%	26-38%	30-29%	20-16%	13-20%	24-31%	185-22%		
<b>Approved Violations</b>	14-74%	0-00%	12-50%	23-85%	0-00%	32-91%	25-64%	30-91%	5-62%	20-95%	19-73%	41-82%	120-92%	43-62%	75-71%	107-84%	51-80%	53-69%	670-78%		
<b>Total Notices Printed</b>	14-74%	0-00%	12-50%	23-85%	0-00%	32-91%	25-64%	30-91%	5-62%	20-95%	19-73%	41-82%	120-92%	43-62%	75-71%	107-84%	51-80%	53-69%	670-78%		

Generated By: JKOHAGEN

Generated On: 4/21/2014 3:52:38 PM

# Customer Management Report (Ventura) All Detection Types

01-Oct-2002 to 31-Oct-2002

Operator Id: %

VE-VIVA-01	VE-VITP-03	VE-VITP-01	VE-VITG-01	VE-VIRA-01	VE-VIOP-01	VE-VIMO-01	VE-THSE-01	VE-TGDA-01	VE-MITG-01	VE-MIDE-01	VE-MAMI-01	VE-MALE-01	VE-MA10-01	VE-JONB-01	VE-FOV1-01	VE-CATH-01	VE-BRJO-01	TOTAL
------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	-------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 4/21/2014 3:52:38 PM

© Redflex Traffic Systems, Inc.

# Customer Management Report (Ventura) All Detection Types

01-Apr-2004 to 30-Apr-2004

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>		21	0	31	57	302	49	22	33	11	26	81	108	42	63	77	99	140	76	1238
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	8	0	15	3	17	4	1	1	0	1	11	6	1	15	11	5	12	7	118
	Plate Obstruction	2	0	1	3	27	3	2	2	1	1	5	4	1	1	3	0	1	4	61
	Signal Obstruction	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Vehicle Obstruction	1	0	0	0	2	1	1	0	0	1	1	6	0	0	1	0	1	0	15
Police Rejects	Other	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1
Policy/Weather	Extended Vehicle	0	0	0	1	1	0	0	1	0	0	0	14	0	0	0	0	0	3	20
	Sun Glare	0	0	0	1	26	1	0	0	0	1	6	0	1	1	3	0	12	1	53
	Weather/Nature	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Registration Issues	Can Not Identify State	0	0	0	0	0	1	0	0	0	0	1	0	0	0	0	0	0	0	2
	Out of Country Plate	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1
	Paper Plates	1	0	0	3	3	0	2	0	0	0	2	4	1	3	2	3	1	1	26
	Wrong or No DMV	0	0	0	3	18	1	1	1	0	0	5	3	4	3	2	7	7	1	56
<b>Total</b>		12	0	16	15	95	11	7	5	1	4	31	38	8	23	22	16	34	17	355
<b>Sub Total Violations</b>		9	0	15	42	207	38	15	28	10	22	50	70	34	40	55	83	106	59	883
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		9	0	15	42	207	38	15	28	10	22	50	70	34	40	55	83	106	59	883
<b>Less Rejects</b>																				
Camera Malfunction	Datar Unreadable/Incorrect	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera Flash	0-00%	0-00%	0-00%	9-21%	26-13%	4-11%	1-07%	0-00%	0-00%	4-18%	3-06%	17-24%	1-03%	3-08%	4-07%	9-11%	41-39%	5-08%	127-14%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	1-00%	3-08%	1-07%	0-00%	0-00%	0-00%	0-00%	5-07%	0-00%	2-05%	1-02%	0-00%	1-01%	1-02%	15-02%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Face Not in Frame	1-11%	0-00%	1-07%	0-00%	0-00%	0-00%	1-07%	2-07%	0-00%	0-00%	0-00%	1-01%	0-00%	2-05%	2-04%	1-01%	0-00%	0-00%	11-01%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	7-18%	0-00%	3-11%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	13-01%

Generated By: JKOHAGEN

Generated On: 4/21/2014 3:57:35 PM

# Customer Management Report (Ventura) All Detection Types

01-Apr-2004 to 30-Apr-2004

Operator Id: %

	VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Plate Burn Out	3-33%	0-00%	1-07%	2-05%	11-05%	0-00%	0-00%	0-00%	0-00%	0-00%	4-08%	0-00%	4-12%	0-00%	1-02%	1-01%	17-16%	0-00%	44-05%
Plate Not in Frame	0-00%	0-00%	3-20%	1-02%	1-00%	0-00%	0-00%	1-04%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	8-01%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	5-02%	2-05%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	3-05%	0-00%	0-00%	7-12%	19-02%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	2-04%	0-00%	0-00%	22-37%	26-03%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	2-20%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-02%	5-01%
Scene Image No Flash	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects Process Issues																			
Unclear Images	0-00%	0-00%	0-00%	2-05%	4-02%	4-11%	0-00%	0-00%	0-00%	1-05%	1-02%	0-00%	1-03%	1-02%	1-02%	0-00%	9-08%	2-03%	26-03%
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	3-00%
Total	4-44%	0-00%	7-47%	14-33%	48-23%	22-58%	3-20%	6-21%	2-20%	6-27%	8-16%	30-43%	6-18%	8-20%	17-31%	13-16%	68-64%	39-66%	301-34%
Approved Violations	5-56%	0-00%	8-53%	28-67%	159-77%	16-42%	12-80%	22-79%	8-80%	16-73%	42-84%	40-57%	28-82%	32-80%	38-69%	70-84%	38-36%	20-34%	582-66%
Total Notices Printed	5-56%	0-00%	8-53%	28-67%	159-77%	16-42%	12-80%	22-79%	8-80%	16-73%	42-84%	40-57%	28-82%	32-80%	38-69%	70-84%	38-36%	20-34%	582-66%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 4/21/2014 3:57:35 PM

# Customer Management Report (Ventura) All Detection Types

01-Apr-2005 to 30-Apr-2005

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>		5	0	26	6	147	49	13	31	5	18	49	94	34	42	52	83	95	68	817	
<b>Less Uncontrollable Factors</b>																					
Obstruction	Driver Obstruction/Duckers	0	0	5	0	9	2	0	0	0	1	3	6	3	2	3	1	3	0	38	
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1	0	0	2	
	Plate Obstruction	0	0	1	1	26	4	0	0	0	1	2	4	2	1	0	0	2	7	51	
	Vehicle Obstruction	2	0	0	0	1	0	0	0	0	0	0	2	0	0	0	0	2	0	7	
Police Rejects	Invalid Offense	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1	
	Safe Turn On Red	0	0	0	3	4	1	0	1	0	1	1	7	1	1	1	1	1	2	25	
Policy/Weather	Extended Vehicle	0	0	0	0	1	0	0	0	0	0	0	8	0	0	0	0	0	4	13	
	Sun Glare	0	0	2	0	21	2	0	0	0	3	8	4	0	1	3	2	37	7	90	
	Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1	
Registration Issues	Out of Country Plate	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1	0	0	0	2	
	Paper Plates	0	0	1	0	3	3	0	0	0	0	3	6	0	3	1	2	1	3	26	
	Wrong or No DMV	0	0	1	0	5	3	0	0	0	0	4	2	3	2	3	2	0	3	28	
<b>Total</b>		2	0	10	4	70	15	0	2	0	6	23	39	9	10	12	11	44	27	284	
<b>Sub Total Violations</b>		3	0	16	2	77	34	13	29	5	12	26	55	25	32	40	72	51	41	533	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
<b>Available For Prosecution</b>		3	0	16	2	77	34	13	29	5	12	26	55	25	32	40	72	51	41	533	
<b>Less Rejects</b>																					
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	1-01%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	
	Face Not in Frame	2-67%	0-00%	5-31%	0-00%	0-00%	0-00%	6-46%	0-00%	0-00%	1-08%	1-04%	1-02%	1-04%	9-28%	2-05%	3-04%	5-10%	2-05%	38-07%	
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
	Plate Not in Frame	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	1-03%	1-02%	6-08%	1-02%	0-00%	13-02%	
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	0-00%	0-00%	1-20%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-10%	8-02%

Generated By: JKOHAGEN

Generated On: 4/21/2014 3:58:08 PM

# Customer Management Report (Ventura) All Detection Types

01-Apr-2005 to 30-Apr-2005

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-09%	0-00%	0-00%	0-00%	0-00%	3-01%
Police Rejects	Unclear Images	0-00%	0-00%	2-12%	0-00%	6-08%	4-12%	2-15%	2-07%	0-00%	2-17%	1-04%	8-15%	0-00%	5-16%	1-02%	12-17%	17-33%	5-12%	67-13%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-02%	2-03%	2-04%	0-00%	6-01%
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	1-01%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-08%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Total		2-67%	0-00%	8-50%	0-00%	9-12%	8-24%	9-69%	3-10%	1-20%	3-25%	5-19%	13-24%	3-12%	19-59%	5-12%	23-32%	25-49%	11-27%	147-28%
Approved Violations		1-33%	0-00%	8-50%	2-100%	68-88%	26-76%	4-31%	26-90%	4-80%	9-75%	21-81%	42-76%	22-88%	13-41%	35-88%	49-68%	26-51%	30-73%	386-72%
Total Notices Printed		1-33%	0-00%	8-50%	2-100%	68-88%	26-76%	4-31%	26-90%	4-80%	9-75%	21-81%	42-76%	22-88%	13-41%	35-88%	49-68%	26-51%	30-73%	386-72%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 4/21/2014 3:58:08 PM

# Customer Management Report (Ventura) All Detection Types

01-Oct-2005 to 31-Oct-2005

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>		10	0	43	7	201	52	11	39	9	11	57	69	37	71	104	66	91	79	957
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	1	0	11	0	15	4	4	2	0	2	5	1	0	20	8	4	4	6	87
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
	Plate Obstruction	0	0	1	0	28	3	0	1	0	0	1	9	0	0	6	4	3	6	62
	Signal Obstruction	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
	Vehicle Obstruction	0	0	0	1	7	1	0	0	0	0	0	3	0	1	2	0	1	0	16
Police Rejects	Driver Unidentifiable	1	0	1	0	8	4	0	0	1	1	5	3	3	5	6	8	24	2	72
	Invalid Offense	0	0	0	0	0	0	0	1	0	0	0	5	0	0	0	1	0	0	7
Policy/Weather	Extended Vehicle	0	0	0	1	1	1	0	0	0	0	0	1	0	0	0	1	0	2	7
	Sun Glare	0	0	0	1	18	2	1	2	1	1	10	4	1	0	9	5	14	18	87
Registration Issues	Can Not Identify State	0	0	0	0	1	0	0	0	0	0	2	1	0	0	0	0	0	0	4
	Paper Plates	0	0	0	0	2	3	0	0	0	1	1	2	1	3	4	4	3	3	27
	Wrong or No DMV	0	0	0	0	6	1	0	3	0	1	3	1	1	0	3	3	4	3	29
<b>Total</b>		2	0	13	3	86	20	5	9	2	6	27	30	6	30	38	30	53	40	400
<b>Sub Total Violations</b>		8	0	30	4	115	32	6	30	7	5	30	39	31	41	66	36	38	39	557
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		8	0	30	4	115	32	6	30	7	5	30	39	31	41	66	36	38	39	557
<b>Less Rejects</b>																				
Camera Malfunction	Face Camera Flash	1-12%	0-00%	0-00%	2-50%	10-09%	2-06%	0-00%	1-03%	0-00%	1-20%	0-00%	3-08%	0-00%	2-05%	1-02%	2-06%	11-29%	2-05%	38-07%
	Face Camera Focus Blurry	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	2-05%	0-00%	4-10%	1-02%	1-03%	1-03%	1-03%	12-02%
	Face Not in Frame	0-00%	0-00%	7-23%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	4-13%	1-03%	0-00%	2-05%	6-09%	1-03%	2-05%	0-00%	25-04%
	Misc Camera Issue	2-25%	0-00%	5-17%	1-25%	7-06%	11-34%	4-67%	3-10%	0-00%	0-00%	6-20%	3-08%	4-13%	5-12%	5-08%	3-08%	4-11%	5-13%	68-12%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	3-10%	0-00%	2-06%	0-00%	2-03%	0-00%	8-21%	0-00%	16-03%
	Plate Not in Frame	2-25%	0-00%	8-27%	0-00%	5-04%	1-03%	0-00%	0-00%	0-00%	0-00%	2-07%	0-00%	0-00%	3-07%	1-02%	0-00%	0-00%	1-03%	23-04%

Generated By: JKOHAGEN

Generated On: 4/21/2014 3:59:23 PM

# Customer Management Report (Ventura) All Detection Types

01-Oct-2005 to 31-Oct-2005

Operator Id: %

	VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	8-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-02%	0-00%	0-00%	4-10%	14-03%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-03%	0-00%	4-01%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-14%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-14%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Police Rejects																			
Incorrect Details	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	2-00%
Plate Unclear	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
Total	6-75%	0-00%	20-67%	3-75%	36-31%	14-44%	5-83%	8-27%	2-29%	1-20%	16-53%	10-26%	6-19%	16-39%	19-29%	7-19%	27-71%	14-36%	210-38%
Approved Violations	2-25%	0-00%	10-33%	1-25%	79-69%	18-56%	1-17%	22-73%	5-71%	4-80%	14-47%	29-74%	25-81%	25-61%	47-71%	29-81%	11-29%	25-64%	347-62%
Total Notices Printed	2-25%	0-00%	10-33%	1-25%	79-69%	18-56%	1-17%	22-73%	5-71%	4-80%	14-47%	29-74%	25-81%	25-61%	47-71%	29-81%	11-29%	25-64%	347-62%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 4/21/2014 3:59:23 PM



# Customer Management Report (Ventura) All Detection Types

01-Apr-2006 to 30-Apr-2006

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>		8	0	24	15	177	39	25	19	12	10	49	99	37	45	88	57	41	48	793
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	1	0	8	2	8	4	1	0	0	0	6	9	1	4	13	4	2	0	63
	Plate Obstruction	2	0	0	1	14	3	1	0	0	0	2	9	3	0	3	0	1	1	40
	Vehicle Obstruction	0	0	0	1	1	0	0	0	0	0	3	2	0	0	1	0	1	0	9
Police Rejects	Driver Unidentifiable	2	0	2	3	20	0	3	2	1	1	4	5	4	10	8	12	6	4	87
	Invalid Offense	0	0	0	3	0	8	1	3	0	0	0	10	0	0	1	0	0	6	32
Policy/Weather	Extended Vehicle	0	0	1	0	2	1	0	0	0	1	0	15	0	0	0	0	0	1	21
	Sun Glare	1	0	0	3	38	1	2	2	2	3	6	11	4	6	12	13	2	10	116
	Weather/Nature	0	0	2	0	0	1	0	0	0	1	0	0	1	0	1	2	0	1	9
Registration Issues	Can Not Identify State	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1	0	0	2
	Out of Country Plate	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Paper Plates	1	0	4	0	4	5	1	2	1	0	3	2	1	0	4	0	0	1	29
	Wrong or No DMV	0	0	1	0	4	1	0	0	0	1	1	1	0	0	1	5	1	3	19
<b>Total</b>		7	0	18	13	93	24	9	9	4	7	25	64	14	20	44	37	13	27	428
<b>Sub Total Violations</b>		1	0	6	2	84	15	16	10	8	3	24	35	23	25	44	20	28	21	365
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		1	0	6	2	84	15	16	10	8	3	24	35	23	25	44	20	28	21	365
<b>Less Rejects</b>																				
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	4-11%	0-00%	0-00%	0-00%	0-00%	1-04%	1-05%	7-02%
	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	1-00%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	1-04%	0-00%	1-05%	0-00%	0-00%	3-01%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	3-19%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-05%	0-00%	0-00%	7-02%
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:00:11 PM

# Customer Management Report (Ventura) All Detection Types

01-Apr-2006 to 30-Apr-2006

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%
Plate Not in Frame	0-00%	0-00%	0-00%	1-50%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	1-04%	1-02%	2-10%	1-04%	0-00%	8-02%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-38%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-38%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects Process Issues																			
Incorrect Details	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Too Old	0-00%	0-00%	0-00%	0-00%	4-05%	2-13%	0-00%	0-00%	0-00%	1-33%	2-08%	2-06%	1-04%	1-04%	0-00%	3-15%	0-00%	1-05%	17-05%
Total	0-00%	0-00%	0-00%	1-50%	6-07%	3-20%	4-25%	0-00%	6-75%	1-33%	3-12%	14-40%	2-09%	3-12%	2-05%	9-45%	2-07%	2-10%	58-16%
Approved Violations	1-100%	0-00%	6-100%	1-50%	78-93%	12-80%	12-75%	10-100%	2-25%	2-67%	21-88%	21-60%	21-91%	22-88%	42-95%	11-55%	26-93%	19-90%	307-84%
Total Notices Printed	1-100%	0-00%	6-100%	1-50%	78-93%	12-80%	12-75%	10-100%	2-25%	2-67%	21-88%	21-60%	21-91%	22-88%	42-95%	11-55%	26-93%	19-90%	307-84%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:00:11 PM

# Customer Management Report (Ventura) All Detection Types

01-Oct-2006 to 31-Oct-2006

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>		13	0	14	12	133	34	36	40	6	11	44	57	45	68	83	57	88	68	809
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	5	0	7	1	12	5	10	2	0	1	10	6	9	9	17	5	8	4	111
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1	0	3	0	5
	Plate Obstruction	0	0	1	2	16	8	7	3	0	2	3	8	1	0	4	8	0	6	69
	Signal Obstruction	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Vehicle Obstruction	0	0	0	0	0	0	2	1	0	0	0	0	0	0	0	1	1	4	9
Police Rejects	Plate Unidentifiable	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
	Safe Turn On Red	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
	Yielding to an Emergency	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1
Policy/Weather	Extended Vehicle	0	0	0	1	2	1	0	0	0	0	0	5	0	1	0	0	0	2	12
	Sun Glare	3	0	0	1	19	3	5	2	3	4	14	3	6	16	16	7	28	22	152
	Weather/Nature	0	0	0	1	0	1	0	0	0	0	0	0	0	0	1	2	2	0	7
	Yellow with Red Light	0	0	2	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	3
Registration Issues	Can Not Identify State	0	0	0	0	1	0	0	0	0	0	0	1	1	0	0	0	0	1	4
	Gender Match	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1
	Paper Plates	0	0	0	0	5	4	1	2	1	0	0	2	1	4	4	0	4	5	33
	Wrong or No DMV	0	0	0	0	1	0	1	1	0	0	0	1	0	2	1	0	1	0	8
<b>Total</b>	<b>8</b>	<b>0</b>	<b>10</b>	<b>6</b>	<b>58</b>	<b>22</b>	<b>26</b>	<b>12</b>	<b>4</b>	<b>7</b>	<b>27</b>	<b>26</b>	<b>18</b>	<b>34</b>	<b>45</b>	<b>24</b>	<b>51</b>	<b>40</b>	<b>418</b>	
<b>Sub Total Violations</b>		<b>5</b>	<b>0</b>	<b>4</b>	<b>6</b>	<b>75</b>	<b>12</b>	<b>10</b>	<b>28</b>	<b>2</b>	<b>4</b>	<b>17</b>	<b>31</b>	<b>27</b>	<b>34</b>	<b>38</b>	<b>33</b>	<b>37</b>	<b>28</b>	<b>391</b>
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		<b>5</b>	<b>0</b>	<b>4</b>	<b>6</b>	<b>75</b>	<b>12</b>	<b>10</b>	<b>28</b>	<b>2</b>	<b>4</b>	<b>17</b>	<b>31</b>	<b>27</b>	<b>34</b>	<b>38</b>	<b>33</b>	<b>37</b>	<b>28</b>	<b>391</b>
<b>Less Rejects</b>																				
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-03%	3-09%	1-03%	1-04%	8-02%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-20%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-03%	0-00%	2-06%	3-08%	1-04%	10-03%

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:00:51 PM

# Customer Management Report (Ventura) All Detection Types

01-Oct-2006 to 31-Oct-2006

Operator Id: %

	VE-BRU0-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-20%	0-00%	0-00%	0-00%	0-00%	1-03%	1-04%	0-00%	5-13%	1-03%	0-00%	0-00%	10-03%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	0-00%	0-00%	1-03%	0-00%	3-01%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	2-33%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	3-01%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-00%
Police Rejects																			
Driver Unidentifiable images poor	0-00%	0-00%	2-50%	0-00%	5-07%	2-17%	1-10%	2-07%	0-00%	0-00%	2-12%	6-19%	1-04%	4-12%	4-11%	0-00%	5-14%	5-18%	39-10%
Vehicle On or Passed Stop Line	0-00%	0-00%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	3-01%
Process Issues																			
Too Old	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	0-00%	0-00%	2-50%	3-50%	8-11%	2-17%	6-60%	2-07%	0-00%	0-00%	2-12%	8-26%	3-11%	9-26%	11-29%	8-24%	11-30%	8-29%	83-21%
Approved Violations	5-100%	0-00%	2-50%	3-50%	67-89%	10-83%	4-40%	26-93%	2-100%	4-100%	15-88%	23-74%	24-89%	25-74%	27-71%	25-76%	26-70%	20-71%	308-79%
Total Notices Printed	5-100%	0-00%	2-50%	3-50%	67-89%	10-83%	4-40%	26-93%	2-100%	4-100%	15-88%	23-74%	24-89%	25-74%	27-71%	25-76%	26-70%	20-71%	308-79%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:00:51 PM

# Customer Management Report (Ventura) All Detection Types

01-Apr-2007 to 30-Apr-2007

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents		12	0	26	16	147	38	15	28	9	9	51	63	38	57	82	54	63	63	771
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	4	0	9	2	15	2	2	3	2	2	9	4	1	14	15	6	3	2	95
	Motor Cycle Helmet	0	0	1	0	0	0	0	0	1	0	0	0	0	0	1	0	0	0	3
	Plate Obstruction	0	0	2	1	13	5	2	3	0	2	2	6	2	1	3	2	0	1	45
	Vehicle Obstruction	0	0	0	0	2	0	1	0	0	0	1	2	1	3	1	2	0	0	13
Police Rejects	Citation Issued manually	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1
	Emergency Vehicle Responding	1	0	0	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	3
	Incorrect Plate on Vehicle	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Safe Turn On Red	0	0	0	0	0	0	0	7	0	0	0	0	0	0	0	0	0	0	12
Policy/Weather	Extended Vehicle	0	0	0	1	1	0	0	0	0	0	1	8	0	0	0	1	0	8	20
	Sun Glare	2	0	1	1	20	2	2	1	1	1	6	3	5	21	21	5	14	13	119
	Weather/Nature	0	0	2	0	1	0	1	2	0	0	0	0	0	2	0	1	0	0	9
Registration Issues	Gender Match	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Paper Plates	0	0	0	1	2	1	0	0	1	1	2	0	1	1	0	1	1	0	12
	Wrong or No DMV	0	0	0	0	3	0	0	0	0	0	0	2	1	1	0	0	1	0	8
Total		7	0	15	7	59	10	9	16	5	6	21	25	11	43	41	18	19	30	342
Sub Total Violations		5	0	11	9	88	28	6	12	4	3	30	38	27	14	41	36	44	33	429
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		5	0	11	9	88	28	6	12	4	3	30	38	27	14	41	36	44	33	429
<b>Less Rejects</b>																				
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	2-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	2-00%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:01:37 PM

# Customer Management Report (Ventura) All Detection Types

01-Apr-2007 to 30-Apr-2007

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	2-33%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-25%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	3-01%
Police Rejects																			
Driver Unidentifiable images poor	2-40%	0-00%	1-09%	2-22%	9-10%	6-21%	1-17%	2-17%	0-00%	1-33%	7-23%	0-00%	5-19%	5-36%	11-27%	6-17%	5-11%	3-09%	66-15%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-00%
Vehicle On or Passed Stop Line	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	0-00%	1-02%	1-03%	6-01%
Total	2-40%	0-00%	1-09%	3-33%	11-12%	7-25%	4-67%	7-58%	1-25%	1-33%	7-23%	2-05%	6-22%	5-36%	12-29%	7-19%	7-16%	5-15%	88-21%
Approved Violations	3-60%	0-00%	10-91%	6-67%	77-88%	21-75%	2-33%	5-42%	3-75%	2-67%	23-77%	36-95%	21-78%	9-64%	29-71%	29-81%	37-84%	28-85%	341-79%
Total Notices Printed	3-60%	0-00%	10-91%	6-67%	77-88%	21-75%	2-33%	5-42%	3-75%	2-67%	23-77%	36-95%	21-78%	9-64%	29-71%	29-81%	37-84%	28-85%	341-79%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:01:37 PM

# Customer Management Report (Ventura) All Detection Types

01-Oct-2007 to 31-Oct-2007

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents		15	76	3	15	192	46	34	45	331	13	51	42	49	37	116	64	107	93	1329
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	2	16	2	2	15	8	12	5	37	2	8	1	5	10	20	6	7	6	164
	Motor Cycle Helmet	0	0	0	0	0	0	0	1	0	0	0	0	0	1	0	0	0	0	2
	Plate Obstruction	0	1	0	2	19	7	1	1	8	0	5	6	1	0	4	3	1	5	64
	Vehicle Obstruction	0	0	0	0	2	0	0	0	7	0	1	1	0	0	1	2	1	1	16
Police Rejects	Citation Issued manually	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
	Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0	0	2
	Incorrect/Incomplete DMV	0	1	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	2
	Invalid Offense	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1
	Police Discretion	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Safe Turn On Red	0	1	0	0	0	0	0	10	37	0	0	0	0	0	0	0	0	10	58
Policy/Weather	Extended Vehicle	1	0	0	0	8	0	0	0	0	0	0	4	1	0	0	0	0	2	16
	Sun Glare	4	8	0	1	1	2	6	3	209	4	9	1	5	11	11	16	7	13	311
	Weather/Nature	0	0	0	1	0	0	0	1	0	0	0	0	0	0	1	0	0	1	4
Registration Issues	Paper Plates	1	2	0	2	5	1	0	2	5	0	2	2	0	0	3	0	4	3	32
	Wrong or No DMV	0	0	0	0	2	0	0	0	0	0	1	1	1	0	1	0	4	0	10
Total		8	30	2	8	52	18	19	23	304	6	27	17	13	22	43	27	24	41	684
Sub Total Violations		7	46	1	7	140	28	15	22	27	7	24	25	36	15	73	37	83	52	645
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		7	46	1	7	140	28	15	22	27	7	24	25	36	15	73	37	83	52	645
Less Rejects																				
Camera Malfunction	Face Camera Flash	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
	Face Camera Focus Blurry	4-57%	0-00%	0-00%	0-00%	0-00%	0-00%	3-20%	0-00%	8-30%	0-00%	1-04%	0-00%	0-00%	0-00%	3-04%	2-05%	0-00%	0-00%	21-03%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-20%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	4-01%

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:02:15 PM

# Customer Management Report (Ventura) All Detection Types

01-Oct-2007 to 31-Oct-2007

Operator Id: %

	VE-BRU0-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Image Missing	0-00%	0-00%	0-00%	0-00%	5-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	7-01%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	4-15%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	1-14%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-14%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate No Flash	1-14%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Scene Image Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects																			
Driver Unidentifiable images poor	1-14%	3-07%	0-00%	0-00%	2-01%	2-07%	3-20%	2-09%	12-44%	0-00%	1-04%	2-08%	4-11%	3-20%	5-07%	3-08%	1-01%	4-08%	48-07%
Vehicle On or Passed Stop Line	0-00%	1-02%	0-00%	0-00%	0-00%	3-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Process Issues																			
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	2-03%	0-00%	0-00%	0-00%	3-00%
Total	7-100%	6-13%	0-00%	0-00%	9-06%	5-18%	9-60%	3-14%	26-96%	1-14%	2-08%	2-08%	6-17%	3-20%	10-14%	5-14%	1-01%	8-15%	103-16%
Approved Violations	0-00%	40-87%	1-100%	7-100%	131-94%	23-82%	6-40%	19-86%	1-04%	6-86%	22-92%	23-92%	30-83%	12-80%	63-86%	32-86%	82-99%	44-85%	542-84%
Total Notices Printed	0-00%	40-87%	1-100%	7-100%	131-94%	23-82%	6-40%	19-86%	1-04%	6-86%	22-92%	23-92%	30-83%	12-80%	63-86%	32-86%	82-99%	44-85%	542-84%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:02:15 PM



# Customer Management Report (Ventura) All Detection Types

01-Dec-2010 to 31-Dec-2010

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	12	72	9	8	64	20	29	50	205	5	19	37	21	14	16	8	41	36	666	
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	0	14	4	0	1	1	3	1	6	0	1	3	1	1	2	0	2	1	41
	Motor Cycle Helmet	0	0	0	0	1	1	0	0	2	0	0	0	0	0	0	0	0	0	4
	Plate Obstruction	3	1	0	1	0	0	1	0	0	1	0	4	0	1	0	0	0	2	14
	Vehicle Obstruction	0	1	0	0	4	0	2	0	2	0	2	1	1	0	0	0	0	0	13
Police Rejects	Citation Issued manually	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	1
	Driver Obstruction (PD)	0	1	0	0	0	0	0	0	3	0	0	2	0	1	0	0	0	0	7
	Emergency Vehicle Responding	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
	Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1
	Multiple vehicles in frame	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1
	On or Passed the Stop Bar (PD)	2	0	1	0	0	0	0	1	1	0	0	2	0	0	1	0	0	0	8
	Plate Obstruction (PD)	0	0	0	1	0	1	0	0	0	0	0	0	0	0	0	0	0	1	3
	Plate Unidentifiable	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
	Safe Turn On Red	0	15	0	0	0	0	16	106	0	0	0	0	0	0	0	0	0	4	141
	Sun Glare	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	2
Policy/Weather	Extended Vehicle	0	0	1	0	0	1	0	0	0	0	5	0	0	0	0	0	0	3	10
	Sun Glare	0	9	1	0	0	3	0	4	3	1	2	0	4	2	1	0	4	34	
Registration Issues	Out of Country Plate	0	1	0	0	0	0	0	1	0	0	0	0	0	0	1	0	0	0	3
	Paper Plates	1	0	0	0	0	1	0	6	0	0	1	1	0	0	0	0	0	0	10
	Wrong or No DMV	0	2	0	1	1	0	1	1	0	0	1	0	1	0	1	2	0	0	11
<b>Total</b>		6	45	7	3	7	8	24	131	2	6	18	5	7	6	3	6	16	306	
<b>Sub Total Violations</b>		6	27	2	5	57	12	23	26	3	13	19	16	7	10	5	35	20	360	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		6	27	2	5	57	12	23	26	3	13	19	16	7	10	5	35	20	360	

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:07:10 PM

# Customer Management Report (Ventura) All Detection Types

01-Dec-2010 to 31-Dec-2010

Operator Id: %

		VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Less Rejects</b>																				
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	2-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-23%	2-11%	0-00%	0-00%	0-00%	1-20%	0-00%	0-00%	7-02%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	1-20%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	3-11%	0-00%	0-00%	0-00%	0-00%	1-04%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-10%	7-02%
	Red-light not visible in	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total		1-17%	3-11%	0-00%	1-20%	1-02%	0-00%	3-13%	1-04%	0-00%	0-00%	4-31%	6-32%	0-00%	0-00%	0-00%	1-20%	0-00%	2-10%	23-06%
<b>Approved Violations</b>		5-83%	24-89%	2-100%	4-80%	56-98%	12-100%	20-87%	25-96%	74-100%	3-100%	9-69%	13-68%	16-100%	7-100%	10-100%	4-80%	35-100%	18-90%	337-94%
<b>Total Notices Printed</b>		5-83%	24-89%	2-100%	4-80%	56-98%	12-100%	20-87%	25-96%	74-100%	3-100%	9-69%	13-68%	16-100%	7-100%	10-100%	4-80%	35-100%	18-90%	337-94%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:07:10 PM

# Customer Management Report (Ventura) All Detection Types

01-Oct-2013 to 31-Oct-2013

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	17	160	6	14	162	44	45	94	96	10	36	87	31	65	72	41	85	55	1120	
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	1	14	1	0	1	8	2	0	1	0	1	1	0	3	9	1	4	6	53
	Motor Cycle Helmet	0	0	1	0	1	0	1	0	2	0	0	0	0	0	0	0	0	0	5
	Plate Obstruction	1	0	0	2	1	2	1	0	0	1	0	2	0	0	0	1	0	1	12
	Vehicle Obstruction	0	3	0	1	2	0	2	1	0	0	1	6	1	0	5	0	2	0	24
Police Rejects	Driver Obstruction (PD)	0	1	0	1	4	0	0	1	0	1	1	0	0	1	0	2	0	12	
	Emergency Vehicle Responding	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1	
	Incorrect/Incomplete DMV	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1	
	Multiple vehicles in frame	1	5	0	0	0	1	2	0	0	1	0	0	0	0	0	0	0	10	
	On or Passed the Stop Bar (PD).	1	1	0	2	0	0	2	0	0	0	0	1	3	4	0	0	0	14	
	Plate Obstruction (PD)	0	1	0	0	3	0	0	1	0	0	0	1	0	0	0	0	0	6	
	Plate Unidentifiable	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
	Safe Turn On Red	0	33	0	0	0	0	0	38	5	0	0	0	0	0	0	0	0	9	85
	Sun Glare	3	4	1	1	4	2	2	0	3	0	2	0	0	4	2	0	3	2	33
	Policy/Weather	Extended Vehicle	0	2	0	0	2	0	0	0	0	1	4	0	0	0	0	0	0	9
Sun Glare		0	31	0	1	10	1	10	0	10	0	2	0	8	21	2	0	13	109	
Weather/Nature		0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1	
Registration Issues	Paper Plates	0	6	0	0	7	0	2	8	0	2	1	3	0	3	2	2	1	37	
	Wrong or No DMV	0	2	0	1	3	2	0	1	1	1	2	4	1	1	2	4	2	28	
<b>Total</b>	8	103	3	9	38	16	24	50	24	5	11	23	13	36	24	8	14	32	441	
<b>Sub Total Violations</b>	9	57	3	5	124	28	21	44	72	5	25	64	18	29	48	33	71	23	679	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
<b>Available For Prosecution</b>	9	57	3	5	124	28	21	44	72	5	25	64	18	29	48	33	71	23	679	

**Less Rejects**

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:10:04 PM

# Customer Management Report (Ventura) All Detection Types

01-Oct-2013 to 31-Oct-2013

Operator Id: %

		VE-BRU0-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Camera Flash	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	2-09%	4-01%	
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%	
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-00%	
	Face Not in Frame	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	8-38%	0-00%	0-00%	1-20%	0-00%	1-02%	2-11%	0-00%	2-04%	0-00%	0-00%	0-00%	15-02%	
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	3-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-06%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	6-01%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-20%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Police Rejects Process Issues	Driver Unidentifiable images poor	1-11%	14-25%	1-33%	0-00%	0-00%	5-18%	5-24%	0-00%	3-04%	0-00%	0-00%	6-09%	1-06%	8-28%	3-06%	3-09%	1-01%	3-13%	54-08%	
	Too Old	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	1-02%	0-00%	0-00%	0-00%	3-00%	
Total		1-11%	17-30%	1-33%	1-20%	4-03%	5-18%	13-62%	4-09%	3-04%	1-20%	1-04%	12-19%	5-28%	9-31%	8-17%	3-09%	1-01%	6-26%	95-14%	
Approved Violations		8-89%	40-70%	2-67%	4-80%	120-97%	23-82%	8-38%	40-91%	69-96%	4-80%	24-96%	52-81%	13-72%	20-69%	40-83%	30-91%	70-99%	17-74%	584-86%	
Total Notices Printed		8-89%	40-70%	2-67%	4-80%	120-97%	23-82%	8-38%	40-91%	69-96%	4-80%	24-96%	52-81%	13-72%	20-69%	40-83%	30-91%	70-99%	17-74%	584-86%	

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:10:04 PM

# Customer Management Report (Ventura) All Detection Types

01-Jan-2014 to 31-Jan-2014

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents		24	143	10	17	124	52	34	69	75	8	45	73	0	43	67	52	49	63	948
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	2	24	2	1	8	10	10	2	11	1	2	12	0	15	18	1	1	7	127
	Motor Cycle Helmet	0	0	0	0	1	0	0	1	0	0	0	0	0	0	0	0	0	1	3
	Plate Obstruction	2	3	0	4	1	2	0	2	0	0	1	1	0	0	0	1	0	4	21
	Vehicle Obstruction	3	7	0	1	2	0	4	0	0	2	3	2	0	1	2	2	0	1	30
Police Rejects	Driver Obstruction (PD)	1	1	0	0	2	1	0	0	0	0	0	0	0	0	1	1	0	0	7
	Gender Mismatch	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Incorrect/Incomplete DMV	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Invalid Offense	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Multiple vehicles in frame	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	On or Passed the Stop Bar (PD)	0	2	0	0	1	1	0	0	0	0	0	1	0	0	0	0	0	1	6
	Plate Obstruction (PD)	1	0	0	1	0	1	0	0	0	0	0	0	0	0	0	0	0	0	3
	Safe Turn On Red	0	32	0	0	0	0	0	22	3	0	0	0	0	0	0	0	0	10	67
	Sun Glare	2	7	0	0	0	1	2	1	0	0	1	0	0	1	1	0	0	0	16
	Policy/Weather	Extended Vehicle	0	2	0	1	1	0	0	0	0	0	1	4	0	0	0	0	0	0
Sun Glare		0	8	2	0	1	6	2	1	0	0	1	0	0	4	1	0	0	5	31
Registration Issues	Out of Country Plate	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1
	Paper Plates	0	6	0	0	2	2	2	0	2	0	2	4	0	0	3	0	0	3	26
	Wrong or No DMV	1	1	0	0	3	1	0	4	0	0	2	2	0	1	1	0	2	1	19
Total		12	95	4	8	24	25	20	33	17	3	13	26	0	22	27	5	3	33	370
Sub Total Violations		12	48	6	9	100	27	14	36	58	5	32	47	0	21	40	47	46	30	578
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		12	48	6	9	100	27	14	36	58	5	32	47	0	21	40	47	46	30	578

## Less Rejects

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:10:38 PM

# Customer Management Report (Ventura) All Detection Types

01-Jan-2014 to 31-Jan-2014

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	2-00%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera No Flash	0-00%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	2-00%
	Face Not in Frame	0-00%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-20%	1-03%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	4-01%
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	1-11%	3-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Plate Not in Frame	0-00%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-20%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-07%	0-00%	0-00%	1-20%	2-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	6-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-14%	1-03%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%	
Police Rejects	Driver Unidentifiable images poor	1-08%	6-12%	0-00%	0-00%	3-03%	5-19%	2-14%	1-03%	0-00%	0-00%	0-00%	1-02%	0-00%	5-24%	1-02%	3-06%	3-07%	2-07%	33-06%
	Incorrect Speed	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Process Issues	Too Old	0-00%	0-00%	1-17%	0-00%	1-01%	0-00%	1-07%	0-00%	0-00%	1-20%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Total		1-08%	7-15%	4-67%	1-11%	9-09%	5-19%	7-50%	2-06%	0-00%	4-80%	7-22%	3-06%	0-00%	5-24%	4-10%	3-06%	3-07%	3-10%	68-12%
Approved Violations		11-92%	41-85%	2-33%	8-89%	91-91%	22-81%	7-50%	34-94%	58-100%	1-20%	25-78%	44-94%	0-00%	16-76%	36-90%	44-94%	43-93%	27-90%	510-88%
Total Notices Printed		11-92%	41-85%	2-33%	8-89%	91-91%	22-81%	7-50%	34-94%	58-100%	1-20%	25-78%	44-94%	0-00%	16-76%	36-90%	44-94%	43-93%	27-90%	510-88%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:10:38 PM

# Customer Management Report (Ventura) All Detection Types

01-Feb-2014 to 28-Feb-2014

Operator Id: %

		VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents		13	159	1	16	126	32	31	81	56	4	38	71	16	30	69	56	51	68	918
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	6	58	1	2	12	5	12	4	10	0	6	6	6	10	14	6	3	18	179
	Motor Cycle Helmet	0	0	0	0	2	1	0	1	1	0	0	0	0	0	0	0	0	0	5
	Plate Obstruction	0	0	0	0	1	0	0	0	0	1	0	3	0	0	1	1	0	3	10
	Vehicle Obstruction	0	13	0	1	5	0	3	0	2	0	0	5	0	0	4	0	0	1	34
Police Rejects	Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2	1	3
	Multiple vehicles in frame	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
	Plate Obstruction (PD)	0	0	0	0	1	0	0	0	0	0	0	1	0	0	0	0	0	0	2
	Plate Unidentifiable	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Police Discretion	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1	0	2
	Safe Turn On Red	0	32	0	0	0	0	0	19	3	0	0	0	0	0	0	0	0	12	66
	Sun Glare	1	2	0	1	2	1	0	0	1	0	1	1	0	3	1	0	1	2	17
Policy/Weather	Extended Vehicle	0	1	0	0	2	0	0	0	1	0	1	6	0	0	0	0	0	0	11
	Sun Glare	0	3	0	1	3	0	2	0	0	1	1	3	1	4	1	0	0	0	20
	Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1
	Paper Plates	0	1	0	4	2	0	1	1	1	0	1	2	1	1	0	1	4	5	25
	Wrong or No DMV	1	5	0	0	1	1	0	4	4	0	1	0	0	1	0	1	3	2	24
Total	8	117	1	10	31	8	18	29	23	2	12	28	9	19	21	10	13	44	403	
Sub Total Violations		5	42	0	6	95	24	13	52	33	2	26	43	7	11	48	46	38	24	515
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		5	42	0	6	95	24	13	52	33	2	26	43	7	11	48	46	38	24	515

## Less Rejects

Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-15%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-04%	5-01%
--------------------	-------------------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:12:07 PM

# Customer Management Report (Ventura) All Detection Types

01-Feb-2014 to 28-Feb-2014

Operator Id: %

		VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Manufacturing	Face Camera Focus Blurry	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-50%	0-00%	2-05%	1-14%	0-00%	4-08%	0-00%	0-00%	0-00%	9-02%
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	1-17%	3-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	2-02%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
	Rear Plate No Flash	0-00%	0-00%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-15%	0-00%	0-00%	0-00%	0-00%	0-00%	3-07%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Police Rejects	Driver Unidentifiable images poor	0-00%	6-14%	0-00%	0-00%	0-00%	3-12%	2-15%	0-00%	1-03%	0-00%	0-00%	3-07%	0-00%	0-00%	0-00%	2-04%	1-03%	1-04%	19-04%
	Incorrect Speed	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-08%	0-00%	2-29%	0-00%	0-00%	2-04%	0-00%	0-00%	7-01%
Total		0-00%	7-17%	0-00%	2-33%	7-07%	5-21%	6-46%	0-00%	2-06%	1-50%	5-19%	10-23%	3-43%	0-00%	5-10%	4-09%	1-03%	2-08%	60-12%
Approved Violations		5-100%	35-83%	0-00%	4-67%	88-93%	19-79%	7-54%	52-100%	31-94%	1-50%	21-81%	33-77%	4-57%	11-100%	43-90%	42-91%	37-97%	22-92%	455-88%
Total Notices Printed		5-100%	35-83%	0-00%	4-67%	88-93%	19-79%	7-54%	52-100%	31-94%	1-50%	21-81%	33-77%	4-57%	11-100%	43-90%	42-91%	37-97%	22-92%	455-88%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:12:07 PM



# Customer Management Report (Ventura) All Detection Types

01-Mar-2014 to 31-Mar-2014

Operator Id: %

	VE-BRUO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	17	237	5	28	134	25	35	97	93	7	78	87	6	31	88	61	65	78	1172	
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	5	62	4	6	18	7	14	5	17	0	8	11	2	9	24	1	7	12	212
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	1	2	0	0	0	0	0	2	5
	Plate Obstruction	1	3	0	4	5	0	1	2	2	1	3	6	0	0	1	3	0	6	38
	Vehicle Obstruction	0	9	0	0	6	0	6	3	0	1	2	2	0	1	4	0	2	2	38
Police Rejects	Driver Obstruction (PD)	1	0	0	0	0	0	0	2	0	0	0	0	0	1	2	1	1	0	8
	Multiple vehicles in frame	0	4	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	5
	On or Passed the Stop Bar (PD).	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1
	Plate Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1	0	2
	Plate Unidentifiable	0	0	0	2	0	0	1	0	0	0	0	0	0	0	0	0	0	1	4
	Safe Turn On Red	0	51	0	0	0	0	38	5	0	0	0	0	0	0	0	0	0	11	105
	Sun Glare	0	11	0	0	0	0	0	1	1	0	2	0	1	2	1	6	2	2	27
	Weather Conditions	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
Policy/Weather	Extended Vehicle	1	1	0	0	0	0	1	0	0	0	7	0	0	0	0	0	0	1	11
	Sun Glare	1	19	0	1	2	0	5	0	9	0	9	1	1	5	0	0	1	2	56
	Weather/Nature	1	0	0	0	1	0	0	0	1	0	0	0	0	0	0	0	1	0	4
Registration Issues	Out of Country Plate	0	1	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
	Paper Plates	1	4	0	3	5	1	0	3	3	0	1	2	0	1	1	1	1	0	27
	Wrong or No DMV	0	6	0	4	5	0	0	1	0	2	1	0	1	1	2	0	2	2	25
<b>Total</b>		11	171	4	21	42	8	28	51	41	3	27	36	3	19	36	10	19	41	571
<b>Sub Total Violations</b>		6	66	1	7	92	17	7	46	52	4	51	51	3	12	52	51	46	37	601
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		6	66	1	7	92	17	7	46	52	4	51	51	3	12	52	51	46	37	601

## Less Rejects

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:12:33 PM

# Customer Management Report (Ventura) All Detection Types

01-Mar-2014 to 31-Mar-2014

Operator Id: %

		VE-BRU0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Camera Malfunction	Face Camera Flash	0-00%	0-00%	1-100%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-14%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	1-17%	0-00%	0-00%	1-14%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	6-12%	0-00%	0-00%	0-00%	0-00%	0-00%	8-01%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-14%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Rejects	Driver Unidentifiable images poor	3-50%	8-12%	0-00%	1-14%	1-01%	4-24%	0-00%	0-00%	2-04%	1-25%	0-00%	6-12%	1-33%	0-00%	3-06%	0-00%	0-00%	0-00%	30-05%
Total		4-67%	8-12%	1-100%	2-29%	1-01%	5-29%	2-29%	2-04%	2-04%	1-25%	5-10%	14-27%	1-33%	0-00%	3-06%	0-00%	0-00%	0-00%	51-08%
Approved Violations		2-33%	58-88%	0-00%	5-71%	91-99%	12-71%	5-71%	44-96%	50-96%	3-75%	46-90%	37-73%	2-67%	12-100%	49-94%	51-100%	46-100%	37-100%	550-92%
Total Notices Printed		2-33%	58-88%	0-00%	5-71%	91-99%	12-71%	5-71%	44-96%	50-96%	3-75%	46-90%	37-73%	2-67%	12-100%	49-94%	51-100%	46-100%	37-100%	550-92%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 4/21/2014 4:12:33 PM