

# Customer Management Report (Ventura) All Detection Types

01-Oct-2001 to 31-Oct-2001

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	0	0	0	0	0	89	67	75	0	0	148	0	218	59	255	202	0	193	1306	
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	0	0	0	0	0	3	15	2	0	0	16	0	32	22	47	41	0	7	185
	Plate Obstruction	0	0	0	0	0	11	3	1	0	0	22	0	3	1	10	6	0	19	76
	Vehicle Obstruction	0	0	0	0	0	0	6	0	0	0	7	0	10	0	2	4	0	1	30
Police Rejects	Driver Unidentifiable	0	0	0	0	0	3	1	0	0	0	0	1	1	0	4	0	0	1	11
Policy/Weather	Sun Glare	0	0	0	0	0	0	1	2	0	0	18	0	24	0	14	10	0	26	95
	Yellow with Red Light	0	0	0	0	0	0	0	0	0	0	9	0	3	5	15	2	0	0	34
Registration Issues	Out of Country Plate	0	0	0	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	2
	Paper Plates	0	0	0	0	0	2	0	1	0	0	2	0	4	2	6	5	0	6	28
	Wrong or No DMV	0	0	0	0	0	2	3	3	0	0	1	0	3	0	7	2	0	7	28
<b>Total</b>		0	0	0	0	0	21	29	9	0	0	75	0	82	31	101	74	0	67	489
<b>Sub Total Violations</b>		0	0	0	0	0	68	38	66	0	0	73	0	136	28	154	128	0	126	817
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		0	0	0	0	0	68	38	66	0	0	73	0	136	28	154	128	0	126	817
<b>Less Rejects</b>																				
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-01%	3-00%
	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	4-05%	0-00%	1-01%	0-00%	8-05%	1-01%	0-00%	6-05%	21-03%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	4-06%	2-05%	4-06%	0-00%	0-00%	5-07%	0-00%	5-04%	0-00%	4-03%	33-26%	0-00%	22-17%	79-10%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	3-04%	8-21%	0-00%	0-00%	0-00%	3-04%	0-00%	3-02%	10-36%	27-18%	7-05%	0-00%	4-03%	65-08%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	5-08%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	8-01%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	20-15%	0-00%	1-01%	1-01%	0-00%	0-00%	23-03%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-02%	0-00%	0-00%	1-01%	0-00%	2-01%	5-18%	0-00%	5-04%	0-00%	3-02%	18-02%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-03%	1-02%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	4-03%	11-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	2-02%	0-00%	0-00%	6-01%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	1-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	0-00%	0-00%	0-00%	0-00%	2-00%
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	13-20%	0-00%	0-00%	1-01%	0-00%	2-01%	3-11%	1-01%	7-05%	0-00%	1-01%	29-04%
<b>Total</b>		0-00%	0-00%	0-00%	0-00%	0-00%	14-21%	13-34%	25-38%	0-00%	0-00%	17-23%	0-00%	35-26%	21-75%	42-27%	59-46%	0-00%	41-33%	267-33%
<b>Approved Violations</b>		0-00%	0-00%	0-00%	0-00%	0-00%	54-79%	25-66%	41-62%	0-00%	0-00%	56-77%	0-00%	101-74%	7-25%	112-73%	69-54%	0-00%	85-67%	550-67%
<b>Total Notices Printed</b>		0-00%	0-00%	0-00%	0-00%	0-00%	54-79%	25-66%	41-62%	0-00%	0-00%	56-77%	0-00%	101-74%	7-25%	112-73%	69-54%	0-00%	85-67%	550-67%

Generated By: JKOHAGEN  
Generated On: 9/23/2014 11:21:26 AM

# Customer Management Report (Ventura) All Detection Types

01-Oct-2001 to 31-Oct-2001

Operator Id: %

VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	-------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Mar-2002 to 31-Mar-2002

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	36	0	40	83	0	62	46	48	14	47	124	151	142	115	152	142	0	102	1304	
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	10	0	18	2	0	4	5	2	0	0	13	10	10	24	15	44	0	14	171
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1
	Plate Obstruction	3	0	2	13	0	13	0	2	0	5	13	19	8	2	7	8	0	14	109
	Vehicle Obstruction	1	0	0	1	0	1	0	1	0	1	35	3	1	0	0	2	0	2	48
Police Rejects	Driver Unidentifiable	0	0	0	1	0	2	1	0	0	2	1	4	0	0	2	0	0	1	14
Policy/Weather	Sun Glare	1	0	4	4	0	0	3	1	0	14	0	5	5	6	2	0	6	51	
	Yellow with Red Light	0	0	0	1	0	0	0	1	0	3	0	5	0	2	0	0	0	0	13
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0	0	0	2
	Out of Country Plate	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
	Paper Plates	0	0	1	3	0	1	0	0	1	2	1	7	6	5	7	4	0	2	40
	Wrong or No DMV	2	0	0	7	0	2	4	1	1	3	3	5	8	4	11	3	0	4	58
<b>Total</b>		17	0	25	32	0	23	13	8	2	14	83	49	43	40	51	65	0	43	508
<b>Sub Total Violations</b>		19	0	15	51	0	39	33	40	12	33	41	102	99	75	101	77	0	59	796
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		19	0	15	51	0	39	33	40	12	33	41	102	99	75	101	77	0	59	796
<b>Less Rejects</b>																				
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	3-03%	1-01%	0-00%	3-03%	0-00%	0-00%	1-02%	9-01%
	Face Camera Focus Blurry	1-05%	0-00%	0-00%	0-00%	0-00%	1-03%	1-03%	0-00%	0-00%	0-00%	0-00%	5-05%	3-03%	0-00%	0-00%	2-03%	0-00%	2-03%	15-02%
	Face Not in Frame	0-00%	0-00%	8-53%	0-00%	0-00%	0-00%	3-09%	0-00%	0-00%	0-00%	3-07%	1-01%	1-01%	8-11%	7-07%	15-19%	0-00%	4-07%	50-06%
	Misc Camera Issue	0-00%	0-00%	3-20%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-03%	0-00%	22-22%	1-01%	0-00%	2-02%	2-03%	0-00%	1-02%	33-04%
	Plate Burn Out	1-05%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	3-05%	7-01%
	Plate Not in Frame	2-11%	0-00%	1-07%	0-00%	0-00%	1-03%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-05%	11-01%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	0-00%	0-00%	0-00%	0-00%	1-01%	1-01%	0-00%	1-01%	0-00%	0-00%	5-08%	10-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	2-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-02%	0-00%	0-00%	0-00%	0-00%	3-03%	0-00%	2-02%	0-00%	0-00%	0-00%	7-01%
<b>Total</b>		4-21%	0-00%	13-87%	0-00%	0-00%	6-15%	8-24%	3-08%	0-00%	1-03%	3-07%	33-32%	10-10%	10-13%	16-16%	22-29%	0-00%	19-32%	148-19%
<b>Approved Violations</b>		15-79%	0-00%	2-13%	51-100%	0-00%	33-85%	25-76%	37-92%	12-100%	32-97%	38-93%	69-68%	89-90%	65-87%	85-84%	55-71%	0-00%	40-68%	648-81%
<b>Total Notices Printed</b>		15-79%	0-00%	2-13%	51-100%	0-00%	33-85%	25-76%	37-92%	12-100%	32-97%	38-93%	69-68%	89-90%	65-87%	85-84%	55-71%	0-00%	40-68%	648-81%

Generated By: JKOHAGEN  
Generated On: 9/23/2014 11:22:00 AM

# Customer Management Report (Ventura) All Detection Types

01-Mar-2002 to 31-Mar-2002

Operator Id: %

TOTAL
VE-VIVA-01
VE-VITP-03
VE-VITP-01
VE-VITG-01
VE-VIRA-01
VE-VIOP-01
VE-VIMO-01
VE-THSE-01
VE-TGDA-01
VE-MITG-01
VE-MIDE-01
VE-MAMI-01
VE-MALE-01
VE-MA10-01
VE-JONB-01
VE-FOV1-01
VE-CATH-01
VE-BRJO-01

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Sep-2002 to 30-Sep-2002

Operator Id: %

		VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents		26	0	53	61	0	53	47	26	11	24	116	86	132	91	138	127	101	115	1207	
<b>Less Uncontrollable Factors</b>																					
Obstruction	Driver Obstruction/Duckers	7	0	9	0	0	3	2	1	0	0	7	4	8	8	13	5	1	1	69	
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1	
	Plate Obstruction	1	0	5	10	0	10	6	1	0	0	3	4	7	2	7	3	5	14	78	
	Vehicle Obstruction	1	0	1	0	0	1	3	0	0	2	50	5	3	1	8	3	3	10	91	
Police Rejects	Driver Unidentifiable	0	0	2	1	0	1	1	0	0	0	1	0	4	1	1	2	2	1	17	
	Safe Turn On Red	0	0	0	1	0	0	0	0	0	0	0	0	0	2	0	2	0	0	5	
Policy/Weather	Extended Vehicle	2	0	0	0	0	2	0	0	0	0	0	16	1	1	1	0	0	0	23	
	Sun Glare	0	0	1	4	0	0	2	0	2	8	19	0	9	4	7	4	12	14	86	
	Weather/Nature	0	0	0	1	0	0	0	0	0	0	0	0	0	1	0	0	0	0	2	
	Yellow with Red Light	0	0	0	0	0	0	0	0	0	0	0	1	2	1	0	0	0	0	4	
Registration Issues	Can Not Identify State	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1	2	
	Paper Plates	0	0	0	1	0	1	0	0	1	1	1	0	6	0	1	2	3	2	19	
	Wrong or No DMV	4	0	6	3	0	6	3	2	1	1	3	8	9	6	8	10	3	8	81	
Total	15	0	24	21	0	25	17	4	4	12	84	38	50	27	46	31	29	51	478		
<b>Sub Total Violations</b>		<b>11</b>	<b>0</b>	<b>29</b>	<b>40</b>	<b>0</b>	<b>28</b>	<b>30</b>	<b>22</b>	<b>7</b>	<b>12</b>	<b>32</b>	<b>48</b>	<b>82</b>	<b>64</b>	<b>92</b>	<b>96</b>	<b>72</b>	<b>64</b>	<b>729</b>	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
<b>Available For Prosecution</b>		<b>11</b>	<b>0</b>	<b>29</b>	<b>40</b>	<b>0</b>	<b>28</b>	<b>30</b>	<b>22</b>	<b>7</b>	<b>12</b>	<b>32</b>	<b>48</b>	<b>82</b>	<b>64</b>	<b>92</b>	<b>96</b>	<b>72</b>	<b>64</b>	<b>729</b>	
<b>Less Rejects</b>																					
Camera Malfunction	Digital Distortion	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	3-00%	
	Face Camera Flash	0-00%	0-00%	0-00%	3-08%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	3-06%	0-00%	0-00%	0-00%	0-00%	3-04%	0-00%	11-02%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	2-03%	1-01%	0-00%	4-06%	1-02%	11-02%
	Face Camera No Flash	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	2-00%
	Face Not in Frame	0-00%	0-00%	5-17%	0-00%	0-00%	2-07%	7-23%	0-00%	0-00%	1-08%	2-06%	3-06%	3-04%	5-08%	10-11%	2-02%	0-00%	3-05%	43-06%	
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	0-00%	0-00%	1-03%	3-08%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	14-22%	0-00%	0-00%	4-06%	0-00%	23-03%	
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	6-07%	1-01%	24-33%	6-09%	39-05%	
	Plate Not in Frame	0-00%	0-00%	2-07%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	2-06%	2-04%	0-00%	0-00%	1-01%	3-03%	2-03%	5-08%	18-02%	
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-03%	2-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%	
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-03%	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	5-01%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Scene Image No Flash	0-00%	0-00%	2-07%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Process Issues	Too Old	0-00%	0-00%	4-14%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	2-06%	1-02%	1-01%	3-05%	3-03%	5-05%	0-00%	2-03%	22-03%	
Total		0-00%	0-00%	15-52%	8-20%	0-00%	7-25%	12-40%	1-05%	0-00%	3-25%	8-25%	14-29%	4-05%	24-38%	22-24%	11-11%	41-57%	18-28%	188-26%	

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:22:39 AM

# Customer Management Report (Ventura) All Detection Types

01-Sep-2002 to 30-Sep-2002

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Approved Violations	11-100%	0-00%	14-48%	32-80%	0-00%	21-75%	18-60%	21-95%	7-100%	9-75%	24-75%	34-71%	78-95%	40-62%	70-76%	85-89%	31-43%	46-72%	541-74%
Total Notices Printed	11-100%	0-00%	14-48%	32-80%	0-00%	21-75%	18-60%	21-95%	7-100%	9-75%	24-75%	34-71%	78-95%	40-62%	70-76%	85-89%	31-43%	46-72%	541-74%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Mar-2003 to 31-Mar-2003

Operator Id: %

		VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>		24	0	41	62	0	50	34	41	9	18	65	108	106	73	137	143	95	94	1100	
<b>Less Uncontrollable Factors</b>																					
Obstruction	Driver Obstruction/Duckers	9	0	14	3	0	4	1	2	0	0	4	6	4	11	12	4	3	5	82	
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	0	0	2	0	0	0	0	0	2	
	Plate Obstruction	2	0	1	7	0	1	0	0	0	0	3	3	3	3	8	6	2	11	50	
	Vehicle Obstruction	2	0	0	3	0	2	0	1	1	2	36	15	3	1	4	4	5	4	83	
Police Rejects	Driver Unidentifiable	0	0	1	0	0	0	0	0	0	0	1	1	0	0	0	0	1	1	5	
	Invalid Offense	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1	
Policy/Weather	Extended Vehicle	0	0	0	2	0	1	0	2	0	0	0	13	0	0	1	0	1	1	21	
	Sun Glare	0	0	0	3	0	2	1	2	0	2	1	4	4	4	13	15	56	14	121	
	Weather/Nature	0	0	0	1	0	0	0	0	0	0	0	0	0	1	0	0	1	0	3	
	Yellow with Red Light	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1	
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1	
	Out of Country Plate	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1	
	Paper Plates	2	0	1	2	0	1	2	1	0	0	0	4	2	2	3	1	2	4	27	
	Wrong or No DMV	0	0	1	4	0	4	0	2	0	2	1	4	5	2	6	7	1	5	44	
<b>Total</b>	15	0	18	25	0	15	4	10	10	1	7	46	51	24	24	47	37	72	46	442	
<b>Sub Total Violations</b>		9	0	23	37	0	35	30	31	8	11	19	57	82	49	90	106	23	48	658	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
<b>Available For Prosecution</b>		9	0	23	37	0	35	30	31	8	11	19	57	82	49	90	106	23	48	658	
<b>Less Rejects</b>																					
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
	Face Camera Flash	0-00%	0-00%	1-04%	2-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-09%	3-04%	0-00%	1-01%	1-01%	3-13%	0-00%	16-02%
	Face Camera Focus Blurry	2-22%	0-00%	1-04%	12-32%	0-00%	3-09%	1-03%	0-00%	0-00%	0-00%	1-09%	6-32%	10-18%	0-00%	21-43%	4-04%	3-03%	8-35%	6-12%	78-12%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
	Face Not in Frame	0-00%	0-00%	5-22%	1-03%	0-00%	1-03%	11-37%	0-00%	0-00%	0-00%	0-00%	1-05%	3-05%	5-06%	1-02%	16-18%	1-01%	1-04%	3-06%	49-07%
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	9-18%	0-00%	2-02%	0-00%	0-00%	12-02%
	Plate Burn Out	0-00%	0-00%	1-04%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Plate Not in Frame	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	2-02%	3-03%	1-04%	3-06%	13-02%
	Rear Plate Camera Blurry	0-00%	0-00%	1-04%	1-03%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	5-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	2-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Scene Image No Flash	0-00%	0-00%	2-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Process Issues	Incorrect Details	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	2-00%

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:23:09 AM

# Customer Management Report (Ventura) All Detection Types

01-Mar-2003 to 31-Mar-2003

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total	2-22%	0-00%	12-52%	16-43%	0-00%	6-17%	13-43%	2-06%	1-12%	1-09%	8-42%	21-37%	9-11%	31-63%	26-29%	14-13%	13-57%	14-29%	189-29%
Approved Violations	7-78%	0-00%	11-48%	21-57%	0-00%	29-83%	17-57%	29-94%	7-88%	10-91%	11-58%	36-63%	73-89%	18-37%	64-71%	92-87%	10-43%	34-71%	469-71%
Total Notices Printed	7-78%	0-00%	11-48%	21-57%	0-00%	29-83%	17-57%	29-94%	7-88%	10-91%	11-58%	36-63%	73-89%	18-37%	64-71%	92-87%	10-43%	34-71%	469-71%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current



# Customer Management Report (Ventura) All Detection Types

01-Apr-2003 to 01-Apr-2003

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	1	0	0	4	0	1	0	2	0	1	3	7	2	2	3	4	5	7	42	
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers																			
	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1	2	
	Vehicle Obstruction																			
	0	0	0	0	0	0	0	0	0	0	2	1	0	0	0	0	0	0	3	
Police Rejects	Driver Unidentifiable																			
	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	
	Policy/Weather																			
	0	0	0	1	0	0	0	0	0	0	1	1	1	0	0	0	1	0	5	
Registration Issues	Paper Plates																			
	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	1	
<b>Total</b>	0	0	0	1	0	0	0	0	0	0	3	2	2	0	0	1	2	1	12	
<b>Sub Total Violations</b>	1	0	0	3	0	1	0	2	0	1	0	5	0	2	3	3	3	6	30	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
<b>Available For Prosecution</b>	1	0	0	3	0	1	0	2	0	1	0	5	0	2	3	3	3	6	30	
<b>Less Rejects</b>																				
Camera Malfunction	Face Camera Focus Blurry																			
	0-00%	0-00%	0-00%	1-33%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-67%	1-17%	4-13%
	Face Not in Frame																			
	0-00%	0-00%	0-00%	1-33%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-40%	0-00%	1-50%	0-00%	0-00%	0-00%	0-00%	4-13%	
	Rear Plate Camera Blurry																			
	1-100%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	
<b>Total</b>	1-100%	0-00%	0-00%	2-67%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-40%	0-00%	1-50%	0-00%	0-00%	0-00%	2-67%	1-17%	9-30%
<b>Approved Violations</b>	0-00%	0-00%	0-00%	1-33%	0-00%	1-100%	0-00%	2-100%	0-00%	1-100%	0-00%	3-60%	0-00%	1-50%	3-100%	3-100%	1-33%	5-83%	21-70%	
<b>Total Notices Printed</b>	0-00%	0-00%	0-00%	1-33%	0-00%	1-100%	0-00%	2-100%	0-00%	1-100%	0-00%	3-60%	0-00%	1-50%	3-100%	3-100%	1-33%	5-83%	21-70%	

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:23:35 AM

# Customer Management Report (Ventura) All Detection Types

01-Sep-2003 to 30-Sep-2003

Operator Id: %

		VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents		22	0	34	46	0	58	12	53	7	21	88	97	45	76	119	111	102	98	989	
<b>Less Uncontrollable Factors</b>																					
Obstruction	Driver Obstruction/Duckers	4	0	11	1	0	1	1	1	0	1	1	4	2	11	9	1	9	1	58	
	Plate Obstruction	3	0	0	3	0	6	0	2	1	1	4	6	2	1	5	2	2	8	46	
	Vehicle Obstruction	1	0	0	3	0	0	1	0	0	0	40	9	0	0	4	6	0	3	67	
Police Rejects	Driver Unidentifiable	0	0	0	1	0	2	0	2	0	0	0	0	1	3	2	5	2	2	20	
	Safe Turn On Red	0	0	0	0	0	1	0	0	0	0	1	0	0	0	0	0	0	0	2	
Policy/Weather	Extended Vehicle	1	0	0	1	0	1	0	0	0	0	0	11	0	0	1	0	1	4	20	
	Sun Glare	0	0	0	3	0	0	0	0	1	2	8	0	0	1	3	1	6	2	27	
	Weather/Nature	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1	
	Yellow with Red Light	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1	
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	1	1	0	2	0	1	0	5	
	Paper Plates	0	0	2	1	0	2	0	2	0	0	1	0	1	4	1	3	1	4	22	
	Wrong or No DMV	0	0	0	2	0	1	1	2	0	3	0	3	2	5	2	3	2	4	30	
Total		9	0	13	15	0	14	4	9	2	7	55	34	9	25	30	21	24	28	299	
Sub Total Violations		13	0	21	31	0	44	8	44	5	14	33	63	36	51	89	90	78	70	690	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution		13	0	21	31	0	44	8	44	5	14	33	63	36	51	89	90	78	70	690	
<b>Less Rejects</b>																					
Camera Malfunction	Databar Unreadable/Incorrect	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Camera Flash	0-00%	0-00%	0-00%	12-39%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	2-06%	7-11%	1-03%	0-00%	0-00%	3-03%	42-54%	5-07%	73-11%
	Face Camera Focus Blurry	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	1-02%	0-00%	5-10%	2-02%	1-01%	3-04%	1-01%	16-02%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-06%	0-00%	5-01%
	Face Not in Frame	2-15%	0-00%	3-14%	1-03%	0-00%	2-05%	2-25%	2-05%	0-00%	0-00%	2-06%	0-00%	5-14%	2-04%	12-13%	0-00%	0-00%	1-01%	34-05%	
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	4-01%
	Misc Camera Issue	1-08%	0-00%	0-00%	1-03%	0-00%	1-02%	1-12%	0-00%	0-00%	0-00%	0-00%	1-03%	1-02%	2-06%	6-12%	1-01%	0-00%	0-00%	1-01%	16-02%
	Plate Burn Out	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	6-08%	0-00%	8-01%
	Plate Not in Frame	0-00%	0-00%	3-14%	1-03%	0-00%	0-00%	1-12%	1-02%	0-00%	1-07%	2-06%	0-00%	0-00%	10-20%	0-00%	1-01%	0-00%	2-03%	22-03%	
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	2-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-02%	0-00%	0-00%	0-00%	0-00%	1-01%	4-06%	9-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	1-01%	0-00%	0-00%	2-03%	5-01%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-60%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	4-01%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	2-00%
Process Issues	Too Old	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	1-01%	1-01%	1-01%	6-01%	
Total		4-31%	0-00%	8-38%	17-55%	0-00%	4-09%	4-50%	5-11%	3-60%	2-14%	10-30%	12-19%	9-25%	23-45%	20-22%	8-09%	59-76%	17-24%	205-30%	
Approved Violations		9-69%	0-00%	13-62%	14-45%	0-00%	40-91%	4-50%	39-89%	2-40%	12-86%	23-70%	51-81%	27-75%	28-55%	69-78%	82-91%	19-24%	53-76%	485-70%	
Total Notices Printed		9-69%	0-00%	13-62%	14-45%	0-00%	40-91%	4-50%	39-89%	2-40%	12-86%	23-70%	51-81%	27-75%	28-55%	69-78%	82-91%	19-24%	53-76%	485-70%	

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:24:07 AM

# Customer Management Report (Ventura) All Detection Types

01-Sep-2003 to 30-Sep-2003

Operator Id: %

VE-VIVA-01	VE-VITP-03	VE-VITP-01	VE-VITG-01	VE-VIRA-01	VE-VIOP-01	VE-VIMO-01	VE-THSE-01	VE-TGDA-01	VE-MITG-01	VE-MIDE-01	VE-MAMI-01	VE-MALE-01	VE-MA10-01	VE-JONB-01	VE-FOV1-01	VE-CATH-01	VE-BRJO-01	TOTAL
------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	-------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Mar-2004 to 31-Mar-2004

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	19	0	21	49	19	3	27	29	8	23	65	100	37	50	95	20	83	29	677	
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	4	0	6	2	0	0	2	2	0	1	6	6	1	6	6	0	7	1	50
	Plate Obstruction	1	0	1	1	5	0	1	3	0	2	7	5	0	2	9	1	1	2	41
	Vehicle Obstruction	0	0	0	2	0	0	3	0	0	0	26	5	0	0	0	0	2	1	39
Police Rejects	Other	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	1
	Safe Turn On Red	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
	Vehicle Does Not Appear In All	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Policy/Weather	Extended Vehicle	0	0	0	1	0	0	0	0	0	0	16	0	0	1	0	0	1	0	19
	Sun Glare	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1	0	0	2
	Weather/Nature	0	0	0	0	0	0	1	0	0	0	0	0	1	0	0	0	0	0	2
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
	Paper Plates	0	0	0	1	0	0	1	0	2	1	5	1	2	4	0	2	0	0	19
	Wrong or No DMV	0	0	0	3	2	1	2	0	1	1	3	2	1	3	3	3	2	2	28
<b>Total</b>		5	0	7	10	8	1	9	7	1	7	41	4	12	24	4	17	7	204	
<b>Sub Total Violations</b>		14	0	14	39	11	2	18	22	7	16	24	33	38	71	16	66	22	473	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		14	0	14	39	11	2	18	22	7	16	24	33	38	71	16	66	22	473	
<b>Less Rejects</b>																				
Camera Malfunction	Face Camera Flash	0-00%	0-00%	1-07%	8-21%	0-00%	0-00%	1-06%	1-05%	0-00%	0-00%	2-08%	9-15%	2-06%	1-03%	2-03%	0-00%	19-29%	5-23%	51-11%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-03%	0-00%	0-00%	4-06%	0-00%	7-01%
	Face Camera No Flash	0-00%	0-00%	0-00%	9-23%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	10-02%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	2-03%	0-00%	0-00%	0-00%	5-01%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	3-09%	0-00%	16-23%	0-00%	12-18%	0-00%	32-07%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Rear Plate Camera Blurry	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-01%	0-00%	1-02%	1-05%	6-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-29%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	1-05%	4-01%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-29%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Scene Image No Flash	0-00%	0-00%	2-14%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Rejects	Unclear Images	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	1-02%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	3-01%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Vehicle On or Passed Stop Line	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	4-07%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	6-01%
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	1-00%
<b>Total</b>		1-07%	0-00%	3-21%	18-46%	0-00%	0-00%	3-17%	2-09%	4-57%	1-06%	4-17%	19-32%	5-15%	4-11%	22-31%	2-12%	36-55%	8-36%	132-28%
<b>Approved Violations</b>		13-93%	0-00%	11-79%	21-54%	11-100%	2-100%	15-83%	20-91%	3-43%	15-94%	20-83%	41-68%	28-85%	34-89%	49-69%	14-88%	30-45%	14-64%	341-72%

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:24:40 AM

# Customer Management Report (Ventura) All Detection Types

01-Mar-2004 to 31-Mar-2004

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Notices Printed	13-93%	0-00%	11-79%	21-54%	11-100%	2-100%	15-83%	20-91%	3-43%	15-94%	20-83%	41-68%	28-85%	34-89%	49-69%	14-88%	30-45%	14-64%	341-72%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Sep-2004 to 30-Sep-2004

Operator Id: %

		VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents		19	0	40	6	200	21	10	29	8	8	94	58	65	69	61	101	178	55	1022
Less Uncontrollable Factors																				
Obstruction	Driver Obstruction/Duckers	4	0	7	0	8	0	2	7	0	0	3	2	2	7	5	1	2	0	50
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
	Plate Obstruction	1	0	0	0	20	1	1	1	0	0	4	1	1	3	2	0	0	6	41
	Vehicle Obstruction	0	0	0	0	3	0	0	0	0	0	1	3	0	0	1	0	0	1	9
Police Rejects	Driver Unidentifiable	0	0	0	0	1	0	0	0	0	0	1	0	0	0	0	0	0	0	2
	Invalid Offense	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Policy/Weather	Extended Vehicle	0	0	0	0	2	0	0	1	1	0	0	5	0	1	0	0	0	4	14
	Sun Glare	0	0	0	0	16	0	0	1	1	0	10	0	0	1	2	0	3	2	36
	Weather/Nature	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Yellow with Red Light	0	0	0	0	0	0	0	1	0	0	0	1	0	0	0	0	0	0	2
Registration Issues	Can Not Identify State	0	0	1	0	1	0	0	0	0	0	0	0	0	0	1	0	0	0	3
	Out of Country Plate	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0	2
	Paper Plates	1	0	0	0	14	1	0	0	1	0	4	1	2	1	4	0	3	3	35
	Wrong or No DMV	0	0	0	0	5	0	1	0	0	0	2	1	4	0	0	0	1	4	18
Total		6	0	8	0	71	2	4	12	3	0	26	14	10	13	15	2	9	20	215
Sub Total Violations		13	0	32	6	129	19	6	17	5	8	68	44	55	56	46	99	169	35	807
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		13	0	32	6	129	19	6	17	5	8	68	44	55	56	46	99	169	35	807
Less Rejects																				
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-25%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	1-01%	0-00%	5-01%
	Face Camera Flash	0-00%	0-00%	0-00%	4-67%	6-05%	0-00%	0-00%	2-12%	1-20%	0-00%	10-15%	5-11%	3-05%	4-07%	4-09%	0-00%	4-02%	5-14%	48-06%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	1-01%	2-05%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	5-01%
	Face Not in Frame	3-23%	0-00%	3-09%	0-00%	1-01%	0-00%	3-50%	1-06%	0-00%	0-00%	0-00%	0-00%	2-04%	13-23%	10-22%	1-01%	0-00%	2-06%	39-05%
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	9-47%	0-00%	0-00%	0-00%	1-12%	0-00%	17-39%	0-00%	0-00%	0-00%	18-18%	32-19%	0-00%	77-10%
	Misc Camera Issue	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	2-33%	0-00%	0-00%	1-12%	0-00%	7-16%	8-15%	1-02%	0-00%	52-53%	96-57%	0-00%	168-21%
	Plate Burn Out	2-15%	0-00%	0-00%	0-00%	14-11%	0-00%	0-00%	0-00%	0-00%	0-00%	13-19%	0-00%	6-11%	0-00%	0-00%	0-00%	11-07%	0-00%	46-06%
	Plate Not in Frame	3-23%	0-00%	11-34%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	1-01%	2-05%	0-00%	28-50%	0-00%	0-00%	1-01%	0-00%	47-06%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	1-17%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	1-03%	0-00%	3-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-02%	0-00%	0-00%	1-01%	2-06%	9-01%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Scene Image Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-25%	1-01%	0-00%	0-00%	0-00%	0-00%	1-01%	3-02%	0-00%	7-01%
Police Rejects	Unclear Images	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	1-02%	2-04%	1-02%	0-00%	0-00%	0-00%	6-01%

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:25:07 AM

# Customer Management Report (Ventura) All Detection Types

01-Sep-2004 to 30-Sep-2004

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Process																			
Too Old																			
Issues	0-00%	0-00%	2-06%	0-00%	5-04%	0-00%	0-00%	0-00%	0-00%	1-12%	5-07%	1-02%	2-04%	0-00%	0-00%	9-09%	3-02%	0-00%	28-03%
Total	9-69%	0-00%	18-56%	5-83%	31-24%	11-58%	5-83%	5-29%	1-20%	7-88%	32-47%	40-91%	22-40%	49-88%	15-33%	83-84%	153-91%	10-29%	496-61%
Approved Violations	4-31%	0-00%	14-44%	1-17%	98-76%	8-42%	1-17%	12-71%	4-80%	1-12%	36-53%	4-09%	33-60%	7-12%	31-67%	16-16%	16-09%	25-71%	311-39%
Total Notices Printed	4-31%	0-00%	14-44%	1-17%	98-76%	8-42%	1-17%	12-71%	4-80%	1-12%	36-53%	4-09%	33-60%	7-12%	31-67%	16-16%	16-09%	25-71%	311-39%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:25:07 AM

# Customer Management Report (Ventura) All Detection Types

01-Mar-2005 to 31-Mar-2005

Operator Id: %

		VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Total Processed Incidents		10	0	34	7	158	51	34	36	6	13	53	90	40	62	41	86	107	83	911	
<b>Less Uncontrollable Factors</b>																					
Obstruction	Driver Obstruction/Duckers	0	0	5	0	9	0	5	0	0	0	0	6	3	5	3	1	3	0	40	
	Motor Cycle Helmet	0	0	0	0	0	1	0	0	0	0	0	1	0	0	0	0	0	0	2	
	Plate Obstruction	1	0	2	0	26	7	4	1	0	0	4	14	0	2	0	2	1	17	81	
	Signal Obstruction	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
	Vehicle Obstruction	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	3	
Police Rejects	Driver Unidentifiable	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	
	Other	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
	Safe Turn On Red	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1	1	0	3	
Policy/Weather	Extended Vehicle	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	
	Sun Glare	0	0	1	0	10	1	0	0	1	0	3	0	0	0	0	0	8	6	30	
Registration Issues	Out of Country Plate	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	2	
	Paper Plates	0	0	0	0	6	3	1	0	1	1	2	4	4	0	0	3	7	2	34	
	Wrong or No DMV	0	0	0	0	6	0	0	0	0	1	4	5	1	0	1	1	2	4	25	
Total		1	0	8	0	62	13	10	1	2	2	13	31	8	7	4	9	23	30	224	
Sub Total Violations		9	0	26	7	96	38	24	35	4	11	40	59	32	55	37	77	84	53	687	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution		9	0	26	7	96	38	24	35	4	11	40	59	32	55	37	77	84	53	687	
<b>Less Rejects</b>																					
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%	
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-00%	
	Face Not in Frame	3-33%	0-00%	5-19%	0-00%	0-00%	1-03%	6-25%	1-03%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	16-29%	13-35%	1-01%	1-01%	0-00%	48-07%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Plate Not in Frame	1-11%	0-00%	4-15%	1-14%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-02%	0-00%	2-04%	0-00%	1-01%	1-01%	1-02%	14-02%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	2-08%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	7-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-05%	0-00%	0-00%	0-00%	0-00%	3-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-05%	0-00%	0-00%	0-00%	0-00%	3-00%	
Police Rejects	Expired Time	0-00%	0-00%	0-00%	0-00%	0-00%	2-05%	0-00%	3-09%	0-00%	0-00%	1-02%	0-00%	1-03%	0-00%	1-03%	0-00%	0-00%	1-02%	9-01%	
	Unclear Images	2-22%	0-00%	2-08%	3-43%	5-05%	4-11%	1-04%	4-11%	2-50%	1-09%	9-22%	13-22%	1-03%	9-16%	0-00%	10-13%	24-29%	10-19%	100-15%	
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-02%	2-00%	
Total		6-67%	0-00%	11-42%	4-57%	8-08%	8-21%	9-38%	8-23%	2-50%	1-09%	12-30%	17-29%	2-06%	33-60%	15-41%	14-18%	26-31%	16-30%	192-28%	
Approved Violations		3-33%	0-00%	15-58%	3-43%	88-92%	30-79%	15-62%	27-77%	2-50%	10-91%	28-70%	42-71%	30-94%	22-40%	22-59%	63-82%	58-69%	37-70%	495-72%	

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:25:45 AM



# Customer Management Report (Ventura) All Detection Types

01-Mar-2005 to 31-Mar-2005

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Notices Printed	3-33%	0-00%	15-58%	3-43%	88-92%	30-79%	15-62%	27-77%	2-50%	10-91%	28-70%	42-71%	30-94%	22-40%	22-59%	63-82%	58-69%	37-70%	495-72%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Sep-2005 to 30-Sep-2005

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	14	0	55	6	171	56	23	28	8	15	66	70	19	54	111	75	109	82	962	
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	6	0	13	0	15	3	7	0	0	1	3	3	0	11	14	6	6	4	92
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
	Plate Obstruction	0	0	0	0	25	8	2	1	1	0	3	10	1	1	4	6	2	10	74
	Vehicle Obstruction	2	0	0	1	3	1	1	0	0	0	2	4	0	0	1	1	1	1	18
Police Rejects	Driver Unidentifiable	0	0	0	0	3	5	1	0	0	2	1	6	0	6	3	9	11	8	55
	Invalid Offense	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
	Safe Turn On Red	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	0	0	0	0	3	0	0	1	0	0	0	1	5
	Sun Glare	0	0	1	0	23	5	3	0	7	18	1	1	2	21	4	50	18	154	
	Weather/Nature	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Registration Issues	Can Not Identify State	0	0	0	0	2	0	0	0	0	0	0	0	0	1	0	0	0	0	3
	Paper Plates	1	0	0	0	12	4	1	0	0	0	6	1	1	4	1	1	4	36	
	Wrong or No DMV	0	0	0	0	0	1	2	2	0	0	1	0	0	7	3	4	3	23	
<b>Total</b>		9	0	14	2	83	27	17	4	10	27	34	3	22	56	30	75	50	464	
<b>Sub Total Violations</b>		5	0	41	4	88	29	6	24	7	5	39	36	16	32	55	45	34	32	498
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		5	0	41	4	88	29	6	24	7	5	39	36	16	32	55	45	34	32	498
<b>Less Rejects</b>																				
Camera Malfunction	Face Camera Flash	0-00%	0-00%	2-05%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-20%	1-03%	1-03%	0-00%	1-03%	2-04%	0-00%	3-09%	3-09%	15-03%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	2-06%	3-05%	2-04%	2-06%	1-03%	12-02%
	Face Not in Frame	3-60%	0-00%	10-24%	0-00%	1-01%	0-00%	2-33%	2-08%	0-00%	0-00%	0-00%	1-03%	2-12%	2-06%	8-15%	2-04%	2-06%	0-00%	35-07%
	Misc Camera Issue	0-00%	0-00%	1-02%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	3-05%	0-00%	0-00%	1-03%	8-02%
	Plate Burn Out	0-00%	0-00%	1-02%	0-00%	2-02%	1-03%	0-00%	0-00%	0-00%	0-00%	8-21%	0-00%	0-00%	9-28%	0-00%	0-00%	3-09%	0-00%	24-05%
	Plate Not in Frame	1-20%	0-00%	2-05%	1-25%	1-01%	0-00%	0-00%	0-00%	1-14%	0-00%	2-05%	0-00%	0-00%	2-06%	2-04%	1-02%	1-03%	0-00%	14-03%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	8-09%	2-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-02%	0-00%	0-00%	4-12%	16-03%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	4-01%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-03%	2-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
	Scene Image No Flash	0-00%	0-00%	12-29%	0-00%	0-00%	0-00%	0-00%	7-29%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	20-04%
Police Rejects Process Issues	Incorrect Details	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Too Old	0-00%	0-00%	0-00%	0-00%	1-01%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-07%	0-00%	0-00%	5-01%
<b>Total</b>		4-80%	0-00%	30-73%	1-25%	17-19%	6-21%	3-50%	10-42%	1-14%	1-20%	12-31%	5-14%	2-12%	18-56%	19-35%	8-18%	11-32%	11-34%	159-32%
<b>Approved Violations</b>		1-20%	0-00%	11-27%	3-75%	71-81%	23-79%	3-50%	14-58%	6-86%	4-80%	27-69%	31-86%	14-88%	14-44%	36-65%	37-82%	23-68%	21-66%	339-68%

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:26:23 AM

# Customer Management Report (Ventura) All Detection Types

01-Sep-2005 to 30-Sep-2005

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Notices Printed	1-20%	0-00%	11-27%	3-75%	71-81%	23-79%	3-50%	14-58%	6-86%	4-80%	27-69%	31-86%	14-88%	14-44%	36-65%	37-82%	23-68%	21-66%	339-68%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Mar-2006 to 31-Mar-2006

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL		
<b>Total Processed Incidents</b>	19	0	69	33	258	51	38	34	5	14	59	87	23	64	99	45	83	77	1058		
<b>Less Uncontrollable Factors</b>																					
Obstruction	Driver Obstruction/Duckers	4	0	37	14	24	5	6	3	0	2	8	11	2	17	23	8	2	4	170	
	Motor Cycle Helmet	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
	Plate Obstruction	0	0	5	4	22	6	2	0	0	1	11	0	2	2	3	1	5	64		
	Signal Obstruction	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1	0	2		
	Vehicle Obstruction	1	0	1	1	12	0	0	0	0	3	2	0	1	0	0	0	1	22		
Police Rejects	Driver Unidentifiable	0	0	1	0	19	1	2	1	1	0	2	1	0	2	2	0	9	8	49	
	Invalid Offense	0	0	0	0	4	4	0	0	0	0	6	0	0	1	0	0	3	18		
Policy/Weather	Extended Vehicle	1	0	0	0	2	1	0	0	1	0	6	0	0	0	1	0	2	14		
	Sun Glare	0	0	0	1	33	1	3	3	1	1	9	5	3	2	10	6	8	98		
	Weather/Nature	1	0	1	0	0	1	1	0	0	0	0	0	0	1	0	1	1	7		
Registration Issues	Can Not Identify State	0	0	0	0	4	0	0	0	0	0	0	0	0	0	0	0	1	5		
	Out of Country Plate	0	0	1	0	1	0	0	0	0	0	0	0	0	0	0	0	0	2		
	Paper Plates	1	0	2	0	4	1	2	1	1	1	3	1	0	2	0	3	0	22		
	Wrong or No DMV	0	0	0	0	11	1	1	1	1	2	1	1	1	2	0	4	2	28		
<b>Total</b>		8	0	48	20	137	21	17	9	3	6	26	46	7	25	43	18	29	39	502	
<b>Sub Total Violations</b>		11	0	21	13	121	30	21	25	2	8	33	41	16	39	56	27	54	38	556	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
<b>Available For Prosecution</b>		11	0	21	13	121	30	21	25	2	8	33	41	16	39	56	27	54	38	556	
<b>Less Rejects</b>																					
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-00%	
	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	2-00%	
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-04%	0-00%	1-03%	5-01%	
	Face Not in Frame	1-09%	0-00%	5-24%	0-00%	5-04%	1-03%	8-38%	0-00%	0-00%	1-12%	3-09%	0-00%	0-00%	6-15%	8-14%	1-04%	0-00%	0-00%	39-07%	
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%	
	Misc Camera Issue	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	2-05%	4-01%	
	Plate Burn Out	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
	Plate Not in Frame	0-00%	0-00%	1-05%	3-23%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-05%	0-00%	0-00%	1-02%	0-00%	9-02%	
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-12%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-13%	8-01%
	Rear Plate Flash Inappropriate	1-09%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Police Rejects	Incorrect Details	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	2-00%	
<b>Total</b>		2-18%	0-00%	6-29%	5-38%	11-09%	2-07%	8-38%	0-00%	0-00%	2-25%	3-09%	5-12%	0-00%	9-23%	9-16%	3-11%	3-06%	8-21%	76-14%	
<b>Approved Violations</b>		9-82%	0-00%	15-71%	8-62%	110-91%	28-93%	13-62%	25-100%	2-100%	6-75%	30-91%	36-88%	16-100%	30-77%	47-84%	24-89%	51-94%	30-79%	480-86%	
<b>Total Notices Printed</b>		9-82%	0-00%	15-71%	8-62%	110-91%	28-93%	13-62%	25-100%	2-100%	6-75%	30-91%	36-88%	16-100%	30-77%	47-84%	24-89%	51-94%	30-79%	480-86%	

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:27:02 AM

# Customer Management Report (Ventura) All Detection Types

01-Mar-2006 to 31-Mar-2006

Operator Id: %

VE-VIVA-01	VE-VITP-03	VE-VITP-01	VE-VITG-01	VE-VIRA-01	VE-VIOP-01	VE-VIMO-01	VE-THSE-01	VE-TGDA-01	VE-MITG-01	VE-MIDE-01	VE-MAMI-01	VE-MALE-01	VE-MA10-01	VE-JONB-01	VE-FOV1-01	VE-CATH-01	VE-BRJO-01	TOTAL
------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	-------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Sep-2006 to 30-Sep-2006

Operator Id: %

		VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents		24	0	36	18	150	38	30	36	13	16	60	82	32	40	112	82	64	70	903
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	10	0	5	0	10	4	2	0	1	2	10	12	1	5	10	13	4	7	96
	Motor Cycle Helmet	0	0	0	0	1	1	0	0	0	0	1	0	0	0	0	0	0	0	3
	Plate Obstruction	2	0	0	1	11	5	3	1	0	0	2	9	0	0	5	0	0	4	43
	Vehicle Obstruction	1	0	0	0	3	0	1	0	0	0	1	2	1	1	3	2	2	0	17
Police Rejects	Citation Issued manually	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
	Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1
Policy/Weather	Extended Vehicle	0	0	0	0	1	1	0	0	1	1	0	4	0	0	0	0	0	2	10
	Sun Glare	1	0	1	2	16	2	4	0	2	0	16	4	4	5	30	15	21	15	138
	Weather/Nature	0	0	0	1	0	0	0	0	0	1	0	0	0	0	0	0	0	0	2
Registration Issues	Can Not Identify State	0	0	0	0	1	1	1	1	0	1	0	2	0	0	0	2	0	0	9
	Paper Plates	0	0	1	1	1	3	1	2	0	0	1	4	2	3	5	4	0	3	31
	Wrong or No DMV	0	0	0	0	5	0	1	1	0	1	1	3	1	2	0	2	3	0	20
Total		14	0	7	5	49	17	13	5	4	6	32	40	9	16	55	38	30	31	371
Sub Total Violations		10	0	29	13	101	21	17	31	9	10	28	42	23	24	57	44	34	39	532
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		10	0	29	13	101	21	17	31	9	10	28	42	23	24	57	44	34	39	532
<b>Less Rejects</b>																				
Camera Malfunction	Digital Distortion	0-00%	0-00%	2-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Face Camera Flash	0-00%	0-00%	0-00%	1-08%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	1-04%	1-04%	0-00%	1-02%	2-06%	2-05%	10-02%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-06%	1-03%	0-00%	0-00%	3-11%	0-00%	2-09%	1-04%	0-00%	2-05%	2-06%	2-05%	15-03%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-00%
	Face Not in Frame	1-10%	0-00%	1-03%	2-15%	1-01%	0-00%	2-12%	0-00%	0-00%	0-00%	2-07%	0-00%	1-04%	4-17%	4-07%	1-02%	0-00%	2-05%	21-04%
	Image Missing	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Misc Camera Issue	0-00%	0-00%	11-38%	0-00%	1-01%	0-00%	2-12%	2-06%	0-00%	0-00%	1-04%	0-00%	1-04%	7-29%	0-00%	0-00%	0-00%	1-03%	26-05%
	Plate Burn Out	0-00%	0-00%	1-03%	0-00%	2-02%	1-05%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	6-01%
	Plate Not in Frame	1-10%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	2-15%	3-03%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	3-05%	0-00%	0-00%	1-03%	11-02%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-13%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
	Rear Plate No Flash	2-20%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
	Scene Image Flash Inappropriate	0-00%	0-00%	2-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-05%	0-00%	4-01%
	Scene Image No Flash	0-00%	0-00%	1-03%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-05%	0-00%	4-01%
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	10-10%	2-10%	3-18%	0-00%	2-22%	2-20%	7-25%	2-05%	0-00%	2-08%	1-02%	11-25%	5-15%	9-23%	56-11%
	Vehicle On or Passed Stop Line	0-00%	0-00%	0-00%	1-08%	0-00%	2-10%	0-00%	0-00%	0-00%	3-30%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
Total		4-40%	0-00%	19-66%	7-54%	20-20%	6-29%	8-47%	8-26%	4-44%	5-50%	14-50%	2-05%	5-22%	16-67%	9-16%	19-43%	9-26%	18-46%	173-33%
Approved Violations		6-60%	0-00%	10-34%	6-46%	81-80%	15-71%	9-53%	23-74%	5-56%	5-50%	14-50%	40-95%	18-78%	8-33%	48-84%	25-57%	25-74%	21-54%	359-67%

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:27:32 AM

# Customer Management Report (Ventura) All Detection Types

01-Sep-2006 to 30-Sep-2006

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Notices Printed	6-60%	0-00%	10-34%	6-46%	81-80%	15-71%	9-53%	23-74%	5-56%	5-50%	14-50%	40-95%	18-78%	8-33%	48-84%	25-57%	25-74%	21-54%	359-67%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Mar-2007 to 31-Mar-2007

Operator Id: %

		VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>		13	0	22	11	138	40	26	19	4	18	39	41	25	61	75	58	111	73	774	
<b>Less Uncontrollable Factors</b>																					
Obstruction	Driver Obstruction/Duckers	1	0	5	1	5	3	4	2	1	4	3	0	1	7	10	3	5	8	63	
	Motor Cycle Helmet	1	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	3
	Plate Obstruction	3	0	2	0	8	1	3	2	0	2	0	1	0	1	1	1	0	0	3	28
	Vehicle Obstruction	0	0	6	0	3	0	1	1	1	1	2	1	1	1	0	1	0	2	2	22
Police Rejects	Gender Mismatch	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Incorrect/Incomplete DMV	0	0	0	1	2	0	0	0	0	0	1	0	1	2	0	0	0	0	0	7
	Safe Turn On Red	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	6	8
Policy/Weather	Extended Vehicle	0	0	0	0	3	0	0	0	0	0	1	12	0	0	0	0	0	0	1	17
	Sun Glare	2	0	0	0	15	3	2	0	0	1	12	1	1	20	16	1	19	10	103	
	Weather/Nature	0	0	1	1	0	0	0	0	0	0	0	1	0	1	0	0	0	1	0	5
Registration Issues	Paper Plates	0	0	0	2	0	2	1	0	0	0	0	2	1	2	3	2	4	3	22	
	Wrong or No DMV	0	0	0	0	2	3	0	0	0	0	0	1	1	0	0	1	4	1	13	
<b>Total</b>		7	0	14	5	39	13	11	7	2	9	18	19	6	33	31	8	35	35	292	
<b>Sub Total Violations</b>		6	0	8	6	99	27	15	12	2	9	21	22	19	28	44	50	76	38	482	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		6	0	8	6	99	27	15	12	2	9	21	22	19	28	44	50	76	38	482	
<b>Less Rejects</b>																					
Camera Malfunction	Databar Unreadable/Incorrect	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	2-05%	4-01%
	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	2-00%
	Face Camera Focus Blurry	0-00%	0-00%	2-25%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-10%	0-00%	0-00%	1-04%	1-02%	2-04%	0-00%	0-00%	8-02%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-33%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	3-07%	0-00%	0-00%	0-00%	9-02%
	Image Missing	0-00%	0-00%	1-12%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Plate Burn Out	0-00%	0-00%	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	2-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	3-01%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	3-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	2-04%	0-00%	0-00%	6-01%
	Rear Plate No Flash	1-17%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	1-12%	1-17%	14-14%	3-11%	3-20%	0-00%	0-00%	2-22%	5-24%	1-05%	6-32%	8-29%	7-16%	3-06%	8-11%	4-11%	66-14%	
	Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-05%	0-00%	4-01%	
	Vehicle On or Passed Stop Line	0-00%	0-00%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	14-32%	0-00%	1-01%	0-00%	15-03%	

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:28:04 AM



# Customer Management Report (Ventura) All Detection Types

01-Mar-2007 to 31-Mar-2007

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total	1-17%	0-00%	5-62%	2-33%	16-16%	10-37%	9-60%	2-17%	0-00%	4-44%	7-33%	1-05%	7-37%	11-39%	27-61%	9-18%	13-17%	6-16%	130-27%
Approved Violations	5-83%	0-00%	3-38%	4-67%	83-84%	17-63%	6-40%	10-83%	2-100%	5-56%	14-67%	21-95%	12-63%	17-61%	17-39%	41-82%	63-83%	32-84%	352-73%
Total Notices Printed	5-83%	0-00%	3-38%	4-67%	83-84%	17-63%	6-40%	10-83%	2-100%	5-56%	14-67%	21-95%	12-63%	17-61%	17-39%	41-82%	63-83%	32-84%	352-73%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Sep-2007 to 30-Sep-2007

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	19	72	14	15	165	49	19	37	10	15	56	32	29	36	118	68	182	57	993	
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	2	16	3	0	9	8	4	3	0	1	5	1	0	7	25	8	11	4	107
	Motor Cycle Helmet	0	0	0	0	1	0	0	1	0	0	0	0	0	0	0	0	1	2	5
	Plate Obstruction	1	0	1	2	12	5	0	1	0	0	4	1	1	0	5	1	0	2	36
	Signal Obstruction	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	2
	Vehicle Obstruction	0	1	1	0	4	0	4	0	0	0	5	0	0	1	7	4	2	1	30
Police Rejects	Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1
	Incorrect/Incomplete DMV	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
	Police Discretion	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1	0	2
	Safe Turn On Red	0	2	0	0	0	0	0	9	0	0	0	0	0	0	0	0	0	1	12
Policy/Weather	Extended Vehicle	1	0	0	1	0	0	0	0	1	0	3	0	0	1	0	0	0	0	7
	Sun Glare	3	3	4	0	19	4	0	3	4	5	9	0	6	8	9	13	38	12	140
	Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1	0	0	2
Registration Issues	Paper Plates	2	2	0	2	5	3	0	0	0	2	0	1	2	0	0	9	6	34	
	Wrong or No DMV	0	2	0	0	1	1	0	1	0	2	1	0	0	0	1	0	0	9	
<b>Total</b>	9	26	10	5	51	21	8	18	5	7	28	6	8	18	47	28	64	29	388	
<b>Sub Total Violations</b>	10	46	4	10	114	28	11	19	5	8	28	26	21	18	71	40	118	28	605	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
<b>Available For Prosecution</b>	10	46	4	10	114	28	11	19	5	8	28	26	21	18	71	40	118	28	605	
<b>Less Rejects</b>																				
Camera Malfunction	Face Camera Focus Blurry	2-20%	0-00%	0-00%	0-00%	0-00%	3-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	1-02%	0-00%	0-00%	7-01%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-07%	0-00%	0-00%	0-00%	6-01%
	Image Missing	0-00%	1-02%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Misc Camera Issue	2-20%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	2-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
	Rear Plate No Flash	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
Police Rejects	Driver Unidentifiable images poor	2-20%	3-07%	0-00%	0-00%	0-00%	3-11%	2-18%	4-21%	0-00%	1-12%	1-04%	1-04%	0-00%	1-06%	7-10%	2-05%	8-07%	1-04%	36-06%
	Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
	Vehicle On or Passed Stop Line	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	Too Old	2-20%	15-33%	0-00%	1-10%	41-36%	11-39%	3-27%	3-16%	1-20%	3-38%	8-29%	7-27%	8-38%	5-28%	17-24%	12-30%	34-29%	8-29%	179-30%
<b>Total</b>	9-90%	19-41%	0-00%	1-10%	43-38%	20-71%	6-55%	8-42%	1-20%	4-50%	9-32%	9-35%	9-43%	7-39%	30-42%	17-42%	43-36%	9-32%	244-40%	

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:28:31 AM

# Customer Management Report (Ventura) All Detection Types

01-Sep-2007 to 30-Sep-2007

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Approved Violations	1-10%	27-59%	4-100%	9-90%	71-62%	8-29%	5-45%	11-58%	4-80%	4-50%	19-68%	17-65%	12-57%	11-61%	41-58%	23-57%	75-64%	19-68%	361-60%
Total Notices Printed	1-10%	18-39%	4-100%	9-90%	71-62%	8-29%	5-45%	11-58%	4-80%	4-50%	19-68%	17-65%	12-57%	11-61%	41-58%	23-57%	75-64%	19-68%	352-58%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Jul-2013 to 31-Jul-2013

Operator Id: %

		VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>		16	195	3	17	59	47	35	102	70	12	32	54	29	42	9	46	34	76	878	
<b>Less Uncontrollable Factors</b>																					
Obstruction	Driver Obstruction/Duckers	0	6	1	1	1	0	0	1	3	0	0	2	0	2	0	2	1	5	25	
	Motor Cycle Helmet	0	0	0	1	1	0	0	0	2	0	0	1	1	1	0	0	0	0	2	9
	Plate Obstruction	0	6	0	1	2	1	0	0	0	0	2	0	0	0	1	0	0	0	1	17
	Vehicle Obstruction	0	10	0	0	2	0	1	1	1	0	1	1	4	1	0	0	0	1	4	26
Police Rejects	Driver Obstruction (PD)	0	2	0	1	0	0	0	3	4	0	0	2	0	0	0	0	2	0	0	14
	Emergency Vehicle Responding	0	0	0	0	0	0	1	1	0	0	0	0	0	0	0	0	0	1	0	3
	Incorrect/Incomplete DMV	0	0	0	0	0	1	0	0	0	1	0	2	0	0	1	0	0	0	0	5
	Invalid Offense	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1
	Multiple vehicles in frame	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
	On or Passed the Stop Bar (PD)	2	4	0	1	2	0	0	0	0	1	0	0	0	4	0	0	0	0	0	15
	Plate Obstruction (PD)	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Plate Unidentifiable	0	0	0	0	0	0	0	0	1	1	0	0	0	0	0	0	0	0	0	2
	Safe Turn On Red	0	56	0	0	0	0	0	31	4	0	0	0	0	0	0	0	0	0	13	104
	Sun Glare	1	6	0	1	1	2	0	4	1	0	0	0	0	0	0	0	0	6	2	24
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	1	1	0	0	0	2	0	0	0	0	0	0	0	4
	Sun Glare	5	33	0	2	2	6	14	6	5	2	1	3	6	20	2	1	5	10	123	
	Weather/Nature	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
	Yellow with Red Light	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1
Registration Issues	Paper Plates	0	4	0	0	1	1	1	3	2	0	2	0	1	1	0	2	1	5	24	
	Wrong or No DMV	1	6	0	0	0	0	1	6	2	0	2	2	1	0	0	2	2	2	27	
<b>Total</b>		9	136	1	9	12	11	19	58	26	5	8	19	14	25	3	10	17	46	428	
<b>Sub Total Violations</b>		7	59	2	8	47	36	16	44	44	7	24	35	15	17	6	36	17	30	450	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
<b>Available For Prosecution</b>		7	59	2	8	47	36	16	44	44	7	24	35	15	17	6	36	17	30	450	
<b>Less Rejects</b>																					
Camera Malfunction	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Not in Frame	0-00%	0-00%	1-50%	0-00%	0-00%	0-00%	1-06%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	1-06%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%	
	Plate Not in Frame	1-14%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	0-00%	0-00%	3-43%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%	
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-19%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	
Police Rejects	Driver Unidentifiable images poor	2-29%	9-15%	0-00%	0-00%	1-02%	7-19%	1-06%	1-02%	1-02%	0-00%	0-00%	2-06%	1-07%	3-18%	0-00%	0-00%	1-06%	0-00%	29-06%	
	No Images	0-00%	0-00%	0-00%	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
<b>Total</b>		3-43%	9-15%	1-50%	1-12%	5-11%	7-19%	7-44%	4-09%	1-02%	3-43%	1-04%	2-06%	1-07%	3-18%	0-00%	0-00%	1-06%	2-07%	51-11%	

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:29:07 AM

# Customer Management Report (Ventura) All Detection Types

01-Jul-2013 to 31-Jul-2013

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Approved Violations	4-57%	50-85%	1-50%	7-88%	42-89%	29-81%	9-56%	40-91%	43-98%	4-57%	23-96%	33-94%	14-93%	14-82%	6-100%	36-100%	16-94%	28-93%	399-89%
Total Notices Printed	4-57%	50-85%	1-50%	7-88%	42-89%	29-81%	9-56%	40-91%	43-98%	4-57%	23-96%	33-94%	14-93%	14-82%	6-100%	36-100%	16-94%	28-93%	399-89%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Apr-2014 to 30-Apr-2014

Operator Id: %

		VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>		22	200	6	21	168	33	34	94	87	11	82	74	19	41	84	61	50	71	1158
<b>Less Uncontrollable Factors</b>																				
Obstruction	Driver Obstruction/Duckers	3	20	1	1	11	3	7	0	7	0	2	6	3	7	14	1	1	3	90
	Motor Cycle Helmet	0	0	0	0	0	0	0	0	1	0	0	0	0	2	0	0	1	0	4
	Plate Obstruction	1	0	0	4	4	1	0	0	0	0	1	0	0	0	1	0	0	1	13
	Vehicle Obstruction	0	15	0	0	4	0	7	1	1	0	2	3	0	2	4	2	1	1	43
Police Rejects	Driver Obstruction (PD)	0	0	0	0	1	0	0	1	0	0	1	1	0	0	0	1	1	1	7
	Funeral Procession/Police	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1
	Gender Mismatch	0	0	0	0	1	0	0	0	0	0	0	1	0	0	0	0	0	0	2
	Incorrect/Incomplete DMV	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1	0	0	3
	Invalid Offense	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
	Multiple vehicles in frame	0	14	0	0	1	0	0	0	0	0	0	1	0	0	1	0	0	0	17
	On or Passed the Stop Bar (PD)	0	1	0	0	0	0	0	0	0	0	0	0	2	1	1	0	0	0	5
	Plate Obstruction (PD)	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
	Plate Unidentifiable	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1
	Police Discretion	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1
	Safe Turn On Red	0	48	0	0	0	0	0	26	3	0	0	0	0	0	0	0	0	10	87
	Sun Glare	1	8	0	1	8	2	0	4	4	0	2	2	0	1	6	1	1	1	42
	Policy/Weather	Extended Vehicle	0	0	0	1	0	0	0	0	0	0	0	6	0	0	0	0	0	0
Sun Glare		5	22	3	0	8	10	9	1	13	2	9	2	3	13	8	1	4	19	132
Registration Issues	Out of Country Plate	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	Paper Plates	0	5	0	1	2	1	1	1	4	0	1	2	0	0	1	1	1	2	23
	Wrong or No DMV	1	3	0	0	2	1	1	2	4	0	4	3	0	1	2	4	3	1	32
<b>Total</b>	13	138	4	8	42	18	25	36	39	2	23	27	8	27	39	13	13	39	514	
<b>Sub Total Violations</b>		9	62	2	13	126	15	9	58	48	9	59	47	11	14	45	48	37	32	644
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		9	62	2	13	126	15	9	58	48	9	59	47	11	14	45	48	37	32	644
<b>Less Rejects</b>																				
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-22%	0-00%	0-00%	3-33%	0-00%	0-00%	0-00%	0-00%	0-00%	5-11%	0-00%	0-00%	1-03%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Plate Burn Out	0-00%	0-00%	1-50%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	1-09%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	3-33%	8-13%	1-50%	2-15%	3-02%	2-13%	3-33%	0-00%	7-15%	0-00%	0-00%	10-21%	1-09%	2-14%	6-13%	3-06%	1-03%	2-06%	54-08%
	Insufficient Strobe Lighting	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:29:43 AM

# Customer Management Report (Ventura) All Detection Types

01-Apr-2014 to 30-Apr-2014

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Process Too Old Issues	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-02%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Total	3-33%	9-15%	2-100%	3-23%	3-02%	2-13%	7-78%	4-07%	8-17%	5-56%	0-00%	12-26%	2-18%	2-14%	11-24%	3-06%	1-03%	3-09%	80-12%
Approved Violations	6-67%	53-85%	0-00%	10-77%	123-98%	13-87%	2-22%	54-93%	40-83%	4-44%	59-100%	35-74%	9-82%	12-86%	34-76%	45-94%	36-97%	29-91%	564-88%
Total Notices Printed	6-67%	53-85%	0-00%	10-77%	123-98%	13-87%	2-22%	54-93%	40-83%	4-44%	59-100%	35-74%	9-82%	12-86%	34-76%	45-94%	36-97%	29-91%	564-88%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-May-2014 to 31-May-2014

Operator Id: %

		VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>		19	193	1	24	162	25	43	110	95	10	58	101	13	55	57	54	49	76	1145	
<b>Less Uncontrollable Factors</b>																					
Obstruction	Driver Obstruction/Duckers	0	18	1	0	0	4	6	1	5	0	1	6	2	2	6	1	0	5	58	
	Motor Cycle Helmet	0	0	0	0	2	0	0	0	0	0	0	1	0	0	0	0	0	0	3	
	Plate Obstruction	1	0	0	1	1	1	1	0	0	0	1	3	0	0	0	0	0	0	10	
	Vehicle Obstruction	0	12	0	0	10	0	3	2	0	1	3	2	1	0	6	2	1	0	43	
Police Rejects	Driver Obstruction (PD)	0	1	0	0	2	0	0	0	4	0	0	1	0	0	1	0	1	0	10	
	Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1	0	0	0	2	
	Multiple vehicles in frame	0	7	0	0	1	0	0	0	0	0	0	1	0	0	0	0	0	0	10	
	On or Passed the Stop Bar (PD)	0	0	0	3	0	0	0	0	0	0	0	0	1	0	0	0	0	0	4	
	Plate Obstruction (PD)	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2	
	Plate Unidentifiable	1	0	0	0	0	0	0	0	0	0	0	3	1	0	1	0	1	2	9	
	Police Discretion	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1	
	Safe Turn On Red	0	44	0	0	0	0	0	42	2	0	0	0	0	0	0	0	0	0	10	98
	Sun Glare	1	10	0	1	4	0	1	0	5	1	3	1	3	7	3	0	1	5	46	
	Policy/Weather	Extended Vehicle	0	0	0	0	4	0	0	0	0	0	0	7	0	0	0	0	0	1	12
Sun Glare		7	17	0	1	7	6	12	6	15	1	0	2	0	17	9	0	4	11	115	
Registration Issues	Out of Country Plate	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	2	
	Paper Plates	0	3	0	0	2	1	0	4	4	0	1	3	0	1	1	1	0	3	24	
	Wrong or No DMV	0	4	0	2	1	1	0	1	2	1	1	3	1	0	2	1	4	0	24	
<b>Total</b>		11	116	1	9	35	13	23	56	37	4	12	33	9	27	30	5	12	40	473	
<b>Sub Total Violations</b>		8	77	0	15	127	12	20	54	58	6	46	68	4	28	27	49	37	36	672	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
<b>Available For Prosecution</b>		8	77	0	15	127	12	20	54	58	6	46	68	4	28	27	49	37	36	672	
<b>Less Rejects</b>																					
Camera Malfunction	Face Camera Flash	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-05%	2-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	5-01%	
	Misc Camera Issue	0-00%	1-01%	0-00%	0-00%	4-03%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-05%	1-03%	11-02%
	Plate Burn Out	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-10%	3-06%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
Police Rejects	Driver Unidentifiable images poor	3-38%	6-08%	0-00%	0-00%	6-05%	3-25%	11-55%	5-09%	6-10%	4-67%	1-02%	8-12%	0-00%	9-32%	5-19%	2-04%	5-14%	5-14%	79-12%	
	Incorrect Speed	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Process Issues	Too Old	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	2-00%	
<b>Total</b>		3-38%	10-13%	0-00%	0-00%	10-08%	3-25%	14-70%	11-20%	9-16%	4-67%	1-02%	12-18%	0-00%	9-32%	5-19%	2-04%	8-22%	7-19%	108-16%	
<b>Approved Violations</b>		5-62%	67-87%	0-00%	15-100%	117-92%	9-75%	6-30%	43-80%	49-84%	2-33%	45-98%	56-82%	4-100%	19-68%	22-81%	47-96%	29-78%	29-81%	564-84%	

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:30:08 AM



# Customer Management Report (Ventura) All Detection Types

01-May-2014 to 31-May-2014

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Notices Printed	5-62%	67-87%	0-00%	15-100%	117-92%	9-75%	6-30%	43-80%	49-84%	2-33%	45-98%	56-82%	4-100%	19-68%	22-81%	47-96%	29-78%	29-81%	564-84%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Jul-2014 to 31-Jul-2014

Operator Id: %

		VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>		25	194	3	16	165	39	34	107	69	0	44	81	19	49	45	27	50	78	1045	
<b>Less Uncontrollable Factors</b>																					
Obstruction	Driver Obstruction/Duckers	0	12	0	0	3	2	0	1	1	0	0	2	2	1	9	0	1	5	39	
	Motor Cycle Helmet	0	0	0	0	1	0	1	0	0	0	0	0	0	0	0	0	0	0	2	
	Plate Obstruction	1	1	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	3	
	Vehicle Obstruction	3	10	0	0	6	0	4	0	0	0	1	2	1	1	4	0	0	3	35	
Police Rejects	Driver Obstruction (PD)	0	3	0	0	3	0	0	1	0	0	0	1	0	1	0	0	2	0	11	
	Funeral Procession/Police	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1	
	Incorrect/Incomplete DMV	0	2	0	0	0	0	0	0	0	0	2	1	0	0	1	0	0	0	6	
	Multiple vehicles in frame	0	4	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	4	
	On or Passed the Stop Bar (PD)	0	0	0	0	0	0	0	0	0	0	0	1	4	0	0	0	0	0	5	
	Plate Obstruction (PD)	0	0	0	0	0	0	1	2	0	0	0	1	0	0	0	0	0	0	4	
	Plate Unidentifiable	0	0	0	0	2	0	0	0	0	0	0	1	0	0	0	0	0	0	3	
	Safe Turn On Red	0	51	0	0	0	0	0	33	4	0	0	0	0	0	0	0	0	0	11	99
	Sun Glare	0	5	0	0	8	7	2	2	0	0	2	2	0	4	2	0	3	3	40	
	Policy/Weather	Extended Vehicle	1	1	0	1	1	0	0	0	1	0	0	3	0	0	0	0	0	0	8
Sun Glare		7	23	2	0	12	12	12	2	6	0	3	9	1	21	6	3	9	11	139	
Weather/Nature		0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1	
Registration Issues	Out of Country Plate	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1	
	Paper Plates	1	7	0	1	2	2	2	2	3	0	1	1	0	1	3	0	0	6	32	
	Wrong or No DMV	0	6	0	1	1	1	0	4	2	0	0	3	0	0	0	1	2	1	22	
<b>Total</b>	13	125	2	3	39	24	22	48	18	0	10	27	9	29	25	4	17	40	455		
<b>Sub Total Violations</b>		12	69	1	13	126	15	12	59	51	0	34	54	10	20	20	23	33	38	590	
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
<b>Available For Prosecution</b>		12	69	1	13	126	15	12	59	51	0	34	54	10	20	20	23	33	38	590	
<b>Less Rejects</b>																					
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Face Not in Frame	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	2-04%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	5-01%	
Police Rejects Process Issues	Driver Unidentifiable images poor	1-08%	7-10%	1-100%	0-00%	4-03%	5-33%	4-33%	0-00%	3-06%	0-00%	0-00%	6-11%	2-20%	3-15%	5-25%	1-04%	0-00%	0-00%	42-07%	
	Too Old	1-08%	3-04%	0-00%	0-00%	0-00%	0-00%	1-08%	3-05%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	9-02%	
<b>Total</b>	3-25%	10-14%	1-100%	0-00%	4-03%	5-33%	6-50%	6-10%	3-06%	0-00%	1-03%	10-19%	2-20%	4-20%	5-25%	1-04%	0-00%	1-03%	62-11%		

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:19:58 AM

# Customer Management Report (Ventura) All Detection Types

01-Jul-2014 to 31-Jul-2014

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Approved Violations	9-75%	59-86%	0-00%	13-100%	122-97%	10-67%	6-50%	53-90%	48-94%	0-00%	33-97%	44-81%	8-80%	16-80%	15-75%	22-96%	33-100%	37-97%	528-89%
Total Notices Printed	9-75%	59-86%	0-00%	13-100%	122-97%	10-67%	6-50%	53-90%	48-94%	0-00%	33-97%	44-81%	8-80%	16-80%	15-75%	22-96%	33-100%	37-97%	528-89%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: JKOHAGEN

Generated On: 9/23/2014 11:19:58 AM

# Customer Management Report (Ventura) All Detection Types

01-Aug-2014 to 31-Aug-2014

Operator Id: %

		VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL		
<b>Total Processed Incidents</b>		17	205	3	24	163	43	44	126	81	15	51	96	28	60	50	64	71	81	1222		
<b>Less Uncontrollable Factors</b>																						
Obstruction	Driver Obstruction/Duckers	2	12	0	0	3	5	4	3	4	0	0	7	3	6	7	1	1	1	59		
	Motor Cycle Helmet	0	1	0	0	2	0	0	1	1	0	1	1	0	1	0	0	0	0	2	10	
	Plate Obstruction	0	0	0	0	2	0	0	1	1	0	1	4	0	0	0	0	1	0	0	10	
	Vehicle Obstruction	0	9	0	1	4	0	4	1	1	2	1	4	0	1	3	4	4	2	1	38	
Police Rejects	Driver Obstruction (PD)	0	1	0	0	1	1	0	1	1	0	2	0	0	0	0	1	0	0	8		
	Incorrect/Incomplete DMV	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1	0	0	0	2		
	Multiple vehicles in frame	0	4	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	4	
	On or Passed the Stop Bar (PD)	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1	2	
	Plate Obstruction (PD)	0	1	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2	
	Plate Unidentifiable	0	2	0	1	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1	5	
	Safe Turn On Red	0	50	0	0	0	0	0	30	4	0	0	0	0	0	0	0	1	0	15	100	
	Sun Glare	0	13	1	2	3	4	4	1	2	0	1	1	2	3	1	3	4	3	3	48	
	Policy/Weather	Extended Vehicle	0	0	0	0	0	0	0	0	2	0	0	9	0	0	0	0	0	0	0	11
		Sun Glare	4	22	2	0	21	9	21	5	16	6	6	2	10	25	8	2	11	19	189	
Registration Issues	Paper Plates	1	11	0	2	5	0	1	5	0	3	0	3	0	0	1	1	3	1	37		
	Wrong or No DMV	0	3	0	1	4	1	1	5	2	0	1	3	0	1	0	1	3	2	28		
<b>Total</b>		7	129	3	7	45	20	35	55	35	11	13	34	16	37	21	15	24	46	553		
<b>Sub Total Violations</b>		10	76	0	17	118	23	9	71	46	4	38	62	12	23	29	49	47	35	669		
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
<b>Available For Prosecution</b>		10	76	0	17	118	23	9	71	46	4	38	62	12	23	29	49	47	35	669		
<b>Less Rejects</b>																						
Camera Malfunction	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	2-00%		
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%		
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	3-00%		
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%		
Police Rejects Process Issues	Driver Unidentifiable images poor	1-10%	16-21%	0-00%	1-06%	3-03%	1-04%	4-44%	2-03%	3-07%	0-00%	0-00%	3-05%	0-00%	3-13%	3-10%	1-02%	2-04%	0-00%	43-06%		
	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%		
<b>Total</b>		1-10%	16-21%	0-00%	1-06%	3-03%	1-04%	5-56%	5-07%	4-09%	0-00%	0-00%	5-08%	0-00%	3-13%	5-17%	1-02%	2-04%	0-00%	52-08%		
<b>Approved Violations</b>		9-90%	60-79%	0-00%	16-94%	115-97%	22-96%	4-44%	66-93%	42-91%	4-100%	38-100%	57-92%	12-100%	20-87%	24-83%	48-98%	45-96%	35-100%	617-92%		
<b>Total Notices Printed</b>		9-90%	60-79%	0-00%	16-94%	115-97%	22-96%	4-44%	66-93%	42-91%	4-100%	38-100%	57-92%	12-100%	20-87%	24-83%	48-98%	45-96%	35-100%	617-92%		

Generated By: JKOHAGEN  
Generated On: 9/23/2014 11:20:37 AM

# Customer Management Report (Ventura) All Detection Types

01-Aug-2014 to 31-Aug-2014

Operator Id: %

VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	-------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current