

# Customer Management Report (Ventura) All Detection Types

01-Sep-2012 to 30-Sep-2012 Operator Id: %

Operator Id	VE-ERJQ-01	VE-CATH-01	VE-FOVJ-01	VE-JONB-01	VE-MAT0-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MATG-01	VE-TGDA-01	VE-THSE-01	VE-VMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents	18	172	35	20	52	32	45	97	56	21	23	42	26	38	71	40	56	66	910

Less Uncontrollable Factors	3	10	0	1	0	0	1	2	6	1	0	3	0	3	10	1	0	2	43
Obstruction	0	0	0	1	3	0	1	0	3	0	0	1	0	0	0	0	0	1	11
Driver Obstruction/Due	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Motor Cycle Helmet	0	2	0	0	0	3	1	1	0	1	0	1	1	0	0	1	0	1	12
Plate Obstruction	0	1	0	0	4	0	2	0	0	2	0	1	1	1	2	0	0	0	14
Vehicle Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Driver Obstruction (PD)	0	0	0	0	0	1	0	0	0	0	1	1	0	0	1	0	1	1	7
Police Rejects	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Invalid Offense	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Multiple vehicles in frame	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
On or Passed the Stop Bar (PD)	0	3	0	0	0	2	1	3	2	0	0	2	4	0	0	0	0	0	17
Plate Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Plate Underenforceable	0	0	0	0	2	0	0	0	0	0	0	1	0	0	0	0	0	0	2
Safe Turn On Red	0	78	0	0	0	0	0	46	7	0	0	0	0	0	0	0	0	9	140
Sun Glare	0	1	0	0	0	0	3	0	0	0	0	0	1	1	0	0	3	1	10
Policy/Weath	0	0	0	0	2	0	0	0	0	1	0	2	0	0	0	0	1	0	7
Extended Vehicle	0	16	0	2	2	1	1	3	2	5	3	0	3	13	3	4	3	12	73
Sun Glare	0	8	0	0	2	3	2	2	2	0	1	1	1	0	1	0	1	0	27
Paper Plates	1	0	0	0	2	4	2	5	1	1	5	2	3	3	1	2	1	2	29
Wrong or No DMV	1	1	0	0	0	18	14	62	23	11	8	15	13	21	8	11	32	396	
Total	5	121	0	5	18	44	31	35	33	11	5	27	13	3	18	8	45	34	514
Sub Total Violations	13	51	0	15	34	18	31	35	33	10	18	27	13	17	53	32	45	34	514
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	13	51	0	15	34	18	31	35	33	10	18	27	13	17	53	32	45	34	514

Less Rejects	0-00%	0-00%	2-06%	7-47%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	9-42%
Camera	0-00%	0-00%	2-06%	7-47%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	15-03%
Malfunction	0-00%	0-00%	10-29%	5-33%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%

Generated By: RMEKES  
 Generated On: 5/17/2013 2:07:49 PM  
 © Redflex Traffic Systems, Inc

# Customer Management Report (Ventura) All Detection Types

01-Sep-2012 to 30-Sep-2012

Operator Id: %

	VE-BRJ0-01	VE-CATH-01	VE-FOV1-01	VE-IONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Face Not in Frame	1-08%	0-00%	0-00%	0-00%	1-03%	0-00%	5-16%	0-00%	0-00%	4-40%	0-00%	0-00%	1-08%	0-00%	2-04%	0-00%	0-00%	0-00%	14-03%
Image Missing	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	4-01%
Misc Camera Issue	0-00%	0-00%	18-51%	0-00%	4-12%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	0-00%	25-05%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	3-01%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	3-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Scene Image No Flash	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	4-13%	1-03%	2-05%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Driver Unidentifiable Images poor	1-08%	4-08%	0-00%	0-00%	0-00%	1-08%	4-13%	1-03%	2-05%	0-00%	0-00%	1-04%	2-15%	2-12%	7-13%	8-25%	4-09%	2-05%	38-08%
Police Rejects	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	2-15%	4-08%	33-94%	12-80%	7-21%	5-28%	11-35%	3-09%	2-05%	5-50%	0-00%	2-07%	3-23%	2-12%	10-19%	8-25%	7-18%	6-18%	122-24%
Approved Violations	11-85%	47-82%	2-08%	3-20%	27-79%	13-72%	20-85%	32-91%	31-94%	5-50%	18-100%	25-93%	10-77%	15-89%	43-81%	24-75%	38-44%	28-82%	392-76%
Total Notices Printed	11-85%	47-82%	2-08%	3-20%	27-79%	13-72%	20-85%	32-91%	31-94%	5-50%	18-100%	25-93%	10-77%	15-89%	43-81%	24-75%	38-44%	28-82%	392-76%

# Customer Management Report (Ventura) All Detection Types

Operator Id: %

Less Uncontrollable Factors	24	179	6	36	48	37	39	91	82	11	35	31	36	43	30	60	63	55	TOTAL
Obstruction	0	8	1	2	4	3	2	1	4	1	0	2	1	3	4	3	2	3	44
Driver Obstruction/Duckers	0	0	0	0	0	0	0	0	2	0	3	0	0	0	0	0	0	0	6
Motor Cycle Helmet	0	0	0	0	0	0	0	0	1	0	0	3	0	0	0	1	2	1	19
Plate Obstruction	3	2	0	5	0	0	0	0	1	0	0	3	1	0	0	1	2	1	33
Vehicle Obstruction	0	6	0	1	7	0	7	0	0	1	3	1	0	0	3	0	2	2	33
Police	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	4
Rejects	0	0	0	0	1	1	0	0	1	0	0	0	0	0	0	0	0	0	4
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	3
Invalid Offense	0	1	0	0	1	0	1	0	0	0	0	1	0	0	0	0	0	0	3
Multiple Vehicles in Frame	0	1	0	0	0	0	1	0	0	0	0	1	0	0	0	0	0	0	3
On or Passed the Stop Bar (PD)	0	1	0	1	0	0	3	1	6	0	0	4	3	0	0	0	0	1	23
Plate Obstruction (PD)	0	0	0	1	0	1	0	0	0	0	0	0	0	0	0	0	0	0	2
Plate Undetectable	0	0	0	0	0	0	1	1	0	0	0	0	0	0	0	0	0	0	2
Safe Turn On Red	0	80	0	0	0	0	0	47	5	0	0	0	0	0	0	0	0	7	139
Sun Glare	0	1	0	1	2	0	0	0	0	0	0	0	1	1	0	1	1	1	9
Policy/Weather	0	0	0	0	1	1	0	0	0	2	0	4	0	0	0	0	0	1	11
Extended Vehicle	0	11	0	0	4	2	2	1	16	0	4	0	4	8	4	4	4	11	78
Sun Glare	3	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1
Two Vehicles in Beam	2	4	0	2	0	0	0	1	1	0	2	0	0	2	0	0	1	0	15
Registration	1	7	0	2	1	1	0	1	4	0	1	0	4	1	1	0	2	1	27
Paper Plates	9	121	1	15	21	11	14	55	40	4	13	15	14	15	12	11	17	31	419
When or No DMV	1	7	0	2	1	1	0	1	4	0	1	0	4	1	1	0	2	1	27
Issues	1	7	0	2	1	1	0	1	4	0	1	0	4	1	1	0	2	1	27
Total	15	58	0	21	27	26	25	36	42	7	22	16	22	28	18	49	46	24	487
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	15	58	0	21	27	26	25	36	42	7	22	16	22	28	18	49	46	24	487

## Less Rejects

Camera Malfunction	0-00%	0-00%	0-00%	2-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%
Face Not in Frame	0-00%	0-00%	1-20%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	1-14%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Image Missing	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	1-04%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Misc Camera Issue	1-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	8-02%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Rear Plate Flash Inappropriate	1-07%	0-00%	0-00%	3-14%	0-00%	0-00%	0-00%	0-00%	0-00%	1-14%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	8-02%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	1-44%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-08%	1-03%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-07%
Police	2-13%	7-12%	0-00%	0-00%	0-00%	1-04%	2-08%	2-06%	4-10%	0-00%	1-05%	0-00%	0-00%	6-21%	0-00%	8-16%	2-04%	5-21%	40-08%
Driver Undetectable Images poor	4-27%	7-12%	1-20%	6-29%	1-04%	1-04%	7-28%	7-19%	5-12%	3-43%	1-05%	1-06%	1-05%	6-21%	0-00%	8-16%	5-11%	7-59%	71-15%
Total	11-73%	51-88%	4-80%	15-71%	26-55%	25-86%	18-72%	25-81%	37-58%	4-57%	21-95%	15-94%	21-95%	22-79%	18-100%	41-94%	41-89%	17-71%	416-85%

Approved Violations  
Total Notices Printed  
Generated By: RWEEKS  
Generated On: 5/17/2013 2:12:02 PM

**Customer Management Report (Ventura) All Detection Types**  
 01-Oct-2012 to 31-Oct-2012 Operator Id: %

VE-BRJQ-01	VE-CATH-01	VE-FOVV-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	-------

Generated By: RWEEKS  
 Generated On: 5/17/2013 2:12:02 PM

© Radflex Traffic Systems, Inc.

# Customer Management Report (Ventura) All Detection Types

01-Nov-2012 to 30-Nov-2012

Operator Id: %

	VE-BRJC-01	VE-CATH-01	VE-FOV-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MICE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents	15	173	7	40	34	30	36	74	55	7	29	40	25	45	44	55	47	77	833

## Less Uncontrollable Factors

Obstruction	0	12	1	1	2	5	1	0	1	1	1	1	2	3	5	0	3	2	41
Driver Obstruction/Duckers	0	0	0	0	1	0	1	0	0	0	0	0	0	0	0	0	0	1	3
Motor Cycle Helmet	3	4	0	3	0	0	5	1	1	0	0	2	0	1	2	2	0	3	27
Plate Obstruction	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Signal Obstruction	0	8	0	3	0	0	3	2	1	1	0	1	0	0	1	1	0	3	24
Vehicle Obstruction	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	3
Driver Obstruction (PD)	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Incomplete DMV	0	1	0	0	0	0	0	0	1	0	0	1	0	0	0	0	0	0	3
Multiple vehicles in frame	0	0	0	0	0	0	0	0	3	1	0	0	0	0	0	0	0	0	15
On or Passed the Stop Bar (PD)	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Plate Unreadable	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Safe Turn On Red	0	73	0	0	0	0	0	38	4	0	0	0	0	0	0	0	0	15	130
Safe Turn On Red	0	0	0	0	0	0	0	0	1	0	0	0	0	2	0	0	0	2	8
Sun Glare	0	2	0	0	0	0	0	0	0	0	1	3	0	0	0	0	0	0	5
Policy/Weather Extended Vehicle	3	18	0	0	1	1	5	1	7	0	3	0	2	12	1	4	2	13	74
Sun Glare	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Two Vehicles in Beam	0	0	0	2	0	0	1	0	0	0	0	0	1	0	0	0	0	0	6
Weather/Nature	0	5	0	2	1	1	0	2	2	0	1	1	0	1	1	1	0	0	18
Registration Issues	1	6	0	3	1	0	1	3	0	1	0	1	1	1	4	3	3	1	30
Whong or No DMV	8	133	1	15	5	8	18	53	21	4	6	12	7	20	15	15	8	41	382
Sub Total Violations	7	40	6	25	28	22	18	21	34	3	23	28	18	25	29	40	38	36	441
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	7	40	6	25	28	22	18	21	34	3	23	28	18	25	29	40	38	36	441

## Less Rejects

Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unreadable Images poor	2-29%	0-00%	0-00%	0-00%	1-04%	6-27%	6-33%	1-05%	3-09%	0-00%	1-04%	3-11%	1-08%	11-44%	5-17%	6-15%	0-00%	7-19%	53-12%
Police Rejects	2-29%	0-00%	0-00%	1-04%	2-07%	8-36%	6-33%	1-05%	3-09%	1-33%	1-04%	5-18%	1-08%	11-44%	5-17%	7-18%	1-03%	8-22%	63-14%
Total	5-71%	40-100%	6-100%	24-86%	26-93%	14-64%	12-87%	20-95%	31-91%	2-67%	22-96%	23-92%	17-94%	14-58%	24-83%	33-92%	37-97%	28-78%	378-86%

Approved By: RWEEKS  
Generated On: 5/17/2013 2:12:31 PM

© Redflex Traffic Systems, Inc

**Customer Management Report (Ventura) All Detection Types**  
**01-Nov-2012 to 30-Nov-2012 Operator Id: %**

VE-VIVA-01	28.79%
VE-VTP-03	37.87%
VE-VTP-01	33.82%
VE-VTG-01	24.43%
VE-VIRA-01	14.58%
VE-VIOP-01	17.94%
VE-VIMO-01	23.82%
VE-THSE-01	22.96%
VE-TGDA-01	2.67%
VE-MITG-01	31.91%
VE-MIDE-01	20.95%
VE-MAMH-01	12.87%
VE-MALE-01	14.84%
VE-MA10-01	28.93%
VE-JONB-01	24.96%
VE-FOV-01	6.100%
VE-CATH-01	40.100%
VE-BRUO-01	5.71%
TOTAL	378.85%
Total Notices Printed	

# Customer Management Report (Ventura) All Detection Types

01-Dec-2012 to 31-Dec-2012 Operator Id: %

Total Processed Incidents	VE-RRJC-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAM1-01	VE-MIDE-01	VE-MTG-01	VE-TGDA-01	VE-THSE-01	VE-VIMC-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
12	159	6	29	32	15	51	83	44	9	36	31	28	44	37	36	46	59	757	
<b>Less Uncontrollable Factors</b>																			
Obstruction	0	10	3	2	1	1	4	0	0	2	1	5	1	2	4	3	0	3	42
Driver Obstruction/Duckers	0	1	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2
Motor Cycle Helmet	2	5	0	1	1	1	2	1	1	1	2	1	0	1	0	0	0	1	20
Plate Obstruction	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Signal Obstruction	2	1	0	1	2	7	0	0	1	0	2	2	1	3	2	2	1	0	23
Vehicle Obstruction	0	1	0	0	0	0	1	2	3	0	1	0	0	0	1	1	1	1	12
Police Rejects	0	0	0	0	0	0	0	1	1	0	0	1	0	0	0	0	0	0	4
Driver Obstruction (PD)	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2
Emergency Vehicle Responding	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	2
Emergency/Incomplete DMV	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Invalid Offense	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Multiple vehicles in frame	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
On or Passed the Stop Bar (PD)	0	0	0	1	0	0	0	0	1	0	0	3	5	0	0	0	0	0	12
Plate Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2
Plate Turn On Red	0	74	0	0	0	0	0	38	9	0	0	0	0	0	0	0	0	133	
Sun Glare	0	2	0	0	0	0	0	1	0	0	1	0	0	0	0	0	1	1	8
Policy/Weather	0	0	0	1	1	0	0	0	0	0	0	1	0	0	0	0	0	1	4
Extended Vehicle	0	12	0	0	0	0	5	0	2	3	0	0	7	11	2	1	0	13	56
Sun Glare	0	0	0	1	0	0	0	0	0	0	0	0	1	1	0	0	0	0	2
Weather/Nature	0	0	0	1	0	0	0	0	0	0	0	0	1	1	0	0	0	0	2
Registration Paper Plates	0	4	0	1	1	1	2	0	0	0	0	1	1	0	2	1	0	2	21
Whoring or No DMV	0	4	0	1	1	0	0	7	1	0	1	1	0	0	1	2	2	1	21
Issues	4	116	3	11	8	21	52	18	7	7	6	15	16	17	13	8	6	37	355
Total	8	43	3	18	24	30	31	26	2	30	16	12	27	24	28	40	22	22	392
Sub Total Violations	8	43	3	18	24	30	31	26	2	30	16	12	27	24	28	40	22	22	392
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	8	43	3	18	24	30	31	26	2	30	16	12	27	24	28	40	22	22	392

Generated By: RWEKKS  
 Generated On: 5/17/2013 2:06:01 PM  
 © Redflex Traffic Systems, Inc

# Customer Management Report (Ventura) All Detection Types

01-Dec-2012 to 31-Dec-2012

Operator Id: %

Camera Malfunction	VE-BAJ0-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VVA-01	TOTAL
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-50%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	2-25%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-20%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-02%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%
Police Driver/Undetectable Images poor	0-00%	1-02%	0-00%	0-00%	1-04%	2-25%	4-13%	2-06%	0-00%	1-50%	0-00%	1-06%	1-06%	3-11%	3-12%	8-29%	0-00%	2-09%	29-07%
Police Redlight not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	2-01%
Total	0-00%	1-02%	0-00%	0-00%	1-04%	4-50%	11-37%	3-10%	0-00%	2-100%	2-07%	2-12%	1-08%	3-11%	4-17%	8-29%	2-05%	2-09%	46-12%
Approved Violations	8-100%	42-98%	3-100%	18-100%	23-96%	4-50%	19-53%	28-90%	26-100%	0-00%	28-93%	14-88%	11-92%	24-89%	20-53%	20-71%	38-95%	20-91%	346-88%
Total Notices Printed	8-100%	42-98%	3-100%	18-100%	23-96%	4-50%	19-53%	28-90%	26-100%	0-00%	28-93%	14-88%	11-92%	24-89%	20-53%	20-71%	38-95%	20-91%	346-88%



# Customer Management Report (Ventura) All Detection Types

01-Jan-2013 to 31-Jan-2013 Operator Id: %

Category	VE-BRJ0-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VMCO-01	VE-VICP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VWA-01	TOTAL
<b>Total Processed Incidents</b>	19	150	9	12	33	27	26	86	59	21	42	34	23	40	48	44	44	67	782
<b>Less Uncontrollable Factors</b>																			
Obstruction	3	8	6	4	1	2	3	1	4	2	2	2	2	2	7	2	2	2	55
Driver Obstruction/Duckers	2	6	1	0	1	1	0	3	2	10	0	2	0	0	0	0	0	0	30
Plate Obstruction	0	2	0	0	2	0	0	0	0	5	0	0	0	0	0	0	0	0	11
Vehicle Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Police	0	2	0	0	0	0	1	0	3	0	1	2	0	0	1	1	1	1	13
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	1	0	1	0	0	0	0	0	0	0	2
Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	2
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	2
On or Passed the Stop Bar (PD)	0	1	0	0	0	0	0	2	0	0	1	3	3	0	0	0	0	0	10
Plate Obstruction (PD)	0	1	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	2
Plate Undetectable	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Safe Turn On Red	0	70	0	0	0	0	0	38	5	0	0	0	0	0	0	0	0	7	120
Sum Glare	0	1	0	0	0	0	0	0	2	0	0	0	0	0	1	2	2	1	9
Policy/Weath	0	1	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	3
Expanded Vehicle	0	1	0	0	0	0	0	1	6	0	1	0	7	12	11	6	2	25	67
Sum Glare	0	10	0	0	0	3	3	1	6	0	1	0	0	0	0	0	0	0	1
Weather/Nature	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Registration	0	1	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	2
Out of County Plate	1	2	0	0	0	0	0	2	3	2	2	2	1	1	1	1	0	0	16
Pager Plates	1	3	0	0	0	1	0	0	0	0	4	1	0	0	0	0	0	0	16
Wrong or No DMV	3	108	7	5	6	9	2	7	28	19	14	12	14	15	27	17	13	44	411
<b>Total</b>	10	108	7	5	6	9	2	7	28	19	14	12	14	15	27	17	13	44	411
<b>Sub Total Violations</b>	9	42	2	7	27	18	17	32	31	2	28	22	9	25	19	27	31	23	371
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	9	42	2	7	27	18	17	32	31	2	28	22	9	25	19	27	31	23	371
<b>Less Rejects</b>																			
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	1-04%	2-01%

# Customer Management Report (Ventura) All Detection Types

01-Jan-2013 to 31-Jan-2013 Operator Id: %

mainunit	VE-BRJ0-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MATG-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VINC-01	VE-VICP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-18%	0-00%	0-00%	0-00%	1-04%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Image Missing	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Plate Bum Out	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Camera Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	3-33%	1-02%	1-50%	0-00%	0-00%	2-11%	4-24%	2-05%	5-16%	0-00%	0-00%	1-05%	0-00%	6-24%	3-16%	7-25%	1-03%	4-17%	0-00%	40-11%
Total	4-44%	1-02%	1-50%	0-00%	3-11%	2-11%	8-47%	4-12%	6-19%	0-00%	1-04%	4-18%	1-11%	8-32%	5-26%	7-26%	1-03%	6-28%	0-00%	62-17%
Approved Violations	5-56%	41-86%	1-50%	7-100%	24-89%	16-89%	9-53%	28-88%	25-81%	2-100%	27-96%	18-82%	8-89%	17-68%	14-74%	20-74%	30-97%	17-74%	0-00%	309-83%
Total Notices Printed	5-56%	41-86%	1-50%	7-100%	24-89%	16-89%	9-53%	28-88%	25-81%	2-100%	27-96%	18-82%	8-89%	17-68%	14-74%	20-74%	30-97%	17-74%	0-00%	309-83%

**Customer Management Report (Ventura) All Detection Types**  
 01-Feb-2013 to 28-Feb-2013 Operator Id: %

Category	VE-BRJO-01	VE-CATH-01	VE-FOVL-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAM-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VMO-01	VE-VOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	16	155	12	14	28	28	35	75	54	10	33	33	31	46	58	36	43	69	776
<b>Less Uncontrollable Factors</b>																			
Obstruction	0	7	5	1	1	1	12	14	5	0	3	1	4	3	11	2	2	3	75
Driver Obstruction/Duckers	0	0	0	1	0	0	0	0	0	0	1	0	0	1	2	0	0	1	6
Motor Cycle Helmet	0	8	1	2	0	2	1	3	1	1	1	2	0	0	0	0	0	3	25
Plate Obstruction	0	1	1	0	0	0	0	0	0	0	1	1	1	0	4	0	0	1	10
Vehicle Obstruction	0	1	1	0	0	0	0	0	0	0	1	1	1	0	0	0	0	1	10
Police	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Chlotion Issued manually	0	2	0	0	0	0	0	1	2	1	0	1	0	0	1	1	1	0	10
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Incorrect/Incomplete DMV	0	1	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Invalid Offense	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Multiple vehicles in frame	0	4	0	0	0	1	0	0	0	0	0	1	0	0	0	0	0	0	6
On or Passed the Stop Bar (PD)	0	2	0	1	2	0	1	1	3	0	0	4	1	0	0	0	0	1	16
Plate Underintelligible	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Plate Turn On Red	0	35	0	0	0	0	0	19	4	0	0	0	0	0	0	0	0	7	66
Sun Glare	0	1	0	0	0	0	0	0	0	1	0	0	0	1	1	0	0	1	5
Policy/Wealth Extended Vehicle	0	0	0	0	0	1	0	0	0	0	0	3	0	0	0	0	0	1	6
er	1	17	0	4	2	3	4	1	4	1	5	1	5	8	7	2	3	19	87
Sun Glare	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Yellow with Red Light	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Registration	0	1	1	0	0	0	0	0	1	0	1	1	0	3	1	1	0	0	14
Paper Plates	2	3	1	0	0	2	1	4	3	0	0	1	1	3	2	0	0	0	23
Issues	3	84	9	10	6	10	19	45	23	4	12	16	12	20	29	8	8	40	358
Wrong or No DMV	2	3	1	0	0	2	1	4	3	0	0	1	1	3	2	0	0	0	23
<b>Sub Total Violations</b>	13	71	3	4	22	18	16	30	31	6	21	17	19	28	29	28	35	29	418
Less In Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	13	71	3	4	22	18	16	30	31	6	21	17	19	28	29	28	35	29	418

Generated By: RWEEKS  
 Generated On: 5/17/2013 2:04:36 PM  
 © Redflex Traffic Systems, Inc

# Customer Management Report (Ventura) All Detection Types

Operator Id: %

01-Feb-2013 to 28-Feb-2013

Category	VE-9RJD-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MATD-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMC-01	VE-VICP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Less Rejects																				
Camera																				
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Not In Frame	2-13%	0-00%	1-33%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Misc Camera Issue	0-00%	0-00%	1-33%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%
Plate Not In Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable Images poor	3-23%	9-13%	0-00%	1-25%	0-00%	4-22%	7-44%	4-13%	0-00%	0-00%	2-10%	3-18%	2-11%	9-35%	0-00%	3-10%	7-25%	2-05%	10-34%	66-16%
Too Old	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police																				
Process	5-38%	10-14%	2-67%	1-35%	0-00%	7-38%	9-56%	4-13%	4-13%	1-17%	3-14%	3-16%	3-16%	5-35%	4-14%	7-25%	3-09%	12-41%	87-21%	
Issues	8-62%	61-86%	1-33%	3-75%	22-100%	11-61%	7-44%	26-87%	27-87%	5-83%	18-88%	14-82%	16-84%	17-65%	25-86%	21-75%	32-81%	17-59%	331-79%	
Total	8-62%	61-86%	1-33%	3-75%	22-100%	11-61%	7-44%	26-87%	27-87%	5-83%	18-88%	14-82%	16-84%	17-65%	25-86%	21-75%	32-81%	17-59%	331-79%	
Approved Violations																				
Total Notices Printed	8-62%	61-86%	1-33%	3-75%	22-100%	11-61%	7-44%	26-87%	27-87%	5-83%	18-88%	14-82%	16-84%	17-65%	25-86%	21-75%	32-81%	17-59%	331-79%	

# Customer Management Report (Ventura) All Detection Types

01-Mar-2013 to 31-Mar-2013

Operator Id: %

Category	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMC-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	16	172	6	21	49	35	34	81	79	7	34	34	14	41	48	45	67	73	857
<b>Less Uncontrollable Factors</b>																			
Obstruction	2	7	1	1	2	2	2	5	4	0	1	0	2	4	2	1	2	3	41
Driver Obstruction/Duckers	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Motor Cycle Helmet	3	4	0	2	1	0	4	1	1	0	2	1	1	0	0	0	1	2	28
Plate Obstruction	0	1	0	0	1	0	1	0	1	4	0	2	0	0	0	0	0	1	12
Vehicle Obstruction	1	4	0	0	0	0	0	0	3	0	1	1	0	0	1	1	1	0	13
Police	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Rejects	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Invalid Offense	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Multiple vehicles in frame	0	6	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	7
On or Passed the Stop Bar (PD)	0	0	0	1	1	1	0	3	3	0	0	4	1	0	0	0	0	0	14
Plate Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Plate Undeniable	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Plate Undeniable	0	31	0	0	0	0	0	25	8	0	0	0	0	0	0	0	0	5	89
Safe Turn On Red	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sun Glare	1	1	0	1	0	0	0	0	1	0	0	1	0	0	0	0	0	1	6
Policy/Weather	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Extended Vehicle	2	21	1	0	2	8	5	4	16	0	3	0	4	17	6	10	3	20	122
Weather/Nature	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	3
Registration	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Out of County Plate	0	8	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Paper Plates	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Whrong or No DMV	1	1	0	0	0	0	1	1	2	0	3	1	0	0	0	0	0	0	28
<b>Total</b>	10	86	3	7	10	13	14	39	39	5	12	13	9	22	18	15	17	35	14
<b>Sub Total Violations</b>	6	86	3	14	39	22	20	42	40	2	22	21	5	19	31	30	50	38	480
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	6	86	3	14	39	22	20	42	40	2	22	21	5	19	31	30	50	38	480

Generated By: RMEEEKS  
Generated On: 3/17/2013 2:03:04 PM

© Redflex Traffic Systems, Inc

# Customer Management Report (Ventura) All Detection Types

Operator Id: %

Camera Matrion	VE-BRQ0-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-00%
Face Not In Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-01%
Mac Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	2-04%	1-03%	6-01%
Plate Not In Frame	0-00%	0-00%	0-00%	2-14%	1-03%	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	2-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	3-01%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-40%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Scene Image No Flash	0-00%	0-00%	1-33%	0-00%	0-00%	0-00%	2-10%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	2-33%	10-12%	0-00%	2-14%	1-03%	4-18%	1-05%	1-02%	1-02%	0-00%	1-05%	3-14%	0-00%	0-00%	2-05%	5-17%	1-02%	9-24%	43-08%
Camera Rejects Total	2-33%	10-12%	1-33%	4-29%	2-05%	7-32%	7-35%	8-19%	1-02%	0-00%	1-05%	3-14%	2-40%	0-00%	4-13%	6-20%	4-08%	10-28%	72-15%
Approved Violations	4-87%	76-88%	2-67%	10-71%	37-95%	15-88%	13-85%	34-81%	39-98%	2-100%	21-95%	18-88%	3-60%	18-100%	27-97%	24-80%	48-92%	28-74%	418-85%
Total Notices Printed	4-87%	76-88%	2-67%	10-71%	37-95%	15-88%	13-85%	34-81%	39-98%	2-100%	21-95%	18-88%	3-60%	19-100%	27-97%	24-80%	48-92%	28-74%	418-85%

# Customer Management Report (Ventura) All Detection Types

Operator Id: %

01-Apr-2013 to 30-Apr-2013

Category	VE-ERJ0-01	VE-CATH-01	VE-FOV-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VVA-01	TOTAL
<b>Total Processed Incidents</b>	15	171	4	10	48	22	45	91	71	12	42	33	34	51	46	32	33	62	622
<b>Less Uncontrollable Factors</b>																			
Obstruction	0	13	1	0	1	2	4	2	3	0	2	3	2	3	8	2	0	2	48
Driver Obstruction/Duckers	0	1	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0	4
Motor Cycle Helmet	1	6	0	0	2	1	3	1	0	0	0	2	0	0	1	0	0	0	17
Plate Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Signal Obstruction	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1
Vehicle Obstruction	0	2	1	0	2	0	2	0	0	1	0	0	1	0	0	0	0	0	9
Police																			
Driver Obstruction (PD)	0	4	0	0	0	0	0	1	3	0	1	0	0	1	0	0	0	0	10
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	1	1	0	0	0	0	0	0	0	0	0	2
Invalid Offense	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Multiple vehicles in frame	0	3	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	3
On or Passed the Stop Bar (PD)	0	0	0	0	0	2	1	2	3	1	0	3	3	0	0	0	0	0	15
Plate Obstruction (PD)	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Safe Turn On Red	0	25	0	0	0	0	0	38	5	0	0	0	0	0	0	0	0	5	73
Sun Glare	0	3	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	3
Policy/Weather																			
Extended Vehicle	0	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	7
Sun Glare	2	30	1	0	4	7	10	3	8	2	9	1	7	23	8	1	4	17	137
Registration																			
Authorized Vehicles	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Paper Plates	2	5	0	0	0	0	2	0	0	0	2	1	1	0	2	0	1	1	20
Whong or No DMV	0	4	0	0	0	0	3	1	3	0	0	0	0	1	1	0	2	4	20
<b>Total</b>	5	67	3	2	12	12	25	50	30	4	14	16	14	28	20	3	8	31	314
<b>Sub Total Violations</b>	10	74	1	8	36	10	20	41	41	8	28	17	20	23	26	29	25	31	448
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	10	74	1	8	36	10	20	41	41	8	28	17	20	23	26	29	25	31	448

Less Rejects

Generated By: RWEEKS

Generated On: 5/17/2013 2:00:05 PM

© Redflex Traffic Systems, Inc

# Customer Management Report (Ventura) All Detection Types

01-Apr-2013 to 30-Apr-2013  
Operator Id: %

Camera Malfunction	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MAT10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	3-01%	
Image Missing	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	3-01%	
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-12%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Driver Undetectable images poor	3-30%	5-07%	0-00%	0-00%	1-03%	4-40%	2-10%	3-07%	4-10%	0-00%	0-00%	3-18%	1-05%	1-04%	2-08%	2-07%	1-04%	2-06%	34-08%	
Police Rejects Process Issues	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Too Old	3-30%	5-07%	0-00%	0-00%	0-00%	4-40%	4-20%	4-10%	5-12%	2-25%	1-04%	4-24%	1-05%	1-04%	2-08%	2-07%	2-08%	3-10%	46-10%	
Approved Violations	7-70%	68-93%	1-100%	1-100%	8-100%	33-92%	6-80%	18-80%	37-90%	36-88%	6-75%	27-86%	13-78%	19-95%	22-96%	24-92%	27-93%	23-92%	28-90%	402-50%
Total Notices Printed	7-70%	68-93%	1-100%	1-100%	8-100%	33-92%	6-80%	18-80%	37-90%	36-88%	6-75%	27-86%	13-78%	19-95%	22-96%	24-92%	27-93%	23-92%	28-90%	402-50%



# Customer Management Report (Ventura) All Detection Types

01-May-2013 to 31-May-2013

Operator Id: %

Total Processed Incidents	4	B4	18	4	30	2	27	34	38	10	9	21	11	33	25	38	16	36	440	
VE-BRJ0-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-CATH-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-FOV-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-JONB-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-MA10-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-MALE-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-MAMI-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-MIDE-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-MITG-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-TGDA-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-THSE-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-VMC-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-VOP-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-VRA-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-VITG-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-VITP-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-VITP-03	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
VE-VIVA-01	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
TOTAL	4	4	18	4	30	2	27	34	38	10	9	21	11	33	25	38	16	36	440	

Less Uncontrollable Factors	0	2	1	0	0	4	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Driver Obstruction/Duckers	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Motor Cycle Helmet	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Plate Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Vehicle Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Police Rejects	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Incomplete DMV	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Multiple vehicles in frame	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
On or Passed the Stop Bar (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Plate Unidentifiable	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Safe Turn On Red	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sun Glare	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Policy/Meal/Extended Vehicle	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sun Glare	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Registration Paper Plates	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Wrong or No DMV	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sub Total Violations	4	41	18	13	1	1	12	23	20	6	6	15	7	24	17	31	13	22	289	
Less In Progress	1	18	13	1	0	1	8	3	3	2	2	1	1	8	10	5	4	4	100	
Available For Prosecution	3	23	3	3	16	1	10	15	17	4	4	14	6	16	7	26	9	12	189	

Less Rejects	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Camera Malfunction	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Face Camera Flash	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Face Camera Focus Blurry	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%
Face Not in Frame	0.00%	0.00%	1.33%	0.00%	0.00%	0.00%	1.10%	0.00%	0.00%	3.75%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%

Generated By: RWEEKS  
 Generated On: 5/17/2013 1:57:11 PM  
 © Redflex Traffic Systems, Inc



# B

## Customer Management Report (Ventura) All Detection Types 01-May-2013 to 31-May-2013 Operator Id: %

	VE-BRJ0-01	VE-CATH-01	VE-FOV-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMC-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Misc Camera Issue	0-00%	0-00%	0-00%	2-67%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%
Plate Not In Frame	0-00%	0-00%	0-00%	0-00%	0-00%	1-100%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-100%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%
Police Repairs	0-00%	1-04%	1-33%	0-00%	1-06%	0-00%	3-30%	0-00%	1-08%	0-00%	0-00%	2-14%	1-08%	1-08%	1-14%	0-00%	1-11%	1-08%	13-07%
Driver Undetectable Images poor	0-00%	1-04%	2-67%	2-67%	1-06%	1-100%	5-50%	0-00%	1-06%	3-75%	0-00%	3-21%	1-06%	1-14%	0-00%	0-00%	1-11%	1-08%	23-12%
Approved Violations	3-100%	22-96%	1-33%	1-33%	15-94%	0-00%	5-50%	15-100%	16-94%	1-25%	4-100%	11-79%	6-100%	15-94%	6-86%	26-100%	8-89%	11-92%	166-88%
Total Notices Printed	3-100%	22-96%	1-33%	1-33%	15-94%	0-00%	5-50%	15-100%	16-94%	1-25%	4-100%	11-79%	6-100%	15-94%	6-86%	26-100%	8-89%	11-92%	166-88%