

Customer Management Report (Vista) All Detection Types

01-Jul-2015 to 31-Jul-2015

Operator Id: %

		VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Total Processed Incidents		14	124	147	42	169	41	413	59	101	1110
Less Uncontrollable Factors											
Obstruction	Driver Obstruction/Duckers	1	1	20	0	2	0	3	0	3	30
	Motor Cycle Helmet	0	0	0	0	0	0	1	0	1	2
	Plate Obstruction	2	1	4	0	4	1	3	1	2	18
	Vehicle Obstruction	1	1	7	1	8	6	10	0	1	35
Police Rejects	Emergency Vehicle Responding	9	1	3	5	11	1	0	15	6	51
	Face Obstruction	0	1	0	0	1	0	0	0	0	2
	Incorrect/Incomplete DMV	0	0	1	0	3	0	3	0	0	7
	Police Discretion	0	21	31	3	20	3	80	1	24	183
	Safe Turn On Red	0	0	2	0	1	0	4	0	2	9
	Sun Glare	0	0	1	1	0	0	1	1	1	5
Policy/Weather	Extended Vehicle	0	0	0	1	0	0	1	0	0	2
	Sun Glare	0	5	17	7	14	9	14	0	18	84
	Weather/Nature	0	5	2	1	2	0	4	1	1	16
Registration Issues	Paper Plates	0	8	4	3	3	1	9	0	3	31
	Wrong or No DMV	0	1	0	1	0	0	1	0	0	3
Total		13	45	92	23	69	21	134	19	62	478
Sub Total Violations		1	79	55	19	100	20	279	40	39	632
Less in Progress		0	0	0	0	0	0	0	0	0	0
Available For Prosecution		1	79	55	19	100	20	279	40	39	632
Less Rejects											
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
	Image Missing	0-00%	0-00%	3-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: HHAENIN

Generated On: 1/4/2016 1:30:11 PM

Customer Management Report (Vista) All Detection Types

01-Jul-2015 to 31-Jul-2015

Operator Id: %

		VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Police	Driver Unidentifiable images poor	0-00%	1-01%	0-00%	1-05%	1-01%	0-00%	1-00%	1-02%	0-00%	5-01%
Rejects	Too Old	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process	Issues										
Total		0-00%	1-01%	3-05%	2-11%	3-03%	0-00%	1-00%	1-02%	0-00%	11-02%
Approved Violations		1-100%	78-99%	52-95%	17-89%	97-97%	20-100%	278-100%	39-98%	39-100%	621-98%
Total Notices Printed		1-100%	78-99%	52-95%	17-89%	97-97%	20-100%	278-100%	39-98%	39-100%	621-98%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: HHAENIN

Generated On: 1/4/2016 1:30:11 PM

Customer Management Report (Vista) All Detection Types

01-Aug-2015 to 31-Aug-2015

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Total Processed Incidents	13	157	171	49	182	65	450	56	113	1256
Less Uncontrollable Factors										
Obstruction										
Driver Obstruction/Duckers	0	2	21	2	4	0	1	0	4	34
Motor Cycle Helmet	0	2	0	0	0	0	1	0	0	3
Plate Obstruction	0	0	3	1	1	0	3	1	0	9
Vehicle Obstruction	0	1	10	1	4	4	4	0	3	27
Police Rejects										
Emergency Vehicle Responding	2	1	7	3	1	0	0	13	2	29
Face Obstruction	0	0	1	0	0	0	1	0	1	3
Incorrect/Incomplete DMV	0	1	0	0	0	0	2	0	0	3
Police Discretion	2	27	18	6	27	4	60	1	25	170
Safe Turn On Red	0	2	3	0	4	0	10	0	4	23
Sun Glare	0	0	0	0	1	1	2	0	1	5
Policy/Weather										
Extended Vehicle	0	1	1	0	0	0	4	0	0	6
Sun Glare	0	2	29	11	20	11	21	8	15	117
Weather/Nature	1	0	0	1	0	0	0	0	0	2
Registration Issues										
Out of Country Plate	0	0	1	0	0	0	2	0	0	3
Paper Plates	0	6	4	1	6	0	9	2	4	32
Wrong or No DMV	0	0	1	0	0	0	1	0	0	2
Total	5	45	99	26	68	20	121	25	59	468
Sub Total Violations	8	112	72	23	114	45	329	31	54	788
Less in Progress	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	8	112	72	23	114	45	329	31	54	788
Less Rejects										
Camera Malfunction										
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%
Test Pattern	0-00%	0-00%	27-38%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	27-03%

Generated By: HHAENIN

Generated On: 1/4/2016 1:31:28 PM

Customer Management Report (Vista) All Detection Types

01-Aug-2015 to 31-Aug-2015

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Police Driver Unidentifiable images poor	0-00%	0-00%	2-03%	0-00%	2-02%	1-02%	1-00%	0-00%	0-00%	6-01%
Rejects										
Total	0-00%	0-00%	29-40%	0-00%	2-02%	1-02%	2-01%	0-00%	0-00%	34-04%
Approved Violations	8-100%	112-100%	43-60%	23-100%	112-98%	44-98%	327-99%	31-100%	54-100%	754-96%
Total Notices Printed	8-100%	112-100%	43-60%	23-100%	112-98%	44-98%	327-99%	31-100%	54-100%	754-96%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: HHAENIN

Generated On: 1/4/2016 1:31:28 PM

Customer Management Report (Vista) All Detection Types

01-Sep-2015 to 30-Sep-2015

Operator Id: %

		VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Total Processed Incidents		19	128	200	42	154	62	421	83	116	1225
Less Uncontrollable Factors											
Obstruction	Driver Obstruction/Duckers	0	7	35	1	7	1	7	1	6	65
	Motor Cycle Helmet	0	1	0	0	0	0	0	1	0	2
	Plate Obstruction	0	2	7	1	0	0	3	1	5	19
	Vehicle Obstruction	2	2	7	0	4	6	8	1	2	32
Police Rejects	Emergency Vehicle Responding	2	2	6	2	4	0	7	18	3	44
	Incorrect/Incomplete DMV	0	2	1	0	0	0	2	0	0	5
	Police Discretion	2	19	18	3	25	3	58	1	19	148
	Safe Turn On Red	0	0	2	0	2	0	7	0	5	16
	Sun Glare	0	0	0	0	1	0	0	0	0	1
Policy/Weather	Extended Vehicle	0	0	0	0	0	0	5	2	0	7
	Sun Glare	0	4	36	12	28	19	20	15	15	149
	Weather/Nature	0	1	3	1	1	1	2	2	2	13
Registration Issues	Paper Plates	0	3	7	0	1	0	11	0	2	24
Total		6	43	122	20	73	30	130	42	59	525
Sub Total Violations		13	85	78	22	81	32	291	41	57	700
Less in Progress		0	0	0	0	0	0	0	0	0	0
Available For Prosecution		13	85	78	22	81	32	291	41	57	700
Less Rejects											
Camera Malfunction	Face Camera Flash	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	2-00%
	Face Camera No Flash	0-00%	1-01%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	2-00%
	Misc Camera Issue	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: HHAENIN

Generated On: 1/4/2016 1:32:00 PM

Customer Management Report (Vista) All Detection Types

01-Sep-2015 to 30-Sep-2015

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	17-06%	0-00%	0-00%	17-02%
Test Pattern	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-00%
Police Rejects										
No Video	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	1-08%	3-04%	1-01%	0-00%	3-04%	0-00%	18-06%	0-00%	1-02%	27-04%
Approved Violations	12-92%	82-96%	77-99%	22-100%	78-96%	32-100%	273-94%	41-100%	56-98%	673-96%
Total Notices Printed	12-92%	82-96%	77-99%	22-100%	78-96%	32-100%	273-94%	41-100%	56-98%	673-96%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: HHAENIN

Generated On: 1/4/2016 1:32:00 PM

Customer Management Report (Vista) All Detection Types

01-Oct-2015 to 31-Oct-2015

Operator Id: %

		VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Total Processed Incidents		17	135	91	48	189	18	427	76	122	1123
Less Uncontrollable Factors											
Obstruction	Driver Obstruction/Duckers	0	3	10	3	3	0	4	2	3	28
	Motor Cycle Helmet	1	2	0	0	0	0	1	0	0	4
	Plate Obstruction	0	0	2	2	7	1	6	4	4	26
	Vehicle Obstruction	2	1	3	1	4	0	6	1	1	19
Police Rejects	Emergency Vehicle Responding	1	0	1	3	1	3	4	8	0	21
	Face Obstruction	0	0	0	0	0	0	1	0	0	1
	Incorrect/Incomplete DMV	1	0	0	0	0	0	1	0	1	3
	Multiple vehicles in frame	0	0	0	1	0	0	1	0	0	2
	Police Discretion	2	12	2	5	9	3	35	4	6	78
	Safe Turn On Red	0	10	12	1	14	0	54	0	29	120
	Sun Glare	0	0	0	0	0	0	0	0	2	2
	Policy/Weather	Extended Vehicle	0	0	0	0	0	0	8	0	0
	Sun Glare	1	5	13	8	25	3	6	8	8	77
	Weather/Nature	0	2	1	3	1	0	2	0	2	11
Registration Issues	Out of Country Plate	0	0	0	0	0	0	1	0	0	1
	Paper Plates	0	6	0	1	6	0	9	2	9	33
Total		8	41	44	28	70	10	139	29	65	434
Sub Total Violations		9	94	47	20	119	8	288	47	57	689
Less in Progress		0	0	0	0	0	0	0	0	0	0
Available For Prosecution		9	94	47	20	119	8	288	47	57	689
Less Rejects											
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: HHAENIN

Generated On: 1/4/2016 1:32:34 PM

Customer Management Report (Vista) All Detection Types

01-Oct-2015 to 31-Oct-2015

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Rejects										
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	2-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	2-00%
Process Issues										
Too Old	0-00%	1-01%	2-04%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	4-01%
Total	0-00%	1-01%	2-04%	0-00%	7-06%	0-00%	2-01%	0-00%	3-05%	15-02%
Approved Violations	9-100%	93-99%	45-96%	20-100%	112-94%	8-100%	286-99%	47-100%	54-95%	674-98%
Total Notices Printed	9-100%	93-99%	45-96%	20-100%	112-94%	8-100%	286-99%	47-100%	54-95%	674-98%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: HHAENIN

Generated On: 1/4/2016 1:32:34 PM

Customer Management Report (Vista) All Detection Types

01-Nov-2015 to 30-Nov-2015

Operator Id: %

		VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Total Processed Incidents		7	148	166	38	171	11	425	73	85	1124
Less Uncontrollable Factors											
Obstruction	Driver Obstruction/Duckers	0	4	10	1	2	0	5	1	3	26
	Plate Obstruction	0	1	7	1	4	0	4	3	2	22
	Vehicle Obstruction	1	1	5	1	7	3	9	2	1	30
Police Rejects	Emergency Vehicle Responding	1	1	1	1	2	0	1	10	2	19
	Face Obstruction	0	1	1	0	0	0	0	1	0	3
	Incorrect/Incomplete DMV	0	0	0	0	0	0	3	0	0	3
	Police Discretion	0	26	19	4	30	2	56	2	17	156
	Safe Turn On Red	0	12	11	0	14	0	20	0	15	72
	Sun Glare	0	0	1	0	0	0	0	0	1	2
	Extended Vehicle	0	2	0	0	0	0	3	0	0	5
Policy/Weather	Sun Glare	0	2	8	7	19	0	6	5	4	51
	Weather/Nature	0	0	1	0	0	0	0	1	0	2
Registration Issues	Paper Plates	0	3	5	0	3	0	12	1	2	26
Total		2	53	69	15	81	5	119	26	47	417
Sub Total Violations		5	95	97	23	90	6	306	47	38	707
Less in Progress		0	0	0	0	0	0	0	0	0	0
Available For Prosecution		5	95	97	23	90	6	306	47	38	707
Less Rejects											
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	2-00%
	Image Missing	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: HHAENIN

Generated On: 1/4/2016 1:32:56 PM

Customer Management Report (Vista) All Detection Types

01-Nov-2015 to 30-Nov-2015

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Test Pattern	0-00%	0-00%	0-00%	5-22%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%
Video Skips	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects										
Process Issues										
Driver Unidentifiable images poor	0-00%	0-00%	1-01%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	2-00%
Too Old	0-00%	1-01%	1-01%	0-00%	1-01%	0-00%	1-00%	0-00%	1-03%	5-01%
Total	0-00%	1-01%	4-04%	5-22%	6-07%	0-00%	1-00%	1-02%	1-03%	19-03%
Approved Violations	5-100%	94-99%	93-96%	18-78%	84-93%	6-100%	305-100%	46-98%	37-97%	688-97%
Total Notices Printed	5-100%	94-99%	93-96%	18-78%	84-93%	6-100%	305-100%	46-98%	37-97%	688-97%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: HHAENIN

Generated On: 1/4/2016 1:32:56 PM

Customer Management Report (Vista) All Detection Types

01-Dec-2015 to 31-Dec-2015

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL	
Total Processed Incidents	17	133	144	48	165	8	369	81	86	1051	
Less Uncontrollable Factors											
Obstruction	Driver Obstruction/Duckers	1	3	15	2	7	0	5	4	3	40
	Motor Cycle Helmet	0	1	0	0	0	0	0	0	0	1
	Plate Obstruction	1	2	2	1	5	0	1	1	2	15
	Vehicle Obstruction	0	1	2	1	7	1	7	1	2	22
Police Rejects	Citation Issued manually	0	0	0	0	0	0	1	0	0	1
	Emergency Vehicle Responding	4	0	1	1	2	0	5	8	0	21
	Incorrect/Incomplete DMV	0	0	0	0	0	0	1	0	0	1
	Multiple vehicles in frame	0	0	0	0	0	0	1	0	0	1
	Police Discretion	3	20	5	4	15	1	35	4	10	97
	Safe Turn On Red	0	7	16	0	16	0	27	0	10	76
Policy/Weather	Extended Vehicle	0	0	0	0	1	0	3	0	0	4
	Sun Glare	1	2	4	8	16	0	2	9	2	44
	Weather/Nature	0	3	2	4	0	0	3	0	0	12
Registration Issues	Paper Plates	0	7	2	3	6	0	14	3	3	38
	Wrong or No DMV	0	0	0	0	0	0	1	0	0	1
Total		10	46	49	24	75	2	105	31	32	374
Sub Total Violations		7	87	95	24	90	6	264	50	54	677
Less in Progress		2	17	23	5	18	2	72	11	16	166
Available For Prosecution		5	70	72	19	72	4	192	39	38	511
Less Rejects											
Camera Malfunction	Face Camera Flash	0-00%	0-00%	1-01%	2-11%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	2-00%

Generated By: HHAENIN

Generated On: 1/4/2016 1:33:18 PM

Customer Management Report (Vista) All Detection Types

01-Dec-2015 to 31-Dec-2015

Operator Id: %

	VST-CCSA-01	VST-EMVW-01	VST-HAME-01	VST-MEHA-01	VST-SACC-01	VST-SAVI-01	VST-SYSH-01	VST-VISA-01	VST-VWEM-01	TOTAL
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Process Issues	0-00%	0-00%	2-03%	0-00%	1-01%	0-00%	0-00%	0-00%	1-03%	4-01%
Total	0-00%	0-00%	3-04%	2-11%	2-03%	0-00%	3-02%	0-00%	1-03%	11-02%
Approved Violations	5-100%	70-100%	69-96%	17-89%	70-97%	4-100%	189-98%	39-100%	37-97%	500-98%
Total Notices Printed	5-100%	70-100%	69-96%	17-89%	70-97%	4-100%	189-98%	39-100%	37-97%	500-98%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: HHAENIN

Generated On: 1/4/2016 1:33:18 PM