

# Customer Management Report (Santa Clarita) All Detection Types

01-Dec-2012 to 31-Dec-2012

Operator Id: %

	SCL-BCNR-01	SCL-BCSC-01	SCL-MMMB-01	SCL-NRBC-01	SCL-NRMB-01	SCL-OVL-Y-01	SCL-VAMB-01	SCL-VAMB-03	SCL-WCSC-01	SCL-WCSC-03	TOTAL	
<b>Total Processed Incidents</b>	91	90	76	53	90	69	552	0	177	28	1226	
<b>Less Uncontrollable Factors</b>												
Obstruction	Driver Obstruction/Duckers	0	1	9	8	3	3	8	0	3	1	36
	Plate Obstruction	1	1	1	0	1	3	3	0	3	1	14
	Vehicle Obstruction	7	1	2	0	2	1	18	0	5	1	37
Police Rejects	Emergency Vehicle Responding	9	11	0	1	0	10	0	0	6	2	39
	Incorrect/Incomplete DMV	2	1	3	1	3	0	10	0	2	1	23
	Invalid Offense	12	4	0	0	0	2	7	0	0	0	25
	Straight through on left	0	0	0	0	0	0	0	0	1	0	1
	Sun Glare	0	0	0	0	0	0	1	0	0	0	1
	VEHICLE OBSTRUCTION	1	0	0	0	0	0	1	0	0	0	2
	View of Driver Obstructed	0	0	0	1	0	0	0	0	0	0	1
	Weather Conditions	0	0	0	0	0	0	1	0	0	0	1
Policy/Weather	Extended Vehicle	1	1	0	0	0	0	1	0	0	0	3
	Sun Glare	15	4	3	6	1	1	14	0	4	5	53
	Two Vehicles in Beam	0	0	0	0	0	0	0	0	1	0	1
	Weather/Nature	1	0	1	1	1	0	3	0	1	0	8
Registration Issues	Paper Plates	4	4	4	2	3	2	22	0	7	0	48
	Wrong or No DMV	0	0	0	0	1	0	0	0	0	0	1
<b>Total</b>		53	28	23	20	15	22	89	0	33	11	294
<b>Sub Total Violations</b>		38	62	53	33	75	47	463	0	144	17	932
Less in Progress		0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		38	62	53	33	75	47	463	0	144	17	932

## Less Rejects

Camera Malfunction	Face Camera Flash	0-00%	1-02%	0-00%	3-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
--------------------	-------------------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------

Generated By: MHUNTER

Generated On: 2/15/2013 9:26:09 AM

# Customer Management Report (Santa Clarita) All Detection Types

01-Dec-2012 to 31-Dec-2012

Operator Id: %

	SCL-BCNR-01	SCL-BCSC-01	SCL-MMMB-01	SCL-NRBC-01	SCL-NRMB-01	SCL-OVL-Y-01	SCL-VAMB-01	SCL-VAMB-03	SCL-WCSC-01	SCL-WCSC-03	TOTAL
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	2-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-00%	0-00%	2-01%	0-00%	4-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects											
Driver Unidentifiable images poor	2-05%	0-00%	1-02%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
Limit line obstructed	1-03%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
<b>Total</b>	<b>3-08%</b>	<b>1-02%</b>	<b>1-02%</b>	<b>5-15%</b>	<b>2-03%</b>	<b>1-02%</b>	<b>2-00%</b>	<b>0-00%</b>	<b>4-03%</b>	<b>0-00%</b>	<b>19-02%</b>
<b>Approved Violations</b>	<b>35-92%</b>	<b>61-98%</b>	<b>52-98%</b>	<b>28-85%</b>	<b>73-97%</b>	<b>46-98%</b>	<b>461-100%</b>	<b>0-00%</b>	<b>140-97%</b>	<b>17-100%</b>	<b>913-98%</b>
<b>Total Notices Printed</b>	<b>35-92%</b>	<b>61-98%</b>	<b>52-98%</b>	<b>28-85%</b>	<b>73-97%</b>	<b>46-98%</b>	<b>461-100%</b>	<b>0-00%</b>	<b>140-97%</b>	<b>17-100%</b>	<b>913-98%</b>

Generated By: MHUNTER

Generated On: 2/15/2013 9:26:09 AM

# Customer Management Report (Santa Clarita) All Detection Types

01-Jan-2013 to 31-Jan-2013

Operator Id: %

		SCL-BCNR-01	SCL-BCSC-01	SCL-MMMB-01	SCL-NRBC-01	SCL-NRMB-01	SCL-OVL-Y-01	SCL-VAMB-01	SCL-VAMB-03	SCL-WCSC-01	SCL-WCSC-03	TOTAL
<b>Total Processed Incidents</b>		210	136	99	43	56	107	399	7	65	24	1146
<b>Less Uncontrollable Factors</b>												
Obstruction	Driver Obstruction/Duckers	35	13	20	6	7	29	15	0	9	1	135
	Motor Cycle Helmet	0	1	0	0	0	0	1	0	0	0	2
	Plate Obstruction	29	9	3	0	2	6	3	0	2	2	56
	Vehicle Obstruction	4	1	1	0	0	2	3	0	0	1	12
Police Rejects	Emergency Vehicle Responding	12	19	0	1	1	10	3	4	3	1	54
	Incorrect/Incomplete DMV	1	0	2	1	0	0	6	0	0	0	10
	Invalid Offense	45	17	2	0	0	14	23	0	4	1	106
	On or Passed the Stop Bar (PD)	0	0	0	0	0	0	2	0	0	0	2
	Police Discretion	0	0	0	0	0	0	2	0	0	0	2
	View of Driver Obstructed	0	0	0	0	0	0	1	0	0	0	1
	Yielding to an Emergency	0	1	0	0	0	0	0	0	0	0	1
Policy/Weather	Extended Vehicle	0	0	1	0	0	0	0	0	0	1	2
	Sun Glare	15	26	8	7	1	1	7	0	0	2	67
	Weather/Nature	1	0	0	1	0	2	3	0	0	0	7
Registration Issues	Paper Plates	9	2	5	2	0	0	13	0	1	1	33
<b>Total</b>		151	89	42	18	11	64	82	4	19	10	490
<b>Sub Total Violations</b>		59	47	57	25	45	43	317	3	46	14	656
Less in Progress		0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		59	47	57	25	45	43	317	3	46	14	656
<b>Less Rejects</b>												
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Camera Flash	0-00%	0-00%	1-02%	2-08%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	4-01%

Generated By: MHUNTER

Generated On: 2/15/2013 9:27:29 AM

# Customer Management Report (Santa Clarita) All Detection Types

01-Jan-2013 to 31-Jan-2013

Operator Id: %

	SCL-BCNR-01	SCL-BCSC-01	SCL-MMMB-01	SCL-NRBC-01	SCL-NRMB-01	SCL-OVL-Y-01	SCL-VAMB-01	SCL-VAMB-03	SCL-WCSC-01	SCL-WCSC-03	TOTAL
Face Camera Focus Blurry	6-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%
Face Not in Frame	7-12%	1-02%	0-00%	1-04%	1-02%	0-00%	1-00%	0-00%	0-00%	0-00%	11-02%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-02%	0-00%	2-00%
Plate Burn Out	5-08%	2-04%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	8-01%
Plate Not in Frame	1-02%	2-04%	1-02%	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	0-00%	6-01%
Rear Plate Camera Blurry	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	1-02%	0-00%	3-00%
Rear Plate Flash Inappropriate	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-33%	0-00%	0-00%	3-00%
Police Rejects											
Limit line obstructed	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues											
Too Old	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	22-37%	5-11%	3-05%	5-20%	3-07%	2-05%	4-01%	1-33%	2-04%	0-00%	47-07%
Approved Violations	37-63%	42-89%	54-95%	20-80%	42-93%	41-95%	313-99%	2-67%	44-96%	14-100%	609-93%
Total Notices Printed	37-63%	42-89%	54-95%	20-80%	42-93%	41-95%	313-99%	2-67%	44-96%	14-100%	609-93%

Generated By: MHUNTER

Generated On: 2/15/2013 9:27:29 AM

# Customer Management Report (Santa Clarita) All Detection Types

01-Feb-2013 to 28-Feb-2013

Operator Id: %

		SCL-BCNR-01	SCL-BCSC-01	SCL-MMMB-01	SCL-NRBC-01	SCL-NRMB-01	SCL-OVLY-01	SCL-VAMB-01	SCL-VAMB-03	SCL-WCSC-01	SCL-WCSC-03	TOTAL
<b>Total Processed Incidents</b>		137	156	64	44	71	105	510	100	86	20	1293
<b>Less Uncontrollable Factors</b>												
Obstruction	Driver Obstruction/Duckers	3	4	4	1	0	4	9	1	1	0	27
	Plate Obstruction	10	4	0	3	1	4	0	18	0	1	41
	Vehicle Obstruction	4	1	2	1	1	3	6	1	0	0	19
Police Rejects	Emergency Vehicle Responding	14	10	1	1	1	12	1	15	6	0	61
	Incorrect/Incomplete DMV	1	2	2	0	1	2	6	2	0	0	16
	Invalid Offense	38	21	3	0	0	15	10	5	2	1	95
	On or Passed the Stop Bar (PD).	0	0	0	0	1	0	2	0	1	1	5
	Plate Unidentifiable	0	0	0	0	0	0	0	0	1	0	1
	Police Discretion	1	0	0	0	0	0	2	0	0	0	3
	Straight through on left	0	24	0	0	0	0	2	0	13	0	39
	VEHICLE OBSTRUCTION	1	0	0	0	0	0	0	0	0	0	1
	View of Driver Obstructed	0	0	1	0	0	0	0	0	0	0	1
	screeching stop	8	4	0	0	0	3	10	1	0	0	26
	Policy/Weather	Extended Vehicle	2	0	1	0	0	0	1	0	0	0
Sun Glare		10	17	6	12	0	5	13	4	2	1	70
Weather/Nature		2	1	0	0	0	0	1	0	1	0	5
Registration Issues	Out of Country Plate	0	0	0	0	0	0	1	0	0	0	1
	Paper Plates	9	6	4	1	1	1	28	5	3	1	59
<b>Total</b>		103	94	24	19	6	49	92	52	30	5	474
<b>Sub Total Violations</b>		34	62	40	25	65	56	418	48	56	15	819
Less in Progress		0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		34	62	40	25	65	56	418	48	56	15	819
<b>Less Rejects</b>												
Camera Malfunction	Face Camera Flash	1-03%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Face Camera Focus Blurry	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Face Camera No Flash	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Not in Frame	1-03%	2-03%	1-02%	1-04%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	6-01%
	Image Missing	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	1-02%	1-02%	0-00%	0-00%	0-00%	0-00%	2-00%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
	Plate Not in Frame	0-00%	1-02%	0-00%	0-00%	3-05%	0-00%	0-00%	1-02%	0-00%	0-00%	5-01%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-04%	1-02%	0-00%	3-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	2-00%
	Rear Plate No Flash	0-00%	0-00%	3-08%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
	Scene Image No Flash	0-00%	0-00%	2-05%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	3-00%

Generated By: MHUNTER

Generated On: 4/26/2013 10:22:53 AM

# Customer Management Report (Santa Clarita) All Detection Types

01-Feb-2013 to 28-Feb-2013

Operator Id: %

		SCL-BCNR-01	SCL-BCSC-01	SCL-MMMB-01	SCL-NRBC-01	SCL-NRMB-01	SCL-OVLY-01	SCL-VAMB-01	SCL-VAMB-03	SCL-WCSC-01	SCL-WCSC-03	TOTAL
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-00%
	Red-light not visible in	0-00%	0-00%	1-02%	1-04%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	3-00%
	Unclear Scene Image	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	2-00%
<b>Total</b>		<b>2-06%</b>	<b>6-10%</b>	<b>8-20%</b>	<b>5-20%</b>	<b>5-08%</b>	<b>1-02%</b>	<b>3-01%</b>	<b>7-15%</b>	<b>1-02%</b>	<b>0-00%</b>	<b>38-05%</b>
<b>Approved Violations</b>		<b>32-94%</b>	<b>56-90%</b>	<b>32-80%</b>	<b>20-80%</b>	<b>60-92%</b>	<b>55-98%</b>	<b>415-99%</b>	<b>41-85%</b>	<b>55-98%</b>	<b>15-100%</b>	<b>781-95%</b>
<b>Total Notices Printed</b>		<b>32-94%</b>	<b>56-90%</b>	<b>32-80%</b>	<b>20-80%</b>	<b>60-92%</b>	<b>55-98%</b>	<b>415-99%</b>	<b>41-85%</b>	<b>55-98%</b>	<b>15-100%</b>	<b>781-95%</b>

Generated By: MHUNTER

Generated On: 4/26/2013 10:22:53 AM

# Customer Management Report (Santa Clarita) All Detection Types

01-Mar-2013 to 31-Mar-2013

Operator Id: %

	SCL-BCNR-01	SCL-BCSC-01	SCL-MMMB-01	SCL-NRBC-01	SCL-NRMB-01	SCL-OVL-Y-01	SCL-VAMB-01	SCL-VAMB-03	SCL-WCSC-01	SCL-WCSC-03	TOTAL
<b>Total Processed Incidents</b>	141	205	124	64	94	87	647	154	133	33	1682
<b>Less Uncontrollable Factors</b>											
Obstruction											
Driver Obstruction/Duckers	3	8	21	2	3	4	2	4	0	1	48
Motor Cycle Helmet	0	0	0	0	0	0	0	0	1	0	1
Plate Obstruction	15	7	4	3	0	0	6	14	2	1	52
Signal Obstruction	0	0	0	1	0	0	1	0	0	0	2
Vehicle Obstruction	7	2	4	1	2	2	24	2	2	0	46
Police Rejects											
Emergency Vehicle Responding	13	21	0	0	1	11	1	36	5	3	91
Incorrect/Incomplete DMV	2	0	1	1	1	1	13	1	4	0	24
Invalid Offense	1	0	0	0	0	0	0	0	0	0	1
On or Passed the Stop Bar (PD)	0	0	0	1	0	0	3	0	0	1	5
Police Discretion	0	0	0	1	0	0	2	0	0	0	3
Straight through on left	0	5	0	0	0	0	0	0	3	0	8
VEHICLE OBSTRUCTION	1	0	0	0	0	0	0	0	0	0	1
View of Driver Obstructed	0	0	0	1	0	0	1	0	1	0	3
screaching stop	22	12	5	0	0	13	18	5	0	3	78
Policy/Weather											
Extended Vehicle	1	0	0	0	0	0	5	0	0	0	6
Sun Glare	18	27	16	14	7	1	47	10	0	3	143
Weather/Nature	3	0	0	0	0	0	1	0	0	0	4
Registration Issues											
Out of Country Plate	0	0	0	0	1	0	1	0	0	0	2
Paper Plates	4	15	2	3	3	1	31	4	3	1	67
<b>Total</b>	90	97	53	28	18	33	156	76	21	13	585
<b>Sub Total Violations</b>	51	108	71	36	76	54	491	78	112	20	1097
Less in Progress	0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>	51	108	71	36	76	54	491	78	112	20	1097

Generated By: MHUNTER

Generated On: 4/26/2013 10:28:23 AM

# Customer Management Report (Santa Clarita) All Detection Types

01-Mar-2013 to 31-Mar-2013

Operator Id: %

		SCL-BCNR-01	SCL-BCSC-01	SCL-MMMB-01	SCL-NRBC-01	SCL-NRMB-01	SCL-OVL-Y-01	SCL-VAMB-01	SCL-VAMB-03	SCL-WCSC-01	SCL-WCSC-03	TOTAL
<b>Less Rejects</b>												
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	2-06%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	3-00%
	Face Camera Focus Blurry	0-00%	0-00%	3-04%	0-00%	1-01%	0-00%	5-01%	2-03%	0-00%	0-00%	11-01%
	Face Not in Frame	0-00%	0-00%	3-04%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	4-00%
	Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	1-00%
	Misc Camera Issue	0-00%	2-02%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	2-02%	0-00%	6-01%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	2-00%
	Plate Not in Frame	0-00%	1-01%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	1-03%	1-01%	1-02%	0-00%	0-00%	1-01%	0-00%	4-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	3-04%	0-00%	0-00%	4-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	1-00%
	Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Limit line obstructed	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-00%
	Red-light not visible in	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%	5-06%	0-00%	0-00%	12-01%
Total		1-02%	3-03%	7-10%	3-08%	6-08%	1-02%	14-03%	12-15%	4-04%	2-10%	53-05%
<b>Approved Violations</b>		50-98%	105-97%	64-90%	33-92%	70-92%	53-98%	477-97%	66-85%	108-96%	18-90%	1044-95%
<b>Total Notices Printed</b>		50-98%	105-97%	64-90%	33-92%	70-92%	53-98%	477-97%	66-85%	108-96%	18-90%	1044-95%

Generated By: MHUNTER

Generated On: 4/26/2013 10:28:23 AM



# Customer Management Report (Santa Clarita) All Detection Types

01-Apr-2013 to 30-Apr-2013

Operator Id: %

		SCL-BCNR-01	SCL-BCSC-01	SCL-MMMB-01	SCL-NRBC-01	SCL-NRMB-01	SCL-OVL-Y-01	SCL-VAMB-01	SCL-VAMB-03	SCL-WCSC-01	SCL-WCSC-03	TOTAL
<b>Total Processed Incidents</b>		15	204	114	76	108	115	611	145	127	24	1539
<b>Less Uncontrollable Factors</b>												
Obstruction	Driver Obstruction/Duckers	3	2	11	4	7	5	12	3	0	0	47
	Plate Obstruction	3	6	1	2	1	1	4	15	6	0	39
	Signal Obstruction	0	0	0	0	0	0	0	1	0	0	1
	Vehicle Obstruction	0	1	5	0	2	2	13	1	1	0	25
Police Rejects	Emergency Vehicle Responding	1	26	2	2	1	19	0	21	8	4	84
	Incorrect/Incomplete DMV	1	2	1	0	2	1	6	1	1	0	15
	On or Passed the Stop Bar (PD).	0	0	0	0	0	0	3	0	0	0	3
	Plate Unidentifiable	0	1	0	0	0	0	0	0	1	0	2
	Police Discretion	0	1	0	0	0	0	4	0	0	0	5
	View of Driver Obstructed	0	0	0	1	0	0	2	0	0	0	3
	screeching stop	0	15	3	1	1	14	17	6	4	0	61
	Policy/Weather	Extended Vehicle	0	0	1	0	0	0	2	0	0	0
	Sun Glare	0	23	20	26	7	3	87	14	3	3	186
Registration Issues	Out of Country Plate	0	0	1	0	0	0	2	0	0	0	3
	Paper Plates	0	4	3	3	4	3	17	7	5	1	47
<b>Total</b>		8	81	48	39	25	48	169	69	29	8	524
<b>Sub Total Violations</b>		7	123	66	37	83	67	442	76	98	16	1015
Less in Progress		0	0	0	0	0	0	0	0	0	0	0
<b>Available For Prosecution</b>		7	123	66	37	83	67	442	76	98	16	1015
<b>Less Rejects</b>												
Camera Malfunction	Face Camera Focus Blurry	0-00%	0-00%	1-02%	0-00%	0-00%	2-03%	1-00%	1-01%	0-00%	0-00%	5-00%
	Face Not in Frame	0-00%	4-03%	0-00%	2-05%	0-00%	0-00%	0-00%	2-03%	1-01%	0-00%	9-01%
	Image Missing	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: MHUNTER

Generated On: 5/13/2013 3:19:33 PM

# Customer Management Report (Santa Clarita) All Detection Types

01-Apr-2013 to 30-Apr-2013

Operator Id: %

	SCL-BCNR-01	SCL-BCSC-01	SCL-MMMB-01	SCL-NRBC-01	SCL-NRMB-01	SCL-OVL-Y-01	SCL-VAMB-01	SCL-VAMB-03	SCL-WCSC-01	SCL-WCSC-03	TOTAL
Misc Camera Issue	0-00%	1-01%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	3-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-04%	0-00%	0-00%	3-00%
Plate Not in Frame	0-00%	4-03%	0-00%	0-00%	1-01%	0-00%	0-00%	1-01%	2-02%	0-00%	8-01%
Rear Plate Camera Blurry	0-00%	2-02%	0-00%	1-03%	0-00%	0-00%	1-00%	4-05%	3-03%	0-00%	11-01%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	4-05%	1-01%	0-00%	6-01%
Police Rejects											
Driver Unidentifiable images poor	0-00%	0-00%	1-02%	0-00%	2-02%	0-00%	0-00%	1-01%	0-00%	0-00%	4-00%
Plate Unclear	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Red-light not visible in	2-29%	2-02%	0-00%	0-00%	0-00%	0-00%	3-01%	7-09%	0-00%	0-00%	14-01%
Total	2-29%	14-11%	3-05%	3-08%	3-04%	2-03%	6-01%	23-30%	9-09%	0-00%	65-06%
Approved Violations	5-71%	109-89%	63-95%	34-92%	80-96%	65-97%	436-99%	53-70%	89-91%	16-100%	950-94%
Total Notices Printed	5-71%	109-89%	63-95%	34-92%	80-96%	65-97%	436-99%	53-70%	89-91%	16-100%	950-94%

Generated By: MHUNTER

Generated On: 5/13/2013 3:19:33 PM