



Location Performance Summary Report By Lane

Submission Criteria

From Violation Date: 9/1/2015

To Violation Date: 9/30/2015

Violation Type: ALL

Location	A	B (C+D+E)	C	D	E	F	G (A-B-F)	H (G/(G+E))	I (B/A)	J (E/A)
	Violation Events	Violation Event Rejections	Non- Violations	Non- Controllable Rejections	Controllable Rejections	Violation Events Still In Workflow	Citations Issued	Issuance Rate	Rejection Percentage	Controllable Rejection Percentage
MI01 N/B ROLLINS RD @ MILLBRAE AVE										
Lane 3	56	55	55	0	0	0	1	100.00%	98.21%	0.00%
Lane 4	541	323	290	21	12	0	218	94.78%	59.70%	2.22%
	597	378	345	21	12	0	219	94.81%	63.32%	2.01%
MI03 E/B MILLBRAE AVE @ ROLLINS RD										
Lane 2	17	12	7	5	0	0	5	100.00%	70.59%	0.00%
Lane 3	50	20	7	8	5	0	30	85.71%	40.00%	10.00%
Lane 4	56	20	16	2	2	1	35	94.59%	35.71%	3.57%
Lane 5	255	133	119	8	6	0	122	95.31%	52.16%	2.35%
	378	185	149	23	13	1	192	93.66%	48.94%	3.44%
MI04 W/B MILLBRAE AVE @ ROLLINS RD										
Lane 3	7	6	1	4	1	0	1	50.00%	85.71%	14.29%
Lane 4	14	4	0	3	1	0	10	90.91%	28.57%	7.14%
Lane 5	17	4	0	3	1	0	13	92.86%	23.53%	5.88%
Lane 6	742	529	491	21	17	0	213	92.61%	71.29%	2.29%
	780	543	492	31	20	0	237	92.22%	69.62%	2.56%
MI06 S/B EL CAMINO REAL @ MILLBRAE AVE EB										
Lane 1	72	15	4	11	0	0	57	100.00%	20.83%	0.00%
Lane 2	190	43	26	15	2	0	147	98.66%	22.63%	1.05%
	262	58	30	26	2	0	204	99.03%	22.14%	0.76%
MI07 S/B HWY 101 EXIT @ MILLBRAE AVE WB										
Lane 2	157	50	17	22	11	0	107	90.68%	31.85%	7.01%
Lane 3	475	101	54	39	8	0	374	97.91%	21.26%	1.68%
	632	151	71	61	19	0	481	96.20%	23.89%	3.01%
Totals:	2,649	1,315	1,087	162	66	1	1,333	95.28%	49.64%	2.49%



Location Performance Summary Report By Lane

Submission Criteria

From Violation Date: 9/1/2015

To Violation Date: 9/30/2015

Violation Type: ALL

Locations With No Events

MI05 W/B MILLBRAE @ ROLLINS LEFT TURN
MI02 S/B ROLLINS RD @ MILLBRAE AVE