CITY OF OAKLAND



POLICE ADMINISTRATION BUILDING · 455 - 7TH STREET · OAKLAND, CALIFORNIA 94607-3985

Police Department

, ż,

Telephone Device for the Deaf (510) 777-3333 Patrol Desk (510) 238-3455 Fax (510) 238-2251

Januaray 6, 2009

State of California, Department of Transportation Bahman Zarechian, P.E. Caltrans District 4 Division of Operations Mail station: 5 111 Grand Ave. PO Box 23660 Oakland, CA 94623-0660

Re: 27th St. & Northgate Ave - Encroachment Permit - Justification

Sirs:

The City of Oakland is requesting an encroachment permit to allow the installation of a red light camera system at the listed intersection to enforce red light violations as authorized. The enforcement of red light violations using camera systems is authorized by section 21455.5 of the California Vehicle Code. The intersection of 27th Street at Northgate Avenue, adjacent to the freeway 980 on ramp, warrants the installation of a photo enforcement system for several reasons outlined below.

According to the United States Department of Transportation (USDOT), each year red light violations cause as many as 200,000 crashes and 1000 fatalities. In the year 2007, the City of Oakland investigated 228 intersection collisions, resulting in injury, directly attributable to red light violations. Three collisions involving a red light violation resulted in a death. These violations directly affect the quality of life in our community and create a serious danger to the motoring public and law enforcement officers. Red light running is a serious issue impacting the safety of our citizens.

While the Oakland Police Department diligently endeavors to make the streets safe, a red light camera program would provide 24 hour, seven days a week enforcement where violations and crashes most frequently occur. Collisions involving red light running

are most likely to result in injuries and significant property damage. It is often more dangerous for a police officer to apprehend and cite a red light runner because the officer must also run the red light.

The Police Department believes the intersection warrants the installation of a red light camera enforcement system for the following reasons:

In 2007 there were 6 collisions in the intersection. Five resulted in injury to one of the involved parties. There were 6 collisions in or near the intersection that did not involve a red light violation. However, in 3 of the non red light incidents, one party fled the scene in violation of 20002VC, committing a red light violation as they fled.

In 2008 there were 7 collisions in the intersection. Five resulted in injury to one of the involved parties. There were 9 collisions in or near the intersection that did not involve a red light violation. However, in 3 of the non red light incidents, one party fled the scene in violation of 20002VC, committing a red light violation as they fled.

Redflex conducted video surveys of the intersection and recorded red light violations. The video surveys revealed a significant number of red light violations with the majority being committed by drivers traveling northbound on Northgate Ave. and westbound on 27^{th} St. During an eight-hour video survey in a single day, there were 70 red light violations recorded in the southbound direction, and 20 red light violations recorded in the northbound direction.

The intersection was evaluated by traffic engineering who verified that the yellow phase was in compliance with Caltrans specifications.

Westlake Middle School and Foster Middle School are located within a half mile of this intersection. Many children cross 27th St. to get to school.

Based on this information, The Oakland Police Department Traffic Section decided to include this intersection in the City's red light photo enforcement program.

In summary, this intersection warrants the installation of a red light camera enforcement system for the following reasons:

- There have been a significant number of reported collisions at the intersection over the last 2 years.
- The video survey revealed that the intersection experiences a significant number of red light violations.
- 27th St. is a major arterial roadway to access downtown Oakland.
- This well traveled roadway also traverses a residential and light commercial area with Two Middle Schools within a half mile of the intersection.

A review of collision records demonstrated a high number of injury accidents at this intersection.

Sincerely,

Lieutenant Anthony Banks, Sr.
Oakland Police Department
2651 73rd Ave
Oakland, Ca. 94605
510-777-8637

Color Legend - Highest Degree of Injury

Medium Blue = Fatal

Purple = Severe Injury


Green = Other Visible Injury

Teal = Complaint of Pain

Dark Blue = Property Damage Only

Settings Used For Query

<u>Parameter</u>	Setting
Street Name	27th Street
Cross Street	Northgate Avenue
Starting Date	10/1/2002
Ending Date	9/30/2007
Intersection	Intersection Related



CITY OF OAKLAND



POLICE ADMINISTRATION BUILDING • 455 - 7TH STREET • OAKLAND, CALIFORNIA 94607-3985

Police Department ·

Telephone Device for the Deaf (510) 777-3333 Patrol Desk (510) 238-3455 Fax (510) 238-2251

February 24, 2009

State of California, Department of Transportation Bahman Zarechian, P.E. Caltrans District 4 Division of Operations Mail station: 5 111 Grand Ave. PO Box 23660 Oakland, CA 94623-0660

Re: MacArthur BI & Beaumont Ave - Encroachment Permit - Justification

Sirs:

The City of Oakland is requesting an encroachment permit to allow the installation of a red light camera system at the listed intersection to enforce red light violations as authorized. The enforcement of red light violations using camera systems is authorized by section 21455.5 of the California Vehicle Code. The intersection of MacArthur BI at Beaumont Avenue, adjacent to the freeway 580 on ramp, warrants the installation of a photo enforcement system for several reasons outlined below.

According to the United States Department of Transportation (USDOT), each year red light violations cause as many as 200,000 crashes and 1000 fatalities. In the year 2007, the City of Oakland investigated 228 intersection collisions, resulting in injury, directly attributable to red light violations. Three collisions involving a red light violation resulted in a death. These violations directly affect the quality of life in our community and create a serious danger to the motoring public and law enforcement officers. Red light running is a serious issue impacting the safety of our citizens.

While the Oakland Police Department diligently endeavors to make the streets safe, a red light camera program would provide 24 hour, seven days a week enforcement where violations and crashes most frequently occur. Collisions involving red light running

are most likely to result in injuries and significant property damage. It is often more dangerous for a police officer to apprehend and cite a red light runner because the officer must also run the red light. This program also allows officers to focus on more serious crimes, by performing red light enforcement duties that traditionally have fallen upon the officer.

The Police Department believes the intersection warrants the installation of a red light camera enforcement system for the following reasons:

In 2008 there were 15 collisions in the intersection. Two resulted in an injury to at least one of the involved parties.

From 10-1-2002 to 9-30-07, there were 69 property damage collisions and 13 injury collisions in this intersection.

Redflex conducted video surveys of the intersection and recorded red light violations. The video surveys revealed a significant number of red light violations with the majority being committed by drivers traveling northbound on Beaumont Ave and westbound on MacArthur Bl. During a twelve-hour video survey in a single day, there were 38 red light violations recorded in the northbound direction, and 5 red light violations recorded in the westbound direction.

The intersection was evaluated by traffic engineering who verified that the yellow phase was in compliance with Caltrans specifications.

Edna Brewer Middle School and the Alameda County Hospital (Highland) are located within a quarter mile of this intersection. Many children cross MacArthur Bl. to get to school.

Based on this information, The Oakland Police Department Traffic Section decided to include this intersection in the City's red light photo enforcement program.

In summary, this intersection warrants the installation of a red light camera enforcement system for the following reasons:

- There have been a significant number of reported collisions at the intersection over the last 8 years.
- The video survey revealed that the intersection experiences a significant number of red light violations.
- 14th St. is a major arterial roadway to access central Oakland.
- This well traveled roadway also traverses a residential and light commercial area with one Middle School, and a major hospital within a quarter mile of the intersection.

 A review of collision records demonstrated a high number of accidents at this intersection.

Sincerely,

Lieutenant Anthony Banks, Sr. Oakland Police Department 2651 73rd Ave Oakland, Ca. 94605 510-777-8637

Collision Diagram From: 10/1/2002 To: 9/30/2007 Horizontal Street: BEAUMONT AVENUE Vertical Street: MACARTHUR BOULEVARD (W) Date Prepared: 2/3/2009 2/27/03 Improp Turn 6/22/05 Improp To 1/15/06 Improp Turn 10/25/02 12/1/03 Unsf Spd 9/17/05 Improp Turn 2/17/06 Improp Turn 11/2/04 Othr Haz Mymt 2/1/03 Improp Turn 6/28/05 Sigs/Sig 1/18/03 Sign/Si 9/19/04 Sigs/Sig 7/14/03 Unknow 6/19/03 Unsf Spd 5/25/03 Unknown 7/3/04 Unsf Spd 7/10/03 Unknow 12/19/06 Sigs/Sigr 5/26/06 Improp Turn 1/18/07 Unsf Spd 1/23/04 Unknown 5/21/04 Unsf Sp **Number of Collisions** Legend Pedestrian Right Turn Moving Vehicle **Fixed Object Left Turn** <u>46</u> **Property Damage Only** Stopped Vehicle 99 **Injury Collisions** Bicycle 8 **Backing Vehicle** Sideswipe DUI 0 **Fatal Collisions** 7 Ran Off Road Day **Total Collisions** 0 Injury Movement Night Fatai Unknown **Collisions Not Plotted: 18**

Color Legend - Highest Degree of Injury

Medium Blue = Fatal

Purple = Severe Injury

Green = Other Visible Injury

Teal = Complaint of Pain

Dark Blue = Property Damage Only

Settings Used For Query

<u>Parameter</u>	Setting
Street Name	Beaumont Avenue
Cross Street	Macarthur Boulevard (W)
Starting Date	10/1/2002
Ending Date	9/30/2007
Intersection	Intersection Related

CITY OF OAKLAND



POLICE ADMINISTRATION BUILDING • 455 - 7TH STREET • OAKLAND, CALIFORNIA 94607-3985

Police Department

Telephone Device for the Deaf (510) 777-3333 Patrol Desk (510) 238-3455 Fax (510) 238-2251

March 9, 2009

State of California, Department of Transportation Bahman Zarechian, P.E. Caltrans District 4 Division of Operations Mail station: 5 111 Grand Ave. PO Box 23660 Oakland, CA 94623-0660

Re: 35th St & Market St - Encroachment Permit - Justification

Sirs;

The City of Oakland is requesting an encroachment permit to allow the installation of a red light camera system at the listed intersection to enforce red light violations as authorized. The enforcement of red light violations using camera systems is authorized by section 21455.5 of the California Vehicle Code. The intersection of 35th St at Market St, adjacent to the freeway 24 on ramp, warrants the installation of a photo enforcement system for several reasons outlined below.

According to the United States Department of Transportation (USDOT), each year red light violations cause as many as 200,000 crashes and 1000 fatalities. In the year 2007, the City of Oakland investigated 228 intersection collisions, resulting in injury, directly attributable to red light violations. Three collisions involving a red light violation resulted in a death. These violations directly affect the quality of life in our community and create a serious danger to the motoring public and law enforcement officers. Red light running is a serious issue impacting the safety of our citizens.

While the Oakland Police Department diligently endeavors to make the streets safe, a red light camera program would provide 24 hour, seven days a week enforcement where violations and crashes most frequently occur. Collisions involving red light running

are most likely to result in injuries and significant property damage. It is often more dangerous for a police officer to apprehend and cite a red light runner because the officer must also run the red light. This program also allows officers to focus on more serious crimes, by performing red light enforcement duties that traditionally have fallen upon the officer.

The Police Department believes the intersection warrants the installation of a red light camera enforcement system for the following reasons:

In 2008 there were 7 collisions in the intersection. Three resulted in an injury to at least one of the involved parties. Two were hit & run collisions.

From 10-1-2002 to 9-30-07, there were 25 property damage collisions and 10 injury collisions in this intersection.

Redflex conducted video surveys of the intersection and recorded red light violations. The video surveys revealed a significant number of red light violations with the majority being committed by drivers traveling eastbound on 35th St. During a twelve-hour video survey in a single day, there were 94 red light violations recorded in the eastbound direction,.

The intersection was evaluated by traffic engineering who verified that the yellow phase was in compliance with Caltrans specifications.

Hoover Elementary School and the Oakland School for the Arts (6-12) are located within a quarter mile of this intersection. Many children cross 35th St. to get to school. This intersection is also a major thoroughfare to west Oakland

Based on this information, The Oakland Police Department Traffic Section decided to include this intersection in the City's red light photo enforcement program.

In summary, this intersection warrants the installation of a red light camera enforcement system for the following reasons:

- There have been a significant number of reported collisions at the intersection over the last 8 years.
- The video survey revealed that the intersection experiences a significant number of red light violations.
- 35thSt. is a major arterial roadway to access west Oakland and many commuters use this roadway as a bypass of Freeway 580 to access Highway 24
- This well traveled roadway also traverses a residential area with one Middle School, and one elementary school within a quarter mile of the intersection.
- A review of collision records demonstrated a high number of accidents at this intersection.


Sincerely,

Lieutenant Anthony Banks, Sr.
Oakland Police Department
2651 73rd Ave
Oakland, Ca. 94605
510-777-8637

Collision Diagram

<u>Vertical Street: 35TH STREET</u> From: <u>10/1/2002</u> To: <u>9/30/2007</u>

Horizontal Street: MARKET STREET (W) Date Prepared: 3/20/2009



Color Legend - Highest Degree of Injury

Medium Blue = Fatal

Purple = Severe Injury

Green = Other Visible Injury

Teal = Complaint of Pain

Dark Blue = Property Damage Only

Settings Used For Query

<u>Parameter</u>	Setting
Street Name	35th Street
Cross Street	Market Street (W)
Starting Date	10/1/2002
Ending Date	9/30/2007
Intersection	Intersection Related