

Customer Management Report (Oxnard) All Detection Types

01-Jun-2016 to 30-Jun-2016 Operator Id: %

Total Processed Incidents		OX-FIVE-01(I)	OX-FIVE-03(I)	OX-GOSN-01(P)	OX-GOVE-01(P)	OX-RO1-01(P)	OX-ROGO-01(I)	OX-ROGO-03(I)	OX-SACH-01(I)	OX-SACH-03(I)	OX-VICH-01(P)	OX-VWO-01(P)	TOTAL
Less Uncontrollable Factors	42	149	97	24	145	17	93	113	157	13	33	883	
Obstruction	1	1	4	0	3	0	1	2	22	1	1	36	
Driver Obstruction/Duckers	0	1	0	0	0	0	1	0	0	0	1	3	
Plate Obstruction	0	3	2	0	0	1	0	3	1	0	0	10	
Vehicle Obstruction	6	6	3	0	9	1	6	3	15	0	0	49	
Police	4	0	6	3	6	2	1	1	5	1	3	32	
Driver Obstruction (PD)	0	0	1	1	1	0	0	0	0	0	0	3	
Emergency Vehicle Responding	0	9	0	0	0	0	0	6	12	0	0	27	
Incorrect/Incomplete DMV	2	5	6	5	17	3	11	16	17	0	1	83	
On or Passed the Stop Bar (PD), Police Discretion	6	0	0	2	0	0	0	0	1	0	0	9	
Sun Glare	0	0	0	0	0	1	3	0	3	1	0	8	
Policy/Weath	7	60	23	0	7	2	12	2	20	5	6	144	
Extended Vehicle	2	5	1	1	0	0	0	0	0	1	4	14	
Sun Glare	2	6	6	1	5	1	3	5	6	2	0	37	
Weather/Nature	30	96	52	13	48	11	38	38	102	11	16	455	
Registration Issues	12	53	45	11	97	6	55	75	55	2	17	428	
Paper Plates	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution	12	53	45	11	97	6	55	75	55	2	17	428	
Less Total Violations	12	53	45	11	97	6	55	75	55	2	17	428	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution	12	53	45	11	97	6	55	75	55	2	17	428	
Less Rejects	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Camera	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Flash	0-00%	0-00%	0-00%	3-27%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Malfunction	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Test Pattern													

Generated By:
Generated On: 1/3/2017 9:55:48 AM

Customer Management Report (Oxnard) All Detection Types

01-Jun-2016 to 30-Jun-2016 Operator Id: %

	OX-FIVE-01(I)	OX-FIVE-03(I)	OX-GOSN-01(P)	OX-GOVE-01(P)	OX-RO1-01(P)	OX-ROGO-01(I)	OX-ROGO-03(I)	OX-SACH-01(I)	OX-SACH-03(I)	OX-VICH-01(P)	OX-VWO-01(P)	TOTAL
Police	0-00%	16-30%	1-02%	1-09%	0-00%	0-00%	2-04%	0-00%	1-02%	0-00%	4-24%	25-06%
Rejects	1-08%	0-00%	0-00%	2-18%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Red-light not visible in	1-08%	16-30%	1-02%	6-55%	1-01%	0-00%	2-04%	0-00%	1-02%	0-00%	5-29%	33-08%
Total	11-92%	37-70%	44-98%	5-45%	96-99%	6-100%	53-96%	75-100%	54-98%	2-100%	12-71%	395-92%
Approved Violations	11-92%	37-70%	44-98%	5-45%	96-99%	6-100%	53-96%	75-100%	54-98%	2-100%	12-71%	395-92%
Total Notices Printed	11-92%	37-70%	44-98%	5-45%	96-99%	6-100%	53-96%	75-100%	54-98%	2-100%	12-71%	395-92%

Legend: (P) = Production (I) = Inoperative
 Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By:
 Generated On: 1/3/2017 9:55:48 AM

Customer Management Report (Oxnard) All Detection Types

01-Jul-2016 to 31-Jul-2016 Operator Id: %

	OX-FIVE-01(I)	OX-FIVE-03(I)	OX-GOSN-01(P)	OX-GOVE-01(P)	OX-RO1-01(P)	OX-ROGO-01(I)	OX-ROGO-03(I)	OX-SACH-01(I)	OX-SACH-03(I)	OX-VICH-01(P)	OX-VWO-01(P)	TOTAL
Total Processed Incidents	49	143	112	37	114	18	82	105	130	21	31	842
Less Uncontrollable Factors												
Obstruction	0	4	3	0	5	0	2	1	18	1	1	35
Driver Obstruction/Duckers	0	3	1	1	0	1	1	0	0	0	4	11
Plate Obstruction	0	0	0	1	0	0	0	0	0	0	0	1
Signal Obstruction	0	0	0	1	0	0	0	0	0	0	0	1
Vehicle Obstruction	5	3	1	1	1	2	2	4	0	0	0	19
Police Rejects	1	2	2	0	4	0	6	5	19	0	1	40
Driver Obstruction (PD)	8	3	2	5	4	3	2	4	3	2	0	36
Emergency Vehicle Responding	0	0	0	0	1	0	0	0	0	0	0	1
Multiple vehicles in frame	0	11	0	0	0	0	0	5	3	0	1	20
On or Passed the Stop Bar (PD),	1	5	12	2	10	2	7	16	15	1	2	73
Police Discretion	0	2	0	0	0	0	0	0	1	0	0	3
Safe Turn On Red	6	1	2	1	0	0	0	0	1	0	0	11
Sun Glare	0	0	1	1	1	1	0	1	0	2	0	7
Policy/Weath	7	67	35	10	11	1	11	3	23	9	10	187
er	1	0	0	1	0	0	0	0	0	1	0	3
Sun Glare	0	0	0	0	1	0	0	1	0	0	0	2
Weather/Nature	0	0	0	0	1	0	0	1	0	0	0	2
Registration	3	5	4	3	4	0	4	5	6	0	1	35
Issues	32	106	63	26	42	10	35	45	89	16	20	484
Paper Plates	17	37	49	11	72	8	47	60	41	5	11	358
Total	0	0	0	0	0	0	0	0	0	0	0	0
Sub Total Violations	17	37	49	11	72	8	47	60	41	5	11	358
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	17	37	49	11	72	8	47	60	41	5	11	358
Less Rejects												
Camera	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
Datarab Unreadable/Incorrect	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-20%	0-00%	1-00%
Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Focus Blurry												

Generated By:
Generated On: 1/3/2017 9:57:53 AM

Customer Management Report (Oxnard) All Detection Types

01-Jul-2016 to 31-Jul-2016 Operator Id: %

	OX-FIVE-01(I)	OX-FIVE-03(I)	OX-GOSN-01(P)	OX-GOVE-01(P)	OX-RO1-01(P)	OX-ROGO-01(I)	OX-ROGO-03(I)	OX-SACH-01(I)	OX-SACH-03(I)	OX-VICH-01(P)	OX-VWO-01(P)	TOTAL
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-20%	0-00%	1-00%
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-20%	0-00%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	1-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-09%	1-00%
Police	1-06%	5-14%	6-12%	0-00%	0-00%	2-25%	0-00%	0-00%	2-05%	2-40%	3-27%	21-06%
Reflects	3-18%	0-00%	1-02%	2-18%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-09%	7-02%
Red-light not visible in	4-24%	5-14%	8-16%	3-27%	0-00%	2-25%	2-04%	0-00%	2-05%	5-100%	5-45%	36-10%
Total	13-76%	32-86%	41-84%	8-73%	72-100%	6-75%	45-96%	60-100%	39-95%	0-00%	6-55%	322-90%
Approved Violations	13-76%	32-86%	41-84%	8-73%	72-100%	6-75%	45-96%	60-100%	39-95%	0-00%	6-55%	322-90%
Total Notices Printed	13-76%	32-86%	41-84%	8-73%	72-100%	6-75%	45-96%	60-100%	39-95%	0-00%	6-55%	322-90%

Legend: (P) = Production (I) = Inoperative
 Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By:
 Generated On: 1/3/2017 9:57:53 AM

Customer Management Report (Oxnard) All Detection Types

01-Aug-2016 to 31-Aug-2016 Operator Id: %

Category	OX-FIVE-01(I)	OX-FIVE-03(I)	OX-GOSN-01(P)	OX-GOVE-01(P)	OX-R01-01(P)	OX-R0GO-01(I)	OX-R0GO-03(I)	OX-SACH-01(I)	OX-SACH-03(I)	OX-VICH-01(P)	OX-VIWO-01(P)	TOTAL
Total Processed Incidents	55	162	95	28	127	17	84	131	145	23	26	893
Less Uncontrollable Factors												
Obstruction	2	1	7	1	5	0	3	5	20	1	0	45
Driver Obstruction/Duckers	0	0	0	0	0	0	0	1	0	0	0	1
Motor Cycle Helmet	0	4	4	1	1	0	1	0	2	0	1	14
Plate Obstruction	1	1	4	1	2	1	1	2	0	1	0	14
Vehicle Obstruction	1	11	4	0	13	1	6	3	18	1	2	60
Police Rejects	5	4	1	1	8	2	2	3	4	1	0	31
Emergency Vehicle Responding	0	0	0	0	0	0	1	0	1	0	0	2
Incorrec/Incomplete DMV	0	6	0	0	0	0	0	9	5	0	0	20
On or Passed the Stop Bar (PD)	2	7	8	0	12	1	12	19	17	0	0	78
Police Discretion	16	2	7	1	0	0	0	0	0	0	0	26
Sun Glare	0	0	0	0	4	2	3	0	0	0	0	12
Policy/Weath	12	86	27	7	7	0	7	3	20	12	12	193
Extended Vehicle	1	1	0	2	0	0	0	0	0	0	0	7
Sun Glare	0	0	0	0	0	0	0	0	0	0	0	0
Weather/Nature	0	0	0	0	1	0	0	1	0	0	0	2
Registration	1	2	1	3	3	1	4	6	2	0	1	24
Out of Country Plate	1	0	0	0	0	0	0	0	0	0	0	1
Paper Plates	0	125	63	17	56	8	40	52	89	22	16	530
Wrong or No DMV	13	37	32	11	71	9	44	79	56	1	10	363
Sub Total Violations	13	37	32	11	71	9	44	79	56	1	10	363
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	13	37	32	11	71	9	44	79	56	1	10	363
Less Rejects												
Camera	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-100%	0-00%	2-01%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	1-10%	2-01%
Face Camera Focus Blurry	0-00%	0-00%	2-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%
Video Skips	4-31%	11-30%	1-03%	3-27%	1-01%	0-00%	4-09%	0-00%	1-02%	0-00%	3-30%	28-08%
Police Rejects	0-00%	0-00%	0-00%	1-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-10%	2-01%
Driver Unidentifiable images poor	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	4-31%	12-32%	4-12%	4-35%	1-01%	1-11%	4-09%	0-00%	1-02%	1-100%	5-50%	37-10%
Too Old	9-69%	25-68%	28-88%	7-64%	70-99%	8-89%	40-91%	79-100%	55-98%	0-00%	5-50%	326-90%
Approved Violations	9-69%	25-68%	28-88%	7-64%	70-99%	8-89%	40-91%	79-100%	55-98%	0-00%	5-50%	326-90%
Total Notices Printed	9-69%	25-68%	28-88%	7-64%	70-99%	8-89%	40-91%	79-100%	55-98%	0-00%	5-50%	326-90%

Generated By:
Generated On: 1/3/2017 10:01:01 AM

Customer Management Report (Oxnard) All Detection Types

01-Aug-2016 to 31-Aug-2016

Operator Id: %

OX-FIVE-01(I)	OX-FIVE-03(I)	OX-GOSN-01(P)	OX-GOVE-01(P)	OX-R01-01(P)	OX-ROGO-01(I)	OX-ROGO-03(I)	OX-SACH-01(I)	OX-SACH-03(I)	OX-VICH-01(P)	OX-VWQ-01(P)	TOTAL
---------------	---------------	---------------	---------------	--------------	---------------	---------------	---------------	---------------	---------------	--------------	-------

Legend: (P) = Production (I) = Inoperative
 Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: .

Generated On: 1/3/2017 10:01:01 AM

© Redflex Traffic Systems, Inc.

Customer Management Report (Oxnard) All Detection Types

01-Sep-2016 to 30-Sep-2016 Operator Id: %

	OX-FIVE-01(I)	OX-FIVE-03(I)	OX-GOSN-01(P)	OX-GOVE-01(P)	OX-R01-01(P)	OX-R0GO-01(I)	OX-R0GO-03(I)	OX-SACH-01(I)	OX-SACH-03(I)	OX-VICH-01(P)	OX-VIWO-01(P)	TOTAL
Total Processed Incidents	21	173	86	41	153	18	67	136	110	11	26	842
Less Uncontrollable Factors												
Obstruction	0	5	2	0	5	0	3	4	21	0	0	40
Driver Obstruction/Duckers	0	1	3	0	1	0	2	2	1	0	0	10
Plate Obstruction	2	5	0	1	1	2	0	4	1	0	2	18
Vehicle Obstruction	0	13	8	1	18	3	7	6	18	0	3	77
Police Rejects	4	5	5	2	9	4	1	1	3	0	0	34
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	1	0	0	1
Emergency Vehicle Responding	0	0	0	0	1	0	0	0	0	0	0	1
Gender Mismatch	0	0	0	0	0	0	0	0	0	0	0	0
Incorrect/Incomplete DMV	0	16	1	0	0	0	0	5	5	0	0	27
On or Passed the Stop Bar (PD)	2	6	7	6	11	2	3	18	11	2	1	69
Police Discretion	3	4	9	4	0	0	0	0	0	0	0	20
Sun Glare	0	0	0	0	8	0	3	0	0	1	0	12
Policy/Weath	3	53	12	4	16	2	11	2	11	6	5	125
Extended Vehicle	0	0	0	1	0	0	0	0	2	0	0	3
Sun Glare	0	0	0	0	0	0	0	0	0	0	0	0
Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	0
Registration Issues	1	7	3	3	3	0	2	4	2	2	2	29
Out of Country Plate	15	115	50	22	73	13	32	48	77	11	13	467
Paper Plates	6	58	36	19	80	5	35	90	33	0	0	375
Sub Total Violations	0	0	0	0	0	0	0	0	1	0	0	1
Less In Progress	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	6	58	36	19	80	5	35	90	33	0	0	375
Less Rejects												
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	11-58%	0-00%	0-00%	2-06%	0-00%	0-00%	0-00%	0-00%	13-03%
Video Skips	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-00%
Police Rejects	0-00%	21-36%	2-06%	1-05%	7-09%	0-00%	8-23%	0-00%	2-06%	0-00%	10-77%	51-14%
Driver Unidentifiable Images poor	0-00%	0-00%	0-00%	1-05%	0-00%	1-20%	0-00%	1-01%	0-00%	0-00%	0-00%	3-01%
Red-light not visible in	0-00%	4-07%	1-03%	0-00%	6-08%	0-00%	2-06%	6-07%	2-06%	0-00%	1-08%	22-06%
Process Issues	0-00%	25-43%	3-08%	13-68%	13-16%	1-20%	13-37%	8-09%	6-18%	0-00%	11-85%	93-25%
Total	6-100%	33-57%	33-92%	6-32%	67-84%	4-80%	22-63%	82-91%	27-82%	0-00%	2-15%	282-75%
Approved Violations	6-100%	33-57%	33-92%	6-32%	67-84%	4-80%	22-63%	82-91%	27-82%	0-00%	2-15%	282-75%
Total Notices Printed	6-100%	33-57%	33-92%	6-32%	67-84%	4-80%	22-63%	82-91%	27-82%	0-00%	2-15%	282-75%

Generated By:
Generated On: 1/3/2017 10:01:44 AM

Customer Management Report (Oxnard) All Detection Types
 01-Sep-2016 to 30-Sep-2016 Operator Id: %

OX-FIVE-01(I)	OX-FIVE-03(I)	OX-GOSN-01(P)	OX-GOVE-01(P)	OX-R01-01(P)	OX-ROGO-01(I)	OX-ROGO-03(I)	OX-SACH-01(I)	OX-SACH-03(I)	OX-VICH-01(P)	OX-VIWO-01(P)	TOTAL
---------------	---------------	---------------	---------------	--------------	---------------	---------------	---------------	---------------	---------------	---------------	-------

Legend: (P) = Production (I) = Inoperative
 Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Customer Management Report (Oxnard) All Detection Types

01-Oct-2016 to 31-Oct-2016 Operator Id: %

	OX-FIVE-01(I)	OX-FIVE-03(I)	OX-GOSN-01(P)	OX-GOVE-01(P)	OX-RO1-01(P)	OX-ROGO-01(I)	OX-ROGO-03(I)	OX-SACH-01(I)	OX-SACH-03(I)	OX-VICH-01(P)	OX-VIMO-01(P)	TOTAL
Total Processed Incidents	36	152	57	22	106	14	106	139	123	10	34	799
Less Uncontrollable Factors												
Obstruction	2	5	3	1	6	0	1	2	17	0	2	39
Driver Obstruction/Duckers	0	0	0	0	0	0	0	1	0	0	0	1
Motor Cycle Helmet	0	2	1	1	4	1	0	1	0	1	0	11
Plate Obstruction	0	2	0	2	3	1	2	6	1	0	0	17
Vehicle Obstruction	0	11	3	1	8	1	10	10	23	0	2	69
Police Rejects	1	4	2	1	6	1	3	2	3	0	4	27
Driver Obstruction (PD)	0	10	2	0	0	0	0	6	6	0	0	24
Emergency Vehicle Responding	0	7	6	1	6	1	9	17	10	1	0	60
On or Passed the Stop Bar (PD)	2	9	5	0	0	0	0	0	0	0	0	20
Police Discretion	6	0	1	1	3	3	2	0	0	0	0	10
Sun Glare	0	33	10	3	9	2	27	0	12	0	12	111
Policy/Weath	3	4	2	0	0	0	2	4	1	1	3	18
er	1	0	0	0	2	0	0	1	0	0	0	4
Sun Glare	0	5	4	4	2	0	4	7	6	1	1	33
Weather/Nature	1	0	0	0	2	0	0	0	0	0	0	3
Registration	0	1	1	1	3	3	2	0	0	0	0	10
Issues	1	33	10	3	9	2	27	0	12	0	12	111
Paper Plates	0	4	2	0	0	0	2	4	1	1	3	18
Out of Country Plate	0	0	0	0	2	0	0	1	0	0	0	4
Wrong or No DMV	1	5	4	4	2	0	4	7	6	1	1	33
Total	0	0	0	0	1	2	2	0	0	0	0	4
Sub Total Violations	20	60	18	8	56	4	46	82	44	6	10	354
Less In Progress	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	20	60	18	8	56	4	46	82	44	6	10	354
Less Rejects												
Camera Malfunction	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	3-01%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
Plate Not in Frame	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
Video Skips	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	3-15%	23-38%	2-11%	2-25%	1-02%	0-00%	11-24%	1-01%	2-05%	1-17%	9-90%	55-16%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	2-25%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%
Red-light not visible in	1-05%	2-03%	0-00%	0-00%	0-00%	0-00%	2-04%	4-05%	1-02%	0-00%	0-00%	10-03%
Process Issues	5-25%	27-45%	2-11%	4-50%	1-02%	0-00%	15-33%	6-07%	5-11%	1-17%	9-90%	75-21%
Total	15-75%	33-55%	16-99%	4-50%	55-98%	4-100%	31-67%	76-93%	39-99%	5-83%	1-10%	279-79%
Approved Violations	15-75%	33-55%	16-99%	4-50%	55-98%	4-100%	31-67%	76-93%	39-99%	5-83%	1-10%	279-79%
Total Notices Printed	15-75%	33-55%	16-99%	4-50%	55-98%	4-100%	31-67%	76-93%	39-99%	5-83%	1-10%	279-79%

Generated By:
Generated On: 1/3/2017 10:02:34 AM

Customer Management Report (Oxnard) All Detection Types

01-Nov-2016 to 30-Nov-2016 Operator Id: %

Category	OX-FIVE-01(I)	OX-FIVE-03(I)	OX-GOSN-01(P)	OX-GOVE-01(P)	OX-R01-01(P)	OX-ROGO-01(I)	OX-ROGO-03(I)	OX-SACH-01(I)	OX-SACH-03(I)	OX-VICH-01(P)	OX-VWVO-01(P)	TOTAL
Total Processed Incidents	55	115	10	13	117	19	119	97	125	10	29	709

Less Uncontrollable Factors

Obstruction	1	3	2	0	8	0	3	6	16	2	0	41
Driver Obstruction/Duckers	1	0	0	1	0	0	0	2	1	0	1	6
Motor Cycle Helmet	1	0	0	1	0	1	2	2	2	1	3	13
Plate Obstruction	0	1	0	1	0	1	1	5	2	0	0	11
Vehicle Obstruction	1	4	0	0	8	1	4	4	7	0	2	31
Police Rejects	2	2	1	0	3	6	3	1	1	2	0	21
Driver Obstruction (PD)	0	0	0	0	3	0	0	0	0	0	0	3
Emergency Vehicle Responding	0	13	0	0	0	0	0	3	5	0	0	22
Incorrect/Incomplete DMV	0	5	1	0	4	0	9	7	21	1	0	55
On or Passed the Stop Bar (PD)	7	0	0	0	0	0	0	1	0	0	0	1
Police Discretion	0	0	0	0	0	0	0	1	0	0	0	1
Safe Turn On Red	3	2	0	0	0	0	0	0	0	0	0	5
Sun Glare	0	0	0	0	11	2	3	0	1	1	0	18
Policy/Weath	1	18	4	1	8	0	27	2	9	1	11	82
Extended Vehicle	0	4	0	0	0	0	2	0	0	0	0	8
Sun Glare	0	4	0	0	0	0	2	0	0	0	0	8
Weather/Nature	4	4	0	3	2	2	4	0	1	0	3	23
Registration	0	0	0	0	0	0	0	1	0	0	0	1
Paper Plates	0	0	0	0	0	0	0	1	0	0	0	1
Wrong or No DMV	21	56	8	7	47	13	58	34	66	8	23	341
Total	34	59	2	6	70	6	61	63	59	2	6	368
Sub Total Violations	0	0	0	0	0	0	0	0	0	0	0	0
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	34	59	2	6	70	6	61	63	59	2	6	368

Less Rejects

Camera	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-17%	2-01%
Face Camera Focus Blurry	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	2-01%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-17%	1-00%
Rear Plate Flash Inappropriate	1-03%	13-22%	1-50%	0-00%	2-03%	0-00%	12-20%	1-02%	0-00%	0-00%	3-50%	33-09%
Police Rejects	0-00%	0-00%	0-00%	0-00%	0-00%	1-17%	0-00%	0-00%	1-02%	0-00%	0-00%	2-01%
Driver Unidentifiable images poor	2-05%	3-05%	0-00%	0-00%	4-06%	0-00%	4-07%	6-10%	4-07%	0-00%	0-00%	23-06%
Red-light not visible in	4-12%	17-29%	1-50%	0-00%	6-09%	1-17%	16-26%	8-13%	5-08%	0-00%	5-83%	53-17%
Too Old	30-88%	42-71%	1-50%	6-100%	64-91%	5-83%	45-74%	55-87%	54-92%	2-100%	1-17%	305-83%
Process Issues	30-88%	42-71%	1-50%	6-100%	64-91%	5-83%	45-74%	55-87%	54-92%	2-100%	1-17%	305-83%
Total	4-12%	17-29%	1-50%	0-00%	6-09%	1-17%	16-26%	8-13%	5-08%	0-00%	5-83%	53-17%
Approved Violations	30-88%	42-71%	1-50%	6-100%	64-91%	5-83%	45-74%	55-87%	54-92%	2-100%	1-17%	305-83%
Total Notices Printed	30-88%	42-71%	1-50%	6-100%	64-91%	5-83%	45-74%	55-87%	54-92%	2-100%	1-17%	305-83%

Generated By:
Generated On: 1/3/2017 10:03:21 AM

Customer Management Report (Oxnard) All Detection Types
 01-Nov-2016 to 30-Nov-2016 Operator Id: %

OX-FIVE-01(I)	OX-FIVE-03(I)	OX-GOSN-01(P)	OX-GOVE-01(P)	OX-R01-01(P)	OX-ROGO-01(I)	OX-ROGO-03(I)	OX-SACH-01(I)	OX-SACH-03(I)	OX-VICH-01(P)	OX-VIMO-01(P)	TOTAL
---------------	---------------	---------------	---------------	--------------	---------------	---------------	---------------	---------------	---------------	---------------	-------

Legend: (P) = Production (I) = Inoperative
 Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Customer Management Report (Oxnard) All Detection Types

01-Dec-2016 to 31-Dec-2016 Operator Id: %

Category	OX-FIVE-01(I)	OX-FIVE-03(I)	OX-GOSN-01(P)	OX-GOVE-01(P)	OX-R01-01(P)	OX-ROGO-01(I)	OX-ROGO-03(I)	OX-SACH-01(I)	OX-SACH-03(I)	OX-VICH-01(P)	OX-VIMO-01(P)	TOTAL
Total Processed Incidents	14	48	48	19	103	6	46	62	51	18	24	439
Less Uncontrollable Factors												
Obstruction	0	1	3	0	4	0	2	1	5	0	0	16
Driver Obstruction/Duckers	0	0	0	1	0	0	0	0	0	0	0	1
Motor Cycle Helmet	1	0	3	0	3	0	1	1	0	1	1	11
Plate Obstruction	1	1	1	0	1	0	0	0	0	2	0	6
Vehicle Obstruction	0	2	3	1	4	1	3	2	4	1	0	21
Police Rejects	1	1	1	1	3	0	1	0	1	1	1	11
Emergency Vehicle Responding	0	0	0	0	0	0	1	0	0	0	0	1
Incorrect/Incomplete DMV	0	3	0	0	0	1	0	1	3	0	0	8
On or Passed the Stop Bar (PD)	1	21	3	1	3	0	12	24	24	1	0	90
Police Discretion	1	0	4	0	0	0	0	0	0	0	0	5
Sun Glare	1	0	0	0	5	0	3	0	0	0	0	9
Policy/Weath	0	2	10	0	4	0	8	0	2	0	7	33
Extended Vehicle	0	0	1	0	0	0	0	0	0	0	0	4
Sun Glare	0	0	0	0	0	0	0	0	0	0	0	0
Weather/Nature	0	0	0	1	0	0	0	0	0	0	0	1
Registration Issues	1	3	2	1	1	1	3	6	0	2	1	20
Out of Country Plate	7	34	31	6	28	2	34	35	39	8	13	237
Paper Plates	7	14	17	13	75	4	12	27	12	10	11	202
Sub Total Violations	7	14	17	13	75	4	12	27	12	10	11	202
Less In Progress	0	0	0	4	10	0	0	0	0	4	0	18
Available For Prosecution	7	14	17	9	65	4	12	27	12	6	11	184
Less Rejects												
Camera Malfunction	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-09%	2-01%
Face Camera Flash	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%
Face Camera Focus Blurry	0-00%	0-00%	1-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%
Police Rejects	3-43%	2-14%	1-06%	0-00%	0-00%	0-00%	2-17%	1-04%	0-00%	0-00%	5-45%	14-08%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	1-01%
Red-light not visible in	3-43%	2-14%	4-24%	0-00%	1-02%	0-00%	2-17%	1-04%	1-08%	0-00%	6-55%	20-11%
Total	4-57%	12-86%	13-76%	9-100%	64-98%	4-100%	10-83%	26-96%	11-92%	6-100%	5-45%	184-89%
Approved Violations	4-57%	12-86%	13-76%	9-100%	64-98%	4-100%	10-83%	26-96%	11-92%	6-100%	5-45%	184-89%
Total Notices Printed	4-57%	12-86%	13-76%	9-100%	64-98%	4-100%	10-83%	26-96%	11-92%	6-100%	5-45%	184-89%

Legend: (P) = Production (I) = Inoperative
 Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By
 Generated On: 1/3/2017 10:04:11 AM