

Customer Management Report (Oakland) All Detection Types

01-May-2013 to 31-May-2013

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL	
Total Processed Incidents	128	1623	234	249	301	66	109	252	217	174	70	66	195	3684	
Less Uncontrollable Factors															
Obstruction	Driver Obstruction/Duckers	3	22	36	11	5	1	4	34	3	11	12	2	20	164
	Motor Cycle Helmet	0	6	0	6	0	0	0	1	0	1	0	1	0	15
	Plate Obstruction	2	15	1	6	3	2	4	7	2	8	4	0	3	57
	Vehicle Obstruction	2	1	0	0	4	0	1	0	1	0	0	0	3	12
Police Rejects	Emergency Vehicle Responding	4	30	3	1	7	25	7	4	20	7	2	0	4	114
	Invalid Offense	0	290	3	21	20	0	5	0	16	16	1	0	14	386
	Plate Unidentifiable	0	0	0	1	0	0	1	2	0	0	0	0	0	4
	Police Discretion	1	12	1	1	7	0	0	0	3	2	1	0	6	34
	Safe Turn On Red	0	41	1	4	3	0	2	0	2	2	1	0	2	58
Policy/Weather	Extended Vehicle	0	3	0	1	0	1	0	1	0	0	0	0	6	13
	Sun Glare	6	223	67	46	59	12	4	49	3	14	12	17	14	526
Registration Issues	Can Not Identify State	0	0	0	0	0	0	0	0	1	0	0	0	0	1
	Out of Country Plate	1	1	0	0	1	0	0	0	0	0	0	0	1	4
	Paper Plates	5	72	7	5	11	3	15	13	21	6	3	4	18	183
	Wrong or No DMV	0	2	1	0	0	1	0	2	1	0	0	0	0	7
Total		24	718	120	103	120	45	43	113	74	67	36	24	91	1578
Sub Total Violations		104	905	114	146	181	21	66	139	143	107	34	42	104	2106
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		104	905	114	146	181	21	66	139	143	107	34	42	104	2106
Less Rejects															
Camera Malfunction	Face Camera Flash	1-01%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-04%	6-00%
	Face Camera Focus Blurry	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%

Generated By: PCIROLIA

Generated On: 2/27/2014 3:58:04 PM

Customer Management Report (Oakland) All Detection Types

01-May-2013 to 31-May-2013

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	0-00%	0-00%	2-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-09%	0-00%	0-00%	3-00%
Police Rejects														
Process Issues														
Driver Unidentifiable images poor	0-00%	1-00%	0-00%	2-01%	0-00%	0-00%	2-03%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	7-00%
Too Old	0-00%	4-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	5-00%
Total	2-02%	6-01%	0-00%	2-01%	0-00%	0-00%	2-03%	2-01%	0-00%	2-02%	6-18%	0-00%	4-04%	26-01%
Approved Violations	102-98%	899-99%	114-100%	144-99%	181-100%	21-100%	64-97%	137-99%	143-100%	105-98%	28-82%	42-100%	100-96%	2080-99%
Total Notices Printed	102-98%	899-99%	114-100%	144-99%	181-100%	21-100%	64-97%	137-99%	143-100%	105-98%	28-82%	42-100%	100-96%	2080-99%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: PCIROLIA

Generated On: 2/27/2014 3:58:04 PM

Customer Management Report (Oakland) All Detection Types

01-Jun-2013 to 30-Jun-2013

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Total Processed Incidents	130	1783	187	207	349	57	116	262	211	147	72	44	256	3821
Less Uncontrollable Factors														
Obstruction	3	12	35	3	3	2	2	26	2	8	4	0	15	115
Driver Obstruction/Duckers	3	12	35	3	3	2	2	26	2	8	4	0	15	115
Motor Cycle Helmet	0	4	0	1	0	0	0	0	1	0	0	0	0	6
Plate Obstruction	2	18	0	4	2	1	1	7	5	3	0	3	6	52
Vehicle Obstruction	3	1	5	0	7	0	3	0	2	2	0	0	2	25
Police Rejects	5	29	2	2	7	15	8	5	17	2	0	0	7	99
Emergency Vehicle Responding	5	29	2	2	7	15	8	5	17	2	0	0	7	99
Face Obstruction	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Funeral Procession/Police	0	0	0	0	0	0	0	0	0	0	0	0	4	4
Invalid Offense	0	387	3	23	33	0	9	0	21	2	8	1	12	499
Plate Unidentifiable	0	4	0	2	2	0	0	0	1	1	0	0	0	10
Police Discretion	2	11	0	2	5	0	2	3	5	1	0	0	1	32
Safe Turn On Red	0	47	1	7	5	1	1	0	1	2	1	0	0	66
Sun Glare	0	3	0	0	0	0	0	0	0	0	0	0	0	3
Yielding to an Emergency	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Policy/Weather	0	5	0	0	0	1	0	2	0	0	1	0	7	16
Extended Vehicle	0	5	0	0	0	1	0	2	0	0	1	0	7	16
Sun Glare	2	237	42	28	46	6	8	50	4	12	13	4	15	467
Registration Issues	8	71	4	4	15	5	9	17	11	4	2	5	11	166
Paper Plates	8	71	4	4	15	5	9	17	11	4	2	5	11	166
Wrong or No DMV	0	0	0	0	1	0	1	0	0	0	0	0	1	3
Total	25	831	92	76	126	31	44	110	70	37	29	13	81	1565
Sub Total Violations	105	952	95	131	223	26	72	152	141	110	43	31	175	2256
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	105	952	95	131	223	26	72	152	141	110	43	31	175	2256

Less Rejects

Camera Malfunction	Face Camera Flash	1-01%	1-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-04%	10-00%
--------------------	-------------------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	--------

Generated By: PCIROLIA

Generated On: 2/27/2014 3:59:23 PM

Customer Management Report (Oakland) All Detection Types

01-Jun-2013 to 30-Jun-2013

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Manufacturing														
Face Camera Focus Blurry	0-00%	8-01%	0-00%	4-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	12-01%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	2-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	2-01%	0-00%	6-05%	0-00%	0-00%	0-00%	9-00%
Misc Camera Issue	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	5-03%	0-00%	0-00%	0-00%	3-10%	0-00%	9-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Plate Not in Frame	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-02%	0-00%	1-01%	4-00%
Rear Plate Camera Blurry	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-02%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	5-03%	6-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-03%	8-19%	0-00%	0-00%	11-00%
Police Rejects														
Driver Unidentifiable images poor	0-00%	2-00%	1-01%	0-00%	1-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-03%	1-01%	7-00%
No Video	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-04%	0-00%	0-00%	0-00%	0-00%	7-00%
Red-light not visible in	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	3-00%
Total	3-03%	12-01%	2-02%	6-05%	3-01%	1-04%	1-01%	11-07%	7-05%	11-10%	9-21%	4-13%	16-09%	86-04%
Approved Violations	102-97%	940-99%	93-98%	125-95%	220-99%	25-96%	71-99%	141-93%	134-95%	99-90%	34-79%	27-87%	159-91%	2170-96%
Total Notices Printed	102-97%	940-99%	93-98%	125-95%	220-99%	25-96%	71-99%	141-93%	134-95%	99-90%	34-79%	27-87%	159-91%	2170-96%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: PCIROLIA

Generated On: 2/27/2014 3:59:23 PM

Customer Management Report (Oakland) All Detection Types

01-Jul-2013 to 31-Jul-2013

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Total Processed Incidents	119	907	191	238	354	46	108	165	204	188	43	41	162	2766
Less Uncontrollable Factors														
Obstruction														
Driver Obstruction/Duckers	2	4	37	12	3	2	2	19	3	9	11	0	12	116
Motor Cycle Helmet	0	1	0	1	0	0	0	1	0	1	0	1	0	5
Plate Obstruction	3	30	0	6	3	2	7	3	4	9	0	1	2	70
Vehicle Obstruction	1	3	8	1	2	0	4	0	5	0	0	0	6	30
Police Rejects														
Emergency Vehicle Responding	5	14	1	3	14	9	5	0	16	7	0	0	6	80
Funeral Procession/Police	0	0	0	0	0	0	0	0	0	0	0	0	3	3
Invalid Offense	1	159	2	16	24	0	3	0	8	10	0	0	4	227
Plate Unidentifiable	2	1	0	0	0	0	0	0	0	0	0	0	0	3
Police Discretion	1	3	1	0	2	0	0	0	5	1	1	0	2	16
Safe Turn On Red	0	32	1	5	10	0	5	0	3	7	0	0	2	65
Sun Glare	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Policy/Weather														
Extended Vehicle	0	2	0	1	1	2	0	5	1	0	0	0	5	17
Sun Glare	4	146	57	54	61	12	11	45	3	23	11	13	24	464
Registration Issues														
Out of Country Plate	0	1	0	0	1	0	0	0	0	1	0	0	0	3
Paper Plates	4	40	8	13	18	5	7	6	7	3	2	0	7	120
Wrong or No DMV	2	1	0	0	0	0	1	0	0	0	0	0	0	4
Total	25	438	115	112	139	32	45	79	55	71	25	15	73	1224
Sub Total Violations	94	469	76	126	215	14	63	86	149	117	18	26	89	1542
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	94	469	76	126	215	14	63	86	149	117	18	26	89	1542
Less Rejects														
Camera Malfunction														
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-03%	0-00%	0-00%	1-01%	5-00%

Generated By: PCIROLIA

Generated On: 2/27/2014 4:00:08 PM

Customer Management Report (Oakland) All Detection Types

01-Jul-2013 to 31-Jul-2013

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Misc Camera Issue	0-00%	0-00%	4-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-07%	0-00%	0-00%	0-00%	0-00%	0-00%	6-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	2-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-06%	1-04%	0-00%	3-00%
Police Rejects														
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-04%	0-00%	3-00%
No Video	0-00%	1-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	0-00%	4-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-02%	0-00%	0-00%	0-00%	1-01%	4-00%
Process Issues														
Too Old	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	0-00%	3-00%
Total	0-00%	1-00%	4-05%	1-01%	3-01%	0-00%	1-02%	6-07%	5-03%	9-08%	1-06%	2-08%	2-02%	35-02%
Approved Violations	94-100%	468-100%	72-95%	125-99%	212-99%	14-100%	62-98%	80-93%	144-97%	108-92%	17-94%	24-92%	87-98%	1507-98%
Total Notices Printed	94-100%	468-100%	72-95%	125-99%	212-99%	14-100%	62-98%	80-93%	144-97%	108-92%	17-94%	24-92%	87-98%	1507-98%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: PCIROLIA

Generated On: 2/27/2014 4:00:08 PM

Customer Management Report (Oakland) All Detection Types

01-Jul-2013 to 31-Jul-2013

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Total Processed Incidents	119	907	191	238	354	46	108	165	204	188	43	41	162	2766
Less Uncontrollable Factors														
Obstruction														
Driver Obstruction/Duckers	2	4	37	12	3	2	2	19	3	9	11	0	12	116
Motor Cycle Helmet	0	1	0	1	0	0	0	1	0	1	0	1	0	5
Plate Obstruction	3	30	0	6	3	2	7	3	4	9	0	1	2	70
Vehicle Obstruction	1	3	8	1	2	0	4	0	5	0	0	0	6	30
Police Rejects														
Emergency Vehicle Responding	5	14	1	3	14	9	5	0	16	7	0	0	6	80
Funeral Procession/Police	0	0	0	0	0	0	0	0	0	0	0	0	3	3
Invalid Offense	1	159	2	16	24	0	3	0	8	10	0	0	4	227
Plate Unidentifiable	2	1	0	0	0	0	0	0	0	0	0	0	0	3
Police Discretion	1	3	1	0	2	0	0	0	5	1	1	0	2	16
Safe Turn On Red	0	32	1	5	10	0	5	0	3	7	0	0	2	65
Sun Glare	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Policy/Weather														
Extended Vehicle	0	2	0	1	1	2	0	5	1	0	0	0	5	17
Sun Glare	4	146	57	54	61	12	11	45	3	23	11	13	24	464
Registration Issues														
Out of Country Plate	0	1	0	0	1	0	0	0	0	1	0	0	0	3
Paper Plates	4	40	8	13	18	5	7	6	7	3	2	0	7	120
Wrong or No DMV	2	1	0	0	0	0	1	0	0	0	0	0	0	4
Total	25	438	115	112	139	32	45	79	55	71	25	15	73	1224
Sub Total Violations	94	469	76	126	215	14	63	86	149	117	18	26	89	1542
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	94	469	76	126	215	14	63	86	149	117	18	26	89	1542
Less Rejects														
Camera Malfunction														
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-03%	0-00%	0-00%	1-01%	5-00%

Generated By: PCIROLIA

Generated On: 2/27/2014 4:00:08 PM

Customer Management Report (Oakland) All Detection Types

01-Jul-2013 to 31-Jul-2013

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Misc Camera Issue	0-00%	0-00%	4-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-07%	0-00%	0-00%	0-00%	0-00%	0-00%	6-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	2-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	1-06%	1-04%	0-00%	3-00%
Police Rejects														
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-04%	0-00%	3-00%
No Video	0-00%	1-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	0-00%	4-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-02%	0-00%	0-00%	0-00%	1-01%	4-00%
Process Issues														
Too Old	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	0-00%	3-00%
Total	0-00%	1-00%	4-05%	1-01%	3-01%	0-00%	1-02%	6-07%	5-03%	9-08%	1-06%	2-08%	2-02%	35-02%
Approved Violations	94-100%	468-100%	72-95%	125-99%	212-99%	14-100%	62-98%	80-93%	144-97%	108-92%	17-94%	24-92%	87-98%	1507-98%
Total Notices Printed	94-100%	468-100%	72-95%	125-99%	212-99%	14-100%	62-98%	80-93%	144-97%	108-92%	17-94%	24-92%	87-98%	1507-98%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: PCIROLIA

Generated On: 2/27/2014 4:00:08 PM

Customer Management Report (Oakland) All Detection Types

01-Sep-2013 to 30-Sep-2013

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Total Processed Incidents	151	1557	282	218	364	163	113	324	173	168	79	81	278	3951
Less Uncontrollable Factors														
Obstruction	6	27	40	6	6	6	2	41	2	12	13	4	21	186
Driver Obstruction/Duckers	6	27	40	6	6	6	2	41	2	12	13	4	21	186
Motor Cycle Helmet	0	2	1	0	1	0	0	3	0	2	0	1	1	11
Plate Obstruction	1	18	2	8	2	2	8	7	1	9	2	2	2	64
Vehicle Obstruction	2	4	4	2	3	0	3	1	2	0	0	1	2	24
Police Rejects	4	38	0	0	18	10	9	9	13	7	0	0	8	116
Emergency Vehicle Responding	4	38	0	0	18	10	9	9	13	7	0	0	8	116
Face Obstruction	0	0	0	0	0	0	1	1	0	0	0	0	0	2
Gender Mismatch	0	1	0	0	0	0	0	0	1	0	0	1	0	3
Invalid Offense	1	261	2	19	29	1	2	0	15	9	8	0	17	364
On or Passed the Stop Bar (PD).	0	2	0	0	0	0	0	0	0	0	0	0	0	2
Plate Unidentifiable	1	4	0	3	0	0	1	0	0	0	0	0	0	9
Police Discretion	0	12	2	2	3	1	1	3	2	1	2	2	5	36
Safe Turn On Red	0	78	0	4	9	0	0	0	8	5	0	0	3	107
Sun Glare	0	2	1	0	0	0	0	0	0	1	0	0	0	4
Policy/Weather	1	6	0	1	1	2	3	7	0	2	0	0	10	33
Extended Vehicle	1	6	0	1	1	2	3	7	0	2	0	0	10	33
Sun Glare	5	104	55	41	56	29	11	60	2	23	20	14	40	460
Weather/Nature	0	0	0	0	0	0	0	1	0	0	0	0	0	1
Registration Issues	0	0	0	0	0	0	0	0	0	0	0	0	1	1
Out of Country Plate	0	0	0	0	0	0	0	0	0	0	0	0	1	1
Paper Plates	5	67	2	7	10	10	6	16	8	9	4	4	16	164
Wrong or No DMV	0	0	0	0	1	0	1	0	0	0	0	0	0	2
Total	26	626	109	93	139	61	48	149	54	80	49	29	126	1589
Sub Total Violations	125	931	173	125	225	102	65	175	119	88	30	52	152	2362
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	125	931	173	125	225	102	65	175	119	88	30	52	152	2362

Generated By: PCIROLIA

Generated On: 2/27/2014 4:01:38 PM

Customer Management Report (Oakland) All Detection Types

01-Sep-2013 to 30-Sep-2013

Operator Id: %

		OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Less Rejects															
Camera Malfunction	Face Camera Flash	1-01%	2-00%	2-01%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-02%	5-03%	13-01%
	Face Camera Focus Blurry	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	1-02%	2-01%	0-00%	0-00%	11-37%	0-00%	0-00%	15-01%
	Face Camera No Flash	0-00%	0-00%	15-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	15-01%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-02%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
	Misc Camera Issue	0-00%	86-09%	5-03%	0-00%	0-00%	1-01%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-01%	94-04%
	Plate Burn Out	0-00%	2-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	6-03%	0-00%	0-00%	0-00%	0-00%	9-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	4-05%	1-03%	0-00%	7-00%
	Rear Plate Camera Blurry	0-00%	3-00%	0-00%	0-00%	0-00%	2-02%	0-00%	2-01%	1-01%	0-00%	1-03%	0-00%	0-00%	9-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	15-13%	0-00%	0-00%	1-02%	0-00%	17-01%
Police Rejects	Driver Unidentifiable images poor	0-00%	2-00%	0-00%	0-00%	3-01%	0-00%	0-00%	2-01%	0-00%	0-00%	2-07%	1-02%	0-00%	10-00%
	No Images	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
Process Issues	Too Old	4-03%	1-00%	2-01%	2-02%	0-00%	0-00%	2-03%	1-01%	1-01%	2-02%	0-00%	0-00%	4-03%	19-01%
Total		5-04%	97-10%	24-14%	2-02%	5-02%	3-03%	4-06%	18-10%	19-16%	8-09%	15-50%	3-06%	11-07%	214-09%
Approved Violations		120-96%	834-90%	149-86%	123-98%	220-98%	99-97%	61-94%	157-90%	100-84%	80-91%	15-50%	49-94%	141-93%	2148-91%
Total Notices Printed		120-96%	834-90%	149-86%	123-98%	220-98%	99-97%	61-94%	157-90%	100-84%	80-91%	15-50%	49-94%	141-93%	2148-91%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: PCIROLIA

Generated On: 2/27/2014 4:01:38 PM

Customer Management Report (Oakland) All Detection Types

01-Oct-2013 to 31-Oct-2013

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL	
Total Processed Incidents	159	1655	227	238	316	116	58	322	150	184	78	67	287	3857	
Less Uncontrollable Factors															
Obstruction	Driver Obstruction/Duckers	12	24	49	11	7	9	1	39	5	13	11	1	19	201
	Motor Cycle Helmet	0	8	0	0	0	0	0	0	0	1	0	1	0	10
	Plate Obstruction	2	18	0	7	3	2	4	7	6	13	0	0	6	68
	Vehicle Obstruction	0	2	1	1	5	0	1	2	1	0	0	1	2	16
Police Rejects	Emergency Vehicle Responding	3	29	0	5	6	16	3	4	13	1	0	1	7	88
	Face Obstruction	0	0	0	0	0	0	0	1	0	0	0	0	0	1
	Funeral Procession/Police	0	0	0	0	0	0	0	0	0	1	0	0	2	3
	Invalid Offense	1	319	2	16	29	1	4	0	8	5	4	0	24	413
	Plate Unidentifiable	0	2	1	0	0	0	0	0	0	0	0	0	0	3
	Police Discretion	3	9	2	1	4	0	0	1	1	2	1	0	3	27
	Safe Turn On Red	0	125	3	5	7	0	0	0	4	2	1	0	14	161
	Sun Glare	1	0	0	0	0	0	0	0	0	0	0	3	0	4
	Yielding to an Emergency	0	0	0	0	0	0	0	0	0	1	0	0	0	1
Policy/Weather	Extended Vehicle	0	2	1	0	0	0	1	5	0	0	1	1	10	21
	Sun Glare	2	82	17	48	37	12	2	45	1	24	17	9	32	328
Registration Issues	Gender Match	0	0	0	0	1	0	0	0	0	0	0	0	0	1
	Out of Country Plate	0	0	0	0	0	0	0	0	0	0	0	0	1	1
	Paper Plates	8	66	8	12	9	9	3	12	13	4	4	2	11	161
	Wrong or No DMV	0	0	0	0	0	0	1	1	0	1	0	0	0	3
Total		32	686	84	106	108	49	20	117	52	68	39	19	131	1511
Sub Total Violations		127	969	143	132	208	67	38	205	98	116	39	48	156	2346
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		127	969	143	132	208	67	38	205	98	116	39	48	156	2346

Generated By: PCIROLIA

Generated On: 2/27/2014 4:02:09 PM

Customer Management Report (Oakland) All Detection Types

01-Oct-2013 to 31-Oct-2013

Operator Id: %

		OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Less Rejects															
Camera Malfunction	Face Camera Flash	0-00%	2-00%	1-01%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	6-04%	13-01%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	13-10%	0-00%	0-00%	0-00%	3-01%	0-00%	1-01%	2-05%	0-00%	0-00%	19-01%
	Face Not in Frame	0-00%	1-00%	0-00%	0-00%	2-01%	1-01%	8-21%	3-01%	0-00%	0-00%	0-00%	0-00%	0-00%	15-01%
	Misc Camera Issue	0-00%	7-01%	5-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-10%	0-00%	0-00%	16-01%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%	0-00%	0-00%	0-00%	0-00%	1-01%	4-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
	Rear Plate Camera Blurry	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%	1-01%	0-00%	0-00%	1-02%	0-00%	4-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-00%	
Police Rejects	Driver Unidentifiable images poor	0-00%	2-00%	1-01%	0-00%	0-00%	1-01%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-00%
	Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	3-03%	0-00%	0-00%	0-00%	1-01%	5-00%
Process Issues	Too Old	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total		0-00%	12-01%	9-06%	15-11%	2-01%	2-03%	8-21%	14-07%	4-04%	4-03%	6-15%	3-06%	8-05%	87-04%
Approved Violations		127-100%	957-99%	134-94%	117-89%	206-99%	65-97%	30-79%	191-93%	94-96%	112-97%	33-85%	45-94%	148-95%	2259-96%
Total Notices Printed		127-100%	957-99%	134-94%	117-89%	206-99%	65-97%	30-79%	191-93%	94-96%	112-97%	33-85%	45-94%	148-95%	2259-96%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: PCIROLIA

Generated On: 2/27/2014 4:02:09 PM

Customer Management Report (Oakland) All Detection Types

01-Nov-2013 to 30-Nov-2013

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Total Processed Incidents	130	1436	293	264	295	87	102	232	142	110	79	45	294	3509
Less Uncontrollable Factors														
Obstruction	7	20	47	15	5	10	2	41	5	8	8	2	18	188
Driver Obstruction/Duckers	7	20	47	15	5	10	2	41	5	8	8	2	18	188
Motor Cycle Helmet	0	0	0	0	0	1	0	1	1	1	0	0	2	6
Plate Obstruction	3	21	0	7	4	3	3	7	4	5	2	2	3	64
Vehicle Obstruction	3	1	2	1	3	0	2	1	2	1	0	0	3	19
Police Rejects	1	25	1	1	7	6	7	4	13	2	2	0	11	80
Emergency Vehicle Responding	1	25	1	1	7	6	7	4	13	2	2	0	11	80
Face Obstruction	0	0	0	0	0	0	0	1	0	0	0	0	0	1
Invalid Offense	1	336	6	31	25	1	8	1	12	4	1	0	24	450
On or Passed the Stop Bar (PD)	1	0	0	0	0	0	0	0	0	0	0	0	0	1
Plate Unidentifiable	1	4	0	1	2	0	0	1	1	0	0	1	2	13
Police Discretion	2	6	2	1	3	0	0	1	0	0	0	0	1	16
Safe Turn On Red	0	66	0	7	4	0	0	0	0	2	0	0	5	84
Yielding to an Emergency	0	0	0	0	0	0	0	0	0	0	0	0	1	1
Policy/Weather	1	2	2	0	2	0	0	0	0	0	1	0	15	23
Extended Vehicle	1	2	2	0	2	0	0	0	0	0	1	0	15	23
Sun Glare	4	52	21	27	19	16	6	21	0	17	17	3	37	240
Weather/Nature	0	0	0	1	0	0	0	0	0	0	0	0	0	1
Registration Issues	2	50	11	9	10	5	1	13	8	4	3	1	8	125
Paper Plates	2	50	11	9	10	5	1	13	8	4	3	1	8	125
Wrong or No DMV	0	0	0	0	0	0	0	0	0	0	1	0	1	2
Total	26	583	92	101	84	42	29	92	46	44	35	9	131	1314
Sub Total Violations	104	853	201	163	211	45	73	140	96	66	44	36	163	2195
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	104	853	201	163	211	45	73	140	96	66	44	36	163	2195

Less Rejects

Camera Malfunction	Face Camera Flash	0-00%	0-00%	2-01%	1-01%	1-00%	0-00%	9-12%	3-02%	0-00%	0-00%	0-00%	0-00%	2-01%	18-01%
--------------------	-------------------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	--------

Generated By: PCIROLIA

Generated On: 2/27/2014 4:03:15 PM

Customer Management Report (Oakland) All Detection Types

01-Nov-2013 to 30-Nov-2013

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Production														
Face Camera Focus Blurry	1-01%	5-01%	0-00%	5-03%	0-00%	0-00%	0-00%	5-04%	0-00%	0-00%	0-00%	2-06%	0-00%	18-01%
Face Camera No Flash	1-01%	1-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	5-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	3-02%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
Image Missing	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	24-03%	0-00%	2-01%	0-00%	0-00%	5-07%	0-00%	0-00%	15-23%	0-00%	0-00%	1-01%	47-02%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	10-07%	0-00%	0-00%	1-02%	0-00%	0-00%	11-01%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	1-01%	2-00%
Rear Plate Camera Blurry	0-00%	2-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-01%	1-01%	0-00%	3-07%	0-00%	0-00%	8-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	4-03%	0-00%	0-00%	0-00%	1-03%	0-00%	6-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Rejects														
Driver Unidentifiable images poor	0-00%	1-00%	1-00%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	5-00%
No Images	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	2-00%
Process Issues														
Too Old	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	2-00%
Total	2-02%	35-04%	3-01%	11-07%	2-01%	0-00%	17-23%	28-20%	3-03%	16-24%	5-11%	4-11%	6-04%	132-06%
Approved Violations	102-98%	818-96%	198-99%	152-93%	209-99%	45-100%	56-77%	112-80%	93-97%	50-76%	39-89%	32-89%	157-96%	2063-94%
Total Notices Printed	102-98%	818-96%	198-99%	152-93%	209-99%	45-100%	56-77%	112-80%	93-97%	50-76%	39-89%	32-89%	157-96%	2063-94%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: PCIROLIA

Generated On: 2/27/2014 4:03:15 PM

Customer Management Report (Oakland) All Detection Types

01-Dec-2013 to 31-Dec-2013

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Total Processed Incidents	123	1443	340	203	361	90	84	222	166	122	103	44	361	3662
Less Uncontrollable Factors														
Obstruction														
Driver Obstruction/Duckers	5	26	46	9	8	3	1	48	4	9	20	0	34	213
Motor Cycle Helmet	0	1	0	1	0	0	0	1	0	0	0	0	1	4
Plate Obstruction	8	32	1	3	6	3	4	6	8	5	1	1	5	83
Signal Obstruction	0	0	0	0	0	1	0	0	0	0	0	0	0	1
Vehicle Obstruction	1	3	3	0	4	1	3	2	1	0	0	0	4	22
Police Rejects														
Emergency Vehicle Responding	5	28	7	7	9	15	9	6	8	4	4	0	6	108
Face Obstruction	1	1	1	0	0	0	0	1	0	0	0	0	1	5
Invalid Offense	2	330	7	23	37	1	5	2	9	6	5	0	28	455
Plate Unidentifiable	0	0	1	0	1	1	0	1	2	0	1	0	3	10
Police Discretion	2	14	1	1	4	2	0	2	4	2	0	0	4	36
Safe Turn On Red	0	52	0	2	9	0	0	0	2	0	4	0	2	71
Sun Glare	0	0	0	0	0	0	0	0	0	0	0	1	0	1
Policy/Weather														
Extended Vehicle	0	3	1	0	1	3	0	2	0	0	1	1	15	27
Sun Glare	2	32	24	10	22	13	2	7	0	5	22	4	40	183
Weather/Nature	0	1	0	0	0	0	0	0	0	1	0	0	0	2
Registration Issues														
Out of Country Plate	0	2	0	0	0	0	0	0	0	0	0	0	0	2
Paper Plates	5	55	13	10	18	5	2	12	11	7	1	5	16	160
Wrong or No DMV	0	0	2	0	0	0	0	0	1	0	0	0	1	4
Total	31	580	107	66	119	48	26	90	50	39	59	12	160	1387
Sub Total Violations	92	863	233	137	242	42	58	132	116	83	44	32	201	2275
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	92	863	233	137	242	42	58	132	116	83	44	32	201	2275

Less Rejects

Generated By: PCIROLIA

Generated On: 2/27/2014 4:05:09 PM

Customer Management Report (Oakland) All Detection Types

01-Dec-2013 to 31-Dec-2013

Operator Id: %

		OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	3-02%	5-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	8-04%	17-01%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	11-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	11-00%
	Face Not in Frame	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	1-02%	3-02%	0-00%	2-02%	1-02%	0-00%	0-00%	8-00%
	Misc Camera Issue	0-00%	30-03%	9-04%	0-00%	3-01%	0-00%	0-00%	0-00%	0-00%	6-07%	0-00%	0-00%	1-00%	49-02%
	Plate Burn Out	0-00%	1-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	8-06%	0-00%	0-00%	0-00%	0-00%	10-00%
	Plate Not in Frame	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	2-01%	5-00%
	Rear Plate Camera Blurry	0-00%	4-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-01%	0-00%	1-01%	3-07%	0-00%	0-00%	10-00%
	Rear Plate Flash Inappropriate	0-00%	1-00%	0-00%	0-00%	1-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%	
Police Rejects	Driver Unidentifiable images poor	0-00%	2-00%	1-00%	1-01%	1-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%	7-00%
	Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-01%	0-00%	0-00%	0-00%	2-00%
Process Issues	Too Old	3-03%	46-05%	25-11%	8-06%	15-06%	3-07%	5-09%	12-09%	7-06%	4-05%	3-07%	5-16%	11-05%	147-06%
Total		3-03%	85-10%	36-15%	15-11%	36-15%	3-07%	6-10%	29-22%	7-06%	18-22%	7-16%	6-19%	23-11%	274-12%
Approved Violations		89-97%	778-90%	197-85%	122-89%	206-85%	39-93%	52-90%	103-78%	109-94%	65-78%	37-84%	26-81%	178-89%	2001-88%
Total Notices Printed		89-97%	778-90%	197-85%	122-89%	206-85%	39-93%	52-90%	103-78%	109-94%	65-78%	37-84%	26-81%	178-89%	2001-88%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: PCIROLIA

Generated On: 2/27/2014 4:05:09 PM

Customer Management Report (Oakland) All Detection Types

01-Jan-2014 to 31-Jan-2014

Operator Id: %

		OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Total Processed Incidents		98	1372	227	352	318	85	83	192	125	160	71	46	226	3355
Less Uncontrollable Factors															
Obstruction	Driver Obstruction/Duckers	4	15	43	3	4	5	1	25	4	11	19	2	14	150
	Motor Cycle Helmet	1	2	0	3	0	0	0	0	0	0	0	0	0	6
	Plate Obstruction	1	35	3	21	2	3	7	2	2	11	1	0	5	93
	Vehicle Obstruction	0	5	2	2	6	0	1	1	2	0	0	0	3	22
Police Rejects	Emergency Vehicle Responding	0	31	1	2	12	12	5	7	10	10	0	0	8	98
	Face Obstruction	1	1	2	1	0	0	0	1	0	0	0	0	3	9
	Invalid Offense	2	335	12	31	34	0	6	3	12	9	3	1	24	472
	Plate Unidentifiable	1	2	0	2	1	0	0	0	0	0	0	1	0	7
	Police Discretion	3	14	5	1	5	1	2	0	1	0	1	0	4	37
	Safe Turn On Red	0	75	3	5	16	0	0	0	6	1	2	0	5	113
Policy/Weather	Extended Vehicle	0	5	0	1	0	0	4	6	0	1	0	0	11	28
	Sun Glare	4	52	12	27	19	11	1	14	1	15	11	3	23	193
	Weather/Nature	0	1	0	0	1	0	0	0	0	0	0	0	0	2
Registration Issues	Out of Country Plate	0	3	0	0	0	0	0	0	0	0	0	0	0	3
	Paper Plates	5	52	15	14	16	5	7	10	8	8	0	3	12	155
	Wrong or No DMV	0	0	0	0	1	0	0	0	0	0	0	0	0	1
Total		22	628	98	113	117	37	34	69	46	66	37	10	112	1389
Sub Total Violations		76	744	129	239	201	48	49	123	79	94	34	36	114	1966
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		76	744	129	239	201	48	49	123	79	94	34	36	114	1966
Less Rejects															
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	2-01%	1-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	3-03%	8-00%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	3-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	4-00%

Generated By: PCIROLIA

Generated On: 2/27/2014 4:05:44 PM

Customer Management Report (Oakland) All Detection Types

01-Jan-2014 to 31-Jan-2014

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Face Not in Frame	0-00%	1-00%	2-02%	0-00%	0-00%	0-00%	1-02%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	6-00%
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate Camera Blurry	0-00%	2-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-01%	1-03%	0-00%	0-00%	5-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
Police Rejects														
Driver Unidentifiable images poor	0-00%	1-00%	0-00%	1-00%	1-00%	0-00%	0-00%	0-00%	0-00%	3-03%	0-00%	0-00%	0-00%	6-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues														
Too Old	2-03%	10-01%	1-01%	3-01%	2-01%	0-00%	0-00%	2-02%	2-03%	0-00%	1-03%	0-00%	2-02%	25-01%
Total	2-03%	14-02%	3-02%	9-04%	4-02%	1-02%	3-06%	6-05%	2-03%	7-07%	3-09%	0-00%	6-05%	60-03%
Approved Violations	74-97%	730-98%	126-98%	230-96%	197-98%	47-98%	46-94%	117-95%	77-97%	87-93%	31-91%	36-100%	108-95%	1906-97%
Total Notices Printed	74-97%	730-98%	126-98%	230-96%	197-98%	47-98%	46-94%	117-95%	77-97%	87-93%	31-91%	36-100%	108-95%	1906-97%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: PCIROLIA

Generated On: 2/27/2014 4:05:44 PM

Customer Management Report (Oakland) All Detection Types

01-Feb-2014 to 28-Feb-2014

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Total Processed Incidents	121	1038	231	268	261	71	68	167	144	135	56	57	187	2804
Less Uncontrollable Factors														
Obstruction														
Driver Obstruction/Duckers	6	15	42	11	7	5	1	26	5	13	8	1	12	152
Motor Cycle Helmet	0	3	0	1	0	0	0	1	0	1	0	0	0	6
Plate Obstruction	1	32	2	8	1	5	6	1	3	9	3	2	5	78
Vehicle Obstruction	1	0	1	0	7	0	2	3	0	1	0	0	2	17
Police Rejects														
Emergency Vehicle Responding	1	9	1	0	8	12	4	2	10	4	0	0	3	54
Invalid Offense	2	178	4	20	18	0	2	2	6	11	3	0	12	258
On or Passed the Stop Bar (PD).	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Plate Unidentifiable	0	1	0	0	1	0	0	0	0	0	0	0	1	3
Police Discretion	0	3	2	3	0	0	1	1	2	0	1	0	2	15
Safe Turn On Red	1	46	0	4	12	0	1	0	3	1	0	0	5	73
Policy/Weather														
Extended Vehicle	0	2	1	1	0	0	2	0	2	1	0	1	4	14
Sun Glare	10	115	43	44	45	17	4	31	1	26	16	19	29	400
Weather/Nature	0	1	1	4	0	0	0	3	0	1	1	1	0	12
Registration Issues														
Paper Plates	3	50	7	11	9	4	5	5	11	3	2	3	12	125
Wrong or No DMV	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Total	25	456	105	107	108	43	28	75	43	71	34	27	87	1209
Sub Total Violations	96	582	126	161	153	28	40	92	101	64	22	30	100	1595
Less in Progress	13	180	27	34	41	7	10	19	22	7	3	7	27	397
Available For Prosecution	83	402	99	127	112	21	30	73	79	57	19	23	73	1198
Less Rejects														
Camera Malfunction														
Face Camera Flash	1-01%	1-00%	2-02%	10-08%	0-00%	0-00%	0-00%	4-05%	0-00%	1-02%	1-05%	2-09%	4-05%	26-02%
Face Camera Focus Blurry	1-01%	4-01%	0-00%	3-02%	0-00%	1-05%	0-00%	1-01%	0-00%	2-04%	2-11%	3-13%	1-01%	18-02%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-00%

Generated By: PCIROLIA

Generated On: 2/27/2014 4:06:36 PM

Customer Management Report (Oakland) All Detection Types

01-Feb-2014 to 28-Feb-2014

Operator Id: %

	OKL-07JA-01	OKL-27NO-01	OKL-35MA-01	OKL-36MA-01	OKL-66SL-01	OKL-BEMA-01	OKL-FOHI-01	OKL-HIBR-01	OKL-MC82-01	OKL-MCOA-01	OKL-NOZ7-01	OKL-REMO-01	OKL-SL66-01	TOTAL
Face Not in Frame	0-00%	3-01%	0-00%	0-00%	0-00%	0-00%	1-03%	3-04%	0-00%	0-00%	0-00%	0-00%	1-01%	8-01%
Image Missing	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Misc Camera Issue	1-01%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-07%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	2-00%
Rear Plate Camera Blurry	0-00%	2-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-01%	0-00%	1-02%	0-00%	0-00%	0-00%	5-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	6-08%	0-00%	1-02%	0-00%	0-00%	0-00%	8-01%
Police Rejects														
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
No Video	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues														
Too Old	0-00%	0-00%	1-01%	0-00%	1-01%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Total	3-04%	10-02%	3-03%	17-13%	3-03%	2-10%	4-13%	19-26%	1-01%	5-09%	4-21%	5-22%	7-10%	83-07%
Approved Violations	80-96%	392-98%	96-97%	110-87%	109-97%	19-90%	26-87%	54-74%	78-99%	52-91%	15-79%	18-78%	66-90%	1115-93%
Total Notices Printed	80-96%	389-97%	95-96%	110-87%	104-93%	19-90%	26-87%	52-71%	77-97%	51-89%	15-79%	18-78%	66-90%	1102-92%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: PCIROLIA

Generated On: 2/27/2014 4:06:36 PM