

Customer Management Report (Fremont) All Detection Types

01-Oct-2017 to 31-Oct-2017

Operator Id: %

	FR-AMFR-01	FR-AUGR-01	FR-BLMO-01	FR-DEFR-01	FR-DEPP-01	FR-MIMO-01	FR-MIWS-01	FR-MOFA-01	FR-MOFR-01	FR-STBL-01	TOTAL	
Total Processed Incidents	275	114	104	38	92	181	0	193	228	246	1471	
Less Uncontrollable Factors												
Police Rejects	Driver Obstruction (PD)	15	19	10	3	7	25	0	16	13	16	124
	Emergency Vehicle Responding	0	2	1	6	2	0	0	4	24	0	39
	Gender Mismatch	3	0	1	0	1	2	0	0	0	4	11
	Incorrect/Incomplete DMV	3	1	1	0	2	5	0	5	1	3	21
	Invalid Offense	1	3	1	0	0	7	0	0	4	0	16
	Multiple vehicles in frame	0	4	2	0	0	1	0	2	1	0	10
	Non-Prosecutable Violation	5	2	2	0	0	3	0	9	106	7	134
	On or Passed the Stop Bar (PD).	40	8	6	14	6	10	0	2	1	49	136
	Paper Plates	11	6	6	2	4	4	0	10	2	5	50
	Plate Obstruction (PD)	5	7	5	2	4	5	0	3	6	2	39
	Plate Unidentifiable	4	2	2	0	6	0	0	1	0	1	16
	Sun Glare	10	2	12	1	6	0	0	3	5	17	56
Total		97	56	49	28	38	62	0	55	163	104	652
Sub Total Violations		178	58	55	10	54	119	0	138	65	142	819
Less in Progress		0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		178	58	55	10	54	119	0	138	65	142	819
Less Rejects												
Police Rejects	Driver Unidentifiable images poor	51-29%	1-02%	4-07%	3-30%	8-15%	11-09%	0-00%	3-02%	24-37%	5-04%	110-13%
	Insufficient Strobe Lighting	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-01%	3-00%
	No Images	0-00%	1-02%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	3-00%
	No Video	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	2-03%	0-00%	4-00%
	Plate Unclear	3-02%	2-03%	3-05%	0-00%	2-04%	5-04%	0-00%	8-06%	8-12%	2-01%	33-04%
	Red-light not visible in	2-01%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	9-07%	2-03%	5-04%	19-02%
	Unclear Scene Image	1-01%	3-05%	0-00%	1-10%	0-00%	4-03%	0-00%	2-01%	1-02%	0-00%	12-01%
Process Issues	Too Old	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	2-00%
Total		57-32%	9-16%	7-13%	5-50%	10-19%	21-18%	0-00%	25-18%	37-57%	15-11%	186-23%
Approved Violations		121-68%	49-84%	48-87%	5-50%	44-81%	98-82%	0-00%	113-82%	28-43%	127-89%	633-77%
Total Notices Printed		121-68%	49-84%	48-87%	5-50%	44-81%	98-82%	0-00%	113-82%	28-43%	127-89%	633-77%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: CMEDINA

Generated On: 4/19/2018 11:43:44 AM

Customer Management Report (Fremont) All Detection Types

01-Nov-2017 to 30-Nov-2017

Operator Id: %

	FR-AMFR-01	FR-AUGR-01	FR-BLMO-01	FR-DEFR-01	FR-DEPP-01	FR-MIMO-01	FR-MIWS-01	FR-MOFA-01	FR-MOFR-01	FR-STBL-01	TOTAL
Total Processed Incidents	186	93	120	48	62	132	0	205	118	252	1216
Less Uncontrollable Factors											
Police Rejects	7	17	10	4	0	7	0	13	8	9	75
Driver Obstruction (PD)	7	17	10	4	0	7	0	13	8	9	75
Emergency Vehicle Responding	3	1	2	4	5	1	0	7	16	3	42
Gender Mismatch	2	0	0	0	0	1	0	0	0	1	4
Incorrect/Incomplete DMV	1	0	0	0	1	0	0	5	1	3	11
Invalid Offense	1	1	0	1	0	3	0	0	2	0	8
Multiple vehicles in frame	0	2	0	0	0	2	0	0	1	0	5
Non-Prosecutable Violation	4	5	2	1	1	11	0	6	4	4	38
On or Passed the Stop Bar (PD)	32	5	7	17	1	12	0	9	6	65	154
Paper Plates	8	3	5	2	3	8	0	9	4	18	60
Plate Obstruction (PD)	2	3	6	0	3	4	0	3	5	4	30
Plate Unidentifiable	2	5	1	1	0	3	0	0	0	1	13
Sun Glare	12	1	9	0	5	1	0	1	9	11	49
Weather Conditions	1	0	0	0	0	1	0	2	1	0	5
Total	75	43	42	30	19	54	0	55	57	119	494
Sub Total Violations	111	50	78	18	43	78	0	150	61	133	722
Less in Progress	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	111	50	78	18	43	78	0	150	61	133	722
Less Rejects											
Police Rejects	7-06%	1-02%	11-14%	2-11%	3-07%	10-13%	0-00%	2-01%	12-20%	13-10%	61-08%
Driver Unidentifiable images poor	7-06%	1-02%	11-14%	2-11%	3-07%	10-13%	0-00%	2-01%	12-20%	13-10%	61-08%
Insufficient Strobe Lighting	0-00%	2-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	3-00%
Plate Unclear	3-03%	3-06%	2-03%	0-00%	2-05%	0-00%	0-00%	9-06%	6-10%	3-02%	28-04%
Red-light not visible in	2-02%	1-02%	0-00%	3-17%	0-00%	0-00%	0-00%	1-01%	1-02%	2-02%	10-01%
Unclear Scene Image	0-00%	2-04%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	3-00%
Process Issues	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Total	14-13%	9-18%	13-17%	5-28%	5-12%	11-14%	0-00%	12-08%	19-31%	19-14%	107-15%
Approved Violations	97-87%	41-82%	65-83%	13-72%	38-88%	67-86%	0-00%	138-92%	42-69%	114-86%	615-85%
Total Notices Printed	97-87%	41-82%	65-83%	13-72%	38-88%	67-86%	0-00%	138-92%	42-69%	114-86%	615-85%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: CMEDINA

Generated On: 4/19/2018 11:44:31 AM

Customer Management Report (Fremont) All Detection Types

01-Dec-2017 to 31-Dec-2017

Operator Id: %

	FR-AMFR-01	FR-AUGR-01	FR-BLMO-01	FR-DEFR-01	FR-DEPP-01	FR-MIMO-01	FR-MIWS-01	FR-MOFA-01	FR-MOFR-01	FR-STBL-01	TOTAL
Total Processed Incidents	176	84	151	32	66	131	0	220	144	198	1202
Less Uncontrollable Factors											
Police	Citation Issued manually	0	0	0	1	0	0	0	0	0	1
Rejects	Driver Obstruction (PD)	5	9	2	1	9	17	0	8	16	76
	Emergency Vehicle Responding	0	0	4	7	9	1	0	20	32	75
	Gender Mismatch	2	1	0	0	0	0	0	1	1	6
	Incorrect/Incomplete DMV	2	1	0	0	2	3	0	5	1	19
	Invalid Offense	1	1	1	1	0	0	0	3	1	8
	Multiple vehicles in frame	0	3	1	0	0	1	0	2	0	7
	Non-Prosecutable Violation	7	4	54	1	0	6	0	7	1	85
	On or Passed the Stop Bar (PD)	28	3	8	12	3	4	0	11	5	117
	Paper Plates	9	4	7	0	6	0	0	21	4	59
	Plate Obstruction (PD)	1	10	5	0	2	4	0	2	6	34
	Plate Unidentifiable	1	3	4	0	2	5	0	1	2	20
	Sun Glare	6	1	4	0	1	1	0	5	6	30
Registration	Out of Country Plate	0	0	0	0	0	1	0	0	0	1
Issues											
Total		62	40	90	23	34	43	0	81	79	538
Sub Total Violations		114	44	61	9	32	88	0	139	65	664
Less in Progress		0	0	0	0	0	0	0	0	0	0
Available For Prosecution		114	44	61	9	32	88	0	139	65	664
Less Rejects											
Police	Driver Unidentifiable images poor	7-06%	4-09%	8-13%	2-22%	4-12%	3-03%	0-00%	4-03%	18-28%	56-08%
Rejects	Insufficient Strobe Lighting	0-00%	0-00%	1-02%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	3-00%
	Plate Unclear	6-05%	3-07%	0-00%	0-00%	0-00%	2-02%	0-00%	2-01%	3-05%	18-03%
	Red-light not visible in	1-01%	2-05%	0-00%	0-00%	0-00%	6-07%	0-00%	2-01%	0-00%	12-02%
	Unclear Scene Image	0-00%	1-02%	0-00%	0-00%	0-00%	1-01%	0-00%	1-01%	0-00%	3-00%
Process	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	2-00%
Issues											
Total		14-12%	10-23%	9-15%	2-22%	4-12%	14-16%	0-00%	9-06%	22-34%	94-14%
Approved Violations		100-88%	34-77%	52-85%	7-78%	28-88%	74-84%	0-00%	130-94%	43-66%	570-86%
Total Notices Printed		100-88%	34-77%	52-85%	7-78%	28-88%	74-84%	0-00%	130-94%	43-66%	570-86%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: CMEDINA

Generated On: 4/25/2018 4:05:08 PM

Customer Management Report (Fremont) All Detection Types

01-Jan-2017 to 31-Dec-2017

Operator Id: %

	FR-AMFR-01	FR-AUGR-01	FR-BLMO-01	FR-DEFR-01	FR-DEPP-01	FR-MIMO-01	FR-MIWS-01	FR-MOFA-01	FR-MOFR-01	FR-STBL-01	TOTAL	
Total Processed Incidents	3085	1248	1067	419	1008	1796	1332	1729	1515	2803	16002	
Less Uncontrollable Factors												
Police	Citation Issued manually	0	0	0	1	0	0	0	0	0	1	
Rejects	Driver Obstruction (PD)	156	119	50	22	50	164	96	75	96	932	
	Emergency Vehicle Responding	23	8	38	49	46	11	2	124	285	611	
	Funeral Procession/Police	10	9	3	0	8	0	1	0	1	32	
	Gender Mismatch	23	7	4	1	9	10	4	5	3	88	
	Incorrect Plate on Vehicle	0	0	0	0	0	0	1	0	0	1	
	Incorrect/Incomplete DMV	58	25	10	4	14	23	26	40	20	275	
	Invalid Offense	19	33	5	5	5	94	49	12	80	317	
	Multiple vehicles in frame	0	15	3	0	1	15	3	2	6	45	
	Non-Prosecutable Violation	23	15	120	2	7	30	21	106	131	476	
	On or Passed the Stop Bar (PD)	605	91	132	121	34	168	66	81	83	2070	
	Paper Plates	101	62	52	20	54	66	38	94	47	676	
	Plate Obstruction (PD)	26	47	23	3	28	24	26	17	25	253	
	Plate Unidentifiable	37	45	10	5	30	29	36	13	14	240	
	Police Discretion	0	0	0	0	1	0	0	0	0	1	
	Safe Turn On Red	0	0	0	0	0	0	0	0	0	1	
	Sun Glare	192	43	89	3	86	21	70	23	76	791	
	Weather Conditions	1	1	1	1	0	2	0	4	1	12	
	Yielding to an Emergency	0	0	0	0	0	0	0	0	0	1	
Registration	Out of Country Plate	1	0	0	0	0	1	1	0	0	4	
Issues												
Total		1275	520	540	237	373	658	439	597	868	6827	
Sub Total Violations		1810	728	527	182	635	1138	893	1132	647	9175	
Less in Progress		0	0	0	0	0	0	0	0	0	0	
Available For Prosecution		1810	728	527	182	635	1138	893	1132	647	9175	
Less Rejects												
Camera	Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Malfunction	Driver Unidentifiable images poor	270-15%	35-05%	67-13%	15-08%	56-09%	85-07%	90-10%	23-02%	125-19%	106-07%	872-10%
Police	Incorrect Speed	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-01%	0-00%	0-00%	0-00%	6-00%
Rejects	Insufficient Strobe Lighting	1-00%	4-01%	1-00%	0-00%	0-00%	2-00%	0-00%	1-00%	1-00%	8-01%	18-00%
	No Images	8-00%	2-00%	0-00%	1-01%	1-00%	1-00%	24-03%	0-00%	2-00%	2-00%	41-00%
	No Video	11-01%	0-00%	0-00%	4-02%	0-00%	0-00%	2-00%	13-01%	2-00%	0-00%	32-00%
	Plate Unclear	37-02%	21-03%	13-02%	2-01%	25-04%	16-01%	24-03%	58-05%	22-03%	22-01%	240-03%
	Red-light not visible in	7-00%	3-00%	1-00%	7-04%	0-00%	7-01%	1-00%	14-01%	4-01%	10-01%	54-01%
	Unclear Scene Image	38-02%	54-07%	8-02%	17-09%	15-02%	62-05%	89-10%	13-01%	20-03%	18-01%	334-04%

Generated By: CMEDINA

Generated On: 4/19/2018 11:48:40 AM

Customer Management Report (Fremont) All Detection Types

01-Jan-2017 to 31-Dec-2017

Operator Id: %

		FR-AMFR-01	FR-AUGR-01	FR-BLMO-01	FR-DEFR-01	FR-DEPP-01	FR-MIMO-01	FR-MIWS-01	FR-MOFA-01	FR-MOFR-01	FR-STBL-01	TOTAL
Process	Too Old	22-01%	13-02%	9-02%	2-01%	9-01%	16-01%	10-01%	11-01%	10-02%	21-01%	123-01%
Issues												
Total		394-22%	132-18%	99-19%	48-26%	106-17%	189-17%	246-28%	133-12%	186-29%	188-13%	1721-19%
Approved Violations		1416-78%	596-82%	428-81%	134-74%	529-83%	949-83%	647-72%	999-88%	461-71%	1295-87%	7454-81%
Total Notices Printed		1416-78%	596-82%	428-81%	134-74%	529-83%	949-83%	647-72%	999-88%	461-71%	1295-87%	7454-81%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: CMEDINA

Generated On: 4/19/2018 11:48:40 AM

Customer Management Report (Fremont) All Detection Types

01-Jan-2018 to 31-Jan-2018

Operator Id: %

	FR-AMFR-01	FR-AUGR-01	FR-BLMO-01	FR-DEFR-01	FR-DEPP-01	FR-MIMO-01	FR-MIWS-01	FR-MOFA-01	FR-MOFR-01	FR-STBL-01	TOTAL	
Total Processed Incidents	252	72	115	36	50	134	60	205	106	185	1215	
Less Uncontrollable Factors												
Police Rejects	Driver Obstruction (PD)	10	12	7	1	4	18	14	9	18	9	102
	Emergency Vehicle Responding	5	1	5	4	1	0	0	14	26	2	58
	Gender Mismatch	3	0	0	0	0	3	2	3	1	1	13
	Incorrect/Incomplete DMV	3	0	3	0	1	6	2	3	1	1	20
	Invalid Offense	0	0	0	0	0	1	0	0	0	0	1
	Multiple vehicles in frame	0	0	0	0	0	1	0	1	0	0	2
	Non-Prosecutable Violation	9	2	8	3	2	9	3	7	5	5	53
	On or Passed the Stop Bar (PD).	52	10	15	15	1	8	1	11	6	55	174
	Paper Plates	10	4	6	1	4	8	1	6	3	14	57
	Plate Obstruction (PD)	10	6	3	0	1	1	5	4	2	0	32
	Plate Unidentifiable	5	1	2	0	2	4	0	3	1	0	18
	Sun Glare	9	2	5	0	4	0	3	9	2	1	35
	Weather Conditions	0	0	0	0	0	0	0	2	0	0	2
	Yielding to an Emergency	0	0	0	0	0	0	0	0	1	0	1
Registration Issues	Out of Country Plate	0	0	0	0	0	1	0	0	0	0	1
Total		116	38	54	24	20	60	31	72	66	88	569
Sub Total Violations		136	34	61	12	30	74	29	133	40	97	646
Less in Progress		0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		136	34	61	12	30	74	29	133	40	97	646
Less Rejects												
Police Rejects	Driver Unidentifiable images poor	11-08%	2-06%	3-05%	2-17%	0-00%	3-04%	3-10%	8-06%	11-28%	6-06%	49-08%
	Insufficient Strobe Lighting	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-01%	0-00%	1-01%	3-00%
	Plate Unclear	5-04%	1-03%	2-03%	0-00%	0-00%	4-05%	0-00%	0-00%	1-02%	0-00%	13-02%
	Red-light not visible in	1-01%	0-00%	0-00%	0-00%	0-00%	4-05%	0-00%	1-01%	0-00%	0-00%	6-01%
	Unclear Scene Image	2-01%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	5-01%
Process Issues	Too Old	8-06%	0-00%	7-11%	1-08%	1-03%	5-07%	3-10%	2-02%	5-12%	5-05%	37-06%
Total		27-20%	4-12%	12-20%	3-25%	1-03%	17-23%	6-21%	12-09%	17-42%	14-14%	113-17%
Approved Violations		109-80%	30-88%	49-80%	9-75%	29-97%	57-77%	23-79%	121-91%	23-57%	83-86%	533-83%
Total Notices Printed		109-80%	30-88%	49-80%	9-75%	29-97%	57-77%	23-79%	121-91%	23-57%	83-86%	533-83%

Generated By: CMEDINA

Generated On: 4/19/2018 11:45:02 AM

Customer Management Report (Fremont) All Detection Types

01-Jan-2018 to 31-Jan-2018

Operator Id: %

TOTAL	FR-STBL-01	FR-MOFR-01	FR-MOFA-01	FR-MIWS-01	FR-MIMO-01	FR-DEPP-01	FR-DEFR-01	FR-BLMO-01	FR-AUGR-01	FR-AMFR-01
-------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: CMEDINA

Generated On: 4/19/2018 11:45:02 AM

Customer Management Report (Fremont) All Detection Types

01-Feb-2018 to 28-Feb-2018

Operator Id: %

	FR-AMFR-01	FR-AUGR-01	FR-BLMO-01	FR-DEFR-01	FR-DEPP-01	FR-MIMO-01	FR-MIWS-01	FR-MOFA-01	FR-MOFR-01	FR-STBL-01	TOTAL
Total Processed Incidents	257	56	88	22	66	145	131	207	122	212	1306
Less Uncontrollable Factors											
Obstruction	Driver Obstruction/Duckers	1	0	0	0	0	1	1	1	2	6
	Plate Obstruction	19	2	3	0	1	4	5	4	6	45
	Vehicle Obstruction	6	4	4	0	2	12	4	11	1	56
Police Rejects	Driver Obstruction (PD)	6	3	1	0	4	19	8	5	12	74
	Emergency Vehicle Responding	0	1	3	2	3	1	10	19	2	41
	Gender Mismatch	2	0	1	0	0	1	0	0	1	5
	Incorrect/Incomplete DMV	4	0	0	0	2	2	6	0	4	21
	Non-Prosecutable Violation	4	2	2	2	1	4	8	4	3	36
	On or Passed the Stop Bar (PD).	66	2	8	9	1	4	9	4	47	150
	Paper Plates	0	0	0	0	0	1	0	0	0	1
	Sun Glare	15	1	2	0	3	3	0	1	8	33
	Weather Conditions	0	0	0	0	1	1	0	0	1	3
Policy/Weather	Extended Vehicle	0	2	0	1	1	5	0	0	1	16
	Sun Glare	20	0	7	0	1	5	2	12	5	52
	Weather/Nature	0	0	0	0	0	0	0	1	0	1
Registration Issues	Out of Country Plate	0	0	0	0	1	0	0	1	0	2
	Paper Plates	4	4	8	1	7	5	7	6	12	69
Total		147	21	39	15	27	54	66	69	105	611
Sub Total Violations		110	35	49	7	39	91	65	53	107	695
Less in Progress		0	0	0	0	0	0	0	0	0	0
Available For Prosecution		110	35	49	7	39	91	65	53	107	695
Less Rejects											
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-05%	0-00%	0-00%	3-00%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	2-00%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-00%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	1-00%
Police Rejects	Driver Unidentifiable images poor	5-05%	0-00%	2-04%	1-14%	4-10%	3-03%	11-17%	1-01%	12-23%	41-06%
	Red-light not visible in	6-05%	1-03%	0-00%	0-00%	0-00%	3-03%	0-00%	0-00%	0-00%	10-01%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-02%	0-00%	1-01%	3-00%
Process Issues	Too Old	9-08%	3-09%	3-06%	0-00%	2-05%	1-01%	0-00%	6-04%	2-04%	31-04%
Total		20-18%	4-11%	5-10%	1-14%	6-15%	8-09%	18-28%	7-05%	16-30%	93-13%
Approved Violations		90-82%	31-89%	44-90%	6-86%	33-85%	83-91%	47-72%	132-95%	37-70%	602-87%

Generated By: CMEDINA

Generated On: 4/19/2018 11:45:31 AM

Customer Management Report (Fremont) All Detection Types

01-Feb-2018 to 28-Feb-2018

Operator Id: %

	FR-AMFR-01	FR-AUGR-01	FR-BLMO-01	FR-DEFR-01	FR-DEPP-01	FR-MIMO-01	FR-MIWS-01	FR-MOFA-01	FR-MOFR-01	FR-STBL-01	TOTAL
Total Notices Printed	90-82%	31-89%	44-90%	6-86%	33-85%	83-91%	47-72%	132-95%	37-70%	99-93%	602-87%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: CMEDINA

Generated On: 4/19/2018 11:45:31 AM

Customer Management Report (Fremont) All Detection Types

01-Mar-2018 to 31-Mar-2018

Operator Id: %

	FR-AMFR-01	FR-AUGR-01	FR-BLMO-01	FR-DEFR-01	FR-DEPP-01	FR-MIMO-01	FR-MIWS-01	FR-MOFA-01	FR-MOFR-01	FR-STBL-01	TOTAL	
Total Processed Incidents	372	74	109	23	52	154	152	231	102	225	1494	
Less Uncontrollable Factors												
Obstruction	Driver Obstruction/Duckers	2	1	1	0	0	4	5	4	1	2	20
	Plate Obstruction	7	2	0	0	3	3	2	5	6	2	30
	Vehicle Obstruction	3	5	1	0	1	10	3	4	6	1	34
Police Rejects	Driver Obstruction (PD)	10	1	3	1	2	3	4	8	8	7	47
	Emergency Vehicle Responding	0	0	1	2	1	1	1	8	11	2	27
	Gender Mismatch	0	0	0	0	0	0	4	1	0	1	6
	Incorrect/Incomplete DMV	12	0	0	0	1	7	3	2	0	4	29
	Invalid Offense	0	0	0	0	0	1	0	0	0	0	1
	Multiple vehicles in frame	0	0	0	0	0	1	0	0	1	0	2
	Non-Prosecutable Violation	3	2	2	1	3	3	5	7	1	1	28
	On or Passed the Stop Bar (PD).	92	6	15	9	2	13	1	9	7	56	210
	Safe Turn On Red	3	0	0	0	0	0	0	0	0	3	6
	Sun Glare	13	2	6	0	0	3	4	2	4	4	38
	Weather Conditions	1	0	0	0	0	0	0	1	0	0	2
Policy/Weather	Extended Vehicle	3	7	6	0	2	6	7	2	0	0	33
	Sun Glare	79	5	11	0	5	3	29	4	10	9	155
	Weather/Nature	0	2	0	0	1	0	1	1	1	0	6
Registration Issues	Paper Plates	12	4	7	1	0	8	10	10	6	10	68
Total		240	37	53	14	21	66	79	68	62	102	742
Sub Total Violations		132	37	56	9	31	88	73	163	40	123	752
Less in Progress		0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		132	37	56	9	31	88	73	163	40	123	752
Less Rejects												
Camera Malfunction	Face Camera Flash	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	2-00%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	2-00%
	Rear Plate Flash Inappropriate	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Video Not In Sync	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	2-02%	1-03%	1-02%	1-11%	1-03%	5-06%	13-18%	4-02%	5-12%	3-02%	36-05%
	No Video	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Red-light not visible in	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	1-01%	1-02%	1-01%	4-01%
	Unclear Scene Image	1-01%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	3-00%
Process Issues	Too Old	27-20%	1-03%	7-12%	2-22%	5-16%	14-16%	7-10%	19-12%	9-22%	7-06%	98-13%
Total		31-23%	5-14%	9-16%	4-44%	6-19%	19-22%	23-32%	25-15%	15-38%	11-09%	148-20%

Generated By: CMEDINA

Generated On: 4/19/2018 11:45:56 AM

Customer Management Report (Fremont) All Detection Types

01-Mar-2018 to 31-Mar-2018

Operator Id: %

	FR-AMFR-01	FR-AUGR-01	FR-BLMO-01	FR-DEFR-01	FR-DEPP-01	FR-MIMO-01	FR-MIWS-01	FR-MOFA-01	FR-MOFR-01	FR-STBL-01	TOTAL
Approved Violations	101-77%	32-86%	47-84%	5-56%	25-81%	69-78%	50-68%	138-85%	25-62%	112-91%	604-80%
Total Notices Printed	101-77%	32-86%	47-84%	5-56%	25-81%	69-78%	49-67%	138-85%	25-62%	112-91%	603-80%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: CMEDINA

Generated On: 4/19/2018 11:45:56 AM